

U.S. Department of Labor
Mine Safety and Health Administration
Educational Field and Small Mine Services



Location _____ Date _____

Competent Person _____ Duration _____ Time _____

Drills

- Lubricating oil when drilling large holes.
- Keep drill bits sharp and in good repair.
- Make sure the drill has a ground pin on the power cord. [56.12025](#)

Grinders

- Maintain proper gap between tool rest and grinding wheel (1/8") [56.14115b](#)
- Use goggles or face shield when grinding. [56.14115a](#)
- Turn grinder off when not in use.

Welding Accessories

- Keep welding hood and glasses clean and in good working order.
- Always use gloves when welding or cutting. [56.15007](#)
- Always use an approved striker.

Hand tools

- Never use broken tools. [56.14100b](#)
- Check punches and chisels for damaged or mushroomed heads and repair before using.
- Keep tools clean and in good repair for each use report any damaged tools for replacement.
- Use the proper tools for the jobs do not use tools beyond their design capacity. [56.14205](#)
- Maintain safe working habits, wear your PPE, never cut towards yourself with a knife and be aware of other employees around you. [56.15002](#); [.15003](#); [.15004](#); [.15007](#); [.15014](#)

Chains and Come-Along

- Inspect come-along for damage and repair as often as necessary. [56.14100b](#)
- Be aware of rated capacities, don't overload. [56.14205](#)
- Never use a handle not designed for a come-along. [56.14205](#)

Fatalgrams: [56.12025](#); [.14100](#); [.14205](#); [.15002](#); [.15007](#).

Attendees: