

Figure 1 - No.2 Miner parked in entry after completing cut in 2-right crosscut. Roof bolter waiting to pull into 2-right to begin installing roof supports.





Figure 2 - No.2 miner backed into last open crosscut to allow roof bolter to be moved into 2-right crosscut.






Figure 4 - No.2 miner moved back across intersection to allow scoop to proceed inby in the No.2 entry. The accident occurred during this move.



Photograph 1 - Boom of Continuous Mining Machine



Photograph 2 - Remote Control Unit