Mine Citation/Order

22. Signature

Patrick Alan Stanfield

U.S. Department of Labor Mine Safety and Health Administration



	Wille Safety and Fleatth Administration
Section IViolation Data	
1. Date Mo Da Yr 2. Time (24 Hr. Clock) 12/06/2011 0800	3. Citation/ Order Number 8258547
4. Served To	5. Operator
Berman Cornett (Safety Director)	PERFORMANCE COAL COMPANY, et al
6. Mine	7. Mine ID 46-08436 (Contractor)
UPPER BIG BRANCH MINE-SOUTH	(Contractor)
8. Condition or Practice	8a. Written Notice (103g)
The Fletcher Roof bolter (serial #2005	5325) is not being maintained
permissible, in that;	
(1) the off-side rear headlight is not	secured to the machine. The one bolt
holding the light on is loose.	
(2) the off-side XP enclosure is not se	ecurely mounted to the machine-mounting
bolt broken,	
(3) the area light at the operator's si	ide rear is not secured to the machine-
bolts are missing, one of the bolts pro	ovided is loose,
(4) the packing gland for the power cor	nductor to the operator's side rear area
light is badly bent to the degree that	the conductor inside the packing gland
can be damaged,	
(5) one of the spotlights at the ATRS is	is missing, the exposed ends of the
	See Continuation Form (MSHA Form 7000-3a)
5. Heldan H. Hedan	Part/Section of
55.51	itle 30 CFR 75.503
Other Section II-Inspector's Evaluation	
10. Gravity:	
A. Injury or Illness (has) (is): No Likelihood Unlikely	Reasonably Likely Highly Likely Occurred
B. Injury or illness could reasonably be expected to be: No Lost Workdays Lost Workday	ays Or Restricted Duty ☐ Permanently Disabling ☐ Fatal ✔
C. Significant and Substantial: Yes ✓ No ✓	D. Number of Persons Affected: 008
11. Negligence (check one) A. None B. Low C. Mc	oderate D. High 🗸 E. Reckless Disregard 🗌
12. Type of Action 104(d)(2) 13. Type of Issuance	
14. Initial Action A. Citation ☐ B. Order ✔ C. Safeguard ☐ D. Written Notice ☐	E. Citation/ 8082692
15. Area or Equipment Fletcher Roof Bolter (seri	al # 2005325)
remain Flefcher Kool Bolter (Bell	A1 # 2003323/
16. Termination Due A. Date Mo Da Yr B. Time (24 Hr. Clock)	
Section III—Termination Action	
17. Action to Terminate	
18. Terminated Mo Da Yr	
A. Date B. Time (24 Hr. Clock	
A. Date B. Time (24 Hr. Clock	
Section IV—Automated System Data 19. Type of Inspection 20. Event Number 4.4.0.2.4.9	21. Primary or Mill

MSHA Form 7000-3, Apr 08 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

23. AR Number

23908

Mine Citation/Order Continuation

U.S. Department of Labor Mine Safety and Health Administration



Section I-Subsequent Action/Continuation Data							
1. Subsequent Action 1a. Continuation	2. Dated (Original Issue)	Mo I 12/06	Da Yr /2011	3. Citation/ Order Number 8258547			
				5. Operator PERFORMANCE COAL COMPANY, et al			
				46-08436	(Contractor)		
O							

Section II-Justification for Action

Continuation of 8. Condition or Practice

power conductors are lightly taped,

- (6) the housing for the other spotlight on the ATRS is broken, near the packing gland,
- (7) 3 packing glands at the off-side main Controller (XP enclosure) are not secured to prevent loosening,
- (8) one of the bolts in the aluminum lid of the off-side main controller (XP enclosure) is missing a flat washer.

The bolter is located one crosscut inby spad 24079. This area was affected by an explosion on 04.05.2010. The bolter was not in use on this day; however, it was readily available for use. The mine has a history of methane liberation and is on a 103(i) spot for methane liberation.

The Operator has engaged in aggravated conduct constituting more than ordinary negligence. This is an unwarrantable failure to comply with an unwarrantable failure.

This citation is being issued to the following entities as a unitary operator: Performance Coal Company, Massey Coal Services, Inc., A.T. Massey Coal Company, Inc., and Massey Energy Company.

							Se	ee Continuation Form
Section III-Subse	quent Action Take	រា						
8. Extended To	A. Date Mo	Da	Yr	B. Time (24 Hr. Clock)		C. Vacated	D. Terminated	E. Modified
Section IV-Inspec	tion Data							<u> </u>
9. Type of Inspe	ection E16		10. E	vent Number 4440348				
11. Signature A			AR Number	12. Date	Mo Da Yr	13. Time (24 Hr. Clock)		
Patrick Alan Stanfield		23908		12/06/2011	0800			