

Belt Reports

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT

Day

DATE 12-28-09

NAME Jim Bowyer

WORK PERFORMED

Set #19 Brk pump out in deeper water
checked EM 110s
Had to go to 1 North & start it
checked splices 1 North, 1 South, 4 sec # 1, 2, 3
checked south side seals
changed 2 washed rollers
cleaned 3 sec # 1 & 2
checked 1 South Portal 2 Brk
cleaned on 1 South tail cage
cleaned on 4 sec # 1 tail
washed out scraper 4 sec # 2 head
checked # 14, 3 & 8 pumps
inspected 1 South, 1 North, 4 sec # 1, 2, 3

MATERIALS OR SUPPLIES NEEDED

2

3

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

3 sec # 1 head hold down roller broke

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT

Day

DATE 12-29-09

NAME Jim Bowyer

WORK PERFORMED

checked #1981K, E on 110's
knowing 1 South tail & checked 46-tail
filled 2 new dusturators & flow them South
cleaned up sub well & set 5 timbers at 13-14 on 1 North
emptied magnet at ground out
checked 3 section left 2 timbers 2 replace
cleaned 4 on #1 tail & washed out screens 4 on #2
checked replace 1 North, 1 South 4 on #1, 2, 3
checked grapples 14, 30, 4 on 110's
Timbered 1 South 1 North, 4 on #1, #2, #3

MATERIALS OR SUPPLIES NEEDED

2 _____ 3 _____

MAINTANCE NEEDED

4 _____ 5 _____

ADDITIONAL COMMENTS OR REMARKS

Need 2 replace made 3 on #1
Need dust at 1 South tail

PERFORMANCE COAL
BELT REPORT

MINE USS

SECTION

SHIFT DAY

DATE 12-29-09

NAME Scott Halstead

WORK PERFORMED

1. Ran Jim Fawcett & Jack Roles to end of track on Long Wall
2. Greased Drive Rollers at Mother Drive
3. Cut strings out of Bottom Rollers at Mother drive
4. Cleaned flow thru at Mother Drive discharge
5. Spot Cleaned Belt 12-19 BK WALK Side
6. Spot Cleaned Sime. offside 31 BK
7. Firebassed L W Belt, N. Maino, Glory Hole, 2 Section

MATERIALS OR SUPPLIES NEEDED

- | | |
|-------|-------|
| 2 | 3 |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

MAINTANCE NEEDED

- | | |
|-------|-------|
| 4 | 5 |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 12-30-09

NAME Jim Bowyer

WORK PERFORMED

Picked up pumps & fitting before start of shift
checked 19, 14, 30 EM 110 pumps
changed & checked fittings at east main
checked seals on South Side
set up picks NM #1 & EM's when spinner came back
cleaned on 3 section head & tail
cleaned tail on 4 section #1 & #2 heads
checked splices 4 section #1, 1 North 1 South
anchored belts

MATERIALS OR SUPPLIES NEEDED

2 Need rock dust at
South tail & 3 sec 1 head

MAINTANCE NEEDED

4 Need hold down roller
put on 3 section head

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT DAY

DATE 12-30-09

NAME Scott Halstead

WORK PERFORMED

1. Did P.M. on Mother Drive, took Bearing temp Readings
2. Replaced Burnt out Light Bulbs at Mother Drive
3. Did P.M. on Mother Drive
4. Cleaned on Discharge, cleaned up Mud & Water
5. CRd Splices in Belt
6. Dusted around Mother Drive Area
7. Firebossed LW, Belt, 1 Section Belt

MATERIALS OR SUPPLIES NEEDED

- | | |
|---|---|
| 2 | 3 |
| | |
| | |
| | |

MAINTANCE NEEDED

- | | |
|---|---|
| 4 | 5 |
| | |
| | |
| | |
| | |

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USB

SECTION

SHIFT DAY

DATE 12-31-09

NAME Scott Halstead

WORK PERFORMED

1. CKD 89 BX Refuge Start of Shift
2. Cleaned Spillage up at Mother Drive discharge
3. Did PM on Storage Unit, took Bearing temp readings
4. Filled trickle Duster with Dust and turned on at Storage Unit
5. Greased Motherdrive Discharge and Drive Rollers
6. Cleaned on Mud and Water at Motherdrive
7. Dusted around Mother Drive.
8. CKD Splices in Belt
9. Firebored LW Belt, and 1 Section Belts
10. Trained Some on 1 Section #1 Belt.

MATERIALS OR SUPPLIES NEEDED

- | | |
|-------|-------|
| 2 | 3 |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

MAINTANCE NEEDED

- | | |
|-------|-------|
| 4 | 5 |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT DAY

DATE 1-1-10

NAME Scott Haddock

WORK PERFORMED

1. CKd 8BK & 89BK Refuges Start of Shift
2. Cleaned Mother Drive Flow then and Sprayed out Slobber Chute
3. Did PM CK List on Mother Drive, took Bearing Temp. Readings
4. Worked on cleaning up Mud and Water around Drive Area of Mother Drive
5. Hand Dusted around Mother Drive to Dry up Water.
6. CKd Fire Exts on My Firebossed Run and Punched date tags
7. CKd Splices in Belt
8. Firebossed 1 W Belt, 1 Section #1 & 2 Belts.
9. Trimmied Splice on 1 Section #1 Belt, and did some training at tail

MATERIALS OR SUPPLIES NEEDED

2

3

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT DAY

DATE 1-4-10

NAME Jim Bowyer

WORK PERFORMED

Went over New Radio System start of shift
Checked South Side Seals
Cleaned spillage with 1 South tail & trained on it same
changed & washed filters at E Main
Checked 3 sec # 8, 14 jumps EM 110's 4 sec 110 #30
Checked spillage 1 South 1 North @ 4 sec #1, 2, 3
Emptied magnet
Inspected 1 South, 1 North, 4 sec 1, 2, 3

MATERIALS OR SUPPLIES NEEDED

2 Need rock dust 3 sec 1 in 3
#1 head & 1 South Tail

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 1-10-10

NAME George Curry

WORK PERFORMED

Walked 4 section left + Rt Return

Inspected 3 section belt

Referenced P.M. on 1 south level.

MATERIALS OR SUPPLIES NEEDED

2 _____

3 _____

MAINTANCE NEEDED

4 _____

5 _____

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT DAY

DATE 1-6-10

NAME Jim Benyer

WORK PERFORMED

went to 3 sec & picked up a mandrel, fittings, couplings, etc
Oregon start of shift

Took Dick E. Garry C. Pack to 4 section
checked South Side Seals

went to M.P. 11 with George & checked air function &
changed filter & washed down of E. Main

shoveled & dusted 1 South tail

shoveled & dusted 1 North tail

checked splices 1 South 1 North

checked rollers 3 Section

checked pumps

Inchman

emptied magnet at EM Panel
out

MATERIALS OR SUPPLIES NEEDED

2 4' x 6' rock dust at 1/2 South tail
& 3 Section head

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT DAY

DATE 1-11-10

NAME Jim Bowyer

WORK PERFORMED

Drum #1 gathered up pump, line, cable etc. & set it at
LBB & set water off of truck
changed & washed rollers at E.M.
cleaned some of 3 sec & 1 head
replaced roller key rollers 4-9 on 1 South
emptied magnet at 1 South head
cleaned spillage South tail
stripped Bottom Roller 15-16 on 1 North
checked sensors
fine work

MATERIALS OR SUPPLIES NEEDED

2 Hard coal dust at South tail & 3 sec head

MAINTANCE NEEDED

4	5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 1-12-10

NAME Jim Bouyer

WORK PERFORMED

Worked on #5 Seal
Empty magnet
had to go reset CD monitor 34 & 15 South
had to go outside and get battery man 7 take to 3 section
checked F.M. 112, 4 sec 112, #14, 30 yamps
checked system 1 South
took 2 casks of SCS's from Plunkly to top hill
3 section
Finished

MATERIALS OR SUPPLIES NEEDED

2 Need dust 1 South tail & 3 section head

MAINTANCE NEEDED

4	5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 1-13-10

NAME Jim Boyer

WORK PERFORMED

Took Glen's report
Took George to 1 South tail
shoveled 42-42' Bel track side on 1 South
shoveled 2 Bottom rollers 26 Bel on 1 South
Got 110 pump going EM
checked EM pump, #30, 300 #8, 14
went to EM pump out 2 took pump 2 line to 3 per head
found deluge pipe at 3 head and some on it had
to go to 1 South tail get George (sid) took outside
checked seals
filled 1 sin dust at 1 South tail (Dust total)
emptied magnet
checked spec 1 South
Finished

MATERIALS OR SUPPLIES NEEDED

2 cleaned off pump box at 1 North head

MAINTANCE NEEDED

4 Head and dust 1 South tail & 3 head

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT DAY

DATE 1-14-10

NAME Jim Boyer

WORK PERFORMED

(Dropy II)

Recovered pump & starter box from top of hill. Took to
3 section 1/6 BRK in return. Set it hooked up line
Brought back pump out to
went to 1 South tail of hill. I saw dust
along cable, discharge line. I set pump beside track
at 3 section head
cleaned on 3 sec. haul taking up some
put wallet of water at D-Box 19 BRK
checked splices 1 South
got 3 section belt going when off out on ship
D unit

Finished

checked pump

MATERIALS OR SUPPLIES NEEDED

2 _____

3 _____

MAINTANCE NEEDED

4 _____

5 _____

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USS

SECTION

SHIFT

Day

DATE

1-15-10

NAME Tim Bauxer

WORK PERFORMED

put in structure 3 section belt 80-36 Brk Tim & Droopy with me
changed pulsed rollers at E Main
checked Lann traps
Rich Droopy I went back with more structure I installed
emptied magnet 13 Brk
checked South rollers
Tim Bauxer

MATERIALS OR SUPPLIES NEEDED

2

3

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL BELT REPORT

MIN 7 U32

SECTION

SHIFT *D.R.*

DATE 1-16-70

NAME Tim Boyer

WORK PERFORMED

Put in night 2 top structure at 23 Bk in 3 section
 checked 8 iron pumps
 lifted on 1 stem from 6-9 Bk 2 diff times
 cleaned & dusted on 3 sec hand
 checked 1 South column
 emptied oxygen
 finished

MATERIALS OR SUPPLIES NEEDED

[Faint, illegible handwriting on lined paper]

3

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL BELT REPORT

MINE UBB

SECTION

SHIFT Day

DATE 1-18-10

NAME Jim Bowyer

WORK PERFORMED

(Drop your time) Got sand & rocks outside & took to 16 Brk pump
in Right Rotor on 3
checked #14, 8, 16, 18 pumps. & pumped #50
upfilled 3 sec belt & over 3 layers from 23-25 Brk & blocked it
changed & replaced rollers at East Mine
changed out lined area at 3 section sand & turn dustie
cleaned off power line at East Mine
cleaned on intake and dusted around 3 section head area
went to magnet & checked for shield off mine, captured magnet
checked rollers South
filled & dug dust at 1 South tail
of in house

MATERIALS OR SUPPLIES NEEDED

2 Head seal dust at 3
1 South tail & 3 section head

MAINTANCE NEEDED

4 _____ 5 _____

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT DAY

DATE 1-20-10

NAME Jim Bowyer

WORK PERFORMED

Took crew to section (2 trips)
George & I blocked 1 South at 35 & 35 Brk
Checked South Side Sealer
checked E.M. 110's
checked jumps on old works 4 section
checked again 1 South
checked R 14, 8, 16, 18, A 30 jumps
checked on status 2 West head 3 section head
filled 2 air ducts at 1 South of main line
Ditching

MATERIALS OR SUPPLIES NEEDED

2 Need rock dust 1 South tail
& 3 section head

MAINTANCE NEEDED

4	5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 1-21-10

NAME Jim Bowyer

WORK PERFORMED

changed & washed filter at East Mine
got water off track at mouth of 3 section
Replaced 2 broken up spacers at 3 sec head
checked and ran pumps # 14, 16, 18, # 30
checked spacers 3 sec (64)
turned spacers 1 South
checked spacers 1 South
hauled dusted 16-18 belt back into 1 South
cleaned & replaced spacers 1 South belt
hauled dust
filled 1 sec dust in 3 section head

MATERIALS OR SUPPLIES NEEDED

2 4 cubic dust at 3 section head

MAINTANCE NEEDED

4	5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT

DAY

DATE 1-22-10

NAME Jim Bouyer

WORK PERFORMED

Checked #14, 8, 16, 18 pumps, #30, 1 South tail pump
picked up 3 men on 3 sec & went to 4 section and secured
discharge line back to 3 section
Checked South Side Seal
Charged E. M. filler
Turned flywheel on 1 South
cleaned V-plow at 1 South tail
Sections

MATERIALS OR SUPPLIES NEEDED

2 Head seal dust at 3 section 3 head

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 1-25-10

NAME Jim Bowyer

WORK PERFORMED

Put spray bar back on 1 South of takeup
hooked dist from punch at 3 head Ten loaded
put rail 2 belt back in at 20th on 3 sec #1
Charged crushed yellow at 10M
walked return of 4 section panels
checked #10 of scale on South side
checked pulleys 1 South
shouldered and gullage at 1 South of low then
took Drassy to 3 section then went to
4 section finished up belt & equipment
Finished

checked #14, 8, 16, 18, #30 yump

MATERIALS OR SUPPLIES NEEDED

2 _____

3 _____

MAINTANCE NEEDED

4 _____

5 _____

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT DAY

DATE 1-26-10

NAME Jim Bowyer

WORK PERFORMED

Took Rick, Dove & Nick to 3 section start of shift
Took Harley to East Main Pump Out
Set water on mid line sprayer on 3 sec belt
Had to see water 2 get 20 Buckets of mine dirt
and take them to 3 section
Checked #14, 8, 16, 18, #30, R M 1105, pumps
checked L-shaped filter at East Pump
Got water off tank near 3 sec. line
Finished

MATERIALS OR SUPPLIES NEEDED

2 _____ 3 _____

MAINTANCE NEEDED

4 _____ 5 _____

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 1-27-10

NAME Jim Bowyer

WORK PERFORMED

fixed phone line outside 2 places
loaded up belt boss, junction boxes, cables before start of shift
I took them to 3 section
checked # 14, 8, 16, 18, 30. 1 South tail & E.M. 112'S
did fine work on 1 South belt
pulled 4" 5" wide piece of belt from head - 11 Bsk
out of belt walkway
checked South side ~~and~~ seals
changed 2 unhooked filters E.M.
of 112'S
cleaned off some dirt at 1 North head

MATERIALS OR SUPPLIES NEEDED

2 _____	3 _____
_____	_____
_____	_____
_____	_____

MAINTANCE NEEDED

4 _____	5 _____
_____	_____
_____	_____
_____	_____
_____	_____

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 1-28-10

NAME Jim Bowyer

WORK PERFORMED

Rounded up 200' of water line and getting before shift
 Rehooked line in place at 1 South head
 Fixed blocking 8-9 Bk. (Droopy with line)
 Checked 12-14 Bk's
 Checked 18-21 Bk's on south side
 Rehooked jump at 1 South head
 (Droopy helped me) saw & hooked up 200' line from 43-46 Bk
 on 1 South set fire hose stand & hooked up fire hose
 moved and dust 2' to E.M. to clean up before line
 cleaned some on 3 on 1 taking rollers
 dropped bottom roller 27 Bk on 1 South
 fixed blocking at 10 Bk on 1 South
 fine lined

MATERIALS OR SUPPLIES NEEDED

2 Checked A 13, 14, 8, 16, 18 jumps
 3

MAINTANCE NEEDED

4
 5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT

Day

DATE

1-29-10

NAME

Tom Sawyer

WORK PERFORMED

Picked up parts before start of shift
checked EM 110's #30
checked #12 #21 seals
checked 2 damaged filters at east main
checked South splice
installed 2 diff. valves at #3 Bk on 1 South
checked 3 sec #1 head area
filled down dust at 1 South floor then followed floor to
set sand yoke at 26 Bk power line off 3 sec #1 belt
refueling

MATERIALS OR SUPPLIES NEEDED

2	3
_____	_____
_____	_____
_____	_____

MAINTANCE NEEDED

4	5
_____	_____
_____	_____
_____	_____
_____	_____

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT DAY

DATE 1-30-10

NAME Jim Baeyer

WORK PERFORMED

Drop by with me Put in Top Side Roller 1 South 10 Brk
Checked #10 #21 seals
Reassembled pump at 1 South tail Took it to 19 Brk on 3
Empty magnet took on hour
Set 2 feeders pump discharge, being called at 19 Brk
checked 14 5 30 F on 110's pump
checked 1 South spool
filled 1 am duplex 1 South flow thru
aligned 1 South flow thru
functioned
Chopped Bottom Roller at 36 Brk on 1 South

MATERIALS OR SUPPLIES NEEDED

2

3

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT

Day

DATE

2-1-10

NAME Jim Bouyer

WORK PERFORMED

Checked #19, 14, 18, 16, 8 Brk pumps
put directionals on life line at Plumley smelter
emptied magnet
checked for backup 1 South & X's
checked office extinguisher
changed & washed filters at East 4 mine
worked on guards at 3 sec & 1 head
worked on guards at 1 South on off side (made more clamps)
checked office 1 South
checked
went back up to 19 Brk & checked on pump
pump is down

MATERIALS OR SUPPLIES NEEDED

2 Quik rock dust 3 section #1 head

MAINTANCE NEEDED

4 Pump down at 19 Brk 3 sec (top of hill)

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT DAY

DATE 2-2-10

NAME Jim Boyer

WORK PERFORMED

Gathered up stuff for jump before start of shift
checked EM 11/12
Took Coarse to Base & Dinky to E Main Punch Out
checked 1 South head (station) dimensional - 1 1/2 Bk
hauled dust from E M Punch out to 3 sec #1 & #2 heads
checked 14, 8, 16, 18 Bk jumps & #30, 4 on 112
walked 3 section, pretty looking for water vehicles, found it
I got water going
set jump at 19 Bk (top of hill)
checked ground 3 sec #1 then #2 head
checked around power box 26 Bk on 3 section
checked 1 South officer
cleaned 1 South floor then I am done
quitted MATERIALS OR SUPPLIES NEEDED
checked 19 Bk jump again

MAINTANCE NEEDED

Need work dust Section #1 head

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Dry

DATE 2-3-10

NAME Jim Bowyer

WORK PERFORMED

Checked #19 pump start of shift (too hot to handle tunnel set off)
Checked seals south side
Checked EM 110's
Changed Quashed filter at East Mains
Checked South Scales
went down to #19 pump & cleaned it out
checked 14, 8, 16, 18, 30 pumps
subing life line 23, 24, 25
cleaned & oiled around 3 sec #1 hand flaking
finished

MATERIALS OR SUPPLIES NEEDED

2	3
_____	_____
_____	_____
_____	_____

MAINTANCE NEEDED

4	5
_____	_____
_____	_____
_____	_____
_____	_____

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 2-4-10

NAME Jim Bowyer

WORK PERFORMED

checked #19, 14, 30, EIM 110's
checked early on South of 3 head
took dust to 1 South tail Drassy VI dusted 16-tail
gilled 2 on dusted at 1 South tail & 1 South Flow the
checked magnet, dusted head of South tailup - 2 Bph
worked on 19th ramp & discharge lines & pumped back
trimmed splices on 1 South
opened life line on 3rd 23-24 Bph into
checked 1 South splices
D. H. Bowyer

MATERIALS OR SUPPLIES NEEDED

2 _____	3 _____
_____	_____
_____	_____
_____	_____

MAINTANCE NEEDED

4 _____	5 _____
_____	_____
_____	_____
_____	_____
_____	_____

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 2-5-10

NAME Jim Bowyer

WORK PERFORMED

Chained out top side roller at 13-14 Bk on 1 South
checked #14 Bk pump and checked line to outside
Changed & washed filter at East Mine
checked 14, 8, 16, 18 & 32 pumps
removed splice on 3 sect #8 belt & checked splice
should be dusted 3 sections & 1 tail
Cleaned up power box & dusted area at 26 Bk on 3 sec.
adjusted 18" line (able to do it) at mouth of 3
checked South splice
filled and won dust at 1 South from then & cleaned below then
Chained out rock box 3 sections #1
greased

MATERIALS OR SUPPLIES NEEDED

2 Need rock at 3 sect #1 & head & 1 South tail

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT Day

DATE 2-8-10

NAME Jim Bouger

WORK PERFORMED

checked #19, EM 110's pumps
checked seals (south side), fixed getting #21 seal
walked through of 4 section old panels
changed out of 11th at East Mine
checked 14, 8, 16, 18 pumps on 3 section
checked splices 1 South, 3 section #1, #2
Finished in the

MATERIALS OR SUPPLIES NEEDED

2 _____ 3 _____

MAINTANCE NEEDED

4 _____ 5 _____

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

Lined area for work performed.

MATERIALS OR SUPPLIES NEEDED

2 _____
3 _____
Lined area for materials or supplies needed.

MAINTANCE NEEDED

4 _____
5 _____
Lined area for maintenance needed.

ADDITIONAL COMMENTS OR REMARKS

Lined area for additional comments or remarks.

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT

Day

DATE

2-9-10

NAME Jim Bowyer

WORK PERFORMED

Checked E Mine ramp
helped get chutes on track under medical
helped get chutes on track under medical
helped get chutes on track under medical
helped get chutes on track under medical
helped get chutes on track under medical

MATERIALS OR SUPPLIES NEEDED

2

3

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 2-10-10

NAME Jim Bowyer

WORK PERFORMED

Took 6' splice to 4 section (Start of Shift)
Cleaned French filter at East 4 Main
Checked magnet at East Main
Cleaned snow off of hand lines
Cleaned 7 dusts (3 sec #1, 2, 3, 4, 5, 6, 7)
Adjusted ground 3 sec #2 head
Extended ground on 3 sec #2 head
Checked #14, 8, 16, 18 #30 pumps
Checked splice 1 South
Finished

MATERIALS OR SUPPLIES NEEDED

2 Had rock dust at 3 sec #1 head

MAINTANCE NEEDED

4 _____
5 _____

ADDITIONAL COMMENTS OR REMARKS

6 _____

PERFORMANCE COAL
BELT REPORT

MINE USB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

MATERIALS OR SUPPLIES NEEDED

2

3

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

6

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT Day

DATE 2-11-10

NAME Jim Bowyer

WORK PERFORMED

Droopy & I went up mine rib roll on 1 North at 34 Brk offside
went to 24 Brk on 1 North got life line & check for
ables in clear to run belt
went to 1 North head & set up again up & start it
Reconnected fine hose I dismantled off old 4 section took to 52 Brk
went to 4 section & got spreader & roller, bag in took to 52 Brk
checked scale south side
Empty magnet
made trip to catch tools to replace 1 North
let tubing off for splines
checked yamps
grease
stayed at 1 North head & took up slack etc

MATERIALS OR SUPPLIES NEEDED

2 Used seal dust at 3 section #1 head & #2 head

MAINTANCE NEEDED

4
5

ADDITIONAL COMMENTS OR REMARKS

6

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

MATERIALS OR SUPPLIES NEEDED

2	3
_____	_____
_____	_____
_____	_____

MAINTANCE NEEDED

4	5
_____	_____
_____	_____
_____	_____
_____	_____

ADDITIONAL COMMENTS OR REMARKS

6 _____

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 2-16-10

NAME Jim Bowyer

WORK PERFORMED

Recovered and put a guano at 26 Bkt on 1 North
Replaced & fixed blocking. Replaced 19-20 Bkt 1 North
Changed & washed filters at East Main
Cleaned up power boxes at 4 section at north
dusted guano 3 sec #1 head
cleaned guano filled & ran dust at 1 South Floor then
Empty magnet
checked 1 South splice
Cleaned on 1 South tubing
checked EM 110's, # 8, 14, 16, 18 & 30 jumps
pinchamps belts

MATERIALS OR SUPPLIES NEEDED

2 _____ 3 _____

MAINTANCE NEEDED

4 _____ 5 _____

ADDITIONAL COMMENTS OR REMARKS

6 _____

PERFORMANCE COAL BELT REPORT

MINE USB

SECTION

SHIFT

DATE

NAME:

WORK PERFORMED

MATERIALS OR SUPPLIES NEEDED

2

3

MAINTANCE NEEDED

△

13

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL BELT REPORT

MIKE USB

SECTION

SHIFT Day

DATE: 2-17-10

NAME: Jim Bowyer

WORK PERFORMED

checked. I got #12 Bk going out on water (logon)
 Checked cheaping early in day. I sent 1 South
 cleaned up at 1 South. I dropped got it going. (Blue & Roger with me)
 checked south sea
 cleaned lots of got at 1 South. I saw things
 hung up, stay down at 3 sent #1 head
 drilled 1 South, I saw then 1 South tail & I saw then
 went back to clean some more on 1 South to keep
 checked EM 112's # 8, 14, 16, 18, 3 Dumps
 dropped BR on 1 South 27-28 Bk
 spent 1/2 day clean at 3 Bk on 1 South
 finished

MATERIALS OR SUPPLIES NEEDED

2.

3.

MAINTANCE NEEDED

[illegible]

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

MATERIALS OR SUPPLIES NEEDED

2 _____	3 _____
_____	_____
_____	_____
_____	_____

MAINTANCE NEEDED

4 _____	5 _____
_____	_____
_____	_____
_____	_____
_____	_____

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USB

SECTION

SHIFT Day

DATE 2-18-10

NAME Jim Berneyer

WORK PERFORMED

Took Rick Young to 50 Brk
Checked R 19, E M 110's
checked South side seals
took dust system off of 2000 dustie back tail
emptied magnet (R 19 II)
fixed discharge line at 16 Brk pump
checked R 14, 8, 16, 18 pumps & cleaned
changed 2000 dustie off line at R 19 main
put 2000 in at 23 Brk on 1 South
checked 2000 1 South
Ditchman

helped Virgil & Do Not unload cables etc at 62 main line

MATERIALS OR SUPPLIES NEEDED

2	3

MAINTANCE NEEDED

4	5

ADDITIONAL COMMENTS OR REMARKS

6

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

MATERIALS OR SUPPLIES NEEDED

2

3

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL BELT REPORT

MINF USB

SECTION

SHIFT

DATE 2-19-10

NAME: Tim Bowyer

WORK PERFORMED

Went to 4 station looking for hysls. saw
checked #19, 30, 50, 60, 70, 80, 90, 100, 110, 120, 130, 140, 150, 160, 170, 180, 190, 200, 210, 220, 230, 240, 250, 260, 270, 280, 290, 300, 310, 320, 330, 340, 350, 360, 370, 380, 390, 400, 410, 420, 430, 440, 450, 460, 470, 480, 490, 500, 510, 520, 530, 540, 550, 560, 570, 580, 590, 600, 610, 620, 630, 640, 650, 660, 670, 680, 690, 700, 710, 720, 730, 740, 750, 760, 770, 780, 790, 800, 810, 820, 830, 840, 850, 860, 870, 880, 890, 900, 910, 920, 930, 940, 950, 960, 970, 980, 990, 1000, 1010, 1020, 1030, 1040, 1050, 1060, 1070, 1080, 1090, 1100, 1110, 1120, 1130, 1140, 1150, 1160, 1170, 1180, 1190, 1200, 1210, 1220, 1230, 1240, 1250, 1260, 1270, 1280, 1290, 1300, 1310, 1320, 1330, 1340, 1350, 1360, 1370, 1380, 1390, 1400, 1410, 1420, 1430, 1440, 1450, 1460, 1470, 1480, 1490, 1500, 1510, 1520, 1530, 1540, 1550, 1560, 1570, 1580, 1590, 1600, 1610, 1620, 1630, 1640, 1650, 1660, 1670, 1680, 1690, 1700, 1710, 1720, 1730, 1740, 1750, 1760, 1770, 1780, 1790, 1800, 1810, 1820, 1830, 1840, 1850, 1860, 1870, 1880, 1890, 1900, 1910, 1920, 1930, 1940, 1950, 1960, 1970, 1980, 1990, 2000, 2010, 2020, 2030, 2040, 2050, 2060, 2070, 2080, 2090, 2100, 2110, 2120, 2130, 2140, 2150, 2160, 2170, 2180, 2190, 2200, 2210, 2220, 2230, 2240, 2250, 2260, 2270, 2280, 2290, 2300, 2310, 2320, 2330, 2340, 2350, 2360, 2370, 2380, 2390, 2400, 2410, 2420, 2430, 2440, 2450, 2460, 2470, 2480, 2490, 2500, 2510, 2520, 2530, 2540, 2550, 2560, 2570, 2580, 2590, 2600, 2610, 2620, 2630, 2640, 2650, 2660, 2670, 2680, 2690, 2700, 2710, 2720, 2730, 2740, 2750, 2760, 2770, 2780, 2790, 2800, 2810, 2820, 2830, 2840, 2850, 2860, 2870, 2880, 2890, 2900, 2910, 2920, 2930, 2940, 2950, 2960, 2970, 2980, 2990, 3000, 3010, 3020, 3030, 3040, 3050, 3060, 3070, 3080, 3090, 3100, 3110, 3120, 3130, 3140, 3150, 3160, 3170, 3180, 3190, 3200, 3210, 3220, 3230, 3240, 3250, 3260, 3270, 3280, 3290, 3300, 3310, 3320, 3330, 3340, 3350, 3360, 3370, 3380, 3390, 3400, 3410, 3420, 3430, 3440, 3450, 3460, 3470, 3480, 3490, 3500, 3510, 3520, 3530, 3540, 3550, 3560, 3570, 3580, 3590, 3600, 3610, 3620, 3630, 3640, 3650, 3660, 3670, 3680, 3690, 3700, 3710, 3720, 3730, 3740, 3750, 3760, 3770, 3780, 3790, 3800, 3810, 3820, 3830, 3840, 3850, 3860, 3870, 3880, 3890, 3900, 3910, 3920, 3930, 3940, 3950, 3960, 3970, 3980, 3990, 4000, 4010, 4020, 4030, 4040, 4050, 4060, 4070, 4080, 4090, 4100, 4110, 4120, 4130, 4140, 4150, 4160, 4170, 4180, 4190, 4200, 4210, 4220, 4230, 4240, 4250, 4260, 4270, 4280, 4290, 4300, 4310, 4320, 4330, 4340, 4350, 4360, 4370, 4380, 4390, 4400, 4410, 4420, 4430, 4440, 4450, 4460, 4470, 4480, 4490, 4500, 4510, 4520, 4530, 4540, 4550, 4560, 4570, 4580, 4590, 4600, 4610, 4620, 4630, 4640, 4650, 4660, 4670, 4680, 4690, 4700, 4710, 4720, 4730, 4740, 4750, 4760, 4770, 4780, 4790, 4800, 4810, 4820, 4830, 4840, 4850, 4860, 4870, 4880, 4890, 4900, 4910, 4920, 4930, 4940, 4950, 4960, 4970, 4980, 4990, 5000, 5010, 5020, 5030, 5040, 5050, 5060, 5070, 5080, 5090, 5100, 5110, 5120, 5130, 5140, 5150, 5160, 5170, 5180, 5190, 5200, 5210, 5220, 5230, 5240, 5250, 5260, 5270, 5280, 5290, 5300, 5310, 5320, 5330, 5340, 5350, 5360, 5370, 5380, 5390, 5400, 5410, 5420, 5430, 5440, 5450, 5460, 5470, 5480, 5490, 5500, 5510, 5520, 5530, 5540, 5550, 5560, 5570, 5580, 5590, 5600, 5610, 5620, 5630, 5640, 5650, 5660, 5670, 5680, 5690, 5700, 5710, 5720, 5730, 5740, 5750, 5760, 5770, 5780, 5790, 5800, 5810, 5820, 5830, 5840, 5850, 5860, 5870, 5880, 5890, 5900, 5910, 5920, 5930, 5940, 5950, 5960, 5970, 5980, 5990, 6000, 6010, 6020, 6030, 6040, 6050, 6060, 6070, 6080, 6090, 6100, 6110, 6120, 6130, 6140, 6150, 6160, 6170, 6180, 6190, 6200, 6210, 6220, 6230, 6240, 6250, 6260, 6270, 6280, 6290, 6300, 6310, 6320, 6330, 6340, 6350, 6360, 6370, 6380, 6390, 6400, 6410, 6420, 6430, 6440, 6450, 6460, 6470, 6480, 6490, 6500, 6510, 6520, 6530, 6540, 6550, 6560, 6570, 6580, 6590, 6600, 6610, 6620, 6630, 6640, 6650, 6660, 6670, 6680, 6690, 6700, 6710, 6720, 6730, 6740, 6750, 6760, 6770, 6780, 6790, 6800, 6810, 6820, 6830, 6840, 6850, 6860, 6870, 6880, 6890, 6900, 6910, 6920, 6930, 6940, 6950, 6960, 6970, 6980, 6990,

MATERIALS OR SUPPLIES NEEDED

2

63

MAINTANCE NEEDED

4

13

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

1 _____

MATERIALS OR SUPPLIES NEEDED

2 _____ 3 _____

MAINTANCE NEEDED

4 _____ 5 _____

ADDITIONAL COMMENTS OR REMARKS

6 _____

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 2-23-10

NAME Jim Bowyer

WORK PERFORMED

Took Harley & Travis Weldon to East Main Finish Out. ~~Removed~~
Laminar dust magnet, got Island mine, I have to return today belt.
checked 13 belt pump, 30
checked up Borey, outside
changed & washed filter at East Main
checked 1 South Opine
checked 1 South belt up at 23 Borey
had to go outside & take coal people to check 1 South belt
checked 1 South Opine
checked 14, 16, 18 & EM pumps
gave lesson

MATERIALS OR SUPPLIES NEEDED

2	3

MAINTANCE NEEDED

4	5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

MATERIALS OR SUPPLIES NEEDED

2

3

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT Day

DATE 2-24-10

NAME Jim Bowyer

WORK PERFORMED

Put 4" check valve in line to pump off of 3 sec
Checked seals South side
Checked EM 1105 & #19 pump #30
Checked & ran pumps on 3 sec #14, 8, 16, 18
went to check check valve & help seal Brian & Greg with line
I took them outside
Checked magnet 2 XS
Took 2 Bottom rollers & hammers I took to 45 Bel on 1 South
Cleaned behind 3 sec, #1 tail up & dusted head area
Cleaned V-plane 1 south of low, then I tail
gilded from dustier at 1 South glow thru
checked 1 South splice
went to grease 3 sec #1 tail but it needs grease hose on
side & gutter in other
2 Pairs mid yet dust spray on 1 South
Finished

MAINTANCE NEEDED

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

MATERIALS OR SUPPLIES NEEDED

2

3

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT Day

DATE 3-1-10

NAME Jim Bowyer

WORK PERFORMED

Took Rick & Ben to Phuley Run start of shift
Dug out 2 fire lanes. Saw construction area
checked rollers of old 4 section
changed 4 washed rollers at E Main
checked 1st 2 rollers 2 places at 2d Bld on 3rd #1
checked on water sprayer on 3rd #1 belt
checked 4 rollers at 1 South
checked Bottom Roller 3d Bld on 1 North
checked 4 rollers at 1 North head
checked 4 rollers
Finished

MATERIALS OR SUPPLIES NEEDED

1. Good work done at 1 South tail, ~~and~~ East Main Punch Out

MAINTANCE NEEDED

1. Good roller made in 1 South

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

MATERIALS OR SUPPLIES NEEDED

2 _____	3 _____
_____	_____
_____	_____
_____	_____

MAINTANCE NEEDED

4 _____	5 _____
_____	_____
_____	_____
_____	_____
_____	_____

ADDITIONAL COMMENTS OR REMARKS

6 _____

PERFORMANCE COAL
BELT REPORT

MINE USE

SECTION

SHIFT DAY

DATE 3-2-10

NAME: Jim Bouyer

WORK PERFORMED

Took Ave base Report
Took Sam down to work area
Checked Spine dressed 14-20 scale Dancers
Took Shelly to EM quick out
Checked EM 110's, #14, 8, 16, 18, 19, 30 yamps
Checked and hung at site roll 3 on #1 at 17 But
Shuffled 17-18 but on opposite 3 #1 butt
Checked 3 on #1 tail
Checked #1 South Spine
emptied magnet
of chancery.

MATERIALS OR SUPPLIES NEEDED

1. Special work dust EM quick out #1 South tail

MAINTANCE NEEDED

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

MATERIALS OR SUPPLIES NEEDED

2 _____	3 _____
_____	_____
_____	_____
_____	_____

MAINTANCE NEEDED

4 _____	5 _____
_____	_____
_____	_____
_____	_____
_____	_____

ADDITIONAL COMMENTS OR REMARKS

6 _____

PERFORMANCE COAL
BELT REPORT

MINE USB

SECTION

SHIFT Day

DATE 3-3-10

NAME Jim Bowyer

WORK PERFORMED

Put water down before section under on Trip 11 start of shift
checked #192 LEM-110's
checked South Sash
changed pushed gitter at East Main
checked 1 South Sash
shovelled dust from 3 section to 1 South tail gitter
and my dust at tail
pushed up back at mouth of 3 section
went to Dallas Island put in on 1 South Main and there
checked #14, 8, 16, 16, 30 yards
spun down
cleaned up spillage entry South tail

MATERIALS OR SUPPLIES NEEDED

1 Good coal dust 3 section #1 head
#1 South tail
East Main Punch Out

MAINTANCE NEEDED

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE USB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

MATERIALS OR SUPPLIES NEEDED

2

3

MAINTANCE NEEDED

4

5

ADDITIONAL COMMENTS OR REMARKS

PERFORMANCE COAL
BELT REPORT

MINE UBB

SECTION

SHIFT

DATE

NAME

WORK PERFORMED

MATERIALS OR SUPPLIES NEEDED

2 _____	3 _____
_____	_____
_____	_____
_____	_____

MAINTANCE NEEDED

4 _____	5 _____
_____	_____
_____	_____
_____	_____
_____	_____

ADDITIONAL COMMENTS OR REMARKS

