

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Electrical		3. Date/Time of Accident 04/09/2016 02:03 PM		4. Date/Time of Death 04/10/2016 11:35 PM		5. Fatal Case No 4	
6. Mine Information :									
a) Mining Company Name Freeport-McMoRan Safford Inc			b) Mine Name Freeport-McMoRan Safford Inc			c) Parent of Mining Company Freeport-McMoRan Inc			
7. Mine Location :		a) City Safford	b) County Graham	c) State AZ	8. Mine ID Number: 02-03131		9. Union: NO		
10. Primary Mineral Mined: COPPER ORE MINING, N.E.C.		11. Number of Mine Employees:	a) Total 697	b) Underground 0	c) Open Pit/Quarry 267	d) Mill/Prep Plant 294	e) Other 136		
12. Contractor Name:					13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City	b) County		c) State	d) Zip Code			
16. Number of Contractor Employees:		a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:				
a) Mine Employees: 90		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0		
19) Location of Accident								20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 07-Advance Mining	<input checked="" type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)	Feet	Inches	
<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 09-Office Facility	21. Nonfatal Injuries: 0	22. Fatal Injuries: 1						
23. Victim Information :									
a) Name Bryan A. Ortiz			b) Age 25						
c) Regular Job Title: Hydromet EW Operator I				d) Activity at Time of Accident: Priming Pump			<input checked="" type="checkbox"/> Mine Employee		
24. Experience :		Years Weeks Days	Years Weeks Days	Years Weeks Days	Years Weeks Days	Years Weeks Days	Years Weeks Days		
a) Total:	4	46	0	b) at the mine:	4	46	0	c) at activity (23d):	4 11 0
d) with Contractor:	0	0	0						
25. Autopsy Performed: If Yes, Location					26. Mine Telephone No.: (928) 792-5824				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):  
 The victim was tasked with priming a diaphragm pump located outside the stripping machine, adjacent to the hydraulic room. The victim was found unresponsive, kneeling with his faced against the stainless steel flange of the return HDPE pipe with his knee contacting damp pavement. CPR was administered. The victim appears to have received electrical shock. The victim was removed from life support on April 10, 2016.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:			29. Model:		
30. District: M6000 Rocky Mountain		32. Field Office: Mesa North AZ			33. Event Number: 6696158
34. Accident Investigator: Lee Hughes		35. MSHA Person Notified: James Eubanks		Date 04/09/2016	Time 02:16 PM
36. Type of Report: Amended	37. Name of Preparer and Date Prepared: Pete Del Duca				Date 04/10/2016
38. Reason For Amendment: Victim was removed from life support and has deceased.					