

METAL / NONMETAL

Near Miss Accident

Surface Sand & Gravel - May, 2015 - An inspection party walked up the wood plank walkway to inspect the conveyor head pulley. As they started back down a section of the walkway unexpectedly dropped out from beneath the miner leading the the party. He escaped the 30 foot fall to the ground by holding onto the handrail.



Best Practices

- Examine your work places for all possible hazards and correct them before you perform work.
- Conduct structural inspections periodically.
- Look, listen & feel for abnormalities in walkways.

