19. Type of Inspection

(activity code)

22. Signature

20. Event Number

E16

Patrick Alan Stanfield



Mine Citati	on/Order				U.S. Department of Labor Mine Safety and Health Administration					
Section I-Viola	tion Data				<u>,</u>			· ·		
1. Date	Mo Da Yr 12/06/2011	2. Time (24 H	r. Clock) 0800		. 1	3. Citation/ Order Number	49002	75		
4. Served To	-	-		5. Operator						
Berman Co	ornett (Safety D	irector)			MANCE CO	AL COMPANY	, et al			
6. Mine UPPER BI	G BRANCH M	INE-SOUTH	[7. Mine ID	7. Mine ID 46-08436 (Contractor)					
8. Condition of								Notice (103g)		
not being (1) the enclose (2) instructer being so (3) the power of are brown	ing mainta e cutter mare. The side the X motor cir supported e XP enclo conductors oken and t	ined in otor cir handle to P enclos cuit bre by the wore on are con he XP en	r (serial # a safe operarult breaker or reset the lure on the oaker, the 12 iring for the the off-side nected is not closure is ling from the	ting cond: cannot be breaker ha ff-side o: 0 volt RC e relay. of the ma t securely	ition; e reset as bolts f the ma V relay achine w y mounte de the c connect	from outsi missing i chine cont is not mou here the cont mou ompartment the antenn	de the n the aining nted. utter unting . a to t	XP mechanism. the It is motor bolts		
	Other	OI ACC		The 50 Of IX		75.512				
Section IIInspe	ector's Evaluation									
B. Injury o	r Illness (has) (is): r illness could rea- be expected to be	No Likelihood No Lost W		Reasonably orkdays Or Restric		Highly Llkely Permanently Disa	Occurr	red ☐ Fatal ✓		
	ant and Substantia		No 🗌			D. Number of Perso	ons Affected:	008		
11. Negligeno	ce (check one)	A. None	B. Low 🗌 🤇	C. Moderate	D. High	E. Reck	less Disrega	rd 🗸		
12. Type of A	ction 104(d)(2	2)	13. Type of Issu	ance (check one)	Citation	Order 🗸 Safe	eguard 🗍	Written Notice		
14. Initial Act		C. Safeguard [D. Written Notice	E. Citation/ Order Nun	nber 80	082692	F. Dated	Mo Da Yr 03/17/2009		
15. Area or E	ر quipment	oy conti	nuous miner	(serial #	JM5811)					
16. Terminati	on Due A. Date	Mo Da Yr	B. Time (24 Hr. Cloo	ck)						
Section IIITerr	mination Action		i				· · · · · · · · ·			
17. Action to	Terminate									
18. Terminate	A. Date Mo	Da Yr	Fime (24 Hr. Clock		-1					
Section IVAut	I omated System Data									

MSHA Form 7000-3, Apr 08 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency established a National Small business and Agliculture Regulatory Ombudsman and To Regional Fairness Boards to receive comments from small businesses about rederin a gency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

4440348

21. Primary or Mill

23. AR Number

23908

Mine Citation/Order Continuation

U.S. Department of Labor Mine Safety and Health Administration



Section ISubsequent Action/Continuation Data						
1. Subsequent Action 1a. Continuation	2. Dated (Original Issue)	Мо 12/0	Da Yr 5/2011	3. Citation/ Order Number 4900275		
4. Served To		5. Opera	5. Operator			
Berman Cornett (Safety Director)		PERF	PERFORMANCE COAL COMPANY, et al			
6. Mine		7. Mine	7. Mine ID 46-08436 (C			
UPPER BIG BRANCH MINE-SC	UIR		10 00 100			
Section II Justification for Action						

Continuation of 8. Condition or Practice

receiver (off machine component).

- (5) the 3/0 trailing cable is not properly bushed at the XP enclosure where the cable is attached to the machine. The individual conductors are all that are protruding through the packing gland.
- (6) The cable from the receiver to the antenna is not long enough to connect to the antenna. This is a remote controlled machine.

An agent of the operator has failed to make an adequate weekly electrical examination of the Joy continuous miner, model 12CM12 (serial #JM5811 located on the HG22 section) for the week prior to 04.05.2010. Numerous citations are issued for this machine that should have been detected during the examination. Some of the cited conditions have existed for a significant amount of time.

The following citations are issued affecting the safe operation of the machine;

- (1) Order #4900271 is issued citing 30 C.F.R. Part 75.503 for failure to maintain the equipment permissible,
- (2) Citation #4900274 is issued citing 30 C.F.R. Part 75.907 for failure to ground the shielding of the medium voltage trailing cable.

This machine is located in an area affected by an explosion on 04.05.2010. The Operator is issued a large number of similar citations/Orders, upon inspection of the underground electrical equipment, following an explosion. This mine is currently on a 103(i) spot for methane liberation. The machine is used inby the last open crosscut and returns. This increases the necessity of maintaining the approved permissible equipment in a safe and approved condition.

The Operator has engaged in aggravated conduct constituting more than ordinary negligence. This is an unwarrantable failure to comply with a mandatory standard.

This citation is being issued to the following entities as a unitary operator: Performance Coal Company, Massey Coal Services, Inc., A.T. Massey Coal Company, Inc., and Massey Energy Company.

									See Continuation Form	
Section IIISubsec	quent Action Take	'n								
8. Extended To	A. Date Mo	Da	Yr	B. Time (24	Hr. Clock)		C. Vacated	D. Terminated	E. Modified	
Section IVInspec	tion Data		,	•						
9. Type of Inspe	ection E16		10. E	vent Numbe	4440348					
11. Signature			1.		AR Number	12. Date	Mo Da Yr	13. Time (24 Hr. Cl	ock)	
Patrick Alan Stanfield					23908		12/06/2011	12/06/2011 0800		