

## DAILY COVER SHEET

Date 1-9-7 Event No. 4116857

Arrived at the Mine \_\_\_\_\_ Departed from the Mine \_\_\_\_\_

List Records Books Checked gro-shiteon 58-79

Accompanied By: Company Representative \_\_\_\_\_

Woodell WIP

Miners Representative \_\_\_\_\_

Nile

## AREAS OF INSPECTION ACTIVITY:

Inspector's Initials \_\_\_\_\_

Supervisor's Initials and Date \_\_\_\_\_ Page No. 1

\*U.S. Government Printing Office: 1997 - 508-470

Date 1-9-7

25.400 0855  
Loose Coal 1" to 40"  
is present under  
NO. 1 2RB belt  
beginning at the belt head  
and extend to the  
tail piece for a distance  
of 75'

Due 1-10-7 - 0800

Person would be  
injury if Re below  
was to catch fire

Inspector's Initials \_\_\_\_\_

Supervisor's Initials \_\_\_\_\_

Page No. 2

\*U.S.G.P.O.: 2001 - 609-238

Date 1-9-7

25.410 0900  
Electrical dust  
is allowed to be present  
under the frame and  
electrical equipment  
at B-ND 2 RRB  
box, and B-BW,

Due 1-10-7 - 0800

sb. persons would  
be in injury if  
Re Floor Coal dust  
was to ignite  
when entering B-BW

Inspector's Initials \_\_\_\_\_

Supervisor's Initials \_\_\_\_\_

Page No. 3

\*U.S.G.P.O.: 2001 - 609-238

Date 1-9-7

25.360H 0915  
up to date, data  
time and initial  
is not present at  
the NO. 2 RRBs,

Due 1-10-7  
1400

C-1000  
sb. persons would  
not be in injury from  
this violation

Inspector's Initials \_\_\_\_\_

Supervisor's Initials and Date \_\_\_\_\_

Page No. 4

\*U.S.G.P.O.: 2001 - 609-238

Date 1-9-7

25.400 0910  
Loose Coal is present  
in the NO. 2 belt head  
and tail (partially up)  
again in the bottom belt  
extending to B-18

Due 1-10-7  
0800

sb. persons would be  
in injury if they was  
to catch fire

Inspector's Initials \_\_\_\_\_

Supervisor's Initials \_\_\_\_\_

Page No. 5

\*U.S.G.P.O.: 2001 - 609-238

Date 1-9-7

25.360E 0915  
up to date, data  
time and initial  
is not present and  
NO. 2 belt head

Due 1-10-7  
1400  
C-1000

sb. persons would  
not be in injury if  
the floor this  
violation

Inspector's Initials \_\_\_\_\_

Supervisor's Initials \_\_\_\_\_

Page No. 6

\*U.S.G.P.O.: 2001 - 609-238

Date 1-9-7

75.202A 0930

The Coal Rib at the  
 The No 3 EUGAS 30"  
 L.B. main is GAPPED  
 out for 140 ft. beginning  
 on the west side of the  
 box and extending  
 into the cross at  
 for 20 ft.

Due 1-9-7-140

8b. persons would be  
 injured if the  
 rib was to roll off

Inspector's Initials

Supervisor's Initials and Date

Page No. 2  
U.S.G.P.O.: 2001-609-238

Date 1-9-7

75.1225 0940

The No 3 EUGAS 30"  
 The bottom roller  
 and the No 2 roller  
 head, is bad.

Due 1-9-7  
 120  
 C-1130

8b. persons would be  
 injured if the  
 bottom roller  
 beat up and catch  
 the coal on fire.

Inspector's Initials

Supervisor's Initials and Date

Page No. 8  
U.S.G.P.O.: 2001-609-238

Date 1-9-7

75.701 0950

The Grandstand  
 is not quite better  
 being changed at  
 the section of the  
 being started at  
 the speed, 20944

Due 1200

0-1100

8b. persons would  
 be injured if  
 the grandstand  
 started to move.

Inspector's Initials

Supervisor's Initials and Date

Page No. 9  
U.S.G.P.O.: 2001-609-238

Date 1-9-7

75.523-361 1015

The emergency  
 battery, by the  
 No 1 scoop did  
 not activate immediately

Due 1-9-7  
 1400

8b. persons would  
 be injured if the  
 battery was starting to  
 at the scoop.

Inspector's Initials

Supervisor's Initials and Date

Page No. 10  
U.S.G.P.O.: 2001-609-238

Date 1-7-7

75.3424ii 1330

The operator is not  
 maintaining a record  
 indicating the  
 No 2 roller and main  
 DRO had been calibrated  
 at least once every  
 31 days

Due 1-10-9-1500

persons would not  
 be injured

Inspector's Initials

Supervisor's Initials and Date

Page No. 11  
U.S.G.P.O.: 2001-609-238

Date 1-09-07

Time-0745 HRS.

STAND - FIRE DRILL

75.883(b)(4)

THE LAST FIRE DRILL

WAS MADE ON 10-3-06.

FIRE DRILL WAS DUE

ON 11-3-07. FIRE DRILL

REQ'D EVERY 90 DAYS.

NOW - S &amp; S

# MEN - 10

TERM DUE - 1-10-07

WONDEL WILLS - SUPER.

8b - PERSONS WOULD

NOT BE INJURED

DUE TO NOT MAKING

A FIRE DRILL

Inspector's Initials

Supervisor's Initials and Date

Page No. 1  
U.S.G.P.O.: 2001-609-238

Date 1-9-07Time - 0905 HRS.

75.380(1)(1)

THE INTAKE ESCAPEWAY  
IS NOT BEING MAINTAINED  
IN A SAFE TRAVELABLE  
CONDITION IN THAT ACCUMULATION  
OF WATER 30' LONG X 20' W.  
@ CC #8, #10, #25 @  
DEPTHS OF 1"-13"

DUE - 1-10-07 @ 1000 HRS

8(b) - PERSONS COULD FALL  
BY TRIP/STUMBLE IN DEEP  
WATER CAUSING INJURY.

Inspector's Initials

Supervisor's Initials and Date 1-10-07 Page No. 2  
G20 U.S. GPO: 2006-543-041Date 1-9-07Time - 1100 HRS

75.514

THE POWER CABLE  
ON J. CAR-5N#17503 ON  
MMU 030 SECTION IS  
NOT BEING MAINTAINED  
IN A SAFE MECHANICAL  
AND ELECTRICAL CONDITION  
IN THAT 2 CABLE SPLICES  
WERE FOUND WITH  
LEADS EXPOSED.

DUE - 1-9-07 @ 1200 HRS.

Term - 1-9-07 @ 1130 HRS.

PERSONS COMING IN CONTACT  
WITH CABLE COULD BE ELECTROCUTED  
CAUSING

Inspector's Initials

Supervisor's Initials and Date 1-10-07 Page No. 2  
G20 U.S. GPO: 2006-543-041

## DAILY COVER SHEET

Date 1-10-2007 Event No. 4116857

Arrived at the Mine \_\_\_\_\_ Departed from the Mine \_\_\_\_\_

List Records Books Checked Prashita - belt book

Accompanied By: Company Representative

Miners Representative

AREAS OF INSPECTION ACTIVITY:

Inspector's Initials

Supervisor's Initials and Date 1-10-07 Page No. 1  
U.S. Government Printing Office: 1997 - 608-470Date 1-10-07

77.410 (a) (1) 0840

The backup alarm on the  
988 End loader did not function  
when tested

8b Miners are exposed to hazards by  
not being able to tell gear intention

J 1230

Inspector's Initials

Supervisor's Initials and Date 1-10-07 Page No. 2  
U.S. G.P.O. 2005-742-563Date 1-10-07

75.220 a 1 0945

The brock thaw opening at spool  
20' x 20' measuring 27' x 8"  
Bad ribs present throughout section  
p12 RCB

C.O. # 726 4923

8b - Miner would be exposed to  
causing injuries from rock fall or  
cib roll

Inspector's Initials

Supervisor's Initials and Date 1-10-07 Page No. 3  
U.S. G.P.O. 2005-742-563Date 1-10-07

0952  
DST  
The deceler on the 030 section  
guard over the chindole  
on the pick breaker was open  
allowing exposure to moving  
chain and gears 6" x 24"  
S/N 54.9187

75.1722 (a)

C.O. # 726 4924

8b Miners exposed to amputation  
type injuries

Inspector's Initials

Supervisor's Initials and Date 1-10-07 Page No. 4  
U.S. G.P.O. 2005-742-563

Date 1-7-07

75.573

1022

2 lights on the outside of  
the right holder one inoperative  
2 lights on the opposite side of  
the right holder one inoperative

C. 7264925

As no injury would result  
from this violation.

Inspector's Initials

Supervisor's Initials and Date

M. 7

Page No. 5

U.S. G.P.O. 2005-742-593

## DAILY COVER SHEET

Date 1-16-7 Event No. 4116857

Arrived at the Mine Departed from the Mine

List Records Books Checked pro-shit

Accompanied By: Company Representative

Miners Representative

## AREAS OF INSPECTION ACTIVITY:

Inspector's Initials

Supervisor's Initials and Date

M. 7

Page No. 1

\*U.S. Government Printing Office: 1997 - 508-470

Date 1-16-7

25.37291

1000

The revision that  
was submitted in  
response to PIR  
no. 04-11, was denied  
by letter dated 11-5-6  
a corrected plan  
was to be submitted  
to mine within  
10 days of your  
receipt of the  
denial. To date  
a corrected copy  
has not been received

Due 1-25-6  
0800

Person would have  
injury

Inspector's Initials

Supervisor's Initials and Date

M. 7

Page No. 2

\*U.S. G.P.O.: 2001 - 609-238

## DAILY COVER SHEET

Date 1-22-7 Event No. 4116857

Arrived at the Mine Departed from the Mine

List Records Books Checked pro-shit/ow

Accompanied By: Company Representative

Miners Representative

## AREAS OF INSPECTION ACTIVITY:

Inspector's Initials

Supervisor's Initials and Date

M. 7

Page No. 1

\*U.S. Government Printing Office: 1997 - 508-470

Date 1-22-7

25.2229  
no 3 0900  
no 2 0900  
2000 in loose air  
Gipped out to 4  
presence of 1000

Due 1-22-7  
1000

C. 1100

8h person was  
beginning to work  
if person was to  
roll off onto person  
walking along the  
track

Inspector's Initials

Supervisor's Initials and Date

M. 7

Page No. 1

\*U.S. G.P.O.: 2001 - 609-238

## DAILY COVER SHEET

Date 1-30-7 Event No. 4116857

Arrived at the Mine Departed from the Mine

List Records Books Checked pro-shit

Accompanied By: Company Representative

Miners Representative

## AREAS OF INSPECTION ACTIVITY:

Inspector's Initials

Supervisor's Initials and Date

M. 7

Page No. 1

\*U.S. Government Printing Office: 1997 - 508-470

Date 1-30-07  
75.202 0915  
On 1-28-07, has 4072  
50 foot bits, were the  
Mine roof Fall from  
ground the plate  
Person in this incident

On 2-13-7 102  
4 3-wires  
5, pre-shift examined  
8b. persons would  
be injury. 2nd  
was to Fall.

Inspector's Initials

Supervisor's Initials and Date

Page No. 2

GPO U.S. GPO: 2008-543-041

Date 1-30-07  
75.380-01 0930  
The intake of Pipe was  
off at mine 09  
beginning at 230114  
and continuing to 102  
is not being maintained  
in rate collection  
log and has accumulators  
in the warehouse. 101  
Ref.

On 2-13-7  
4 3-wires  
5, pre-shift examined  
8b. persons would  
be injury. 2nd  
was to Fall.

Inspector's Initials

Supervisor's Initials and Date

Page No. 3

GPO U.S. GPO: 2008-543-041

Date 1-30-07  
75.5501 1020  
non-permissible Jack  
hammer and non Perm  
110V. Elect. Plug  
is on the table.

C-1045  
4, 8 ft  
5, unprovoked  
8b. persons would  
be injury. 2nd  
was to Fall.

Inspector's Initials

Supervisor's Initials and Date

Page No. 4

GPO U.S. GPO: 2008-543-041

Date 1-30-2007 1108hrs  
The 4466k pump (100A) does not  
have a device to prevent the cord from  
being plugged into a 225A  
box.  
This is a 4466k KVA box

1 person would be exposed to  
an extremely shocking shock hazard

It is likely the same accident  
was prevented if the pump  
was plugged into the wrong  
box.

The pump requires - should  
have been noticed during  
weekly electrical exam.

Inspector's Initials

Supervisor's Initials and Date

Page No. 2

GPO U.S. GPO: 2008-543-041

Date 1-30-07  
75.410 1115  
Flat Coal is allowed  
to accumulate on  
the floor and floor  
components of the  
KVA Box at 4466k  
on No. 5 belt

On 1-31-7  
0800

4, Two days  
5, pre-shift examined  
8b. persons would  
be injury. 2nd  
was to Fall.

Inspector's Initials

Supervisor's Initials and Date

Page No. 3

GPO U.S. GPO: 2008-543-041

Date 1-31-7  
75.360-01 1145  
an 4466k pump  
pre-shift examined  
on the KVA Box at  
BR 44 on No. 5 belt  
condition was poor  
at Flat Coal  
dust in the box  
dust was not reported  
in the pre-shift  
exam.

On 1-31-7 1140  
4, 8 ft

5, pre-shift examined  
8b. persons would  
be injury. 2nd  
was to Fall.

Inspector's Initials

Supervisor's Initials and Date

Page No. 4

GPO U.S. GPO: 2008-543-041

Date 1-30-7

75.17284

7140

The 400Volt  
power supply for  
the No. 4 Take-up  
is not being main-  
tained in safe operation  
(redaction). The  
door are not secured  
allowing person  
to come in contact  
with the energized  
components.

Call 1-30-7 1200  
1-1150

is unknown, 3, fire shift  
ex animal, 3, person, was to  
be in injury if the door  
to reach into the box.

Inspector's Initials  
Supervisor's Initials and Date MT 1-7 Page No.  
GPO U.S. GPO: 2008-543-041

Date 1-30-7

75.515

1150

The power cable  
entering the place  
for the 400V but have  
4 inch pump is not  
to be 6 inch  
One 1-30-7  
1400

4, unknown  
3, unknown  
8, person would  
be in injury if the  
to pull on the  
cable, causing it  
pull power leads from  
the connectors.

Inspector's Initials  
Supervisor's Initials and Date MT 1-7 Page No.  
GPO U.S. GPO: 2008-543-041

## DAILY COVER SHEET

Date 2-6-7 Event No. 4116857

Arrived at the Mine Departed from the Mine

List Records Books Checked go - 5th floor  
shift

Accompanied By: Company Representative

Wickell Wicks  
Miners Representative NON

## AREAS OF INSPECTION ACTIVITY:

Inspector's Initials  
Supervisor's Initials and Date MT 1-7 Page No. 1  
\*U.S. Government Printing Office: 1997 - 508-470

Date 2-6-7

75.202a 1030

The mine cart  
in the intake for  
009 beginning at the  
lot and extend to  
the 103, the cart is  
broken with outside  
wires left and  
right rib out.

Due 2-13-7.  
0400

unknown  
5 days  
8, person traveling  
the 500V  
would be in injury from  
the cart falling

Inspector's Initials  
Supervisor's Initials and Date MT 1-7 Page No. 2  
\*U.S. GPO: 2001-529-233

## DAILY COVER SHEET

Date 2-20-7 Event No. 4116857

Arrived at the Mine Departed from the Mine

List Records Books Checked present

Accompanied By: Company Representative

Miners Representative NONE

## AREAS OF INSPECTION ACTIVITY:

Inspector's Initials  
Supervisor's Initials and Date MT 1-7 Page No.  
\*U.S. Government Printing Office: 1997 - 508-470

Date 2-20-7

75.57001 1400

Page 1 of the approved  
methane and dust control  
plan for the 041-0, it is not  
being compliance with  
the operator is required  
to check the  
scrubber valuer  
weekly and record  
if any the pre-check  
board, no record  
could be found.

Due 2-20-2  
2000

8, person would not  
be in injury from this  
falling

Inspector's Initials  
Supervisor's Initials and Date MT 1-7 Page No. 2  
GPO U.S. GPO: 2008-543-041

Date 2-20-7

75.400

1630

Loose coal 1" to 10  
inches on one side  
bolt, head to tail  
under bolt and on the  
outside.

Dec 2-21-7  
1400

8b persons would be  
injury if the belt  
was to catch fire

Inspector's Initials

Supervisor's Initials and Date

Page No. 3  
GPO U.S. GPO: 2006-543-041

Date 2-19-7

75.400

1630

Loose coal No 2  
bolt from head  
to 3' head 1" to  
2' BL under bolt  
and on off side

Dec 2-21-7  
1400

8b persons would  
be injury if the  
belt was to catch  
fire

Inspector's Initials

Supervisor's Initials and Date

Page No. 4  
GPO U.S. GPO: 2006-543-041

Date 2-20-7

75.22001

1630

Page 6 of the  
approved safety plan  
is his been  
compliance with  
in the No. 4 entry  
on 11/10/04 at 5:10  
21017, the 4170 plan  
was measured 28 ft  
below the plan.

Dec 2-20-7-1700

8b. 8b persons will  
be injury if the  
the vib on it was to  
fall.

Inspector's Initials

Supervisor's Initials and Date

Page No. 5  
GPO U.S. GPO: 2006-543-041

8436

Date 2-20-7

75.519

1645

The power cable  
to the No. 2 Rout  
bolt is not proper  
brushed.

Dec 2-20-7  
1800

C-1650

8b person would  
be injury from  
electrical shock.

Inspector's Initials

Supervisor's Initials and Date

Page No. 6  
GPO U.S. GPO: 2006-543-041

## DAILY COVER SHEET

Date 2-25-7

Event No. 4114957

Arrived at the Mine

Departed from the Mine

List Records Books Checked

ON SITE

Accompanied By: Company Representative

Miners Representative

NONE

AREAS OF INSPECTION ACTIVITY:

Inspector's Initials

Supervisor's Initials and Date

Page No. 1

U.S. Government Printing Office: 1997 - 508-470

Date 2-25-6

75.904

1610

The circuit breaker  
for the RETURN Pump  
at the #2 section  
belt PVA is not  
identified.

Dec 2-25-7  
1400

4 UNPROW

3 UNPROW 1-day

8b persons would be  
injury if the wiring  
breaker was energized.

Inspector's Initials

Supervisor's Initials and Date

Page No. 2  
GPO U.S. GPO: 2006-543-041

Date 2-24-7

75.504 1013  
 The Circuit breaker  
 for the No. 15 lamp  
 charger at the 2  
 section belt runbar  
 is not identified.

Dec 2-25-7  
 1400

4. UNKNOWN  
 5. 1-24K  
 8. Persons would be  
 involved if the wiring  
 break it was energized.

Inspector's Initials

Supervisor's Initials and Date 2-26-7 Page No. 3  
 GPO U.S. GPO: 2008-543-041

Date 2-25-7

75.400 1015  
 The No. 2 Section  
 belt runbar has  
 float cord on  
 the floor and  
 electrical components  
 at

Dec 2-28-7  
 0500

4. UNKNOWN  
 5. Two days since  
 8. Persons would be  
 involved if the float  
 cord just was to  
 ignite

Inspector's Initials

Supervisor's Initials and Date 2-26-7 Page No. 4  
 GPO U.S. GPO: 2008-543-041

Date 2-25-7

75.360 1012  
 A maintenance plan  
 with elimination  
 has been conducted  
 on the 2nd section  
 belt runbar.

Dec 2-25-1400

4. UNKNOWN  
 5. UNKNOWN  
 8. Persons working  
 in the area could  
 be involved from before  
 not recorded, or  
 reported.

Inspector's Initials

Supervisor's Initials and Date 2-26-7 Page No. 5  
 GPO U.S. GPO: 2008-543-041

Date 2-25-7

75.400 1130  
 Loose coal 1' to 15'  
 is present on the  
 belt conveyor, from  
 front to the belt  
 head.

Dec 2-28-7  
 1400

4. UNKNOWN  
 5. 5-days  
 8. Persons could be  
 involved if the loose  
 coal, dust was  
 to catch fire, or  
 the bottom rollers  
 rolling in the coal.

Inspector's Initials

Supervisor's Initials and Date 2-26-7 Page No. 6  
 GPO U.S. GPO: 2008-543-041

Date 2-25-7

75.1765 1055  
 [REDACTED]  
 was not checked out  
 on the check-in-out  
 board.

Dec 2-25-7  
 0-1055

4. UNKNOWN  
 5. 3 days  
 8. Persons would be  
 involved from this  
 violation.

Inspector's Initials

Supervisor's Initials and Date 2-26-7 Page No. 7  
 GPO U.S. GPO: 2008-543-041

## DAILY COVER SHEET

Date 3-6-07 Event No. 4116857

Arrived at the Mine ☒ Departed from the Mine ☒

List Records Books Checked ON-SHIFT

PRE-SHIFT

Accompanied By: Company Representative

Bill Haeless - MFW  
 Rick Hodge - Suft,  
 Miners Representative

## AREAS OF INSPECTION ACTIVITY:

- ① UBB #2 SECTION
- ② 041 MMU/040 SECTION
- ③ Permissibility and FEEDER
- ④ #2 SHUTTLE CAR
- ⑤ #3 " "
- ⑥ RT. Roof Bolter
- ⑦ #1 SHUTTLE CAR
- ⑧ RT. MINER

Inspector's Initials

Supervisor's Initials and Date 3-7-07 Page No. 8



Date 3-6-07Time - 1040 HRSSTAND - 75.1103-7(A)

THE Cont. Miner  
JM #5633 on mmu  
041-0 SECTION did not  
HAVE A FUNCTIONAL  
BATTERY BACKUP FOR  
ACTUATING FIRE  
SUPPRESSION WHEN THE  
POWER WAS DE-energized

EXPOSURE - PERSON EXPOSING  
TO FIRE AND/OR SMOKE  
C.M. ON FIRE

Term 0800 - 3-7-07  
DUE

Inspector's Initials

Supervisor's Initials and Date

MS 3-7-7

Page No.

U.S. G.P.O. 2005-742-563

Date 3-6-7#1 SC - ET16880Time - 1100 AMSTAND - 75.514

BAD splice on  
CABLE - LEADS EXPOSED

Term - 1110 AM

Taped splice

THE Jay 105C SER. #ET16880  
on mmu 041/040 SECTION  
HAD A TRAILING CABLE  
splice with power  
conductors exposed.

PERSON EXPOSED TO  
ELECT. SHOCK,

Inspector's Initials

Supervisor's Initials and Date

MS 3-7-7

Page No.

U.S. G.P.O. 2005-742-563

Date 3-6-07Time - 1135STAND - 75.503

RT SIDE FRAM

LITE NOT WORKING

#2 Bolter

SER. #2003339

LT SIDE NER OP,

CAB

75.1719-TA) 75.503

THE ROOF Bolter Ser.

#2003339 on mmu 041/040

HAS TWO LIGHTS

NOT WORKING.

Term 0800 - 3-7-07

DUE

NOW S.S.

5 LIGHTS WORKING

UNLIKELY ABOUT IT WOULD

HAPPEN,

Inspector's Initials

Supervisor's Initials and Date

MS 3-7-7

Page No.

U.S. G.P.O. 2005-742-563

8436

## DAILY COVER SHEET

Date 3-7-07Event No. 4116857

Arrived at the Mine

Departed from the Mine

List Records Books Checked

WEEKLY FILES,

ON SHIFT, PRE-SHIFT

Accompanied By: Company Representative

Rick Hodge - Supv.

Bill Harless - MPM

Miners Representative

## AREAS OF INSPECTION ACTIVITY:

- ① mmu 041/040 - Equipment
- Fork Lift/CHARGER
- #2 Scoop/CHARGER
- Left Roof Bolter
- #1 Scoop/CHARGER
- MAINT. Scoop
- Right Roof Bolter

Inspector's Initials

Supervisor's Initials and Date

MS 3-7-7

Page No.

U.S. Government Printing Office: 1997 - 508-470

Date 3-7-07Time - 1005 HRSSTAND - 75.816

ON mmu 040/041 SECTION  
THE HI-VOLTAGE CABLE  
WAS NOT GUARDED AS  
THE HI-VOLT CABLE SLED  
THE MEASURED HT.  
OF CABLE FROM FLOOR  
TO CABLE WAS 5.5 FT.  
DUE - 1030 HRS  
Term @ 1015 HRS

EXP - PERSON EXPOSED  
TO UNGUARDED HI-VOLT.  
CABLE ELECT. SHOCK AND  
AT THAT HEIGHT WOULD  
COME IN CONTACT,

Inspector's Initials

Supervisor's Initials and Date

MS 3-7-7

Page No.

GPO U.S. G.P.O. 2006-543-041

Date 3-7-07Time - 1110 HRSSTAND - 75.701

ON mmu 040/041 SLED  
NO GROUND CLAMP  
WAS ATTACHED FROM  
#2 Scoop TO CHARGER

DUE @ 1115 HRS

Term @ 1112 HRS

EXP - PERSON EXPOSED  
TO ELECT. SHOCK. SECTION  
& AREA IS WET.

Inspector's Initials

Supervisor's Initials and Date

MS 3-7-7

Page No.

GPO U.S. G.P.O. 2006-543-041

## DAILY COVER SHEET

Date 3-14-7 Event No. 4116887Arrived at the Mine        Departed from the Mine       List Records Books Checked Pre-shift

Weeply Air way base

Accompanied By: Company Representative

Miners Representative

AREAS OF INSPECTION ACTIVITY:

Inspector's Initials

Supervisor's Initials and Date 3-14-7 Page No. 1

U.S. Government Printing Office: 1997 - 508-470

Date 3-14-7

75.36441 0730  
 The mine roof is not being  
 supported by the main roof  
 NO RECORD COULD BE  
 FOUND.

Doc 3-14-7  
 1100  
 0-2000  
 4 UNKNOWN  
 5 UNKNOWN  
 8 PERSONS WOULD BE  
 INJURED FROM THIS  
 VIOLATION

Inspector's Initials

Supervisor's Initials and Date 3-14-7 Page No. 2

GPO U.S. GPO: 2006-543-041

Date 3-14-7

75.2024 0840  
 The mine roof is  
 not adequately supported  
 by the main roof  
 at New Main.  
 Several roof bolts  
 are missing from  
 main roof. Fallen  
 from around New  
 The coal rib on the  
 upper way side of  
 partition in  
 several locations  
 is broken and supports  
 are missing.  
 Doc 3-14-7 1600

Inspector's Initials

Supervisor's Initials and Date 3-14-7 Page No. 3

GPO U.S. GPO: 2006-543-041

Date 3-14-7

4. Examine  
 5. 5 days or more  
 8. Persons would be  
 injured from the  
 roof and rib falling

Inspector's Initials

Supervisor's Initials and Date 3-14-7 Page No. 4

GPO U.S. GPO: 2006-543-041

Date 3-15-7

75.2024 0850  
 The mine roof has  
 fallen from around  
 two of the roof bolts  
 in the main roof  
 of the main roof  
 of the main roof

Doc 3-15-7. 0800  
 4 UNKNOWN  
 5 UNKNOWN  
 8 PERSONS WOULD  
 BE INJURED IF THE  
 ROOF AND RIB FELL.

Inspector's Initials

Supervisor's Initials and Date 3-15-7 Page No. 5

GPO U.S. GPO: 2006-543-041

Date 3-15-7

75.2024 0900  
 The mine roof  
 leaning to the right  
 two persons could  
 be injured from the  
 main roof falling  
 from around  
 two of the roof bolts

Doc 3-15-7 0900  
 4 UNKNOWN  
 5 UNKNOWN  
 8 PERSONS WOULD BE  
 INJURED IF THE  
 ROOF AND RIB FELL.

Inspector's Initials

Supervisor's Initials and Date 3-15-7 Page No. 6

GPO U.S. GPO: 2006-543-041

Date

3-14-7

75.2026 1000

~~Root Fall~~

The Hard Gate 18  
CAN NOT be Travel  
IN ITS ENTIRETY.  
Root Fall has  
OCCURRED IN THE  
SECOND CROSS CUT  
OUT BY THE FALL  
IN 4 CROSS-CUT  
BETWEEN H-5 EXCUT  
AND OUTBY IN  
THE 4 ENTRY,

Dec 3-19-7  
0800

Inspector's Initials

Supervisor's Initials and Date

Page No. 7

GPO U.S. GPO: 2008-543-041

Date

3-14-7

4, UNKNOWN

5, UNKNOWN

8b. Persons would  
be injured if  
the Root was to  
CONTINUE TO FALL  
WITH OUT any  
ADDITIONAL ROOT  
SUPPORT.

Inspector's Initials

Supervisor's Initials and Date

Page No. 8

GPO U.S. GPO: 2008-543-041

Date

3-14-7

75.36461 1005

AT LEAST ONE  
OF THE INTER-  
FOR HARD GATE 18  
CAN NOT be Travel  
IN ITS ENTIRETY,  
ROOT FALL has OCCUR-  
BETWEEN PRE-  
4 AND 5 ENTIRE  
BLOCK TOWER #10

Dec 3-19-7-  
0800

4, UNKNOWN

5, UNKNOWN

8b. Persons would  
NOT be INJURY  
FALLING FROM THE

Inspector's Initials

Supervisor's Initials and Date

Page No. 9

GPO U.S. GPO: 2008-543-041

Date

3-14-7

75.602 1030

The 3500g Chaper  
One head is plug INTO  
a 100amp Breaker  
which can be pulled  
AND PLUG INTO  
a 225 AMP CIRCUIT  
BLOCK

Dec 3-14-7  
1100

C 1045

4, UNKNOWN

5, UNKNOWN

8b. Persons would be  
INJURY if One 100 amp  
Circuit was pulled  
IN THE

Inspector's Initials

Supervisor's Initials and Date

Page No. 10

GPO U.S. GPO: 2008-543-041

Date

3-14-7

75.523-351 1035

The emergency alarm  
was sounding on  
the floor 1 IN  
THE NEW DIRT  
ACTIVE IMMEDIATE  
WHEN ACTED BY  
AN INTERCOM  
DRIVER

Dec 3-14-7  
2000

4, UNKNOWN

5, UNKNOWN

8b. Persons would be  
INJURY if the Box  
was STOPPED IN THE  
STREET

Inspector's Initials

Supervisor's Initials and Date

Page No. 11

GPO U.S. GPO: 2008-543-041

## DAILY COVER SHEET

Date

Event No.

3-19-7 4116052

Arrived at the Mine

Departed from the Mine

List Records Books Checked

ON-SHIFT

Accompanied By: Company Representative

Miners Representative

None

## AREAS OF INSPECTION ACTIVITY:

- Family Travel

Inspector's Initials

Supervisor's Initials and Date

Page No.

\*U.S. Government Printing Office: 1997 - 608-470

Date 3-14-7

75.2026 1000

~~Root Fall~~  
 The ~~Root~~ <sup>Root</sup> ~~Gate~~ 18  
 cannot be travel  
 in its entirety.  
 Root Fall has  
 occurred in the  
 second crosscut  
 out by the face  
 in 4 cross-cut  
 between H-5 & H-6  
 and out by in  
 the 4 entry.

Dec 3-19-7  
 0800

Inspector's Initials

Supervisor's Initials and Date

MS 3-19-7 Page No. 7

GPO U.S. GPO: 2005-543-041

Date 3-14-7

4, UNKNOWN  
 5, UNKNOWN  
 8b, persons would  
 be injured if  
 the root was to  
 continue to fall  
 without any  
 additional root  
 support.

Inspector's Initials

Supervisor's Initials and Date

MS 3-14-7 Page No. 8

GPO U.S. GPO: 2005-543-041

Date 3-14-7

75.86461 1005  
 at least one  
 of the intake  
 for Hardgate 18  
 cannot be travel  
 in its entirety.  
 Root Fall has occurred  
 between the  
 4 and 5 entries  
 block time 11:00

Dec 3-19-7-  
 0800

4, UNKNOWN

5, UNKNOWN

8b, persons would

not be injured

from the intake

Inspector's Initials

Supervisor's Initials and Date

MS 3-14-7 Page No. 9

GPO U.S. GPO: 2005-543-041

Date 3-14-7

75.602 1030

The 35 comp charge  
 car head is plug into  
 a 100 amp breaker  
 which car be made.  
 and plug into  
 a 225 amp circuit  
 breaker

Dec 3-14-7  
 11:00

0 1045

4, UNKNOWN

5, UNKNOWN

8b, persons would be  
 injured if the 100 amp  
 car head was plugged  
 in.

Inspector's Initials

Supervisor's Initials and Date

MS 3-14-7 Page No. 12

GPO U.S. GPO: 2005-543-041

Date 3-14-7

75.523-351 1035

The emergency alarm  
~~button~~ <sup>button</sup> on  
 the hauler in  
 the new did not  
 activate immediately  
 when actuated by  
 the emergency  
 device

Dec 3-14-7  
 2000

4, UNKNOWN

5, UNKNOWN

8b, persons would be  
 injured if the rock  
 was stopped in time  
 at the hauler the  
 hauler was stopped

Inspector's Initials

Supervisor's Initials and Date

MS 3-14-7 Page No. 11

GPO U.S. GPO: 2005-543-041

TERMINATED OUTLINE  
 # 55-55

Timber was 5000  
 8:00

TERMINATED OUTLINE  
 # at 0900

Timber was 5000  
 under one two hundred  
 Fall on the 11 was  
 The fall was 1000  
 at 0936

Park's Block was 1000

1-1020

Date 3-19-7  
75.368 d3 1030

PA L APT 106  
DOOR INHIBITOR  
SWITCH did NOT  
FUNCTION APT 106  
DOOR OR DOOR WAS  
CLOSE.

Due 3-19-7  
1040

P-1038

4, UNKNOWN

5 UNKNOWN

th, persons would not  
be involved from this  
violation.

Inspector's Initials \_\_\_\_\_

Supervisor's Initials and Date \_\_\_\_\_

479-217

Page No. \_\_\_\_\_