## U. S. Department of Labor

Mine Safety and Health Administration 100 Bluestone Road Mount Hope, WV 25880-1000



OCT 16 2009

Mr. Berman Cornett Safety Director Performance Coal Company P.O. Box 69 Naoma, WV 25140

Dear Mr. Cornett:

Subject:

Supplement (6th) to the Roof-Control Plan, Upper Big Branch

Mine-South, I.D. No. 46-08436, Performance Coal Company,

Montcoal, Raleigh County, West Virginia,

Permit No. 4-RC-11-94-12307-11, approved October 25, 2005

Your supplement, received on October 14, 2009, to the roof-control plan, for a Block Shearing Plan, has been reviewed and cannot be approved as submitted. On February 17, 2009, a letter was sent informing you that the submitted plan update was denied and of the deficiencies in the submittal. Additionally, on August 21, 2009, a letter informing you that your plan was inadequate and contained several deficiencies was sent to you. Both of these letters informed you that no additional roof control plan supplement would be approved until an updated roof control plan for this mine was approved. To date these deficiencies have never been addressed.

This letter provides you with an opportunity to address the aforementioned deficiencies to the roof-control plan or the appropriate enforcement action may be taken. Please respond within 10-days from receipt of this letter.

Should you have any questions concerning this matter, please contact Don Winston at this office at (304) 877-3900 Extension 130.

Sincerely,

Robert G. Hardman District Manager

Coal Mine Safety and Health, District 4

Enclosure

cc:

Mount Hope Field Office (1 encl.)

Lee Barker (1 encl.)

Files/cls



## Performance Coal Company

P.O. Box 69

Naoma, WV

25140

October 13, 2009

Mr. Robert G. Hardman Mine Safety and Health Administration 100 Bluestone Drive Mount Hope, WV 25880

Re:

Performance Coal Company

Upper Big Branch Mine MSHA ID: 46-08436 State ID: U-3042-92 Block Shear Plan

Dear Sir:

Enclosed for your review and approval please find the block shear plan for the Upper Big Branch Mine.

Additional roof support will be installed in the area of the block being sheared prior to shearing. The additional support will include cribs and 50-ton Heintzman jacks or equivalent. Support locations are shown on the attached map.

If you have any questions or comments, feel free to contact me at (304) 854-3516.

Respectfully Submitted, Performance Coal Company, Inc.

Eric Lilly

Mine Engineer

