



Section I--Violation Data

1. Date Mo Da Yr 11/17/2013	2. Time (24 Hr. Clock) 0840	3. Citation/ Order Number 8754902
4. Served To Danny Woodruff-Safety Manager		5. Operator STAR MINE OPERATIONS, LLC
6. Mine REVENUE MINE		7. Mine ID 05-03528 (Contractor)
8. Condition or Practice		8a. Written Notice (103g) <input type="checkbox"/>

A 103J order was verbally issued by Kenneth Valentine at 08:40 hrs. on this date when MSHA received an escalation report stating two miners were down at this operation on November 17, 2013. Two miners were overcome by unknown gasses from a recent blast which may have displaced the oxygen. This order is being issued to withdraw all personnel from the affected area and to assure the safety of all persons at this operation. It prohibits all activity and entry at the underground portion of this mine until MSHA has determined that it is safe to resume normal mining operations to recover and/or restore operations.

See Continuation Form (MSHA Form 7000-3a)

9. Violation	A. Health <input type="checkbox"/> Safety <input type="checkbox"/> Other <input type="checkbox"/>	B. Section of Act	C. Part/Section of Title 30 CFR
--------------	---------------------------------------------------------------------------------------------------------	----------------------	------------------------------------

Section II--Inspector's Evaluation

10. Gravity:

A. Injury or Illness (has) (is): No Likelihood Unlikely Reasonably Likely Highly Likely Occurred

B. Injury or illness could reasonably be expected to be: No Lost Workdays Lost Workdays Or Restricted Duty Permanently Disabling Fatal

C. Significant and Substantial: Yes No D. Number of Persons Affected:

11. Negligence (check one) A. None B. Low C. Moderate D. High E. Reckless Disregard

12. Type of Action 103j 13. Type of Issuance (check one) Citation Order Safeguard Written Notice

14. Initial Action A. Citation B. Order C. Safeguard D. Written Notice E. Citation/
Order Number F. Dated Mo Da Yr

15. Area or Equipment The whole underground portion of the Revenue Mine.

16. Termination Due	A. Date Mo Da Yr	B. Time (24 Hr. Clock)
---------------------	------------------	------------------------

Section III--Termination Action

17. Action to Terminate

18. Terminate	A. Date Mo Da Yr	B. Time (24 Hr. Clock)
---------------	------------------	------------------------

Section IV--Automated System Data

19. Type of Inspection (activity code) E06	20. Event Number 6616214	21. Primary or Mill P
22. Signature Lee A. Hughes		23. AR Number 4729

MSHA Form 7000-3, Apr 08 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

CITATION/ORDER DOCUMENTATION

DATE 11/17/13
TIME 08:40

CIT/ORD No. 82549D2

EVENT No. 6616214

CONTRACTOR ID No. _____

VIOLATION

DESCRIBE: **CONDITION/PRACTICE/HAZARD/LOCATION** 103j

MSHA received an escalation report stating 2 mines were down on this date.

- May be from gases from a blast they conducted on 11/16/13.

- 103j order verbally issued by Kenneth Valentine at 08:40 hr. on this date.

- Issued to Danny Wescroft (Safety Manager)

GRAVITY

No Likelihood () Unlikely () Reasonably Likely () Highly Likely () Occurred ()

Justification: _____

No Lost Workdays () Lost Workdays or Restricted Duty () Permanently Disabling () Fatal ()

Justification: _____

Persons affected: _____

NEGLIGENCE

None () Low () Moderate () High () Reckless Disregard ()

Justification: _____

Area/Equipment (Orders): The whole underground portion of the mine.





Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 11/17/2013	3. Citation/ Order Number 8754902 - 01
4. Served To Danny Woodruff-Safety Manager	5. Operator STAR MINE OPERATIONS, LLC	
6. Mine REVENUE MINE	7. Mine ID (Contractor) 05-03528	

Section II--Justification for Action

Change	From	To
12. Type of Action1	103j	103k
<p>Reason The initial order is modified to reflect that MSHA is now proceeding under the authority of section 103(k) of the Federal Mine Safety and Health Act of 1977. This section 103(k) order is intended to protect the safety and health of all persons on site, including those involved in rescue and recovery operations or investigation of the accident. The Mine Operator is reminded that the mine shall remain closed and locked until the Mine Operator and the Mine Rescue team has developed a plan to clear the mine and the plan has been approved by MSHA. Once the mine is cleared, the Mine Operator shall submit a written action plan to MSHA and obtain prior approval from an Authorized Representative of the Secretary for all actions to recover and/or restore operations in the affected area. Additionally, the Mine Operator is reminded of its existing obligations - to prevent destruction of evidence that would aid in investigating the cause, or causes of the accident.</p>		

To modify the K order to a J order.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06	10. Event Number 6616214				
11. Signature Lee A. Hughes	AR Number 4729	12. Date Mo Da Yr 11/17/2013	13. Time (24 Hr. Clock) 1840		



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>		2. Dated (Original Issue) Mo Da Yr 11/17/2013			3. Citation/ Order Number 8754902 - 02	
4. Served To Danny Woodruff-Safety Manager				5. Operator STAR MINE OPERATIONS, LLC (Contractor)		
6. Mine REVENUE MINE				7. Mine ID 05-03528		

Section II--Justification for Action

To correct the verbiage from the first modification. The original justification should have read as follows; To modify the 103(j) to a 103(k) order.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06		10. Event Number 6616214			
11. Signature Lee A. Hughes		AR Number 4729	12. Date Mo Da Yr 11/18/2013	13. Time (24 Hr. Clock) 1406	

Mine Citation/Order
Continuation

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 11/17/2013	3. Citation/ Order Number 8754902 - 03
4. Served To Danny Woodruff, Safety Manager	5. Operator STAR MINE OPERATIONS, LLC	
6. Mine REVENUE MINE	7. Mine ID 05-03528	(Contractor)

Section II--Justification for Action

Change From To

8. Condition Or Practice

Reason After review and approval of the company's submitted plan to recover the underground portion of the Revenue Mine, the 103K Order #8754902 will be modified. This modification will allow two fully equipped mine rescue teams to explore and attempt to recover all accessible underground working of the mine in an orderly manner. Toxic gas monitoring will be conducted along with air flow measurements, directions, and physical conditions of ventilation structures will be documented while the teams explore the mine. Exploration will continue with the discretion of the mine rescue team Captains, Mine Operators approval and MSHA oversight.

The first mine rescue team will be allowed to enter the mine November 19th at 1305hrs.

Allow entrance by mine rescue teams to clear all areas of the underground mine.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06	10. Event Number 6616214		
11. Signature Mike Tromble	AR Number 4708	12. Date Mo Da Yr 11/19/2013	13. Time (24 Hr. Clock) 1305

Mine Citation/Order
Continuation

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>		2. Dated (Original Issue) Mo Da Yr 11/17/2013		3. Citation/Order Number 8754902 - 04	
4. Served To Danny Woodruff, Safety Manager			5. Operator STAR MINE OPERATIONS, LLC		
6. Mine REVENUE MINE			7. Mine ID 05-03528 (Contractor)		

Section II--Justification for Action

Change From To

8. Condition Or Practice

Reason After the decision of the mine rescue teams to retreat from the underground sections of the Revenue Mine, this 103(k) order #8754902 will be modified. This modification will close all sections of the underground areas in the Revenue Mine. The mine operator is reminded that the mine shall remain closed and locked until the Mine Operator and Mine Rescue teams have developed a plan to clear the mine and the plan has been reviewed and approved by MSHA. Once the mine is cleared by the Mine Rescue teams, the Mine Operator shall submit a written action plan to MSHA and obtain prior approval for all actions to recover and/or restore operations in the affected area. The mine operator is reminded of his existing obligation to prevent the destruction of evidence that would aid the investigation of the cause or causes of the accident.

Modification after mine rescue teams retreated from the mine on 11/20/2013 at 1433 hrs.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06	10. Event Number 6616214		
11. Signature Mike Tromble	AR Number 4708	12. Date Mo Da Yr 11/20/2013	13. Time (24 Hr. Clock) 1433

Mine Citation/Order
Continuation

U.S. Department of Labor
Mine Safety and Health Administration



Section I-Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>		2. Dated (Original Issue) Mo Da Yr 11/17/2013			3. Citation/ Order Number 8754902 - 05	
4. Served To John Trujillo Jr., Surface Operation Manager				5. Operator STAR MINE OPERATIONS, LLC		
6. Mine REVENUE MINE				7. Mine ID 05-03528 (Contractor)		

Section II-Justification for Action

Change	From	To
8. Condition Or Practice		
Reason	<p>This 103(k) order #8754902 is hereby modified to allow the mine operator to enter the Crushing Gallery through the mill decline to inspect the Sump Area, Crushing gallery and to make necessary repairs . This also allows a onetime entrance in to the Course Ore Drift through the Revenue Portal to inspect the Coffe Dam and do necessary repairs to stop the water from entering the Coffe Dam. In addition operator is allowed to inspect the crushing gallery two times daily to verify that the sump pump is running and keeping up with the French drains under the Crushing Gallery. This will be done with gas detecting devices and constant communication with the surface.</p> <p>This order was modified on 11/25/2013 @ 1146 hrs.</p>	

Modification to allow one time entry in to Course Ore Drift for repairs and inspection. Also allow inspection of the crusher gallery sump pump twice a day.

See Continuation Form

Section III-Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV-Inspection Data

9. Type of Inspection E06	10. Event Number 6616214		
11. Signature Mike Tromble	AR Number 4708	12. Date Mo Da Yr 11/25/2013	13. Time (24 Hr. Clock) 1146



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>		2. Dated (Original Issue) Mo Da Yr 11/17/2013		3. Citation/ Order Number 8754902 - 06	
4. Served To John Trujillo Jr., Surface Operation Manager			5. Operator STAR MINE OPERATIONS, LLC		
6. Mine REVENUE MINE			7. Mine ID 05-03528		(Contractor)

Section II--Justification for Action

Change	From	To
8. Condition Or Practice	<p>Reason This 103(k) order #8754902 is hereby modified to release Revenue Mine Mill Infrastructure to include the Crushing Gallery under the following conditions. The mine operator must maintain all ventilation in the mill and the mine. The mine operator must have constant communication to the surface. The mine operator must have constant Toxic gas monitoring at all times in the mill and in the Crushing Gallery. Should CO levels exceed 50 ppm the mill and the crusher gallery will be immediately evacuated. If there is a loss of communication, interruption in ventilation, or set Toxic gas levels reached all personnel will be evacuated from the mill and crushing gallery. The mine operator will establish evacuation procedures and train all persons entering these areas in these procedures. This modification does not release access to the coarse ore drift. This 103(k) order was modified on 11/26/2013 @ 13:44hrs</p>	

Modified to allow access into the Mill and Crushing Gallery

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06	10. Event Number 6616214		
11. Signature Mike Tromble	AR Number 4708	12. Date Mo Da Yr 11/26/2013	13. Time (24 Hr. Clock) 1344



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 11/17/2013	3. Citation/ Order Number 8754902 - 07
4. Served To Danny Woodruff-Safety Manager	5. Operator STAR MINE OPERATIONS, LLC (Contractor)	
6. Mine REVENUE MINE	7. Mine ID 05-03528	

Section II--Justification for Action

Change	From	To
8. Condition Or Practice	<p>Reason This 103(k) order #8754902 is hereby modified to release Revenue Mine Mill Infrastructure to include the Coarse Ore Bin under the following conditions. The mine operator must install a barricade no further than 150 feet past the switch in the Revenue Drift from the Coarse Ore Drift intersection. The mine operator must maintain all ventilation in the mill and the mine. The mine operator must have constant communication to the surface. The mine operator must have constant Toxic gas monitoring at all times in the Main Mill, Crushing Gallery and the Coarse Ore Bin. Should CO levels exceed 50 ppm the Main Mill, Crusher Gallery and the Coarse Ore Bin will be immediately evacuated. If there is a loss of communication, interruption in ventilation, or set Toxic gas levels reached all personnel will be evacuated from the Main Mill, Crushing Gallery and the Coarse Ore Bin. The mine operator will establish evacuation procedures and train all persons entering these areas in these procedures. This 103(k) order was modified on 11/27/2013 @ 09:48</p>	

8754902-07 Modification to allow work in the Mill and Crushing Gallery.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06	10. Event Number 6616214		
11. Signature Lee A. Hughes	AR Number 4729	12. Date Mo Da Yr 11/27/2013	13. Time (24 Hr. Clock) 0948



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 11/17/2013	3. Citation/ Order Number 8754902 - 08
4. Served To Danny Woodruff-Safety Manager	5. Operator STAR MINE OPERATIONS, LLC	
6. Mine REVENUE MINE	7. Mine ID 05-03528	(Contractor)

Section II--Justification for Action

Change	From	To
--------	------	----

8. Condition Or Practice

Reason This 103(k) order #8754902 is hereby modified to allow the operator to send miners in to re-establish ventilation. The mine operator is being allowed to travel beyond the barrier that was erected at the Coarse Ore drift to access the 300KVA substation in order to reset the 10 HP fan, which is located in the Coarse Ore drift. The electrician can then proceed to the Yellow Rose intersection and turn on both stages of the dual 30 HP fan which ventilates the Yellow Rose drift. The electrician can then proceed to the air door to start both dual 30 HP fans. The hog wire barricade is to be re-erected, in the same location, as the miners exit the mine. The mine operator must have constant communication to the surface. The mine operator must have constant Toxic gas monitoring at all times while in the mine. Should CO levels exceed 50 ppm or communications be lost all miners will be immediately evacuated. The mine operator will establish evacuation procedures and train all miners entering these areas in these procedures.
This 103(k) order was modified on 11/29/2013 @ 11:49.

8754902-08 Modification to allow access into the Revenue to re-establish the ventilation system after a power outage which occurred on 11/28/2013.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06	10. Event Number 6616214		
11. Signature Lee A. Hughes	AR Number 4729	12. Date Mo Da Yr 11/29/2013	13. Time (24 Hr. Clock) 1149



Section I-Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 11/17/2013	3. Citation/ Order Number 8754902 - 09
4. Served To Danny Woodruff-Safety Manager	5. Operator STAR MINE OPERATIONS, LLC	
6. Mine REVENUE MINE	7. Mine ID 05-03528 (Contractor)	

Section II-Justification for Action

Change	From	To
8. Condition Or Practice		

Reason After review of the company's submitted plan to recover the underground portion of the Revenue mine, the 103 (k) Order #8754902 will be modified. This is the 2nd attempt to clear the mine. This modification will allow two fully equipped mine rescue teams to explore and attempt to recover all accessible underground working of the mine in an orderly manner. Toxic gas monitoring will be conducted along with air flow measurements, directions, and physical conditions of ventilation structures will be documented while the teams explore the mine. Exploration will continue with the discretion of the mine rescue team Captains, Mine Operators approval and MSHA oversight. This modification also allows the Command Center to make any changes deemed necessary in the recovery the mine. This will be at their discretion without further modification to this order. The mine rescue team will be allowed to enter the mine December 3rd at 0900 hrs.

Allow 2nd attempt by mine rescue teams to recover the mine

See Continuation Form

Section III-Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV-Inspection Data

9. Type of Inspection E06	10. Event Number 6616214		
11. Signature Mike Tromble	AR Number 4708	12. Date Mo Da Yr 12/03/2013	13. Time (24 Hr. Clock) 0900



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 11/17/2013	3. Citation/ Order Number 8754902 - 10
4. Served To John Trujillo Sr. - Mine Manager	5. Operator STAR MINE OPERATIONS, LLC (Contractor)	
6. Mine REVENUE MINE	7. Mine ID 05-03528	

Section II--Justification for Action

Change	From	To
8. Condition Or Practice	<p>Reason This 103(k) order #8754902 is hereby modified to allow the mine operator access from the Revenue portal down the Revenue Drift to the first set of air doors past the intersection of the Revenue and the Yellow Rose drifts. The mine operator must install a barricade at the entrance to the Yellow Rose drift. All previous provisions of the 103(k) order are in effect including the requirement to maintain ventilation and toxic gas monitoring at all times. This 103(k) order was modified on 12/05/2013 @ 1444</p>	

This is to allow the mine operator access to restore power and ventilation after a power outage. This area has been inspected by MSHA prior to this modification and is cleared for work.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06	10. Event Number 6616214		
11. Signature Mike Tromble	AR Number 4708	12. Date Mo Da Yr 12/05/2013	13. Time (24 Hr. Clock) 1444

Mine Citation/Order
Continuation

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 11/17/2013	3. Citation/ Order Number 8754902 - 11
4. Served To Danny Woodruff-Safety Manager	5. Operator STAR MINE OPERATIONS, LLC	
6. Mine REVENUE MINE	7. Mine ID 05-03528	(Contractor)

Section II--Justification for Action

Change	From	To
8. Condition Or Practice	<p>Reason This order is hereby modified to allow the mine operator access to the Yellow Rose Drift, Revenue Drift, Virginius Drift, and Virginius South Drift for the purpose of correcting the conditions cited in those areas. No other work is permitted and no access to the Monogahela drift is allowed. To preserve the ventilation needed to investigate the accident no changes to ventilation are allowed by this modification. The provisions for gas testing, and constant communication from earlier modifications are still in place.</p>	

This action is being taken to allow the mine operator to correct the conditions cited in the mine.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06	10. Event Number 6616214		
11. Signature Keith S. Markeson	AR Number 4428	12. Date Mo Da Yr 12/09/2013	13. Time (24 Hr. Clock) 0825

Mine Citation/Order
Continuation

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 11/17/2013	3. Citation/ Order Number 8754902 - 12
4. Served To Danny Woodruff-Safety Ma	5. Operator STAR MINE OPERATIONS, LLC	
6. Mine REVENUE MINE	7. Mine ID 05-03528	(Contractor)

Section II--Justification for Action

Change **From** **To**

8. Condition Or Practice

Reason This 103(k) order #8754902 is hereby modified to allow the mine operator access to the Monongahela area of the mine to correct cited conditions in this area. All previous provisions of the 103(k) order are in effect including the requirement to maintain ventilation and toxic gas monitoring at all times. This 103(k) order was modified on 12/18/2013 @ 1040

Allow repairs in the Monongahela area of the mine to correct cited conditions.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input checked="" type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	----------------------------------------	-------------------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06	10. Event Number 6616214		
11. Signature Mike Tromble	AR Number 4708	12. Date Mo Da Yr 12/18/2013	13. Time (24 Hr. Clock) 1040

Mine Citation/Order
Continuation

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>		2. Dated (Original Issue) Mo Da Yr 11/17/2013			3. Citation/ Order Number 8754902 - 12	
4. Served To Jack Clark - Underground Operations Manager				5. Operator STAR MINE OPERATIONS, LLC		
6. Mine REVENUE MINE				7. Mine ID 05-03528		(Contractor)

Section II--Justification for Action

Order #8754902 is terminated. Conditions that contributed to the accident have been corrected and normal mining operations can resume.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date	Mo	Da	Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input checked="" type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	---------	----	----	----	------------------------	-------------------------------------	---------------------------------------------------	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06		10. Event Number 6616214					
11. AR Name Keith S. Markeson			AR Number 4428		12. Date Mo Da Yr 03/05/2014		13. Time (24 Hr. Clock) 1458