


2005 SUMMER PROP/ REDZONE SPECIAL SAFETY INITIATIVE



"BEST PRACTICES"

- Develop Standard Operating Procedures (SOP) for tramming remotecontrolled continuous mining machines. Develop a procedure for tramming either facing the rear or front of the machine.
- Train the section crew in the SOP for normal face mining and a move from place to place and ensure that it is followed. Develop standard cable handling procedures during these moves.
- Tram mining machine from a safe location i.e. out of the red zone to avoid pinch points.
- Assure that all persons are in the clear and out of the red zone before tramming with remote controls.
- It is NOT safe to stand in the middle of the machine when it is tramming.

