



Aggregate Contractor Fatalities



Use Fall Protection

Block Equipment Against Motion

Ten fatalities occurred in the aggregates industry in 2010 and 50% of these victims were contractor employees. Details of these contractor fatalities are as follows:

- An electrician was installing ground fault indicator lights when an arc flash occurred.
- A blaster was conducting a post-exam when the ground collapsed engulfing him.
- A drill operator was struck by a drill rig that rolled down a grade.
- The victim was underneath a front-end loader, with the engine running, checking a hydraulic fuel leak when the equipment moved and rolled over him.
- While working at an elevated height, a welder climbed a ladder preparing to weld an overhead pipe. He fell over the hand rail, and died from a fall of 40 feet.
- Four out of the five contractor fatalities involved contractors working in maintenance.
- 80% of these fatalities occurred in the final quarter of the year.

Best Practices:

Maintenance activities by their nature are not routine tasks. Accordingly, contractors performing maintenance need to make safety practices a **HABIT**:

**Hazard
Assessment
Before
Initiating
Task**

- All mine operators should make it a HABIT to ensure that contractors have thought through the tasked job and address/eliminate any hazards that person could encounter.
- This is a “basic” risk assessment and an “excellent Safety HABIT” to get into for oneself, one’s co-workers and all contractors.

* This product was developed as part of the MSHA Alliance Program. It does not necessarily reflect the official views of MSHA. Use of the Alliance Program logo is reserved for MSHA and its active Alliance partners. The MSHA Alliance Program is to promote miner safety and health through voluntary partnerships, which provide training and education, outreach, technical assistance, and a national dialog on mine safety and health. For more information, contact MSHA at (202) 693-9414 or <http://www.msha.gov/alliances/alliances.htm>.