

Appendix Y - Selected Photographs



Photograph 1 - No.1 personnel carrier on damaged overcast



Photograph 2 - No.1 personnel carrier on damaged overcast



Photograph 3 - No. 3 personnel carrier in the No. 4 Entry



Photograph 4 - No. 3 personnel carrier in the No. 4 Entry



Photograph 5 - Inby segment of roof strap at A Left No. 3 Seal



Photograph 6 - Inby segment of roof strap at A Left No. 3 Seal



Photograph 7 - Outby segment of roof strap at A Left No. 3 Seal



Photograph 8 - Middle segment of roof strap found in No. 5 Entry



Photograph 9 - Oxygen cylinder found in the No. 5 Entry



Photograph 10 - Acetylene cylinder found in the No. 5 Entry



Photograph 11 - Debris from stopping near B Left Section



Photograph 12 - Damaged roof straps near A Left No. 3 Seal