


Mine north side first
Bust into Main west against Joss Valley fault,
if looks good, will pull pillars

100' to 150' to 200'

Back shore

old roof support
iron plate, 5' bolt

1050



Some ribs → No special support
 cable bolts
 6" bolts
 in bad areas

systematic
 support
 bolts
 developed by anti-wash bridge system
 smaller bolts - S

left because irregular shape
 not because deep cover
 also for wet floor, otherwise

↪ Mains