

PRE-SHIFT SECTIONS

PRE-SHIFT SECTIONS


DATE OF EXAMINATION 8-2-07
 TIME OF EXAMINATION START 9:45 AM/PM
 EXAM. CALLED OUT — YES/NO
 CALLED OUT BY Josh Fielder

SECTION/AREA Main West
 END 9:55 AM/PM
 CALL OUT TIME 9:56 AM/PM
 REPORT RECEIVED BY Phillip Cox SIGNATURE

DATE OF EXAMINATION 8/3/07
 TIME OF EXAMINATION START 330 AM/PM
 EXAM. CALLED OUT — YES/NO
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE

SECTION/AREA Main West
 END 430 AM/PM
 CALL OUT TIME _____ AM/PM

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	51036		Deep water @ 40	Pumped and scooped
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.8	0	0			None Observed	
Trans Former	20.8	0	0			None Observed	



LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0%	0	50188		none ob	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0%	0			diagonal stopping needs repaired (bounce)	SENT MEN TO REPAIR DONE
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
trans former	20.8	0%	0			none ob	
Pillar line	20.8	0%	0			none ob	

ON-SHIFT HAZARDS IDENTIFIED

V = VIOLATION
H = HAZARD

LOCATIONS	HAZARDS	ACTION
one section roadways	acc in section roadways	Cleaned with scoop
feeder	ACC	Cleaned

ON-SHIFT HAZARDS IDENTIFIED

V = VIOLATION
H = HAZARD

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Phillip all areas appeared reasonably safe at time of exam

PRE-SHIFT REMARKS areas reasonably safe, need routine timber along pillar mining on.

PRE-SHIFT/MINE EXAMINER Signature CERT.# 9174
 COUNTER SIGNATURE _____ CERT.# 8462
 SECTION SUPERVISOR _____ 2MSHA02828

PRE-SHIFT/MINE EXAMINER Signature CERT.# 9174
 COUNTER SIGNATURE _____ CERT.# 7485
 SECTION SUPERVISOR _____ 2MSHA02829