MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

[redacted] MSHA Atty agreed to Lby and terminate order.

I mailed to R.O. and advised them each that air does still not reverse. Discussed w/ Keith Stone and Wayne Hensinger.

Inspector's Initials [redacted]

Supervisor's Initials a[redacted] 10/6 Page No. 9

GPO U.S. GOVERNMENT PRINTING OFFICE: 2009—540-493

Day

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 3/9/10 Event No. 6286108

Arrived at the Mine 0810 Departed from the Mine

List Records Books Checked Pre Shift / Section Weekly

Accompanied By: Company Representative Rick Hiccum

Miners Representative N/A

AREAS OF INSPECTION ACTIVITY:

Outby Bases, Chargers, Etc. Equip.

Safety Talk w/ Evs. Shift

Production

Inspector's Initials [redacted]

Supervisor's Initials ar[redacted]/2010 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

Arrived at Upper Big Branch Mine - Ellis Portal

Met with Everett Hagen and Terry Moore

Supervisor [redacted]

Vent. Dept. [redacted]

and CMI Trainee [redacted] are also on Mine Site to Check Ventilation on Sections.

Review Map w/ other Inspectors on Areas to Be Inspected

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]/2010 Page No. 2

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

Got w/ Rick Nicolau to Check Outby Boxes, Pumps, Etc.
Check MT-2 Bus (NVO)
Travel to 78 Brk (NVO)

Check D-Box @ 79 Brk
AEI S/N 27998-208 (NVO)

Check 6 North XVA @ 79 Brk AEI
S/N 22038-2300-1205 (NVO)

Check SCSR Caches
@ 81 Brk P.C.-1 (10) P.C.-2 (10)
P.C.-4 (2), P.C. 5-2 (2) 37-(10)
45-(10), 46-(10), (10)
(64) Total OK

Inspector's Initials [redacted]
Supervisor's Initials an [redacted] 3/10 Page No. 3

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

Check Door Box
AEI S/N 27474-108 (NVO)

Check Outby Chamber @
59 Brk (NVO)

Check Capacitor Box for
Longwall @ 93 Brk
AEI S/N 31224-909 (NVO)

Check Longwall Splitter
AEI S/N 30600-709 (NVO)

Check Mother Drive KVA
AEI S/N 13060-1400-100
(NVO)

Inspector's Initials [redacted]
Supervisor's Initials an [redacted] 3/10 Page No. 4

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

Check Splitter for 1 Section
AEI S/N 28911-109 (NVO)

Check Box @ 7 North
Head AEI S/N 22040-2300-306
(NVO)

Check D-Box @ 7 North
Head AEI S/N 22397-505 (NVO)

Check Longwall Mantrip Charger
@ Inby LW Switch
Enforcer S/N HA47148 (NVO)

Check Box @ 120 Brk
AEI S/N 11521-500-398 (NVO

Inspector's Initials [redacted]
Supervisor's Initials ar [redacted] 3/10 Page No. 5

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

CHECK No. 26 CACHE (10)
SCSR'S (OE)

CHECK No. 2 O-Box FOR
GLORY HOLE [redacted] ASI
S/N 10525-497
-1- CITATION

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/10 Page No. 6

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

1056 8087751 75.360 (A)
THIS PERSON CONDUCTING
THE PRESHIFT EXAM ON THE
ELECTRICAL O-BOX S/N 10525-497
LOCATED AT THE GLORY HOLE
DID NOT CERTIFY, BY DATE,
TIME, INITIALS THAT AN
EXAMINATION WAS MADE
IN THIS AREA
THE DATE FOUND WAS
3/8/10 AT 1204 pm BY
SM

EXAMINERS SHOULD HAVE
KNOWN AS AREA IS TO
BE PRE SHIFTED WHEN
MEN ARE UNDERGROUND

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/10 Page No. 7

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

HAS EXISTED FOR 2 SHIFTS

1 PERSON EXPOSED - EXAMINER

IF ACCIDENT OCCURRED IT
WOULD BE NO LOST WORKDAYS

IT IS UNLIKELY TO OCCUR
JUST FAILURE TO CERTIFY
BY DTI'S, RECORDING
VIOLATION

THUR. 1100. [redacted] PERSON
DID EXAM AND CERTIFIED
WITH DTI'S

Inspector's Initials [redacted]

Supervisor's Initials a [redacted] 3/10 Page No. 8

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

TRAVEL UP TO 1 SECTION
-1- CITATION AT MOUTH
[redacted] DOORS (AIR LOCK)

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/10 Page No. 9

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

1130 8087752 75.[redacted]816(b)
THE HIGH VOLTAGE CABLE
12,470 VOLTS IS NOT GUARDED
AT THE OUTSIDE DOORS (AIRLOCK)
LOCATED AT THE MOUTH OF
1 SECTION. WHEN OPENING THE
OUTBY SET OF DOORS THE
DOOR COMES IN CONTACT WITH
THE HIGH VOLTAGE CABLE
SUPPLYING 12,470 VOLTS TO
THE SECTION SPLITTER.
THE DOOR ALSO PINCHES ON
CABLE AGAINST BLOCK USED
IN DOOR, NOT PROTECTING IT
FROM CONTACT IF PERSONS
HOLDING ONTO DOOR

EXAMINER SHOULD HAVE KNOWN
OF HAZARD

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/10 Page No. 10

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

HAS EXISTED FOR 2 SHIFTS

1 PERSON EXPOSED - PERSON
OPENING DOOR

IF ACCIDENT OCCURRED IT
WOULD RESULT IN NO LOST
WORKDAYS

IT IS UNLIKELY TO OCCUR
DUE TO MINIMUM EXPOSURE

Inspector's Initials [redacted]

Supervisor's Initials a [redacted] 3/10 Page No. 11

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

CHECK D-BOX @ MOUSE DRIVE (NVO)

CHECK 133 BRK D-BOX (NVO)

CHECK BOX @ 133 BRK AEI S/N 27201-1400-1008 (NVO)

SPLITTER @ MOUTH OF 1 SECTION AEI S/N - 12821-199

CHECK 1 SECT. No. 1 HEAD KVA AEI S/N 22906-1200.1005 (NVO)

Inspector's Initials [redacted]

Supervisor's Initials a[redacted] 3/10 Page No. 12

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

1165 8087758 75.220(a)(1)

THE OPERATOR IS NOT FOLLOWING THE ROOF CONTROL PLAN AS APPROVED BY THE DISTRICT MANAGER. LOCATED ON THE PRIMARY ESCAPEWAY AS 53# 24125 (#2) THE MOUTH OF A CROSSCUT IN THE 2x1 BREAK IS 36 FT WIDE AT THE MOUTH TURN AND DOES NOT REDUCE WIDTH TO 20 FT WIDE UNTIL 16 FT IN TO CROSSCUT. Pg. 12, DRAWING 2 SHOWS MAXIMUM WIDTH AT MOUTH OF TURNS TO BE 26 FT WIDE MAXIMUM AND REDUCED TO 20 FT WIDE WITH 6 FT OF START OF

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/10 Page No. 13

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

TURN.

EXAMINER SHOULD HAVE KNOWN

HAS SUBSTD FOR AT 1 MONTH

1 PERSON SUPPOSED - EXAMINER OF POWER CENTER

IF ACCIDENT OCCURRED IT WOULD RESULT IN FATAL INJURIES FROM FALL OF ROOF AND TO REDUCTION OF PILLAR

IT IS UNLIKELY TO OCCUR SANDSTONE ROOF IN AREA NO VISIBLE CRACKS IN ROOF

Inspector's Initials [redacted]

Supervisor's Initials a[redacted] 3/10 Page No. 14

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

CHECK 153 FORKLIFT CHARGER (NWO)

CHECK CLA FORKLIFT S/N 153 [redacted] -1- CITATION

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]3010 Page No. 15

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

1204 3087754 75.400

THE CLA FORKLIFT S/N 153 BEING USED FOR SUPPLYING THE No. 1 SECTION [redacted] HAS ACCUMULATION OF COMBUSTIBLES ON TOP OF THE MACHINE. HYDRAULIC OIL HAS ACCUMULATED ON TOP OF THE PUMP COMPARTMENT AND MACHINE. THIS MACHINE IS USED IN THE PRIMARY ESCAPEWAY.

OPERATOR / EXAMINER SHOULD HAVE KNOWN AS IT IS OBVIOUS ON SURFACES OF MACHINE

HAS EXISTED FOR 2 DAYS

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]3010 Page No. 16

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

10 PERSON EXPOSED - # OF MEM ON SECTION

IF ACCIDENT OCCURRED IT WOULD RESULT IN PERMANENTLY DISABLING INJURIES

IT IS UNLIKELY TO OCCUR. MACHINE IS ONLY OPERATED 2 TIMES PER DAY AND IS EQUIPPED WITH AUTOMATIC FIRE SUPP.

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]3010 Page No. 17

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

[redacted] TRAVEL BACK OUTSIDE ARRIVED ON SURFACE

MET WITH JASON WHITEHEAD, WAYNE PERSINGER TO GO OVER PROBLEMS ON LONG WALL

SPOKE TO [redacted] ON CITATIONS I WROTE AND ROOF CAUSE AND ABATEMENT TIMES

INFORMED MR. PERSINGER THAT AFTER CITATION WROTE ON LIFELINE ON 2 SECTION TODAY BY BENNY CLARK. ALL LIFELINE CITATIONS THE NEGLIGENCE

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 18

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

GOES UP FROM MODERATE

HELD SAFETY DISCUSSION WITH EVENING SHIFT (15) MEN (DOY GAVE SAFETY TALK) SPOKE ON LIFELINE, ESCAPEWAY AND VENT. AND ROOF CONTROL

AT 430 WAYNE PERSINGER INFORMED ME THAT THEY HAD MADE CHANGE AT REGULATOR BUT AIR IS STILL GOING SAME WAY AS WHEN CITED

TALK TO [redacted] ON PHONE AT 450 pm AND INFORMED HIM OF SITUATION

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 19

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/9/10

[redacted] INFORMED ME TO LEAVE ORDER STANDING AND RETURN TO OFFICE.

GAVE WAYNE PERSINGER TELEPHONE NUMBERS OF SUPERVISORS AND TOLD HIM TO CALL THEM WHEN ORDER COULD BE LIFTED.

LEFT MINE SITE

RETURN TO MT HOPE OFFICE

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 20

*U.S. GPO: 2009-541-759

Ony

MSHA Form 7000-10l, June 93 (revised)

DAILY COVER SHEET

Date 3-9-10 Event No. 628608

Arrived at the Mine 0800 Departed from the Mine

List Records Books Checked Pre-Shift

On shift, Weekly Way book

Accompanied By: Company Representative

Roman Cornett

Miners Representative

None

AREAS OF INSPECTION ACTIVITY:

- mine Out
- Intake From break 78 to 40

Production

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

Mat Weekly Kirk Stone, Kirk Sykes Clyde Gray and Tony Mowell discuss the areas that we was to travel to we intercept Terry Mowell mine Foreman of this revised mine map, Weekly air Way book Clyde and I travel from intersurface with Roman Cornett and [redacted] to break 78. Begin work

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 2

GPO U.S. GOVERNMENT PRINTING OFFICE:2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

~~From~~ A

Travel From break 78 To mine Out

Pre Act Meeting at break 78, and at ~~last~~ Recovered out break 12.

The mine roof appears solid, Be All ways cry. Check Reflectors, Reflective on Reflects adequate all Ventilation Controls in place No hazards observed in face area.

Inspector's Initials [redacted]

Supervisor's Initials and Dat [redacted] 3/10 Page No. 3

GPO U.S. GOVERNMENT PRINTING OFFICE:2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date _____

#1 Cty-Dr
#1 R/B-Dr
#1 Scoop Chg-Dr
#1 Fork Lift Chg-Dr
Scoop Power Center
Dr
belt FVA box
Dr
#3 Scoop Chg-Dr
Dr
Coal Feeder
Dr
pressure Pump
Dr

Inspector's Initials [redacted]

Supervisor's Initials and Date [redacted]3/10/10 Page No. 4

GPO U.S. GOVERNMENT PRINTING OFFICE: 2009—540-493

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

75.380d6 100's

The intake overcast or
break 12 is not provided
with a ladder, stairway
ramp, or similar facilities
To allow persons to
cross and travel to
the surface

Due 3-9-10 15
0-1800
10 people.

Inspector's Initials [redacted]

Supervisor's Initials and D[redacted]3/10/10 Page No. 5

GPO U.S. GOVERNMENT PRINTING OFFICE: 2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

4, 5 days or more

5. Weekly all way examination

6. 10 people

7. Lost workdays or
restricted duty.
If persons needed to
escape out the intake
and the intake Bonding
Rey would not be able
to cross the overcast

8. Reasonably likely that
a injury could occur.
It possibly could to escape
out the entry

Inspector's Initials [redacted]

Supervisor's Initials and Date [redacted]3/10/10 Page No. 6

GPO U.S. GOVERNMENT PRINTING OFFICE: 2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

75.380(d)(7) 1005

Belt line in the primary escape way for inby ends is not being maintained throughout the entire length of the escape way. Belt line is running through debris, not over rollers.

Due 3-9-10 1400

C-1305

1 person

Inspector's Initials [redacted]

Supervisor's Initials and Da[redacted]/10 Page No. 7

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

4, 5 days a week

5. Weekly air ways examined

6, 10 people

7. No lost work days. Persons could not be employed from this violation.

8. UNK. - The intake stoppings are overcast but only for a distance of 20 ft. Persons could see the reflectors on the other side of the overcast.

Inspector's Initials [redacted]

Supervisor's Initials and Date [redacted]/10 Page No. 8

G20 U.S. GOVERNMENT PRINTING OFFICE:2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

75.200(a) 1125

The no. 2 entry on mine map beginning at spad 23765 and extending outby for a distance of 80 ft. was measured 21 ft to 22 ft wide.

Due 3-9-10 1400

1-Person

Inspector's Init[redacted]

Supervisor's Initials and Da[redacted]/10 Page No. 9

G20 U.S. GOVERNMENT PRINTING OFFICE:2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

5 days or more

5. Pre-shift exam should have been aware of this condition

6- 1 person

7. No lost workdays persons work not be away from this violation

8. Unlikely - That an injury could occur Roof and ribs are solid.

Inspector's Initia[redacted]

Supervisor's Initials and Da[redacted]3/10 Page No. 10

GPO U.S. GOVERNMENT PRINTING OFFICE: 2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

25-514 1120

Pre cable splices on Pencil Elbow may or may not insulated To the same degree as the outer jacket

Occ 3-9-10 1120 C-1145

1 person

Inspector's Ini[redacted]

Supervisor's Initials and Da[redacted]3/10 Page No. 11

GPO U.S. GOVERNMENT PRINTING OFFICE: 2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

4, 3 hrs or more

5 Miner operator should have observed This Condition

6. 1-person

7. No lost work days No injury would occur From this violation

8. Unlikely That a injury would occur No bar wire exposed

Inspector's Init[redacted]

Supervisor's Initials and Date[redacted]3/10 Page No. 12

GPO U.S. GOVERNMENT PRINTING OFFICE: 2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

75.904 1130

The circuit breaker for the No. 1 SL car on mine 010 at the Section power center is not identified.

Occ 3-9-10 1145
C 1130

1-person

Inspector's Initials [redacted]

Supervisor's Initials and Date [redacted]3/10/10 Page No. 13

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

4, 1 day of mine

S. pre-shift examiner should have observed this condition

C 1-person

2, permanent disabling injury could occur Electrical shock, can could be fatal or Reversible burns

3. Reasonably likely that Incorrect Breaker could be opened

Inspector's Initials [redacted]

Supervisor's Initials and Date [redacted]3/10/10 Page No. 14

G20 U.S. GOVERNMENT PRINTING OFFICE: 2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-10-10

75.904 1135

The circuit breaker for the welder at the K Section mine 010 is not properly identified. The circuit breaker is marked as SCAR Charger

Occ 3-9-10 1145
C 1130

1-person

Inspector's Initials [redacted]

Supervisor's Initials and Date [redacted]/10/10 Page No. 15

G20 U.S. GOVERNMENT PRINTING OFFICE: 2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

4, 1 day assault

5. Pre-Shift examiner should observe this condition

6. 1-person

7. Reasonably disabling Burns would occur

8. Reasonably likely that a misfire could occur, Resulting energized circuit breaker in the KV cable Between could deenergize the wrong feed

Inspector's Initials [redacted]

Supervisor's Initials and Da[redacted]3/10 Page No. 16

MSHA Form 7000-10K, June 93 (revised)

Date 3-19-10

25.3 20E 1141

UP to date, date, time and initials are not present at Brushing Change on mine map

Due 3-9-10 1500

1-person

Inspector's Init[redacted]

Supervisor's Initials and Da[redacted]3/10 Page No. 17

GPO U.S. GOVERNMENT PRINTING OFFICE:2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

4, 4hrs,

5. Brushing Examined

6-1 Person

7. NO lost workdays Persons would not be injury Fatal Violation

8. Unlikely But a injury could occur NO. Violation Issued at This Time

Inspector's Init[redacted]

Supervisor's Initials and D[redacted]3/10 Page No. 18

GPO U.S. GOVERNMENT PRINTING OFFICE:2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

4, 4 hrs.

5. Pre-shift Examiner Should have been aware of this Violation

6, 1 person

7. No lost workdays Persons would not be injury from this Violation

8. Worst Case injury would occur No DT at Present

Inspector's Initials [redacted]

Supervisor's Initials and D[redacted]3/10 Page No. 19

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

25. 226 a 1155

Page 12 of the approved Roof control Plan is not being complied with in Reference to the Coal feeder. The entry opening was measured 35 ft. wide

On 3-9-10 1655

1 person

Inspector's Initials [redacted]

Supervisor's Initials and Da[redacted]3/10 Page No. 20

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

4, 5 days or more

5. Pre-shift examiner Should have been aware of this violation

6 - 1 Person

7. No lost work days Persons would not be injury from This violation

8. Worst Case injury would occur. Be struck or fall in of Solid objects impact

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]2010 Page No. 21

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

Travel From the Section to the Surface

Discussed Hazards Issued With Terry Moore

No Citations Were Given

Inspector's Initia [redacted]

Supervisor's Initials and D [redacted] 3010 Page No. 22

GPO U.S. GOVERNMENT PRINTING OFFICE: 2008-741-328

MSHA Form 7000-10M, June 93 (revised)

AIR READINGS

Date 3-9-10

Location INTAKE AT 76 PK. A

Width		Bottle Sample No.	
Height	~~4.2~~ 4	CH4 Detected	0
Area	~~12.6~~	Mean Entry	
Velocity	515	Time	0900
Quantity	~~64810~~ 73,130		
Location	INTAKE - B.		

Width		Bottle Sample No.	
Height		CH4 Detected	
Area	160	Mean Entry	
Velocity	450	Time	0935
Quantity	72,000		

Inspector's Initi [redacted]

Supervisor's Init [redacted] 3010 Page No. 23

GPO U.S. GOVERNMENT PRINTING OFFICE 2005-752-759

MSHA Form 7000-10M, June 93 (revised)

AIR READINGS

Date 3-9-10

Location INTAKE SPLIT FOR #1-2 SECTION

Width	14	Bottle Sample No.	
Height	6	CH4 Detected	
Area	144	Mean Entry	
Velocity	1440	Time	1005
Quantity	63,360		
Location	INTAKE SPLIT FOR #2 MAIN DIP		

Width	20	Bottle Sample No.	
Height	6.5	CH4 Detected	
Area	130	Mean Entry	
Velocity	220	Time	
Quantity	25,600		

Inspector's Initia [redacted]

Supervisor's Init [redacted] 3010 Page No. 24

GPO U.S. GOVERNMENT PRINTING OFFICE 2005-752-759

MSHA Form 7000-10M, June 93 (revised)

AIR READINGS

Date

Location Intake Split To MMU 040

Width 19 Bottle Sample No.

Height 7.5 CH4 Detected 0

Area 142.5 Mean Entry

Velocity 55 Time 1035

Quantity 7,800

Location 1 LB MMU 040

Width 20 Bottle Sample No.

Height 6 CH4 Detected .05

Area 120 Mean Entry

Velocity 170 Time 1032

Quantity 20,400

Inspector's Initi [redacted]

Supervisor's Init [redacted] Page No. 25

GPO U.S. GOVERNMENT PRINTING OFFICE 2005-752-759

MSHA Form 7000-10M, June 93 (revised)

AIR READINGS

Date 3-9-10

Location Immediate Ret Off

Width 20 Bottle Sample No.

Height 7 CH4 Detected .05

Area 140 Mean Entry

Velocity 600 Time 1035

Quantity 84,000

Location #3 Belt Entry (Out)

Width 18 Bottle Sample No.

Height 6 CH4 Detected 0

Area 108 Mean Entry

Velocity 170 Time 1055

Quantity 18,360

Inspector's Initi [redacted]

Supervisor's Init [redacted] Page No. 26

GPO U.S. GOVERNMENT PRINTING OFFICE 2005-752-759

E01
Day
46-08436

MSHA Form 7000-10l, June 93 (revised)

Production

DAILY COVER SHEET

Date 3-9-10 Event No. 6286108

Arrived at the Mine 8:06 Departed from the Mine

List Records Books Checked Preshift Book - Belt Weekly Book

Accompanied By: Company Representative Dean Jones Section Foreman

Terry Mac - Mine Foreman

Miners Representative None

AREAS OF INSPECTION ACTIVITY:

Mine Office
22 Headgate MMU 028 #1 Section
Return Air Course from Airlock
Bleed 6
Primary + Secondary
Section Belt

Production

Inspector's Initials [redacted]

Supervisor's Initials a [redacted] 3/12 Page No. 1

*U.S. Government Pri [redacted] 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

Arrived Mt Hope HQ
Weaver met with CMI Keith
Stone + Vent Specist [redacted]
[redacted] who will
be travel with writer to
UBB - Mine on ventilation check
of the mine and field office
system Tom Moore.

Write Issued company mine
field book for required information
sign + dated Mine field book.
Made copy of Rog Dentil plan +
vent plan.

Write left Mt Hope HQ by
COV for mine property.
Arrive mine property met
with Terry Moor - Mine Foreman

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/12 Page No. 2

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

MMU-029 #1 Section HG-22

Review Pushoff Book.

#1, 4 Cts moved 208 more
2 0.08 moved 208 ton
2 Dt 0.08 scraped 208 ton
3 0.08 water in Fm 208 ton

208 16,380

Dean Jones

Met with Terry Moore
mine foreman

Review wall map for
Pushoff Book - Smoke Book
Week Book for required
information - check + Graphical NVO

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/12 Page No. 3

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

Travel from created by
Rail cuts travel secure up
To unload Haul Pump
Work not secure and end of
Work to the 22 Headgate
Sect MMU-029

~~Took 4-wheel onto Section~~

Travel Letter from
unload Check & travel
section.

and on Sect.
Stoppy + mandoor in fair
shape, 208 ov
DTI - NVO 0.2 Cly
Roof + Rib - NVO
Wet + Rockdust - NVO

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/12 Page No. 4

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

Travel from area for
unrelated change

No 3 Face
DTE-NVO
O2-20.8 CH4 0.2
Sand Rat Top

Tail Gate Panel 20B
Belt 2X3

Travel to No 2 Face
mine was being opened
face.
20' out by tele take
Wonderful Corp - NVO
Taken was
CH4 0.2 DTF-NVO
O2 20.8

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] Page No. 5

*U.S. GPO: 2009-541-759

MSHA Form 7000-10M, June 93 (revised)

AIR READINGS

Date 3-9-10

Location 20B 2X3
MMU 029 - 22 Headgate

Width	20.5	Bottle Sample No.	
Height	7.25	CH4 Detected	0.2
Area	148.625	Mean Entry	
Velocity	140	Time	10:19
Quantity	20,807		

Location Minew No 2 Face

Width	4	Bottle Sample No.	
Height	6.75	CH4 Detected	0.2
Area	27	Mean Entry	
Velocity	370	Time	10:30
Quantity	9,990		

O2-20.8

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] Page No. 6

*U.S.GPO:1993-0-709-384

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

Rep & Rel - NVO
Rebelo NVO
Observed many open end
Cut sequence NVO

Travel to face of No 1

DTF-NVO
Wonderful Corp - NVO
Rep & Rel - NVO
Rodelo - NVO

CH4 0.2
O2-20.8

Use 6' Tag Zem & FI
Cable Belts.
Face Area - NVO

Inspector's Initials [redacted]

Supervisor's Initials [redacted] Page No. 7

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

Travel to Tail of Belt - Check air flow checked. air travel outby

Issued 1 calab on Coal float dust to accumulation Loudest supe for a distance of 360 feet duty - Belt Running duty.

Travel to Tail check entries scoop

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/12 Page No. 8

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

1. 11.15 CN-8084609

2. Accumulation of coal float coal dust Black in colour is allowed to accumulate on Rockdusted surfaces on the section Belt for the 22 Headgate main - 029 from the section transpere outby for a distance of 360'

3. 22 Headgate Main - 029 Section Belt

4. At Least this shift

5. Section Foreman on Belt engineer shuttleman 61

7. Unlady - No belt scams present

8. No lost Work day - No belt scams present

Terminated 3-9-10 13:00

Terminated 3-9-10 12:30

Root cause - Belt being allow to run dry

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/12 Page No. 9

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

Check scoop
Fan Chief scoop
Manton Scoop
S/n 1253
Model No. 488-12-23

Issued 1 calab on Compressed cylinder not opp duty storage oxygen cylinder

Issued 1 calab on scoop for Weld & wash job - combustible material

Chief Rect of manton scoop Check OK.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/12 Page No. 10

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised) 46-08436 E-01

Date 3-9-10

1. 11:35 CN-8084610

2. A compress gas cylinder (Oxygen Tank) being Transported on Top of the Mantrac scoop without a protective cap Check Tank tank was empty.

3. MMU-029 22 Headgate Section

4. Mantrac should have known

5 At Least 1 shift on Oxygen

6 1

7. Contributing - Gas cylinder was empty tank valve was Left open.

8. No Lost Workdy Tank empty

Term 11:50 3-9-10

Terminated 11:45 3-9-10

Root cause - Not being provide with protective cap.

Inspector's Initials [redacted]

Supervisor's Initials and Date _____ Page No. 11

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised) 46-08436 E-01

Date 3-9-10

1. 11:45 CN-8084611

2. Accumulation of combustible material (Lubricants & loose coal) is allowed to accumulate under Shield & frame of the Franchild mantrac scoop S/N 1253 at various deep's

3. 22 Headgate MMU-029 Section

4. Several shifts

5. Mantrac should have known

6 1

7. Unlikely - No heat source present

8. No Lost Workdy - No heat source present

Term 3-11-2010 0800

Root cause - Lack of frequent cleaning

Inspector's Initials [redacted]

Supervisor's Initials [redacted] Page No. 12

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

Left Section travel way To EDT - Took Railcar To Portal.

Arrived back at Portal Went To Mine Office.

Issued 3 citation and terminated 2 left 1 pending

Review inspection with mini management & no mini rep. Review citation issued and conference with.

Review citation with field office supervision Tom Moore at this time

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/12 Page No. 13

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-9-10

Left mine property by 600 for Mt Hope HQ.

Arrived Mt Hope HQ and prepared

Inspector's Initials [redacted]

Supervisor's Initials [redacted] Page No. 14

*U.S. GPO: 2009-541-759

OWL / DAY

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 3/10/10 Event No. C286108

Arrived at the Mine 0430 Departed from the Mine

List Records Books Checked CW PRE SHIFT

Accompanied By: Company Representative CHRIS BLANCHARD, JASON WHITEHEAD, WAYNE PERSINGER

Miners Representative N/A

AREAS OF INSPECTION ACTIVITY:

TAIL GATE ENTRIES

EP-TG-1

EP-CW-3

IDLE SHIFT

Inspector's Initials [redacted]

Supervisor's Initials [redacted] Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3/10/10

ARRIVED AT UPPER BIG BRANCH MINE - ELLIS PORTALS

MET WITH WAYNE PERSINGER CHRIS BLANCHARD, SPOKE TO THEM ON WHAT THEY HAD TO DO TO CORRECT VENTILATION ON WALL CHECK CW PRESHIFT (NVO) SAID CHANGE DID NOT AFFECT MINER SECTIONS

CHECK MT-15 (NVO) (13) SCSR'S (OK)

TRAVEL TO 78 BRUCE (NVO) CHANGE RIDES

Inspector's Initials [redacted]

Supervisor's Initials [redacted] Page No. 2

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/10/10

Got on No. 2 Sect (NVO)

Travel to Mouth of Tailgate (NVO)

Took Air Reading @ Regulator One Crosscut Inby. 82,721 cfm

Smoked All Entries Between 40-41 Brk. Air Flow is as Shown on Map.

Smoked All Entries Between 48-49 Brk Air Flow is as Shown on Map

Inspector's Initials [redacted]

Supervisor's Initials a[redacted] Page No. 3

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/10/10

Air Flow in No. 7 Entry Comes Outby into Crosscut Toward No. 6 Entry and Then Inby Toward Fan This Occurs in 49, 50, 51, 52, 53 Breaks

Took Air Reading Outby Tail 82,815 cfm

Smoked Entries at 53 Brk Air Going Inby.

Travel to 56 Brk Crosscut Air w/ Smoke Air Going Inby

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] Page No. 4

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/10/10

Travel to SP CW-3

Took Air Reading @ Regulators

No. 1 - 5852 .25% CH_4 20.8 O_2 Air Out SP

No. 2 - 9870 .25% CH_4 20.8 O_2 Air Out SP

Travel to SP T6-1

No. 1 - 86,100 .05% CH_4 20.8 O_2 Air Out

No. 2 - 20,425 .20% CH_4 20.8 O_2 Air Out

No. 3 1699 .20% CH_4 20.8 O_2 Air Out

Inspector's Initials [redacted]

Supervisor's Initials a[redacted] Page No. 5

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/10/10

TRAVEL BACK TO MOUTH OF TAIL GATE

AT 36 BEG ANSCR AIR WITH SMOKE. AIR FLOW IN DIRECTION OF MAP.

RETURN TO SURFACE

CALLED VENTILATION SUPERVISOR INFORMED HIM OF MY FINDINGS HE INFORMED ME THAT THEY ARE STILL UNDER CITATION WITH AIR FLOW IN No. 7 COMING ONLY 5 BARRELS

Inspector's Initials [redacted]

Supervisor's Initials [redacted] Page No. 6

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/10/10

INFORMED MANAGEMENT OF WHAT VENT. SUPERVISOR INFORMED ME OF.

TOLD THEM THEY ARE STILL UNDER ORDER FROM YESTERDAY

HELD CROSSOUT WITH MANAGEMENT

RETURN TO MT. HOPE OFFICE

Inspector's Initials [redacted]

Supervisor's Initials [redacted] Page No. 7

*U.S. GPO: 2009-541-759

EVE

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 3/10/10 Event No. 628610T

Arrived at the Mine 1920 Departed from the Mine

List Records Books Checked Pre on shift weekly; MAPS of vent Change

Accompanied By: Company Representative

JACK Roles CWC

Miners Representative

N/A

AREAS OF INSPECTION ACTIVITY:

C.W. MAIL ENTRIES Vent Change to Abate order.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3/10/10

Arrived @ mine 1420
Received fire for shift
Exams, weekly exam.
Went over substation
Change conducted by operator
to change air in CW
return
went over map of
Jack holes.
Called fire Maconaqua
Ventilation supervisor informed him
of Changes and update of
Fill gate entry. He informed
me that a revision to
the vent. plan must be
submitted and approved
by D.M. before order could
be lifted. I informed
Jack Yates who called

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 2

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/11/10

Wayne Kessinger V.P.
I discussed the situation
by everyone by phone.
Traveled U.G. w/ Jack
Yates to CW tail
Documented on map
Changes that were made.

Regulation 75.1711
This regulation was apart
of Approved plan but
was not in an inspect-
3/9/10 and 104 d 2 order
was issued. Also, Airlock
doors effected had to be opened
to feed air to regulation.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 3

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

Air locks partially opened
needs to be stable regulated
Controls.
Regulator 224125
AE 4.5 x 9
Ve 1911
Qe 73,386 c/m

Operator built isolation
Controls for tailgate
entry w/ regulators to
feed inbound neutral
Intake air from 3-6
Entries.
Controls were not
Blackened just covered of
Curtain. Some regulators
were unmarked opened.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 4

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

Tunnelled up isolate-
Entry. Air current was
traveling in the right
direction.

A1 AC 5½ x 2
V= 1408
Q= 5808 cfm

Air Reading 37-38
AC 19.5 x 7.5
V= 410
Q= 59,962 cfm

A2 Heading
AC 2.5 x 21.5
V= 1090
Q= 6812 cfm

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 5

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

A3 Back 45
AC 2.5 x 21.5
V= 1040
Q= 6500 cfm

A3 Back 49
AC 5
V= 963
Q= 4515 cfm

A4 Back 50
AC 18 x 2.5
V= 830
Q= 2573
The Air Split back
only (2) pair @ 54
Back.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 6

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

Air reading MP B between
54-55

AC 4.5 x 20
V= 685
Q= 61,650 0% chg
BS: E 2116

Air reading between
54 & 53 Air going to face
Segment split.
AC 5.4 x 18.6
V= 285
Q= 29,500 cfm

Air readings MP B
Entry 6
AC 6.5 x 20
V= 160
Q= 20,800

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 7

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

Entry 5
Ar 6x20
Ve 415
Qe 49,888

Entry 4
Ar 5x21
Ve 437
Qe 45,885

Entry 3
Ar 6x19
Ve 360
Qe 41,040

Smoked Entries 3-6 from MS to mouth the Air was going in by in the right direction.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 480 Page No. 8

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

There were check curtains over belts in stoppings to control air.

Went over injuries w/ Jack Rules informed him that regulations would have to foreman there and check curtains would have to be allowed and stoppings would have to be fixed.

Traveled to Mt Hope District office and met w/ Supervisor to inform him of Situation in the mine so that he could be aware of plan revision is submitted in the morning.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 480 Page No. 9

*U.S. GPO: 2009-541-759

DAY

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 3/11/10 Event No. 6256108

Arrived at the Mine 1050 Departed from the Mine

List Records Books Checked CW Pre Shift

Accompanied By: Company Representative Chris Beanahard

Jason Whitehead, Wayne Brasinger, Jack Rolls Everett Magee

Miners Representative

N/A

AREAS OF INSPECTION ACTIVITY:

Tail Gate Entries on Longwall

Production

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 480 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3/11/10

Arrived at Upper Big Branch Mine - Ellis Portals

Met with Management to Discuss Revision on Tailgate and Inform Them that Order Could Be Terminated once Revision is Varified by Checking Vent. Controls Underground @ Tailgate

Review Map of Area To Be Inspected with Management

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]3510 Page No. 2

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/11/10

Check Longwall Pre Shift Book (NVO)

Intake 99,720
9 - 805
160 - 822

MPA - 14,482
MPB - 35,400

Met with Chris Blankenship, Jason Whitehead, Jack Roles, Tim Davis to Go to Tailgate

Check MIT-7 Manrus (NVO) (13) SCSR's (OK)

Inspector's Initials [redacted]

Supervisor's Initials and [redacted]3510 Page No. 3

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/11/10

Travel to Mouth of Longwall on Tailgate (NVO)

Check Ventilation Controls and Compared them to Revision Submitted (NVO)

Took Air Readings at Regulators and Outby Tail

Smoked other Airways on Way

Took Reading @ 160 Jack on Longwall Face

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]3510 Page No. 4

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/11/10

Traveled other Neutral Splits out
Check with smoke tubes on way back to Mouth
Air flow is as shown on Map in All Areas

Travel Back to Surface

Called MSHA Office

Spoke with Ventilation Supervisor informed him of findings

Lifted Order on Longwall @ 1400

Inspector's Initials [redacted]

Supervisor's Initials [redacted] Page No. 5

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/11/10

Type out Termination

Head Closeout w/ Managemsnt

Return to Mt Hope Office

Inspector's Initials [redacted]

Supervisor's Initials [redacted] Page No. 6

*U.S. GPO: 2009-541-759

MSHA Form 7000-10I, June 93 (revised) 46-08436

DAILY COVER SHEET

Date 3-11-10 Event No. 6286108

Arrived at the Mine 0600 Departed from the Mine

List Records Books Checked Weekly Exam and Daily Exam of seals

Accompanied By: Company Representative Harley Taylor

Miners Representative

AREAS OF INSPECTION ACTIVITY:

Seal Airway 15 thru 6

Inspector's Initials [redacted]

Supervisor's Initials [redacted] Page No. 1

*U.S. Government P[redacted] 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

Arrived at the mine at 0600. Spoke with Gary May & Rick Foster. Scott VAn Dyke & I will be traveling with Harley Taylor Doing Seals.

Went over Daily & weekly seal work. (Book) Check what Harley used to pump seals.

MT-11 WV
Rode to Break 75 walking Seal Airway with Harly Taylor

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 2

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

Handed out literature & stickers on Ending Black lung Approx 35 People.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 3

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

BK 75 5 north Belt

Set #15
6B - Valve
64

Pump #63.
18.8 0^2
0 CH4
0 CO

Outby the Reading Air Moving the wrong WAY. 0900
Citation # 8090312
BK 33 to 34
7 x 18 = 126
V. 200 25,200

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 4

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

CITATION/ORDER #: 8090312

Time: 0900

Location: Seal Airway 15 thru 8

Violation: 75.370(a)(1)

The operator failed to follow the approved ventilation plan, The air ventilating the seals was moving in the wrong direction

No. of Persons Exposed: 1

Inspector's Initials [redacted]

Supervisor's Initials [redacted]/10 Page No. 5

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

Who knew the violation existed?

The daily examiner stated that the air was moving properly yesterday

How long has the violation existed?

Less than one shift

If an accident should occur because of this type violation, how serious would it be?

No lost work days, No Methane detected in any area of seal airway

What is the likelihood that this type accident will occur at this mine?

Why? Unlikely due to the fact no methane detected in seal airway. & No explosive range Found behind seals

Inspector's Initials [redacted]

Supervisor's Initials [redacted]/10 Page No. 6

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

Set 14

62 - Pump

16.3 O2

.1 CH_4

25,340 AT BK 42 moving correctly in the intake Entry.

Mouth of #2 intake

131 BK overcast

Mouth of Main

A= 122

V 567

Q 69,174

Inspector's Initials [redacted]

Supervisor's Initials [redacted]/10 Page No. 7

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

set 13 & seals 56-61

56 gas pipe

O^2 19.3

CH_4 0.0

CO 0 ppm - out gassing

Set 12 53 thru 55

53 test -

O^2 17.2 16.8

CH_4 .63 1.6

CO. 0 PPm . out gass

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/2/10 Page No. 8

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

Set 11 50-52

Gas Valve #50

out-gassing

O^2 17.9 16.1 Hybrid

CH_4 0

CO. 0

Set 10 47-49

out gassing

Gas valve 47

O^2 19.2

CH_4 0

CO. 0

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/2/10 Page No. 9

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

81 Break Pump

NVO

Set #9 44-46

44 valve

18.9 O^2

0 CH_4

0 CO

Set #8 41-43

43 Valve out gassing

O^2 19.3

CH_4 0

Co. 0

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/2/10 Page No. 10

GPO U.S. GOVERNMENT PRINTING OFFICE: 2009—540-493

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

77 Break Pump N/O

32 Break Pump.

32 Seal Pump.

Inspector's Initials [redacted]

Supervisor's Initial [redacted] /10 Page No. 11

GPO U.S. GOVERNMENT PRINTING OFFICE: 2009—540-493

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

TIME 1305

BK 60 3rd OVERCAST

OUT by the BEATER

Section.

207a 8090213

There is a 12 Foot Long Area that is not supported. This AREA is not supported for the entire width of the entry 20' wide.

14 Bolts are not against the top in this Area.

This area must be made weekly

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 12

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

CITATION/ORDER #: 8090313

Time: 1305

Location: OUTBY CROSSCUT 60 SEAL AIRWAY

Violation: 202(a)

An area 12 Feet Long and 20 Feet wide was not supported.

The weekly examiner must travel this Area

No. of Persons Exposed: 1

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 13

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

Who knew the violation existed?

The individuals who installed newly constructed overcast would have known.

How long has the violation existed?

One week

If an accident should occur because of this type violation, how serious would it be?

FATAL due to roof fall.

What is the likelihood that this type accident will occur at this mine? Why?

Reasonably likely the roof is not good in this Area

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/15 Page No. 14

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-09

The examiner walked out of this aseway by using doors & leaving the entry & came back in & walk back.

Set B - 38, 39, 40

38 valve. outby

CH4 1.0%

O2 16.8

CO. 0

OUTBY air

A 181.5

V 52

Q 94138

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 15

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

13:20 8090314

Intake overcast has 6 Blocks missing From the right corner looking inby. This ventilation control is not being used For what it is intended-

75.333(h)

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 16

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

CITATION/ORDER #: 8090314

Time: 1320

Location: Intake overcast Barrier Section

Violation: 75.333(h)

The overcast was not being maintain to serve the purpose for which it was intended. There were six blocks missing From the right corner looking in by.

No. of Persons Exposed: 1

Inspector's Initials [redacted]

Supervisor's Initial [redacted] 3/2/10 Page No. 17

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

Who knew the violation existed?

The person who built this overcast

How long has the violation existed?

less than one week

If an accident should occur because of this type violation, how serious would it be?

No lost workday.

What is the likelihood that this type accident will occur at this mine?

Why? unlikely Intake air could mixing in the return.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/2/10 Page No. 18

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

1330 60 cent

Door at DK 67 8090315

NEW 57 75.333(e)(1)

600FT. 1000FT

Headgate 17 Sump pump

1345

Two 8090316

~~Foot~~ Break entry

Track overcast

right crosscut to

Headgate 17 sump pumps

BK 58

Travel way needs retimbered

Timbers Dry & loose, 11

5 Timbers have Fallen

Leaving unsupported

top exposed

Two places twelve feet

Inspector's Initia [redacted]

Supervisor's Init [redacted] 3/2/10 Page No. 19

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

CITATION/ORDER #: 8090315

Time: 1330

Location: BK67 on 2 north Belt.

Violation: 75.333 (c)(1)

Personel doors were 1000 Ft apart.

No. of Persons Exposed: 3

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 20

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

Who knew the violation existed?

The people in charge of building overcast would have known

How long has the violation existed?

Less than 2 weeks

If an accident should occur because of this type violation, how serious would it be?

No Lost workdays it would cause a confusion and a longer walk.

What is the likelihood that this type accident will occur at this mine? Why?

Unlikely there is very little likely hood of an emergency in this Area

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 21

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

CITATION/ORDER #: 8090316

Time: 1345

Location: Two crosscuts inby the track overcast in the Sect air course

Violation: 75.202(a)

Eleven loose timbers and 5 timbers that have fallen out exposing unsupported top [2 Places 12 Feet from the rib to the First Bolt]

The weekly examiner travels this Area.

No. of Persons Exposed: 1

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/10 Page No. 22

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

Who knew the violation existed?

The weekly examiner should have seen this.

How long has the violation existed?

More than one week

If an accident should occur because of this type violation, how serious would it be?

Fatal due to a roof Fall.

What is the likelihood that this type accident will occur at this mine? Why?

Reasonably likely the top is breaking up in this area.

Inspector's Initials [redacted]

Supervisor's Initials an[redacted] 12/10 Page No. 23

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-11-10

From the rib to the nearest bolt.

Set 6 33 Thru 37

33 Value.

4.4 O2

6% CH4

0 CO

21,850

Set 5 26 thru 32

Pump 26

CH4 0.0

O2 19.4

CO 0

Walked to the surface

Wrote 5 citations

Inspector's Initials [redacted]

Supervisor's Initi[redacted] 3/21/1 Page No. 24

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3.11-10

Delivered the citations to Brennan Cornett & Discussed Root cause.

Drove to Mt. Hope.

Inspector's Initials [redacted]

Supervisor's Initia[redacted] 12/10 Page No. 25

*U.S. GPO: 2009-541-759

EVE

MSHA Form 7000-10I, June 93 (revised) 46-08436

DAILY COVER SHEET

Date 3-14-10 Event No. *6286108

Arrived at the Mine 2135 Departed from the Mine

List Records Books Checked

Long Wall

Accompanied By: Company Representative Keith Stanley
Shannon Dickens

Miners Representative N/A

AREAS OF INSPECTION ACTIVITY:

Hdc - Maintance
Postings
AMS System

PRODUCTION

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/5/10 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3-14-10

Checked equipment at office
Went over Mine Files for
Long Wall at UBB

Traveled to mine

meet with Dispatcher and
went over tracking monitor
system. Also went over CO
system. Saw 3 dead CO's
1.121; 1.103; 1.114; 1.119? in yellow
2150 Time.

Checked Postings while waiting
for Crew to arrive.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/5/10 Page No. 2

G2O U.S. GOVERNMENT PRINTING OFFICE: 2009—540-493

MSHA Form 7000-10K, June 93 (revised)

Date 3-14-10

Talked to Safety director.
They have air change at 0400
~~[redacted]~~ if every thing is
right.

Loaded up on #3 Mantrip. Observed
Mantrip operation by crew

Yard + Parking lot as well lit
and provide good visibility.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/5/10 Page No. 3

G2O U.S. GOVERNMENT PRINTING OFFICE: 2009—540-493

OWL

MSHA Form 7000-10I, June 93 (revised) 46-08436

DAILY COVER SHEET

Date 3-15-10 Event No. 6286108

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked _____

cont. from the shift

Accompanied By: Company Representative Keith Stanley
Shannon Pickens

Miners Representative N/A

AREAS OF INSPECTION ACTIVITY:

Maintence
Long Wall PM
2 Shield Haulers
1 Scoop
LW Belt, 6N Belt, 5N Belt, 4N Belt
Fire deluge, Slip, Seq., CO's
Belt Boxes, KVA's, Splitters, Take-ups, Rock Dusters, Disconnect Boxes

Inspector's Initials [redacted]
Supervisor's Initials [redacted] 3/15/10 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

Arrived on Section at 0015. Had Safety talk with 7 people on Block lung - Vent. Gave out stickers and pamphlets.

Checked equipment, checked 2 Battery chargers on end of sled for rides. NVO

Checked Water Pump Car NVO

checked Mining Car NVO

Checked Power Cords - 480V + 4160V - Pumps + Chargers. NVO

Checked Emergency Ride A-12648 NVO

Inspector's Initials [redacted]
Supervisor's Initials [redacted] 3/15/10 Page No. 2

GPO U.S. GOVERNMENT PRINTING OFFICE: 2009—540-493

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

Roof Bolter 2000043 DR-13-E-CF
Power was pulled.

Checked Life Shelter model #2624-3,5
#452043-02 62°F +4500 psi

#9 Jack 1020 LFM
#6B Jack 625 LFM
Belt CFM
LOB CFM

Checked Panels on Power Boxes NVO

Checked CH4 sensors on Tail NVO
CH4 sensor on Shear unable to check

Inspector's Initials [redacted]
Supervisor's Initials [redacted] 3/15/10 Page No. 3

GPO U.S. GOVERNMENT PRINTING OFFICE: 2009—540-493

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

Shear cable repaired checked CH4 sensor. Checked Shear Panels, Pull Release Panel off and locked for cracks NUO. Checked Shield + Light Power Supplies.

Checked Shield Haeuler + Charger # 636-1012 Long Airdox

Checked Scoop # T339-136R

Checked Shield Haeuler #636-1010 Long Airdox

Checked Long Wall belt Fire deluge, Slip, Seq. CO's KVA Boxes, Take-up. See citations

Inspector's Initials [redacted]

Supervisor's Initials an [redacted] 3570 Page No. 4

GPO U.S. GOVERNMENT PRINTING OFFICE: 2009—540-493

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

Checked 6 North Belt Drive. KVA Boxes + Disconnect Box NUO. Checked Pickups to pumps + Rock dusters also Take-up Fire deluge, Seq., Slip + CO's Belt Starter Box NUO. KVA line splitter for 1 + 2 section NUO Take-up

Checked 5 North Belt drive Fire deluge, Seq., Slip, + CO's KVA Boxes Also Belt Starter Box Take up

Checked 4 North Belt drive Fire deluge, Seq., Slip, + CO's KVA Boxes, Belt Starter Box-Take-up splitter, Disconnect Box

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3570 Page No. 5

GPO U.S. GOVERNMENT PRINTING OFFICE: 2009—540-493

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

Due to an air change that is taking place I was side back outside. I fully explained my findings to the operator and explained how citations would be rated on gravity + Negligence.

Inspector's Initials [redacted]

Supervisor's Initials an [redacted] 3570 Page No. 6

GPO U.S. GOVERNMENT PRINTING OFFICE: 2009—540-493

MSHA Form 7000-10M, June 93 (revised)

AIR READINGS

Date 3-15-10

Location

LOB Longwall

Width 18.5 Bottle Sample No. —

Height 7.5 CH4 Detected 0.0

Area 138.75 Mean Entry

Velocity 520 Time 0130

Quantity 72,150

Location

Belt Intake

Width 21 Bottle Sample No. —

Height 7.3 CH4 Detected 0.0

Area 153.3 Mean Entry

Velocity 290 Time 0145

Quantity 44,457

Inspector's Initials LH

Supervisor's Initials and Date JM 3/15/10 Page No. 7

*U.S.GPO:1993-0-709-384

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

1. 0400

2. 75.400 8085073

3. At the drive Unit of the LW belt located behind the drive is an accumulation of mud and slop that is up to 10" deep under the belt. Water + Mud have run to the Power Center and covered the mats and started to move toward the track. The mud accumulation is Rib to Rib and 30' long from behind the fence and spreading out to around the drive motors to the Belt Starter.

4. Fire Boss had dates there from 3-5-10 to present on date board. 10 days

Inspector's Initials LH

Supervisor's Initials and Date JM 3/15/10 Page No. A

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

5. 10 days going by dates on date board and time it would take to build up that much mud.

6. 2 persons Fire Boss + Belt man who work + Travel in area. Also maintence person who could be working on Belt Starter.

7. Permanently disabling due to electrical shock at Belt Starter, Mats where under water + Mud and offered no protection.

8. Reasonably likly as belt Box was surrounded by water and mats were under mud + water. There was no insulating mats at doors + Plugs.

Inspector's Initials LH

Supervisor's Initials and Date JM 3/15/10 Page No. B

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

1. 0430 8085074

2. 75.380-(B)-7-vii

3. Double combs were missing on Secondary lifeline at Break #102 of the Long Wall Section showing that a branch line was present leading to an SCSR Cache box.

4. Fire Boss travels and checks the belt + T rock every shift and life lines are located in the track entry. This is one of the I thinks he is too check on his examination, Condition was obvious when observed.

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]3570 Page No. C

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

5. Since Cache was installed to allow section to comply with law. 7 months ago some time in Sept. of 2009.

6. 1 person, Fire Boss. NO accident has occured causing people to need lifeline to evacuate the mine up till this time.

7. No lost workdays as no accidents have occured to date.

8. Unlikily as this is the secondary escapeway not the primary.

Inspector's Initials [redacted]

Supervisor's Initials and [redacted]31570 Page No. D

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

1. 0431 8085075

2. 75.380-(B)-7-vii-A

3. At break #102 of the Long Wall Belt Starter the secondary Escape life line was not marked with the SCSR Cache Signal to show that the branch line led to 2 Boxes of SCSR's.

4. Fire Boss knows as he travels both belt + T rock entries each shift and is to note condition of life line and check signals to ensure they are present.

5. Since Section has been in place mining, 7 Months

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]3570 Page No. E

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

some time in Sept of 2009.

6. 1 person Fire Boss

7. No lost workdays as no accidents have occured to date that would require people to travel out using life line.

8. Unlikely as this is the secondary escapeway and not the primary.

Inspector's Initials [redacted]

Supervisor's Initials [redacted]3570 Page No. F

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

1. 0415 October H20850760

2. 75400

3. The mother belt for the long wall had accumulation of fine Coal dust, black in Color over rock dusted areas from the tail piece to the belt drive.

4. Entire length of the mother belt coming off of shear

4. Fire bosses should have known during preshift

Inspector's Initials [redacted]

Supervisor's Initials [redacted]3570 Page No. G

GPO U.S. GOVERNMENT PRINTING OFFICE: 2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-15

5. Most likely existed 3 shifts due to the amount of accumulation. Present

6. 2 person, belt man and fire boss

7. No lost work day

8. Unlikely due the rock dust underneath. and no ignition source.

Inspector's Initials [redacted]

Supervisor's Initials [redacted]3570 Page No. H

GPO U.S. GOVERNMENT PRINTING OFFICE: 2008-741-328

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

1. 0515
2. 75,400 Cit# 8085077
3. 330 feet inby #5 belt take up had loose coal on a fine coal dust measuring 1/8 inch deep over previously Rock dusted Area. Color was black.

4. Located on South belt Belt, From take up 330' inby

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/15/10 Page No. I

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3-15-10

4 The fire boss Harold Lee Brown

5 at least three shifts due to the amount of accumulation

6 2 person, belt man on fire boss

7 No last work done

8. unlikely due to no ignition source and Rockdust underneath

Inspector's Initials [redacted]

Supervisor's Initials a [redacted] 3/15/10 Page No. J

GPO U.S. GOVERNMENT PRINTING OFFICE: 2008-741-328

Event Number: 6286108
Inspection Date: 3-15-10
Contractor ID: David Stanley
Total Contractor Employees at This Mine: _____

Work Location (circle applicable codes)
00 - Whole mine
(01) Underground
02 - Surface of underground
03 - Strip, quarry, open pit
04 - Auger Shield Tech.
05 - Culm bank/refuse pile
06 - Dredge operation
(12) - Other mining Blake Acord
17 - Independent shops or yards
30 - Mill/preparation plant 3 weeks total
99 - Office workers at mine site

Work Performed (circle applicable codes)
01 - Mine development, including shaft and slope sinking
02 - Construct/reconstruction of mine faciliti
03 - Demolition of mine facilities
04 - Construction of dams
05 - Excavation or earth moving with mobile equipment
06 - Equipment installation; such as crushers and mills
07 - Equipment service/repair on mine property > 5 days
08 - Handling material within mine property
09 - Drilling and blasting
10 - **Other** (describe):

AR Number: 24558 [redacted] 3/10

MSHA Form 2000-208 / Jan. 2001 *U.S. GPO: 2001—651-790/21

PRODUCTION
DAY

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 3/15/10 Event No. 6286108

Arrived at the Mine 0515 Departed from the Mine

List Records Books Checked 1 Sect. PRE Shift

Accompanied By: Company Representative

Zeke Nicolaid

Miners Representative

N/A

AREAS OF INSPECTION ACTIVITY:

Rec. Dust

Rock Dust Survey

Slip, Sec., Fire Supp. on

1 & 2 Section Belts

Trans. Citations

2 Sect. 1 Belt

Inspector's Initials [redacted]

Supervisor's Initials a [redacted] 3/16/10 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

ARRIVED AT UPPER BIG BRANCH MINE - ELLIS PORTAL

MET WITH SUPERIT HAGER AND INFORMED HIM OF TODAYS INTENSION

SPOKE WITH DEAN JONES ABOUT MMAU PLAN. INFORM HIM THAT IF SCRUBBER CFM IS CORRECT THAN INTENDED CUTS MAY BE TAKEN WHILE REC. DUST IS BEING RUN. MUST GO BACK TO 20' CUTS AFTER PUMPS

Inspector's Initials [redacted]

Supervisor's Initials a [redacted] 3/16/10 Page No. 2

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

CHECK PRE SHIFT (NVO)

1, 2, 3 N/O .5%, .5%, .30%

2RT PB .15% CH4

45,000 CFM

430-520

CHECK NO. 11 MANBUS (NVO)

(13) SCSRS OK

CHECK NO. 13 MANBUS (NVO)

(13) SCSRS OK

CHECK NO. 6 MANBUS (NVO)

(13) SCSRS OK

CHECK NO. 7 MANBUS

(12) SCSRS OK

Inspector's Initials [redacted]

Supervisor's Initials a [redacted] 3/16/10 Page No. 3

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

CHECK No. 14 BUS (NW0)
(13) SCSK's OK

HELD SAFETY TALK WITH
MEN (20) ON MMU PLAN
AND VENTILATION. GAVE
OUT BLACK LUNG STICKERS

GOT PUMPS TURNED ON
AND HANDED OUT TO
MEN.

FOLLOW CREW TO SECTION
(NW0)

ARRIVED ON SECTION

MAKE FACES

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/16/10 Page No. 4

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

TRRM. CITS. ON WAY TO
SECTION

CLEANING @ DOORS - 715
8087752

WIRE PLACE @ BOX. 720
8087752

FORKLIFT CLEANED - 723
8087754

WENT TO FACES -
MET SECTION FOREMAN
HE SAID HE DIDN'T HAVE
ENOUGH AIR

Inspector's Initials [redacted]

Supervisor's Initials ar [redacted] 3/16/10 Page No. 5

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

NO WORK WAS BEING
PERFORMED IN THIS LAST
OPEN CROSSCUT. WENT UP
TO FACES

No.3 (N1100) OTI's PRESENT
.35% CH_4 20.8 O_2
LOB - 8645 cfm
No. 2R (N1100) OTI's PRESENT
.30% CH_4 20.8 O_2
No. 1 (N1100) OTI's PRESENT
.10% CH_4 20.8 O_2

TOOK AIR READING IN
BLOCK @ BOOM CENTER / FEEDER
LINE. BOX - 18900, BELT - 8000
RETURN 8800

Inspector's Initials [redacted]

Supervisor's Initials ar [redacted] 3/16/10 Page No. 6

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

FOREMAN SAID THAT BRENNAN CORNETT TOLD HIM THAT AFTER AIR CHANGE 26,000 WAS @ BOW AND 16,000 WAS IN COB

FOREMAN STATED THAT NO VENT. CHANGES WERE MADE FROM THE CREW WHEN THEY ARRIVED. STATED HE WENT STRAIGHT TO FACES, OBSERVED FACES, AND TOOK COB READING AND COULD NOT GET ENOUGH AIR. MSN WAS LOCATED @ POWER CENTER. POWER WAS NOT ON EQUIP. IN FACE / WAY POWER CENTER.

Inspector's Initials [redacted]

Supervisor's Initials an[redacted] 3/16/0 Page No. 7

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

CHECK PUMPS DURING 2ND HOUR (OK)

WALK OVER TO BELT ENTRY - 2 - CITATIONS

CHECK SUPPLEMENTAL SUPPLIES (N/O)

CHECK FIRE FIGHTING EQUIP. (N/O)

Inspector's Initials [redacted]

Supervisor's Initials an[redacted] 3/16/0 Page No. 8

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

930 4087755 75.400

ACCUMULATION OF LOOSE COAL, AND FLOAT COAL DUST HAS ACCUMULATED UNDER THE SECTION TAILPIECE ROLLER WHEN MEASURED ACCUMULATIONS ARE UP TO 6" IN DEPTH AND THE WIDTH OF TAILPIECE 8 FT. LOCATED ON NO. 1 SECTION MMU 029-0

EXAMINERS SHOULD HAVE KNOWN

HAS EXISTED FOR 2 DAYS

1 PERSON EXPOSED EXAMINER

Inspector's Initials [redacted]

Supervisor's Initials an[redacted] 3/16/0 Page No. 9

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

If Accident Occurred it would Result in Permanently Disabling Injuries from Fire or Smoke Inhalation

It is Reasonably Likely to Occur. While walking past Tailpiece noticed Smoke coming from Roller Area. Fireboss was Sitting on Tail Causing Frame of Tailpiece to Rub Belt & These Conditions Together would Cause Fire, (Mask w/ Smoke Air Going Out By.

Inspector's Initials [redacted]

Supervisor's Initials ar[redacted] 3/16/10 Page No. 10

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

Tram. @ 950 - Fireboss was Raised up Tailpiece and Accumulations were Removed

Section Foreman was Showed Problem. He Removed Belt from Sprocket and Had Min Correct Condition

Inspector's Initials [redacted]

Supervisor's Initials ar[redacted] 3/16/10 Page No. 11

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

0935 8047756 75.1722(a)

The Tail Roller located on the No. 1 Section Tailpiece is not Guarded to Protect persons from Contacting the Moving Parts which are Exposed. The Exposed Roller is Width of Tail & ft and 24" inches High

Examiner should have known

Has Existed for 2 Days - Last Move

1 person Exposed. Belt Shovel

Inspector's Initials [redacted]

Supervisor's Initials a[redacted] 3/16/10 Page No. 12

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

If Accident Occurred it would Result in Permanently Disabling Injuries from Loss of Limb or Laceration by Contact moving Parts

It is Unlikely to Occur. Fisher Sits on Top of Tail Pieces. It is 28" from Fisher to Idler or Roller.

Inspector's Initials [redacted]

Supervisor's Initials an[redacted] 3/16/10 Page No. 13

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

Waited and Checked Air. Last Air Reading Took was 13,900 @ 1050

Took up Pumps since no Production

Hour. Cst. - 1056 ✓

Maint. Scoop was Been washed

Started Cutting Rock Dust Survey

Inspector's Initials [redacted]

Supervisor's Initials an[redacted] 3/16/10 Page No. 14

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

Check Slip, Sta., Fire Supp. on 1 Sect. Belt (NVO)

Check Slip, Sta., Fire Supp. on 2 section Belt. (NVO)

Check CO @ Tail 1 Sect. Belt No. 104 (NVO)

Check CO @ Drive 2 Sect. Belt No. 68 (NVO)

Left Section (Mouth) [redacted]

Travel Belt to Tail (NVO)

Starter Box (NVO)

Fire Hose (NVO)

Return to Ride to Go to Surface

Inspector's Initials [redacted]

Supervisor's Initials ar[redacted] 3/16/10 Page No. 15

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

1300 8087757 75.340 (d)(7)(iii)

THE SECONDARY LIFELINE LOCATED AT 130 BRK ON GLORY HOLE WAS NOT TOGETHER THE LIFELINE WAS SEPARATED FOR 3 CROSSCUTS 130 TO 127 BRK.

THE END OF LIFELINE HAS BEEN ROLLED UP AND HUNG ON THE RIB OUT OF THE WAY.

BY THE LIFELINE LOCATED LIKE THIS, IT IS NOT LOCATED IN A MANNER FOR MINERS TO USE TO EFFECTIVELY ESCAPE.

EXAMINER SHOULD HAVE KNOWN OF HAZARD

Inspector's Initials [redacted]

Supervisor's Initials ar[redacted] 3/10 Page No. 16

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

HAS EXISTED FOR 2 WEEKS

10 PEOPLE EXPOSED - # OF MEN ON SECTION

IF ACCIDENT OCCURRED IT WOULD RESULT IN [redacted] PERMANENTLY DISABLING INJURIES FROM FAILURE TO EXIT MINE IN SMOKE

IT IS UNLIKELY TO OCCUR PERSON [redacted] EXITING MINE WILL BE ON TRACK EQUIP.

INFORMED MR. PERSINGER [redacted] ON 3/9/10 THAT ALL LIFELINE CITATIONS THE

Inspector's Initials [redacted]

Supervisor's Initials a[redacted] 3/10 Page No. 17

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

NEGLIGENCE WOULD GO UP AND WITH LIFELINE ROLLED UP AND HUNG OUT OF THE WAY THE NEGLIGENCE IS HIGH.

TERM. - 1324 LIFELINE WAS PUT TOGETHER AND LOCATED WHERE MINERS CAN USE TO EXIT MINE

Inspector's Initials [redacted]

Supervisor's Initials a[redacted] 3/10 Page No. 18

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/15/10

Spoke with Rick on Citations and How I was Citing them He said I'd Get no Argument from him.

Return to Surface

Discuss Citations, Root Cause, Abatement Time

Type out Citations/Termin.

Mail Closeout

Return to Mt. Hope Office

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]/10 Page No. 19

*U.S. GPO: 2009-541-759

Dry

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 3/16/10 Event No. 6286108

Arrived at the Mine 0545 Departed from the Mine

List Records Books Checked

1 Sect. Pre Shift

Accompanied By: Company Representative

Berman Cornett

Miners Representative

N/A

AREAS OF INSPECTION ACTIVITY:

Surface Equip.

Records / Postings

Production

Inspector's Initials [redacted]

Supervisor's Initials an[redacted]/10 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

Arrived at Upper Big Branch Mine - Ellis Portal.

Met with Suckett Hager and Wayne Persinger Rick Nicodemi

Was Going to Run Dust on 040 But Section is in Non Producing Status, Was Going to do Dust on 029 But Lt CM Down with Pan off (Broice)

Inspector's Initials [redacted]

Supervisor's Initials an[redacted]/10 Page No. 2

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

Informed them of Citation on Not Activating MMU -1- Citation

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/17/10 Page No. 3

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

0620 8087758 75.370(a)(1)

The Operator has failed to Notify the District Manager within 3 Days ● that the No. 2 Section MMU 040-0 is in Active Status The MMU has been Active since 3/8/10 and producing Coal

The Operator should have known

Has Existed for 5 Days

● person Exposed.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/17/10 Page No. 4

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

If Accident Occurred it would Result in No Lost Workdays

It is Unlikely to Occur Just Failure to Report Section in Active Status

Term @ 915 - Spoke with Health Dept. Operator has now Notified District Manager of Activating MMU-040-0

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/17/10 Page No. 5

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

CHECK PRES SMOKE FOR
1 SECTION (NVO)

EXCUSED TO DO RECORDS & POSTINGS

CHECK SURFACE FIRST AID (NVO)

CHECK DIESEL FUEL TANK (NVO)

CHECK MINE MAP -1- CITATION

Inspector's Initials [redacted]

Supervisor's Initials an [redacted] 3/17/10 Page No. 6

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

900 8087759 75.1202

THE OPERATOR DOES NOT
HAVE AN ACCURATE AND Up TO DATE MINE
MAP AT EITHER PORTALS. THE
MAP DOES NOT SHOW THE
VENTILATION CHANGES THAT WAS
MADE ON 3/15/10 & 3/11/10

OPERATOR SHOULD HAVE KNOWN
AS THEY MADE THE CHANGE

HAS EXISTED FOR 8 DAYS

10 PERSON AFFECTED IN OR
MINE ON NO. 1 SECTION. CHANGED
THEIR PRIMARY ESCAPEWAY

Inspector's Initials [redacted]

Supervisor's Initials an [redacted] 3/17/10 Page No. 7

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

IF ACCIDENT OCCURRED IT
WOULD RESULT IN NO COST
WORKDAY

IT IS UNLIKELY TO OCCUR
REASONABLE PROBABILITY
MAP ESCAPEWAY IS MARKED
W/ LIFELINE. JUST NEED CORRECTED
ON MAP TO SHOW OTHER
DIRECTIONAL CHANGES OF
AIR

Inspector's Initials [redacted]

Supervisor's Initials an [redacted] 3/17/10 Page No. 8

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

CHECK TRAINING RECORDS ON SOME OF MEN

APPROX. 50

DOWN SURFACE

CHECK CHARGER @ PORTAL S/N 0503-3878 (NVO)

CHECK 966 FRONT END LOADER (NVO)

CAT 50 FORKLIFT (NVO)

OLD MYSTIK - S/N 6502 (NVO)

CHECK CHARGER [redacted] (SOUTH) S/N 109829 (NVO)

Inspector's Initials [redacted]

Supervisor's Initials an [redacted] 3/17/10 Page No. 9

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/16/10

KVA BESIDE FAN S/N 21996-250 (NVO)

KVA AT MOTOR BARN (NVO)

[redacted]

HELD CLOSEOUT W/ BERMAN LOWRY

DISCUSS CITATIONS AND ROOT CAUSE - ASSESSMENT TIME

TYPE OUT CITATIONS

RETURN TO MR. HOPE

Inspector's Initials [redacted]

Supervisor's Initials ar [redacted] 3/17/10 Page No. 16

*U.S. GPO: 2009-541-759

DAY / SWE

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 3/17/10 Event No. 6256108

Arrived at the Mine 0545 Departed from the Mine

List Records Books Checked PRE SHIFT 2 SECTION

Accompanied By: Company Representative TERRY MOORE, RICK NICOLAU

Miners Representative N/A

AREAS OF INSPECTION ACTIVITY:

2 SECTION EQUIP SCRUBBER READINGS TERM. CITATIONS

1 SECT. SCRUBBER READINGS

PRODUCTION

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/18/10 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

Arrived at Upper Big Branch Mine - Ellis Portal

No One on Surface to Speak with

Left Ellis and Drove to South Portal.

Met with David Tarazcokzy and informed him of Today's Inspection.

Informed him I wanted to Go to 2 Section to Check Equip.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/17/10 Page No. 2

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

Check Pre Shift Book for 2 Section

Check Elec. Book for 2 Section - 1 - Citation

Pre Shift 2 Section

No. 1 N/O

No. 2 N/O

No. 2R N550 Clean / D1550

No. 3 N/O

.0% 20.8 O_2 All Faces

LOB 28427 com

5-535

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/17/10 Page No. 3

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

0900 8687760 75.512

The Operator could not produce a written Record of the Weekly Electrical Exam Being Conducted on the No. 2 Section (MMM 040-0) for the following Equip.

Joy CM Last Pass was

Joy CM 3/5/10

Maint. Scoop

Feeder

No. 2 S/C

Splitter Box

Examiners Should have known as they are Required to Record the Exam

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/17/10 Page No. 4

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

HAS SKIDDED FOR 5 DAYS SINCE LAST RECORD

1 PERSON SUPPOSED - OPERATORS

IF ACCIDENT OCCURRED IT WOULD BE NO LOST WORKDAYS

IT IS UNLIKELY TO OCCUR JUST A RECORD VIOLATION

Inspector's Initials [redacted]

Supervisor's Initials a[redacted] 3/18/10 Page No. 5

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/18/10

CHECK 10 JSEP PRIOR TO GOING UNDERGROUND (NVO)

TRAVEL TO ELLIS SWITCH (NVO)

CHECK [redacted] NO. 2 MOTOR (NVO)

TRAVEL TO 2 SECTION (NVO)

DO MANTRIP OBSERVATION (NVO)

TRAM CITE NO. 1 CLARKSON DTI'S IN PLACE 1100

CHECK RVA S/N 29959-500-409 (NVO)

Inspector's Initials [redacted]

Supervisor's Initials a[redacted] 3/18/10 Page No. 6

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

0105 8047761 75.370(a)(1)

THE OPERATOR IS NOT FOLLOWING THE [redacted] VENT. PLAN AS APPROVED BY THE D.M. ON 2 SECT. MMW 040.

BELT AIR WAS MOVING [redacted] IN THE WRONG DIRECTION FROM THE SECTION BELT HEAD TO THE FEEDER (2 BRKS). CHECKED WITH SMOKE AT FEEDER TO VERIFY [redacted] AIR MOVING IN WRONG DIRECTION TOOK AIR READING AND 12285 CFM WAS MOVING TOWARD FACE.

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/18/10 Page No. 7

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

SECTION FOREMAN OR MANAGER SHOULD HAVE KNOWN AS IT WAS OBVIOUS AT BELT DRIVE AND I MUST TRAM AS SCOOP CHARGER JUST ONTOP MINE

HAS SAMPLED FOR 6 HOURS PAS SHIFT EXAMINER SAID AIR WAS RIGHT DURING PRESHIFT

#10 PERSON EXPOSED - # OF MINE ON SECTION

IF ACCIDENT OCCURRED IT WOULD RESULT IN PERMANENTLY DISABILING INJURIES FROM SMOKE INHALATION

Inspector's Initials [redacted]

Supervisor's Initials [redacted]80 Page No. 8

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

IT IS UNLIKELY TO OCCUR NO. STUCK ROLLERS OR BELT RUBBING ON BELT LINE STRUCTURE. AREA WAS WELL ROCK DUSTED AND WATER WAS RUNNING ON BELT.

THE AIR WENT TO HEADER LINE AND WENT THROUGH CROSSCUT TO RETURN. THIS WAS CHECKED W/ SMOKE TUBE

TERM. @ 1120 - REGULATOR WAS OPENED AT DRIVE AND AIR [redacted] REVERSED TO AS SHOWN ON REVISION. AIR READING @ REGULATOR WENT FROM 5550 TO 13,320

Inspector's Initials [redacted]

Supervisor's Initials and [redacted]80 Page No. 9

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

TERM. CUT. @ 1140 IN BELT ENTRY #2. JACKS WERE SET TO REDUCE WIDTH

MAKE FACES ON SECTION

[redacted]

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]80 Page No. 10

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 17 MAR 10

- ENTRY #1 NIDO
DTI'S PRESENT
- BEHIND CURTEN 3½x6½ =23
- SECTION BOSS 5865
- 7,475 0.0 CH^4 20.8 O^2

- ENTRY 2L NIDO
DTI'S PRESENT 0.0 CH^4 20.8 O^2
-3.5x6=21 12,285

- ENTRY 3 NIDO
DTI'S PRESENT 0.0 CH^4 20.8 O^2
[redacted]

- LOB 7x20 =140 72,800

Inspector's Initials [redacted]
Supervisor's Initials a[redacted]/10 Page No. 11

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

CHECK [redacted] SCRUBBER
READING ON RT CM

CHECK JOY S/C 17649
(NVO)

CHECK SCRUBBER READING
ON RT CM

CHECK JOY S/C 17651
0 - 1 - CITATION

Inspector's Initials [redacted]
Supervisor's Initials a[redacted]/10 Page No. 12

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

1350 8087762 75.605
THE JOY S/C S/N 17651
BEING USED ON NO. 2 SECT.
MMU 040 [redacted] WAS THE
CABLE USED TO SUPPLY
POWER TO THE MACHINE
NOT PROPERLY SECURED AT
THE REEL.
THE CABLE WAS SLIPPED
FROM THE CLAMP [redacted]
WITH ONLY STRAIN RELIEF
AT CONNECTION POINTS

EXAMINER SHOULD HAVE
KNOWN
WAS EXISTED FOR 1 WEEK
1 PERSON EXPOSED - OPERATOR

Inspector's Initials [redacted]
Supervisor's Initials and[redacted]0 Page No. 13

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

IF ACCIDENT OCCURRED IT WOULD RESULT IN NO LOST WORKDAY

IT IS UNLIKELY TO OCCUR. CABLE HAS NOT BEEN RUN THAT LOW. DUE TO MUD ON SECTION AND NO MUD WAS PRESENT ON LAST 200' OF CABLE

TERM. @ 1400 - CABLE WAS STRAINED AT REEL

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]3810 Page No. 14

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

CHECK JOY CM S/N JM6044 (NVO) FIRE SUPP. (OK)

CHECK FEEDER (NVO)

TERM CIT. @ 1430 IN WING PLACES. 3 CRIBS WERE SET TO REDUCE WIDTH

NO. 3 CHARGER OUT OF SERVICE 1433 TERM.

[redacted]

Inspector's Initials [redacted]

Supervisor's Initials ar[redacted]3810 Page No. 15

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/17/10

VISIT TO 1 SECTION

MAKE FACES

NO. 3 (N100) DTI'S PRESSENT .30% CH4 20.8 O2

LOB - 22234 CFM

NO. 2 (N100) DTI'S PRESSENT .20%

NO. 1 (N180) DTI'S PRESSENT .10%

TOOK SEQUENSER READINGS ON BOTH CM'S BETWEEN SHIFTS

TALK TO OVS. SHIFT MGR (C) ON MMU PLAN.

LEFT SECTION - RETURN TO SURFACE

Inspector's Initials [redacted]

Supervisor's Initials ar[redacted]3810 Page No. 16

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/12/10

Held Closeout w/ Rick Nicolay. Discuss Citation Root Cause and Abatement Times.

Type and Citations

Return to Mr. Mops Office

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/8/10 Page No. 17

*U.S. GPO: 2009-541-759

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 3-17-10 Event No. 6286108

Arrived at the Mine 5:58 Departed from the Mine

List Records Books Checked Preshift

Accompanied By: Company Representative Rick Foster, Jack Martin

Miners Representative None

AREAS OF INSPECTION ACTIVITY:

Barrier 062 ~~062~~ dust pumps

Inspector's Initials [redacted]

Supervisor's Initials and Date 3-23-10 [redacted] Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

[redacted]

Inspector's Initials [redacted]

Supervisor's Initials and Date 3-23-10 [redacted] Page No. 2

RESPIRABLE DUST

Date: 3-17-10 Location: 062-0

PUMP	CASSETTE	CODE	OCCUPATION	TIME ON	2nd	TIME OFF	OK TF
RH7	831429		Intake	6130	755	10:37	2105 2130
176	831338	050R	SC night		750	10:41	2107 2130
RH	833579	0502	SC lift		746	10:40	2111 2130
R11	831693	0486R	Belt Room		745	10:18	2105 2130
R13	831585	0486L	Belt Loop		748	10:05	2110 2130
R12	831697	036	Miner		747	8:53	2108 2130
C	831516						

☆ U.S. GOVERNMENT PRINTING OFFICE: 2000–509-166

MSHA Form 7000-10K, June 93 (revised)

Date 3-17-10

Made fones 7-1
SS24535 No. 2
DT&J present
Curtain good -
section clean

Held talk with crew
@ black lung
prevention
✓ escapeway map
✓ communications

Roof bolter 2007048
curtain 12 Hg minimum
L 14" R 18"

Inspector's Initials [redacted]
Supervisor's Initials and Date 3-23-10 [redacted] Page No. 3

GPO U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 3-17-10

E 4119 8:20
Immediate return
No 1 entry 062.
20.8 O2 0.0 CH4
180 + 15 = 195 V
18 W
9.5 H
171 A
195 V
33,345

LOB 2-1 8:30
8 H 20.8 O2
18.75 W 0.0 CH4
150 A
214 V (199+15)
32,100 SS24535

Inspector's Initials [redacted]
Supervisor's Initials and Date 3-23-10 [redacted] Page No. 4

GPO U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 3-17-10



JM5849
BD 5 sprays
No. 3L entry, left
mine operating
1.5 H 9:35
3 W 60 MEAV
22.5 A
259 V 278+11-
6502.5
32 89"T 29.5
rock

Inspector's Initials [redacted]
Supervisor's Initials and Date 3-23-10 [redacted] Page No. 5

GPO U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 3-17-10 night



miner
80psi
JM 5924

Belt right SW
97015/2008301
12" Hg on tag
R 22" L 17"

Intake to 062
316+8 = 324 V
10:25 20.8 O_2 0.0 CH4
7.75 H 155 A
20 W 324 V
1550 A 50,220

Inspector's Initials [redacted]
Supervisor's Initials and Date 3-23-10 [redacted] Page No. 6

GPO U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 3-17-10

Spat No. 1 - No. 6
entry only face
inby SS 24532

section started
running @ 9:48
flush
No. 3 entry left miner
8H = 82
9W = 715
72A = 97
11155
97V
6984
Made fores 1 - 7 with
Jack Martin, section
foreman - appears safe
& competent 20.8 0.0

Inspector's Initial [redacted]
Supervisor's Initials and Date 3-23-10 [redacted] Page No. 7

GPO U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 3-17-10

1101 a porta-potty
is not provided
on the barrier
section 062-0
MMU. Section foreman
& mine foreman could
not provide one.

Time @ 2 weeks since move
No LWD -
Mod - should have been detected
Non SQS
Unlikely - coming on surface
1 person
who knew - foreman should
have known

Inspector's Initials [redacted]
Supervisor's Initials and Date 3-23-10 [redacted] Page No. 8

GPO U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 3-17-10

No. 3 entry, bolter operating

6,251H 1112
3W 20.8
19.75A 0.0
270V 25844.12
5332.50

V supplemental roof supports
Flush R mesh on open
No. 5 entry 1137
7,75H 20.8
8W 0.0
62A
127V (1327.5) 7.5
9114

Inspector's Initials [redacted]
Supervisor's Initials and Date 3-23-10 [redacted] Page No. 9

GPO U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 3-17-10

Afforded Rick Foster (Muse Foreman) & Jack Martin (section foreman) opportunity to stay within 20% parameters

66' for 9 hours
previous 30 shifts needed 58.4'
40' only 3-17-10 -
per Eric 7.89 tons per foot raw tons
7.89 X 40' = 315.6 tons

Cut 32.3
bolted 7.3

Inspector's Initials [redacted]
Supervisor's Initials and Date 3-23-10 [redacted] Page No. 10

GPO U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 3-17-10

Late on belt move (9:48)
Center buggy hung on rock
Cable fault occurred behind miner

Lungs checked at listed times & as required

Spot rock dust sample collected in No. 6 entry

Inspector's Initials [redacted]
Supervisor's Initials and Date 3-23-10 [redacted] Page No. 11

GPO U.S. GPO: 2006-640-217

Day

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 3/22/10 Event No. 6286108

Arrived at the Mine 0515 Departed from the Mine

List Records Books Checked Pre Shift No. 1

Section

Accompanied By: Company Representative Brannon

Bowling - Foreman, Everett Hager

Miners Representative

N/A

AREAS OF INSPECTION ACTIVITY:

Res. Dust (029-0) 1 Sec.

Dust Parameters as

Term. Citations

Production

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/22/10 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3/22/10

Arrived at Upper Big Branch Mine - South Portal

Met with Everett Hager and informed him of Todays Intensions

Gas Pumps Ready to Hand out

Term. Cit. on Maps @ 530 4047759

Check Pre Shift for 1 Section (NVO)

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/22/10 Page No. 2

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/22/10

No. 1 n/o .2% CH4 20.8

No. 2R n/o .1% CH4 20.8

No. 3 n/o .2% CH4 20.8

COB - 23,520

Check No. 9 Manbus (NVO)

Kook in c/ Crew to Section (NVO)

Arrive on Section

Make Faces

No. 1 (N100) .05%

No. 2R (N100) .10%

No. 3 (N100) .10%

COB - 23,625 cfm

DTI's present

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/22/10 Page No. 3

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/22/10

Took Methane Reading on Lt CM Scrubber
1.3
4566 ÷ 6921 = .66
.66 × 4566 = 3014
3014 × 2.0 = 6028 cfm

Check Parameters on Lt CM
Sprays - 50
PSI - 900
Scrubber Screen / Duct Area (OK)

Check Parameters on Lt RB
Filter Area Clean
Op Side - 13 wg
Off Side - 17 wg

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/23/10 Page No. 4

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/22/10

Check Parameters on Rt RB
Filter Area Clean
Op Side - 17 (wg)
Off Side - 15 (wg)
20'
Air Reading for CM
2R = 10,190 MSAV = 66

Check Pumps (OK)
2nd Hour

Observe Work Cycle (OK)
[redacted]'
Air Reading for Bolter
2R = 7092 MSAV = 95.4

Spot Rock Dust Survey Inby Fesole
Too Wet to Sample

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/23/10 Page No. 5

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/22/10

Observe Work Cycle on Bolt Crew (OK)

[redacted]

Check Pumps 4TH Hour (OK)
20'
Air Reading for CM
2R = 8614 cfm MSAV: 60

Observed CM Loading Coal (MVO)

Instm. Cut. @ 1040 - Guard Has Been Installed @ Tail Roller 8087754

Inspector's Initials [redacted]

Supervisor's Initials [redacted] 3/23/10 Page No. 6

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/22/10

CHECK CONDITIONS SCRUBBER

READING RT CM

1.3
4566 ÷ 6933 = .66

.66 x 4566 = 3014

3014 x 2 = 6028 cfm

CHECK PARAMETERS RT CM

SPRAYS - 51

PSI - 75

SCRUBBER CLEAN / DUCT / SCREEN (OK)

AIR READING FOR MB 2R

9120 cfm MSAV = 60

20'

AIR READING FOR CM 2R

10,810 MSAV = 71

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/22/10 Page No. 7

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/22/10

CHECK PARAMETERS ON LT CM

SPRAYS - 48

PSI - 55

SCRUBBER SCREEN / DUCT (OK)

20'

AIR READING FOR CM 3F

STABLE MSAV = 62

GATHERED PUMPS UP

RETURN TO SURFACE

HELD CLOSEOUT W/ MANAGEMENT

TYPE OUT TERMINATIONS

RETURN TO MT HOPE OFFICE

Inspector's Initials [redacted]

Supervisor's Initials and [redacted] 3/22/10 Page No. 8

*U.S. GPO: 2009-541-759

MSHA Form 7000-10N, June 93 (revised)

RESPIRABLE DUST

Date: 3/22/10 Location: 1 Section / 029-0

Inspector's Initials [redacted] Supervisor's Initials and D [redacted] 3/22/10 Page No. 9

PUMP	CASSETTE	CODE	OCCUPATION	TIME ON	2nd	4th	TIME OFF	WT
712	831614	624	M. HEIZ	0600	0830	1040	1400	
713	831602	646	Shuttle Buggy	0600	0830	1040	1400	
714	831730	046	Belt Rt. 2nd	0600	0830	1040	1400	
715	831340	050	S. Coe 5th	0600	0830	1040	1400	
716	831601	050	S. Coe	0600	0830	1040	1400	
617	831794		Jones	0600	0830	1040	1400	

*U.S. Government Printing Office: 1995 — 609-287

Day

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 3/23/10 Event No. 6286108

Arrived at the Mine 0615 Departed from the Mine

List Records Books Checked Longwall Pre-Shift

Accompanied By: Company Representative

Harold Lilly - Asst. Coordinator

Miners Representative

N/A

AREAS OF INSPECTION ACTIVITY:

Res. Dust 050-0

SCSRs

First Aid Supplies

Supplemental Roof Supplies

Production

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]3/10 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 3/23/10

Arrived at Upper Big Branch Mine

Met with Harold Lilly and Jack Coles and informed them of Today's Intensions.

Check Longwall Book (NVO)

Face - N/O

Roof Support. N/O

P/C N/O — Intake - 57,820

Charger N/O — #9 - 533

Track N/O — #160 - 976

Travelway N/O — A - 12,131

Barricade N/O — B - move

433-511 — 0% CH4

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]3/10 Page No. 2

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/23/10

Turned on Pumps and Gave to MSM

Gave Pumps to Pres 90 Miners

Got Avg. of Wall

3.5 passes 10 hr

8.5 RTF

Follow Crew to Station

Make Faces Head to Tail Cuts

Intake - 57,760

#9 - 522

#160 - 975

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]3/10 Page No. 3

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/23/10

Did Parameters on Sheaar
Sprays - 110
PSI - 100

Check Pumps for 2nd
Hour (ok)

Sheaar was on Tail

Observed Sheaar Loading
Towards Head. (two)

Check SCSR's (ok) (40)

Check First Aid Supplies
(two)

Check Supply Roof Supports (two)

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]10 Page No. 4

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/23/10

Observed Sheaar Cut out
on Head and Set Bits

Check Parameters
Sprays - 109
PSI - 105

Do 4 Hour Checks for
Pumps (two)

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]10 Page No. 5

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/23/10

Follow Sheaar to Tail
Took Reading
#160 - 660
#9 - 673

Belts went Down at 1215
Stacker

Belt Started 1230

Followed Sheaar Towards
Head to 120 Shield

2.4 passes

Got Pumps from
men

Inspector's Initials [redacted]

Supervisor's Initials a[redacted]10 Page No. 6

*U.S. GPO: 2009-541-759

MSHA Form 7000-10K, June 93 (revised)

Date 3/23/10

Return to Surface

Spoke with Business Manager and Track Foles on inspection

Hour Daily Crosscut

Return to Mt. Hope Office

Inspector's Initials [redacted]

Supervisor's Initials an [redacted] 3/24/10 Page No. 2

*U.S. GPO: 2009-541-759

E01 DAY PRODUCTION

MSHA Form 7000-10I, June 93 (revised)

H608436

DAILY COVER SHEET

Date 3-23-10 Event No. 6086108

Arrived at the Mine 05:30 Departed from the Mine

List Records Books Checked Preshift

066-067 Portal Section

Accompanied By: Company Representative GARY MAY (Sup)

RICK FOSTER (Mine Foreman)

SHANNON PURDUE (Foreman)

Miners Representative Decline

None Present

AREAS OF INSPECTION ACTIVITY:

Resp. Dust, 066 MMU, X-Ray

Ran Resp Dust Results,

Methane Control Plan, Secondary

to Section, Imm. Danger

Runs 066-067, Dust Parameter

066 CM, Work cycle,

2ND Dust Parameter,

Inspector's Initials [redacted]

Supervisor's Initials and Date 3-26-10 [redacted] Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

Arrive at office

Gather PPE SK and

Bump test Detector

with known Mixture (OK)

SK and Prepare

(6) Resp. Dust Pumps

flow 2.0

Voltage Above 4.85

Pass, tubing, Battery

No Apparent Problem.

Change GRAY (CMT)

with conduit Dust

During this Insp.

on H608436.

066 MMU 2.0

067 MMU 0.8

Dust Standard

Date 3-23-10 Inspector's Initi [redacted]

Supervisor's D&I 3-26 [redacted] Page No. 2

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10N, June 93 (revised)

Date 3-23-10

RESPIRABLE DUST

Location Old Left side

PUMP	CASSETTE	CODE	OCCUPATION	TIME ON	2nd	4th	TIME OFF	HRS
R43	5783164	030	CM	0605				Y
292	5783383	050	SIC	0605				Y
293	5783169	048	RIB (OP)	0605				Y
976	5783142	046	RIB Helper	0605				Y
R46	5783165	802	Shuttle	0605				Y
R47	5783153	NOT USE. Return to HQ						

Inspector's Initials and Date [redacted] 3-24-10

Supervisor's Initials [redacted]

Page No. 3

*U.S.GPO:1993-0-700-382

MSHA Form 7000-10J, June 93 (revised)

Review MM
Physical Review
Spy Safeguard
Roof Visit Pillar
Review Book, Appear
Adequate.
Mine D- Status
3-17-09
# 8082692
75.360(A)(1)
Discussed Insp with
Mr. Gray Prepare
To Day Insp.
Through by GOO
Prior to Stabbing
Time to Old Portal
Along RT. 3,

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 4

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

Meet with:
Gary May Sup
Rick Foster Mine Foreman
Shane Purdue Section Boss.
Ask for Miners Rep
None Present at this
time
Review X-Ray Plans,
Methane Dust Plans
and Dust Results.
Pre-Shift
5:00 - 5:30
1-2 None Observed
3 Need Chains
4 L Scrap Cut
5-6-7-7R None Observed
8 Need Chains
LOB L 25,200 CFM
Right 20,480 CFM

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 5

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

Refuge Chamber, Travelway
Daily Precop, NO Hazards
Recorded.

[redacted] EXAM.

Portal Section.

Review WORK MAP
@ 8-7-6-5-4-3
Started.

Coal Crew works
AHP PORTAL to
PORTAL.

Check 3M831644
Intake Pump, Dust
Section (1) Pump will
Be used.

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 6

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

Raw tons 9.41
AHR 111 FT
8HR 98 FT
40' per side

Operator last 30
Production shifts
by any MM

Place Pumps on
Mined Out Area (3W
Continue Proper work
& Care.

Crew Are Short
Man, (1) RIB Crew
Working Between
Machines (2) 5/C
(1) Head
(1) Center

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 7

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

Travel with Coal Crew
to the 066-067 MMU

Safety Meeting
Conducted Discuss

Foreman Discuss;
Roof Control Plan,

Review Methane Dust
Plan;

Continue Mined Out
Area, Roof & Rib
Exam. Methane (OK)

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 8

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

Made Imm. Danger
Run Across Faces.

#7 Flush 0% ch4

#6 Flush 0% ch4

#5 Flush 0% ch4

#4 Flush 0% ch4

#4 L 35' 0% ch4
Need Bolted

#3 50' 0% ch4

#2-#1 Flush 0% ch4

#8 20' 0% ch4

DFT 20.8%, Area
Wet, Roof + Ribs Supported
Cleaning + Dusting (BA
Positive Pressure

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 9

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

LOB 24553 SSA
2 to 1 Turning Room
off Mains Right Hand.
0% ch4 20.8%

(1) Open Brk Left side

Controls In Place

Reflectors use

NVO

Made 1st ck of
Dump. Proper work
and In the Area
Being sample

MR. Gray Tissue Low
Dir Right side

7339 CFM
0% ch4 20.8%
7:40

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 10

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)



Date 3-23-10 Inspector's Initials [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 11

U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

Dust Parameter
JOY 12-12 CM
Serial JM4598 B
Examined
Plan 5 5 5
4 Plan 4 Plan
end of cutter Drum.
4 4
Spray towards Pan
3 Observed 3
Spraying towards Ribs
PLAN 75 3
OBSERV. 90
Total Plan 110
Observed
#5 Sprays
#3 towards Ribs

Date 3-23-10 Inspector's Initials [redacted]
Supervisor's D&I 3-26-10 [redacted] Page No. 12

U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

(CK) Cutting Rts
(OK)
9:30
Fletcher RIB
Operating In the
@ 4 to 3 X-Cut
Line Curtain
Configuration (Blowing)
Approved Plan Requires
Exhaust Vent.
RIB During Bolting
First Pass. Row 3
Tech 4 No Visible
Dust Present.
2 Mens Non S/S

Date 3-23-10 Inspector's Initials [redacted]
Supervisor's D&I 3-26-10 [redacted] Page No. 13

U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

Cit# 8086927
1 09:30
2 The Approved Vent
Methane and Dust Control
Plan for the 066MMU
is not being complied
with. The Fletcher
Roof Drill operating In
the 4 to 3 X-Cut
with The Line Curtain
Configuration FOR Blowing
Intake AIR IS Behind
the Line moving toward
the face. The Approved
Plan Required Exhaust
Line Curtain Configuration
Tech 4 present, No Visible
Air Born Dust present.
3 066 4 to 3 X-Cut
4 OP of Equipment
5 First Row less
than 15 Mins
6 2 Mens on RIB

Date 3-23-10 Inspector's Init [redacted]
Supervisor's D&I 3-26-10 [redacted] Page No. 14

U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

(7) NO LOST TIME

(8) MyHikely OCCUR
20.8 NO VISIBLE DUST
PRESENT.

09:43
CURTAIN MOVED TO
RIGHT SIDE EXHAUST
VENT AND 43400CFM
30 MINU RECORDED

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 15

U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

SPRAYS WERE IN
CHANGE POSITION, SPRAY
FITTING BROKE OFF IN
THE INLET FOR THAT SPRAY
BLOCK.

NO PRODUCTION. C/M
SET PARK FROM END OF
EVENING SHIFT UNTIL DAY
SHIFT BEGAN DUST
PARAMETERS

OBSERVE R/B CREW
#2 USING PPE AND
MOVING CBS. INSTALLING
#1 FULLY GROUT BOLTS.

GARY MAY (SUPT/BLACK)
INFORM MR. MAY THAT
I WAS VERY DISAPPOINTED
IN THE WAY THE SPRAYS
WERE BEING MAINTAINED ON
THE C/M. NO REMARKS

Date 3-23-10 Inspector's Initials [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 16

U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

10:30

18 SPRAYS INOPERABLE.
AND CITING BROKEN
TIP ON THE SPRAY BLOCK
LOCATED IN THE THROAT
CIT WILL BE ISSUED
THAT IS OBVIOUS THAT
THE SPRAYS ARE NOT
BEING MAINTAINED.
THOMAS RICK FOSTER
WAS IN WORKING PLACE
THIS WORK OBVIOUS.
MINERS WORK FROM
7:30 UNTIL 10:30

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 17

U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

CM Moved #1
Flush out, OP Throttle
Curtain + air Back
#1 Return Flush
Entry OP Make Ad/Justment
the Best As possible.

#1 Is A Rich Cut
10'
Observed Oh 4 (CM)
OPP by operator

(2) 10-SC Bull Fall
Behind the CM.

CM Moved to #2
Rich Cut, Inform
OP to throttle the
Air Back As practicle.
This is A Flush Cut
OP Try to throttle Curtain
Back Best As possible.

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I [redacted] 3-24-10 Page No. 18

U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

C.I.# 8086928

(1) 07:30

(2) The Approved Dust, Methane and Dust Control Plan for the 006 MMU is not Being Complied with. The water sprays for the JOY 12-12 CM, Ser # JM4598B were not Being Maintained. 21 of 40 Required Sprays were Inoperable. A fitting to the SPRAY Block to the Throat SPRAY was Broken. This Section is on a Reduce Standard of 0.8 mg/m3.

(3) 006 MMU

(4) OP Prev. Shift.

(5) Eve Shift Run the CM Title on MidNight, Very Obvious they Are not Maintaing the SPRAYS

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 19

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

(6) CM op. (2) SIC
3 Miners

(7) Permanently Disabling

(8) Reasonable Likely, Reduce Standard 0.8 mg/m3, Cutting 36" Rock, Silica, This miner, Iron, Any EXD could have Not got this Bad Shape between shifts

10:30

ALL SPRAYS 40 Operable and Fitting Replace

CM has back-on-toc a Previous Miner Cut.

Date 3-23-10 Inspector's Initial [redacted]

Supervisor's D&I 3-24-10 [redacted] Page No. 19-A

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

C.E Term 10LB
Water Sprays 40
Operable with 90 PSI
and fitting Replace
Observe Work cycle
Average Height
7.5 90"
Rock 36"
Middle Man Binder.
Fletcher RB
SER# 200-5069 (OK)
L Pot - 12 Hg
R Pot - 12 Hg

Date 3-23-10 Inspector's Initials [redacted]
Supervisor's D&I 3-24-10 [redacted] Page No. 20

MSHA Form 7000-10J, June 93 (revised)

Deep Cantact filters
Suction hoses
NVO
2ND Dust Personnel
40 SPRAYS
90 PSI
Lerfside
Cutting Bits
Observed of Fly Ash sweeping
Appears Adequate
CK Resp. Dist Pumps
throughout the shift
to ensure proper
flow, Cond. wear
And in the correct
environment.

Date 3-23 Inspector's Initials [redacted]
Supervisor's D&I 3-24-10 [redacted] Page No. 21

MSHA Form 7000-10J, June 93 (revised)

Made last hr CKs
Normal Flow 2.0
Gather Pumps off Miner
Sprays Production.
50' X 9.41 Ranton
4710 Tons
Travel to surface with
Pumps Travel Secondary
Fan Rail, Observed Surface
Water Pump
482 Mins
Discuss today Task
Observe Conference Rights
No Remarks
Issue 21 cits, Terra
Return to office, Clean, Store
Pumps on Ch. Prepare today
Reports

Date 3-23-10 Inspector's Initials [redacted]
Supervisor's D&I 3-24-10 [redacted] Page No. 22