PR001
24-Jul-14

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
Fatal Injury	Electrical	07/21/2014 03:50 PM	07/21/2014 03:50 PM	15

6. Mine Information :

a) Mining Company Name	b) Mine Name	c) Parent of Mining Company
Murray Mines Inc.	Murray Mines Inc.	James O Murray Jr

7. Mine Location : a) City	b) County	c) State	8. Mine ID Number:	9. Union:
Ridgeville	Colleton	SC	38-00136	NO

10. Primary Mineral Mined:	11. Number of Mine Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
CONSTRUCTION SAND & GRAVEL M	10	0	4	6	0

12. Contractor Name:	13. Union	14. Contractor ID Number:

15. Contractor Address: a) City	b) County	c) State	d) Zip Code

16. Number of Contractor Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other

17. Number of Persons in Mine at Time of Accident: a) Mine Employees:	b) Contractor Employees:	18. Number of Persons Unaccounted For: a) Mine Employees:	b) Contractor Employees:
8		0	0

19) Location of Accident

- [ ] 01-Underground
- [ ] 02-Surface at Underground
- [ ] 03-Open Pit
- [X] 06-Dredge Mining
- [ ] 07-Advance Mining
- [ ] 08-Retreat Mining
- [ ] 30-Mill/Prep Plant
- [ ] 99-Office Facility
- [ ] Other (specify)

20. Mining Height: Feet Inches

21. Nonfatal Injuries:	22. Fatal Injuries:
	1

23. Victim Information : a) Name	b) Age
Kyle R. Martin	28

c) Regular Job Title:	d) Activity at Time of Accident:	[X] Mine Employee
Assistant Plant Manager	Pulling Cable	

24. Experience :	Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days
a) Total:	11	8	0	b) at the mine:	11	8	0	c) at activity (23d)	11	8	0	d) with Contractor			

25. Autopsy Performed:	If Yes, Location	26. Mine Telephone No.:
YES	MUSC, Charleston, SC	(843) 835-2373

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was attempting to pull slack on the 480 volt power conductors feeding the dredge when the aluminum boat he was riding in contacted exposed conductors and he was electrocuted. First aid was performed and the victim was then transported to a medical facility where he was pronounced dead.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:

30. District:	32. Field Office:	33. Event Number:
M3000 Southeastern	Columbia SC	0926482

34. Accident Investigator:	35. MSHA Person Notified:	Date	Time
Stanley Stevenson	Patrick Sharp	07/21/2014	04:10 P

36. Type of Report:	37. Name of Preparer and Date Prepared	Date
Initial	Mike Hancher MH	07/24/2014

38. Reason For Amendment: