PRESHIFT/ON-SHIFT REPORT
FOR
GENERAL MINE

GENWAL

Mine Name

ID Number

Crandall

SECTION / AREA

2MSHA03582

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11/12/06 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 4:20 AM/PM END 4:36 AM/PM Examiners Initials GA
TIME OF EXAMINATION START 4:25 AM/PM END 4:42 AM/PM Examiners Initials CH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	GA	OK	None observed	
main north Haulage, Seals	21	0	0	BH	OK	none obs	
main west Haulage, seals	21	0	0	LH/BH	OK	none obs	
3rd north Haulage, seals	21	0	0	BH	OK	none obs	
1ST Right	21	0	0	BH	OK	none obs	
Transformers	21	0	0	BH	OK	none obs	
Chargers	21	0	0	BH	OK	none obs	
wash down	21	0	0	BH	OK	none obs	
storage	21	0	0	BH	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe for work & Travel at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 03892
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03583

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-17-06 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 1145 AM/PM END 105 AM/PM Examiners Initials FD
TIME OF EXAMINATION START 11:00 AM/PM END 1:10 AM/PM Examiners Initials Fm/M
TIME OF EXAMINATION START 11:00 AM/PM END 1:10 AM/PM Examiners Initials mc

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Underground Parking	21	0	0	FD	OK	None obs.	
North mains Haulage and Seals	21	0	0	FD	OK	None obs.	
West Mains Haulage and Seals	20.9	0	0	FD/mc Fm	ok	none observed	
3rd North Mains Haulage and Seals	21	0	0	FD	OK	None obs.	
1st Right Haulage	21	0	0	FD	OK	None obs.	
Transformers	21	0	0	FD/mc	ok	none observed	
Chargers	21	0	0	FD	OK	None obs.	
Wash down	20.9	0	0	Fm	ok	none observed	
Storage Area	20.9	0	0	Fm	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 475

2MSHA03584

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-17-06 SECTION/AREA Gen. Mine / /

TIME OF EXAMINATION START 7:50 AM/PM END 8:00 AM/PM Examiners Initials LR/RL/KK
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Underground Parking Area	21.0	0	0	LR	OK	None obs	
Main North Haulage and Seals	21.0	0	0	LR	OK	None obs.	
3rd North Haulage and Seals	21.0	0	0	LR	OK	None obs.	
1st Right Haulage	21.0	0	0	LR	OK	None obs	
Transformers	21.0	0	0	LR/RL/KK	OK	None obs	
Chargers	21.0	0	0	LR	OK	None obs	
Washdown	21.0	0	0	RL	OK	None obs	
Storage Area	21.0	0	0	RL	OK	None obs	
West Main Haulage and Seals	21.0	0	0	LR/RL/KK	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6601
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 4735

2MSHA03585

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-18-06 SECTION/AREA Gen Mine / / / /

TIME OF EXAMINATION START 300 AM/PM END 535 AM/PM Examiners Initials RL JR BK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
underground parking area	20.9	0	0	RL	OK	None observed	
No Mains Haulage Seals	21	0	0	RL	OK	none observed	
West Mains Haulage Seals	20.9	0	0	RL/KK/JR	OK	None observed	
3rd North Haulage Seal	21	0	0	RL	OK	none observed	
1st Right Haulage	21	0	0	RL	OK	none observed	
Transformers	20.9	0	0	RL/JR/RL	OK	None	
chargers	20.9	0	0	JR/RL	OK	None	
washdown	20.9	0	0	JR	OK	None	
Storage area	20.9	0	0	JR	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS ____

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4325
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6481
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATUR [redacted] CERT. # 8462

2MSHA03586

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-16-06 SECTION/AREA Gen. mine / / / /

TIME OF EXAMINATION START 1130 AM/PM END 100 AM/PM Examiners Initials FD/MD
TIME OF EXAMINATION START 11:03 AM/PM END 12:25 AM/PM Examiners Initials MC
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	None observed	
North Mains Haulage Seals	20.9	0	0	MC	OK	None observed	
3rd North Haulage Seals	20.9	0	0	MC	OK	None observed	
1st Right	20.9	0	0	MC	OK	None observed	
West Mains Haulage Seals	21	0	0	FD/MD/MC	OK	None obs	
Transformers	21	0	0	MD/MC	OK	None observed	
Chargers	20.9	0	0	MC	OK	None observed	
Whasdown	21	0	0	MD	OK	None obs.	
Storage Area	21	0	0	FD	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe At Time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9558
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9692
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8X5
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 4733

2MSHA03587

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-18-06 SECTION/AREA Gen. Mine

TIME OF EXAMINATION START 7:00 AM/PM END 9:30 AM/PM Examiners Initials RR/KK
TIME OF EXAMINATION START 8:30 AM/PM END 9:40 AM/PM Examiners Initials RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Underground Parking Area	21.0	0%	0			None	
North Main Haulage Seals	21.0	0	0	RL	OK	None	
West Main Haulage Seals	21.0	0	0	LR/KK	OK	None	
3rd North Haulage Seals	21.0	0	0	RL	OK	None	
1st Right Haulage	21.0	0	0	RL	OK	None	
Transformers	21.0	0	0	LR/KK	OK	None	
Chargers	21.0	0	0	RL	OK	None	
Washdown	21.0	0	0	LR	OK	None	
Storage Area	21.0	0	0	LR	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6806
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 4735

2MSHA03588

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-19-06 SECTION/AREA Gen Mines / / /

TIME OF EXAMINATION START 3:01 AM/PM END 3:48 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 3:00 AM/PM END 520 AM/PM Examiners Initials LR/RL
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	ok	None obs.	
main North haulage	20.9	0	0	KK	ok	None obs.	
3rd north	20.9	0	0	KK	ok	None obs	
1st right	20.9	0	0	KK	ok	None obs.	
Trans.	20.9	0	0	KK/LR/RL	ok	None obs.	
chargers	21.0	0	0	LR/RL	OK	None obs.	
Washdown	21.0	0	0	LR	OK	None obs.	
Storage area	21.0	0	0	LR	OK	None obs.	
Main West haulage	21.0	0	0	LR/RL	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4373
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. #

COUNTER SIGNATURE [redacted] CERT. # 8482

2MSHA03589

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-19-06 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 1130 AM/PM END 105 AM/PM Examiners Initials JD/mc
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	MD/FD	OK	none obs	
North Mains Haulage Seals	21	0	0	MD/FD	OK	none obs	
West Mains Haulage Seals	21	0	0	JD/mc	OK	None obs.	
3rd North Haulage Seals	21	0	0	MD/FD	OK	none obs	
1st Right	21	0	0	MD/FD	OK	none obs	
Transformers	21	0	0	mc/MD	OK	none obs	
Chargers	21	0	0	MD	OK	none obs	
Washdown	21	0	0	mc	OK	None obs.	
Storage Area	21	0	0	JD	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7545
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9692
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE Signature [redacted] CERT. # 4135

2MSHA03590

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-19-06 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 8:00 AM/PM Examiners Initials LR
TIME OF EXAMINATION START 7:00 AM/PM END 9:05 AM/PM Examiners Initials KK/RL
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	LR	OK	None obs.	
North Mains Haulage Seals	21.0	0	0	LR	OK	None obs.	
West Mains Haulage Seals	20.9	0	0	LR/KK/RL	OK	None obs.	
3rd North Haulage Seals	21.0	0	0	LR	OK	None obs.	
1st Right Haulage	21.0	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	LR/KK/RL	OK	None obs.	
Chargers	21.0	0	0	LR	OK	None obs.	
Washdown Area	21.0	0	0	LR	OK	None obs	
Storage Area	21.0	0	0	LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 2954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 4135

2MSHA03591

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-20-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 5:20 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START 3:50 AM/PM END 5:50 AM/PM Examiners Initials RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	RL	OK	none observed	
North Mains Haulage Seals	20.9	0	0	RL	OK	none "	
West Mains Haulage Seals	21.0	0	0	LR/KK	OK	None obs.	
3rd North Haulage Seals	20.9	0	0	RL	OK	none	
1st Right Haulage	20.9	0	0	RL	OK	none	
Timos Sommers	21.0	0	0	LR/RL/KK	OK	None obs.	
Chargers	21.0	0	0	RL	OK	none	
Wash down Area	21.0	0	0	RL	OK	none	
Storage Area	21.0	0	0	RL	OK	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Preshift

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 1954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 03892

2MSHA03592

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-20-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 1:05 AM/PM Examiners Initials BH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage seals	20.9	0	0	BH	OK	None Observed	
3rd North Haulage seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Storage Area's	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE SIGNATURE CERT. # 03892

2MSHA03593

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-20-06 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 7:00 AM/PM END 8:45 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 7 AM/PM END 8:40 AM/PM Examiners Initials dg
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Praking Area	20.9	0	0	dg	ok	None observed	
North Mains Haulage Seals	20.9	0	0	dg	ok	none observed	
West mains Haulage Seals	20.9	0	0	LD	ok	none obs	
3rd North Haulage Seals	20.9	0	0	LD	ok	none obs	
1st Right Haulage	20.9	0	0	LD	ok	none obs	
transformers	20.9	0	0	LD dg	ok	none observed	
chargers	20.9	0	0	LD	ok	none obs	
Washdown Area	20.9	0	0	LD	ok	none obs	
Storage Area	20.9	0	0	LD	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas Examined appear Safe at Time of preshift

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9660
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 6622
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE SIGNATURE CERT. # 7488

2MSHA03594

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-21-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 5:00 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 3 AM/PM END 3:35 AM/PM Examiners Initials dy
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS ~~Parking Area~~	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
North mains Haulage Seals	20.9	0	0	dy	ok	none observed	
West mains Haulage Seals	20.9	0	0	LD	ok	none obs	
3rd North Haulage Seals	20.9	0	0	LD	ok	none obs	
1st Right Haulage	20.9	0	0	LD	ok	none obs	
transformers	20.9	0	0	~~LD~~ dy	ok	none observed	
chargers	20.9	0	0	LD	ok	none obs	
washdown Area	20.9	0	0	LD	ok	none obs	
storage Area	20.9	0	0	LD	ok	none obs	
Parking Area							

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9660
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6622
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 03892

2MSHA03595

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-21-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:10 AM/PM END 12:55 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 11:05 AM/PM END 11:37 AM/PM Examiners Initials FM
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	None	
Main North Haulage Seals	20.9	0	0	FM	ok	None	
Main West Haulage Seals	20.9	0	0	BH	ok	None	
3rd North Haulage Seals	20.9	0	0	BH	ok	None	
1st Right Haulage	20.9	0	0	BH	ok	None	
Transformers	20.9	0	0	BH/FM	ok	None	
Chargers	20.9	0	0	BH	ok	None	
Washdown	20.9	0	0	BH	ok	None	
Storage areas	20.9	0	0	BH	ok	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03596

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-21-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 8:45 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 7 AM/PM END 830 AM/PM Examiners Initials dg
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	dg	ok	none observed	
main North Haulage Seals	20.9	0	0	dg	ok	none observed	
Main West Haulage Seals	20.9	0	0	LD	ok	none obs	
3rd North Haulage Seals	20.9	0	0	LD	ok	none obs	
1st Right Haulage	20.9	0	0	LD	ok	none obs	
transformers	20.9	0	0	~~LD~~ dg	ok	none observed	
chargers	20.9	0	0	LD	ok	none obs	
washdown	20.9	0	0	LD	ok	none obs	
storage Area	20.9	0	0	LD	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9660
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE SIGNATURE CERT. # 1485

2MSHA03597

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-22-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 5:00 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 3 AM/PM END 3:30 AM/PM Examiners Initials [illegible]
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	dy	ok	none observed	
Main North Haulage Seals	20.9	0	0	dy	ok	None observed	
Main west Haulage Seals	20.9	0	0	LD	ok	none obs	
3rd North Haulage Seals	20.9	0	0	LD	ok	none obs	
1st Right Haulage	20.9	0	0	LD	ok	none obs	
transformers	20.9	0	0	LD/dy	ok	None observed	
Chargers	20.9	0	0	LD	ok	none obs	
washdown	20.9	0	0	LD	ok	none obs	
storage Area	20.9	0	0	LD	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas Examined appear safe at time of pres. shift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9660
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6622
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03598

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-22-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:10 AM/PM END 12:55 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 11:05 AM/PM END 11:40 AM/PM Examiners Initials FM
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None	
Main North Haulage Seals	20.9	0	0	FM	OK	None	
Main West Haulage Seals	20.9	0	0	BH	OK	None	
3rd North Haulage Seals	20.9	0	0	BH	OK	None	
1st Right Haulage	20.9	0	0	BH	OK	None	
Transformers	20.9	0	0	BH/FM	OK	None	
Chargers	20.9	0	0	BH	OK	None	
Washdown	20.9	0	0	BH	OK	None	
Storage Area's	20.9	0	0	BH	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Area appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8395
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8397
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE SIGNATURE CERT. # 03892

2MSHA03599

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 112206 SECTION/AREA Genitine / / /

TIME OF EXAMINATION START 735 AM/PM END 9 AM/PM Examiners Initials dg
TIME OF EXAMINATION START 7:33 AM/PM END 9:04 AM/PM Examiners Initials TC
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	dg	ok	None observed	
Main North Haulage seals	20.9	0	0	dg	ok		
3rd No Haulage seals	20.9	0	0	dg	ok		
1st Right Haulage	20.9	0	0	dg	ok	None observed	
Main West Haulage seals	20.9	0	0	TC	ok	None obs.	
Transformers	20.9	0	0	TC/dg	ok	None obs.	
chargers	20.9	0	0	TC	ok	None obs.	
washdown	20.9	0	0	TC	ok	None obs.	
Storage areas	20.9	0	0	TC	ok	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe. At time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 6622
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 7485

2MSHA03600

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1/23 06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:50 AM/PM END 4 AM/PM Examiners Initials dy
TIME OF EXAMINATION START 3:00 AM/PM END 4:02 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 3:00 AM/PM END 4:10 AM/PM Examiners Initials SW

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	dy	ok	None observed	
Main North Haulage & seals	20.9	0	0	SW	ok	none obs.	
Main West Haulage & seals	20.9	0	0	TC/SW	ok	None obs.	
3rd Haulage & seals North	20.9	0	0	SW	ok	none obs.	
1st Right Haulage	20.9	0	0	SW	ok	none obs.	
Transformers	20.9	0	0	TC/SW	ok	none obs.	
Chargers	20.9	0	0	TC/SW	ok	none obs.	
Washdown	20.9	0	0	TC	ok	none obs	
storage areas	20.9	0	0	SW	ok	none obs.	
Belt Transformers	20.9	0	0	TC/SW	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared to Be Safe At Time of Exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 6622
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 7485

2MSHA03601

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-24-06 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 4:02 AM/PM END 5:01 AM/PM Examiners Initials RM
TIME OF EXAMINATION START 3:00 AM/PM END 5:15 AM/PM Examiners Initials JD mc
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	RM	OK	NONE OBSERVED	
Main North Seals & haulage	20.9	0	0	RM	OK		
3rd North Haulage & Seals	20.9	0	0	RM	OK		
1st Right haulage	20.9	0	0	RM	OK	NONE OBSERVED	
Tranformers	20.9	0	0	RM/MC/FD	OK	none observed	
Main West haulage & Seals	20.9	0	0	MC/FD	OK	none observed	
Chargers	20.9	0	0	RM	OK	none observed	
Washdown	20.9	0	0	MC	OK	none observed	
storage areas	20.9	0	0	MC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 6845
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7375
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9458
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 8462

2MSHA03602

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-24-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 11:30 AM/PM Examiners Initials MC Fm
TIME OF EXAMINATION START 1:33 AM/PM END 1:46 AM/PM Examiners Initials DD/FD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc/Fm	ok	none observed	
Main North Haulage Seals	20.9	0	0	mc/Fm	ok	none observed	
Main West Haulage Seals	21	0	0	DD/FD	ok	none obs.	
3rd North Haulage Seals	21	0	0	DD/FD	ok	none obs.	
1st Right Haulage	21	0	0	DD/FD	ok	none obs.	
Transformers	21	0	0	Fm/FD	ok	none obs.	
Chargers	21	0	0	DD	ok	none obs.	
Washdown	21	0	0	DD	ok	none obs.	
Storage Area	21	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. #
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03603

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-24-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 700 AM/PM END 1000 AM/PM Examiners Initials KK/BR/RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	21.0	0	0	KK	OK	None obs.	
main North Haulage seals	21.0	0	0	KK	OK	None obs.	
Main West Haulage seals	20.9	0	0	KK/BR/RL	OK	None obs	
2nd North Haulage seals	20.9	0	0	KK	OK	None obs.	
1st Right Haulage	20.9	0	0	KK	OK	None obs.	
Storage area	20.9	0	0	KK	OK	None obs.	
Washdown	20.9	0	0	KK	OK	None obs.	
Trans	20.9	0	0	KK/BR/RL	OK	None obs	
Chargers	20.9	0	0	KK/BR/RL	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas apparent Safe at time of Exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 4735

2MSHA03604

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-25-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 515 AM/PM Examiners Initials KR/KR/KL
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	None obs.	
Main North Haulage seal	20.9	0	0	KK	OK	None obs.	
Main West Haulage seal	20.9	0	0	KK/KR/KL	OK	None obs	
2nd North Haulage seal	20.9	0	0	KK	OK	None obs.	
1st Right	20.9	0	0	KK	OK	None obs	
Chargers	20.9	0	0	KK/KR/KL	OK	None.	
Tramm	20.9	0	0	KK/KR/KL	OK	None obs	
Washdown	20.9	0	0	KK	OK	None.	
Storage area	20.9	0	0	KK	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved safe at time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6407
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03605

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-25-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 1100 AM/PM END 200 AM/PM Examiners Initials DD FD
TIME OF EXAMINATION START 11:00 AM/PM END 12:13 AM/PM Examiners Initials MC
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking	20.9	0	0	MC	OK	none observed	
main North haulage seals	20.9	0	0	MC	OK	none observed	
main West haulage seals	21	0	0	DD/FD	ok	none obs.	
3rd North Haulage Seals	20.9	0	0	MC	OK	none observed	
1st Right Haulage	20.9	0	0	MC	OK	none observed	
Trans.	21	0	0	DD/FD	ok	none obs	
Chargers	21	0	0	MC	ok	none obs.	
Wash down	21	0	0	FD	ok	none obs.	
Storage Area	21	0	0	FD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe At time of preshift

PRE-SHIFT/MINE EXAMINE[redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINE[redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINE[redacted] CERT. # 9158
PRE-SHIFT/MINE EXAMINER[redacted] CERT. #

COUNTER SIGNATUR[redacted] CERT. # 8462

2MSHA03606

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-25-06 SECTION/AREA Gen. Mine / /

TIME OF EXAMINATION START 700 AM/PM END 820 AM/PM Examiners Initials LR/KK/RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs.	
Main North Haulage Seals	20.9	0	0	LR	OK	None obs.	
Main West Haulage Seals	20.9	0	0	LR/KK/RL	0	None obs.	
3rd North Haulage Seals	20.9	0	0	LR	OK	None obs.	
1st Right Haulage	20.9	0	0	LR	OK	None obs	
Turns.	20.9	0	0	LR/KK/RL	OK	None obs	
Chargers	20.9	0	0	LR/KK/RL	O	None obs	
Wash down Area	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	LR	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature [redacted]

PRE-SHIFT/MINE EXAMINER _____ CERT. # 4325
PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
PRE-SHIFT/MINE EXAMINER _____ CERT. # 6401
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

SIGNATURE [redacted]

COUNTER SIGNATURE _____ CERT. # 8925

2MSHA03607

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-26-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 5:40 AM/PM Examiners Initials KK
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking areas	20.9	0	0	KK	OK	None obs.	
Main North Haulage	20.9	0	0	KK	OK	None obs.	
Main West Haulage	20.9	0	0	KK	OK	None obs.	
3rd North Haulage	20.9	0	0	KK	OK	None obs.	
1st Right	20.9	0	0	KK	OK	None obs	
Trans	20.9	0	0	KK	OK	None obs	
chargers	20.9	0	0	KK	OK	None obs.	
Washdown	20.9	0	0	KK	OK	None obs	
Storage area	20.9	0	0	KK	OK	None obs.	
Belt Kitcher	20.9	0	0	KK	OK	None.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7954
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 8462

2MSHA03608

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-26-06 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 1110 AM/PM END 1215 AM/PM Examiners Initials FD
TIME OF EXAMINATION START 1100 AM/PM END 200 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	FD	OK	None obs.	
West mains Haulage Seals	21	0	0	FD/mc/DD	OK	None observed	
3rd North Haulage Seals	21	0	0	FD	OK	None obs.	
1st Right	21	0	0	FD	OK	None obs.	
Transformers	21	0	0	FD/mc/DD	OK	None observed	
Chargers	21	0	0	FD/DD	OK	None observed	
Wash down	20.9	0	0	mc	OK	None observed	
Storage Area	20.9	0	0	mc	OK	None observed	
~~Belt Head~~							

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonally safe At time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03609

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-26-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 700 AM/PM END 935 AM/PM Examiners Initials KK/RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	DG	ok	none obs.	
Main North Haulage seal	20.9	0	0	KK	ok	None obs.	
Main West Haulage seals	20.9	0	0	KK/RL	ok	none obs	
5th North Haulage seals	20.9	0	0	KK	ok	None obs	
1st right	20.9	0	0	KK	ok	none	
Texans.	20.9	0	0	KK/RL	ok	None	
Chargers	20.9	0	0	KK/RL	ok	None	
Washdown	20.9	0	0	KK	ok	none	
storage area	20.9	0	0	KK	ok	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7154
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 4735
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 4735

2MSHA03610

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-27-06 SECTION/AREA Gen Mine / / / /

TIME OF EXAMINATION START 3:00 AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START 3:09 AM/PM END 4:15 AM/PM Examiners Initials mc
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	mc	ok	none observed	
Main North Haul	20.9	0	0	mc	ok	none observed	
Main West Haul	20.9	0	0	mc/RK/RL	ok	Deep Water x-cut 63	Sent 1 man to pump Pump need repaired
3rd north haulage	20.9	0	0	mc	ok	none observed	Pumped out 11-27-06 BH
1st Right Haul.	20.9	0	0	mc	ok	none observed	
Storage area	20.9	0	0	RL	ok	None	
Washdown	20.9	0	0	KK	ok	None	
chargers	20.9	0	0	mc	ok	none observed	
Trans.							

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas seemed reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 03892

2MSHA03611

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-27-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:10 AM/PM END 12:38 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 11:53 AM/PM END 12:54 AM/PM Examiners Initials MC/FM
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North Haulage Seals	20.9	0	0	MC/FM	OK	None observed	
Main West Haulage Seals	20.8	0	0	BH	OK	Deep water X-cut 63	Pump needs repaired Pumped 11/27/06 OK
Parking Area	20.9	0	0	MC/FM	OK	None observed	
3rd North Haulage Seals	20.9	0	0	MC/FM	OK	None observed	
1st Right Haulage	20.9	0	0	MC	OK	None observed	
Transformers	20.9	0	0	BH/MC	OK	None observed	
Chargers	20.9	0	0	BH/MC	OK	None observed	
Wash down	20.9	0	0	BH	OK	None Observed	
Storage Area	20.8	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe At time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03612

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-27-06 SECTION/AREA Crandall General Mine

TIME OF EXAMINATION START 7:30 AM/PM END 9:00 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:10 AM/PM END 7:45 AM/PM Examiners Initials TC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area.	20.9	0	0	TC	OK	none obs.	
Main North haulage seals	20.9	0	0	TC	OK	none obs	
Main West haulage seals	20.9	0	0	SW	OK	none observed	
3rd North haulage seals	20.9	0	0	SW	OK	none observed	
1st Right haulage	20.9	0	0	SW	OK	none observed	
Transformers.	20.9	0	0	TC/SW	OK	none observed	
chargers	20.9	0	0	TC/SW	OK	none observed	
washdown	20.9	0	0	SW	OK	none observed	
Storage Area.	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area Appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9548
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9362
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03613

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-28-06 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 3:00 AM/PM END 4:05 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 3 AM/PM END 330 AM/PM Examiners Initials dg
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
4b Parking	20.9	0	0	TC	OK	none obs.	
Main North Haulage Seals	20.9	0	0	TC	OK	none obs.	
Main West Haulage Seals	20.9	0	0	TC/dg	OK	none obs.	
3rd North Haulage Seals	20.9	0	0	TC/	OK	none obs.	
1st Right Haulage	20.9	0	0	TC	OK	none obs.	
Transformers	20.9	0	0	TC/dg	OK	none obs.	
Chargers	20.9	0	0	TC/JG	OK	None obs.	
Washdown	20.9	0	0	JG	OK	NONE OBSERVED	
Storage Area	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 7485
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03614

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11/28/06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 1210 AM/PM END 1259 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 12:30 AM/PM END 103 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 11:48 AM/PM END 1:05 AM/PM Examiners Initials FM

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	209	0	0	FM	OK	None observed	
main north Haulage, seals	209	0	0	FM	OK	none observed	
main west Haulage, seals	21	0	0	LH/BH	OK	none observed	
3rd north	209	0	0	FM	OK	none observed	
1st Right	209	0	0	FM	OK	none observed	
Transformers	21	0	0	LH/FM BH	OK	none observed	
Chargers	21	0	0	LH	OK	none observed	
wash down	21	0	0	BH	OK	none observed	
storage Area	21	0	0	BH	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe for work & Travel at Time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8385
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 03892

2MSHA03615

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-28-06 SECTION/AREA Examina / / /

TIME OF EXAMINATION START 7:00 AM/PM END 8:15 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 7:39 AM/PM END 9:15 AM/PM Examiners Initials LD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	TC	ok	none obs.	
Main North Haulage Seals	20.9	0	0	TC	ok	none obs.	
Main West Haulage Seals	20.9	0	0	TC/LD	ok	none obs.	
3RD North Haulage Seals.	20.9	0	0	TC	ok	none obs.	
1ST Right Haulage [redacted]	20.9	0	0	TC	ok	none obs.	
Transformers	20.9	0	0	TC/LD	ok	none obs.	
Chargers	20.9	0	0	TC/LD	ok	none obs.	
Washdown	20.9	0	0	LD	ok	none obs	
Storage Area	20.9	0	0	LD	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas appeared Safe at Time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9660
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03616

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-29-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 4:05 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 3:40 AM/PM END 5:10 AM/PM Examiners Initials LD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	TC	ok	none obs.	
Main North Haulage Seals	20.9	0	0	TC	ok	none obs.	
Main West Haulage Seals	20.9	0	0	TC/LD	ok	none obs.	
3rd North Haulage Seals	20.9	0	0	TC	ok	none obs.	
1st Right Haulage	20.9	0	0	TC	ok	none obs.	
Transformers	20.9	0	0	TC/LD	ok	none obs.	
Chargers	20.9	0	0	TC/LD	ok	none obs.	
Washdown	20.9	0	0	LD	ok	none obs	
Storage Area	20.9	0	0	LD	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas appeard Safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9660
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature [redacted] CERT. # 03892

2MSHA03617

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-29-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 12:22 AM/PM END 12:46 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 1203 AM/PM END 1253 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 11:55 AM/PM END 1:10 AM/PM Examiners Initials Fm

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	α	none observed	
main North Haulage Seals	20.9	0	0	FM	α	none observed	
main west Haulage Seals	20.9	0	0	LH/BP	ok	none observed	
3rd north Haulage Seals	20.9	0	0	FM	α	none observed	
1st Right Haulage	20.9	0	0	FM	α	none observed	
Transformers	20.9	0	0	LH/BP	ok	none observed	
chargers	20.9	0	0	LH/BP	ok	none observed	
washdown	20.9	0	0	LH/BP	ok	none observed	
Storage Area	20.9	0	0	LH/BP	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9599
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8997
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 0889R

2MSHA03618

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-29-06 SECTION/AREA Crandall / General / Mine. /

TIME OF EXAMINATION START 7:47 AM/PM END 8:50 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7 AM/PM END 9:15 AM/PM Examiners Initials dg
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	ok	none observed	
Main North Seals haulage	21.0	0	0	SW	ok	none observed	
Main West haulage Seals	21.0	0	0	~~dg~~ SW	ok	None observed	
3rd North Haulage Seals	21.0	0	0	SW	ok	none observed	
1st Right haulage	21.0	0	0	SW	ok	none observed	
Transformers	21.0	0	0	~~dg~~ SW	ok	None observed	
chargers	21.0	0	0	~~SW~~ dg	ok	None observed	
washdown	20.9	0	0	dg	ok	none observed	
Storage Area	20.9	0	0	dg	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

PRE-SHIFT/MINE EXAMINER Signature [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE Signature [redacted] CERT. # 7485

2MSHA03619

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-30-06 SECTION/AREA Crandall / Mine / / /

TIME OF EXAMINATION START 3:57 AM/PM END 5:00 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:30 AM/PM END 5:25 AM/PM Examiners Initials dg
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	ok	none observed	
Main North haulage seals	21.0	0	0	SW	ok	none observed	
Main West haulage seals	21.0	0	0	dg/SW	ok	none observed	
3rd North haulage seals	21.0	0	0	SW	ok	none observed	
1st Right haulage	21.0	0	0	SW	ok	none observed	
Transformers	21.0	0	0	dg/SW	ok	none observed	
Chargers	21.0	0	0	dg/SW	ok	none observed	
wash down	20.9	0	0	dg	ok	none observed	
Storage Area	20.9	0	0	dg	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6622
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

SIGNATURE

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03620

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-30-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 12:00 AM/PM END 1:05 AM/PM Examiners Initials BH/LH
TIME OF EXAMINATION START 11:53 AM/PM END 1:25 AM/PM Examiners Initials FM
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	none observed	
Main North Haulage Seals	20.9	0	0	FM	ok	none observed	
main west Haulage Seals	20.9	0	0	BH/LH/FM	ok	none observed	
3rd North Haulage Seals	20.9	0	0	FM	ok	none observed	
1st Right Haulage	20.9	0	0	FM	ok	none observed	
transformers	20.9	0	0	BH/LH/FM	ok	none observed	
Chargers	20.9	0	0	FM	ok	none observed	
Washdown	20.9	0	0	FM	ok	none observed	
Storage Area	20.9	0	0	FM	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8385
PRE-SHIFT/MINE EXAMINER CERT. # 8703
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03621

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 11-30-06 SECTION/AREA Crandall / General / Mine /

TIME OF EXAMINATION START 7:53 AM/PM END 8:45 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:30 AM/PM END 8:35 AM/PM Examiners Initials dg
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area.	21.0	0	0	SW	OK	none observed	
Main North Seals haulage	21.0	0	0	SW	OK	none observed	
Main West haulage Seals	21.0	0	0	SW	OK	none observed	
3rd North haulage Seals	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	dg/SW	OK	none observed	
Charging	21.0	0	0	dg/SW	OK	none observed	
Washdown	20.9	0	0	dg	ok	None observed	
Storage Area.	20.9	0	0	dg	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6622
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03622

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-1-06 SECTION/AREA Crandall / General / Mine /

TIME OF EXAMINATION START 3:50 AM/PM END 5:00 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 4:20 AM/PM END 5:30 AM/PM Examiners Initials TC
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area.	21°	0	0	SW	ok	none observed	
Main North seals haulage	21.0	0	0	SW	ok	none observed	
Main West haulage seals	21.0	0	0	TC/SW	ok	none obs.	
3rd North seals haulage	21.0	0	0	SW	ok	none observed	
1st Right haulage	21.0	0	0	SW	ok	none observed	
Transformers.	21.0	0	0	TC/SW	ok	none obs.	
Chargers	21.0	0	0	TC/SW	ok	none obs.	
Washdown	20.9	0	0	TC	ok	none obs.	
Storage Area.	20.9	0	0	TC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All AREAS APPEARED Safe AT Time Of Exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9548
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 4735

2MSHA03623

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-1-06 SECTION/AREA Gen / / /

TIME OF EXAMINATION START 11:00 AM/PM END 1:45 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	ok	None	
Main North Haulage Seals	20.9	0	0	KK	ok	None	
Main West Haulage Seals	20.9	0	0	RL/LR	ok	none	
3rd North Haulage Seals	20.9	0	0	KK	ok	None	
1st Right	20.9	0	0	KK	ok	None	
Travis	20.9	0	0	KK RL/LR	ok	none	
chargers	20.9	0	0	KK RL/LR	ok	none	
Washdown	20.9	0	0	KK	ok	None	
Storage	20.9		0	KK	ok	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature [redacted]

PRE-SHIFT/MINE EXAMINER ____ CERT. # 7954
PRE-SHIFT/MINE EXAMINER ____ CERT. # 6404
PRE-SHIFT/MINE EXAMINER ____ CERT. # 4355
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

SIGNATURE [redacted]

COUNTER SIGNATURE ____ CERT. # 8462

2MSHA03624

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-1-06 SECTION/AREA Gen. / / /

TIME OF EXAMINATION START 700 AM/PM END 900 AM/PM Examiners Initials DD/MD
TIME OF EXAMINATION START 500 AM/PM END 910 AM/PM Examiners Initials JD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	JD	OK	None obs.	
main North Haulage seals	21	0	0	JD	OK	None obs.	
main West Haulage seals	21	0	0	DD/MD	ok	none obs.	
3rd North Haulage seals	21	0	0	JD	OK	See below	working on it is all over 12-1-06
1st Right	21	0	0	JD	OK	None obs.	
Trans.	21	0	0	DD/MD	ok	none obs.	
Chargers	21	0	0	JD	OK	None obs.	
Washdown	21	0	0	MD	ok	none obs.	
Storage	21	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Transformer Room x-cut 5 needs vent and a Fire extinguiser. Rest appeared to be safe

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9158
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9692
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 7462

2MSHA03625

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-2-06 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 330 AM/PM END 520 AM/PM Examiners Initials FD MD
TIME OF EXAMINATION START 300 AM/PM END 500 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
North Mains Haulage Seals	21	0	0	DD	ok	none obs	
Westmains Haulage Seals	21	0	0	FD/MD	ok	None obs.	
3rd North Haulage Seals	21	0	0	DD	ok	none obs.	
1st Right	21	0	0	DD	ok	none obs.	
Transformers	21	0	0	FD/MD	ok	None obs.	
Chargers	21	0	0	DD	ok	none obs.	
~~Wash~~ washdown	21	0	0	MD	ok	none obs	
Storage Area	21	0	0	FD/MD	ok	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9692
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 4735

2MSHA03626

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-02-06 SECTION/AREA Fan Mine / / /

TIME OF EXAMINATION START 1100 AM/PM END 110 AM/PM Examiners Initials RL/KK/
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	21	Ø	Ø		Ø	None	
No Main Haulage Seals	21	Ø	Ø		Ø	Rib Roll #21xc	Cleaned 12-2-06 ZR
W Main Haulage Seals	21	Ø	Ø	RL	Ø	None	
3rd North Haulage Seals	21	Ø	Ø		Ø	None	
1st Right	21	Ø	Ø		Ø	None	
Transformers	21	Ø	Ø		Ø	None	
Chargers	21	Ø	Ø		Ø	None	
Washdown	21	Ø	Ø		Ø	None	
Storage Area	21	Ø	Ø		Ø	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 4325
PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 8462

2MSHA03627

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-2-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:06 AM/PM END 8:20 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 700 AM/PM END 935 AM/PM Examiners Initials FD DD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
main north Haulage seals	20.9	0	0	mc	ok	none observed	
main west Haulage seals	21	0	0	mc/FD DD	ok	None obs.	
3rd north Haulage seals	20.9	0	0	mc	ok	Trans Room x out 6 needs dusted Fire Ext needs insp tag	Done 12-2-06 mc
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	21	0	0	mc/FD	ok	None obs.	
Chargers	21	0	0	mc/FD	OK	None obs.	
washdown	21	0	0	FD	OK	None obs	
storage Area	21	0	0	DD	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared to be safe, except what's noted above.

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 9458
PRE-SHIFT/MINE EXAMINER CERT. # 80058
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 82462

2MSHA03628

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-3-06 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 515 AM/PM Examiners Initials FD-MC
TIME OF EXAMINATION START 300 AM/PM END 405 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Areas	21	0	0	DD	ok	none obs	
North Mains Haulage Seals	21	0	0	DD	ok	none obs	
West Mains Haulage Seals	21	0	0	FD/mc	ok	None obs.	
3rd North Haulage Seals	21	0	0	DD	ok	none obs.	
1st Right	21	0	0	DD	ok	none obs.	
Transformers	21	0	0	mc/fd	ok	None obs	
Chargers	21	0	0	DD	ok	none obs	
Washdown	21	0	0	MC	ok	None obs.	
Storage Areas	21	0	0	MC	ok	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8925

2MSHA03629

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 10-3-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 1130 AM/PM END 105 AM/PM Examiners Initials RL
TIME OF EXAMINATION START 1100 AM/PM END 120 AM/PM Examiners Initials RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	RL	OK	none observed	
Main No Haulage Seal	21	0	0	RL	OK	none "	
Main West Haulage Seals	20.9	0	0	RL/RL/LR	OK	none obs.	
3rd No Haulage Seals	21	0	0	RL	OK	none observed	
1st Right Haulage	21	0	0	RL	OK	none "	
Transformers	20.9	0	0	RL/RL/LR	OK	none obs	
Chargers	21	0	0	RL	OK	none observed	
workshops	21	0	0	RL	OK	none observed	
Storage Areas	21	0	0	RL	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre shift.

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6406
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7964
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03630

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-3-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:30 AM/PM END 9:20 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 7:20 AM/PM END 9:25 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 7:50 AM/PM END 9:10 AM/PM Examiners Initials FD

EXAM. CALLED OUT ----- YES NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	FD	OK	None obs.	
Main North Haulage Seals	21	0	0	FD	OK	None obs.	
Main West Haulage Seals	20.9	0	0	MC DD FD	OK	none observed	
3rd North Haulage Seals	21	0	0	FD	OK	None obs.	
1st Right Haulage	21	0	0	FD	OK	None obs	
Transformers	20.9	0	0	MC/FD	ok	none observed	
Chargers	21	0	0	FD	OK	None obs.	
washdown	20.9	0	0	MC	ok	none observed	
Storage Area	20.9	0	0	MC	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature [redacted] CERT. # 7325
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR Signature [redacted] CERT. # 8462

2MSHA03631

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-4-06 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 330 AM/PM END 525 AM/PM Examiners Initials FD
TIME OF EXAMINATION START 300 AM/PM END 530 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	mc	ok	none observed	
North Mains Haulage seals	20.9	0	0	mc	ok	none observed	
West Mains Haulage seals	21	0	0	FD/DD	ok	None obs.	
3rd North Haulage seals	20.9	0	0	mc	ok	none observed	
1st Right	20.9	0	0	mc	ok	none observed	
Transformers	21	0	0	FD/DD	ok	None obs.	
Chargers	20.9	0	0	FD/mc	ok	none observed	
Washdown	21	0	0	FD	ok	None obs.	
Storage Area	21	0	0	FD	ok	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS - Areas Approved Reasonably Safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03632

PRE-SHIFT GENERAL MINE

ATE OF EXAMINATION 12-4-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:12 AM/PM END 12:40 AM/PM Examiners Initials TC
ME OF EXAMINATION START 11:52 AM/PM END 1:10 AM/PM Examiners Initials FM
ME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

ALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

OCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	None observed	
Northmains Haulage Seals	20.9	0	0	FM	ok	None observed	
Westmains Haulage Seals	20.9	0	0	TC/FM	ok	None obs.	
3rd north Haulage Seals	20.9	0	0	FM	ok	None observed	
1st Right	20.9	0	0	FM	ok	None observed	
Chargers	20.9	0	0	TC/FM	ok	None obs.	
Transformers	20.9	0	0	TC/FM	ok	None obs.	
Washdown	20.9	0	0	TC	ok	None obs.	
Storage Area	20.9	0	0	TC	ok	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8097
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7685

2MSHA03633

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12/4/06 SECTION/AREA gen mine / /

TIME OF EXAMINATION START 8:15 AM/PM END 9:00 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 8:07 AM/PM END 8:50 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 7:55 AM/PM END 9:20 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
main North Haulage, Seals	20.9	0	0	BH	OK	None Observed	
main west Haulage, Seals	21	0	0	LH BP BH	OK	none observed	
3rd north Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right	20.9	0	0	BH	OK	None observed	
Transformers	21	0	0	LH BP BH	OK	none observed	
chargers	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe for work & Travel at Time of exam.

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9599
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03634

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12 5 06 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 404 AM/PM END 414 AM/PM Examiners Initials CT
TIME OF EXAMINATION START 3:00 AM/PM END 5:10 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21	0	0	CT	OK	None observed	
main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
main West Haulage seals	20.9	0	0	BH	OK	None Observed	
3rd North Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right	20.9	0	0	BH	OK	None Observed	
Tranformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 03892
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 7485

2MSHA03635

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-5-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:46 AM/PM END 1:32 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 12:48 AM/PM END 1:21 AM/PM Examiners Initials JG
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
MAIN North haulage seals	20.9	0	0	FM	OK	none observed	
MAIN West haulage seals	20.9	0	0	FM/JG	OK	NONE OBSERVED	
3rd North Haulage seals	20.9	0	0	FM	OK	none observed	
1st Right	20.9	0	0	FM	OK	none observed	
TRANSformers	20.9	0	0	FM/JG	OK	NONE OBSERVED	
Chargers	20.9	0	0	FM	OK	none observed	
Washdown	20.9	0	0	FM	OK	none observed	
Storage Area	20.9	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8397
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03636

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-5-06 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 7:40 AM/PM END 9:25 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 8:06 AM/PM END 9:00 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 800 AM/PM END 840 AM/PM Examiners Initials DD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
Main North Haulage Seals	21	0	0	DD	ok	none obs.	
Main West Haulage Seals	20.9	0	0	BH/BP	ok	None Observed	
3rd North Haulage Seals	20.9	0	0	BH/BP	ok	None Observed	
1st Right	20.9	0	0	BH	ok	None Observed	
Transformers	20.9	0	0	BH/BP	ok	None Observed	
Chargers	20.9	0	0	BH	ok	None Observed	
Washdown	20.9	0	0	BH	ok	None Observed	
Storage Areas	20.9	0	0	BH	ok	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8325
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8558
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03637

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12/6/06 SECTION/AREA gen mine / / /

TIME OF EXAMINATION START 4:40 AM/PM END 5:05 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 4:55 AM/PM END 5:10 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 4:05 AM/PM END 5:25 AM/PM Examiners Initials BH

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	BH	OK	none obs	
main north Haulage, seals	21	0	0	BH	OK	none obs	
main west Haulage, seals	21	0	0	BH LH	OK	none obs	
3rd north Haulage, seals	21	0	0	BH	OK	none obs	
1ST Right	21	0	0	BH	OK	none obs	
Transformers	21	0	0	LH BP BH	OK	none obs	
Chargers	21	0	0	LH BP BH	OK	none obs	
wash down	21	0	0	BH	OK	none obs	
storage	21	0	0	BH	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe for work & Travel at Time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9399
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8385
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 7485

2MSHA03638

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12.6.06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 1110 AM/PM END 1237 AM/PM Examiners Initials [illegible]
TIME OF EXAMINATION START 11:46 AM/PM END 1:32 AM/PM Examiners Initials FM
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking	209	0	0	FM	∝	None observed	
Main North Haulage / Seals	209	0	0	FM	∝	none observed	
Main West Haulage / Seals	209	0	0	FM	∝	none observed	
3 North Haulage / Seals	21	0.8	0	[illegible]	∝	N/O	
3 North Faces / Work Area	21	0.8	0	[illegible]	19480	N/O	
1 Right	21	0.8	0	[illegible]	∝	N/O	
Transformers	209	0	0	FM	∝	none observed	
Chargers	209	0	0	FM	∝	none observed	
Wash Down	209	0	0	FM	∝	None observed	
Storage	209	0	0	FM	∝	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 8226
PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 7485

2MSHA03639

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-6-06 SECTION/AREA GenMine / /

TIME OF EXAMINATION START 11:45 AM/PM END 1:32 AM/PM Examiners Initials FM
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM
CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	209	0	0	FM	∝	none observed	
main North haulage-Seals	209	0	0	FM	∝	none observed	
main West haulage-Seals	209	0	0	FM	∝	none observed	
3rd North haulage-Seals							
1st Right							
TRAnsformers	209	0	0	FM			
Chargers	209	0	0	FM			
washdown	209	0	0	FM	∝	none observed	
storage area	209	0	0	FM	∝	none observed	

12-6-06

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS _____

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ CERT. # _____

2MSHA03640

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12 6 06 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 808 AM/PM END 816 AM/PM Examiners Initials CA
TIME OF EXAMINATION START 7:00 AM/PM END 9:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CA	OK	None observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH	OK	None Observed	
3rd North Haulage Seals	20.9	0	0	BH	OK	Gob Pile x-cut 8 Needs dust	Sent men to dust Done CA 12 6 06
1st Right	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area's	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Except as noted above all area's safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 03892
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 03892

2MSHA03641

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12 7 06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 4:10 AM/PM END 4:15 AM/PM Examiners Initials CA
TIME OF EXAMINATION START 3:06 AM/PM END 5:10 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	CA	OK	None observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH	OK	None Observed	
3rd North Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at Time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 03892
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 8925

2MSHA03642

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12 7 06 SECTION/AREA Gen / Mine / / /

TIME OF EXAMINATION START 11 AM/PM END 1:15 AM/PM Examiners Initials dg
TIME OF EXAMINATION START 11:47 AM/PM END 1:10 AM/PM Examiners Initials FM
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	FM	ok	none observed	
Main North	20.9	0	0	FM	ok	none observed	
Haulage Seals Main West Pumps	20.9	0	.1	dg/FM	ok	none observed	
3rd No Haulage Seals	20.9	0	0	FM	ok	none observed	
1st Right	20.9	0	0	FM	ok	none observed	
Transformers	20.9	0	0	dg/FM	ok	none observed	
Chargers	20.9	0	0	FM	ok	none observed	
washdown	20.9	0	0	dg	ok	none observed	
Storage areas	20.9	0	0	dg	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6624
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03643

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-7-06 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 819 AM/PM END 920 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 830 AM/PM END 913 AM/PM Examiners Initials [illegible]
TIME OF EXAMINATION START 8:30 AM/PM END 9:33 AM/PM Examiners Initials BH

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	BH	OK	None Observed	
main north Haulage Seal	20.9	0	0	BH	OK	None Observed	
main west Haulage Seals	20.9	0	0	BP/LH	ok	none observed	
3rd north Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BP/LH	ok	none observed	
chargers	20.9	0	0	BP/LH	ok	none observed	
washdown	20.9	0	0	BP/LH	ok	none observed	
Storagearea	20.9	0	0	BP/LH	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9599
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03644

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12 8 06 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 357 AM/PM END 4/4 AM/PM Examiners Initials CL
TIME OF EXAMINATION START 415 AM/PM END 528 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 410 AM/PM END 520 AM/PM Examiners Initials BP BH

EXAM. CALLED OUT ----- YES/NO 300 AM CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	CL	OK	None observed	
main north Haulage - Seals	21	0	0	BH	OK	none observed	
main west Haulage - Seals	21	0	0	LH/BP	OK	none observed	
3rd north Haulage - Seals	21	0	0	BH	OK	none observed	
1st Right	21	0	0	BH	OK	none observed	
TRANsformers	21	0	0	BH BP LH	OK	none observed	
Chargers	21	0	0	BH	OK	none observed	
wash down	21	0	0	BP	OK	none observed	
storage area	21	0	0	BH	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe for work & Travel at Time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 03892
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8385
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9599

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 4735

2MSHA03645

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-8-06 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 11:25 AM/PM END 1:30 AM/PM Examiners Initials KK/KR/FM
TIME OF EXAMINATION START 11:54 AM/PM END 1:15 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:55 AM/PM END 12:36 AM/PM Examiners Initials DL

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
U.G Parking	20.9	0	0	FM	OK	none observed	
Main North Haulage Seals	20.9	0	0	FM	OK	none observed	
Main West Haulage Seals	20.9	0	0	KK/KR/FM	OK	None	
3rd North Haulage Seals	20.9	0	0	FM	OK	none observed	
1st Right Haulage	20.9	0	0	FM	OK	none observed	
Transformers	20.9	0	0	KK/KR/FM	OK	None	
Chargers	20.9	0	0	KK/FM	OK	none observed	
Wash down	20.9	0	0	FM	OK	none observed	
Storage Area	20.9	0	0	FM	OK	none observed	
3rd North Work Area	21.0	0	0	DL	OK	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8226
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 8462

2MSHA03646

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-8-06 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 700 AM/PM END 920 AM/PM Examiners Initials DD-MC
TIME OF EXAMINATION START 700 AM/PM END 825 AM/PM Examiners Initials DD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	ok	none obs.	
North Mains Haulage Seals	20.9	0	0	DD	ok	none obs.	
West Mains Haulage Seals	21	0	0	FD/MC	OK	None obs.	
3rd North Haulage Seals	20.9	0	0	DD	ok	none obs.	
1st Right	20.9	0	0	DD	ok	none obs.	
Wash down	21	0	0	MC	OK	None obs.	
Storage Area	21	0	0	MC	OK	None obs.	
Transformers	21	0	0	FD/MC/DD	OK	None obs.	
Chargers	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 7335
PRE-SHIFT/MINE EXAMINER CERT. #

SIGNATURE

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03647

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-9-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:01 AM/PM END 4:54 AM/PM Examiners Initials mc
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
MAIN North Haulage	20.9	0	0	MC	ok	None observed	
MAIN West Haulage	20.9	0	0	MC	ok	None observed	
Parking Area	20.9	0	0	MC	ok	None observed	
3RD North Haulage	20.9	0	0	MC	ok	None observed	
1ST Right Haulage	20.9	0	0	MC	ok	None observed	
Transformers	20.9	0	0	MC	ok	None observed	
Chargers	20.9	0	0	MC	ok	None observed	
Washdown	20.9	0	0	MC	ok	None observed	
Storage Areas	20.9	0	0	MC	ok	None observed	
Batt Kitchen	20.9	0	0	MC	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATU[redacted] CERT. # 84162

2MSHA03648

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-9-00 SECTION/AREA General / / /

TIME OF EXAMINATION START 200 AM/PM END 400 AM/PM Examiners Initials KK/RM
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM
CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	None obs.	
Main North Haulage seals	21.0	0	0	KK	OK	None obs	
Main West Haulage seals	20.9	0	0	KK/RM	OK	None obs	
3rd North Haulage seals	20.9	0	0	RM	OK	None obs.	
1st Right Haulage	20.9	0	0	RM	OK	None obs	
Trans.	20.9	0	0	KK/RM	OK	None obs	
Chargers	20.9	0	0	KK/RM	OK	None obs.	
Washdown	20.9	0	0	RM	OK	None obs	
Elevator area	20.9	0	0	RM	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift.

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 6845
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE SIGNATURE CERT. # 8462

2MSHA03649

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-9-06 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 700 AM/PM END 930 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 800 AM/PM END 910 AM/PM Examiners Initials
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North Haulage seals	21	0	0	FD	OK	None obs.	
Main West Haulage	21	0	0	DD/mc	ok	none obs.	
Parking Area	21	0	0	FD	OK	None obs.	
Trans.	21	0	0	DD/mc	ok	none obs.	
3rd North	21	0	0	FD	OK	None obs.	
1st Right	21	0	0	FD	OK	None obs.	
chargers	21	0	0	FD	OK	None obs.	
washdown	21	0	0	mc	ok	none obs.	
Storage Areas	21	0	0	mc	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe at the time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8058
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9158
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE SIGNATURE CERT. # 8462

2MSHA03650

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-10-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 4:16 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 330 AM/PM END 540 AM/PM Examiners Initials FD-DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
Main North Haulage Seals	20.9	0	0	mc	ok	none observed	
Main West Haulage Seals	21	0	0	mc/FD/DD	OK	None obs.	
3rd North Haulage Seals	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	OK	none observed	
Transformers	21	0	0	mc/FD	ok	None obs.	
Chargers	20.9	0	0	mc	ok	none observed	
Washdown	21	0	0	FD	OK	None obs.	
Storage	21	0	0	DD	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared to be Safe

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7375
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8055
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9458
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 4735

2MSHA03651

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-10-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 1100 AM/PM END 125 AM/PM Examiners Initials RL
TIME OF EXAMINATION START 1160 AM/PM END 135 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North Haulage Seals	21	Ø	Ø	RL	OK	none observed	
Main West Haulage	21	Ø	Ø	LR/KK	OK	None "	
Parking area	21	Ø	Ø	RL	OK	none observed	
Transformers	21	Ø	Ø	LR/KK	OK	None "	
3rd North	21	Ø	Ø	RL	OK	none observed	
1st Right	21	Ø	Ø	RL	OK	none "	
Chargers	21	Ø	Ø	RL	OK	none "	
Washdown	21	Ø	Ø	RL	OK	none "	
Storage area	21	Ø	Ø	RL	OK	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03652

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-10-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:30 AM/PM END 9:20 AM/PM Examiners Initials mc/FD
TIME OF EXAMINATION START 700 AM/PM END 800 AM/PM Examiners Initials DD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
MAIN NORTH HAULAGE SEALS	21	0	0	DD	ok	none obs.	
PARKING AREA	21	0	0	DD	ok	none obs.	
MAIN WEST HAULAGE SEALS	20.9	0	0	mc/FD	ok	none observed	
3RD NORTH HAULAGE SEALS	21	0	0	DD	ok	none obs.	
1ST RIGHT HAULAGE SEALS	21	0	0	DD	ok	none obs.	
TRANSFORMERS	20.9	0	0	mc/DD	ok	none observed	
CHARGERS	21	0	0	DD	ok	none obs.	
WASHDOWN	20.9	0	0	FD	ok	none observed	
STORAGE AREA	20.9	0	0	MC	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 8462

2MSHA03653

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-11-06 SECTION/AREA Pewmine / / /

TIME OF EXAMINATION START 3:30 AM/PM END 5:30 AM/PM Examiners Initials MC/DD
TIME OF EXAMINATION START 300 AM/PM END 420 AM/PM Examiners Initials FD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	FD	OK	None obs.	
Main North Haulage Seals	21	0	0	FD	OK	None obs.	
Main West Haulage Seals	20.9	0	0	MC/DD FD	OK	none observed	
3rd North Haulage	21	0	0	FD	OK	None obs.	
1st Right Haulage	21	0	0	FD	OK	None obs.	
Transformers	20.9	0	0	MC FD	ok	none observed	
chargers	21	0	0	FD	OK	None obs.	
washdown	20.9	0	0	MC	ok	none observed	
storage area	20.9	0	0	MC	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE [redacted] CERT. # 475

2MSHA03654

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-1-06 SECTION/AREA Gen Mine 01 / / /

TIME OF EXAMINATION START 11:58 AM/PM END 1:12 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:00 AM/PM END 1:20 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	209	0	0	FM	OC	None observed	
Main North Haulage-Seals	209	0	0	FM	OC	None observed	
Main West Haulage-Seals	209	0	0	FM/LR KK	OC	None obs.	
3rd North Haulage	209	0	0	FM	OC	None observed	
1st Right Haulage	209	0	0	FM	OC	None observed	
Transformers	209	0	0	FM/LR KK	OC	None obs	
Chargers	209	0	0	FM	OC	None observed	
Washdown	209	0	0	LR	OK	None obs	
Storage Area	209	0	0	FM	OC	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7904
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____

SIGNATURE

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03655

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-11-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:10 AM/PM END 8:16 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 700 AM/PM END 935 AM/PM Examiners Initials DD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
main North Haulage seals	20.9	0	0	mc	ok	none observed	
main West Haulage seals	21	0	0	mc/DD	ok	none obs.	
3rd North Haulage	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	21	0	0	mc/DD	ok	none obs.	
chargers	20.9	0	0	mc	ok	none observed	
washdown	21	0	0	DD	ok	none obs.	
storage area	21	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 9458
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 8462

2MSHA03656

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-12-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START ~~[illegible]~~ 4:03 AM/PM END 500 AM/PM Examiners Initials RM
TIME OF EXAMINATION START 300 AM/PM END 530 AM/PM Examiners Initials DD/FD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	RM	OK	None observed	
Main North haulage & Seals	20.9	0	0	RM	OK	None observed	
Main West haulage Seals	20.9	0	~~0~~	~~RM~~ FD	ok	none obs.	
3rd north haulage Seals	20.9	0	0	RM	OK	None observed	
1st Right haulage	20.9	0	0	RM	OK	None observed	
transformers	20.9	0	0	~~RM~~ FD	ok	none obs.	
Chargers	20.9	0	0	RM	OK	None observed	
Washdown	20.9	0	0	DD	ok	none obs.	
Storage Area	20.9	0	0	FD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas Appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6845
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 7485

2MSHA03657

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-12-06 SECTION/AREA Cardall / General / Mine /

TIME OF EXAMINATION START 12:00 AM/PM END 12:30 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 11:00 AM/PM END 1:00 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 11:58 AM/PM END 12:25 AM/PM Examiners Initials FM

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
Main North Slats haulage	20.9	0	0	FM	OK	None observed	
Main West Slats haulage	20.9	0	0	TC/SW	OK	none observed	
3rd North Haulage Slats	20.9	0	0	TC	OK	none obs.	
1st Right haulage	20.9	0	0	TC	OK	none obs.	
Transformers	20.9	0	0	TC	OK	none obs.	
Chargers	20.9	0	0	TC	OK	none obs.	
Washdown	20.9	0	0	TC	OK	none obs.	
Storage Area	20.9	0	0	TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Approved safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03658

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12/12/06 SECTION/AREA gen / / /

TIME OF EXAMINATION START 8:12 AM/PM END 8:29 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 8:07 AM/PM END 8:20 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 7:50 AM/PM END 9:30 AM/PM Examiners Initials BH

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
MAin north Haulage, Seals	20.9	0	0	BH	OK	None Observed	
MAin west Haulage, seals	21	0	0	LH BP BH	OK	none observed	
3rd north Haulage, seals	20.9	0	0	BH	OK	None Observed.	
1st Right	20.9	0	0	BH	OK	None Observed	
TRANSformers	21	0	0	LH BP BH	OK	none observed	
Chargers	20.9	0	0	BH	OK	None Observed	
wASh down	20.9	0	0	BH	OK	None observed	
storage	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9599
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

2MSHA03659

COUNTER SIGNATURE [redacted] CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-13-00 SECTION/AREA Belt / / /

TIME OF EXAMINATION START 420 AM/PM END 440 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 419 AM/PM END 435 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 330 AM/PM END 320 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Seals main north Haulage	20.9	0	0	BH	OK	None Observed	
Seals mainwest Haulage	20.9	0	0	LH BH BP	ok	none observed	
3rd north Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/BP	OK	none observed	
Chargers	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4599
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8385
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03660

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12.13.06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:06 AM/PM END 11:45 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 11:46 AM/PM END 1:30 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 12:30 AM/PM END 1:30 AM/PM Examiners Initials DG

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME 1:37 AM/PM

CALLED OUT BY Dennis Gomez
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY Foster McArthur
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	None observed	
MAIN North haulage-seals	20.9	0	0	MC	OK	None observed	
main west haulage-seals	20.9	0	3	FM/DG	OK	None observed	
3rd North haulage	20.9	0	0	FM	OK	None observed	
15th Right haulage	20.9	0	0	FM	OK	None observed	
TRAnsformers	20.9	0	0	FM/DG	OK	None observed	
Chargers	20.9	0	0	FM	OK	None observed	
Washdown	20.9	0	0	FM	OK	None observed	
Storage Area	20.9	0	0	FM	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared Reasonably Safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6622
PRE-SHIFT/MINE EXAMINER [redacted] CERT. #

SIGNATURE

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03661

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-13-06 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 7:00 AM/PM END 9:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH	OK	None Observed	
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
All Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area's	20.9	0	0	BH	OK	None Observed	
Kitchen	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 03892 2MSHA03662

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-14-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 5:10 AM/PM Examiners Initials BH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH	OK	None Observed	
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area's	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATU Signature CERT. # 7485

2MSHA03663

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-14-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:52 AM/PM END 1:20 AM/PM Examiners Initials MC/Fm
TIME OF EXAMINATION START 12:30 AM/PM END 1 AM/PM Examiners Initials dg
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc/Fm	ok	None observed	
Main North Haulage seals	20.9	0	0	mc/Fm	ok	None observed	
Main West Haulage seals	20.9	0	.1	mc/Fm dg	ok	None observed	
3rd North Haulage	20.9	0	0	mc/Fm	ok	None observed	
1st Right Haulage	20.9	0	0	mc/Fm	ok	None observed	
Transformers	20.9	0	0	mc/Fm dg	ok	None observed	
Chargers	20.9	0	0	mc/Fm dg	ok	None observed	
Washdown	20.9	0	0	mc/Fm	ok	None observed	
Storage Area	20.9	0	0	mc/Fm	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe at Time of Preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6622
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 7485

2MSHA03664

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12/14/06 SECTION/AREA gen min / / /

TIME OF EXAMINATION START 800 AM/PM END 825 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 751 AM/PM END 819 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 7:45 AM/PM END 9:20 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage, seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage, seals	21	0	0	LH BP BH	OK	none observed	
3rd North Haulage, seals	20.9	0	0	BH	OK	None Observed	
1st Right	20.9	0	0	BH	OK	None Observed	
TRANS	20.9	0	0	BH	OK	None Observed	
Chargers	21	0	0	LH BP BH	OK	none observed	
wash down	20.9	0	0	BH	OK	None Observed	
storage	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe for work & Travel at Time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8399
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 03892

2MSHA03665

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-15-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:05 AM/PM END 5:10 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North Haulage seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage seals	20.9	0	0	BH	OK	None observed	
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
Parking Area	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

2MSHA03666

COUNTER SIGNATUR [redacted] CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-15-06 SECTION/AREA Crandall / General / Mine /

TIME OF EXAMINATION START 11:00 AM/PM END 1:00 AM/PM Examiners Initials JW
TIME OF EXAMINATION START 11:50 AM/PM END 1:05 AM/PM Examiners Initials FM
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North seals haulage	20.9	0	0	FM	ok	None observed	
Main West seals haulage	20.9	0	0	FM/SW	OK	none observed	
3rd North haulage	20.9	0	0	FM	ok	None observed	
Parking Area	20.9	0	0	FM	ok	None observed	
1st Right haulage	20.9			FM	ok	None observed	
Transformers	20.9	0	0	FM/SW	OK	None observed	
Washdown	20.9	0	0	SW	OK	none observed	
Chargers	20.9	0	0	FM/SW	OK	None observed	
Storage Area.	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature [redacted] CERT. # 7485

2MSHA03667

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12/15/06 SECTION/AREA gen / / / /

TIME OF EXAMINATION START 7:45 AM/PM END 8:11 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 8:00 AM/PM END 8:10 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 7:45 AM/PM END 9:40 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main north Haulage, seals	20.9	0	0	BH	OK	None Observed	
Main west Haulage, seals	21	0	0	LH BP BH	OK	none obs	
3rd north Haulage, seals	20.9	0	0	BH	OK	None Observed	
1ST Right	20.9	0	0	BH	OK	None Observed	
Trans	21	0	0	LH BP BH	OK	none obs	
washdown	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe for work & Travel at Time of exam.

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9599
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03668

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-16-06 SECTION/AREA Genmine / / /

TIME OF EXAMINATION START 3:50 AM/PM END 5:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 4:10 AM/PM END 4:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None	
main North Haulage Seals	20.9	0	0	BH	OK	None	
main West Haulage Seals	20.9	0	0	BH/BO	OK	None	
3rd North Haulage	20.9	0	0	BH	OK	None	
1st Right Haulage	20.9	0	0	BH	OK	None	
trans	20.9	0	0	BH	OK	None	
Chargers	20.9	0	0	BH	OK	None	
washdown	20.9	0	0	BH	OK	None	
Storage Area	20.9	0	0	BH	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9599
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 7685

2MSHA03669

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-16-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 12:00 AM/PM END 1:20 AM/PM Examiners Initials ID
TIME OF EXAMINATION START 11:40 AM/PM END 1:30 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 11:44 AM/PM END 120 AM/PM Examiners Initials TC

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	ID	ok	none observed	
Main North Haulage Seals	20.9	0	0	ID	ok	none observed	
main west Haulage Seals	20.9	0	0	ID/TC	ok	none obs.	
3rd North Haulage Seals	20.9	0	0	ID	ok	none observed	
1st Right	20.9	0	0	ID	ok	none observed	
Trans	20.9	0	0	ID/TC	ok	none obs.	
wash down	20.9	0	0	SW	OK	non observed	
chargers	20.9	0	0	ID/TC	OK	None obs.	
Storage Area	20.9	0	0	TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 9660
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR Signature [redacted] CERT. # 7485

2MSHA03670

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12 16 06 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 8:10 AM/PM END 8:9 AM/PM Examiners Initials CT
TIME OF EXAMINATION START 7:00 AM/PM END 9:04 AM/PM Examiners Initials BH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	CT	OK	None observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH	OK	None Observed	
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 03892
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03671

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-18-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 5:10 AM/PM Examiners Initials BH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH	OK	None Observed	
Bed North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Trans	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Areas	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

2MSHA03672

COUNTER SIGNATURE Signature CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-17-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 12:00 AM/PM END 1:15 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 11:05 AM/PM END 1:40 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 11:39 AM/PM END 1:05 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LD	ok	none observed	
Main North Haulage Seals	20.9	0	0	LD	ok	none observed	
Main west Haulage Seals	20.9	0	0	LD/SW TC	ok	none obs.	
3rd North Haulage Seals	20.9	0	0	LD	ok	none observed	
1st Right Haulage	20.9	0	0	LD	ok	none observed	
transformers	20.9	0	0	LD/SW	ok	none observed	
Chargers	20.9	0	0	TC	ok	none obs.	
Wash down	20.9	0	0	TC	ok	none obs	
Storage Areas	20.9	0	0	TC	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All AREAS Appeared SAFE AT Time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9660
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03673

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-17-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 9:10 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 833 AM/PM END 905 AM/PM Examiners Initials CT
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	CT	OK	None observed	
Main North Haulage Seals	20.9	0	0	CT	OK	None observed	
Main west Haulage Seals	20.9	0	0	BH	OK	None Observed	
3rd North Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Areas	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 03892
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

2MSHA03674

SIGNATURE

COUNTER SIGNATURE [redacted] CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12/18/06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 347 AM/PM END 408 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 3:55 AM/PM END 5:19 AM/PM Examiners Initials BH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BP	OK	none observed	
3rd North Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Trans	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9599
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

2MSHA03675

COUNTER SIGNATURE SIGNATURE CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-18-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 1100 AM/PM END 125 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 1236 AM/PM END 135 AM/PM Examiners Initials mc
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
North mains Haulage Seals	20.9	0	0	mc	ok	none observed	
West mains Haulage Seals	21	0	0	FD/DD	OK	None obs.	
3rd North Haulage Seals	20.9	0	0	mc	ok	none observed	
1st Right	20.9	0	0	mc	ok	none observed	
Transformers	21	0	0	FD/mc	ok	none observed	
Chargers	20.9	0	0	mc	ok	none observed	
Washdown	21	0	0	FD	OK	None Obs.	
Storage Area	21	0	0	DD	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 235
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03676

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12/18/06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 700 AM/PM END 9:50 AM/PM Examiners Initials DG/KK/LR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	DG	OK	noneobs	
Main North Haulage area	20.9	0	0	DG	OK	noneobs.	
N.W. Haulage area	20.9	0	0	KK/LR	OK	None obs.	
3rd North Haulage	20.9	0	0	KK/LR	OK	None obs	
1st Right Haulage	20.9	0	0	KK	OK	None obs	
Trans.	20.9	0	0	KK/LR	OK	None obs	
Chargers	20.9	0	0	KK/LR	OK	None obs.	
Washdown	20.9	0	0	LR	OK	None obs	
Storage area	20.9	0	0	LR	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7954
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 4375
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 4735
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE SIGNATURE CERT. # 4735

2MSHA03677

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-18-06 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 550 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DG	OK	nae obs	
North Mains Haulage Seals	20.9	0	0	DG	OK	nae obs	
West Mains Haulage Seals	20.9	0	0	LR/KK	OK	None	
3rd North Haulage Seals	20.9	0	0	LR/KK	OK	None	
1st Right	20.9	0	0	LR/KK	OK	None	
Trans-	20.9	0	0	LR/KK	OK	None	
Chargers	20.9	0	0	LR	OK	None	
Washdown	20.9	0	0	KK	OK	None	
Storage Area	20.9	0	0	KK	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 4735
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

2MSHA03678

COUNTER SIGNATURE [redacted] CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-19-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:30 AM/PM END 1:15 AM/PM Examiners Initials MC DD
TIME OF EXAMINATION START 11:55 AM/PM END 1:10 AM/PM Examiners Initials FD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	FD	OK	None obs.	
Main North Haulage Seals	21	0	0	FD	OK	None obs.	
Main West Haulage Seals	20.9	0	0	MC/DD FD	OK	None observed	
3rd North Haulage	21	0	0	FD	OK	None Obs.	
1st Right Haulage	21	0	0	FD	OK	None obs.	
Transformers	21	0	0	DD/FD	OK	None Obs.	
Chargers	21	0	0	FD	OK	None obs.	
Washdown	20.9	0	0	MC	OK	None observed	
Storage Area	20.9	0	0	MC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe at time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7325
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 9458
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE [redacted] CERT. # 4735

2MSHA03679

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-19-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:38 AM/PM END 9:41 AM/PM Examiners Initials KG
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	None observed	
main North Haulage seals	21.0	0	0	KK	OK	None observed	
main West Haulage seals	20.9	0	0	KK	OK	None observed	
3rd North Haulage	20.9	0	0	KK	OK	None observed	
1st right Haulage	20.9	0	0	KK	OK	None observed	
Trans	20.9	0	0	KK	OK	None observed	
chargers	20.9	0	0	KK	OK	None observed	
Washdown	20.9	0	0	KK	OK	None observed	
Storage area	20.9	0	0	KK	OK	None observed	
Belt Kitchen	20.9	0	0	KK	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7964
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE Signature CERT. # 4135

2MSHA03680

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-20-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 500 AM/PM END 525 AM/PM Examiners Initials DG
TIME OF EXAMINATION START 300 AM/PM END 535 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	DG	OK	weeds	
main North Haulage seals	21.0	0	0	KK/LR	OK	None observed	
N.W. Haulage seals	20.9	0	0	KK/LR	OK	None observed	
3rd North Haulage	20.9	0	0	KK	OK	None observed	
5th North Haulage	20.9	0	0	KK	OK	None observed	
Storage area	20.9	0	0	KK	OK	None observed	
washdown	20.9	0	0	KK	OK	None observed	
Trans	20.9	0	0	KK/LR	OK	None observed	
chargers	20.9	0	0	KK/LR	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 1735
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 8462

2MSHA03681

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-20-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:30 AM/PM END 1:20 AM/PM Examiners Initials MC-RD
TIME OF EXAMINATION START 1100 AM/PM END 1210 AM/PM Examiners Initials DD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	ok	none obs.	
Main North Haulage Seals	20.9	0	0	DD	ok	none obs.	
Main west Haulage Seals	20.9	0	0	MC/RD	ok	none observed	
3rd North Haulage	21	0	0	DD	ok	none obs.	
1st Right Haulage	21	0	0	DD	ok	none obs.	
Transformers	21	0	0	DD	ok	none obs.	
chargers	21	0	0	DD	ok	none obs.	
wrighdown	20.9	0	0	MC-RD	ok	none observed	
storage area	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 2375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. #

COUNTER SIGNATURE [redacted] CERT. # 4135

2MSHA03682

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-20-06 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 700 AM/PM END 1000 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DB	OK	None	
Main North Haulage Seals	20.9	0	0	LR/KK	OK	None obs	
Main West Haulage seals	20.9	0	0	LR/KK	OK	None obs	
3rd North Haulage	20.9	0	0	LR/KK	OK	None obs	
1st Right Haulage	20.9	0	0	KK	OK	None obs	
Turns.	20.9	0	0	LR/KK	OK	None obs	
Chargers	20.9	0	0	LR/KK	OK	None obs	
Washdown	20.9	0	0	KK	OK	None obs.	
Storage Area	20.9	0	0	LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7964
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 4775

2MSHA03683

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-21-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 500 AM/PM END 535 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	LR	OK	None	
Main North Haulage secy	20.9	0	0	KK/LR	OK	None obs	
Main N. Haulage secy	20.9	0	0	KK/LR	OK	None obs	
3rd North Haulage	20.9	0	0	KK/LR	OK	None obs.	
1st crosscut	20.9	0	0	LR	OK	None obs.	
Storage area	20.9	0	0	LR	OK	None obs.	
washdown	20.9	0	0	KK	OK	None obs	
Trans.	20.9	0	0	KK/LR	OK	None obs.	
chargers	20.9	0	0	KK/LR	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

SIGNATURE

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03684

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-21-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:07 AM/PM END 12:05 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 11:20 AM/PM END 125 AM/PM Examiners Initials JD-DD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	MC	OK	none observed	
MAIN NORTH HAULAGE SEALS	20.9	0	0	mc	OK	none observed	
MAIN WEST HAULAGE SEALS	21	0	0	mc/JD DD	OK	None obs.	
3RD NORTH HAULAGE	20.9	0	0	mc	ok	none observed	
1ST Right HAULAGE	20.9	0	0	mc	ok	none observed	
TRANSFORMERS	21	0	0	mc/JD	OK	None obs.	
CHARGERS	20.9	0	0	mc	ok	none observed	
WASHDOWN	21	0	0	JD	OK	None obs.	
STORAGE AREA	21	0	0	DD	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe at the time of exam.

PRE-SHIFT/MINE EXAMINER Signature [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. #

SIGNATURE

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03685

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-21-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 700 AM/PM END 1000 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None	
Main North Haulage Seals	20.9	0	0	LR/KK	OK	None obs.	
Main West Haulage Seals	20.9	0	0	LR/KK	OK	None obs.	
3 North Haulage	20.9	0	0	KK	OK	None obs.	
1st Right Haulage	20.9	0	0	KK	OK	None obs	
Storage Area	20.9	0	0	LR	OK	None obs.	
Washdown	20.9	0	0	LR	OK	None obs.	
Trans.	20.9	0	0	LR/KK	OK	None obs.	
Chargers	20.9	0	0	LR/KK	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 1954
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8925

2MSHA03686

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-22-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 500 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	LR	OK	None	
main North seals	20.9	0	0	KK	OK	None obs.	
M. West seals Fanlay	20.9	0	0	KK	OK	None obs.	
3rd North Fanlay	20.9	0	0	KK	OK	None obs.	
Right Fanlay	20.9	0	0	KK	OK	None obs	
Storage area	20.9	0	0	KK	OK	None obs.	
Washdown	20.9	0	0	KK	OK	None obs	
Trans.	20.9	0	0	KK/LR	OK	None obs.	
chargers	20.9	0	0	KK/LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of pre-shift.

PRE-SHIFT/MINE EXAMINER Signature [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 03892

2MSHA03687

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-22-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 12:00 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 11:02 AM/PM END 12:04 AM/PM Examiners Initials MC
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	None Observed	
Main North Haulage Seals	20.9	0	0	MC	OK	None Observed	
Main West Haulage Seals	20.9	0	0	MC/BH	OK	None Observed	
3rd North Haulage	20.9	0	0	MC	OK	None Observed	
1st Right Haulage	20.9	0	0	MC	OK	None Observed	
Transformers	20.9	0	0	MC/BH	OK	None Observed	
Chargers	20.9	0	0	MC/BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Areas	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6395
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 738
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03688

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-22-06 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 7:42 AM/PM END 9:30 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 7:00 AM/PM END 9:30 AM/PM Examiners Initials SW
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	ok	none observed	
Main North Haulage Seals	20.9	0	0	SW	ok	none observed	
Main West Haulage Seals	20.9	0	0	TC/SW	ok	none obs.	
3rd north Haulage Seals	20.9	0	0	TC	ok	none obs.	
1st Right haulage	20.9	0	0	TC	ok	none obs.	
Transformers	20.9	0	0	TC/SW	ok	none obs.	
Chargers	20.9	0	0	TC/SW	ok	none obs.	
wash down	20.9	0	0	TC	ok	none obs.	
Storage Areas	20.9	0	0	TC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All AREAS seemed safe AT Time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9562
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03689

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 122306 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 3:00 AM/PM END 4:10 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 3:47 AM/PM END 4:01 AM/PM Examiners Initials JP
TIME OF EXAMINATION START 3:40 AM/PM END 5:15 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JP	ok	None observed	
MAIN NORTH HAULAGE	20.9	0	0	JP	ok	None observed	
MAIN WEST HAULAGES	20.9	0	0	~~JG~~ SW	OK	none observed	
3RD NORTH HAULAGE	20.9	0	0	JG	OK	none observed	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	none observed	
SEALS	20.9	0	0	JP JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	JP JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	TC	OK	NONE OBSERVED	
STORAGE AREA	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIMES OF EXAMINATION

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8951
PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9362

COUNTER SIGNATURE SIGNATURE CERT. # 03892

2MSHA03690

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12 23 06 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 1218 AM/PM END 1246 AM/PM Examiners Initials CA
TIME OF EXAMINATION START 11:00 AM/PM END 12:45 AM/PM Examiners Initials BH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CA	OK	None observed	
Main North Haulage Seals	20.9	0	0	CA	OK	None observed	
Main West Haulage Seals	20.9	0	0	BH	OK	None Observed	
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None observed	
Storage Areas	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 03892
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE SIGNATURE CERT. # 03892

2MSHA03691

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-23-06 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 7:20 AM/PM END 8:30 AM/PM Examiners Initials JC
TIME OF EXAMINATION START 8:12 AM/PM END 8:30 AM/PM Examiners Initials JP
TIME OF EXAMINATION START 7:34 AM/PM END 9:15 AM/PM Examiners Initials JC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JP	OK	None observed	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JP	OK	None observed	
MAIN WEST HAULAGE SEALS	20.9	0	0	TC/SW	OK	none obs.	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	TC/SW	OK	none observed	
CHARGERS	20.9	0	0	TC/SW	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	TC	OK	None obs.	
UNDERGROUND STORAGE	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS SEEMED SAFE AT Time of Exam

PRE-SHIFT/MINE EXAMINE[redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINE[redacted] CERT. # 8951
PRE-SHIFT/MINE EXAMINE[redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINE[redacted] CERT. # 9548

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03692

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-26-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:32 AM/PM END 5:25 AM/PM Examiners Initials MC/FD
TIME OF EXAMINATION START 300 AM/PM END 410 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
Main North Haulage Seals	21	0	0	DD	ok	none obs.	
Main West Haulage Seals	20.9	0	0	MC FD	OK	none observed	
3rd North Haulage	21	0	0	DD	ok	none obs.	
1st Right Haulage	21	0	0	DD	ok	none obs.	
Transformers	20.9	0	0	MC FD	OK	none observed	
Chargers	21	0	0	MC/DD	ok	none obs	
Washdown	20.9	0	0	MC	OK	none observed	
Storage Area	20.9	0	0	DD	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 9458
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 8462

2MSHA03693

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-26-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:40 AM/PM END 1:20 AM/PM Examiners Initials MC DD
TIME OF EXAMINATION START 1110 AM/PM END 1220 AM/PM Examiners Initials FD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	21	0	0	FD	OK	None obs.	
MAIN NORTH Haulage SEALS	21	0	0	FD	OK	None Obs.	
MAIN WEST Haulage SEALS	20.9	0	0	MC DD FD	OK	NONE observed	
3RD NORTH Haulage	21	0	0	FD	OK	None obs.	
1st Right Haulage	21	0	0	FD	OK	None Obs.	
TRANSFORMERS	20.9	0	0	MC FD	OK	None observed	
CHARGERS	21	0	0	FD	OK	None obs.	
WASHDOWN	20.9	0	0	MC	OK	NONE observed	
STORAGE AREA	20.9	0	0	MC	OK	NONE observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared to be Safe at the time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 9458
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATUR Signature [redacted] CERT. # 4735

2MSHA03694

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-26-06 SECTION/AREA Pen Mine / / / /

TIME OF EXAMINATION START 700 AM/PM END 930 AM/PM Examiners Initials RL-LR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	Ø	Ø	DG	OK	none observed	
Main North Haul Seals	21	Ø	Ø	DG	OK	none "	
Main West Haulage Seals	21	Ø	Ø	RL/LR	OK	none "	
3rd No Haulage	21	Ø	Ø	LR	OK	none "	
1st Right Haulage	21	Ø	Ø	LR	OK	none "	
Transformers	21	Ø	Ø	LR/RL	OK	none "	
Chargers.	21	Ø	Ø	LR	OK	none "	
Workdown	21	Ø	Ø	LR	OK	none "	
Storage	21	Ø	Ø	LR	OK	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

SIGNATURE

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATUR [redacted] CERT. # 4735

2MSHA03695

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-27-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 310 AM/PM END 535 AM/PM Examiners Initials RL/AK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- ____ AM/PM
CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	Ø	Ø	DG	ok	none observed	
Main North Haulage Seal	21	Ø	Ø	RL	ok	none "	
Main West Haulage Seal	21	Ø	Ø	RL	ok	none "	
3rd No Haulage	21	Ø	Ø	RL	ok	none "	
Int Right Haulage	21	Ø	Ø	RL	ok	none "	
Transformers	22	Ø	Ø	RL	ok	none "	
Chargers	21	Ø	Ø	RL	ok	none "	
Workshop	21	Ø	Ø	RL	ok	none "	
Storage area	21	Ø	Ø	RL	ok	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATUR[redacted] CERT. # 8462

2MSHA03696

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-27-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:04 AM/PM END 12:11 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 11:30 AM/PM END 2:00 AM/PM Examiners Initials DD/FD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
Main North Haulage seals	20.9	0	0	mc	ok	none obs.	
Main West Haulage seals	20.9	0	0	mc/FD	ok	none obs	
3rd North Haulage	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	mc/DD	ok	none obs.	
Chargers	20.9	0	0	mc	ok	none observed	
Washdown	20.9	0	0	FD	ok	none obs	
Storage Area	20.9	0	0	FD	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9155
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 8467

2MSHA03697

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-27-06 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 700 AM/PM END 945 AM/PM Examiners Initials LR/RL
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DG	OK	None	
Main North Haulage Seals	20.9	0	0	LR	OK	None	
Main West Haulage Seals	20.9	0	0	LR/RL	OK	None	
3rd No Haulage	20.9	0	0	LR	OK	None	
1st Right Haulage	20.9	0	0	LR	OK	None	
Turns Sounders	20.9	0	0	LR/RL	OK	None	
Chargers	20.9	0	0	LR	OK	None	
Washdown	20.9	0	0	LR	OK	None	
Storage Area	20.9	0	0	LR	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4735
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 4735

2MSHA03698

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-28-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 540 AM/PM Examiners Initials RL/LR
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	Ø	Ø	DG	Ø	none observed	
Main North Haulage Seal	21	Ø	Ø	LR	Ø	none "	
Main West Haulage Seals	21	Ø	Ø	LR/RL	Ø	none "	
3rd No Haulage	21	Ø	Ø	LR	Ø	none "	
1st Right Haulage	21	Ø	Ø	LR	Ø	none "	
Transformer	21	Ø	Ø	LR	Ø	none "	
Charger	21	Ø	Ø	LR	Ø	none "	
Washdown	21	Ø	Ø	LR	Ø	none "	
Storage Area	21	Ø	Ø	LR	Ø	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4323
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4735
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 8462

2MSHA03699

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-28-06 SECTION/AREA Bedmine / / /

TIME OF EXAMINATION START 11:02 AM/PM END 1:28 AM/PM Examiners Initials MC/DD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	MC	OK	none observed	
MAIN NORTH Haulage SEALS	20.9	0	0	MC/DD	OK	none observed	
MAIN WEST Haulage SEALS	20.9	0	0	MC/DD	OK	none observed	
3RD NORTH HAULAGE	20.9	0	0	MC	OK	none observed	
1ST Right Haulage	20.9	0	0	MC	OK	none observed	
TRANSFORMERS	20.9	0	0	MC/DD	OK	none observed	
CHARGERS	20.9	0	0	MC	OK	none observed	
WASHDOWN	20.9	0	0	MC	OK	none observed	
STORAGE AREA	20.9	0	0	MC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe At Time of Preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 8482

2MSHA03700

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-28-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 700 AM/PM END 940 AM/PM Examiners Initials DG RL LR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DG	G	none observed	
Main North Haulage Seal	21	0	0	LR	G	none "	
Main West Haulage Seal	21	0	0	LR/RL	G	none "	
3rd North Haulage	21	0	0	LR	G	none "	
1st Right Haulage	21	0	0	LR	G	none "	
Transformer	21	0	0	LR/RL	G	none "	
Charger	21	0	0	LR	G	none "	
Workdown	21	0	0	LR	G	none "	
Storage Area	21	0	0	LR	G	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4735
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATUR Signature CERT. # 4735

2MSHA03701

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-29-06 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 540 AM/PM Examiners Initials RL/JR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	Ø	Ø	DG	OK	none observed	
Main North Haulage seals	21	Ø	Ø	RL	OK	none observed	
Main West Haulage seals	21	Ø	Ø	RL/JR	OK	none "	
3rd North Haulage	21	Ø	Ø	RL	OK	none "	
1st Right Haulage	21	Ø	Ø	RL	OK	none "	
Transformers	21	Ø	Ø	RL/JR	OK	none "	
Chargers	21	Ø	Ø	RL	OK	none "	
Washdown	21	Ø	Ø	RL	OK	none "	
Storage Area	21	Ø	Ø	RL	OK	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4325
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 9279

2MSHA03702

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-29-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 1115 AM/PM END 1242 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 1158 AM/PM END 1240 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 12:00 AM/PM END 1:13 AM/PM Examiners Initials FM

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	None observed	
MAIN North Haulage Seals	20.9	0	0	FM	ok	None observed	
main west Haulage Seals	20.9	0	0	BP/LH	ok	none observed	
3rd north Haulage Seals	20.9	0	0	BP/LH	ok	none observed	
1st Right	20.9	0	0	BP/LH	ok	none observed	
chargers	20.9	0	0	BP	ok	none observed	
washdown	20.9	0	0	BP	ok	none observed	
Storage Area	20.9	0	0	FM	ok	None observed	
Transformers	20.9	0	0	FM	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared reasonably safe At time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8579
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8097
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 9272

2MSHA03703

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-29-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:10 AM/PM END 8:30 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 7:30 AM/PM END 8:40 AM/PM Examiners Initials JG
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LD	ok	none observed	
Main North Haulage Seals	20.9	0	0	LD	ok	none observed	
Maine West Haulage Seals	20.9	0	0	JG	ok	NONE OBSERVED	
3rd North Haulage Seals	20.9	0	0	LD	ok	none observed	
1st right Haulage	20.9	0	0	LD	ok	none observed	
transformers	20.9	0	0	JG	ok	NONE OBSERVED	
chargers	20.9	0	0	JG	OK	NONE OBSERVED	
washdown	20.9	0	0	JG	ok	NONE OBSERVED	
Storage Area	20.9	0	0	JG	Ok	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS ALERTS REPORTED REASONABLY SAFE AT TIME OF PRE-SHIFT - DID SOME MORE ROCK DUSTING ON M. WEST INTAKES 116-134

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9660
PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
PRE-SHIFT/MINE EXAMINER Signature CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03704

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12 30 06 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 3:20 AM/PM END 445 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 4:10 AM/PM END 5:30 AM/PM Examiners Initials LD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	LD	ok	none observed	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	LD	ok	none observed	
MAIN WEST HAULAGE-SEALS	20.9	0	0	LD/JG	Ok	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	LD	ok	none observed	
1ST RIGHT HAULAGE	20.9	0	0	LD	ok	none observed	
TRANSFORMERS	20.9	0	0	LD/JG	Ok	NONE OBSERVED	
CHARGERS	20.9	0	0	LD	ok	none observed	
WASHDOWN	20.9	0	0	JG	Ok	NONE OBSERVED	
STORAGE AREA	20.9	0	0	JG	Ok	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS TRAVELED REPORTED SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7485
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9660
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 9279

2MSHA03705

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12/30/06 SECTION/AREA gen mine / / /

TIME OF EXAMINATION START 1201 AM/PM END 1245 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 1210 AM/PM END 1240 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 12:06 AM/PM END 1:40 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None	
main north Haulage, seals	20.9	0	0	BH	OK	None	
main west Haulage, seals	21	0	0	LH BP BH	OK	none observed	
3rd north Haulage seals	20.9	0	0	BH	OK	None	
1st Right	20.9	0	0	BH	OK	None	
Transformers	21	0	0	LH BP BH	OK	none observed	
chargers	21	0	0	LH BP BH	OK	none observed	
wash down	20.9	0	0	BH	OK	None	
storage	20.9	0	0	BH	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe for work & Travel at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6599
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6399
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 9279

2MSHA03706

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-30-06 SECTION/AREA Crandall General Mine

TIME OF EXAMINATION START 7:45 AM/PM END 8:35 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:30 AM/PM END 8:55 AM/PM Examiners Initials JG
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North SLAB haulage	20.9	0	0	SW	OK	none observed	
Main West SLAB haulage	20.9	0	0	SW JG	OK	NONE OBSERVED	
3rd North SLAB haulage	20.9	0	0	SW	OK	none observed	
1st Right.	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW JG	OK	NONE OBSERVED	
chargers	20.9	0	0	SW JG	OK	NONE OBSERVED	
washdown	20.9	0	0	JG	OK	NONE OBSERVED	
Storage Area.	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS REASONABLY SAFE AT TIME OF EXAMINATION - REPLACED ROOFBOLT AT X-CUT 74 M WEST

SIGNATURE

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03707

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12 31 06 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 3:10 AM/PM END 4:25 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 3:55 AM/PM END 5:00 AM/PM Examiners Initials SW
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	SW	OK	none observed	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	SW	OK	none observed	
MAIN WEST HAULAGE-SEALS	20.9	0	0	SW/JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	SW	OK	none observed	
1ST RIGHT HAULAGE	20.9	0	0	SW	OK	none observed	
UNDERGROUND STORAGE	20.9	0	0	JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	SW/JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	SW/JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 9279

2MSHA03708

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12-31-06 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 1104 AM/PM END 1140 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 11:55 AM/PM END 1:30 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Haulage Seals main west	20.9	0	0	BP/BH	ok	none observed	
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
~~underground~~ Storage Areas	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BP	ok	none observed	
Chargers	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 2599
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 9279

2MSHA03709

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 12 31 06 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 7:30 AM/PM END 8:35 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 7:45 AM/PM END 8:55 AM/PM Examiners Initials SW
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	SW	OK	none observed	
MAIN NORTH HAULAGE - SEALS	20.9	0	0	SW	OK	none observed	
MAIN WEST HAULAGE - SEALS	20.9	0	0	SW/JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE - SEALS	20.9	0	0	SW	OK	none observed	
1ST RIGHT HAULAGE	20.9	0	0	SW	OK	none observed	
STORAGE AREA	20.9	0	0	JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	SW/JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	SW/JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7485
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9549
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR Signature CERT. # 7485

2MSHA03710

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-1-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 3:15 AM/PM END 4:25 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 4:00 AM/PM END 5:20 AM/PM Examiners Initials SW
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	SW	OK	none observed	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	SW	OK	none observed	
MAIN WEST HAULAGE-SEALS	20.9	0	0	SW/JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	SW	OK	none observed	
1ST RIGHT HAULAGE	20.9	0	0	SW	OK	none observed	
STORAGE AREA	20.9	0	0	JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	SW JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	SW/JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at time of Pre-Shift.

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7485
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9548
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 4765

2MSHA03711

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-1-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 11:59 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 11:00 AM/PM END 1:30 AM/PM Examiners Initials LR/RL
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	ok	None obs	
Main North Haulage seals	20.9	0	0	KK	ok	None obs	
3rd North Haulage	20.9	0	0	KK	ok	None obs.	
1st right Haulage	20.9	0	0	KK	ok	none obs.	
Main West Haulage seals	20.9	0	0	RL/LR	ok	none observed	
5/Conveyor area	20.9	0	0	RL	ok	none "	
Washdown	20.9	0	0	RL	ok	none "	
Trans	20.9	0	0	KK/LR/RL	ok	none "	
Chargers	20.9	0	0	KK/LR/RA	ok	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exams

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03712

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-1-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:59 AM/PM END 9:05 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 700 AM/PM END 930 AM/PM Examiners Initials DD/FD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
main North Haulage seals	20.9	0	0	mc	ok	none observed	
main West Haulage seals	21	0	0	mc/DD	ok	none obs	
3rd North Haulage	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	21	0	0	mc/FD	ok	none obs.	
chargers	20.9	0	0	mc	ok	none observed	
washdown	21	0	0	FD	ok	none obs.	
storage area	21	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

SIGNATURE

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03713

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-2-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 520 AM/PM Examiners Initials DD-MC
TIME OF EXAMINATION START 300 AM/PM END 355 AM/PM Examiners Initials DD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
North Mains Seals Hauling	21	0	0	DD	ok	none obs.	
West mains Seals Hauling	21	0	0	FD/MC	OK	None Obs.	
3rd North	21	0	0	DD	ok	none obs.	
1st Right	21	0	0	DD	ok	none obs.	
Storage Area	21	0	0	MC	OK	None Obs	
Washdown	21	0	0	FD	OK	None Obs.	
Transformers	21	0	0	FD/DD	OK	None Obs.	
Chargers	21	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 3058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 4735

2MSHA03714

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-2-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 2:00 AM/PM Examiners Initials KK/RL/LR
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	21.0	0	0	RL	ok	none	
main North seals Haulgee	21	0	0	RL	ok	none	
Main West seals Haulgee	20.9	0	0	KK/LR/RL	ok	None obs.	
3rd north	21	0	0	RL	ok	none	
1st right	21	0	0	RL	ok	none	
Storage area	20.9	0	0	LR	ok	None obs.	
Washdown	20.9	0	0	LR	ok	None obs.	
Trans.	20.9	0	0	KK/LR/RL	ok	None obs	
Chargers	20.9	0	0	KK/LR/RL	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS _____

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR Signature CERT. # 8462

2MSHA03715

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-2-07 SECTION/AREA Gen. Mine

TIME OF EXAMINATION START 2:30 AM/PM END 8:15 AM/PM Examiners Initials PC
TIME OF EXAMINATION START 7:30 AM/PM END 9:58 AM/PM Examiners Initials MC DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	PC	ok	None Observed	
Main North Haulage Seals, transformer	20.9	0	0	PC	ok	None Observed	
West Mains Haulage Seals	20.9	0	0	mc/DD	OK	none observed	
3rd North	20.9	0	0	mc	OK	none observed	
1st Right	20.9	0	0	mc	OK	none observed	
Storage area	20.9	0	0	mc	OK	none observed	
wash down	20.9	0	0	mc	OK	none observed	
transformers	20.9	0	0	mc/DD	OK	none observed	
Chargers	20.9	0	0	mc	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe at Time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8462
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7875
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03716

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-3-07 SECTION/AREA Gen. Mine

TIME OF EXAMINATION START 3:00 AM/PM END 3:25 AM/PM Examiners Initials PC
TIME OF EXAMINATION START 3:00 AM/PM END 6:00 AM/PM Examiners Initials DD/mc
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	PC	ok	None Observed	
main North Haulage Seals, trans.	20.9	0	0	PC	ok	None Observed	
west mains Seals, Haulage	20.9	0	0	mc/DD	ok	none observed	
3rd North	20.9	0	0	mc	ok	none observed	
1st right	20.9	0	0	mc	ok	none observed	
Storage area	20.9	0	0	mc	ok	none observed	
Wash down	20.9	0	0	mc	ok	none observed	
transformers	20.9	0	0	mc/DD	ok	none observed	
chargers	20.9	0	0	mc/DD	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8462
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7375
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8058
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 4735

2MSHA03717

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-3-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 12:00 AM/PM END 12:20 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:00 AM/PM END 1230 AM/PM Examiners Initials LR
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
MAIN North haulag Seals	20.9	0	0	LR	OK	None observed	
MAIN West haulag Seals	20.9	0	0	LR/KH/RL	OK	Bad Top O.K. by Phone	Set Timber 1-3-07 LR
3rd North	20.9	0	0	LR	OK	None obs.	
1st Right	20.9	0	0	LR	OK	None obs	
Storage Area	20.9	0	0	LR	OK	None obs	
Wash down	20.9	0	0	LR	OK	None obs	
TRANSformers	20.9	0	0	LR	OK	None obs	
Chargers	20.9	0	0	LR	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved safe at time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401

Signature

SIGNATURE

COUNTER SIGNATURE [redacted] CERT. # 8460

2MSHA03718

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-3-07 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 710 AM/PM END 810 AM/PM Examiners Initials FD
TIME OF EXAMINATION START 7:30 AM/PM END 9:20 AM/PM Examiners Initials mc/DD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	FD	OK	None Obs.	
North Mains Haulage Seal	21	0	0	FD	OK	None Obs.	
West Mains Haul Seals	20.9	0	0	mc/DD	OK	none observed	
3rd North	21	0	0	FD	OK	None Obs.	
1st Right	21	0	0	FD	OK	None Obs.	
Storage Area	20.9	0	0	mc	OK	none observed	
Wash down	20.9	0	0	mc	OK	none observed	
Transformers	21	0	0	FD	OK	None Obs.	
Chargers	21	0	0	FD	OK	None Obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe At Time of pre-shift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. #

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03719

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-4-07 SECTION/AREA Gewmine / / /

TIME OF EXAMINATION START 3:38 AM/PM END 5:30 AM/PM Examiners Initials MC/FD
TIME OF EXAMINATION START 400 AM/PM END 520 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
Main North Haulage Seals	21	0	0	DD	ok	none obs.	
Main West Haulage Seals	20.9	0	0	MC/FD	ok	none observed	
3rd North Haulage	21	0	0	DD	ok	none obs.	
1st Right Haulage	21	0	0	DD	ok	none obs.	
Transformers	20.9	0	0	FD/DD	ok	none observed	
chargers	21	0	0	DD	ok	none obs.	
washdown	21	0	0	DD	ok	none obs.	
storage area	21	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7375
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9058
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8058
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 7735

2MSHA03720

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-4-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 1:00 AM/PM Examiners Initials LR/FM
TIME OF EXAMINATION START 11:55 AM/PM END 1:00 AM/PM Examiners Initials KK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	KK	OK	None obs	
Main North Haulage seals	20.9	0	0	LR/FM/KK	OK	None	
Main West Haulage seals	20.9	0	0	LR/FM	OK	None	
3rd North Haulage	20.9	0	0	KK	OK	None	
1st Right Haulage	20.9	0	0	KK	OK	None	
Trans.	20.9	0	0	LR/FM/KK	OK	None	
Chargers	20.9	0	0	KK	OK	None	
Washdown	20.9	0	0	KK	OK	None	
Storage Area	20.9	0	0	KK	OK	None Obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved Safe at time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7154
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03721

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-4-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 8:02 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 700 AM/PM END 825 AM/PM Examiners Initials FD-DD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	mc	ok	none observed	
MAIN NORTH HAULAGE SEALS	20.9	0	0	mc	ok	none observed	
MAIN WEST HAULAGE SEALS	21	0	0	mc FD DD	ok	None Obs.	
3rd NORTH HAULAGE	20.9	0	0	mc	ok	none observed	
1st RIGHT HAULAGE	20.9	0	0	mc	ok	none observed	
TRANSFORMERS	21	0	0	mc/FD	ok	None Obs.	
CHARGERS	20.9	0	0	mc	ok	none observed	
WASHDOWN	21	0	0	FD	ok	None Obs.	
STORAGE AREA	21	0	0	DD	ok	None Obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All appeared to be safe at the time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____

COUNTER SIGNATUR [redacted] CERT. # 9462

2MSHA03722

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-5-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:30 AM/PM END 5:25 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 3:00 AM/PM END 4:10 AM/PM Examiners Initials [illegible]
TIME OF EXAMINATION START 5:00 AM/PM END 5:30 AM/PM Examiners Initials DD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	FD	OK	None Obs.	
Main North Haulage Seals	21	0	0	FD	OK	None Obs.	
Main West Haulage Seals	20.9	0	0	mc/DD FD	OK	none observed	
3rd North Haulage Seals	21	0	0	FD	OK	None Obs.	
1st Right Haulage	21	0	0	FD	OK	None Obs.	
Transformers	21	0	0	DD FD	OK	None Obs.	
Chargers	21	0	0	FD	OK	None Obs.	
Washdown	21	0	0	mc	ok	none obs	
Storage Area	21	0	0	mc	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7335
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9158
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03723

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-5-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:40 AM/PM END 12:55 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 11:03 AM/PM END 12:35 AM/PM Examiners Initials FM
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LD	ok	none observed	
Main North Haulage Seals	20.9	0	0	LD	ok	none observed	
main West Haulage Seals	20.9	0	0	LD/FM	ok	None observed	
3rd North Haulage Seals	20.9	0	0	LD	ok	none observed	
1st Right Haulage	20.9	0	0	LD	ok	none observed	
transformers	20.9	0	0	LD/FM	ok	None observed	
chargers	20.9	0	0	LD/FM	ok	None observed	
washdown	209	0	0	FM	ok	None observed	
storag Area	209	0	0	FM	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9660
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR [redacted] CERT. # 7485

2MSHA03724

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1 5 07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 830 AM/PM END 902 AM/PM Examiners Initials GA
TIME OF EXAMINATION START 7:35 AM/PM END 9:45 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 8:31 AM/PM END 9:42 AM/PM Examiners Initials RH

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	GA	OK	None observed	
Main North Haulage seals	20.9	0	0	GA	OK	None observed	
Main West Haulage seals	20.9	0	0	BH/LH	OK	None Observed	
3rd North Haulage	20.9	0	0	BH/LH	OK	None Observed	
1st Right Haulage	20.9	0	0	LH	OK	None Observed	
Transformers	20.9	0	0	BH/LH	OK	None Observed	
Chargers	20.9	0	0	BH/LH	OK	None Observed	
Washdown	20.9	0	0	LH	OK	None Observed	
Storage Areas	20.9	0	0	BH/LH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 03892
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03725

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1 6 07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 350 AM/PM END 428 AM/PM Examiners Initials CA
TIME OF EXAMINATION START 3:05 AM/PM END 5:08 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CA	OK	None observed	
Main No Haulage Seals	20.9	0	0	CA	OK	None observed	
Main West Haulage Seals	20.9	0	0	BH	OK	None Observed	
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Areas	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 03892
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03726

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-6-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:05 AM/PM END 12:20 AM/PM Examiners Initials Km
TIME OF EXAMINATION START 12:00 AM/PM END 1:10 AM/PM Examiners Initials LD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	LD	ok	none observed	
Main North haulage & seals	20.9	0	0	LD	ok	none observed	
Main West haulage & seals	20.9	0	0	Km/LD	ok	none observed	
3rd North haulage	20.9	0	0	LD	ok	none observed	
1st right haulage	20.9	0	0	LD	ok	none observed	
transformers	20.9	0	0	Km/LD	ok	none observed	
chargers	20.9	0	0	Km/LD	ok	none observed	
wash down	20.9	0	0	Km	ok	none observed	
storage Areas	20.9	0	0	Km	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9379
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03727

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 16 07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 8:15 AM/PM END 8:49 AM/PM Examiners Initials CH
TIME OF EXAMINATION START 7:35 AM/PM END 9:50 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 9:08 AM/PM END 9:40 AM/PM Examiners Initials LH

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	CH	OK	None observed	
Main No Haulage Seals	21	0	0	CH	OK	None observed	
Main West Haulage Seals	20.9	0	0	BH/LH	OK	None Observed	
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/LH	OK	None Observed	
Chargers	20.9	0	0	BH/LH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
Storage Areas	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas & Travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 03892
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 6395
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8703
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 03892

2MSHA03728

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1 7 07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 355 AM/PM END 428 AM/PM Examiners Initials GA
TIME OF EXAMINATION START 3:00 AM/PM END 4:50 AM/PM Examiners Initials BH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	GA	OK	None observed	
Main No Haulage seals	20.9	0	0	GA	OK	None observed	
Main West Haulage Seals	20.9	0	0	BH	OK	Deep water X-cut 46 at Seal	Pumping DONE 1-2-06 GG
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Areas	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Except as noted above all area's safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 03892
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8395
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE SIGNATURE CERT. # 7485

2MSHA03729

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-7-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 12:00 AM/PM END 1:05 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 11:45 AM/PM END 1:30 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 11:00 AM/PM END 1:55 AM/PM Examiners Initials SW

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parcking	20.9	0	0	LD	ok	none observed	
Main North Haulage seals	20.9	0	0	LD	ok	none observed	
Main West Haulage seals	20.9	0	0	LD/TC/SW	ok	none obs.	
3rd North Haulage	20.9	0	0	LD	ok	none observed	
1st Right Haulage	20.9	0	0	LD	ok	none observed	
transformers	20.9	0	0	LD/TC/SW	ok	none obs	
chargers	20.9	0	0	LD/TC/SW	ok	none obs.	
Washdown	20.9	0	0	TC	ok	none obs.	
Storage Areas	20.9	0	0	TC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All AREAS Appeared to be safe At time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9660
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNAT [redacted] CERT. # 7485

2MSHA03730

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1 7 07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 825 AM/PM END 907 AM/PM Examiners Initials CA
TIME OF EXAMINATION START 8:13 AM/PM END 9:40 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 9:00 AM/PM END 9:40 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CA	OK	None observed	
Main No Haulage seals	20.9	0	0	CA	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH/LH	OK	None Observed	
3rd North Haulage	20.9	0	0	LH	OK	None Observed	
1st Right Haulage	20.9	0	0	LH	OK	None Observed	
Transformers	20.9	0	0	BH/LH	OK	None Observed	
Chargers	20.9	0	0	BH/LH	OK	None Observed	
washdown	20.9	0	0	LH	OK	None Observed	
Storage Areas	20.9	0	0	LH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 03892
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 03892

2MSHA03731

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1 9 07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 350 AM/PM END 429 AM/PM Examiners Initials CT
TIME OF EXAMINATION START 3:03 AM/PM END 4:15 AM/PM Examiners Initials LH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	CT	OK	None observed	
Main No Haulage Seals	21	0	0	CT	OK	None observed	
Main Haulage west seals	21	0	0	LH	OK	none obs	
3rd north Haulage	21	0	0	LH	OK	none obs	
Transformers	21	0	0	LH	OK	none obs	
chargers	21	0	0	LH	OK	none obs	
washdown	21	0	0	LH	OK	none obs	
storage Areas	21	0	0	LH	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe for work & Travel at time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 03892
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8703
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 4735

2MSHA03732

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-8-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:48 AM/PM END 12:50 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:00 AM/PM END 1:35 AM/PM Examiners Initials LR/RL
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	FM	OK	none observed	
MAIN North Haulage Seals	20.9	0	0	FM	OK	none observed	
MAIN West Haulage Seals	20.9	0	0	LR/RL	OK	Needs Watered on Haulage 98 to Section Transformer	Assigned man to water
3rd North Haulage	20.9	0	0	FM	OK	none observed	
1st Right	20.9	0	0	FM	OK	none observed	
transformers	20.9	0	0	LR/RL	OK	None observed	
Chargers	20.9	0	0	FM/RL/LR	OK	None observed	
Washdown	20.9	0	0	LR	OK	None observed	
Storage Area	20.9	0	0	RL	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved Safe at time of Exam except as Noted above

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 4735

2MSHA03733

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-8-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:06 AM/PM END 9:05 AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None observed	
Main North Haulage Seal	20.9	0	0	BH	OK	None observed	
main west Haulage Seals	20.9	0	0	BH	OK	~~None Observed~~ See Below BH	working on ~~[illegible]~~
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None observed	
Chargers	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Main west Haulage needs watered 98 to Section transformer

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03734

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-9-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 4:14 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 3:59 AM/PM END 4:20 AM/PM Examiners Initials [illegible]
TIME OF EXAMINATION START 3:48 AM/PM END 4:10 AM/PM Examiners Initials GA

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	Km	OK	None Observed	
Main North Haulage Seals	21	0	0	BH/Km	OK	None Observed	
Main Sotest Haulage Seals	21	0	0	BH	OK	Haulage Need watered 98 to section transformer	Maxwell to water @ pre DG
3rd North Haulage	21	0	0	GA	OK	None observed	
1st Right Haulage	21	0	0	GA	OK	None observed	
Transformers	21	0	0	GA BH/Km	OK	None Observed	
Chargers	21	0	0	BH/GA	OK	None Observed	
Washdown	21	0	0	BH	OK	None Observed	
Storage Area	21	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas and travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8385
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9379
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 03892
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 4735

2MSHA03735

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-9-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 12:55 AM/PM Examiners Initials LR
TIME OF EXAMINATION START 1:30 AM/PM END 1:15 AM/PM Examiners Initials FM/KK
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs.	
Main North Haulage Seals	20.9	0	0	LR	OK	None obs.	
Main West Haulage Seals	20.9	0	0	LR/KK FM	OK	None observed	
3rd North Haulage	20.9	0	0	LR	OK	Roadway Needs Watered	Ass. man to water done 1-9-07 LR
1 Right Haulage	20.9	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	LR/FM KK	OK	None obs.	
Chargers	20.9	0	0	LR	OK	None obs.	
Washdown	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of exam except as noted above

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 4735

2MSHA03736

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION _____ SECTION/AREA _____/_____/_____/_____

TIME OF EXAMINATION START_____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START_____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START_____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN

Void

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS _____

PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ CERT. # _____

2MSHA03737

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-9-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:30 AM/PM END 9:20 AM/PM Examiners Initials MC/FD
TIME OF EXAMINATION START 700 AM/PM END 805 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
main North Haulage Seals	21	0	0	DD	ok	none obs.	
main West Haulage Seals	20.9	0	0	MC/FD DD	ok	none observed	
3rd North Haulage	21	0	0	DD	ok	none obs.	
1st Right Haulage	21	0	0	DD	ok	none obs.	
Transformers	21	0	0	DD	ok	none obs.	
Chargers	21	0	0	DD	ok	none obs.	
washdown	20.9	0	0	FD	ok	none observed	
Storage Area	20.9	0	0	MC	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7575
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9158
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03738

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-10-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 300 AM/PM END 530 AM/PM Examiners Initials DD/FD
TIME OF EXAMINATION START 3:02 AM/PM END 4:03 AM/PM Examiners Initials MC
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM
CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	MC	ok	none observed	
Main north Haulage seals	21	0	0	MC	OK	none observed	
main west Haulage seals	21	0	0	DD/FD MC	ok	none obs.	
3rd North Haulage	21	0	0	MC	OK	none observed	
1st Right	21	0	0	MC	OK	none observed	
Trans.	21	0	0	MC	OK	none observed	
chargers	21	0	0	MC	OK	none observed	
wash down	21	0	0	FD	ok	none obs.	
Storage	21	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

PRE-SHIFT/MINE EXAMINE[redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINE[redacted] CERT. # 2385
PRE-SHIFT/MINE EXAMINE[redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE[redacted] CERT. # 4735

2MSHA03739

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-10-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 12:00 AM/PM END 12:41 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:00 AM/PM END 1:20 AM/PM Examiners Initials SK
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
MAIN North haulage seals	20.9	0	0	FM	OK	none observed	
MAIN West Haulage seals	20.9	0	0	KK	OK	none observed	
3rd North Haulage	20.9	0	0	KK	OK	none observed	
1st Right	20.9	0	0	KK	OK	none observed	
Transformers	20.9	0	0	KK	OK	none observed	
Chargers	20.9	0	0	KK	OK	none observed	
Washdown	20.9	0	0	KK	OK	none observed	
Storage Area	20.9	0	0	KK	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 4735

2MSHA03740

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-10-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:20 AM/PM END 9:15 AM/PM Examiners Initials MC/DD
TIME OF EXAMINATION START 7:00 AM/PM END 8:00 AM/PM Examiners Initials FD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	FD	OK	None Obs.	
Main North Haulage Seals	21	0	0	FD	OK	None Obs.	
Main West Haulage Seals	20.9	0	0	MC/DD FD	OK	none observed	
3rd North Haulage	21	0	0	FD	OK	None Obs.	
1st Right Haulage	21	0	0	FD	OK	None Obs.	
Transformers	21	0	0	MC/FD	OK	None Obs.	
Chargers	21	0	0	MC/FD	OK	None Obs.	
Washdown	20.9	0	0	MC	OK	None observed	
Storage Area	20.9	0	0	MC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe at the time of exam.

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 735
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9458
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8058
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # ____

COUNTER SIGNATURE SIGNATURE CERT. # 8462

2MSHA03741

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-11-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:25 AM/PM END 5:20 AM/PM Examiners Initials MC/FD
TIME OF EXAMINATION START 500 AM/PM END 405 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs	
main north Haulage seals	21	0	0	DD	ok	none obs.	
main west Haulage seals	20.9	0	0	MC/FD	ok	none observed	
3rd North Haulage	21	0	0	DD	ok	none obs.	
1st Right Haulage	21	0	0	DD	ok	none obs.	
Transformers	21	0	0	DD	ok	none obs.	
chargers	21	0	0	DD	ok	none obs	
washdown	20.9	0	0	FD	ok	none observed	
storage Area	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

2MSHA03742

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 4735

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-11-07 SECTION/AREA Gen / / /

TIME OF EXAMINATION START 11:51 AM/PM END 1:05 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 11:00 AM/PM END 1:15 AM/PM Examiners Initials FM/LR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	KK	ok	none	
Main North Haulage roads	20.9	0	0	KK	ok	none	
Main West Haulage roads	20.9	0	0	KK FM LR	ok	None observed	
3rd north	20.9	0	0	KK	ok	none	
1st right	20.9	0	0	KK	ok	none	
chargers	20.9	0	0	KK	ok	none	
Trans.	20.9	0	0	KK FM	ok	None observed	
Washdown	20.9	0	0	KK	ok	none	
Storage area	20.9	0	0	KK	ok	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas Appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 4135

2MSHA03743

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-11-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:07 AM/PM END 7:59 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 700 AM/PM END 935 AM/PM Examiners Initials DD FD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	ok	none observed	
Main North Haulage Seals	20.9	0	0	MC	ok	none observed	
Main West Haulage Seals	21	0	0	MC DD/FD	ok	none obs.	
3rd North Haulage	20.9	0	0	MC	ok	none observed	
1st Right Haulage	20.9	0	0	MC	ok	none observed	
Transformers	20.9	0	0	MC	ok	none observed	
Chargers	20.9	0	0	MC	ok	none observed	
Washdown	20.9	0	0	DD	ok	none obs.	
Storage Areas	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe at Time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8762

2MSHA03744

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-12-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 7:25 AM/PM END 5:15 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 300 AM/PM END 520 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 300 AM/PM END 400 AM/PM Examiners Initials SD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	SD	OK	None obs.	
main North Haulage Seals	21	0	0	SD	OK	None obs.	
main West Haulage Seals	20.9	0	0	mc/DD	OK	none observed	
3rd North Haulage	21	0	0	SD	OK	None obs.	
1st Right Haulage	21	0	0	SD	OK	None obs.	
Transformers	20.9	0	0	mc/DD	OK	none observed	
chargers	21	0	0	SD	OK	None obs.	
washdown	20.9	0	0	mc	ok	none observed	
storage area	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe at the time of exam.

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7385
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9458
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03745

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-12-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:47 AM/PM END 1:12 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 11:10 AM/PM END 1:15 AM/PM Examiners Initials JW
TIME OF EXAMINATION START 11:48 AM/PM END 1:00 AM/PM Examiners Initials FM

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	None observed	
Main North Haulage Seals	20.9	00		FM	ok	None observed	
Main West Haulage Seals	20.9	0	0	~~LD~~/FM	ok	None observed	
3rd North Haulage	20.9	0	0	FM	ok	None observed	
1st Right Haulage	20.9	0	0	FM	ok	None observed	
Transformers	20.9	0	0	~~LD~~/FM	ok	None observed	
Chargers	20.9	0	0	FM	ok	None observed	
Wash down	20.9	0	0	LD	ok	none observed	
Storage Areas	20.9	0	0	~~LD~~	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9660
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR Signature CERT. # 7485

2MSHA03746

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1/12/07 SECTION/AREA gen mine / /

TIME OF EXAMINATION START 7:52 AM/PM END 8:57 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 7:45 AM/PM END 8:00 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 7:42 AM/PM END 9:15 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Haulage, seals Main north	20.9	0	0	BH	OK	None observed	
Haulage, seals Main west	21	0	0	LH/BH/BP	OK	none observed	
3rd north Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Trans	21	0	0	LH/BH/BP	OK	none observed	
Chargers	20.9	0	0	BH	OK	None observed	
washdown	20.9	0	0	BH	OK	None observed	
storage	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8703
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8599
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8395
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 03892

2MSHA03747

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-13-09 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 340 AM/PM END 400 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 330 AM/PM END 340 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 3:45 AM/PM END 5:20 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	BH	OK	None Observed	
main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
main west Haulage Seals	20.9	0	0	BP BH LH	OK	none observed	
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BP BH LH	OK	none observed	
Chargers	20.9	0	0	BH	OK	None Observed	
wash down	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 2599
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8203
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03748

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-13-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 11:00 AM/PM END 12:45 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 11:05 AM/PM END 12:15 AM/PM Examiners Initials LD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	LD	ok	none observed	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	LD	ok	none observed	
MAIN WEST HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE SEALS	20.9	0	0	LD	ok	none observed	
1ST RIGHT HAULAGE	20.9	0	0	LD	ok	none observed	
TRANSFORMERS	20.9	0	0	JG	Ok	NONE OBSERVED	
CHARGERS	20.9	0	0	JG	Ok	NONE OBSERVED	
WASHDOWN	20.9	0	0	JG	Ok	NONE OBSERVED	
STORAGE AREA	20.9	0	0	JG	Ok	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9660
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03749

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-13-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:40 AM/PM END 9:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 8:00 AM/PM END 830 AM/PM Examiners Initials BP
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	BH	OK	None	
Main North Haulage Seals	20.9	0	0	BH	OK	None	
Main West Haulage Seals	20.9	0	0	BH/BP	OK	None	
3rd North Haulage	20.9	0	0	BH	OK	None	
1st Right Haulage	20.9	0	0	BH	OK	None	
transformers	20.9	0	0	BH/BP	OK	None	
Chargers	20.9	0	0	BH	OK	None	
Washdown	20.9	0	0	BH	OK	None	
~~Storage Areas~~	~~20.9~~	~~0~~	~~0~~		~~OK~~		
Storage Areas	20.9	0	0	BH	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9599
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03750

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-14-06 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:47 AM/PM END 5:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 3:45 AM/PM END 5:20 AM/PM Examiners Initials LH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North Haulage Seals	20.9	0	0	BH	OK	None	
~~Main~~ Packing Area	20.9	0	0	BH	OK	None	
Seals Haulage Main West	21	0	0	LH/BH	OK	none obs	
3rd North Haulage	20.9	0	0	BH	OK	None	
1st Right Haulage	20.9	0	0	BH	OK	None	
Trans	20.9	0	0	BH/LH	OK	None	
Chargers	20.9	0	0	BH	OK	None	
Washdown	20.9	0	0	BH	OK	None	
Storage Areas	20.9	0	0	BH	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8395
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8703
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 7485

2MSHA03751

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-14-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:50 AM/PM END 1:05 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 11:08 AM/PM END 12:15 AM/PM Examiners Initials JG
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LD	ok	none observed	
Main North Haulage Seals	20.9	0	0	LD	ok	none observed	
Main West Haulage Seals	20.9	0	0	LD/JG	ok	NONE OBSERVED	
3rd North Haulage Seals	20.9	0	0	LD	ok	none observed	
1st Right Haulage	20.9	0	0	LD	ok	none observed	
transformers	20.9	0	0	LD	ok	none observed	
chargers	20.9	0	0	LD	ok	none observed	
washdown	20.9	0	0	JG	ok	NONE OBSERVED	
storage Areas	20.9	0	0	LD	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9660
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03752

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-14-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:20 AM/PM END 9:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH	OK	None Observed	
3rd North Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03753

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-15-07 SECTION/AREA Canadice / /

TIME OF EXAMINATION START 350 AM/PM END 420 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 3:50 AM/PM END 5:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	BH	OK	None Observed	
main north Haulage Seals	20.9	0	0	BH	OK	None Observed	
main west Haulage Seals	20.9	0	0	BP/BH	OK	none observed	
3rd north Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None observed	
Transformers	20.9	0	0	BP/BH	OK	none observed	
chargers	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
Storage Areas	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 9899
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 8375
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE CERT. # 8462

2MSHA03754

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-15-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:53 AM/PM END 12:41 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 11:00 AM/PM END 12:53 AM/PM Examiners Initials FM
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	None observed	
Main North Haulage Seals	20.9	0	0	MC	OK	None observed	
Main West Haulage Seals	20.9	0	0	MC/FM	OK	None observed	
3rd North Haulage	20.9	0	0	FM	OK	None observed	
1st Right Haulage	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	MC/FM	OK	None observed	
Chargers	20.9	0	0	FM	OK	None observed	
Washdown	20.9	0	0	FM	OK	None observed	
Storage Area	20.9	0	0	FM	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03755

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-15-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 8:10 AM/PM Examiners Initials LR
TIME OF EXAMINATION START 7:00 AM/PM END 9:35 AM/PM Examiners Initials KK/RL
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs.	
Main North Haulage Seals	20.9	0	0	LR	OK	None obs.	
Main West Haulage Seals	20.9	0	0	LR/KK/RL	OK	None obs.	
3rd North Haulage	20.9	0	0	LR	OK	None obs.	
1st Right Haulage	20.9	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	LR/KK/RL	OK	None obs.	
Chargers	20.9	0	0	LR	OK	None obs.	
Washdown	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 4325
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____

COUNTER SIGNATU Signature [redacted] CERT. # 4735

2MSHA03756

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-16-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 3:00 AM/PM END 4:45 AM/PM Examiners Initials LR
TIME OF EXAMINATION START 3:00 AM/PM END 5:15 AM/PM Examiners Initials KK/RL
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs.	
Mains North Haulage Seals	20.9	0	0	LR/KK/RL	OK	None obs.	
Mains West Haulage Seals	20.9	0	0	KK/RL	OK	None obs.	
3rd North Haulage	20.9	0	0	LR	OK	None obs.	
1st Right Haulage	20.9	0	0	LR	OK	None obs.	
Transformer	20.9	0	0	LR/KK/RL	OK	None obs.	
Chargers	20.9	0	0	LR	OK	None obs.	
Washdowns	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 4375
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 6404
PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7454
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE SIGNATURE CERT. # 8462

2MSHA03757

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-16-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 12:54 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 1100 AM/PM END 1200 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21	0	0	DD	ok	none obs.	
MAIN North haulage seals	21	0	0	DD	ok	none obs.	
MAIN West haulage seals	209	0	0	FM/DD	ok	none obs.	
3rd North haulage	209	0	0	FM	ok	none observed	
1st Right	209	0	0	FM	ok	none observed	
Transformers	209	0	0	FM/DD	ok	none obs.	
Chargers	209	0	0	FM	ok	none observed	
washdown	209	0	0	FM	ok	none observed	
storage area	209	0	0	FM	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 8462

2MSHA03758

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-16-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 930 AM/PM Examiners Initials RK/RL
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	RL	OK	none	
Main North Haulage Seals	20.9	0	0	RL	OK	none	
Main West Haulage Seals	20.9	0	0	RL/RR/RK	OK	None	
3rd North haulage	20.9	0	0	RL	OK	none	
1st Right	20.9	0	0	RL	OK	none	
Transformers	20.9	0	0	RL/RR/RK	OK	none	
Chargers	20.9	0	0	RL	OK	none	
Washdown	20.9	0	0	RL	OK	none	
Storage Area	20.9	0	0	RL	OK	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 7854
PRE-SHIFT/MINE EXAMINER CERT. # ____

COUNTER SIGNATURE SIGNATURE CERT. # 4735

2MSHA03759

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-17-07 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 400 AM/PM Examiners Initials LR
TIME OF EXAMINATION START 300 AM/PM END 530 AM/PM Examiners Initials RL/KK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs.	
Main North Haulage Seals	20.9	0	0	LR	OK	None obs.	
Main West Haulage Seals	20.9	0	0	LR/KK/RL	OK	None obs.	
3rd North Haulage	20.9	0	0	LR	OK	None obs.	
1st Right Haulage	20.9	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	LR/KK/RL	OK	None obs.	
Chargers	20.9	0	0	LR	OK	None obs.	
Washdown	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # ____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 8462

2MSHA03760

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-17-07 SECTION/AREA Gen. Mine / /

TIME OF EXAMINATION START 1200 AM/PM END 100 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 12:10 AM/PM END 1:00 AM/PM Examiners Initials KM
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	ok	none obs.	
Main North Haulage/Seals	20.9	0	0	DD	ok	none obs.	
main west Haulage seals	20.9	0	0	DD/KM	ok	none obs.	
3rd North Haulage	20.9	0	0	KM	OK	none observed	
1st Right	20.9	0	0	KM	ok	none observed	
Trans.	20.9	0	0	DD/KM	ok	none obs.	
chargers	20.9	0	0	KM	ok	none observed	
Washdown	20.9	0	0	KM	ok	none observed	
Storage Area	20.9	0	0	KM	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS _____

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9329
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 8462

2MSHA03761

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-17-02 SECTION/AREA Gen Mine / / / /

TIME OF EXAMINATION START 830 AM/PM END 930 AM/PM Examiners Initials RL
TIME OF EXAMINATION START 8.00 AM/PM END 9.30 AM/PM Examiners Initials KK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	RL	OK	none observed	
Main North Seal Haulage	21	0	0	RL	OK	none "	
Main West Seal Haulage	21	0	0	RL/KK	OK	none obs	
3rd North Haulage	21	0	0	RL	OK	none observed	
1st Right Haulage	21	0	0	RL	OK	none observed	
Transformers	21	0	0	RL	OK	none "	
Chargers	21	0	0	RL	OK	none "	
Washdown	21	0	0	RL	OK	none "	
Storage area	21	0	0	RL	OK	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe ~~[illegible]~~ at time of pre-shift

SIGNATURE [redacted]

PRE-SHIFT/MINE EXAMINER ____ CERT. # 6401
PRE-SHIFT/MINE EXAMINER ____ CERT. # 7964
PRE-SHIFT/MINE EXAMINER ____ CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

SIGNATURE [redacted]

COUNTER SIGNATURE ____ CERT. # 4755

2MSHA03762

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-18-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 540 AM/PM Examiners Initials RL/KK
TIME OF EXAMINATION START 300 AM/PM END 500 AM/PM Examiners Initials LR
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs.	
Main North Haulage Seals	20.9	0	0	LR	OK	None obs.	
Main West Seals Haulage	20.9	0	0	RL/KK/LR	OK	None obs.	
3rd North Haulage	20.9	0	0	LR	OK	None obs.	
1st Right Haulage	20.9	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	RL/KK/LR	OK	None obs.	
Chargers	20.9	0	0	LR	OK	None obs.	
Washdown	20.9	0	0	LR	OK	None obs	
Storage Area	20.9	0	0	LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas seemed safe at time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7154
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03763

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-18-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:55 AM/PM END 12:45 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:12 AM/PM END 12:50 AM/PM Examiners Initials mc
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	none observed	
Main North haulage Seals	20.9	0	0	FM	ok	none observed	
Main West haulage Seals	20.9	0	0	mc	ok	Stopping # 140 needs Foamed	working on Done 1-18-07 mc
3rd North haulage	20.9	0	0	mc	ok	none observed	
1st Right	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	FM/mc	ok	none observed	
Chargers	20.9	0	0	mc	ok	none observed	
Storage Area	20.9	0	0	mc	ok	none observed	
Washdown	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe At time of preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7385
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 1175

2MSHA03764

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-18-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:57 AM/PM END 9:18 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 8:15 AM/PM END 920 AM/PM Examiners Initials LR/RL
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO X CALL OUT TIME -------- AM/PM
CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	21.0	0	0	KK	OK	None	
M. North Hanger seals	21.0	0	0	KK	OK	None	
M. West Hanger seals	20.9	0	0	KK/LR/RL	6	None	
3rd North	20.9	0	0	KK	OK	None	
Freight	20.9	0	0	KK	OK	None	
Trans.	20.9	0	0	KK/LR/RL	OK	None	
chargers	20.9	0	0	KK	OK	None	
storage area	20.9	0	0	KK	OK	None	
Washdown	20.9	0	0	KK	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

SIGNATURE

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 4323
PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. #

SIGNATURE

COUNTER SIGNATURE [redacted] CERT. # 4735

2MSHA03765

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-19-07 SECTION/AREA Gen Mine / / / /

TIME OF EXAMINATION START 3:45 AM/PM END 5:20 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 3:10 AM/PM END 5:35 AM/PM Examiners Initials KR/RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	21.0	0	0	KK	ok	none	
M. North Haulage seals	20.9	0	0	KK	ok	none	
M. West Haulage seals	21.0	0	0	KK/KR/RL	ok	none	
3rd North	20.9	0	0	KK	ok	none	
1st right	20.9	0	0	KK	ok	none	
storage area	20.9	0	0	KK	ok	none	
Washdown	20.9	0	0	KK	ok	none	
Trans.	20.9	0	0	KK/KR/RL	ok	None	
chargers	20.9	0	0	KK	ok	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6400
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____

2MSHA03766

COUNTER SIGNATURE [redacted] CERT. # 03892

SIGNATURE

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-19-07 SECTION/AREA Genmine / / /

TIME OF EXAMINATION START 11:45 AM/PM END 12:10 AM/PM Examiners Initials MC/Fm
TIME OF EXAMINATION START 11:05 AM/PM END 1:15 AM/PM Examiners Initials BH
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM
CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc/Fm	ok	none observed	
main north Haulage seals	20.9	0	0	mc/Fm	ok	none observed	
main west Haulage seals	20.9	0	0	BH	OK	None Observed	
3rd north Haulage	20.9	0	0	BH	OK	None observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
chargers	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at Time of exam

SIGNATURE

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. #

2MSHA03767

SIGNATURE

COUNTER SIGNATURE [redacted] CERT. # 03893

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-19-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 8:55 AM/PM END 9:35 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 7:10 AM/PM END 8:32 AM/PM Examiners Initials CH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- 9:33 AM/PM
CALLED OUT BY Charlie Whitten
CALLED OUT BY _____ REPORT RECEIVED B[redacted] _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	CH	OK	NEED ROCK DUST 132-133 X-CUT	SENT MAN TO DUST DONE JG
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
UNDERGROUND STORAGE	20.9	0	0	CH	OK	none obs.	
WASH DOWN	20.9	0	0	CH	OK	none obs.	
TRANSFORMERS	20.9	0	0	CH	OK	none obs.	
CHARGERS	20.9	0	0	CH	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Other Than noted ABOVE AREAS SAFE AT Time of Preshift

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7999
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR[redacted] CERT. # 7485

2MSHA03768

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-20-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 3:45 AM/PM END 4:55 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 3:10 AM/PM END 5:35 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 4:44 AM/PM END 5:20 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	TC/SW	OK	none observed	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE	20.9	0	0	TC	ok	none obs.	
WASHDOWN	20.9	0	0	TC	ok	none obs	
TRANSFORMERS	20.9	0	0	SW	OK	none observed	
CHARGERS	20.9	0	0	SW	OK	none observed.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at time of Pre-shift.

PRE-SHIFT/MINE EXAMINER SIGNATURE [redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE SIGNATURE [redacted] CERT. # 03892

2MSHA03769

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1/20/07 SECTION/AREA gen / / /

TIME OF EXAMINATION START 12:05 AM/PM END 1250 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 12:05 AM/PM END 1:35 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
main West Haulage Seals	21	0	0	LH/BH	OK	none observed	
3rd north Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Storage	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
Trans	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at Time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8703
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03770

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1 2007 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 7:50 AM/PM END 8:40 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 7:00 AM/PM END 9:35 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:51 AM/PM END 9:28 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	~~SW~~ JG	OK	none observed	
3RD NORTH HAULAGE-SEAL	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE	20.9	0	0	TC	OK	none obs.	
WASH DOWN	20.9	0	0	TC	OK	none obs.	
TRANS	20.9	0	0	SW	OK	none observed	
CHARGERS	20.9	0	0	~~JG~~ TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at time of Pre-shift.

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7485

2MSHA03771

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-21-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 3:59 AM/PM END 4:45 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 3:05 AM/PM END 5:35 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:49 AM/PM END 5:30 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	SW/JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE AREA	20.9	0	0	TC	OK	none obs	
WASHROOM	20.9	0	0	TC	OK	none obs.	
TRANS/CHARGER	20.9	0	0	SW/JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS TRAVELED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 03892

2MSHA03772

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-21-06 SECTION/AREA Gen mine 1

TIME OF EXAMINATION START 1154 AM/PM END 1215 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 1147 AM/PM END 1122 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
main north Haulage Seals	20.9	0	0	BH	OK	None observed	
main East Haulage Seals	20.9	0	0	BH/BH	ok	none observed	
3rd north Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
Trans/Charge	20.9	0	0	BH/BH	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9599
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 1485

2MSHA03773

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-21-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 8:14 AM/PM END 9:00 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 7:00 AM/PM END 9:40 AM/PM Examiners Initials JW
TIME OF EXAMINATION START 7:49 AM/PM END 9:30 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	JW JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE	20.9	0	0	TC JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	TC	OK	NONE OBSERVED	
TRANSFORMERS CHARGERS	20.9	0	0	TC JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe to travel at time of Pre-shift.

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9548
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 7488

2MSHA03774

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-22-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 4:00 AM/PM END 4:40 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 3:00 AM/PM END 5:36 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:44 AM/PM END 5:25 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	SW/JG	OK	none observed	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE	20.9	0	0	TC	OK	none obs.	
WASHDOWN	20.9	0	0	TC	OK	NONE Obs.	
TRANSFORMER, CHARGERS	20.9	0	0	SW/JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe to travel at time of Preshift.

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7485
PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8925

2MSHA03775

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-22-07 SECTION/AREA Pewmine / / /

TIME OF EXAMINATION START 11:07 AM/PM END 12:45 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 11:54 AM/PM END 12:42 AM/PM Examiners Initials FM
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	Fm	ok	none observed	
Main North Haulage Seals	20.9	0	0	Fm	ok	none observed	
Main West Haulage Seals	20.9	0	0	mc	ok	none observed	
3rd North Haulage	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	mc	ok	none observed	
Chargers	20.9	0	0	mc	ok	none observed	
washdown	20.9	0	0	mc	ok	none observed	
Storage Area	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe at time of preshift

SIGNATURE [redacted]

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7385
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

SIGNATURE [redacted]

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03776

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-22-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:21 AM/PM END 8:25 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 7:20 AM/PM END 8:44 AM/PM Examiners Initials KK
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	21.0	0	0	KK	ok	none observed	
main North Haulage	21.0	0	0	KK	ok	none observed	
Main West Haulage	20.9	0	0	KK/LR/RL	ok	none observed	
2nd North Haulage	20.9	0	0	KK	ok	none observed	
1st Right Haulage	20.9	0	0	KK	ok	none observed	
Trans	20.9	0	0	KK/LR/RL	ok	none observed	
chargers	20.9	0	0	KK	ok	none observed	
washdown	20.9	0	0	KK	ok	none observed	
storage area	20.9	0	0	KK	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7954
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE [redacted] CERT. # 4735

2MSHA03777

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-23-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 310 AM/PM END 535 AM/PM Examiners Initials SR/RL/KK
TIME OF EXAMINATION START 3.50 AM/PM END 505 AM/PM Examiners Initials KK
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM
CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking	20.9	Ø	Ø	KK	OK	none	
Main North Seals Haulage	20.9	Ø	Ø	KK	OK	none	
Main West Seals Haulage	20.9	Ø	Ø	RL/JR/KK	OK	none	
3rd North Haulage	20.9	Ø	Ø	KK	OK	none	
1st Right Haulage	20.9	Ø	Ø	KK	OK	none	
Transformer	20.9	Ø	Ø	RL/JR/KK	OK	none	
Chargers	20.9	Ø	Ø	KK	OK	none	
Washdown	20.9	Ø	Ø	KK	OK	none	
Storage area	20.9	Ø	Ø	KK	OK	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. #

2MSHA03778

COUNTER SIGNATURE [redacted] CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-23-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:57 AM/PM END 12:45 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 1100 AM/PM END 10:5 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	None observed	
MAIN North Haulage Seals	20.9	0	0	FM	ok	None observed	
MAIN West Haulage Seals	20.9	0	0	DD	ok	none obs.	
3rd North haulage	20.9	0	0	DD	ok	none obs.	
1st Right	20.9	0	0	DD	ok	none obs.	
Transformers	20.9	0	0	DD	ok	none obs.	
Chargers	20.9	0	0	DD	ok	none obs.	
Storage Area	20.9	0	0	DD	ok	none obs.	
Washdown	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8297
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 8462

2MSHA03779

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-23-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 825 AM/PM Examiners Initials LR
TIME OF EXAMINATION START 7:00 AM/PM END 945 AM/PM Examiners Initials LR/RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	ok	None obs.	
Main North Seals Haulage	20.9	0	0	LR	ok	None obs.	
Main West Seals Haulage	20.9	0	0	LR/LK/RL	ok	none obs.	
3rd North Haulage	20.9	0	0	LR	ok	None obs.	
1st Right Haulage	20.9	0	0	LR	ok	None obs.	
Transformers	20.9	0	0	LR/LK/RL	ok	none obs.	
Chargers	20.9	0	0	LR	ok	None obs.	
Wash down	20.9	0	0	LR	ok	None obs.	
Storage Area	20.9	0	0	LR	ok	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 4375
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 6401
PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 7959
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [redacted] CERT. # 4135

2MSHA03780

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-24-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 308 AM/PM END 540 AM/PM Examiners Initials RL/KK
TIME OF EXAMINATION START 300 AM/PM END 510 AM/PM Examiners Initials LR
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking	20.9	0	0	LR	OK	None	
Main North Seals Haulage	20.9	0	0	LR	OK	None	
Main West Seals Haulage	20.9	0	0	RL/KK	OK	None	
3rd North Haulage	20.9	0	0	LR	OK	None	
1st Right Haulage	20.9	0	0	LR	OK	None	
Transformer	20.9	0	0	RL/KK	OK	None	
Lagoon	20.9	0	0	LR	OK	None	
Washdown	20.9	0	0	LR	OK	None	
Storage Area	20.9	0	0	LR	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER SIGNATURE CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 4325
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE SIGNATURE CERT. # 8462

2MSHA03781

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-24-07 SECTION/AREA Ben Mine / /

TIME OF EXAMINATION START 12:15 AM/PM END 1:00 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 11:27 AM/PM END 1:02 AM/PM Examiners Initials MC
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM
CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
Main North Seals Haulage	21	0	0	DD	ok	none obs.	
Main West Seals Haulage	20.9	0	0	mc	ok	none observed	
3rd North Haulage	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Trans.	20.9	0	0	mc	ok	none observed	
Chargers	20.9	0	0	mc	ok	none observed	
Washdown	20.9	0	0	mc	ok	none observed	
Storage Area	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at Time of preshift

SIGNATURE

PRE-SHIFT/MINE EXAMINER [redacted] CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATU[redacted] CERT. # 8462

2MSHA03782