MSHA Form 7000-10H, June 93 (revised)

GENERAL INFORMATION COVER SHEET

Inspection Code E02 Event No. 4116864

Company Name Performance Coal Co

Mine Name Upper Big Branch

Mine I.D. Number 46-08436

Date(s) of Mine File Review 1-30-7

D Status X Citation/Order No. ______ Date ______

Dates of Inspection: began 1-30-7 completed 1-30-7

Pre-Inspection Conference Date 1-30-7

Company Representative(s) [redacted]

Miners Representative(s) None

Post-Inspection Conference Date 1-30-7

Company Representative(s) [redacted]

Miners Representative(s) None

Comments: None

Inspector's In[redacted] Supervisor's Initials and Date [initials] 2-1-7

*U.S. Government Printing Office: 1995 — 609-287

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 1-30-7 Event No. 4116864

Arrived at the Mine ——— Departed from the Mine ———

List Records Books Checked preshift onshift

Accompanied By: Company Representative

[redacted]

Miners Representative None

AREAS OF INSPECTION ACTIVITY:

103 SPOT

Inspector's Initials [redacted]

Supervisor's Initials and Date [initials] 2-1-7 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 1-30-7

Met with [redacted] [redacted] informed him that we was going to do a methane spot today. Travel from the surface to the mouth of UBB into the intake escape-way. Travel to break 124 CH_4 detected 20.8 O_2, check the return for 030 section were seals was being install. 002 methane was found.

Travel from the down No. 4-5 belt.

Inspector's Initi[redacted]

Supervisor's Initials and Date [initials] 2-1-7 Page No. 2

GPO U.S. GPO: 2006-543-041

MSHA Form 7000-10K, June 93 (revised)

Date 1-30-7

belts to the surface. CH_4 was detected on the belt and travel, 20.8 O_2

Inspector's Init[redacted]

Supervisor's Initials and Date [initials] 2-1-7 Page No. 3

GPO U.S. GPO: 2006-543-041