PR001
22-Apr-14

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
Fatal Injury	Fall of Rib	04/11/2014 08:45 AM	04/11/2014 08:45 AM	5

6. Mine Information :

a) Mining Company Name	b) Mine Name	c) Parent of Mining Company
Mississippi Lime Company	Mississippi Lime Company-Ste. Genevieve	Margaret J Heckman

7. Mine Location : a) City	b) County	c) State	8. Mine ID Number:	9. Union:
Ste Genevieve	Ste Genevieve	MO	23-00542	YES

10. Primary Mineral Mined:	11. Number of Mine Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
LIME, N.E.C.	559	128		386	45

12. Contractor Name:	13. Union	14. Contractor ID Number:

15. Contractor Address: a) City	b) County	c) State	d) Zip Code

16. Number of Contractor Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other

17. Number of Persons in Mine at Time of Accident:		18. Number of Persons Unaccounted For:	
a) Mine Employees: 72	b) Contractor Employees:	a) Mine Employees: 0	b) Contractor Employees:

19) Location of Accident

- [X] 01-Underground
- [ ] 02-Surface at Underground
- [ ] 03-Open Pit
- [ ] 06-Dredge Mining
- [ ] 07-Advance Mining
- [ ] 08-Retreat Mining
- [ ] 30-Mill/Prep Plant
- [ ] 99-Office Facility
- [ ] Other (specify)

20. Mining Height: Feet Inches

21. Nonfatal Injuries:	22. Fatal Injuries:
	2

23. Victim Information : a) Name	b) Age
Chris R. Rawson	29

c) Regular Job Title:	d) Activity at Time of Accident:	[X] Mine Employee
Scaler	Scaling	

24. Experience :	Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days
a) Total:	7	45	3	b) at the mine:	6	12	4	c) at activity (23d)	17	2		d) with Contractor			

25. Autopsy Performed:	If Yes, Location	26. Mine Telephone No.:
YES	Mineral Area Hospital, Farmington MO	(573) 883-4020

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victims were scaling from a man basket on a boom truck when large slabs of rock struck the boom causing it to separate from the truck.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:
International	

30. District:	32. Field Office:	33. Event Number:
M5000 South Central	Rolla-South MO	6609900

34. Accident Investigator:	35. MSHA Person Notified:	Date	Time
William O'Dell	Elwood M. Burriss	04/11/2014	09:00 A

36. Type of Report:	37. Name of Preparer and Date Prepared	Date
Amended	Mike Hancher MH	04/13/2014

38. Reason For Amendment:

Items 3; 11a,b,de,e; 17a

PR001
22-Apr-14

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
Fatal Injury	Fall of Rib	04/11/2014 08:45 AM	04/11/2014 08:45 AM	6

6. Mine Information :

a) Mining Company Name	b) Mine Name	c) Parent of Mining Company
Mississippi Lime Company	Mississippi Lime Company-Ste. Genevieve	Margaret J Heckman

7. Mine Location : a) City	b) County	c) State	8. Mine ID Number:	9. Union:
Ste Genevieve	Ste Genevieve	MO	23-00542	YES

10. Primary Mineral Mined:	11. Number of Mine Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
LIME, N.E.C.	559	128		386	45

12. Contractor Name:	13. Union	14. Contractor ID Number:

15. Contractor Address: a) City	b) County	c) State	d) Zip Code

16. Number of Contractor Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other

17. Number of Persons in Mine at Time of Accident: a) Mine Employees:	b) Contractor Employees:	18. Number of Persons Unaccounted For: a) Mine Employees:	b) Contractor Employees:
72		0	

19) Location of Accident
- [X] 01-Underground
- [ ] 02-Surface at Underground
- [ ] 03-Open Pit
- [ ] 06-Dredge Mining
- [ ] 07-Advance Mining
- [ ] 08-Retreat Mining
- [ ] 30-Mill/Prep Plant
- [ ] 99-Office Facility
- [ ] Other (specify)

20. Mining Height: Feet Inches

21. Nonfatal Injuries:	22. Fatal Injuries:
	2

23. Victim Information : a) Name	b) Age
John E. Hahl	53

c) Regular Job Title:	d) Activity at Time of Accident:	[X] Mine Employee
Scaler	Scaling	

24. Experience :	Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days
a) Total:	8	16	6	b) at the mine:	7	43	6	c) at activity (23d)	3	16	0	d) with Contractor			

25. Autopsy Performed:	If Yes, Location	26. Mine Telephone No.:
YES	Mineral Area Hospital, Farmington MO	(573) 883-4020

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victims were scaling from a man basket on a boom truck when large slabs of rock struck the boom causing it to separate from the truck.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:
International	

30. District:	32. Field Office:	33. Event Number:
M5000 South Central	Rolla-South MO	6609900

34. Accident Investigator:	35. MSHA Person Notified:	Date	Time
William O'Dell	Elwood M. Burriss	04/11/2014	09:00 A

36. Type of Report:	37. Name of Preparer and Date Prepared	Date
Amended	Mike Hancher MH	04/13/2014

38. Reason For Amendment:
Items 3; 11a,b,de,e; 17a