PR001
19-Feb-15

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
Fatal Injury	Other Accident	06/17/2014 10:30 AM	06/17/2014 10:30 AM	26

6. Mine Information :

a) Mining Company Name	b) Mine Name	c) Parent of Mining Company
Holcim (Texas) LP	Holcim (Texas) LP	Holcim Ltd; Crow Holdings

7. Mine Location : a) City	b) County	c) State	8. Mine ID Number:	9. Union:
Midlothian	Ellis	TX	41-03307	NO

10. Primary Mineral Mined:	11. Number of Mine Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
HYDRAULIC CEMENT	135			135	

12. Contractor Name:	13. Union	14. Contractor ID Number:
Star Bulk	NO	ZZZ

15. Contractor Address: a) City	b) County	c) State	d) Zip Code
Midlothian	Ellis	TX	76065

16. Number of Contractor Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
45		15	30	

17. Number of Persons in Mine at Time of Accident:		18. Number of Persons Unaccounted For:	
a) Mine Employees: 81	b) Contractor Employees: 45	a) Mine Employees:	b) Contractor Employees:

19) Location of Accident

- [ ] 01-Underground
- [ ] 02-Surface at Underground
- [ ] 03-Open Pit
- [ ] 06-Dredge Mining
- [ ] 07-Advance Mining
- [ ] 08-Retreat Mining
- [X] 30-Mill/Prep Plant
- [ ] 99-Office Facility
- [ ] Other (specify)

20. Mining Height: Feet Inches

21. Nonfatal Injuries:	22. Fatal Injuries:
	1

23. Victim Information : a) Name	b) Age
Ronald Dunn	41

c) Regular Job Title:	d) Activity at Time of Accident:	
Truck Driver	Opening truck hatch	[X] Contractor Employee

24. Experience :	Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days
a) Total:	8	42	3	b) at the mine:	42	3		c) at activity (23d)	42	3		d) with Contractor			

25. Autopsy Performed:	If Yes, Location	26. Mine Telephone No.:
YES	Ft. Worth Medical Examiners Office	(972) 923-5800

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The truck driver parked his bulk tanker truck at a tanker top access platform, went to the top of the trailer, and opened the bulk hatches on the trailer in preparation to get loaded with cement. Another driver noticed the victim was not on top of the truck. The driver found the victim conscious inside the tank of the truck but could not get him out and called for help. A responder team arrived and found the victim unresponsive. He was transported to a hospital and pronounced dead. Apparently the victim dropped his asthma inhaler into the tank of the truck and then entered the tanker to get it but was unable to get out.

On, September 3, 2014, MSHA referred the accident to the Chargeability Review Committee. On February 2, 2015, the Chargeability Review Committee determined that this death should be charged to the mining industry. The autopsy report indicated that the manner of death was accidental and that the cause of death was asthma exacerbated by environmental dust exposure.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:
Transportation Equipment Corp	1978

30. District:	32. Field Office:	33. Event Number:
M5000 South Central	Dallas TX	6654748

34. Accident Investigator:	35. MSHA Person Notified:	Date	Time
Maria C. Rich	Bradley Peay	06/17/2014	09:26 A

36. Type of Report:	37. Name of Preparer and Date Prepared	Date
Amended	Mike Hancher MH	02/19/2015

38. Reason For Amendment: