PRESHIFT/ON-SHIFT REPORT
FOR
GENERAL MINE

GENWAL

Mine Name

ID Number

CRANDALL

SECTION / AREA

2MSHA03380

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-24-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7 AM/PM END 10 AM/PM Examiners Initials DG
TIME OF EXAMINATION START 700 AM/PM END 935 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DG	OK	none obs.	
Main North Haulage Seals	20.9	0	0	DG	OK	none obs.	
Main West Haulage Seals	20.9	0	0	LR/KK	OK	None obs.	
3rd North Haulage	20.9	0	0	LR/KK	OK	None obs.	
1st Right Haulage	20.9	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	LR/KK	OK	None obs.	
Chargers	20.9	0	0	LR	OK	None obs.	
Washdown Area	20.9	0	0	KK	OK	None obs.	
Storage Area	20.9	0	0	KK	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam.

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 4735
PRE-SHIFT/MINE EXAMINER CERT. # 4325
PRE-SHIFT/MINE EXAMINER CERT. # 7951
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATUR CERT. # 4735

2MSHA03381

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-25-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:50 AM/PM END 500 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 300 AM/PM END 535 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	21.0	0	0	KK	OK	none	
M. North Haulage seals	21.0	0	0	KK	OK	none	
M. West Haulage seals	20.9	0	0	KK/LR/RL	OK	None	
Storage area	20.9	0	0	KK	OK	none	
Washdown	20.9	0	0	KK	OK	none	
3rd North Haulage	20.9	0	0	KK	OK	none	
1st right Haulage	20.9	0	0	KK	OK	none	
Trans	20.9	0	0	KK/RL/LR	OK	None	
chargers	20.9	0	0	KK	OK	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7951
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURI CERT. # 8462

2MSHA03382

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-25-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:05 AM/PM END 12:58 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 12:19 AM/PM END 12:59 AM/PM Examiners Initials MC
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	none Observed	
Main North haulage Seals	20.9	0	0	MC	OK	none observed	
Main West haulage Seals	20.9	0	0	FM	OK	None observed	
3rd North haulage	20.9	0	0	FM	OK	None observed	
1st Right	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	MC/FM	OK	None observed	
Chargers	20.9	0	0	FM	OK	None observed	
Storage Areas	20.9	0	0	FM	OK	None observed	
Washdown	20.9	0	0	FM	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared reasonably Safe at time of exam

PRE-SHIFT/MINE EXAMINE Signature CERT. # 8297
PRE-SHIFT/MINE EXAMINE CERT. # 7335
PRE-SHIFT/MINE EXAMINE CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATUR Signature RT. # 8462

2MSHA03383

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-25-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 700 AM/PM END 830 AM/PM Examiners Initials DG
TIME OF EXAMINATION START 710 AM/PM END 955 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DG	OK	none obs.	
Main North Seals Haulage Area	20.9	0	0	DG	O/C	none obs.	
Main West Haulage Seals	20.9	0	0	LR/KK	OK	None obs.	
3rd North Haulage	20.9	0	0	LR/KK	OK	None obs.	
1st Right Haulage	20.9	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	LR/KK	OK	None obs.	
Chargers	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	KK	OK	None obs.	
Washdown	20.9	0	0	KK	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 4235
PRE-SHIFT/MINE EXAMINER ____ CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # 5954
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 4135

2MSHA03384

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-26-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 500 AM/PM Examiners Initials DG
TIME OF EXAMINATION START 300 AM/PM END 5.50 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DG	OK	none obs	
main North Seals Haulage Area	20.9	0	0	DG	OK	none obs.	
M. West Haulage seals	20.9	0	0	KK/LR	OK	none obs.	
3rd north	20.9	0	0	KK/LR	OK	none obs.	
1st right	20.9	0	0	KK	OK	none obs.	
Trans.	20.9	0	0	KK/LR	OK	none obs.	
Chargers	20.9	0	0	KK	OK	none obs.	
Storage area	20.9	0	0	KK/LR	OK	none obs	
Washdown	20.9	0	0	LR	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at axon

Signature

PRE-SHIFT/MINE EXAMINER _ CERT. # 4135
PRE-SHIFT/MINE EXAMINER _ CERT. # 7454
PRE-SHIFT/MINE EXAMINER _ CERT. # 4375
PRE-SHIFT/MINE EXAMINER _ CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 05892

2MSHA03385

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-26-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:55 AM/PM END 12:42 AM/PM Examiners Initials FM/MC
TIME OF EXAMINATION START 11:10 AM/PM END 1:04 AM/PM Examiners Initials BH
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	209	0	0	FM/MC	ok	None observed	
MAIN North haulage seals	209	0	0	FM/MC	ok	None observed	
MAIN West haulage seals	20.9	0	0	BH	ok	None Observed	
3rd North haulage	209	0	0	FM/BH/MC	ok	None observed	
1st Right	209	0	0	FM	ok	None observed	
Transformers	20.9	0	0	MC/BH	ok	None Observed	
Chargers	209	0	0	FM/MC	ok	None observed	
Storage Area	20.9	0	0	BH	ok	None Observed	
Wash down	20.9	0	0	BH	ok	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINE Signature CERT. # 8297
PRE-SHIFT/MINE EXAMINE CERT. # 7375
PRE-SHIFT/MINE EXAMINE CERT. # 8395
PRE-SHIFT/MINE EXAMINE CERT. #

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03386

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-26-07 SECTION/AREA General Mine / / /

TIME OF EXAMINATION START 7:40 AM/PM END 8:45 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:40 AM/PM END 9:30 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 8:15 AM/PM END 9:30 AM/PM Examiners Initials JD

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North SEALS haulage	20.9	0	0	SW	OK	none observed	
Main West SEALS haulage	20.9	0	0	~~SW~~ TC	OK	none obs.	
3rd North haulage	20.9	0	0	SW	OK	none observed	
1st Right.	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	~~SW~~ TC	OK	none obs.	
chargers	20.9	0	0	~~SW~~ JD	OK	none obs.	
Storage Area.	20.9	0	0	TC	OK	none obs.	
Washdown	20.9	0	0	TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appear Safe at time of exam.

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 9548
PRE-SHIFT/MINE EXAMINE CERT. # 9362
PRE-SHIFT/MINE EXAMINE CERT. # 9660
PRE-SHIFT/MINE EXAMINE CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03387

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-22-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 3:55 AM/PM END 5:05 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:42 AM/PM END 5:30 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 4:20 AM/PM END 5:25 AM/PM Examiners Initials LD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North Seals haulage	20.9	0	0	SW	OK	none observed	
Main West Seals haulage	20.9	0	0	~~SW~~ TC	OK	none obs.	
3rd North haulage	20.9	0	0	SW	OK	none observed	
1st Right	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	~~SW~~ LD	OK	none observed	
Chargers	20.9	0	0	~~SW~~ LD	OK	none observed	
Storage Area	20.9	0	0	TC	OK	none obs.	
Washdown	20.9	0	0	TC	OK	none obse	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe At Time Of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9562
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 03892

2MSHA03388

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION ~~1/19~~ 1/27/07 SECTION/AREA gen / / /

TIME OF EXAMINATION START 12:09 AM/PM END 12:38 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 12:00 AM/PM END 1:40 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Haulage, seals main north	20.9	0	0	BH	OK	None Observed	
Haulage, seals main west	21	0	0	LH/BH	OK	none obs	
3rd north Haulage seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	21	0	0	LH BH	OK	none obs	
Chargers	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	
Wash down	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 8703
PRE-SHIFT/MINE EXAMINER _____ CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 03892

2MSHA03389

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-27-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 7:45 AM/PM END 8:55 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:39 AM/PM END 9:30 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 8:15 AM/PM END 9:30 AM/PM Examiners Initials ZD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North SEALS haulage	20.9	0	0	SW	OK	none observed	
Main West SEALS haulage	20.9	0	0	TC/ZD SW	OK	none observed	
3rd North haulage	20.9	0	0	SW	OK	none observed	
1st Right	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	ZD SW	OK	none obs.	
Chargers	20.9	0	0	ZD SW	OK	none obs.	
Storage Area	20.9	0	0	TC	OK	none obs.	
Washdown	20.9	0	0	TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 9548
PRE-SHIFT/MINE EXAMINE CERT. # 9362
PRE-SHIFT/MINE EXAMINE CERT. # 9660
PRE-SHIFT/MINE EXAMINE CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03390

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-28-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 4:05 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:00 AM/PM END 4:20 AM/PM Examiners Initials TC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North Seals	20.9	0	0	SW	OK	none observed	
Main West Seals	20.9	0	0	~~SW~~ TC	OK	Deep water #1 Road xc's 63, 72, 74	working on [redacted]
3rd North Seals	20.9	0	0	SW	OK	none observed	
1st Right.	20.9	0	0	SW	OK	none observed	
transformers	20.9	0	0	~~SW~~ TC	OK	none obs.	
chargers	20.9	0	0	SW	OK	none observed.	
Storage Area	20.9	0	0	TC	OK	none obs.	
Wash down	20.9	0	0	TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS other than listed above All areas Reasonably safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 9548
PRE-SHIFT/MINE EXAMINER ____ CERT. # 9362
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03391

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-28-07 SECTION/AREA Genemines / /

TIME OF EXAMINATION START 1147 AM/PM END 1205 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 11:44 AM/PM END 1:10 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Obs	
main north Seals Haulage	20.9	0	0	BH	OK	None obs	
main west Seals Haulage	20.9	0	0	BH	OK	Deep water x-cut [illegible] ~~None Observed~~ BH	Done Ct 12807
3rd north Haulage	20.9	0	0	BH	OK	None Obs.	
1st Right	20.9	0	0	BH	OK	None Obs.	
Transformers	20.9	0	0	BH	OK	None Obs.	
chargers	20.9	0	0	BH	OK	None Obs.	
Storage Area	20.9	0	0	BH	OK	None Obs.	
washdown	20.9	0	0	BH	OK	None Obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Except as Noted ~~above~~ above
all area's reasonably Safe at Time of exam

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 9599
PRE-SHIFT/MINE EXAMINER _____ CERT. # 8703
PRE-SHIFT/MINE EXAMINER _____ CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature ERT. # 03892

2MSHA03392

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-28-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 7:50 AM/PM END 8:55 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:44 AM/PM END 9:23 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 8:15 AM/PM END 9:30 AM/PM Examiners Initials ZD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage seals	20.9	0	0	SW	OK	none observed	
Main West haulage seals	20.9	0	0	~~SW~~ TC ZD	OK	none obs.	
3rd North haulage	20.9	0	0	SW	OK	none observed	
1st Light	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	~~SW~~ ZD	OK	none observed	
Chargers	20.9	0	0	SW	OK	none observed	
Storage Area	20.9	0	0	TC	OK	none observed	
Washdown	20.9	0	0	TC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All AREAS APPEARED REASONABLY SAFE at time of EXAM

Signature

PRE-SHIFT/MINE EXAMINER _ CERT. # 9548
PRE-SHIFT/MINE EXAMINER _ CERT. # 9362
PRE-SHIFT/MINE EXAMINER _ CERT. # 9660
PRE-SHIFT/MINE EXAMINER _ CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 7485

2MSHA03393

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-29-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 3:55 AM/PM END 5:15 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 4:20 AM/PM END 5:30 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 4:46 AM/PM END 5:30 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North Seals haulage	20.9	0	0	SW	OK	none observed	
Main West Seals haulage	20.9	0	0	SW	OK	none observed	
3rd North haulage	20.9	0	0	SW	OK	none observed	
1st Right.	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW	OK	none obs	
Chargers	20.9	0	0	SW	OK	none observed	
Storage Area	20.9	0	0	TC	OK	none obs.	
Washdown	20.9	0	0	TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared Safe At Time of Exam

PRE-SHIFT/MINE EXAMINE Signature CERT. # 9548
PRE-SHIFT/MINE EXAMINE CERT. # 9660
PRE-SHIFT/MINE EXAMINE CERT. # 9362
PRE-SHIFT/MINE EXAMINE CERT. # _____

COUNTER SIGNATURE Signature CERT. # 9735

2MSHA03394

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-29-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:48 AM/PM END 1:04 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:09 AM/PM END 1:45 AM/PM Examiners Initials RR/KR
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/~~NO~~ CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	α	none observed	
MAIN North haulage seals	20.9	0	0	FM	α	None observed	
MAIN West haulage seals	20.9	0	0	FM/RR/KR	α	none obs.	
3rd North haulage	20.9	0	0	FM	α	none observed	
1st Right	20.9	0	0	FM	α	none observed	
Transformers	20.9	0	0	FM/RR/KR	α	none observed	
Chargers	20.9	0	0	FM	α	none observed	
Storage Area	20.9	0	0	FM	α	none observed	
Washdown	20.9	0	0	FM	α	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all area's appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINE Signature CERT. # 8297
PRE-SHIFT/MINE EXAMINE CERT. # 7954
PRE-SHIFT/MINE EXAMINE CERT. # 4373
PRE-SHIFT/MINE EXAMINE _____ CERT. # _____

COUNTER SIGNATUI Signature ERT. # 8462

2MSHA03395

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-29-07 SECTION/AREA Genming / /

TIME OF EXAMINATION START 7:08 AM/PM END 7:40 AM/PM Examiners Initials MC/KM
TIME OF EXAMINATION START 700 AM/PM END 845 AM/PM Examiners Initials DD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM
CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKing AREA	21	0	0	DD	ok	none obs.	
MAIN NORTH Haulage seals	21	0	0	DD	ok	none obs.	
MAIN WEST Haulage seals	20.9	0	0	MC/KM DD	OK	none observed	
3RD NORTH Haulage	21	0	0	DD	ok	none obs	
1ST Right Haulage	21	0	0	DD	ok	none obs.	
TRANSFORMERS	20.9	0	0	MC DD	OK	none observed	
CHARGERS	21	0	0	DD	ok	none obs.	
WASHDOWN	20.9	0	0	MC	OK	none observed	
STORAGE AREA	20.9	0	0	MC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 7375
PRE-SHIFT/MINE EXAMINE CERT. # 9379
PRE-SHIFT/MINE EXAMINE CERT. # 8058
PRE-SHIFT/MINE EXAMINE CERT. #

Signature

COUNTER SIGNATUF ERT. # 8462

2MSHA03396

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-30-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 530 AM/PM Examiners Initials DD/mc
TIME OF EXAMINATION START 4:00 AM/PM END 5:10 AM/PM Examiners Initials KM
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	KM	OK	none observed.	
Main north Haulage Seals	20.9	0	0	KM	OK	none observed	
Main West Haulage seals	20.9	0	0	DD/mc	ok	none obs	
3rd North Haulage	20.9	0	0	KM	OK	none observed	
1st Right Haulage	20.9	0	0	KM	OK	none observed	
Trans.	20.9	0	0	DD/mc KM	OK	none observed	
Chargers	20.9	0	0	KM	OK	none observed	
Washdown	20.9	0	0	DD	ok	none obs.	
Storage Area	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas apeared safe at the time of preshift

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 9329
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 4735

2MSHA03397

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-30-07 SECTION/AREA Ben Mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 1:01 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START 11:57 AM/PM END 1:05 AM/PM Examiners Initials FM
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	FM	ok	none obs	
Main North Haulage	20.9	0	0	FM	ok	none obs	
Main West Haulage shop	20.9	0	0	KK/LR/FM	ok	none obs	
3rd North Haulage	20.9	0	0	FM	ok	none obs	
1st right Haulage	20.9	0	0	FM	ok	none obs	
Trans.	20.9	0	0	KK/LR/FM	ok	none obs	
changes	20.9	0	0	FM	ok	none obs	
Washdown	20.9	0	0	LR	ok	none obs	
Storage area	20.9	0	0	LR	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas ok approved safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINEI ____ CERT. # 7954
PRE-SHIFT/MINE EXAMINEI ____ CERT. # 4375
PRE-SHIFT/MINE EXAMINEI ____ CERT. # 8797
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03398

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-30-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:04 AM/PM END 8:09 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 200 AM/PM END 930 AM/PM Examiners Initials DD Km
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
Main North Haulage Seal	20.9	0	0	mc	ok	none observed	
Main West Haulage Seal	20.9	0	0	mc DD Km	ok	none obs.	
BR North Haulage	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	mc DD	ok	none obs.	
Chargers	20.9	0	0	mc	ok	none observed	
Washdown	20.9	0	0	DD	ok	none obs.	
Storage Area	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 7375
PRE-SHIFT/MINE EXAMINER ____ CERT. # 8058
PRE-SHIFT/MINE EXAMINER ____ CERT. # 9379
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNAT CERT. # 8462

2MSHA03399

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-31-09 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 3:40 AM/PM Examiners Initials KM/mc
TIME OF EXAMINATION START 3:00 AM/PM END 4:04 AM/PM Examiners Initials DD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
Main North haulage seals	21	0	0	DD	ok	none obs.	
Main West haulage seals	20.9	0	0	KM mc DD	ok	none observed	
3rd North haulage	21	0	0	DD	ok	none obs.	
1st Right haulage	21	0	0	DD	ok	none obs.	
transformers	20.9	0	0	KM DD	ok	none observed	
chargers	21	0	0	DD	ok	none obs.	
washdown	20.9	0	0	mc	ok	none observed	
storage							

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 7325
PRE-SHIFT/MINE EXAMINER CERT. # ____
Signature

COUNTER SIGNATURE ERT. # 4155

2MSHA03400

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-31-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:50 AM/PM END 1:08 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:00 AM/PM END 1:30 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	209	0	0	FM	ok	none observed	
main north haulage seals	209	0	0	FM	ok	none observed	
Main West haulage seals	209	0	0	FM KK/LR	ok	none obs.	
3rd North haulage	209	0	0	FM	ok	none observed	
1st Right haulage	209	0	0	FM	ok	none observed	
Transformers	209	0	0	FM KK/LR	ok	none obs.	
Chargers	209	0	0	FM	ok	none observed	
Washdown	209	0	0	FM	ok	none observed	
storage area	209	0	0	FM	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # ____

Signature

COUNTER SIGNAT CERT. # 8462

2MSHA03401

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 1-31-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:50 AM/PM END 9:00 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 700 AM/PM END 915 AM/PM Examiners Initials DD MC
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	KM	OK	none observed	
Main North haulage seals &	20.9	0	0	KM	OK	none observed	
Main West haulage seals &	20.9	0	0	KM MC/DD	OK	none observed	
3rd North haulage	20.9	0	0	KM	OK	none observed	
1st right haulage	20.9	0	0	KM	OK	none observed	
transformers	20.9	0	0	KM MC	OK	none observed	
chargers	20.9	0	0	KM	OK	none observed	
wash down	20.9	0	0	MC	OK	none observed	
storage	20.9	0	0	MC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 937
PRE-SHIFT/MINE EXAMINE CERT. # 7375
PRE-SHIFT/MINE EXAMINE CERT. # 8058
PRE-SHIFT/MINE EXAMINE _____ CERT. # _____

Signature

COUNTER SIGNATU CERT. # 8462 2MSHA03402

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-1-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:30 AM/PM END 5:20 AM/PM Examiners Initials KM/DO
TIME OF EXAMINATION START 3:00 AM/PM END 4:12 AM/PM Examiners Initials mc
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
Main North seals haulage	20.9	0	0	mc	ok	none observed	
Main West seals haulage	20.9	0	0	mc	ok	none observed	
3rd north haulage	20.9	0	0	mc	ok	none observed	
1st right haulage	20.9	0	0	mc	ok	none observed	
transformers	20.9	0	0	mc	ok	none observed	
chargers	20.9	0	0	mc	ok	none observed	
wash down	21	0	0	DD	ok	none obs.	
storage	21	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINE ____ CERT. # 9329
PRE-SHIFT/MINE EXAMINE ____ CERT. # 7375
PRE-SHIFT/MINE EXAMINE ____ CERT. # 8053
PRE-SHIFT/MINE EXAMINE ____ CERT. # ____

Signature

COUNTER SIGNATUI ____ CERT. # 435

2MSHA03403

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-1-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 1:00 AM/PM Examiners Initials KR/LR
TIME OF EXAMINATION START 11:48 AM/PM END 1:14 AM/PM Examiners Initials FM
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	209	0	0	FM	OC	none observed	
Main North Haulage	209	0	0	FM	OC	none observed	
Main West Haulage	210	0	0	KR/LR/FM	OC	none observed	
3rd North Face	209	0	0	FM	OC	none observed	
1st Right	209	0	0	FM	OC	none observed	
Tubs	209	0	0	KR/LR/FM	OC	none observed	
Chargeup	209	0	0	FM	OC	none observed	
Workshop	209	0	0	FM	OC	none observed	
Storage area	209	0	0	FM	OC	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINI CERT. # 7954
PRE-SHIFT/MINE EXAMINI CERT. # 8297
PRE-SHIFT/MINE EXAMINI CERT. # 4325
PRE-SHIFT/MINE EXAMINI CERT. #

Signature

COUNTER SIGNATUF CERT. # 8462

2MSHA03404

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-1-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 6:20 AM/PM END 8:20 AM/PM Examiners Initials KM/MC
TIME OF EXAMINATION START 700 AM/PM END 805 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
Main North haulage seals	21	0	0	DD	ok	none obs.	
Main West haulage seals	20.9	0	0	KM MC DD	ok	none observed	
3rd north haulage	21	0	0	DD	ok	none obs.	
1st sight haulage	21	0	0	DD	ok	none obs.	
trans.	20.9	0	0	KM MC DD	ok	none observed	
Chargers	21	0	0	DD	ok	none obs.	
washdown	20.9	0	0	KM	ok	none observed	
storage area	20.9	0	0	KM	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

Signature

PRE-SHIFT/MINE EXAMINI CERT. # 9279
PRE-SHIFT/MINE EXAMINI CERT. # 7375
PRE-SHIFT/MINE EXAMINI CERT. # 8058
PRE-SHIFT/MINE EXAMINI _____ CERT. # _____

Signature

COUNTER SIGNAT CERT. # 8462

2MSHA03405

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-2-07 SECTION/AREA General mine / / /

TIME OF EXAMINATION START 3:50 AM/PM END 5:10 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 3:15 AM/PM END 6:00 AM/PM Examiners Initials DD mc
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	KM	ok	none observed	
Main North seals haulage	20.9	0	0	KM	ok	none observed	
Main West haulage seals	20.9	0	0	DD	ok	none observed	
3rd North haulage	20.9	0	0	KM	ok	none observed	
1st right haulage	20.9	0	0	KM	ok	none observed	
transformers	20.9	0	0	KM DD	ok	none observed	
chargers	20.9	0	0	KM	ok	none observed	
washdown	20.9	0	0	mc	ok	none observed	
storage area	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03406

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 22.07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:55 AM/PM END 12:43 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:00 AM/PM END 1:00 AM/PM Examiners Initials SW
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
Main North Haulage Seals	20.9	0	0	FM	OK	None observed	
Main West Haulage Seals	20.9	0	0	SW	OK	none observed	
3rd North haulage	20.9	0	0	SW	OK	none observed	
1st Right	20.9	0	0	SW	OK	none observed	
transformers	20.9	0	0	SW	OK	none observed	
Chargers	20.9	0	0	SW	OK	none observed	
Washdown	20.9	0	0	SW	OK	none observed	
storage Area	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe to travel and work at time of Pre-shift

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 8297
PRE-SHIFT/MINE EXAMINE CERT. # 9548
PRE-SHIFT/MINE EXAMINE CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03407

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2/2/07 SECTION/AREA gen / / / /

TIME OF EXAMINATION START 7:00 AM/PM END 7:17 AM/PM Examiners Initials LH
TIME OF EXAMINATION START 7:44 AM/PM END 9:15 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Obs.	
Haulage, Seals main north	20.9	0	0	BH	OK	None Obs.	
Haulage, seals main west	21	0	0	LH/BH	OK	none obs	
3rd north Haulage Seals	20.9	0	0	BH	OK	None Obs.	
1ST Right Haulage	20.9	0	0	BH	OK	None Obs.	
Transformers	21	0	0	LH/BH	OK	none obs	
Chargers	20.9	0	0	BH	OK	None Obs	
wash down	20.9	0	0	BH	OK	None obs.	
storage	20.9	0	0	BH	OK	None Obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 8703
PRE-SHIFT/MINE EXAMINER CERT. # [illegible]
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 03892

2MSHA03408

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-3-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 346 AM/PM END 356 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 3:45 AM/PM END 5:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Haulage Seals main north	20.9	0	0	BH	OK	None Observed	
Haulage Seals main west	20.9	0	0	BH/BP	OK	none obs	
3rd north Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haul	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/BP	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
wash down	20.9	0	0	BH	OK	None Observed	
Stoage	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9599
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03409

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-3-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 12:00 AM/PM END 12:40 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 11:00 AM/PM END 12:35 AM/PM Examiners Initials TC
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	TC/JG	OK	none obs.	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	TC/JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	TC/JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE	20.9	0	0	TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All AREAS Seemed Reasonably Safe AT Time of Exam

Signature

PRE-SHIFT/MINE EXAMIN CERT. # 7485
PRE-SHIFT/MINE EXAMIN CERT. # 9362
PRE-SHIFT/MINE EXAMIN CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATUI CERT. # 7485

2MSHA03410

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-3-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:47 AM/PM END 9:33 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 6:05 AM/PM END 6:25 AM/PM Examiners Initials BP
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH/BP	OK	None Observed	
3rd North Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformer	20.9	0	0	BH/BP	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # 9599
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE ____ CERT. # 03892

2MSHA03411

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-4-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:52 AM/PM END 5:24 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 3:40 AM/PM END 4:02 AM/PM Examiners Initials LH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None obs	
Main North Haulage Seals	20.9	0	0	BH	OK	None obs	
Main West haulage Seals	20.9	0	0	BH/LH	OK	None obs	
3rd North Haulage Seals	20.9	0	0	BH	OK	none obs	
1st Right Haulage	20.9	0	0	BH	OK	none obs	
Trans	20.9	0	0	BH/LH	OK	none obs	
Chargers	20.9	0	0	BH	OK	none obs	
Wash down	20.9	0	0	BH	OK	none obs	
Storage Area	20.9	0	0	BH	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe for work & Travel.

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 8703
PRE-SHIFT/MINE EXAMINER CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03412

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-4-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 11:50 AM/PM END 12:55 AM/PM Examiners Initials SW
TIME OF EXAMINATION START [illegible] AM/PM END [illegible] AM/PM Examiners Initials [illegible]
TIME OF EXAMINATION START 11:39 AM/PM END 1:30 AM/PM Examiners Initials K

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North Seals haulage	20.9	0	0	SW	OK	none observed	
Main West Seals haulage	20.9	0	0	~~SW~~ TC	OK	none obs.	
3rd North Seals haulage	20.9	0	0	SW	OK	none observed	
1st Right	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	~~SW~~ TC	OK	none obs.	
chargers	20.9	0	0	SW	OK	none observed	
washdown	20.9	0	0	TC	OK	none obs.	
Storage Area.	20.9	0	0	TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Scanned Reasonably Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINE _____ CERT. # 9548
PRE-SHIFT/MINE EXAMINE _____ CERT. # 9362
PRE-SHIFT/MINE EXAMINE _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03413

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2 4 07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 750 AM/PM END 9 AM/PM Examiners Initials GA
TIME OF EXAMINATION START 7:00 AM/PM END 9:35 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	GA	OK	None observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH	OK	None Observed	
3rd We Haulage Seals	20.9	0	0	GA	OK	None observed	
1st RH Haulage	20.9	0	0	GA	OK	None observed	
Transformers	20.9	0	0	GA/BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Areas	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 03892
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 03892

2MSHA03414

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2507 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 357 AM/PM END 410 AM/PM Examiners Initials CA
TIME OF EXAMINATION START 500 AM/PM END 510 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	CA	OK	None observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None	
Main West Haulage Seals	20.9	0	0	BH	OK	None	
3rd North Haulage Seals	20.9	0	0	BH	OK	None	
1st Right Haulage	20.9	0	0	BH	OK	None	
Trans	20.9	0	0	BH	OK	None	
Chargers	20.9	0	0	BH	OK	None	
Washdown	20.9	0	0	BH	OK	None	
Storage Area	20.9	0	0	BH	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8325
PRE-SHIFT/MINE EXAMINER CERT. # 03892
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03415

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 25-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 12:00 AM/PM END 1:17 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:40 AM/PM END 1:27 AM/PM Examiners Initials TC
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
MAIN North haulage seals	20.9	0	0	FM	OK	none observed	
MAIN West haulage seals	20.9	0	0	TC	ok	none obs.	
3rd North haulage	20.9	0	0	FM	OK	none observed	
1st Right haulage	20.9	0	0	FM	OK	none observed	
Trans.	20.9	0	0	FM/TC	ok	none obs.	
Chargers	20.9	0	0	FM	OK	none observed	
wash down	20.9	0	0	TC	ok	none obs.	
Storage Area	20.9	0	0	TC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All AREAS Seemed Reasonably Safe AT Time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03416

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-5-07 SECTION/AREA ____/____/____/____

TIME OF EXAMINATION START 7:48 AM/PM END 9:26 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 7:00 AM/PM END 7:54 AM/PM Examiners Initials LH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH/LH	OK	None Observed	
3rd North Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/LH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at Time of exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # 8703
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE ____ CERT. # 03892

2MSHA03417

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-6-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:42 AM/PM END 5:15 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 3:00 AM/PM END 3:50 AM/PM Examiners Initials LH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH/LH	OK	None Observed	
3rd North Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 8703
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATUR CERT. # 4735

2MSHA03418

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2.6.07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 12:17 AM/PM END 1:30 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:15 AM/PM END 1:50 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	none observed	
Main North haulage seals	20.9	0	0	FM	ok	none observed	
Main West haulage seals	20.9	0	0	FM/KK/LR	ok	None observed	
3rd North haulage	20.9	0	0	FM	ok	none observed	
1st Right haulage	20.9	0	0	FM	ok	none observed	
transformers	20.9	0	0	FM/KK/LR	ok	None observed	
Chargers	20.9	0	0	FM	ok	none observed	
washdown	20.9	0	0	FM	ok	none observed	
storage area	20.9	0	0	FM	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATUR CERT. #

2MSHA03419

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-6-07 SECTION/AREA Gen Mines

TIME OF EXAMINATION START 7:06 AM/PM END 8:04 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 700 AM/PM END 739 AM/PM Examiners Initials DD KM
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
main North Haulage seals	20.9	0	0	mc	ok	none observed	
main west Haulage seals	20.9	0	0	mc DD/KM	OK	none observed	
3rd North Haulage	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	mc	ok	none observed	
chargers	20.9	0	0	mc	ok	none observed	
wash down	20.9	0	0	DD	OK	none observed	
storage Area	20.9	0	0	DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 2325
PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATUR CERT. # 8462

2MSHA03420

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-7-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 401 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 3:00 AM/PM END 5:00 AM/PM Examiners Initials Km/mc
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
main north Haulage seals	20.9	0	0	DD	ok	none obs.	
main west Haulage seals	20.9	0	0	DD/mc Km	ok	x-cut 131 & 135 need Timber set	set timbers in 131 & 135 PC 2-7-06
3rd North Haulage	20.9	0	0	DD	ok	none obs	
1st Right Haulage	20.9	0	0	DD	ok	none obs.	
Transformers	20.9	0	0	DD	ok	none obs	
chargers	20.9	0	0	DD/mc	ok	none observed	
washdown	20.9	0	0	mc	ok	none observed	
storage area	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

Signature

PRE-SHIFT/MINE EXAMINER _ CERT. # 8058
PRE-SHIFT/MINE EXAMINER _ CERT. # 9379
PRE-SHIFT/MINE EXAMINER _ CERT. # 7325
PRE-SHIFT/MINE EXAMINER _ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 4935

2MSHA03421

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2.7.07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:49 AM/PM END 1:12 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:20 AM/PM END 1:50 AM/PM Examiners Initials [illegible]
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	209	0	0	FM	OK	none observed	
MAIN North haulage seals	209	0	0	FM	OK	none observed	
MAIN West haulage seals	20.	0	0	FM/LR/KR	OK	none obs.	
3rd North haulage	209	0	0	FM	OK	none observed	
1st Right	209	0	0	FM	OK	none observed	
transformers	209	0	0	FM/KK/KR	OK	none obs.	
Chargers	209	0	0	FM/KK/KR	OK	none obs.	
Washdown	209	0	0	FM	OK	none observed	
Storage Area	209	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all area's appeared safe at time of EXAM

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXA CERT. #

Signature

COUNTER SIGNATUR CERT. # 8462

2MSHA03422

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-7-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:50 AM/PM END 9:00 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 700 AM/PM END 920 AM/PM Examiners Initials DD mc
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	KM	OK	none observed	
Main North haulage seals	20.9	0	0	KM	OK	none observed	
Main West haulage seals	20.9	0	0	KM DD mc	ok	none obs.	
3rd north haulage	20.9	0	0	KM	OK	none observed	
1st sight	20.9	0	0	KM	OK	none observed	
transformers	20.9	0	0	KM DD mc	OK	none observed	
chargers	20.9	0	0	KM mc	OK	See Below ~~none observed~~	sent men to get dust Done 2-8-07
wash down	20.9	0	0	mc	OK	none observed	
storage area	20.9	0	0	mc	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS charger at xcut 89 main west needs 5 bags dust other Areas Appeared safe

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 7385
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATU CERT. # 8462

2MSHA03423

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-8-07 SECTION/AREA Ce mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 4:05 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 3:00 AM/PM END 4:40 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 300 AM/PM END 530 AM/PM Examiners Initials DD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	none observed	
Main North Haulage Seals	20.9	0	0	MC	OK	none observed	
Main West Haulage Seals	20.9	0	0	MC KM DD	OK	none observed	
3rd North Haulage	20.9	0	0	MC	OK	none observed	
1st Right Haulage	20.9	0	0	MC	OK	none observed	
Transformers	20.9	0	0	MC KM DD	OK	none observed	
Chargers	20.9	0	0	MC/DD	OK	none observed	
Washdown	20.9	0	0	DD	OK	none obs.	
Storage Area	20.9	0	0	DD	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # _____
Signature

COUNTER SIGNATURE CERT. # 4135

2MSHA03424

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-8-07 SECTION/AREA Gen. Mine / /

TIME OF EXAMINATION START 11:00 AM/PM END 200 AM/PM Examiners Initials LR
TIME OF EXAMINATION START 11:00 AM/PM END 200 AM/PM Examiners Initials KK/FM
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs.	
Main North Haulage Seals	20.9	0	0	LR	OK	None obs.	
Main West Haulage Seals	20.9	0	0	LR/FM/KK	OK	None observed	
3rd North Haulage	20.9	0	0	LR	OK	None obs.	
1st Right Haulage	20.9	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	LR/FM/KK	OK	None observed	
Chargers	20.9	0	0	LR/KK	OK	None observed	
Washdown	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam.

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATUR ERT. # 8462

2MSHA03425

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-8-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:25 AM/PM END 9:15 AM/PM Examiners Initials MC/Km
TIME OF EXAMINATION START 700 AM/PM END 800 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	21	0	0	DD	ok	none obs.	
MAIN WEST HAULAGE SEALS	20.9	0	0	MC/Km DD	OK	NONE OBSERVED	
MAIN NORTH HAULAGE SEALS	21	0	0	DD	ok	none obs.	
3RD NORTH HAULAGE	21	0	0	DD	ok	none obs.	
1ST RIGHT HAULAGE	21	0	0	DD	ok	none obs.	
TRANSFORMERS	20.9	0	0	Km DD	OK	NONE OBSERVED	
CHARGERS	21	0	0	Km DD	ok	none obs.	
WASH DOWN	20.9	0	0	Km	OK	NONE OBSERVED	
STOPPAGE	20.9	0	0	Km	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 2375
PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03426

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-9-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:30 AM/PM END 5:15 AM/PM Examiners Initials MC/DD
TIME OF EXAMINATION START 3:50 AM/PM END 5:25 AM/PM Examiners Initials KM
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	KM	ok	none observed	
Main North Haulage Seals	20.9	0	0	KM	OK	none observed	
Main West Haulage Seals	20.9	0	0	MC/DD KM	OK	none observed	
3rd North Haulage	20.9	0	0	KM	OK	none observed	
1st Right Haulage	20.9	0	0	KM	OK	none observed	
Transformers	20.9	0	0	MC KM	OK	none observed	
Chargers	20.9	0	0	MC KM	OK	none observed	
Washdown	20.9	0	0	MC	OK	none observed	
Storage Area	20.9	0	0	MC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 9329
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATU CERT. # 4734

2MSHA03427

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2.9.07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:53 AM/PM END 1:15 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:00 AM/PM END 11:45 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	none observed	
Main North haulage seals	20.9	0	0	FM	ok	none observed	
Main West haulage seals	20.9	0	0	FM/KK/LR	ok	none obs	
3rd North haulage	20.9	0	0	FM	ok	none observed	
1st Right	20.9	0	0	FM	ok	none observed	
Transformers	20.9	0	0	FM/KK/LR	ok	none obs.	
Chargers	20.9	0	0	FM/KK/LR	ok	none obs.	
Storage Area	20.9	0	0	FM	ok	none observed	
Washdown	20.9	0	0	FM	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 1954
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03428

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-9-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:25 AM/PM END 9:05 AM/PM Examiners Initials KM DD
TIME OF EXAMINATION START 7:00 AM/PM END 7:58 AM/PM Examiners Initials MC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	MC	OK	None observed	
Main North haulage seals	20.9	0	0	MC	OK	None observed	
Main West haulage seals	20.9	0	0	KM DD MC	OK	none observed	
3rd North haulage	20.9	0	0	MC	OK	None observed	
1st Right haulage	20.9	0	0	MC	OK	None observed	
transformers	20.9	0	0	KM DD MC	OK	none observed	
chargers	20.9	0	0	DD MC	OK	None observed	
storage area	20.9	0	0	DD KM	OK	none observed	
washdown	20.9	0	0	KM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe At Time of Preshift

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 2325
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE ____ CERT. # 2462

2MSHA03429

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-10-07 SECTION/AREA General mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 5:15 AM/PM Examiners Initials KM MC
TIME OF EXAMINATION START 3:00 AM/PM END 4:01 AM/PM Examiners Initials DD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
Main North haulage seals	21	0	0	DD	ok	none obs.	
Main West haulage seals	20.9	0	0	KM MC DD	ok	none observed	
3rd North haulage	21	0	0	DD	ok	none obs.	
1st right	21	0	0	DD	ok	none obs.	
trans.	20.9	0	0	KM MC DD	ok	none observed	
chargers	20.9	0	0	MC DD	ok	none obs.	
storage area	20.9	0	0	MC	OK	none observed	
washdown	20.9	0	0	MC	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9375
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # ____

COUNTER SIGNATURE Signature CERT. # 8816

2MSHA03430

PRE-SHIFT GENERAL MINE

ATE OF EXAMINATION 2-10-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 1100 AM/PM END 140 AM/PM Examiners Initials KK/RL
ME OF EXAMINATION START 12:20 AM/PM END 1:40 AM/PM Examiners Initials AB
..ME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

ALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	AB	OK	nonoob	
Main No Haulage Seals	21	0	0	AB	OK	nonoob	
Main West Haulage Seals	21	0	0	KK/RL	OK	none observed	
3rd North Haulage	21	0	0	AB	OK	nonoob	
1st Right	21	0	0	AB	OK	nonoob	
Transformers	21	0	0	AB	OK	nonoob	
Chargers	21	0	0	RL/AB	OK	none observed	
Storage Area	21	0	0	AB	OK	nonoob	
Washdown	21	0	0	AB	OK	nonoob	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 7959
PRE-SHIFT/MINE EXAMINER CERT. # 8916
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATUI CERT. # 8462

2MSHA03431

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-10-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 8:00 AM/PM END 9:10 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 7:25 AM/PM END 9:01 AM/PM Examiners Initials MC/DD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	KM	OK	none observed	
Main North haulage seals	20.9	0	0	KM	ok	none observed	
Main West haulage seals	20.9	0	0	KM MC/DD	OK	none observed	
3rd north haulage	20.9	0	0	KM	ok	none observed	
1st right haulage	20.9	0	0	KM	ok	none observed	
Trans.	20.9	0	0	KM MC DD	OK	none observed	
chargers	20.9	0	0	KM MC	OK	none observed	
wash down	20.9	0	0	MC	ok	none observed	
storage	20.9	0	0	MC	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe At Time of prashift

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 9329
PRE-SHIFT/MINE EXAMINE CERT. # 22257
PRE-SHIFT/MINE EXAMINE CERT. # 8058
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATUR ____ CERT. # 2462

2MSHA03432

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-11-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 3:09 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 3:50 AM/PM END 5:45 AM/PM Examiners Initials KM/MC
TIME OF EXAMINATION START 330 AM/PM END 540 AM/PM Examiners Initials DD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	None observed	
Main North Haulage Seals	20.9	0	0	mc	OK	None observed	
Main West Haulage Seals	20.9	0	0	mc KM DD	OK	none observed	
3rd North Haulage	20.9	0	0	MC	OK	None observed	
1st Right Haulage	20.9	0	0	MC	OK	None observed	
Transformers	20.9	0	0	mc KM DD	OK	None observed	
Chargers	20.9	0	0	mc DD	OK	None observed	
Washdown	20.9	0	0	DD	OK	none observed	
Storage Area	20.9	0	0	KM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas released safe at the time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 9319
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATUR CERT. # 7462

2MSHA03433

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-11-02 SECTION/AREA Gen Mine / / / /

TIME OF EXAMINATION START 1130 AM/PM END 130 AM/PM Examiners Initials RL
TIME OF EXAMINATION START 1100 AM/PM END 155 AM/PM Examiners Initials RL/LR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	RL	OK	none observed	
Main North Haulage	21	0	0	RL	OK	none "	
Main West Haulage	20.9	0	0	RL/RN/LR	OK	none "	
3rd North Haulage	20.9	0	0	RL	OK	none observed	
1st Right Haulage	20.9	0	0	RL	OK	none "	
Transformers	20.9	0	0	RL/RN/LR	OK	none "	
Chargers	20.9	0	0	RL/RN/LR	OK	none "	
Wash down	20.9	0	0	RL	OK	none observed	
Storage	20.9	0	0	RL	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas examined Safe at time of Exam.

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 6406
PRE-SHIFT/MINE EXAMINE CERT. # 4375
PRE-SHIFT/MINE EXAMINE CERT. # 7959
PRE-SHIFT/MINE EXAMINER IV CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03434

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-11-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 700 AM/PM END 800 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 7:00 AM/PM END 930 AM/PM Examiners Initials KM/MC
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
North Haulage mains seals	21	0	0	DD	ok	none obs.	
main Haulage west seals	21	0	0	DD/Km/MC	ok	none observed	
3rd North Haulage	21	0	0	DD	ok	none obs.	
1st Right Haulage	21	0	0	DD	ok	none obs.	
Trans	21	0	0	DD MC Km	ok	none observed	
chargers	21	0	0	DD Km	ok	none observed	
washdown	20.9	0	0	Km	ok	none observed	
Storage	20.9	0	0	Km	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at Time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03435

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-12-07 SECTION/AREA General mine / / /

TIME OF EXAMINATION START 4:05 AM/PM END 5:15 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 300 AM/PM END 525 AM/PM Examiners Initials DD MC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	KM	OK	none observed	
Main North haulage & seals	20.9	0	0	KM	OK	none observed	
Main West haulage seals	20.9	0	0	KM DD	OK	none observed	
3rd north haulage	20.9	0	0	KM	OK	none observed	
1st right haulage	20.9	0	0	KM	OK	none observed	
Trans.	20.9	0	0	KM DD	OK	none observed	
Chargers	20.9	0	0	KM MC	OK	none observed	
washdown	20.9	0	0	MC	OK	none observed	
storage	20.9	0	0	MC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe At Time of prevshift

Signature

PRE-SHIFT/MINE EXAMINEI CERT. # 9379
PRE-SHIFT/MINE EXAMINEI CERT. # 8058
PRE-SHIFT/MINE EXAMINEI ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE ____ CERT. # 03892

2MSHA03436

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2.12.07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 12:00 AM/PM END 1:08 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:40 AM/PM END 1:59 AM/PM Examiners Initials BH/tc
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	none observed	
Main North haulage Seals	20.9	0	0	FM	ok	none observed	
Main West haulage Seals	20.9	0	0	BH/tc	ok	None observed	
3rd North haulage	20.9	0	0	FM	ok	none observed	
1st Right haulage	20.9	0	0	FM	ok	none observed	
transformers	20.9	0	0	FM BH/tc	ok	None observed	
Chargers	20.9	0	0	FM BH	ok	None observed	
wash down	20.9	0	0	BH	ok	None observed	
storage Area	20.9	0	0	BH	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 8397
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03437

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-12-06 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 7:50 AM/PM END 9:10 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 730 AM/PM END 940 AM/PM Examiners Initials dg
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North 2CAIS haulage	20.9	0	0	SW	OK	none observed	
Main West 3CAIS haulage	20.9	0	0	~~SW~~ dg	OK	None observed	
3rd North haulage	20.9	0	0	SW	OK	none observed	
1st Right haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	~~SW~~ dg	OK	None observed	
Chargers	20.9	0	0	SW	OK	none observed	
Wash down	20.9	0	0	dg	OK	None observed	
Storage	20.9	0	0	dg	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03438

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 21307 SECTION/AREA Gen / Mine / Crandall /

TIME OF EXAMINATION START 3:15 AM/PM END 5:30 AM/PM Examiners Initials [illegible]
TIME OF EXAMINATION START 3:00 AM/PM END 5:15 AM/PM Examiners Initials [illegible]
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	dg	ok	none observed	
Main North Seals Haulage	20.9	0	0	ID dg	ok	none observed	
Main west Haulage	20.9	0	0	ID	ok	none observed	
3rd No Haulage	20.9	0	0	ID	ok	none observed	
1st Right Haulage	20.9	0	0	ID	ok	none observed	
Transformers	20.9	0	0	ID dg	ok	none observed	
Chargers	20.9	0	0	ID	ok	none observed	
Washdown	20.9	0	0	ID	ok	none observed	
Storage	20.9	0	0	ID	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas apperd Saade at time of exam

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 6622
PRE-SHIFT/MINE EXAMINER _____ CERT. # 9660
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 7272

2MSHA03439

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-13-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:53 AM/PM END 12:45 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:10 AM/PM END 1:05 AM/PM Examiners Initials BH
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
MAIN North haulage seals	20.9	0	0	FM	OK	none observed	
MAIN West haulage seals	20.9	0	0	BH	OK	None Observed	
3rd North haulage	20.9	0	0	BH	OK	None Observed	
1st Right haulage	20.9	0	0	BH	OK	None Observed	
TRANSformers	20.9	0	0	FM/BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 8325
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 9279

2MSHA03440

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-13-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 8:05 AM/PM END 9:00 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 7:15 AM/PM END 9:45 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:10 AM/PM END 9 AM/PM Examiners Initials dg

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	21.0	0	0	SW/JG	OK	None observed	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	21.0	0	0	SW/JG	OK	None observed	
CHARGERS	21.0	0	0	dg/JG	OK	none observed	
WASHDOWN	21.0	0	0	SW	OK	none observed	
UNDERGROUND STORAGE	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe to travel at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03441

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-14-07 SECTION/AREA GENERAL MINE /

TIME OF EXAMINATION START 3:02 AM/PM END 3:55 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 3:00 AM/PM END 5:49 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:20 AM/PM END 5:45 AM/PM Examiners Initials dg

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE SEALS	21.0	0	0	SW/JG	OK	none observed	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	21.0	0	0	SW/JG	OK	none observed	
CHARGERS	21.0	0	0	dg/JG	OK	none observed	
WASHDOWN	20.9	0	0	dg	ok	none observed	
STORAGE	20.9	0	0	dg	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 7485
PRE-SHIFT/MINE EXAMINE CERT. # 9548
PRE-SHIFT/MINE EXAMINE CERT. # 6622
PRE-SHIFT/MINE EXAMINE CERT. # _____

Signature

COUNTER SIGNATU CERT. # 03892

2MSHA03442

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-14-07 SECTION/AREA Gen Mine / / .

TIME OF EXAMINATION START 12:00 AM/PM END 12:57 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:05 AM/PM END 1:15 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	FM	OK	None observed	
MAIN North Haulage seals	20.9	0	0	FM	OK	None observed	
MAIN West haulage seals	20.9	0	0	BH	OK	None Observed	
3rd North haulage	20.9	0	0	BH	OK	None Observed	
1st Right haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	FM/BH	OK	None Observed	
chargers	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
storage area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03443

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-14-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 7:45 AM/PM END 9:10 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:30 AM/PM END 9:45 AM/PM Examiners Initials dg
TIME OF EXAMINATION START 8:15 AM/PM END 9:40 AM/PM Examiners Initials SW

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North SLATS haulage	21.0	0	0	SW	OK	none observed	
Main West SLATS haulage	21.0	0	0	~~SW~~ dg	OK	None observed	
3rd North haulage SLATS	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	SW	OK	none observed	
Chargers	21.0	0	0	~~SW~~ dg	OK	None observed	
washdown	20.9	0	0	dg	OK	None observed	
storage	21.0	0	0	SW	OK	none observed.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03444

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-15-08 SECTION/AREA General / Mine. / / /

TIME OF EXAMINATION START 3:45 AM/PM END 5:20 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:35 AM/PM END 5:40 AM/PM Examiners Initials dy
TIME OF EXAMINATION START 3:00 AM/PM END 5:35 AM/PM Examiners Initials JB

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North ~~haulage~~ seals	20.9	0	0	dy/SW	OK	none observed	
Main West ~~haulage~~ seals	21.0	0	0	SW JD	OK	none observed	
3rd North haulage seals	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	SW	OK	none observed	
chargers	21.0	0	0	~~SW~~ dy	OK	None observed	
washdown	20.9	0	0	dy	OK	None observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas examined appear safe at time of examination

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 63892

2MSHA03445

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-15-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:47 AM/PM END 1:25 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:40 AM/PM END 12:40 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 11:30 AM/PM END 12:30 AM/PM Examiners Initials JC

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
Main North haulage Seals	20.9	0	0	FM	OK	none observed	
Main West haulage Seals	20.9	0	0	FM/BH/JC	OK	None Observed	
3rd North haulage	20.9	0	0	FM	OK	none observed	
1st Right haulage	20.9	0	0	FM	OK	none observed	
Transformers	20.9	0	0	FM/BH/JC	OK	None Observed	
Chargers	20.9	0	0	FM	OK	none observed	
Wash down	20.9	0	0	FM	OK	none observed	
Storage Area	20.9	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03446

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-15-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 8:06 AM/PM END 9:05 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 7:25 AM/PM END 9:45 AM/PM Examiners Initials
TIME OF EXAMINATION START 8:15 AM/PM END 9:40 AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	dy/JD JG	ok	None observed	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	dy/JG	ok	None observed	
CHARGERS	20.9	0	0	JD/JG	ok	none observed	
WASHDOWN	20.9	0	0	dy	ok	None observed	
STORAGE	20.9	0	0	dy	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas examined appear safe at time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 1485
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 1485

2MSHA03447

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-16-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 4:00 AM/PM END 5:15 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:40 AM/PM END 5:35 AM/PM Examiners Initials cg
TIME OF EXAMINATION START 3:00 AM/PM END 5:35 AM/PM Examiners Initials LD

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area.	21.0	0	0	SW	OK	none observed	
Main North haulage seals	21.0	0	0	SW	OK	none observed	
Main West haulage seals	21.0	0	0	~~SW~~ cg	OK	none observed	
3rd north haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	SW	OK	none observed	
chargers	21.0	0	0	~~SW~~ cg	OK	none observed	
washdown	20.9	0	0	LD	OK	none observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 9600
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03448

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-16-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:07 AM/PM END 12:40 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 11:54 AM/PM END 12:45 AM/PM Examiners Initials Fm
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	Fm	ok	none observed	
MAIN NORTH HAULAGE SEALS	20.9	0	0	Fm	ok	none observed	
MAIN WEST HAULAGE SEALS	20.9	0	0	mc	ok	none observed	
3RD NORTH HAULAGE	20.9	0	0	Fm	ok	none observed	
1ST RIGHT HAULAGE	20.9	0	0	Fm	ok	none observed	
TRANSFORMERS	20.9	0	0	mc/Fm	ok	none observed	
CHARGERS	20.9	0	0	mc/Fm	ok	none observed	
WASHDOWN	20.9	0	0	mc	ok	none observed	
STORAGE AREA	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 3325
PRE-SHIFT/MINE EXAMINER ____ CERT. # 8297
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATUR CERT. # 8462

2MSHA03449

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-16-07 SECTION/AREA Gentlemen / / /

TIME OF EXAMINATION START 801 AM/PM END 915 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 710 AM/PM END 945 AM/PM Examiners Initials KK/RL
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	ok	none obs.	
Main North Haulage	20.9	0	0	KK	ok	none obs.	
Main West Haulage	20.9	0	0	KK/RL	ok	none obs.	
3rd North	20.9	0	0	KK	ok	none obs.	
1st right	20.9	0	0	KK	ok	none obs	
Trans.	20.9	0	0	KK/RL	ok	None obs.	
chargers	20.9	0	0	KK	ok	none obs	
Washdown	20.9	0	0	KK	ok	none obs	
storage area	20.9	0	0	KK	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 7954
PRE-SHIFT/MINE EXAMINER ____ CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # 6401
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATU ____ CERT. # 4735

2MSHA03450

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-17-07 SECTION/AREA Gunnison / / /

TIME OF EXAMINATION START 3:44 AM/PM END 5:10 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 300 AM/PM END 535 AM/PM Examiners Initials LR/RL
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	ok	none	
M. North Haulage seals	20.9	0	0	KK	ok	none	
MW. Haulage seals	20.9	0	0	KK/LR/RL	/	None	
3rd north	20.9	0	0	KK	ok	none	
1st reight	20.9	0	0	KK	ok	none	
Trans.	20.9	0	0	KK/LR/RL	ok	None	
chargers	20.9	0	0	KK	ok	none	
washdown	20.9	0	0	KK	ok	none	
storage area	20.9	0	0	KK	ok	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03451

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-17-07 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 1100 AM/PM END 1210 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 11:30 AM/PM END 1:15 AM/PM Examiners Initials KM
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	DD	ok	none obs.	
main north Haulage seals	20.9	0	0	DD	ok	none obs.	
main west Haulage seals	20.9	0	0	DD MC RM	OK	none observed	
3rd north	20.9	0	0	DD	ok	none obs.	
1st Right	20.9	0	0	DD	ok	none obs.	
Trans.	20.9	0	0	DD mc	OK	none observed	
chargers	20.9	0	0	DD mc	OK	none observed	
wash down	20.9	0	0	mc	OK	none observed	
Storage area	20.9	0	0	mc	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe At time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 7325
PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 8462

2MSHA03452

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-17-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 740 AM/PM END 850 AM/PM Examiners Initials RC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	RL	ok	none observed	
Main N. Haulage Tail	20.9	0	0	RL	ok	none "	
Main West Haulage Tail	20.9	0	0	RL/RL	ok	none	
3rd North	20.9	0	0	RL	ok	none observed	
1st Right	20.9	0	0	RL	ok	none observed	
Transformer	20.9	0	0	RL/LR	ok	none	
Chargers	20.9	0	0	RL/LR	ok	none	
Washdown	20.9	0	0	RL	ok	none	
Storage area	20.9	0	0	RL	ok	none.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift.

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # ____

Signature

COUNTER SIGNATUR ____ CERT. # 4735

2MSHA03453

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-18-07 SECTION/AREA Gen-Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 505 AM/PM Examiners Initials LR
TIME OF EXAMINATION START 300 AM/PM END ____ AM/PM Examiners Initials RL/KK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs.	
Main North Haulage & Seals	20.9	0	0	LR	OK	None obs.	
Main West Haulage & Seals	20.9	0	0	LR/RL/KK	OK	none	
3rd North	20.9	0	0	LR	OK	None obs.	
1st Right	20.9	0	0	LR	OK	None obs.	
Trans.	20.9	0	0	LR/RL/KK	OK	none	
Chargers	20.9	0	0	LR	OK	None obs.	
Washdown	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	LR	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared Safe at time of Exam.

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # 6401
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE ____ CERT. # ____

2MSHA03454

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-18-07 SECTION/AREA General mine / / /

TIME OF EXAMINATION START 11:53 AM/PM END 12:52 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 1100 AM/PM END 120 AM/PM Examiners Initials DD mc
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	KM	OK	None obs.	
Main North seal & haulage	20.9	0	0	KM	OK	None obs	
Main West haulage seals	20.9	0	0	KM DD mc	ok	none obs.	
3rd North	20.9	0	0	KM	ok	None obs.	
1st right	20.9	0	0	KM	OK	None obs	
trans.	20.9	0	0	KM DD mc	ok	none obs.	
charger's	20.9	0	0	KM mc	ok	none obs.	
washdown	20.9	0	0	mc	ok	none obs.	
Storage Areas	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 9329
PRE-SHIFT/MINE EXAMINE CERT. # 8058
PRE-SHIFT/MINE EXAMINE CERT. # 3375
PRE-SHIFT/MINE EXAMINE CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03455

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-18-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 745 AM/PM END 830 AM/PM Examiners Initials RL
TIME OF EXAMINATION START 7:00 AM/PM END 1000 AM/PM Examiners Initials KK/LK
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	RL	OK	none observed	
Main North Haulage Seals	20.9	0	0	RL	OK	none observed	
Main West Haulage Seals	20.9	0	0	RL/KK/LK	OK	none obs.	
3rd North	20.9	0	0	RL	OK	none observed	
1st Right	20.9	0	0	RL	OK	none "	
Transformers	20.9	0	0	RL/KK/LK	OK	none obs	
Chargers	20.9	0	0	RL/KK/LK	OK	none obs.	
Washdown	20.9	0	0	RL	OK	none observed	
Storage Area	20.9	0	0	RL	OK	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 7154
PRE-SHIFT/MINE EXAMINER CERT. # 4373
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 4135

2MSHA03456

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-19-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:47 AM/PM END 5:04 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 3:00 AM/PM END 515 AM/PM Examiners Initials RL/LR
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	ok	none obs	
main North Haulage seals	20.9	0	0	KK	ok	none obs.	
Main West Haulage seals	20.9	0	0	KK/LR/RL	ok	None obs.	
3rd North	20.9	0	0	KK	ok	none obs.	
1st Right	20.9	0	0	KK	ok	none obs.	
Trans.	20.9	0	0	KK/LR/RL	OK	none obs.	
Chargers	20.9	0	0	KK/LR/RL	OK	None obs.	
Washdown	20.9	0	0	KK	ok	none	
Storage area	20.9	0	0	KK	ok	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam.

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7951
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURI CERT. # 4135

2MSHA03457

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-19-07 SECTION/AREA Bewmine / / /

TIME OF EXAMINATION START 11:50 AM/PM END 12:30 AM/PM Examiners Initials MC/Fm
TIME OF EXAMINATION START 11:05 AM/PM END 1:05 AM/PM Examiners Initials BH
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	MC/Fm	OK	none observed	
MAIN NORTH Haulage SEALS	20.9	0	0	MC/Fm	OK	none observed	
MAIN WEST Haulage SEALS	20.9	0	0	BH	OK	None Observed	
3rd NORTH Haulage	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
TRANSFORMERS	20.9	0	0	MC/BH	OK	None observed	
CHARGERS	20.9	0	0	BH	OK	None Observed	
WASHDOWN	20.9	0	0	BH	OK	None Observed	
STORAGE AREA	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at Time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03458

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-19-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 9:00 AM/PM Examiners Initials SW
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21°	0	0	SW	OK	none observed	
Main North haulage seals	21°	0	0	SW	OK	none observed	
Main West haulage seals	21°	0	0	SW	OK	none observed	
3rd North haulage seals	21°	0	0	SW	OK	none observed	
1st Right haulage	21°	0	0	SW	OK	none observed	
Transformers	21°	0	0	SW	OK	none observed	
Chargers	21°	0	0	SW	OK	none observed	
Washdown	21°	0	0	SW	OK	none observed	
Storage Area.	21°	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe to travel and work at time of exam.

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 9548
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATUR CERT. # 7485

2MSHA03459

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 70007 SECTION/AREA Gen / Mine / /

TIME OF EXAMINATION START 350 AM/PM END 535 AM/PM Examiners Initials dg
TIME OF EXAMINATION START 3:45 AM/PM END 5:10 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:00 AM/PM END 5:30 AM/PM Examiners Initials ZD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21.0	0	0	SW	OK	none observed	
Main North Haulage Seals	21.0	0	0	SW	OK	none observed	
Main Seals Pump West Haulage	20.9	0	.2	dg SW	OK	none observed	
3rd NO Haulage	21.0	0	0	SW	OK	none observed	
1st Right Haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	SW ZD	OK	none observed	
Chargers	20.9	0	.1	dg SW	OK	none observed	
Washdown	20.9	0	0	dg	OK	None observed	
Storage areas	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe to travel at time of exam.

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03460

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-20-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:05 AM/PM END 12:55 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 1210 AM/PM END 105 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 11:10 AM/PM END 11:31 AM/PM Examiners Initials BH/TC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	DD	ok	none obs.	
MAIN North haulage seals	20.9	0	0	DD	ok	none obs.	
MAIN West haulage seals	20.9	0	0	FM/TC BH/DD	ok	none observed	
3rd North haulage	20.9	0	0	FM	ok	none observed	
1st Right haulage	20.9	0	0	FM	ok	none observed	
Transformers	20.9	0	0	FM DD	ok	none observed	
Chargers	20.9	0	0	FM	ok	none observed	
storage area	20.9	0	0	FM	ok	none observed	
Wash down	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 8297
PRE-SHIFT/MINE EXAMINE CERT. # 8058
PRE-SHIFT/MINE EXAMINE CERT. # 8395
PRE-SHIFT/MINE EXAMINE CERT. # 9362

Signature

COUNTER SIGNATURE _ CERT. # 03492

2MSHA03461

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-20-07 SECTION/AREA general / Mine / /

TIME OF EXAMINATION START 7:45 AM/PM END 9:00 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:00 AM/PM END 9:45 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 740 AM/PM END 940 AM/PM Examiners Initials dy

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area.	21.0	0	0	SW	OK	none observed	
Main North haulage seals	21.0	0	0	SW	OK	none observed	
Main West haulage seals	21.0	0	0	~~SW~~ LD	OK	Rib slaffe off ~~x~~ c 89 Bolts to far from Rib	went to set timber Done 2-21-07 LD
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	~~SW~~ LD	OK	non observed	
chargers	21.0	0	0	~~SW~~ LD	OK	non observed	
washdown	20.9	0	0	dy	OK	non observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas Append Safe at time of exsam ecsept those noted above

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-21-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 3:45 AM/PM END 5:20 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:00 AM/PM END 5:30 AM/PM Examiners Initials JD
TIME OF EXAMINATION START 3:40 AM/PM END 5:30 AM/PM Examiners Initials [illegible]

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North seals haulage	21.0	0	0	SW	OK	none observed	
Main West haulage seals	21.0	0	0	~~SW~~ JD	OK	none observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	~~SW~~ JD	OK	none observed	
Chargers	21.0	0	0	~~SW~~ JD	OK	none observed	
washdown	20.0	0	0	JD	OK	none observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas appeard Safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. # 6602
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03463

PRE-SHIFT GENERAL MINE

ATE OF EXAMINATION 2-21-07 SECTION/AREA Gravmine / /

TIME OF EXAMINATION START 12:06 AM/PM END 1:00 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 12:00 AM/PM END 12:35 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 12:01 AM/PM END 1:30 AM/PM Examiners Initials FM

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	none obs.	
main North haulage Seals	20.9	0	0	FM	ok	none obs.	
Main West haulage Seals	20.9	0	0	TC/BH FM	ok	none obs.	
3rd north haulage	20.9	0	0	FM	ok	none obs.	
1st Right haulage	20.9	0	0	FM	ok	none obs.	
Transformers	20.9	0	0	FM	ok	none obs.	
Chargers	20.9	0	0	FM	ok	none obs.	
Washdown	20.9	0	0	FM	ok	none obs.	
storage Area	20.9	0	0	FM	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINEI CERT. # 9367
PRE-SHIFT/MINE EXAMINEI CERT. # 8395
PRE-SHIFT/MINE EXAMINEI CERT. # 8297
PRE-SHIFT/MINE EXAMINEI CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 03892

2MSHA03464

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-21-07 SECTION/AREA General / Mine / /

TIME OF EXAMINATION START 7:50 AM/PM END 9:10 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 8 AM/PM END 9:40 AM/PM Examiners Initials dg
TIME OF EXAMINATION START 7:00 AM/PM END 9:40 AM/PM Examiners Initials LD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage seals	21.0	0	0	SW	OK	none observed	
Main West haulage seals	21.0	0	0	~~SW~~ dg	OK	None observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	~~SW~~ dg	OK	None observed	
Chargers	21.0	0	0	~~SW~~ dg	OK	None observed	
wash down	20.9	0	0	LD	OK	none observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas Examined appear safe at Time of preshift

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03465

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-22-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 3:50 AM/PM END 5:15 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:00 AM/PM END 5:33 AM/PM Examiners Initials ZP
TIME OF EXAMINATION START 3:35 AM/PM END 5:30 AM/PM Examiners Initials dg

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North SEALS haulage	21.0	0	0	SW	OK	none observed	
Main West SEALS haulage	21.0	0	0	~~SW~~ dg ZP	OK	none observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	~~SW~~ ZP	OK	none observed	
chargers	21.0	0	0	~~SW~~ ZP	OK	none observed	
washdown	20.9	0	0	dg ZP	ok	none observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03466

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-22-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 12:00 AM/PM END 12:52 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 11:55 AM/PM END 12:25 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 11:52 AM/PM END 1:33 AM/PM Examiners Initials FM

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	none observed	
Main North Seal's haulage	20.9	0	0	FM	ok	none observed	
Main West Seal's haulage	20.9	0	0	TC FM	ok	none obs.	
3rd north haulage	20.9	0	0	FM	ok	none observed	
1st Right haulage	20.9	0	0	FM	ok	none observed	
Transformers	20.9	0	0	FM	ok	none observed	
Chargers	20.9	0	0	FM	ok	none observed	
Washdown	20.9	0	0	FM	ok	none observed	
storage area	20.9	0	0	FM	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 03892

2MSHA03467

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-22-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 7:50 AM/PM END 9:00 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 740 AM/PM END 940 AM/PM Examiners Initials dg
TIME OF EXAMINATION START 7:00 AM/PM END 945 AM/PM Examiners Initials JLO

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North Haulage Seals	21.0	0	0	SW	OK	none observed	
Main West Haulage Seals	21.0	0	0.2	~~SW~~ JLO/dg	OK	None observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	~~SW~~	OK	None observed	
Chargers	21.0	0	0	~~SW~~ JLO	OK	None observed	
Washdown	20.9	0	0	dg	ok	None observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas Examined appear safe at time of preshift

PRE-SHIFT/MINE EXAMINE Signature CERT. # 9548
PRE-SHIFT/MINE EXAMINE CERT. # 6622
PRE-SHIFT/MINE EXAMINE CERT. # 9660
PRE-SHIFT/MINE EXAMINE CERT. # _____

COUNTER SIGNATU Signature ERT. # 7485

2MSHA03468

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-23-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 3:51 AM/PM END 5:30 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:00 AM/PM END 5:30 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 4:20 AM/PM END 5:30 AM/PM Examiners Initials [illegible]

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North SEAL haulage	21.0	0	0	SW	OK	none observed	
Main West SEAL haulage	21.0	0	0	~~SW~~ LD	OK	none observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	~~SW~~ LD	OK	none observed	
Chargers	21.0	0	0	~~SW~~ LD	OK	none observed	
Washdown	20.9	0	0	LD	ok	none observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03469

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-23-07 SECTION/AREA Genmine / / /

TIME OF EXAMINATION START 11:08 AM/PM END 12:44 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 11:53 AM/PM END 12:45 AM/PM Examiners Initials FM
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	Fm	ok	none observed	
main North Haulage seals	20.9	0	0	Fm	ok	none observed	
main west Haulage seals	20.9	0	0	mc	ok	none observed	
3rd North Haulage	20.9	0	0	mc/Fm	ok	none observed	
1st Right Haulage	20.9	0	0	Fm	ok	none observed	
Transformers	20.9	0	0	mc/Fm	ok	none observed	
chargers	20.9	0	0	mc	ok	none observed	
washdown	20.9	0	0	mc	ok	none observed	
storage Area	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 7575
PRE-SHIFT/MINE EXAMINER _____ CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # _____

2MSHA03470

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-23-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 7:48 AM/PM END 9:04 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 705 AM/PM END 1000 AM/PM Examiners Initials JR/RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	ok	none observed	
Main North Haulage side	20.9	0	0	KK	ok	none observed	
Main West Haulage side	20.9	0	0	KK/JR/RL	ok	none	
3rd North Haulage	20.9	0	0	KK	ok	none observed	
1st right Haulage	20.9	0	0	KK	ok	none observed	
Trans.	20.9	0	0	KK/RL/JR	ok	none	
chargers	20.9	0	0	KK	ok	none observed	
Washdown	20.9	0	0	KK	ok	none observed	
Storage area	20.9	0	0	KK	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
PRE-SHIFT/MINE EXAMINER _____ CERT. # 6401
PRE-SHIFT/MINE EXAMINER _____ CERT. # 4375
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 4735

2MSHA03471

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-24-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 540 AM/PM Examiners Initials KK/RL
TIME OF EXAMINATION START 300 AM/PM END 505 AM/PM Examiners Initials RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs.	
Main North Haulage Seals	20.9	0	0	LR	OK	None obs	
Main West Haulage Seals	20.9	0	0	SMK/KK	OK	none obs	
3rd North Haulage	20.9	0	0	LR	OK	None obs.	
1st Right Haulage	20.9	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	KK/LR	OK	none obs	
Chargers	20.9	0	0	KK/LR	OK	none obs.	
Washdown	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATU ERT. # 8462

2MSHA03472

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-24-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 1100 AM/PM END 1201 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 11:20 AM/PM END 1:15 AM/PM Examiners Initials KM/MC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	ok	none obs.	
main north Haulage seals	20.9	0	0	DD	ok	none obs.	
main west Haulage seals	20.9	0	0	DD/MC KM	OK	none obs.	
3rd North Haulage	20.9	0	0	DD	ok	none obs.	
1st Right Haulage	20.9	0	0	DD	ok	none obs.	
Transformers	20.9	0	0	DD/MC KM	OK	none obs.	
chargers	20.9	0	0	DD/MC KM	OK	none obs.	
washdown	20.9	0	0	KM	OK	none obs.	
Storage Area	20.9	0	0	MC	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINEI CERT. # 8058
PRE-SHIFT/MINE EXAMINEI CERT. # 9379
PRE-SHIFT/MINE EXAMINEI CERT. # 7375
PRE-SHIFT/MINE EXAMINEI CERT. # ____

Signature

COUNTER SIGNATUR ____ CERT. # 4735

2MSHA03473

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-24-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 735 AM/PM END 9:20 AM/PM Examiners Initials JL
TIME OF EXAMINATION START 700 AM/PM END 930 AM/PM Examiners Initials KR/RL
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	Ø	Ø	JL	OK	None obs	
Main North Haulage Seals	20.9	Ø	Ø	JL	OK	None Obs	
Main west Haulage & Seals	20.9	Ø	Ø	JL KR/RL	OK	None Obs	
3rd North Hulage	20.9	Ø	Ø	JL	OK	None Obs	
1st Right Haulage	20.9	Ø	Ø	JL	OK	None obs	
Transformers	20.9	Ø	Ø	JL	OK	None obs	
Chargers	20.9	Ø	Ø	JL	OK	None obs	
Wash down	20.9	Ø	Ø	JL	OK	None obs	
Storage Area	20.9	Ø	Ø	JL	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at Time of Exam

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 7684
PRE-SHIFT/MINE EXAMINE CERT. # 6901
PRE-SHIFT/MINE EXAMINE CERT. #
PRE-SHIFT/MINE EXAMINE CERT. #

Signature

COUNTER SIGNATUR CERT. # 8762

2MSHA03474

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-25-07 SECTION/AREA Gentlemen / / /

TIME OF EXAMINATION START 300 AM/PM END 356 AM/PM Examiners Initials M
TIME OF EXAMINATION START 300 AM/PM END 630 AM/PM Examiners Initials KK/RC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	M	OK	None obs	
main North Haulage	20.9	0	0	M	OK	None obs	
N. West Haulage	20.9	0	0	M KK	OK	None obs	
1st North	20.9	0	0	M	OK	None obs	
1st right	20.9	0	0	M	OK	None obs	
storage area	20.9	0	0	M	OK	None obs	
Washdown	20.9	0	0	M	OK	None obs	
chargers	20.9	0	0	M	OK	None obs	
Trans.	20.9	0	0	M	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7684
PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 7959
PRE-SHIFT/MINE EXAMINER CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03475

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-25-07 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 11:35 AM/PM END 12:20 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 1100 AM/PM END 120 AM/PM Examiners Initials DD MC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	KM	OK	none observed	
Main North haulage seals	20.9	0	0	KM	OK	none observed	
Main West haulage seals	20.9	0	0	KM DD MC	OK	none observed	
3rd North haulage	20.9	0	0	KM	OK	none observed	
1st Right haulage	20.9	0	0	KM	OK	none observed	
Trans.	20.9	0	0	KM DD MC	ok	none observed	
Chargers	20.9	0	0	KM MC	ok	none observed	
Wash down							
Storage area							

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # ____

Signature

COUNTER SIGNATUR CERT. # 8462

2MSHA03476

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-25-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7.47 AM/PM END 9.20 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 700 AM/PM END 940 AM/PM Examiners Initials LR/RL
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	ok	none obs	
M/North Haulage seal	20.9	0	0	KK	ok	none obs	
M.West Haulage seals	20.9	0	0	KK/LR/RL	ok	none observed	
3rd north Haulage	20.9	0	0	KK	ok	none obs	
1st north Haulage	20.9	0	0	KK	ok	none obs	
Storage area	20.9	0	0	KK	ok	none obs	
Washdown	20.9	0	0	KK	ok	none obs.	
Trans.	20.9	0	0	KK/LR/RL	ok	none obs.	
Chargers	20.9	0	0	KK/RL/LR	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exams

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATUI CERT. # 4135

2MSHA03477

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-26-07 SECTION/AREA Gen Min / / /

TIME OF EXAMINATION START 3:10 AM/PM END 4:20 AM/PM Examiners Initials RR
TIME OF EXAMINATION START 3:00 AM/PM END 5:10 AM/PM Examiners Initials LR/RL
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	ok	none obs	
M North Haulage seal	20.9	0	0	KK	ok	none obs	
M West Haulage seal	20.9	0	0	KK/LR/RL	ok	None obs.	
3rd North	20.9	0	0	KK	ok	none obs	
1st right	20.9	0	0	KK	ok	none obs	
Storage area	20.9	0	0	KK	ok	none	
Washdown	20.9	0	0	KK	ok	none	
Trans.	20.9	0	0	KK/LR/RL	ok	None obs.	
chargers	20.9	0	0	KK/RL/LR	ok	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 7954
PRE-SHIFT/MINE EXAMINE CERT. # 4375
PRE-SHIFT/MINE EXAMINE CERT. # 6401
PRE-SHIFT/MINE EXAMINE CERT. #

Signature

COUNTER SIGNATURE CERT. # 4135

2MSHA03478

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-26-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:10 AM/PM END 1:00 AM/PM Examiners Initials FM/MC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	209	0	0	FM/MC	OK	none observed	
Main North haulage seals	209	0	0	FM/MC	OK	none observed	
Main West haulage seals	209	0	0	FM/MC	OK	none observed	
3rd North haulage	209	0	0	FM/MC	OK	none observed	
1st Right haulage	209	0	0	FM	OK	none observed	
storage area	209	0	0	FM	OK	none observed	
Transformers	209	0	0	FM/MC	OK	none observed	
chargers	209	0	0	FM/MC	OK	none observed	
Wash down	209	0	0	MC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 8297
PRE-SHIFT/MINE EXAMINER ____ CERT. # 7375
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE ____ CERT. # 7485

2MSHA03479

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-26-07 SECTION/AREA Longwall

TIME OF EXAMINATION START 700 AM/PM END 8:40 AM/PM Examiners Initials KR/LR
TIME OF EXAMINATION START 7:47 AM/PM END 9:25 AM/PM Examiners Initials TC
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	TC	ok	none obs.	
M. West Haulage seals	20.9	0	0	KR/LR/TC	ok	COMA Rec. 93, 96, 97	working on
3rd North	20.9	0	0	TC	ok	none obs.	
1st Right	20.9	0	0	TC	ok	none obs.	
storage area	20.9	0	0	TC	ok	none obs.	
washdown	20.9	0	0	TC	ok	none obs.	
Trans.	20.9	0	0	KR/TC/LR	ok	none obs.	
charge	20.9	0	0	TC/LR/KR	ok	none obs.	
Main North Haulage open	20.9	0	0	TC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved Safe at time of Exam except as noted above

Signature

PRE-SHIFT/MINE EXAMINE ___ CERT. # 7954
PRE-SHIFT/MINE EXAMINE ___ CERT. # 4325
PRE-SHIFT/MINE EXAMINE ___ CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03480

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-27-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 4:56 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 3:40 AM/PM END 4:40 AM/PM Examiners Initials CA
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	CA	ok	none obs.	
M.West Haulage & Seals	20.9	0	0	TC/GA	ok	COAL ACC. 93-96-97-109	Have been working on CA 2/27/07 [illegible]
3rd North	20.9	0	0	CA	ok	none obs.	
1st Right	20.9	0	0	CA	ok	none obs.	
Main North	20.9	0	0	CA	ok	none obs	
Storage Area	20.9	0	0	TC	ok	none obs.	
Washdown	20.9	0	0	TC	ok	none obs.	
Transformers	20.9	0	0	TC/GA	ok	none obs.	
Chargers	20.9	0	0	TC/GA	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
#20 MW +	Getting gray	Dusted it
Main No		2-27-07 CA

PRE-SHIFT REMARKS All Areas Seemed Reasonably safe at Time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362
PRE-SHIFT/MINE EXAMINER ____ CERT. # 03892
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATUR Signature CERT. # 7485

2MSHA03481

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-27-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 11:43 AM/PM END 12:35 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 11:00 AM/PM END 12:40 AM/PM Examiners Initials FM
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main West haulage seals	21.0	0	0	~~SW~~ FM	OK	None observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Main North haulage seals	21.0	0	0	SW	OK	none observed	
Storage Area	209	0	0	FM	OK	None observed	
Washdown	209	0	0	FM	OK	None observed	
Transformers	21.0	0	0	~~SW~~ FM	OK	None observed	
chargers	21.0	0	0	~~SW~~ FM	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINE Signature CERT. # 9548
PRE-SHIFT/MINE EXAMINE CERT. # 8297
PRE-SHIFT/MINE EXAMINE CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03482

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-27-07 SECTION/AREA Gen Min / /

TIME OF EXAMINATION START 7:47 AM/PM END 9:24 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 7:45 AM/PM END 8:18 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	TC	ok	none obs.	
Main North Haulage seals	20.9	0	0	TC	ok	none obs.	
Main West Haulge seals	20.9	0	0	TC/BH	ok	none obs.	
3rd north	20.9	0	0	TC	ok	none obs.	
1st Right	20.9	0	0	TC	ok	none obs.	
storage Area	20.9	0	0	TC	ok	none obs.	
Wash Down	20.9	0	0	TC	ok	none obs	
Transformers	20.9	0	0	TC	ok	none obs.	
Chargers	20.9	0	0	TC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas seemed safe At Time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03483

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-28-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 330 AM/PM END 401 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 3:00 AM/PM END 3:25 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 3:51 AM/PM END 5:24 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	TC	ok	none obs	
main North Haulage	20.9	0	0	TC	ok	none obs.	
3rd North Haulage	20.9	0	0	TC	ok	none obs	
1st Right	20.9	0	0	TC	ok	none obs.	
main West Haulage	20.9	0	0	BP/TC	ok	none observed	
Storage Area	20.9	0	0	TC	ok	none obs.	
washdown	20.9	0	0	TC	ok	none obs.	
Transformers	20.9	0	0	TC	ok	none obs.	
charger 1	20.9	0	0	TC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All AREAS SAFE AT TIME OF EXAM

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9599
PRE-SHIFT/MINE EXAMINER CERT. # 8345
PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATUR Signature CERT. # 7485

2MSHA03484

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-28-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:47 AM/PM END 12:37 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:00 AM/PM END 12:40 AM/PM Examiners Initials SW
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	α	None observed	
Main North haulage seals	20.9	0	0	FM	α	None observed	
Main West haulage seals	21.0	0	0	SW	OK	none observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	~~SW~~ FM	OK	none observed	
Chargers	21.0	0	0	SW	OK	none observed	
storage Area	21.0	0	0	SW	OK	none observed	
Wash down	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe to travel and work at time of exam.

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-28-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 7:35 AM/PM Examiners Initials JS
TIME OF EXAMINATION START 7:48 AM/PM END 9:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
main Haulage WEST Seals	20.9	0	0	TC/BH	OK	Machine Door Needs Fixed AT JC 104 has hole in steering	Working on Done JC
3rd north Haulage	20.9	0	0	BH	OK	None Observed	
1ST Right	20.9	0	0	BH	OK	None Observed	
main Haulage north Seals	20.9	0	0	BH	OK	None Observed	
Stoage Area	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
Tranformer's	20.9	0	0	BH/TC	OK	None Observed	
chargers ~~[illegible]~~	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Except as noted above all areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362
PRE-SHIFT/MINE EXAMINER ____ CERT. # 8395
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03486

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-1-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 3:40 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 3:41 AM/PM END 5:15 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	BH	ok	none obs.	
Main West Haulage & Seals	20.9	0	0	TC/BH	ok	Deep water XC 73 & 75	Sent mark to pump Done 3-1-07 FM
Main North Haulage seals	20.9	0	0	BH	ok	none obs.	
3rd north	20.9	0	0	BH	ok	none obs.	
1st Right	20.9	0	0	BH	ok	none obs.	
Storage Area	20.9	0	0	BH	ok	none obs.	
Washdown	20.9	0	0	BH	ok	none obs.	
Transformers	20.9	0	0	BH	ok	none obs.	
Chargers	20.9	0	0	BH	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
~~X-cut 81~~	~~loose top~~	~~set timber~~
M West intake	Getting gray	dusted
seals to 88		

PRE-SHIFT REMARKS Except as noted above all areas appered reasonably safe @ time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03487

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-1-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 11:50 AM/PM END 12:20 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 11:00 AM/PM END 12:46 AM/PM Examiners Initials FM
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	ok	none observed	
Main West SEALS haulage	20.9	0	0	FM	ok	BAD TOP X cut 81	Set timber 3-1-07 SG
3rd North haulage	20.9	0	0	FM	ok	none observed	
1st Right	20.9	0	0	FM	ok	none observed	
Main North SEALS haulage	21.0	0	0	SW	ok	none observed	
Storage Area	20.9	0	0	FM	ok	none observed	
Washdown	20.9	0	0	FM	ok	none observed	
Transformers	21.0	0	0	~~SW~~ FM	ok	none observed	
chargers	20.9	0	0	FM	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
X-cut 81	bad top	set timbers

PRE-SHIFT REMARKS areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATUR Signature CERT. # 7485

2MSHA03488

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3 / 07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 8:10 AM/PM END 9 AM/PM Examiners Initials GA
TIME OF EXAMINATION START 7:00 AM/PM END 8:50 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 7:20 AM/PM END 9:00 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	GA	OK	None observed	
Main No Haulage Seals	20.9	0	0	GA	OK	None observed	
3rd No Haulage Seals	20.9	0	0	GA	OK	None observed	
1st Rt Haulage	20.9	0	0	GA	OK	None observed	
Main West Haulage Seals	20.9	0	0	BH/BP	OK	None Observed	
Transformers	20.9	0	0	BH/BP	OK	None Observed	
Chargers	20.9	0	0	BH/GA	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Areas	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
1st Rt	Getting gray	Dusted haulage

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 03892
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 9549
PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03489

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3 2 07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 350 AM/PM END 444 AM/PM Examiners Initials CT
TIME OF EXAMINATION START 4:20 AM/PM END 520 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 3:36 AM/PM END 5:26 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CT	OK	None observed	
Main No Haulage Seals	20.9	0	0	CT	OK	None observed	
1st Rt Haulage	20.9	0	0	CT	OK	None observed	
3rd No Haulage Seals	20.9	0	0	CT	OK	None observed	
main North Haulage Seals	20.9	0	0	BP/BH	ok	none observed	
Storage Area	20.9	0	0	BP/BH	ok	none observed	
washdown	20.9	0	0	BP/BH	ok	none observed	
Transformers	20.9	0	0	BP/BH	ok	none observed	
charger 1	20.9	0	0	BP/BH	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared Safe at Time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 03892
PRE-SHIFT/MINE EXAMINER CERT. # 9599
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 4135

2MSHA03490

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-2-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:40 AM/PM END 1:10 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 11:00 AM/PM END 1:15 AM/PM Examiners Initials LR/FM
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	ok	none	
Main North Haulage	20.9	0	0	KK	ok	none	
M. West Haulage	20.9	0	0	KK/LR/FM	ok	none	
3rd North	20.9	0	0	KK	ok	none	
1st right	20.9	0	0	KK	ok	none	
Trans.	20.9	0	0	KK/FM/LR	ok	none	
Chargers	20.9	0	0	KK	ok	none	
Storage area	20.9	0	0	KK	ok	none	
Washdown	20.9	0	0	KK	ok	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 4735

2MSHA03491

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-2-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 7:57 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 700 AM/PM END 915 AM/PM Examiners Initials DD KM
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	ok	none observed	
Main North Haulage seals	20.9	0	0	MC	ok	none observed	
Main West Haulage seals	20.9	0	0	MC DD km	ok	none obs.	
3rd North Haulage	20.9	0	0	MC	ok	none observed	
1st Right Haulage	20.9	0	0	MC	ok	none observed	
Transformers	20.9	0	0	MC DD km	ok	none obs.	
chargers	20.9	0	0	MC DD	ok	none obs.	
washdown	20.9	0	0	DD	ok	none obs.	
Storage Area	20.9	0	0	km	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINEI Signature CERT. # 7375
PRE-SHIFT/MINE EXAMINEI CERT. # 8058
PRE-SHIFT/MINE EXAMINEI CERT. # 9379
PRE-SHIFT/MINE EXAMINEI CERT. #

Signature

COUNTER SIGNATUR CERT. # 8462

2MSHA03492

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-3-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 5:10 AM/PM Examiners Initials KM/MC
TIME OF EXAMINATION START 300 AM/PM END 400 AM/PM Examiners Initials DD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
Main North haulage & seals	21	0	0	DD	ok	none obs	
Main West haulage seals	20.9	0	0	KM MC DD	ok	none obs	
3rd North haulage	21	0	0	DD	ok	none obs.	
1st right haulage	21	0	0	DD	ok	none obs.	
Tsans	20.9	0	0	KM MC DD	ok	none obs.	
chargers	20.9	0	0	KM DD	ok	none obs.	
Washdown	20.9	0	0	KM	ok	none obs	
storage area	20.9	0	0	MC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 5055
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 4775

2MSHA03493

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-8-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11.55 AM/PM END 1.20 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 1100 AM/PM END 115 AM/PM Examiners Initials RR/RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	none	
M North Haulage	20.9	0	0	KK	OK	none	
M West Haulage	20.9	0	0	KK/RL	OK	None	
3rd north	20.9	0	0	KK	OK	none	
1st right	20.9	0	0	KK	OK	none	
Storage area	20.9	0	0	KK	OK	none	
Washdown	20.9	0	0	KK	OK	none	
Storage area	20.9	0	0	KK	OK	none	
chargers	20.9	0	0	KK	OK	none	
Trans	20.9	0	0	KK/RL			

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared Safe at time of Exam.

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 2964
PRE-SHIFT/MINE EXAMINER _____ CERT. # 4375
PRE-SHIFT/MINE EXAMINER _____ CERT. # 6401
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATUR CERT. # 4735

2MSHA03494

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-3-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 7:50 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 7:25 AM/PM END 9:00 AM/PM Examiners Initials MC/DD
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	KM	ok	none obs.	
Main North haulage seals	20.9	0	0	KM	OK	none obs	
Main West haulage seals	20.9	0	0	KM MC/DD	OK	none observed	
3rd north	20.9	0	0	KM	OK	none obs.	
1st right	20.9	0	0	KM	OK	none obs	
storage area	20.9	0	0	MC	OK	none observed	
Wash down	20.9	0	0	MC	OK	none observed	
Chargers	20.9	0	0	KM MC	OK	none observed	
Trans.	20.9	0	0	KM DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # ____

Signature

COUNTER SIGNATUR CERT. # 8462

2MSHA03495

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-4-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 530 AM/PM Examiners Initials DD km
TIME OF EXAMINATION START 3:01 AM/PM END 4:05 AM/PM Examiners Initials mc
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none obs.	
Main North Haulage Seals	20.9	0	0	mc	ok	none obs	
main west Haulage seals	20.9	0	0	mc DD km	ok	none obs.	
3rd North	20.9	0	0	mc	ok	none obs	
1st Right	20.9	0	0	mc	ok	none obs	
Storage Area	20.9	0	0	DD	ok	none obs	
wash down	20.9	0	0	DD	ok	none obs.	
chargers	20.9	0	0	mc DD	ok	none obs.	
Trans.	20.9	0	0	mc DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 8058
PRE-SHIFT/MINE EXAMINER ____ CERT. # 7375
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE ____ CERT. # 4735

2MSHA03496

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-4-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 1130 AM/PM END 115 AM/PM Examiners Initials RL
TIME OF EXAMINATION START 11:00 AM/PM END 120 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	Ø	Ø	RL	Ø	none observed	
Main No Haulage Seals	20.9	Ø	Ø	RL	Ø	none "	
Main West Haulage Seals	20.9	Ø	Ø	RL/LR/KK	Ø	None observed	
3rd North	20.9	Ø	Ø	RL	Ø	none observed	
1st Right	20.9	Ø	Ø	RL	Ø	none observed	
Storage area	20.9	Ø	Ø	RL	Ø	none "	
washdown	20.9	Ø	Ø	RL	Ø	none "	
chargers	20.9	Ø	Ø	RL/KK	Ø	None "	
transformers	20.9	Ø	Ø	RL/KK	Ø	None "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 6401
PRE-SHIFT/MINE EXAMINE CERT. # 4375
PRE-SHIFT/MINE EXAMINE CERT. # 7954
PRE-SHIFT/MINE EXAMINE CERT. #

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03497

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-4-07 SECTION/AREA Bewmine / / /

TIME OF EXAMINATION START 7:44 AM/PM END 8:57 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 700 AM/PM END 925 AM/PM Examiners Initials DD/km
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	mc	ok	none observed	
MAIN NORTH HAULAGE SEALS	20.9	0	0	mc	ok	none observed	
MAIN WEST HAULAGE SEALS	20.9	0	0	mc DD km	ok	none obs.	
3RD NORTH HAULAGE	20.9	0	0	mc	ok	none observed	
1ST RIGHT HAULAGE	20.9	0	0	mc	ok	none observed	
TRANSFORMERS	20.9	0	0	mc DD km	ok	none obs.	
CHARGERS	20.9	0	0	mc DD	ok	none obs.	
WASHDOWN	20.9	0	0	DD	ok	none obs.	
STORAGE AREA	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 2375
PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
PRE-SHIFT/MINE EXAMINER _____ CERT. # 9579
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03498

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-5-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 5:30 AM/PM Examiners Initials Km/mc
TIME OF EXAMINATION START 305 AM/PM END 405 AM/PM Examiners Initials DD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	ok	none obs.	
Main North haulage seals	20.9	0	0	DD	ok	none obs	
Main West haulage seals	20.9	0	0	Km DD	ok	none obs	
3rd North haulage	20.9	0	0	DD	ok	none obs.	
1st right haulage	20.9	0	0	DD	ok	none obs.	
Trans	20.9	0	0	mc DD	ok	none obs.	
Chargers	20.9	0	0	mc DD	OK	none obs	
Wash down	20.9	0	0	mc DD	OK	none obs.	
storage Area	20.9	0	0	mc DD	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas Appeared safe at time of exam.

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 9379
PRE-SHIFT/MINE EXAMINE CERT. # 7377
PRE-SHIFT/MINE EXAMINE CERT. # 8058
PRE-SHIFT/MINE EXAMINE CERT. #

Signature

COUNTER SIGNATUR CERT. # 7485

2MSHA03499

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-5-07 SECTION/AREA Gem/Mud / /

TIME OF EXAMINATION START 11:00 AM/PM END 11:27 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 11:00 AM/PM END 12:46 AM/PM Examiners Initials FM
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	210	0	0	KK	OK	none	
M. North Haulage	209	0	0	RK	OK	none	
M. West Haulage	209	0	0	FM	OK	none observed	
3rd north	209	0	0	FM	OK	none observed	
1st right	209	0	0	FM	OK	none observed	
Storage area	209	0	0	FM	OK	none observed	
Washdown	209	0	0	FM	OK	none observed	
Trans.	209	0	0	FM	OK	none observed	
Transfers	209	0	0	FM	OK	none obsered	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINE _____ CERT. # 7954
PRE-SHIFT/MINE EXAMINE _____ CERT. # _____
PRE-SHIFT/MINE EXAMINE _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 7488

2MSHA03500

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-5-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 7:00 AM/PM END 7:40 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 7:50 AM/PM END 9:31 AM/PM Examiners Initials MC
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
main Haulage north Seals	20.9	0	0	mc	ok	none observed	
main Haulage west Seals	20.9	0	0	TC/mc	ok	none observed	
3rd North Haulage Seals	20.9	0	0	mc	ok	none observed	
1st Right	20.9	0	0	mc	ok	none observed	
Stoage Area	20.9	0	0	mc	ok	none observed	
washdown	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	mc	ok	none observed	
Chargers	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonally safe At Time of preshift

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # 7575
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 03892

2MSHA03501

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-6-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:46 AM/PM END 5:13 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 3:00 AM/PM END 3:30 AM/PM Examiners Initials JC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
Main North Haulage Seals	20.9	0	0	mc	ok	none observed	
Main West Haulage Seal	20.9	0	0	mc/JC	ok	none observed	
3rd North Haulage	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	mc	ok	none observed	
Chargers	20.9	0	0	mc	ok	none observed	
washdown	20.9	0	0	mc	ok	none observed	
storage	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main West	Getting gray	dusted
80-45		

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

PRE-SHIFT/MINE EXAMINER Signature ___ CERT. # 7775
PRE-SHIFT/MINE EXAMINER ___ CERT. # 9362
PRE-SHIFT/MINE EXAMINER ___ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATUR Signature CERT. # 74885

2MSHA03502

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-6-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:06 AM/PM END 11:42 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:00 AM/PM END 1:00 AM/PM Examiners Initials SW
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	FM	OC	none observed	
MAIN North haulage seals	20.9	0	0	FM	OC	none observed	
MAIN West haulage seals	21.0	0	0	SW	OK	none observed	
3rd North Haulage	21.0	0	0	SW	OK	none observed	
1st Right Haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	FM SW	OK	none observed	
Chargers	21.0	0	0	SW	OK	none observed	
Washdown	21.0	0	0	SW	OK	none observed	
Storage area	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main West Section	oil cans at chargers	removed from section

PRE-SHIFT REMARKS Areas appeared safe to travel and work at time of exam.

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 8297
PRE-SHIFT/MINE EXAMINE CERT. # 9548
PRE-SHIFT/MINE EXAMINE CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATUR CERT. # 7485

2MSHA03503

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3607 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 8 AM/PM END 8:45 AM/PM Examiners Initials CA
TIME OF EXAMINATION START 7:30 AM/PM END 9:30 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 9:10 AM/PM END 9:39 AM/PM Examiners Initials TC

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CA	OK	None observed	
Main No Haulage Seals	20.9	0	0	CA	OK	None observed	
1st Rt Haulage	20.9	0	0	CA	OK	None observed	
3 No Haulage Seals	20.9	0	0	CA	OK	None observed	
Main West Haulage Seals	20.9	0	0	BH/tc	OK	None Observed	
Transformers	20.9	0	0	BH/tc	OK	None Observed	
Chargers	20.9	0	0	BH/tc	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
Storage Areas	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINI _____ CERT. # 03892
PRE-SHIFT/MINE EXAMINI CERT. # 8395
PRE-SHIFT/MINE EXAMINI CERT. # 9362
PRE-SHIFT/MINE EXAMINI _____ CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 03892

2MSHA03504

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-7-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 4:00 AM/PM END 5:37 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 3:48 AM/PM END 5:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 3:09 AM/PM END 3:20 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	none obs.	
Main North Haulage & seals	20.9	0	0	TC/BP	OK	none obs.	
1st Rt. Haulage	20.9	0	0	BH	OK	none obs.	
3rd north Haulage seals	20.9	0	0	BH	OK	none obs.	
Transformers	20.9	0	0	TC/BH	OK	none obs.	
Main west Haulage seals	20.9	0	0	TC/BH	OK	none obs.	
Chargers	20.9	0	0	BH	OK	none obs.	
Washdown	20.9	0	0	BH	OK	none obs	
storage Areas	20.9	0	0	BH	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 8599
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 7685

2MSHA03505

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3707 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11 AM/PM END 12:15 AM/PM Examiners Initials dg
TIME OF EXAMINATION START 11:00 AM/PM END 12:10 AM/PM Examiners Initials SW
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21.0	0	0	SW	ok	none observed	
Main North Seals Haulage	21.0	0	0	SW	ok	none observed	
1ST RT Haulage	21.0	0	0	SW	ok	none observed	
3rd No Haulage	21.0	0	0	SW	ok	none observed	
Main Seals, Pumps West Haulage	20.9	0	0	dg/SW	ok	None observed	
Transformers	20.9	0	0	dg/SW	ok	None observed	
chargers	20.9	0	0	dg/SW	ok	None observed	
washdown	20.9	0	0	dg	ok	None observed	
Storage areas	21.0	0	0	SW	ok	none observed.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main West Sec.	dustie roadways	hauled water

PRE-SHIFT REMARKS Areas appeared safe to travel and work at time of exam.

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

2MSHA03506

Signature

COUNTER SIGNATUR CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3 7 07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 810 AM/PM END 906 AM/PM Examiners Initials GA
TIME OF EXAMINATION START 7:40 AM/PM END 9:41 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 7:40 AM/PM END 9:41 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	GA	OK	None observed	
Main No Haulage Seals	20.9	0	0	GA	OK	None observed	
1st Rt. Haulage	20.9	0	0	GA	OK	None observed	
3rd No Haulage Seals	20.9	0	0	GA	OK	None observed	
Mainwest Haulage & seals.	20.9	0	0	TC/BP	OK	none obs.	
Transformers	20.9	0	0	TC	OK	None obs.	
Chargers	20.9	0	0	TC	OK	none obs.	
Washdown	20.9	0	0	TC	OK	none obs.	
storagareen	20.9	0	0	TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All AREAS APPEARED Reasonably Safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 03892
PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 9599
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03507

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-8-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 4:30 AM/PM END 5:10 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 4:51 AM/PM END 5:10 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 3:54 AM/PM END 5:25 AM/PM Examiners Initials BH

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage & seals	20.9	0	0	BH	OK	None observed	
Main West Haulage & seals	20.9	0	0	TC/BP BH	OK	None obs.	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
3rd north Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 9362
PRE-SHIFT/MINE EXAMINE CERT. # 9399
PRE-SHIFT/MINE EXAMINE CERT. # 8395
PRE-SHIFT/MINE EXAMINE CERT. # _____

Signature

2MSHA03508

COUNTER SIGNATURE CERT. # 74885

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3887 SECTION/AREA Gen / Mine / /

TIME OF EXAMINATION START 11 AM/PM END 1 AM/PM Examiners Initials dg
TIME OF EXAMINATION START 11:00 AM/PM END 12:30 AM/PM Examiners Initials SW
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21.0	0	0	SW	OK	none observed	
Main Seals North Haulage	21.0	0	0	SW	OK	none observed	
Main Seals pumps West Haulage	20.9	0	.3	dg/SW	OK	none observed	
1st Right Haulage	21.0	0	0	SW	OK	none observed	
3rd No Haulage	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	dg/SW	OK	none observed	
Chargers	20.9	0	.1	dg/SW	OK	none observed	
washdown	20.9	0	0	dg	OK	None observed	
Storage areas	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
West Main Sec.	needs rock dust	dusted

PRE-SHIFT REMARKS Areas appeared safe to travel and work at time of exam.

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATUR CERT. # 7485

2MSHA03509

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 9-8-07 SECTION/AREA Gene Mine / /

TIME OF EXAMINATION START 7:00 AM/PM END 7:30 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 7:44 AM/PM END 9:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 7:00 AM/PM END 7:15 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
main north Haulage Seals	20.9	0	0	BH	OK	None Observed	
main west Haulage Seals	20.9	0	0	TC/BH BP	ok	none observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
3rd north Haulage Seals	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None observed	
chargers	20.9	0	0	BH	OK	None observed	
washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9599
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03510

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-9-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 3:15 AM/PM END 3:46 AM/PM Examiners Initials K
TIME OF EXAMINATION START 3:15 AM/PM END 3:46 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 3:51 AM/PM END 5:25 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	none obs	
Main North Haulage Seals	20.9	0	0	BH	OK	none obs	
Main West Haulage seals	20.9	0	0	TCB BH	OK	none obs	
1st Right Haulage	20.9	0	0	BH	OK	none obs	
3rd North Haulage seals	20.9	0	0	BH	OK	none obs	
Transformers	20.9	0	0	BH	OK	none obs.	
Chargers	20.9	0	0	BH	OK	none obs.	
Wash Down	20.9	0	0	BH	OK	none obs.	
Storag Area.	20.9	0	0	BH	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS _____

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 9362
PRE-SHIFT/MINE EXAMINE CERT. # 9599
PRE-SHIFT/MINE EXAMINE CERT. # 8395
PRE-SHIFT/MINE EXAMINE CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 4335

2MSHA03511

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-9-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:55 AM/PM END 1:20 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:10 AM/PM END 1:30 AM/PM Examiners Initials AR/KK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	∝	none observed	
Main North haulage seals	20.9	0	0	FM	∝	none observed	
Main West haulage seals	20.9	0	0	FM/AR/KK	∝	none observed	
3rd North haulage	20.9	0	0	FM	∝	none observed	
1st Right haulage	20.9	0	0	FM	∝	none observed	
Transformers	20.9	0	0	FM	∝	none observed	
Chargers	20.9	0	0	FM	∝	none observed	
Washdown	20.9	0	0	FM	∝	none observed	
storage Area	20.9	0	0	FM	∝	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 4373
PRE-SHIFT/MINE EXAMINER CERT. # 2954
PRE-SHIFT/MINE EXAMINER CERT. # ____

Signature

COUNTER SIGNATI ____ CERT. # 4135

2MSHA03512

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-9-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 7:58 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 7:00 AM/PM END 8:30 AM/PM Examiners Initials KM/DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
main North Haulage seals	20.9	0	0	mc	ok	none observed	
main west Haulage seals	20.9	0	0	mc/DD KM	ok	none observed	
3rd North Haulage	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	mc KM/DD	ok	none observed.	
chargers	20.9	0	0	mc DD	ok	none observed	
washdown	20.9	0	0	DD	ok	none observed	
storage Area	20.9	0	0	DD	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main Haulage	crib blocks in Roadway	Picked up Hauled off

PRE-SHIFT REMARKS Areas apeared safe at the time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8962

2MSHA03513

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-10-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 4:00 AM/PM END 5:00 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 3:00 AM/PM END 5:35 AM/PM Examiners Initials DD MC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	KM	OK	none obs.	
Main North haulage seals	20.9	0	0	KM	OK	none obs.	
Main West haulage seals	20.9	0	0	KM DD MC	ok	none obs.	
3rd North haulage	20.9	0	0	KM	OK	none obs.	
1st right haulage	20.9	0	0	KM	OK	none obs	
Trans	20.9	0	0	KM DD MC	ok	none obs.	
Chargers	20.9	0	0	KM MC	ok	none obs.	
Wash down	20.9	0	0	MC	ok	none obs	
Storage Area	20.9	0	0	MC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # ____
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 1375
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATUR ____ CERT. # ____

2MSHA03514

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-10-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 1100 AM/PM END 130 AM/PM Examiners Initials LP/RL
TIME OF EXAMINATION START 1155 AM/PM END 142 AM/PM Examiners Initials KK
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	Ø	Ø	KK	OK	none obs	
Main North Haulage Seals	20.9	Ø	Ø	KK	OK	none obs	
Main West Haulage Seals	20.9	Ø	Ø	KK/RL/LR	OK	None obs.	
3rd North Haulage	20.9	Ø	Ø	KK	OK	none obs	
1st Right Haulage	20.9	Ø	Ø	KK	OK	none obs	
Transformers	20.9	Ø	Ø	KK/RL	OK	none obs	
chargers	20.9	Ø	Ø	KK	OK	none obs	
washdown	20.9	Ø	Ø	KK	OK	none obs	
Storage Area	20.9	Ø	Ø	KK	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 7959
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 4735

2MSHA03515

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-10-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 700 AM/PM END 810 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 7:30 AM/PM END 9:25 AM/PM Examiners Initials mc/km
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	ok	none obs.	
main north Haulage Seals	20.9	0	0	DD	ok	none obs.	
main west Haulage seals	20.9	0	0	DD mc/km	ok	stopping # 129+130 need Repair	done 3-11-07
3rd North Haulage	20.9	0	0	DD	ok	none obs.	
1st Right Haulage	20.9	0	0	DD	ok	none obs.	
Trans.	20.9	0	0	DD mc/km	ok	none observed	
chargers	20.9	0	0	DD mc	ok	none observed	
wash down	20.9	0	0	mc	ok	none observed	
Storage Area	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe At Time of preshift

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
PRE-SHIFT/MINE EXAMINER _____ CERT. # 9379
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03516

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-11-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:00 AM/PM END 5:20 AM/PM Examiners Initials KM/DD
TIME OF EXAMINATION START 3:00 AM/PM END 3:56 AM/PM Examiners Initials MC
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	none observed	
Main North haulage seals	20.9	0	0	MC	OK	none observed	
Main West haulage seals	20.9	0	0	KM/DD MC	OK	stopping 129 needs FOAMed	done 3-11-07
3rd North haulage	20.9	0	0	MC	OK	none observed	
1st right haulage	20.9	0	0	MC	OK	none observed	
Trans.	20.9	0	0	KM/DD MC	OK	none observed	
chargers	20.9	0	0	KM/DD MC	OK	none observed	
Washdown	20.9	0	0	KM	OK	none observed	
storage Area	20.9	0	0	KM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATUR CERT. # 4735

2MSHA03517

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-11-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 1:15 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	KK/LR	OK	None obs.	
Main North Haulage & Seals	20.9	0	0	KK/LR	OK	None obs.	
Main West Haulage & Seals	20.9	0	0	KK/LR	OK	None obs.	
3rd North Haulage	20.9	0	0	KK/LR	OK	None obs.	
1st Right Haulage	20.9	0	0	KK/LR	OK	None obs.	
Turns.	20.9	0	0	KK/LR	OK	None obs.	
Changeouts	20.9	0	0	KK/LR	OK	None obs.	
Washdown	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # 7959
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATUR ____ CERT. # 4735

2MSHA03518

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-11-07 SECTION/AREA Genmine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 8:45 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 700 AM/PM END 700 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	DD	ok	none obs.	
Main North Haulage Seals	21	0	0	DD	ok	none obs.	
Main West Haulage Seals	20.9	0	0	mc	ok	none observed	
3rd North Haulage	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	mc	ok	none observed	
chargers	20.9	0	0	mc	ok	none observed	
washdown	20.9	0	0	mc	ok	none observed	
Storage Area	20.9	0	0	mc	ok	none observed	
Kitchen	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 2375
PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03519

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-12-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 530 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 3:01 AM/PM END 3:37 AM/PM Examiners Initials MC
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	ok	none observed	
main north Haulage-Seals	20.9	0	0	MC	ok	none observed	
main west Haulage - Seals	20.9	0	0	DD	ok	none obs.	
3rd North Haulage	20.9	0	0	DD	ok	none obs.	
1st Right	20.9	0	0	DD	ok	none obs.	
Trans.	20.9	0	0	DD	ok	none obs.	
Chargers	20.9	0	0	DD	ok	none obs.	
washdown	20.9	0	0	DD	ok	none obs.	
Storage Area	20.9	0	0	DD	ok	none obs.	
Kitchen	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 03892

2MSHA03520

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-12-07 SECTION/AREA General Mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 12:20 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 11:10 AM/PM END 12:34 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 12:15 AM/PM END 12:30 AM/PM Examiners Initials FM

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None	
Main North Haulage & Seals	20.9	0	0	BH	OK	None	
Main West Haulage & Seals	20.9	0	0	TC/BH	OK	none obs.	
3rd North Haulage	20.9	0	0	BH	OK	None	
1st Right	20.9	0	0	BH	OK	None	
Trans	20.9	0	0	TC/BH	OK	none obs.	
Chargers	20.9	0	0	TC/BH	OK	none obs.	
Wash Down	20.9	0	0	TC	OK	none obs.	
Storage Area	20.9	0	0	TC	OK	none obs	
Kitchen	20.9	0	0	BH	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS _____

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 8385
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03521

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-12-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 7:50 AM/PM END 7:45 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:00 AM/PM END 8:45 AM/PM Examiners Initials ZD
TIME OF EXAMINATION START 7 AM/PM END 8:35 AM/PM Examiners Initials dg

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	ok	none observed	
Main North seals haulage	21.0	0	0	SW	ok	none observed	
Main West seals haulage	20.9	0	0	dg/ZD	ok	none observed	
3rd North haulage	21.0	0	0	SW	ok	none observed	
1st Right	21.0	0	0	SW	ok	none observed	
Transformers	21.0	0	0	ZD/SW	ok	none observed	
chargers	21.0	0	0	ZD/SW	ok	none observed	
washdown	20.9	0	0	ZD	ok	none observed	
Storage Area	20.9	0	0	ZD	ok	none observed	
kitchen	20.9	0	0	dg	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9600
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03522

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-13-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 3:45 AM/PM END 5:15 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 3:30 AM/PM END 5:20 AM/PM Examiners Initials dy
TIME OF EXAMINATION START 3:00 AM/PM END 4:30 AM/PM Examiners Initials DB

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY Dale Black
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY Steve Wilson
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage SLAIS	21.0	0	0	SW	OK	none observed	
Main West haulage SLAIS	21.0	0	0	SW dy	OK	none observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	SW dy	OK	None observed	
chargers	21.0	0	0	SW dy	OK	None observed	
washdown	21.	0	0	dy	ok	None observed	
Storage Area.	21.0	0	0	SW	OK	none observed	
#7 Drive area	20.9	0	0	DB	ok	None observed	
#6 Drive area	20.9	0	0	DB	ok	" "	
Main West working area	20.9	0	0	DB	ok 42,887	" "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
MWest	Getting gray	Bulk dusted it
1/2 to 130		
1+2 entry		

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 7453
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 03892

2MSHA03523

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-13-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 12:20 AM/PM END 12:56 AM/PM Examiners Initials BP
TIME OF EXAMINATION START 11:20 AM/PM END 1:02 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 12:08 AM/PM END 12:45 AM/PM Examiners Initials FM

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	ok	none obs.	
main North Haulage + seals	20.9	0	0	TC/BP	OK	None obs.	
main West Haulage Seals	20.9	0	0	TC/BP BH	OK	none obs.	
3rd North Haulage Seals	20.9	0	0	FM	OK	None Observed	
1st Right Haulage	20.9	0	0	FM	OK	None Observed	
transformers	20.9	0	0	TC/BH BP	OK	none obs.	
Chargers	20.9	0	0	BH	OK	none obs.	
Wash down	20.9	0	0	BH	OK	none obs.	
Storage Areas	20.9	0	0	BH	OK	none obs.	
M.W. Piller Line	20.9	0	0	BH	OK	None Observed	
					OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at Time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 9599
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 8297

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03524

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-13-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 7:35 AM/PM END 9:15 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 710 AM/PM END 830 AM/PM Examiners Initials dy
TIME OF EXAMINATION START 7:10 AM/PM END 8:45 AM/PM Examiners Initials ZD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	ZD	ok	none observed	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	ZD	ok	none observed	
MAIN WEST HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	dy	ok	none observed	
1ST RIGHT HAULAGE	20.9	0	0	dy	ok	none observed	
TRANSFORMERS	20.9	0	0	dy/JG	ok	none observed	
CHARGERS	20.9	0	0	dy/JG	ok	none observed	
WASHDOWN	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE AREA	20.9	0	0	dy	ok	none observed	
MAIN WEST PILLAR LINE	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
X-CUT 88	EQUIPMENT BLOCKING	EQUIPMENT MOVED
	ESCAPEWAY	

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03525

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-14-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 3:10 AM/PM END 4:25 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 3 AM/PM END 440 AM/PM Examiners Initials dg
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	dg	ok	None observed	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	dg	ok	None observed	
MAIN WEST HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	.2	dg	ok	None observed	
1ST RIGHT HAULAGE	20.9	0	0	dg	ok	None observed	
TRANSFORMERS	20.9	0	0	dg/JG	ok	None observed	
CHARGERS	20.9	0	0	dg/JG	ok	None observed	
WASHDOWN	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE AREA	20.9	0	0	dg	ok	None observed	
MAIN WEST PILLAR LINE	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 7485
PRE-SHIFT/MINE EXAMINER _____ CERT. # 6622
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 03892

2MSHA03526

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-14-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:51 AM/PM END 1:16 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:45 AM/PM END 12:55 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 11:58 AM/PM END 1:00 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	Needs Dusted	working on Done CA 3/14/07
MAIN North Haulage Seals	20.9	0	0	FM	OK	None observed	
MAIN West Haulage Seals	20.9	0	0	FM/BH	OK	None Observed	
3rd North Haulage Seals	20.9	0	0	FM	OK	None observed	
1st Right Haulage	20.9	0	0	FM	OK	None observed	
TRANSFORMERS	20.9	0	0	~~FM~~ BH/TC	OK	None Observed	
Chargers	20.9	0	0	~~FM~~ BH/TC	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH/TC	OK	None Observed	
MAIN West PALAR Line	20.9	0	0	BH/TC	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Except as Noted above all area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINE _ CERT. # 8297
PRE-SHIFT/MINE EXAMINE _ CERT. # 8375
PRE-SHIFT/MINE EXAMINE _ CERT. # 9362
PRE-SHIFT/MINE EXAMINE _ CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 03892

2MSHA03527

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-14-07 SECTION/AREA GENERAL MINE / / /

TIME OF EXAMINATION START 7:30 AM/PM END 8:50 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 7 AM/PM END 8:15 AM/PM Examiners Initials dy
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	dy	ok	None observed	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	dy	ok	None observed	
MAIN WEST HAULAGE-SEALS	20.9	0	0	dy/JG	OK	SEE BELOW	SENT MEN TO CLEAR ROADWAYS
3RD NORTH HAULAGE-SEALS	20.9	0	.2	dy	ok	None observed	
1ST RIGHT HAULAGE	20.9	0	0	dy	ok	None observed	
WASHDOWN	20.9	0	0	JG	Ok	NONE OBSERVED	
STORAGE AREA	20.9	0	0	dy	ok	None observed	
TRANSFORMERS	20.9	0	0	dy/JG	Ok	NONE OBSERVED	
CHARGERS	20.9	0	0	dy/JG	Ok	NONE OBSERVED	
MAIN WEST PILLAR LINE	20.9	0	0	JG	Ok	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS MAIN WEST ROADWAYS HAVE ACCUMULATIONS, FROM MOVING EQUIPMENT, IN SEVERAL PLACES THAT NEEDS CLEANED "CLEANED, WATERED, & ROCKDUSTED ROADS"

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

2MSHA03528

COUNTER SIGNATURE Signature CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-15-07 SECTION/AREA GENERAL MINE

TIME OF EXAMINATION START 3:00 AM/PM END 4:15 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 3 AM/PM END 4:30 AM/PM Examiners Initials dg
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	dg	ok	None observed	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	dg	ok	None observed	
MAIN WEST HAULAGE-SEALS	20.9	0	0	dg/JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	dg	ok	None observed	
1ST RIGHT HAULAGE	20.9	0	0	dg	ok	None observed	
WASHDOWN	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE AREA	20.9	0	0	dg	ok	None observed	
TRANSFORMERS	20.9	0	0	dg/JG	ok	None observed	
CHARGERS	20.9	0	0	dg/JG	ok	None observed	
MAIN WEST PILLAR LINE	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
M West	Spots getting gray	Bulk dusted
#35 inby		& watered & drug
		roadways
		GA

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03529

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-15-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 12:01 AM/PM END 12:35 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 12:04 AM/PM END 12:35 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 12:05 AM/PM END 12:10 AM/PM Examiners Initials BP BH

EXAM. CALLED OUT ----- YES NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	none observed	
Main North Haulage Seals	20.9	0	0	FM	ok	none observed	
Main West Haulage & Seals	20.9	0	0	TC/BH	ok	None Observed	
320 North Haulage & seals	20.9	0	0	TC/BP	ok	none obs.	
1st Right Haulage	20.9	0	0	TC	ok	None obs.	
Washdown	20.9	0	0	BH	ok	None Observed	
Storage Area	20.9	0	0	BH	ok	None observed	
Transformers	20.9	0	0	FM/BH	ok	None Observed	
Chargers	20.9	0	0	BH	ok	None Observed	
Main West Pillar line	20.9	0	0	BH	ok	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362
PRE-SHIFT/MINE EXAMINER _ CERT. # 8297
PRE-SHIFT/MINE EXAMINER _ CERT. # 9599
PRE-SHIFT/MINE EXAMINER _ CERT. # 8395

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03530

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-15-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 7:25 AM/PM END 8:25 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 7 AM/PM END 8:15 AM/PM Examiners Initials dg
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	dg	ok	none observed	
MAIN NORTH HAULAGE - SEALS	20.9	0	0	dg	ok	none observed	
MAIN WEST HAULAGE - SEALS	20.9	0	0	dg/JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE - SEALS	20.9	0	0	dg	ok	none observed	
1ST RIGHT HAULAGE	20.9	0	0	dg	ok	none observed	
WASHDOWN	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE AREA	20.9	0	0	dg	ok	none observed	
TRANSFORMERS	20.9	0	0	dg/JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	dg/JG	OK	NONE OBSERVED	
MAIN WEST PILLAR LINE	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
X-CUT 107	SCOOP CHARGING STATION	ROCKDUSTED AREA
	NEEDED FLOOR DUSTED	

PRE-SHIFT REMARKS AREAS REASONABLY SAFE AT TIME OF EXAMINATION

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 7485
PRE-SHIFT/MINE EXAMINE CERT. # 6627
PRE-SHIFT/MINE EXAMINE CERT. # _____
PRE-SHIFT/MINE EXAMINE.. _____ CERT. # _____

Signature

COUNTER SIGNATURI ERT. # 7485

2MSHA03531

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-16-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 3:00 AM/PM END 4:05 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 3 AM/PM END 4:15 AM/PM Examiners Initials dy
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	dy	ok	none observed	
MAIN NORTH HAULAGE - SEALS	20.9	0	0	dy	ok	none observed	
MAIN WEST HAULAGE - SEALS	20.9	0	0	dy JG	Ok	LOOSE TOP AT 109 NEED ROCK DUST #1 ROADWAY 110-114	PRYED DOWN JG DUSTED JG
3RD NORTH HAULAGE - SEALS	20.9	0	.8	dy	ok	none observed	
1ST RIGHT HAULAGE	20.9	0	0	dy	ok	None observed	
WASHDOWN	20.9	0	0	JG	Ok	NONE OBSERVED	
STORAGE AREA	20.9	0	0	dy	ok	none observed	
TRANSFORMERS	20.9	0	0	dy JG	Ok	NONE OBSERVED	
CHARGERS	20.9	0	0	dy JG	Ok	NONE OBSERVED	
MAIN WEST PILLARLINE	20.9	0	0	JG	Ok	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 8468

2MSHA03532

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-16-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 12:00 AM/PM END 12:40 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:15 AM/PM END 12:45 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 1200 AM/PM END 1250 AM/PM Examiners Initials DD / km

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	none observed	
MAIN North haulage seals	20.9	0	0	FM	ok	none observed	
MAIN West haulage seals	20.9	0	0	mc	ok	none observed	
3rd North haulage seals	20.9	0	0	DD/km	ok	none obs	
1st Right haulage	20.9	0	0	DD/km	ok	none obs.	
TRANSFormers	20.9	0	0	mc	ok	none observed	
Chargers	20.9	0	0	mc/km	ok	none observed	
Washdown	20.9	0	0	mc	ok	none observed	
storage Area	20.9	0	0	mc	ok	none observed	
MAIN West Pillar line	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at Time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 8379

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03533

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-16-07 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 7:00 AM/PM END 935 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	KK	OK	None obs.	
Main North Haulage & Seals	20.9	0	0	LR/KK	OK	None obs.	
Main West Haulage & Seals	20.9	0	0	LR	OK	None obs.	
3rd North Haulage & Seals	20.9	0	0	KK	OK	None obs.	
1st Right Haulage	20.9	0	0	KK	OK	None obs.	
Wash down	20.9	0	0	LR	OK	None obs	
Storage Area	20.9	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	LR/KK	OK	None obs.	
Chargers	20.9	0	0	LR/KK	OK	None obs.	
Main West Pillar Line	20.9	0	0	LR	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam.

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # 1954
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATU CERT. # 4735

2MSHA03534

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-17-07 SECTION/AREA Gen. Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 530 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs.	
Main North Haulage & Seals	20.9	0	0	LR/KK	OK	None obs.	
Main West Haulage & Seals	20.9	0	0	LR/KK	OK	None obs.	
3rd North Haulage & Seals	20.9	0	0	LR/KK	OK	None obs.	
1st Right Haulage	20.9	0	0	LR	OK	None obs.	
Washdown	20.9	0	0	KK	OK	None obs.	
Storage Area	20.9	0	0	KK	OK	None obs.	
Trans Formers	20.9	0	0	LR/KK	OK	None obs.	
Chargers	20.9	0	0	LR/KK	OK	None obs.	
Main West Pillar Line	20.9	0	0	KK	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # 7954
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE ____ CERT. # 8462

2MSHA03535

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-17-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:20 AM/PM END 12:05 AM/PM Examiners Initials JM
TIME OF EXAMINATION START 11:00 AM/PM END 12:19 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 11:15 AM/PM END 11:39 AM/PM Examiners Initials MC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	DD	ok	none obs.	
main north Haulage & Seals	20.9	0	0	DD	ok	none obs.	
main west Haulage & Seals	20.9	0	0	DD/[illegible]	ok	none obs.	
3rd North Haulage & Seals	20.9	0	0	mc	ok	none observed	
1st Right Haulage	20.9	0	0	mc	OK	none observed	
wash down	20.9	0	0	DD	ok	none obs.	
Storage area	20.9	0	0	DD	ok	none obs.	
Trans.	20.9	0	0	DD/[illegible]	ok	none obs.	
chargers	20.9	0	0	DD/[illegible]	ok	none obs.	
main West Pillar Line	20.9	0	0	[illegible]	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Vent 93 intak	deep water	Pumped

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 9329
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR Signature CERT. # 8462

2MSHA03536

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3.17.07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 7:00 AM/PM END 915 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	none obs.	
Bottom mains seals	20.9	0	0	KK/LR	OK	none obs.	
Haulage seals Main West	20.9	0	0	LR	OK	None obs.	
2nd North Haulage seals	20.9	0	0	KK	OK	none obs.	
1st right	20.9	0	0	KK	OK	none obs.	
Washdown	20.9	0	0	LR	OK	None obs.	
Storage area	20.9	0	0	LR	OK	None obs.	
Trans.	20.9	0	0	LR/KK	OK	none obs.	
chargers	20.9	0	0	LR/KK	OK	none obs.	
Main West Pillar line	20.9	0	0	LR			

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 4135

2MSHA03537

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-18-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 300 AM/PM END 530 AM/PM Examiners Initials KK/LR
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	KK	OK	none obs.	
M. North seals Haulage	20.9	0	0	KK/LR	OK	none obs	
M. West seals Haulage	20.9	0	0	KK	OK	none obs	
3rd North seals Haulage	20.9	0	0	LR	OK	None obs	
1st Right.	20.9	0	0	LR	OK	None obs	
Washdown	20.9	0	0	KK	OK	none obs	
Storage area	20.9	0	0	KK	OK	none obs.	
Trans.	20.9	0	0	KK/LR	OK	None obs	
chargers	20.9	0	0	LR/KK	OK	None obs	
main west pillar line	20.9	0	0	KK	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINE ____ CERT. # 7954
PRE-SHIFT/MINE EXAMINE ____ CERT. # 4375
PRE-SHIFT/MINE EXAMINE.. ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03538

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-18-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:00 AM/PM END 11:40 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 11:50 AM/PM END 1:06 AM/PM Examiners Initials mc
TIME OF EXAMINATION START 1100 AM/PM END 1215 AM/PM Examiners Initials DD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	none observed	
main North Haulage & Scale	20.9	0	0	MC	OK	none observed	
Main West Haulage Scale	20.9	0	0	MC/KM	OK	none observed	
1st right haulage	20.9	0	0	DD	ok	none obs.	
wash-down	20.9	0	0	MC	OK	none observed	
Storage area	20.9	0	0	MC	OK	none observed	
transformer	20.9	0	0	MC/KM	OK	none observed	
chargers	20.9	0	0	KM/DD	OK	none observed	
Main West Bifor	20.9	0	0	KM	OK	None Observed	
3rd North Haulage Scales	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
MAINWEST 4B-31	Deep WATER	Pumped 3-18-07 mc

PRE-SHIFT REMARKS All Areas Safe At time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATUR CERT. # 8462

2MSHA03539

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-18-07 SECTION/AREA [illegible] / / /

TIME OF EXAMINATION START 7.40 AM/PM END 900 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 830 AM/PM END 1000 AM/PM Examiners Initials RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
portal area	20.9	0	0	RL	OK	none	
main West Haulage	20.9	0	0	RL	OK	none	
M. West Haulage Beat	20.9	0	0	KK	OK	none obs	
M. West Haulage Beat	20.9	0	0	RL	OK	none	
Pump	20.9	0	0	RL	OK	none	
Storage area	20.9	0	0	RL	OK	none	
Washdown	20.9	0	0	KK	OK	none obs	
Trans.	20.9	0	0	KK/RL	OK	none obs	
chargers	20.9	0	0	RL/KK	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS _____

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATUI CERT. # 4735

2MSHA03540

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-19-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 3:40 AM/PM END 4:50 AM/PM Examiners Initials KK
TIME OF EXAMINATION START 800 AM/PM END 420 AM/PM Examiners Initials RL
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	ok	none obs	
M. North Haulage seal	20.9	0	0	KK	ok	none obs	
M. West Haulage seal	20.9	ok	ok	RL	ok	none	
3 North East seal	20.9	0	0	KK	ok	none obs.	
5th Right	20.9	0	0	KK	ok	none obs	
Storage area	20.9	ok	ok	RL	ok	none	
Washdown	20.9	ok	ok	RL	ok	none	
Trucks	20.9	0	0	KK/RL	ok	none	
chargers	20.9	0	0	KK/RL	ok	none	
Beet Kitchen	20.9	0	0	KK	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of EXAM

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 7954
PRE-SHIFT/MINE EXAMINER ____ CERT. # 6480
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 05892

2MSHA03541

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-19-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 12:02 AM/PM END 12:40 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 12:00 AM/PM END 12:37 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 11:00 AM/PM END 1:07 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	none observed	
main north haulage seals	20.9	0	0	BH	ok	None Observed	
main west haulage seals	20.9	0	0	BH	ok	None Observed	
3rd North haulage seals	20.9	0	0	TC	ok	none obs.	
1st Right haulage	20.9	0	0	TC	ok	none obs.	
storage Area	20.9	0	0	BH	ok	None Observed	
wash down	20.9	0	0	BH	ok	None Observed	
transformers	20.9	0	0	TC/BH	ok	None Observed	
Chargers	20.9	0	0	TC/BH	ok	None Observed	
main west Pitter line North Area	20.9	0	0	BH	ok	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 03892

2MSHA03542

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3/9/07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 7 AM/PM END 8:20 AM/PM Examiners Initials dg
TIME OF EXAMINATION START 7:15 AM/PM END 8:35 AM/PM Examiners Initials JG
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
U6 Parking	20.9	0	0	dg	ok	None observed	
Main N0 Seals Roadway	20.9	0	0	dg	ok	None observed	
Main Seals Pumps West Roadways	20.9	0	0	dg/JG	OK	NONE OBSERVED	
3rd N0 Seals Roadway	20.9	0	0	dg	ok	None observed	
1ST Right Haulage	20.9	0	0	dg	ok	None observed	
STORage area	20.9	0	0	dg	ok	None observed	
wash down	20.9	0	0	JG	OK	NONE OBSERVED	
Transformers	20.9	0	0	dg/JG	ok	ACCUMULATIONS 114 NEXT TO POWER CENTER	SENT MEMO TO CLEANUP DONE JC
Chargers	20.9	0	0	dg/JG	OK	NONE OBSERVED	
Main West Pipeline	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS REPORTED REASONARLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 7485
PRE-SHIFT/MINE EXAMINER CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

2MSHA03543

COUNTER SIGNATURE Signature CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-20-07 SECTION/AREA GENERAL MINES

TIME OF EXAMINATION START 3:05 AM/PM END 4:30 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 3 AM/PM END 4:15 AM/PM Examiners Initials dy
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	dy	ok	None observed	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	dy	ok	None observed	
3RD NORTH HAULAGE-SEALS	20.9	0	.1	dy	ok	None observed	
MAIN WEST HAULAGE-SEALS	20.9	0	0	dy/JG	Ok	OIL CANS/ OIL AT SO. MAINS POWER CENTER	Sending man to clean.
1ST RIGHT HAULAGE	20.9	0	0	dy	ok	None observed	Done @ 3 2007
STORAGE AREA	20.9	0	0	dy	ok	None observed	
WASHDOWN	20.9	0	0	JG	Ok	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	dy/JG	Ok	NONE OBSERVED	
CHARGERS	20.9	0	0	dy/JG	Ok	NONE OBSERVED	
MAIN WEST PILLAR SEAL AREA	20.9	0	0	JG	Ok	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main West Int.	Getting Gray	Bulk dusted it
40 to 0		

PRE-SHIFT REMARKS OIL & OIL CANS LEFT IN BUCKET OF GEHL AT SO. MAINS POWER CENTER AREA

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 63892

2MSHA03544

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-20-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:26 AM/PM END 12:47 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 12:01 AM/PM END 12:59 AM/PM Examiners Initials TC/BP
TIME OF EXAMINATION START 12:30 AM/PM END 12:50 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	none observed	
Main North Haulage Seals	20.9	0	0	FM	ok	none observed	
Main West Haulage Seals	20.9	0	0	BH	ok	None Observed	
3rd North Haulage Seals	20.9	0	0	TC/BP	ok	none obs.	
1st Right Haulage	20.9	0	0	BP	ok	none obs	
Tranformers	20.9	0	0	BH/FM	ok	None Observed	
Chargers	20.9	0	0	BH	ok	None Observed	
Washdown	20.9	0	0	BH	ok	None Observed	
Storage Area	20.9	0	0	BH	ok	None Observed	
Main West pillerline Seal Area	20.9	0	0	BH	ok	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared Reasonably Safe At Time Of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 9399

Signature

COUNTER SIGNATURE _ CERT. # 03892

2MSHA03545

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-20-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 7:50 AM/PM END 8:45 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 8:00 AM/PM END 8:40 AM/PM Examiners Initials JD
TIME OF EXAMINATION START 7:45 AM/PM END 9 AM/PM Examiners Initials dg

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North SEALS haulage	20.9	0	0	~~SW~~ JD	OK	none observed	
3rd North SEALS haulage	20.9	0	0	~~SW~~ JD	OK	none observed	
Main West SEALS haulage	20.9	0	0	~~SW~~ dg	OK	Oil accumulations HS Seal 118 X cut	SENT MEN TO DUST CLEAN - DONE JG
1st Right haulage	20.9	0	0	SW	OK	none observed	
Storage Area	20.9	0	0	SW	OK	none observed	
wash down	20.9	0	0	dg	ok	None observed	
Transformers	20.9	0	0	~~SW~~ dg	OK	None observed	
chargers	20.9	0	0	dg	ok	None observed	
Main West SEALS pillarline	20.9	0	0	dg	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift (except what is noted above)

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
PRE-SHIFT/MINE EXAMINER _____ CERT. # 9660
PRE-SHIFT/MINE EXAMINER _____ CERT. # 6622
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03546

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-21-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 3:55 AM/PM END 5:10 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 4:00 AM/PM END 4:50 AM/PM Examiners Initials ZR
TIME OF EXAMINATION START 3:35 AM/PM END 5:25 AM/PM Examiners Initials dy

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area.	21.0	0	0	SW	OK	none observed	
Main North SEALS haulage	21.0	0	0.3	ZR SW	OK	None observed	
3rd North SEALS haulage	21.0	0	0	ZR SW	OK	None observed	
Main West haulage SEALS	21.0	0	0	dy SW	OK	None observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	20.9	0	0	dy	OK	None observed	
Transformers	21.0	0	0	dy SW	OK	None observed	
Chargers	20.9	0	.1	dy	ok	None observed	
Main West SEALS pillar line	20.9	0	0	dy	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas Examined appear safe at Time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03547

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-21-07 SECTION/AREA Gen Min 01

TIME OF EXAMINATION START 12:02 AM/PM END 1:15 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:55 AM/PM END 1:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 12:01 AM/PM END 1:00 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
MAIN North haulage seals	20.9	0	0	FM	OK	None observed	
MAIN West haulage seals	20.9	0	0	FM BH/TC	OK	None Observed	
3rd North haulage seals	20.9	0	0	FM	OK	None observed	
1st Right haulage	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	BH/TC	OK	None Observed	
Chargers	20.9	0	0	BH/TC	OK	None Observed	
Storage Area	20.9	0	0	BH/TC	OK	None Observed	
MAIN West pillar line seals	20.9	0	0	BH/TC	OK	None Observed	
Washdown	20.9	0	0	TC	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINE _____ CERT. # 8297
PRE-SHIFT/MINE EXAMINE _____ CERT. # 8395
PRE-SHIFT/MINE EXAMINE _____ CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

2MSHA03548

Signature

COUNTER SIGNATURE _____ CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-21-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 8:00 AM/PM END 8:40 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 7:40 AM/PM END 8:50 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 745 AM/PM END 9 AM/PM Examiners Initials dy

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	.0	SW	ok	none observed	
Main North Haulage seals	20.9	0	0	LD/SW	ok	none observed	
Main West Haulage seals	21.0	0	0.3	dy/SW	ok	None observed	
3rd Nth Haulage seals	20.9	0	0	LD/SW	ok	none observed	
1st Right haulage	21.0	0	0	SW	ok	none observed	
transformers	21.0	0	0	dy/SW	ok	None observed	
chargers	20.9	0	0	LD/dy	ok	None observed	
Storage area	21.0	0	0	SW	ok	none observed	
Main West pillerline	20.9	0	.1	dy	ok	None observed	
wash down	20.9	0	0	dy	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
3rd North	timber knocked out	replaced timber

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03549

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-22-07 SECTION/AREA General / Mine / / /

TIME OF EXAMINATION START 3:50 AM/PM END 5:30 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 4:05 AM/PM END 4:50 AM/PM Examiners Initials SD
TIME OF EXAMINATION START 3:40 AM/PM END 5:15 AM/PM Examiners Initials dg

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North Seals haulage	21.0	0	0	SD SW	OK	none observed	
Main West haulage Seals	21.0	0	0.2	SW dg	OK	None observed	
3rd North Seals haulage	21.0	0	0	SD SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers.	21.0	0	0	dg SW	OK	None observed	
chargers	20.9	0	0	SD/dg	ok	None observed	
Storage Area.	21.0	0	0	SW	OK	none observed	
Main West pillars Seals	20.9	0	0	dg	ok	None observed	
wash down	20.9	0	0	dg	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main No. Haulage	Getting Gray	Bulk dusted it

PRE-SHIFT REMARKS All areas examined appear safe at time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. # 6632
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE _ CERT. # 03892 2MSHA03550

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-22-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 11:00 AM/PM END 12:15 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 11:50 AM/PM END 1:00 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:00 AM/PM END 12:35 AM/PM Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OC	none observed	
Main north seals & haulage	20.9	0	0	FM	OC	none observed	
Main West Seals & Haulage	20.9	0	0	TC/FM/BH	OC	none obs.	
3RD North Seals & haulage	20.9	0	0	FM	OC	none observed	
1st Right Haulage	20.9	0	0	FM	OC	none observed	
Transformers	20.9	0	0	TC/FM/BH	OC	none obs.	
Chargers	20.9	0	0	TC/FM/BH	OC	none obs.	
Storage Area	20.9	0	0	TC	OC	none obs.	
Main West Pillars & seals	20.9	0	0	TC/BH	OC	none obs.	
Washdown	20.9	0	0	BH	OC	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03551

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-22-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:50 AM/PM END 8:40 AM/PM Examiners Initials LD
TIME OF EXAMINATION START 7:40 AM/PM END 8:50 AM/PM Examiners Initials SW
TIME OF EXAMINATION START 7:40 AM/PM END 8:55 AM/PM Examiners Initials dg

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	ok	none observed	
Main North Seals Haulage	20.9	0	0	LD/SW	ok	Bad Brow #14 Seal	went to set timber done LD 3-23-07
Main West Seals Haulage	21.0	0	0.5	SW dg	ok	None observed	
3rd North Seals Haulage	20.9	0	0	LD/SW	ok	none observed	
1st Right Haulage	21.0	0	0	SW	ok	none observed	
transformers	21.0	0	0	SW	ok	None observed	
chargers	20.9	0	0	LD/dg	ok	None observed	
storag Area	21.0	0	0	SW	ok	none observed	
main west seals pickers	20.9	0	.2	dg	ok	None observed	
wash down	20.9	0	0	dg	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
X-cut 40	need dust transfer room	dusted

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift except what is noted above

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9660
PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03552

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 32307 SECTION/AREA Gen / Mine / / /

TIME OF EXAMINATION START 340 AM/PM END 515 AM/PM Examiners Initials dy
TIME OF EXAMINATION START 4:08 AM/PM END 4:55 AM/PM Examiners Initials ZD
TIME OF EXAMINATION START 3:55 AM/PM END 5:10 AM/PM Examiners Initials SW

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
46 Parking	21.0	0	0	SW	ok	none observed	
Main North Seals Haulage	20.9	0	0	ZD/SW	ok	none observed	
Main Seals Pumps West Haulage	20.9	0	.4	dy/SW	ok	none observed	
3rd No Seals Haulage	20.9	0	0	ZD/SW	ok	none observed	
1st Right Haulage	21.0	0	0	SW	ok	none observed	
Transformers	20.9	0	0	dy/SW	ok	none observed	
Chargers	20.9	0	0	dy/ZD	ok	none observed	
Storage areas	21.0	0	0	SW	ok	none observed	
Main West Pillarline	20.9	0	.1	dy	ok	none observed	
Washdown	20.9	0	0	dy	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe to travel and work at time of exam.

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 6622
PRE-SHIFT/MINE EXAMINER CERT. # 9620
PRE-SHIFT/MINE EXAMINER CERT. # 9548
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATUR CERT. # 4735

2MSHA03553

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-23-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:54 AM/PM END 12:33 AM/PM Examiners Initials FM
TIME OF EXAMINATION START 11:55 AM/PM END 12:15 AM/PM Examiners Initials Km
TIME OF EXAMINATION START 1100 AM/PM END 109 AM/PM Examiners Initials DD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	ok	None observed	
MAIN North haulage seals	20.9	0	0	FM	ok	None observed	
MAIN West haulage seals	20.9	0	0	DD	ok	none observed	
3rd North haulage seals	20.9	0	0	Km	ok	none observed	
1st RIGHT Haulage	20.9	0	0	Km	ok	none observed	
TRANSFORMERS	20.9	0	0	FM/DD	ok	none obs.	
Chargers	20.9	0	0	DD	ok	none obs.	
Wash down	20.9	0	0	DD	ok	none obs.	
storage Area	20.9	0	0	DD	ok	none obs.	
MAIN West Pillar line seals	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # 9379
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03554

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-23-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 830 AM/PM END 858 AM/PM Examiners Initials RC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	RC	ok	none observed	
Main North Haulage Seals	21	0	0	RC	ok	none "	
Main West Haulage Seals	20.9	0	0	KK/LR	ok	none obs	
3rd North Haulage Seals	20.9	0	0	KK	ok	none obs	
1st Right Haulage	20.9	0	0	KK	ok	none obs	
Transformers	20.9	0	0	RH/LR/KK	ok	none obs	
Chargers	20.9	0	0	LR/KK	ok	none obs	
Washdown	20.9	0	0	KK	ok	none obs.	
Storage Area	20.9	0	0	KK	ok	none obs.	
Main West Pitterline Seals	20.9	0	0	KK/LR	ok	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 1957
PRE-SHIFT/MINE EXAMINER CERT. # 4373
PRE-SHIFT/MINE EXAMINER CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 8962

2MSHA03555

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-24-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 300 AM/PM END 515 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START 400 AM/PM END 430 AM/PM Examiners Initials RL
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	RL	OK	None obs.	
Main North Haulage seals	20.9	0	0	RL	OK	None obs.	
Mains West Haulage seals	20.9	0	0	LR/KK	OK	None obs.	
3rd North Haulage & seals	20.9	0	0	LR/KK	OK	None obs.	
1st Right Haulage	20.9	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	LR/KK	OK	None obs.	
Chargers	20.9	0	0	LR/KK	OK	None obs.	
Washdown	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	KK	OK	None obs.	
Mains West Seals Pillar Area	20.9	0	0	LR/KK	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4325
PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 6801
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATU _____ CERT. # 4736

2MSHA03556

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-24-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 1100 AM/PM END 1145 AM/PM Examiners Initials DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	ok	none obs.	
Main North haulage seals	20.9	0	0	DD	ok	none obs.	
Main West haulage seals	20.9	0	0	KM/DD	OK	none observed	
3rd North haulage seals	20.9	0	0	KM	OK	none observed	
1st right haulage	20.9	0	0	KM	OK	none observed	
transformers	20.9	0	0	KM/DD	OK	none observed	
chargers	20.9	0	0	KM	OK	none observed	
Washdown	20.9	0	0	KM	OK	none observed	
storage Area	20.9	0	0	KM	OK	none observed	
Main West seals pillarline	20.9	0	0	KM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 9379
PRE-SHIFT/MINE EXAMINE CERT. # 8058
PRE-SHIFT/MINE EXAMINE CERT. # _____
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATUF ERT. # 8462

2MSHA03557

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-24-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 700 AM/PM END 815 AM/PM Examiners Initials LR
TIME OF EXAMINATION START 200 AM/PM END 957 AM/PM Examiners Initials KK/RL
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs.	
Main North Haulage Seals	20.9	0	0	LR	OK	None obs.	
Main West Haulage Seals	20.9	0	0	RL/KK	OK	none obs	
3rd North Haulage Seals	20.9	0	0	RL	OK	none obs	
1st Right Haulage	20.9	0	0	RL	OK	none obs	
Trans Sponners	20.9	0	0	LR/KK/RL	OK	none obs	
Chargers	20.9	0	0	RL/KK	OK	none obs	
Washdown Area	20.9	0	0	RL	OK	none obs	
Storage Area	20.9	0	0	KK	OK	none obs	
Main West Seals & Pillar Line	20.9	0	0	KK/RL	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 7964
PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 8462 2MSHA03558

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-24-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 325 AM/PM END 350 AM/PM Examiners Initials LR
TIME OF EXAMINATION START 300 AM/PM END 540 AM/PM Examiners Initials KK/RL
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None obs-	
Main North Haulage Seals	20.9	0	0	LR	OK	None obs-	
Main West Haulage Seals	20.9	Ø	Ø	RL/KK	OK	none observed	
3rd North Haulage Seals	20.9	Ø	Ø	RL	OK	none "	
1st Right Haulage	20.9	Ø	Ø	RL	OK	none "	
Transformers	20.9	Ø	Ø	LR/RL/RK	OK	none "	
Chargers	20.9	Ø	Ø	RL/KK	OK	none "	
Washdown Area	20.9	Ø	Ø	RL	OK	none "	
Storage Area	20.9	Ø	Ø	KK	OK	none "	
Main West Seals & Pillow Line	20.9	Ø	Ø	KK/RL	OK	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # 6401
PRE-SHIFT/MINE EXAMINER ____ CERT. # 7954
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 4735

2MSHA03559

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-25-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 1130 AM/PM END 1240 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 11:00 AM/PM END 11:20 AM/PM Examiners Initials KM
TIME OF EXAMINATION START 11:51 AM/PM END 12:45 AM/PM Examiners Initials mc

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	OK	None observed	
Main North Haulage/seals	20.9	0	0	mc	OK	none observed	
Main West Haulage Seals	20.9	0	0	DD	ok	none observed	
3rd North Haulage Seals	20.9	0	0	DD	ok	none observed	
1st Right Haulage	20.9	0	0	DD	ok	none observed	
Transformers	20.9	0	0	DD/KM	ok	none observed	
Chargers	20.9	0	0	DD/KM	ok	none observed	
Wash Area	20.9	0	0	KM	OK	None obs.	
Storage Area	20.9	0	0	DD	ok	none observed	
Main West Seals Pillarline	20.9	0	0	KM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at the time of exa

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 8058
PRE-SHIFT/MINE EXAMINE CERT. # 9379
PRE-SHIFT/MINE EXAMINE CERT. # 7325
PRE-SHIFT/MINE EXAMINE CERT. # _____

Signature

COUNTER SIGNATU CERT. # 8462

2MSHA03560

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-25-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 700 AM/PM END 958 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK/LR	α	none obs.	
M. North Haulage seals	20.9	0	0	KK	α	none obs	
M. West Haulage seals	20.9	0	0	LR/KK	α	none obs.	
3rd North Haulage seals	20.9	0	0	KK	α	none obs	
1st Right Haulage	20.9	0	0	KK	α	none obs.	
Trans.	20.9	0	0	KK/LR	α	none obs.	
chargers	20.9	0	0	KK/LR	α	none obs	
Waselcrown	20.9	0	0	KK	α	none obs	
Storage area	20.9	0	0	KK	α	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 7954
PRE-SHIFT/MINE EXAMINER ____ CERT. # 4375
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATUR ____ CERT. # 8462

2MSHA03561

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-26-07 SECTION/AREA Gen. Mine / /

TIME OF EXAMINATION START 3:00 AM/PM END 5:35 AM/PM Examiners Initials LR/RL
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR/RL	OK	None obs.	
Main North Haulage & Seals	20.9	0	0	LR	OK	None	
Main West Haulage Seals	20.9	0	0	LR/RL	OK	None	
3rd North Haulage & Seals	20.9	0	0	LR	OK	None	
1st Right Haulage	20.9	0	0	LR	OK	None	
Transformers	20.9	0	0	LR/RL	OK	None	
Chargers	20.9	0	0	LR	OK	None	
Washdown Area	20.9	0	0	LR	OK	None	
Storage Area	20.9	0	0	LR	OK	None	
Main West Seals	20.9	0	0	LR/RL	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at Time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # 6486
PRE-SHIFT/MINE EXAMINER CERT. # ____
PRE-SHIFT/MINE EXAMINER CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03562

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-26-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:38 AM/PM END 1:15 AM/PM Examiners Initials mc/Fm
TIME OF EXAMINATION START 11:45 AM/PM END 12:55 AM/PM Examiners Initials DD
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY REPORT RECEIVED BY
CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc/Fm	ok	none observed	
main north Haulage seals	20.9	0	0	mc/Fm	ok	none observed	
main west Haulage seals	20.9	0	0	mc/Fm	ok	none observed	
3rd north Haulage seals	20.9	0	0	DD	ok	none obs.	
1st Right Haulage	20.9	0	0	DD	ok	none obs.	
Transformers	20.9	0	0	mc/Fm DD	ok	none observed	
chargers	20.9	0	0	mc/Fm DD	ok	none observed	
washdown	20.9	0	0	Fm	ok	none observed	
storage Area	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
X cut @ main west	Exposed Roof	set Timber

PRE-SHIFT REMARKS All Areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 8297
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 8925

2MSHA03563

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-26-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 7:45 AM/PM END 9:10 AM/PM Examiners Initials JR
TIME OF EXAMINATION START 7:46 AM/PM END 9:22 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 7:40 AM/PM END 9:13 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main north Haulage & Seals	20.9	0	0	BH	OK	None observed	
Main West Haulage & Seals	20.9	0	0	TC/BH BP	OK	None obs	
3rd north Haulage & Seals	20.9	0	0	BH	OK	None Observed	
1st Right haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	TC/BP BH	OK	None obs.	
Chargers	20.9	0	0	BH	OK	None observed	
Washdown	20.9	0	0	TC/BH	OK	none obs.	
Storage Area	20.9	0	0	TC/BH	OK	none obs	
Main west Seals	20.9	0	0	TC/BP	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 9599
PRE-SHIFT/MINE EXAMINER CERT. # _____

2MSHA03564

Signature

COUNTER SIGNATURE CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-27-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 3:45 AM/PM END 5:10 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 3:40 AM/PM END 5:10 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 3:43 AM/PM END 5:15 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH/TC/BP	OK	none obs.	
3rd North Haulage seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/TC/BP	OK	none obs.	
Chargers	20.9	0	0	BH/BP/TC	OK	none obs.	
Washdown	20.9	0	0	TC	OK	none obs.	
Storage Area	20.9	0	0	TC	OK	none obs.	
Main West Seals work area	20.9	0	0	TC/BP	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All AREAS APPEARED SAFE AT TIME OF EXAM

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8395
PRE-SHIFT/MINE EXAMINER _ CERT. # 9362
PRE-SHIFT/MINE EXAMINER _ CERT. # 9399
PRE-SHIFT/MINE EXAMINER _ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03565

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-27-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 11:00 AM/PM END 1:30 AM/PM Examiners Initials mc/fm
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc/fm	ok	none observed	
main North Haulage seals	20.9	0	0	mc/fm	ok	none observed	
main west Haulage seals	20.9	0	0	mc/fm	ok	none observed	
3rd North Haulage seals	20.9	0	0	mc/fm	ok	none observed	
1st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	mc/fm	ok	none observed	
chargers	20.9	0	0	mc	ok	none observed	
washdown	20.9	0	0	Fm	ok	none observed	
Storage Area	20.9	0	0	mc	ok	none observed	
main west seals work Area	20.9	0	0	mc/fm	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at Time of preshift

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 7375
PRE-SHIFT/MINE EXAMINER ____ CERT. # 8297
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 7488

2MSHA03566

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-27-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 7:58 AM/PM END 9:35 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 8:30 AM/PM END 9:05 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 8:20 AM/PM END 8:47 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
main west Haulage Seals	20.9	0	0	BH/TC BP	OK	none obs.	
3rd North Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/TC BP	OK	none obs.	
Chargers	20.9	0	0	BH/TC BP	OK	none obs.	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	
main wests Seals workarea	20.9	0	0	BP/TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas seemed safe At time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 8367
PRE-SHIFT/MINE EXAMINER CERT. # 8399
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 03892

2MSHA03567

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-28-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 4:15 AM/PM END 5:20 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 3:47 AM/PM END 5:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 4:00 AM/PM END 4:43 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	TC/BP BH	OK	none obs.	
3RD North ~~Haulage Seals~~	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	TC/BP BH	OK	None obs.	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	
Main West Seals Work Area	20.9	0	0	TC BP	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
XC 107 Trans	Garbage and Trash	Cleaned
	Evaporator in kitchen	3-28-07 BP/TC

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINE Signature CERT. # 9367
PRE-SHIFT/MINE EXAMINE CERT. # 8395
PRE-SHIFT/MINE EXAMINE CERT. # 9599
PRE-SHIFT/MINE EXAMINE _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 1485

2MSHA03568

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3.28.07 SECTION/AREA Gen MINe / / /

TIME OF EXAMINATION START 11:00 AM/PM END 12:57 AM/PM Examiners Initials FM-MC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____ REPORT RECEIVED BY ____
CALLED OUT BY ____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	209	0	0	FM	ok	none observed	
MAIN North haulage - seals	209	0	0	FM	ok	none observed	
MAIN West haulage - seals	209	0	0	FM/MC	ok	none observed	
3rd North haulage seals	209	0	0	FM/MC	ok	none observed	
1st Right haulage	209	0	0	MC	ok	none observed	
Transformers	209	0	0	FM/MC	ok	none observed	
Chargers	209	0	0	FM/MC	ok	none observed	
Washdown	209	0	0	MC	ok	none observed	
Storage Area	209	0	0	MC	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER ____ CERT. # 8297
PRE-SHIFT/MINE EXAMINER ____ CERT. # 7875
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03569

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-28-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 8:31 AM/PM END 9:15 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 7:47 AM/PM END 9:22 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage & Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage & Seals	20.9	0	0	TC/BP BH	OK	None Observed	
3RD North Haulage & Seals	20.9	0	0	BH	OK	None Observed	
1ST Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	TC/BP BH	OK	None Observed	
Chargers	20.9	0	0	BP/BH	OK	None Observed	
Wash Down	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9360
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03570

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-29-07 SECTION/AREA Gen mode / /

TIME OF EXAMINATION START 4:30 AM/PM END 4:50 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 3:44 AM/PM END 5:15 AM/PM Examiners Initials BH
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage & Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage & Seals	20.9	0	0	TC/BH	OK	None obs.	
3RD North Haulage & Seals	20.9	0	0	BH	OK	None Observed	
1ST Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	TC/BH	OK	None obs.	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 9362
PRE-SHIFT/MINE EXAMINER _____ CERT. # 8395
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 7485

2MSHA03571

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-29-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 11:30 AM/PM END 12:45 AM/PM Examiners Initials JG
TIME OF EXAMINATION START 11:05 AM/PM END 12 AM/PM Examiners Initials dg
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	dg/JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	dg/JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	dg/JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	dg	OK	NONE OBSERVED	
STORAGE AREA	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS REASONABLY SAFE AT TIME OF EXAMINATION

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 7485
PRE-SHIFT/MINE EXAMINER _____ CERT. # 6622
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 7485

2MSHA03572

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-29-07 SECTION/AREA Gen mine / / /

TIME OF EXAMINATION START 7:48 AM/PM END 9:15 AM/PM Examiners Initials BH
TIME OF EXAMINATION START 7:50 AM/PM END 8:00 AM/PM Examiners Initials BD
TIME OF EXAMINATION START 7:07 AM/PM END 7:36 AM/PM Examiners Initials TC

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____ REPORT RECEIVED BY _____
CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH/TC BP	OK	None Observed	
3rd North Haulage Seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/TC BP	OK	None Observed	
Chargers	20.9	0	0	BH/TC BP	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at Time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. # 9367
PRE-SHIFT/MINE EXAMINER CERT. # 9399
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 03492

2MSHA03573

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-30-07 SECTION/AREA Genmine / /

TIME OF EXAMINATION START 4:00 AM/PM END 4:46 AM/PM Examiners Initials TC
TIME OF EXAMINATION START 3:47 AM/PM END 5:20 AM/PM Examiners Initials BH
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage & Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage & Seals	20.9	0	0	TC/BH	OK	none obs.	
3RD North Haulage & Seals	20.9	0	0	BH	OK	None Observed	
1ST Right Haulage	20.9	0	0	BH	OK	None Observed	
Trans	20.9	0	0	TC/BH	ok	none obs	
Chargers	20.9	0	0	TC/BH	ok	none obs	
Wash Down	20.9	0	0	BH	OK	None Observed	
Storage	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362
PRE-SHIFT/MINE EXAMINER CERT. # 8395
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATU CERT. # [illegible]

2MSHA03574

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-30-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11:15 AM/PM END 420 AM/PM Examiners Initials LR/KK
TIME OF EXAMINATION START 1230 AM/PM END 130 AM/PM Examiners Initials RC
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	RC	OK	none observed	
M. South Haulage Seals	20.9	0	0	RC	OK	none "	
M. West Haulage Seals	20.9	0	0	KK/LR	OK	none obs	
3rd North	20.9	0	0	RC	OK	none observed	
4th Right	20.9	0	0	RC	OK	none observed	
Trans.	20.9	0	0	KK/LR	OK	none obs	
chargers	20.9	0	0	KK/LR	OK	none obs	
Washdown	20.9	0	0	LR	OK	none obs.	
Storage area	20.9	0	0	LR	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 6404
PRE-SHIFT/MINE EXAMINER CERT. # 4325
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03575

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-30-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 700 AM/PM END 900 AM/PM Examiners Initials DD
TIME OF EXAMINATION START 9:30 AM/PM END 8:15 AM/PM Examiners Initials PC
TIME OF EXAMINATION START ____ AM/PM END ____ AM/PM Examiners Initials ____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME -------- ____ AM/PM

CALLED OUT BY ____
CALLED OUT BY ____
CALLED OUT BY ____

REPORT RECEIVED BY ____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	ok	none obs.	
Main North Haulage Seals	20.9	0	0	DD	ok	None observed	
Main West Haulage seals	20.9	0	0	DD/PC	ok	None Observed	
3rd north Haulage	20.9	0	0	DD	ok	none obs.	
1st Right Haulage	20.9	0	0	DD	ok	none obs.	
Trans.	20.9	0	0	DD/PC	ok	None Observed	
chargers	20.9	0	0	DD/PC	ok	None Observed	
Washdown	20.9	0	0	PC	ok	None Observed	
Storage Area	20.9	0	0	PC	ok	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8058
PRE-SHIFT/MINE EXAMINER ____ CERT. # 8462
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____
PRE-SHIFT/MINE EXAMINER ____ CERT. # ____

COUNTER SIGNATURE Signature CERT. # 8462

2MSHA03576

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-31-07 SECTION/AREA Gen Mines / / /

TIME OF EXAMINATION START 3:45 AM/PM END 4:26 AM/PM Examiners Initials JR
TIME OF EXAMINATION START 300 AM/PM END 545 AM/PM Examiners Initials DD/PC
TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- AM/PM

CALLED OUT BY
CALLED OUT BY
CALLED OUT BY

REPORT RECEIVED BY
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	JR	OK	None Observed	
Main North Haulage Seals	20.9	0	0	JR	OK	None Observed	
3rd North Haulage	20.9	0	0	DD/PC	ok	none obs.	
1st Right Haulage	20.9	0	0	PC	ok	none obs.	
Transformers	20.9	0	0	DD	ok	none obs.	
Chargers	20.9	0	0	DD	ok	none obs	
Washdown	20.9	0	0	PC	ok	none obs.	
Storage Area	20.9	0	0	DD	ok	none obs.	
Main West Haulage seals	20.9	0	0	DD/PC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9293
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. #
PRE-SHIFT/MINE EXAMINER CERT. #

Signature

COUNTER SIGNATU CERT. # 4735

2MSHA03577

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-31-07 SECTION/AREA Gen Mine / / /

TIME OF EXAMINATION START 11.40 AM/PM END 12.47 AM/PM Examiners Initials KK
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	none obs	
3rd North Haulage seals	20.9	0	0	KK	OK	none obs	
M. West Haulage seals	20.9	0	0	RL/LR	OK	none observed	
3rd North	20.9	0	0	KK	KK	none obs.	
1st right	20.9	0	0	KK	~~KK~~ OK	none obs	
Trans	20.9	0	0	KK/LR/RL	OK	none observed	
Chargers	20.9	0	0	KK/LR/RL	OK	none observed	
storage area	20.9	0	0	RL	OK	none "	
Washdown	20.9	0	0	RL	OK	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 7954
PRE-SHIFT/MINE EXAMINER CERT. # 6401
PRE-SHIFT/MINE EXAMINER CERT. # 4375
PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03578

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 3-31-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 7:25 AM/PM END 7:55 AM/PM Examiners Initials PC
TIME OF EXAMINATION START 7:30 AM/PM END 9:00 AM/PM Examiners Initials MC/DD
TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	none observed	
Seals, trans Main North Haulage	20.9	0	0	PC	OK	none observed	
Main West Haulage Seals	20.9	0	0	MC/DD	OK	none observed	
3rd North	20.9	0	0	MC/DD	OK	none observed	
1st Right	20.9	0	0	DD	OK	none observed	
Trans.	20.9	0	0	MC/DD	OK	none observed	
Chargers	20.9	0	0	MC/DD	OK	none observed	
Storage area	20.9	0	0	MC	OK	none observed	
Wash down	20.9	0	0	DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 275
PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 8462

2MSHA03579

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-1-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 3:10 AM/PM END 3:35 AM/PM Examiners Initials PC
TIME OF EXAMINATION START 3:00 AM/PM END 5:25 AM/PM Examiners Initials MC
TIME OF EXAMINATION START 300 AM/PM END 530 AM/PM Examiners Initials DD

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ------- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	PC	ok	None Observed	
Haulage & Seals Main North	20.9	0	0	PC	ok	None Observed	
Main West Haulage Seals	20.9	0	0	mc/DD	ok	none observed	
3rd North Haulage chargers	20.9	0	0	mc/DD	ok	none observed	
1st right	20.9	0	0	mc/DD	ok	none observed	
Trans Formers	20.9	0	0	mc/DD	ok	none observed	
Chargers	20.9	0	0	mc/DD	ok	none observed	
Storage areas	20.9	0	0	mc	ok	none observed	
Wash down	20.9	0	0	DD	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe At time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8462
PRE-SHIFT/MINE EXAMINER CERT. # 7375
PRE-SHIFT/MINE EXAMINER CERT. # 8058
PRE-SHIFT/MINE EXAMINER CERT. # _____
Signature

COUNTER SIGNATURE CERT. # 4735

2MSHA03580

2MSHA03581