42-01715 (E08)
Non Injury Accident
Invest.
08-06-2007 Part2.PDF

Mine Activity Data

U. S. Department of Labor
Mine Safety and Health Administration

1. Action: a. New Entry ☐ b. Update ☑ | 2. Activity Code: E08 | 3. Event Number: 4474194

4. Date Event Started: 8/6/2007 | 5. Date Event Finished: | 6. Mine ID: 42-01715

7a. Organization Code (Mine Assignment) 20905 | b. Work Group Identifier 02 | 9. Company Name GENWAL RESOURCES INC

8a. Organization Code (AR Assignment) 20905 | b. Work Group 02 | 10. Mine Name CRANDALL CANYON MINE

11. Report Type (check a. First ☑ b. Interim ☐ c. Last ☐ d. Not Applicable ☐ | 12. Area of Inspections a. Active Sections ☐ b. Idle Sections ☐

c. Outby Areas ☐ d. Shafts/ Slopes ☐ e. Surface Areas (UG) ☐ f. Surface Workings ☐ g. Company Records ☐ h. ATF ☐ i. Impoundments ☐ j. Refuse Piles ☐

k. Major Construction ☐ (1) Shaft/ Slope Sinking (2) Impoundment Construction (3) Buildings (4) Dragline/ Shovel: (5) Other l. Miscellaneous ☐

m. MMU/Pit Number

13. Number of Samples Collected a. Air Samples b. Rock Dust Spot c. Rock Dust Survey d. Respirable Dust e. Noise f. Other

14. Impoundments/Refuse Piles:

a. Number b. FHC c. Configuration

15. Prime Independent Contractor Codes (Major Construction)

16. Inspection Results

	Citations		Orders		Safeguards		Other	
	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con
a. This Inspection								
(1) New Issuances								
(2) Terminations/Vacations								
(3) Modifications/Extensions								
(4) Left Pending								
b. Previously Issued								
(1) Modifications/Extensions								
(2) Terminations/Vacations								

18. Signature and Card Number of Authorized Representative/ Right of Entry Person(s) Responsible for Activity

a. [redacted] Card Number 23807

b.

c.

d.

19. Key Entered By Date

17. Remarks:

MSHA Form 2000-22. Oct. 85 (Revised) Previous editions are Obsolete

Mine Citation/Order Continuation

U.S. Department of Labor
Mine Safety and Health Administration

Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation	2. Dated (Original Issue) Mo Da Yr	3. Citation/ Order Number
☑ ☐	08/06/2007	7287831 - 04

4. Served To	5. Operator
Bodee Allred	GENWAL RESOURCES INC
6. Mine	**7. Mine ID** (Contractor)
CRANDALL CANYON MINE	42-01715

Section II--Justification for Action

The 103(k) order number 7287831 dated 08/06/2007 is hereby modified to allow recovery operations to continue in accordance with approved site specific plans. The approved site specific plans will be reviewed and approved by MSHA and signed by the onsite senior mine operations official and the senior MSHA official prior to implementation of any approved plans.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	☐ C. Vacated	☐ D. Terminated	☑ E. Modified

Section IV--Inspection Data

9. Type of Inspection	10. Event Number
E08	4474194

11. Signature	AR Number	12. Date Mo Da Yr	13. Time (24 Hr. Clock)
SIGNATURE	23791	08/08/2007	1018

MSHA Form 7000-3a, Mar 85 (revised)

Mine Citation/Order Continuation

U.S. Department of Labor
Mine Safety and Health Administration

Section I--Subsequent Action/Continuation Data

1. Subsequent Action	1a. Continuation	2. Dated (Original Issue) Mo Da Yr	3. Citation/ Order Number
☑	☐	08/06/2007	7287831 - 04

4. Served To	5. Operator
Bodee Allred	GENWAL RESOURCES INC
6. Mine	**7. Mine ID** (Contractor)
CRANDALL CANYON MINE	42-01715

Section II--Justification for Action

The 103 (k) order number 7287831 dated 08/08/2007 is hereby modified to allow recovery operations to continue in accordance with approved site specific plans. The approved site specific plans will be reviewed and approved by MSHA and signed by the onsite senior mine operations official and the senior MSHA official prior to implementation of any approved plans.

Delete the modification with the above date of 08/08/2007

See Continuation Form ☐

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	☐ C. Vacated	☐ D. Terminated	☑ E. Modified

Section IV--Inspection Data

9. Type of Inspection	10. Event Number
E08	4474194

11. Signature	AR Number	12. Date Mo Da Yr	13. Time (24 Hr. Clock)
	23791	08/08/2007	1018

MSHA Form 7000-3a, Mar 85 (revised)

Erramouspe, Pat - MSHA

From: Newton, Don - MSHA
Sent: Monday, August 13, 2007 10:02 AM
To: Erramouspe, Pat - MSHA
Cc: zzMSHA-Coal – MSIS DAAs Dist 09 Group
Subject: MSIS\41905\Closed by Ramirez.April

Subsequent Action 04 has been removed for citaiton 7287831.

THANK YOU

Don Newton
MSHA Help Desk Supervisor
newton.don@dol.gov
1-877-778-6055

NMS

Mine Activity Data

U. S. Department of Labor
Mine Safety and Health Administration

1. Action: a. New Entry ☐ b. Update ☑ | 2. Activity Code: E08 | 3. Event Number: 4474194

4. Date Event Started: 8/6/2007 | 5. Date Event Finished: | 6. Mine ID: 42-01715

7a. Organization Code (Mine Assignment) 20905 | b. Work Group Identifier 01 | 9. Company Name GENWAL RESOURCES INC

8a. Organization Code (AR Assignment) 20905 | b. Work Group 02 | 10. Mine Name CRANDALL CANYON MINE

11. Report Type (check a. First ☐ b. Interim ☑ c. Last ☐ d. Not Applicable ☐

12. Area of Inspections: a. Active Sections b. Idle Sections c. Outby Areas ☑ d. Shafts/ Slopes ☐ e. Surface Areas (UG) ☐ f. Surface Workings ☐ g. Company Records ☑ h. ATF ☐ i. Impoundments ☐ j. Refuse Piles ☐ k. Major Construction ☐ (1) Shaft/ Slope Sinking (2) Impoundment Construction (3) Buildings (4) Dragline/ Shovel: (5) Other l. Miscellaneous ☐

m. MMU/Pit Number

13. Number of Samples Collected: a. Air Samples | b. Rock Dust Spot | c. Rock Dust Survey | d. Respirable Dust | e. Noise | f. Other

14. Impoundments/Refuse Piles: a. Number | b. FHC | c. Configuration

15. Prime Independent Contractor Codes (Major Construction)

16. Inspection Results

	Citations		Orders		Safeguards		Other	
	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con
a. This Inspection								
(1) New Issuances								
(2) Terminations/Vacations								
(3) Modifications/Extensions								
(4) Left Pending								
b. Previously Issued								
(1) Modifications/Extensions								
(2) Terminations/Vacations								

18. Signature and Card Number of Authorized Representative/ Right of Entry Person(s) Responsible for Activity

a. SIGNATURE [redacted] Card Number 23983

b.

c.

d.

19. Key Entered By Date

17. Remarks:

MSHA Form 2000-22. Oct. 85 (Revised) Previous editions are Obsolete

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 8-6-07 Event No. 4474194

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked _____

Accompanied By: Company Representative _____

Miners Representative _____

AREAS OF INSPECTION ACTIVITY:

Traveled to the Crandall Canyon as requested by (b) (7)(C)

Inspector's Initials 12D

Supervisor's Initials and Date NMS 8/24/07 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 8-6-07

At the Crandall Canyon Mine-

Arrived @ about 1040 hrs -

(b) (7)(C) stated that I would be on accident investigation team -

Will need to get things in order as to necessary steps

Inspector's Initials 12D

Supervisor's Initials and Date _____ Page No. 2

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-6-07

- Six miners not accounted for -

- Command Vehicle is on the property

- Not a start on preliminary report -

- Spent most of the day in Command Vehicle monitoring projects & progress -

Arrived back at the office 1945 hrs.

Inspector's Initials 12D

Supervisor's Initials and Date _____ Page No. 3

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 8-7-07 Event No. 4474194

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked Hinkle

Accompanied By: Company Representative Phil

Cat

Miners Representative None

AREAS OF INSPECTION ACTIVITY:

At the Crandall Canyon Mine.

Inspector's Initials DJ2 WMS 8/24/07

Supervisor's Initials and Date _____ Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

-Extractor

-J-Channel

-Roc-Props

-Track material runners avail at all times

-Materials/Parts coordinator at phone at all times.

-Spare remote

-1st Aid Supplies

Inspector's Initials DJ2

Supervisor's Initials and Date _____ Page No. 2

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

✓ on fresh air base 120-121 CK #6 Entry

✓ on first aid supplies OK

✓ vent controls -

✓ Compressors

✓ Spare remote

✓ Gas Readings

Inspector's Initials DJ2

Supervisor's Initials and Date _____ Page No. 3

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

Trying to get a lift into the mine -

Rides seem to be a commodity -

Talked to [redacted] (b) (7)(C) at about 0700 ± hrs. [redacted] (b) (7)(C) said he will try & get me a lift.

Inspector's Initials RD

Supervisor's Initials and Date WMS 8/24/07 Page No. 4

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

Projects -

- Power Center X-cut needs cleaned -
- Setting Kennedy stoppings from about 95 X-cut inby - Had another bounce -

- Insist on more gas readings -

- Check on organization

Inspector's Initials RD

Supervisor's Initials and Date _____ Page No. 5

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

[redacted] (b) (7)(C)

are the foremen in the mine -

Inspector's Initials RD

Supervisor's Initials and Date _____ Page No. 6

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

- Fresh air base ± 95 now according to [redacted]

[redacted] trying to get him & I [illegible] in.

- Get trucks out to surface that are not ~~[illegible]~~ DD needed U.G.

Inspector's Initials DD

Supervisor's Initials and Date [illegible] 8/24/07 Page No. 7

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 105, 108

104, 106, 107, 109, 110 out still

Seals X-cuts 105, 106, 107 in return checked & ok —

Return O_2 20.8% CO 8 PPm — No Chg 0845 hrs.

Inspector's Initials DD

Supervisor's Initials and Date _____ Page No. 8

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

Compressor @ 6 belt X-cut 4 (#7 headroller)

Told [redacted] that compressor needs washed -

Took air reading @ 110 X-cut intake leading to section -

7 3/4 ft. x 22 ft. x 350 vel. = 59,675

20.8 O_2 - CO 6 PPm diesel residual -

Inspector's Initials DD

Supervisor's Initials and Date _____ Page No. 9

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

0955 hrs - Return stopping line along #5 belt progressing well - Some foam needed -

Miners working on return stoppings along #6 belt - Runs parallel to 110 x-cut -

Checked groups of miners - not enough gas detectors -

Informed [redacted]

Inspector's Initials 1212

Supervisor's Initials and Date WMS 8/24/07 Page No. 10

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

Bodie Allred called shortly after and said he had passed out meters this A.m.

Told him he had better re-look!

1005 hrs - Gas readings in return x-cut @ #6 belt

O_2 20.8% - CO 8 ppm no chg -

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 11

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

Kennedy stoppings did not face well from the event clear out to ± 95 x-cut in main west.

Blown in different directions - Some portions on stoppings (10 panel segments) blown as far as 45 ft. from origin!

Air reading x-cut 110 ± entering section as follows - 1035 hrs

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 12

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

7 3/4' x 22' x 370 Vel.
= 63,085 CFM

Return stoppings
holding -

Traveled #7 belt
to about 155 X-cut -

Alone so stopped there -

Pillars shelled (bumped)
partially obstructing
walkways on both
sides - 0 11 to 15 X-cut

Inspector's Initials 1212

Supervisor's Initials and Date 8/7 8/24/07 Page No. 13

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

(Would describe as
"fragmented bump"
material, not routine
sloughage - Not recent
event related - Coal
well rockdusted!

Rib to pin spacing
questionable in numerous
spots -

Not home glassed -

Taped to the roof -

Inspector's Initials 12

Supervisor's Initials and Date _____ Page No. 14

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

[redacted]

Traveling not as
~~affected~~ as bad -

Mostly north & South
of pillars affected -
X-cuts less affected -

[redacted] stated this
morning that when
intrusions were being
developed, it bumped
& was "heavy."

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 15

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-1-07

1350 hrs - Checked gas readings in main inlet return x-cut 115 - O2 20.8% - CO 8PPM -

Note - Also checked main inlet #1 seal - Except for breach hole - -- Seal

(b) (5)

Stayed back about 20 feet - O2 19.5% — Curtain is ventilating hole -

Inspector's Initials 12

Supervisor's Initials and Date WAS 8/24/07 Page No. 16

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-1-07

Note - #3 & 4 entries from inby 13 x-cut to 17 x-cut walked.

Pillars showing signs of shelling -

Roof banging.

Note - Found Kennedy stoppings in return knocked out to 200 ft.

Inspector's Initials 12

Supervisor's Initials and Date _____ Page No. 17

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-1-07

Intake air reading section intake about x-cut 111 -

7.75 ft. x 22 ft.
x 580 vel.
= 98,890 CFM

Belt air reading 112 x-cut traveling inby

8.5 ft. x 21 ft - 1054 ft.
x 330
= 55,605 CFM

Inspector's Initials DH

Supervisor's Initials and Date _____ Page No. 18

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

1415 hrs, Gas
readings x-cut ~~[illegible]~~
~~[illegible]~~ DD 114 in return –

O_2 20.8 – CO 8 PPm

All Return & belt
stoppings complete to
#6 belt tail with the
exception of one.

Inspector's Initials (2/2)

Supervisor's Initials and Date WMS 8/24/07 Page No. 19

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 8-8-07 Event No. 447-1194

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked Roads,

Accompanied By: Company Representative Josh Fielder

Miners Representative None

AREAS OF INSPECTION ACTIVITY:

At the Crandall Canyon Mine -

Inspector's Initials 1212

Supervisor's Initials and Date WM 8/24/07 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 8-8-07

- Stoppings intact
- Roc Props
- Bad Roof needs bolted just in by 121 X-cut
- Cln up in -
- Plan intact -

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 2

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-8-07

DBT Battery

S.N. 2007-06-1427

Cab intact w/Tag

Al Lee Mine Trac Diesel

S.N. 06-F8497-1

No cert. on cab -

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 3

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-8-07

ABT Battery Scoop

S.N. 2476

Cab OK - Tag intact -

Inspector's Initials 1212

Supervisor's Initials and Date WMS 8/24/07 Page No. 4

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-8-07

Had a safety meeting with all miners and foreman -

Requested that if any persons have reservations being on the section please speak to their supervisors -

Lifeline is rerouted according to (b) (7)(C) [redacted]

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 5

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-8-07

Miners are preparing to move mine out of X-cut then add cable -

Setting Sq. Sets (8"x8") from 118 X-cut entry.

Intake 119 X
8 ft. x 21 ft. x 735 vel
= 123,480 CFM

Belt 7 ft. x 20 ft.
x 410 vel.
= 57,400 CFM intg

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 6

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-8-07

Gas readings

O2 20.8. CO 2 PPM
No CH4 0.0%

0930 hrs. LST 5
started and mucking

Also 3½ Wagner
LH12 cleaning
feeder area

Prior to loading...
will need to spot
bolt X-cut 120
between 1 & 2 entries

Inspector's Initials 12 12

Supervisor's Initials and Date WMS 8/24/07 Page No. 7

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-8-07

0940 hrs - Splicing
miner cable,
setting sq. sets,
dusting intake,
scraping feeder
area

1040 hrs - No change
in air

1120 - Still mucking
X-cut 20 & feeder
area

Inspector's Initials 12 12

Supervisor's Initials and Date _____ Page No. 8

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-8-07

Set nearly 180 sq.
sets today - No
equipment to Set
Rock Props -

Richard Stickler, Bob
Murray brought in 2
family members of
trapped miners -

Inspector's Initials 12 12

Supervisor's Initials and Date _____ Page No. 9

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 8-9-07 Event No. 4474194

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked Main Wood Section, Haulage

Accompanied By: Company Representative Josh Fiddler

Miners Representative None

AREAS OF INSPECTION ACTIVITY:

At Crandall Canyon mine -

Reviewed log [illegible] thing -

Requested from [redacted] to locate a Plantan Duster -

Inspector's Initials 1212

Supervisor's Initials and Date WMS 8/24/07 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 8-9-07

- Duster for battery scoop

- Hose for manifold (water) 1½" - 2"

- Inby x-cut 121

[redacted]

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 2

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-9-07

Air reading 0740

7½ ft x 21 ft. x 745 vel

= 117,338

O2 20.8 - LO 0

Need to set 4-5 Roc Props x-cut 19 East Rib to protect walkway & power centers

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 3

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-9-07

Setting ~~[illegible]~~ AA Rec.
Props 20 to 21 -
About 35 feet left
to set - then wrap
with cable -

Had to remove 2-3
rock props only
corner 120 to get
Buggy ~~[illegible]~~ AA
around corner -

Also moved feeder
out a few feet -

(b) (7)(C)

Inspector's Initials AA

Supervisor's Initials and Date WMS 8/24/07 Page No. 4

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-9-07

0855 hrs.

7½ ft x 21 ft.
= 158 sq. ft.

x 770 vel.

= 121,668 cfm

0935 -
Area 140 sq ft.
142,380 cfm

NO_2 1.2
O_2 20.8

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 5

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-9-07

Told Command
center 0940 hrs.
that earliest projection
to start loading will
be 1130 hrs -

1030 hrs -

8-10 props still to
set 121 intersection -
Lots of shoveling

Also Tech support folks
want additional support
120 belt intersection
5-6 Props on Sq. sets

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 6

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-9-07

must clean 120½ to 121 -

Props at power center

Sandwiches for 2nd!

1040 hrs -

Area 140 sq. ft.

x 1,044 Vel.

= 146,160 CFm

Inspector's Initials 12B

Supervisor's Initials and Date [illegible] 8/24/07 Page No. 7

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-9-07

Area 145 X

Vel = 1010

= 141,400 CFm

1130 hrs.

O2 20.8% - COO

Still 120 No

Chg

- Made 55' push -

Set Rec Props -

Inspector's Initials 12B

Supervisor's Initials and Date _____ Page No. 8

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-9-07

Made another 55' push - Done at 1510 hrs -

Setting more Props

Air reading 1515 -

140 Area X 1105

= 154,700 CFm

1615 hrs.

140 sq. ft. X 1183

= 154,420 CFm

Inspector's Initials 12B

Supervisor's Initials and Date _____ Page No. 9

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-9-07

Got ready to make 3rd push - Did not get at - Rock stuck in feeder -

Talked with [redacted]

Returned to the surface

Inspector's Initials 1212

Supervisor's Initials and Date [illegible] 8/24/07 Page No. 10

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 8-10-07 Event No. 4474 194

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked Heritage, main West

Accompanied By: Company Representative John Fielder

Miners Representative none

AREAS OF INSPECTION ACTIVITY:

At Grandall Canyon Mine ~~[illegible]~~ (D)

Bolter down unity - Circuit breaker

Inspector's Initials DD

Supervisor's Initials and Date WMS 8/24/07 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 8-10-07

- CM 123

- Checked belt stopping "Sealed"

- Bumped 0130 A.m.

- Reminder of areas

(b) (7)(C)

Inspector's Initials DD

Supervisor's Initials and Date _____ Page No. 2

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-10-07

- Small trailer 60' back in 123

- Tool box 123 removed

- 122 - Oil tub & then Shop car

Unstable supports 118 - 119 (sq sets) 7-8 North side -

Inspector's Initials DD

Supervisor's Initials and Date _____ Page No. 3

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-10-07

Loading 1005

Bolter operating
0950 - Circuit Breaker

Loaded 30'-35'
in straight at
35' in x-cut

Set props

Inspector's Initials 1212

Supervisor's Initials and Date WMS 8/24/07 Page No. 4

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-10-07

Dusted push area

Stretchers, O2,
masks, etc behind
power center -

made next push -

Bolting after push

Need 8-10 bolts -

(b) (7)(C)

[illegible] sent to TRG
to navigate #1 & #0
4 entries -

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 5

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-10-07

(b) (7)(C) got to
124½ the withdrew to
supports at x-cut 23 as
needs would not work -

(b) (7)(C)

(b) (7)(C) states he got to
about 126½ -

Briefed (b) (7)(C) - when
he arrived on the section -

Returned to the surface -

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 6

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 8-11-07 Event No. 4474194

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked Hawkage, Main West

Accompanied By: Company Representative Steve, Radmall

Miners Representative None

AREAS OF INSPECTION ACTIVITY:

At the Crandall Canyon Mine -

Rode in with Radmall

Inspector's Initials 1212

Supervisor's Initials and Date WMS 8/24/07 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 8-11-07

- Cable tub - 124

- Check dusting

- 3 & 4 - Readings every 2 hrs - Gas & air readings Card/Placard -

- Stopping marked

- Check on drill info -

Inspector's Initials 1213

Supervisor's Initials and Date _____ Page No. 2

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-14-07

- X-cut 122 6780 spad lb

- Props are about 110 ft. beyond X-cut 123 -

- Miner advanced 10 to 12 ft. beyond or 120-122 ft. ±

- Left side for 8 ft. looks (resembles) a solid face - Appears South barrier moved north.

Inspector's Initials 1212

Supervisor's Initials and Date _____ Page No. 3

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-11-07

Void on right side 8 ft. across and 2½ ft. of clearance over the top -

5th wheel trailer loaded with rib block about 5 ft. into the entry -

(b) (7)(C)

- Top looks solid -

Inspector's Initials 12D

Supervisor's Initials and Date WMS 8/24/07 Page No. 4

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-11-07

0840 hrs - Miner heading in to x-cut 124 to clean below 5th wheel and to the left of it

Will likely torch goose neck off -

Loading 0845

0915 - Material left ½ of entry very compacted - must use cutter head to move material -

Inspector's Initials 12D

Supervisor's Initials and Date _____ Page No. 5

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-11-07

0955 hrs - Still loading on 1st lift

Using one of the diesel powered cars with the electric buggy. Diesel car putting 35-45 ppm CO out -

1030 hrs - 15 buggies loaded & not yet done -

Inspector's Initials A/D

Supervisor's Initials and Date _____ Page No. 6

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-11-07

- All rock props between 118 & 119 set - Where short sq. set were set in higher area.

- Done loading at 1100 hrs. 17 buggies total -

- Could not break trailer neck off with head pushing -

- Repositioned miner inby trailer

Inspector's Initials AB

Supervisor's Initials and Date WMS 8/24/07 Page No. 7

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-11-07

- 1120 hrs - Started setting Roc Props.

- 1st push ended 45-50 feet beyond x-cut 124 center liner

- Some noise #1 entry between #114 & #119 x-cut

- Added 500 ft. of miner cable - Pulled slack to 121/122

Inspector's Initials AB

Supervisor's Initials and Date _____ Page No. 8

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

- Need to look at x-cut 125 to clean out for next power move -

- Need x-cut 117-118 for electric buggy stash

- Loading again on Right side @ 1325 hrs.

- Diesel cars in section.

- X-cut 123 - two rock props to reset left side

Inspector's Initials AB

Supervisor's Initials and Date _____ Page No. 9

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-11-07

- Bump 1425 hrs

- Another small one 1427 hrs -

- Another at 1452 hrs.

- Push completed 1500 hrs.

- Advance 45' in by 124 X-cut center

- Props out by corner of 124

Inspector's Initials CAB

Supervisor's Initials and Date [illegible] 8/24/07 Page No. 10

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-11-07

- 1515 hrs - Roof working over miner. Decided to pull miner back and put bolter in to roof bolt, preferably ~~[illegible]~~ AD using J Channel on 5 ft. centers -

Talked with (b) (7)(C) [redacted] - - - - Returned to the surface -

Inspector's Initials CAB

Supervisor's Initials and Date _____ Page No. 11

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 8-12-07 Event No. 4474194

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked Hardage, main West

Accompanied By: Company Representative Josh Fielder -

Miners Representative None

AREAS OF INSPECTION ACTIVITY:

At the Crandall Canyon Mine -

Got a lift into the mine with (b) (7)(C) [redacted]

(b) (7)(C) [redacted]

Inspector's Initials DQ

Supervisor's Initials and Date WMS 8/24/07 Page No. 1

*U.S. Government Printing Office: 1997 - 506-470

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

- Check stoppings
- Limit manpower
- Air readings
- Test holes indicate gap on of 1 inch at about 5 ft. ±
- 3 rows of props only
- Check procedures list
- O_2 sensor

Inspector's Initials DQ

Supervisor's Initials and Date _____ Page No. 2

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

X-cut 24 station # 6784

Stations to props 22 feet

Props to mine 38 ft - 1 ft ±

Little air going over cm - No visible void

Air reading outby 124 = 50,240

Bases of props are in fact tilting inward

Inspector's Initials DQ

Supervisor's Initials and Date _____ Page No. 3

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

in several (numerous) locations

28 bolts / 52 channel.

Also 25 Roc Pumps

Reset another 8 Pumps —

Since 1900 hrs.
6 Pumps / 2 channel / 7-8 rows of bolts / + additional cables

Inspector's Initials [illegible]

Supervisor's Initials and Date WMJ 8/24/07 Page No. 4

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

#1 - 520-5 x 126
20.8 0 0
= 64,890

#3 310+10 x 90
20.8 7PPm Co 0 Chg
= 27,000

#4 300+10 x 108
= 31,320
20.8 7PPm Co 0 Chg

0900 hrs

Inspector's Initials [illegible]

Supervisor's Initials and Date _____ Page No. 5

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

Small bump NW of us 0840

0910 hrs - Main Charge water pump down -

One coming from Industrial -

1000 hrs -

#1 505 x 126
= 63,630 cfm

D2 20.8 0 Co 0 Chg

Inspector's Initials [illegible]

Supervisor's Initials and Date _____ Page No. 6

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

1045 hrs - Still no supply pump for water -

Working on additional supports to secure props

1110 hrs—

#1 - ~~350~~ 400 X126

= 50,400 CFm

O2 20.8 CO 0 CH4 0

#3 - 350+5 X95

= 33,725

O2 CO 9 CH4 0

#4 - 300+10 X108

Inspector's Initials DQ

Supervisor's Initials and Date WMS 8/24/07 Page No. 7

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

= 33,480 CFm

O2 20.8 CO 9 CH4 0

1200 hrs—

#5 X 126

= 57,330 CFm

O2 20.8 CO 0 CH4 0

1205 hrs - Then went to lunch.

Inspector's Initials DQ

Supervisor's Initials and Date _____ Page No. 8

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

1300 hrs

#1 - 126 ft sq X 350

= 44,100 CFm

O2 CO 0 CH4 0

#2 - 175 X 3300

= 5775 CFm

O2 20.8 CO 8 CH4 0

#3 - 95 ft sq X 305+10

O2 20.8 CO 8 CH4 0

= 24,495 CFm

#4 - 158 ft sq X 280+12

= 31,536

O2 20.8 CO 8 CH4 0

Inspector's Initials DQ

Supervisor's Initials and Date _____ Page No. 9

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

1400 hrs
#1 entry
430 vel. X126 =
= 54,180

O2 20.8 CO 0 CH4 0

Water at 1400 hrs.

Inky diesel buggy
won't start

Finally loading 1415 hrs.

Inspector's Initials DJ
Supervisor's Initials and Date WMS 8/24/07 Page No. 10

*U.S.GPO: 2004 - 642 - 912

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

Loading complete 1500
hours ± - Puts
advance to about 67-68
feet beyond 124 x-cut
spad -

Set 6 rock props & dusted

Inspector's Initials DJ
Supervisor's Initials and Date _____ Page No. 11

G2O U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

1520 hrs
#1 - 400 X 126
= 50,400
O2 20.8 CO 0 CH4 0

#2 - 1.75 X 3,510
= 6,143
O2 20.8 CO 0 CH4

#3 - 270+10 X 108
= 30,240
O2 20.8 CO 0 CH4 0

#4 250 X 126
= ~~30,240~~ 31,500
O2 20.8 CO 0 CH4 0

Inspector's Initials DJ
Supervisor's Initials and Date _____ Page No. 12

G2O U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 8-12-07

Some ropes to finish -

Setting pumps with bars tilted forward nib -

Trimble balancing and readings -

Left to do on ropes
Top 119-120
130 Horn 120 inby 50

Top to tighten 120-121

Talked with (b) (7)(C)
then returned to surface -

Inspector's Initials 12d

Supervisor's Initials and Date 12MS 8/24/07 Page No. 13

GPO U.S. GPO: 2006-640-217

W445

U. S. Department of Labor
Mine Safety and Health Administration

Mine Activity Data

1. Action: a. New Entry ☐ b. Update ☑		2. Activity Code: E08		3. Event Number: 4474194	
4. Date Event Started:	8/6/2007	5. Date Event Finished:		6. Mine ID: 42-01715	
7a. Organization Code (Mine Assignment)	20905	b. Work Group Identifier	02	9. Company Name	GENWAL RESOURCES INC
8a. Organization Code (AR Assignment)	20905	b. Work Group	02	10. Mine Name	CRANDALL CANYON MINE

11. Report Type (check) a. First ☐ b. Interim ☐ c. Last ☐ d. Not Applicable ☑

12. Area of Inspections: a. Active Sections b. Idle Sections c. Outby Areas ☐ d. Shafts/ Slopes ☐ e. Surface Areas (UG) ☑ f. Surface Workings ☐ g. Company Records ☐ h. ATF ☐ i. Impoundments ☐ j. Refuse Piles ☐ k. Major Construction ☐ (1) Shaft/ Slope Sinking (2) Impoundment Construction (3) Buildings (4) Dragline/ Shovel: (5) Other l. Miscellaneous ☐

m. MMU/Pit Number

13. Number of Samples Collected: a. Air Samples b. Rock Dust Spot c. Rock Dust Survey d. Respirable Dust e. Noise f. Other

14. Impoundments/Refuse Piles:

a. Number b. FHC c. Configuration

15. Prime Independent Contractor Codes (Major Construction)

16. Inspection Results

	Citations		Orders		Safeguards		Other	
a. This Inspection	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con
(1) New Issuances	0							
(2) Terminations/Vacations								
(3) Modifications/Extensions								
(4) Left Pending								
b. Previously Issued								
(1) Modifications/Extensions								
(2) Terminations/Vacations								

18. Signature and Card Number of Authorized Representative/ Right of Entry Person(s) Responsible for Activity

Card Number

a. [SIGNATURE] 23893

b. 23799

c.

d.

19. Key Entered By Date

17. Remarks:

MSHA Form 2000-22. Oct. 85 (Revised) Previous editions are Obsolete

8-11-07 4474594

EO8 - CRANDALL CANYON

Travel to Mine -

Clean-up - Setting
Props continue

TA WMJ 8/24/07

8-10-07 4474194

EO & Crandall Canyon Rescue operations

Travel to mine.
Briefed by (b) (7)(C)
(b) (7)(C)

Mucking - setting props continues

DA 9/MS 8/24/07

MSHA Form 7000-10K, June 93 (revised)

Date 8-10-07

8" Drilling continues.

Inspector's Initials DA

Supervisor's Initials and Date _____ Page No. 2

GPO U.S. GPO: 2006-640-217

8-9-07 4474194

E08- Crandall Canyon

Travel to Mine Site
Briefed by [redacted]

Both Drills going -
They have started
clean up - bolting o

DA
WMS 8/24/07

MSHA Form 7000-10K, June 93 (revised)

Date 8-9-07

setting props -

Inspector's Initials DA

Supervisor's Initials and Date _____ Page No. 12

GPO U.S. GPO: 2006-640-217

==========

**** Galaxy Test Results ****

==========

Instrument ID: 1
Serial #: 00000070
Type: Solaris
Model: SOLARS
Name: ANDERSON
Location: *GALAXY2
Last Cal Date: 8/8/2007
Results: Cal Pass

GAS	AS FOUND	AS LEFT
CH4	2.50	2.50
02	14.6	14.6
CO	056	060
N02	10.0	10.0
NONE	0	0

8-8-07 4474194

EOS- GRANDAE CANYON

Travel to Mine Site

Briefed by (b) (7)(C)

Miners continue to build Stoppings & hauling Material

TS 8/8/07 8/24/07

MSHA Form 7000-10K, June 93 (revised)

Date 8-8-07

Drill is drilling - Big Drill not on Pad as of yet -

Fan reading being taken & reported - Cons Paletta is in mine & taking air readings & Gas reading & also reporting readings.

Inspector's Initials TS

Supervisor's Initials and Date _____ Page No. 1

GPO U.S. GPO: 2008-640-217

==========

**** Galaxy Test Results ****

==========

Instrument ID: 1
Serial #: 00000070
Type: Solaris
Model: SOLARS
Name: ANDERSON
Location: +GALAXY1
Last Cal Date: 8/7/2007
Results: Cal Pass

GAS	AS FOUND	AS LEFT
CH4	2.50	2.50
O2	14.5	14.5
CO	064	060
NO2	10.0	10.0
NONE	0	0

8-6 & 8-7 4474194

E08 - CRANDALL CANYON -

Seismic event on or near Main West Pillar Section MMU-002

TA NM 58/24/07

MSHA Form 7000-10K, June 93 (revised)

Date 8-7-07

Travel to mine site to Command Center - Briefed by

Miners setting feeder breaker, Getting belts started & water lines in -

About 0120 hr - had another bounce - Knocked out some of the ventilation - Miners backed up until dust clears out -

They continue to re-establish ventilation set feeder & cut water to feeder -

Inspector's Initials TA

Supervisor's Initials and Date _____ Page No. 2

GPO U.S. GPO: 2006-640-217

==========

**** Galaxy Test Results ****

==========

Instrument ID: 1
Serial #: 00000070
Type: Solaris
Model: SOLARS
Name: ANDERSON
Location: +GALAXY1
Last Cal Date: 8/6/2007
Results: Cal Pass

GAS	AS FOUND	AS LEFT
CH4	2.50	2.50
O2	14.6	14.6
CO	060	060
NO2	10.0	10.0
NONE	0	0

Mine Activity Data

U. S. Department of Labor
Mine Safety and Health Administration

1. Action: a. New Entry ☐ b. Update ☑ | 2. Activity Code: E08 | 3. Event Number: 4474194

4. Date Event Started: 8/6/2007 | 5. Date Event Finished: | 6. Mine ID: 42-01715

7a. Organization Code (Mine Assignment) 20905 | b. Work Group Identifier 01 | 9. Company Name GENWAL RESOURCES INC

8a. Organization Code (AR Assignment) 20905 | b. Work Group 02 | 10. Mine Name CRANDALL CANYON MINE

11. Report Type (check a. First ☐ b. Interim ☑ c. Last ☐ d. Not Applicable ☐ | 12. Area of Inspections a. Active Sections b. Idle Sections

c. Outby Areas ☑ d. Shafts/ Slopes ☐ e. Surface Areas (UG) ☐ f. Surface Workings ☐ g. Company Records ☑ h. ATF ☐ i. Impoundments ☐ j. Refuse Piles ☐

k. Major Construction ☐ (1) Shaft/ Slope Sinking (2) Impoundment Construction (3) Buildings (4) Dragline/ Shovel: (5) Other l. Miscellaneous ☐

m. MMU/Pit Number

13. Number of Samples Collected a. Air Samples b. Rock Dust Spot c. Rock Dust Survey d. Respirable Dust e. Noise f. Other

14. Impoundments/Refuse Piles:

a. Number b. FHC c. Configuration

15. Prime Independent Contractor Codes (Major Construction)

16. Inspection Results

	Citations		Orders		Safeguards		Other	
	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con
a. This Inspection								
(1) New Issuances								
(2) Terminations/Vacations								
(3) Modifications/Extensions								
(4) Left Pending								
b. Previously Issued								
(1) Modifications/Extensions								
(2) Terminations/Vacations								

18. Signature and Card Number of Authorized Representative/ Right of Entry Person(s) Responsible for Activity

Card Number

a. [redacted] 23983

b. SIGNATURE 23988

c.

d.

19. Key Entered By Date

17. Remarks:

MSHA Form 2000-22. Oct. 85 (Revised) Previous editions are Obsolete

Activity Calendar Event Number: 4474194 Mine ID: 4201715

Shift	Sun 1 2 3	Mon 1 2 3	Tue 1 2 3	Wed 1 2 3	Thur 1 2 3	Fri 1 2 3	Sat 1 2 3
Week 1 8/5/2007	☐☐☐	☐☑☐	☐☑☐	☐☑☐	☐☑☐	☐☑☐	☐☑☐
Week 2 8/12/2007	☐☑☐	☐☐☐	☐☑☐	☐☑☐	☐☑☐	☐☐☐	☐☐☐
Week 3 8/19/2007	☐☑☐	☐☐☐	☐☐☐	☐☐☐	☐☐☐	☐☐☐	☐☐☐

Key Codes: 1- Owl Shift, 2- Day Shift & 3- Evening Shift (Mark "X" in appropriate Block to Indicate Shift)

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 8-14-07 Event No. 4474194

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked _____

Accompanied By: Company Representative _____

Miners Representative _____

AREAS OF INSPECTION ACTIVITY:

At the Crandall Canyon Mine - Was asked to be present to answer any questions that the consultanting/engineering group might have -

Inspector's Initials DLD

Supervisor's Initials and Date WMS 8/24/07 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 8-14-07

Attended the meeting & gave input when asked and when it was appropriate -

Group decided not to go underground at the time. At least not today -

Returned to the office -

Inspector's Initials DLD

Supervisor's Initials and Date _____ Page No. 2

GPO U.S. GPO: 2006-640-217

Mine Activity Data

U. S. Department of Labor
Mine Safety and Health Administration

WPT

1. Action: a. New Entry ☐ b. Update ☑ | 2. Activity Code: E08 | 3. Event Number: 4474194

4. Date Event Started: 8/6/2007 | 5. Date Event Finished: | 6. Mine ID: 42-01715

7a. Organization Code (Mine Assignment) 20905 | b. Work Group Identifier 01 | 9. Company Name GENWAL RESOURCES INC

8a. Organization Code (AR Assignment) 20905 | b. Work Group 02 | 10. Mine Name CRANDALL CANYON MINE

11. Report Type (check a. First ☐ b. Interim ☑ c. Last ☐ d. Not Applicable ☐ | 12. Area of Inspections a. Active Sections b. Idle Sections

c. Outby Areas ☑ d. Shafts/ Slopes ☐ e. Surface Areas (UG) ☐ f. Surface Workings ☐ g. Company Records ☑ h. ATF ☐ i. Impoundments ☐ j. Refuse Piles ☐

k. Major Construction ☐ (1) Shaft/ Slope Sinking (2) Impoundment Construction (3) Buildings (4) Dragline/ Shovel: (5) Other l. Miscellaneous ☐

m. MMU/Pit Number

13. Number of Samples Collected a. Air Samples b. Rock Dust Spot c. Rock Dust Survey d. Respirable Dust e. Noise f. Other

14. Impoundments/Refuse Piles:

a. Number b. FHC c. Configuration

15. Prime Independent Contractor Codes (Major Construction)

16. Inspection Results

	Citations		Orders		Safeguards		Other	
	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con
a. This Inspection								
(1) New Issuances								
(2) Terminations/Vacations								
(3) Modifications/Extensions								
(4) Left Pending								
b. Previously Issued								
(1) Modifications/Extensions								
(2) Terminations/Vacations								

18. Signature and Card Number of Authorized Representative/ Right of Entry Person(s) Responsible for Activity

Card Number

a. SIGNATURE 23983

b.

c.

d.

19. Key Entered By Date

17. Remarks:

MSHA Form 2000-22. Oct. 85 (Revised) Previous editions are Obsolete

Activity Calendar Event Number: 4474194 Mine ID: 4201715

Shift	Sun			Mon			Tue			Wed			Thur			Fri			Sat		
	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3
Week 1 8/5/2007	☐	☐	☐	☐	☑	☐	☐	☑	☐	☐	☑	☐	☐	☑	☐	☐	☑	☐	☐	☑	☐
Week 2 8/12/2007	☐	☑	☐	☐	☐	☐	☐	☑	☐	☐	☑	☐	☐	☑	☐	☐	☐	☐	☐	☐	☐
Week 3 8/19/2007	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐

Reverse, MSHA Form 2000-22, Oct 85 (Revised)

Key Codes: 1- Owl Shift, 2- Day Shift & 3- Evening Shift (Mark "X" in appropriate Block to Indicate Shift)

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 8-17-07 Event No. 4147C435

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked N/A

Accompanied By: Company Representative N/A

Miners Representative None

AREAS OF INSPECTION ACTIVITY:

At the Crandall Canyon mine on EOB -

(b) (7)(C) called and asked (b) (7)(C) to come to the mine & get started on the preliminary investigation -

Inspector's Initials DJL WMS 8/24/07

Supervisor's Initials and Date _____ Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 8-17-07

Once at the mine site, talked with (b) (7)(C) about the information that I needed on the victims to do the preliminary -

Bill Denning showed up to help me with it -

Got information from (b) (7)(C) some time shortly after 1400 hrs -

Inspector's Initials DJL

Supervisor's Initials and Date _____ Page No. _____

GPO U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 8-17-07

Report mostly complete - missing a few details -

Bill says we will amend later -

Traveled back to the office, finished paper work, time, weekly activity & upload/download -

Inspector's Initials DJL

Supervisor's Initials and Date _____ Page No. _____

GPO U.S. GPO: 2006-640-217