HG22

PRESHIFT - ONSHIFT
and
DAILY REPORT

started 3-18-10

Started 3-18-10

Company Performance Coal

Mine 483

SECTION HG 22

LOCATION Naoma Raleigh WV
Post Office County State

Form 6-1489
(March 1970)

Budget Bureau No. 42-R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# M

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-18-10 Shift my Area or Section H622

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1	no obs	my
2.	2	no obs	my
3.	2nt	scrap out	check up bolts
4.	3	needs dust	chg
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7:00 7:00	.20	11.			
2.		9:00		12.			
3.	1-3	9:00	.20	13.			
4.		11:00		14.			
5.	1-3	11:50	.20	15.			
6.		1:00		16.			
7.	1-3	1:50	.20	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	8:00		.20	6.			
2.				7.			
3.	12:00		.20	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 12

Number of Bolts Torqued Above Range 0 Below Range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) discussed rx #8 of rep #28 9+ 808 An Dust control plan #16

[signature]	36526	T. Moore	33359	
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-18 2010 Section or Area Examined HG#22

Time of Examination: from 12:00 a.m. or p.m. to 2:00 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Dean Jones Time A.M 2:25 P.M.

Report received by Patrick R [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 .30 Ch4 20.8 o2	Needs cleaned & Dusted	Reported
2.			
3.	#2 .20 Ch4 20.8 o2	None Observed	None
4.			
5.	#2R .30 Ch4 20.8 o2	Scrap Out	Reflectors Hung
6.			
7.	#3 .30 Ch4 20.8 o2	Part Bolted	Reflectors Hung
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
LO B .10 Ch4 20.8 o2 0ppm CO	22,237		

Remarks: Power Center
Chargers
Out by shelter
Travel ways
} ok at time of examination
intake phone not working

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 36525 Certificate No. Patrick R [signature] Assistant Foreman 2014-A Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 53359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-18-10 Shift EVE Area or Section HG #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .30 Ch4	Needs Cleaned & Dusted	Cleaned & Dusted
2.	20.8°2		
3.	#2 .20 Ch4	NONE OBserved	NONE
4.	20.8°2		
5.	#2R .30 Ch4	Scrap cut	Fineshed and Bolted
6.	20.8°2		
7.	#3 .30 Ch4	Part Bolted	Bolted
8.	20.8°2		

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-430	.30	11.			
2.			20.8°2	12.			
3.	1-3	6-6:30	.20	13.			
4.			20.8°2	14.			
5.	1-3	8:830	.30	15.			
6.			20.8°2	16.			
7.	1-3	10-10:30	.30	17.			
8.			20.8°2	18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35	.10	6.			
2.			20.8°2	7.			
3.	Return	833	.15	8.			
4.			20.8°2	9.			
5.				10.			

Number of Bolts Tested 15
Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Reveiewed pg. 4 sect 11. MMU and Pg. 5 Sect 17 RC Plan with entire crew 4:25 pm

Patrick R Hilles	2014-A	T. Moore	33359	
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-18 2010 Section or Area Examined HG 22

Time of Examination: from 1000 a.m. or p.m. to 1055 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom Brand Time ____ A.M 1100 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 .30	Part Bolted	reported
2.			
3.	#2 .20	None observed	reported
4.	2 R .20	Scrap	reported
5.	#3 .30	None observed	reported
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Pole	27600		

Remarks: HY power center & chargers fresh air base intake phone

20.802 0% CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 2014A Certificate No. Assistant Foreman Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33359 Kyle Anderson 33238

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-18 Shift 3rd Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .30%	part bolted	Reflectors hung
2.			
3.	#2 .20	N/O	
4.	2R .20	Scrap Cut	Reflectors hung
5.	#3 .30	N/O	
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3 100	1:28	30%	11.			
2.				12.			
3.	1-3 445	524	30%	13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	133	30%	6.			
2.				7.			
3.	Return	529	30%	8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Kyle Anderson — Assistant Mine — 33238 Certificate No.

T. Moore — Mine Foreman-Mine Manager — 33359 Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-19-10 20____ Section or Area Examined HG 22

Time of Examination: from 4:40 a.m. or p.m. to 5:24 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no____

By whom Kyle Anderson Time 5:43 A.M. P.M.

Report received by T. Moore (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Chg	Violation or Hazardous Condition	Chg	Action Taken
1.	1	.20	Part Bolts	2	Reflectors
2.	2	.10	N/O		
3.	2R	.120	Scrap		Reflectors
4.	3	.05	N/O		
5.					
6.					
7.					
8.					
9.					
10.					

Air Measurements

Location	CFM	Location	CFM
L.O.B.	23,630		

Remarks:

Power Center - O.K.
Shelter - O.K.
Int. Phones - Not working
Chargers - O.K.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (Preshift-Mine Examiner) Certificate No. 33238 Assistant Foreman Certificate No.

Countersigned T. Moore (Mine Manager—Mine Foreman) 33357

T. Moore (Assistant Foreman) 33359

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-19-10 Shift 1st Area or Section HC22

Violations and other Hazardous Conditions Observed and Reported

	Location	Chy	Violation or Hazardous Condition	Action taken
1.	1	.20	Part Bolted	Bolted
2.	2	.10	N/O	
3.	2R	.20	Scrap	Bolted
4.	3	.05	Need Chemical	Chemical
5.				
6.				
7.				
8.				

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.				11.			
2.	1-3	8-8:20	.20%	12.			
3.				13.			
4.	1-3	10-10:20	.10%	14.			
5.				15.			
6.	1-3	12-12:20	.20%	16.			
7.	1-3	2-2:20	.10%	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.				6.			
2.	Ret	9:29	.05%	7.			
3.	"	1:02	.20%	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 8

Number of Bolts Torqued Above Range 0 Below Range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken None

Remarks (Statement as to General Conditions of Mine or Area of Mine) Fair. Gone the whole Cur say + nil Control on page 5 of the R.C.P. Buddy check S.C.S.R.s.

Terry Moore	33359	T. Moore	33359	
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-18 20 10 Section or Area Examined #6 22

Time of Examination: from 2:00 a.m. or p.m. to 2:25 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom Terry Moore Time ____ A.M 2:39 P.M.

Report received by Patrick R Gillum (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 .05 CH4 20.8 O2	Scrap cut	Reflectors Hung
2.			
3.	#2R .10 20.8 O2	Needs Cleaned & Dusted	Reported
4.			
5.	#3 .10 20.8 O2	NONE OBSERVED	NONE
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
LOB .0 CH4 20.8 O2 0 ppm CO	20,730		

Remarks: intake phone, travel ways, out by shelter, chargers, power centers — ok at time of examination

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By T. Moore Preshift-Mine Examiner — 33359 Certificate No. — Patrick R Gillum Assistant Foreman — 2014 A Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-16-10 Shift EVE Area or Section AG #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .05 CH4 20.8 O2	Scrap cut	Finished & Bolted
2.			
3.	#2R .10 CH4 20.8 O2	Needs Cleaned & Dusted	Cleaned & Dusted
4.			
5.	#3 .10 CH4 20.8 O2	NONE observed	NONE
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-4:30	.20 CH4 20.8 O2	11.			
2.				12.			
3.	1-3	6-6:30	.20 CH4 20.8 O2	13.			
4.				14.			
5.	1-3	8:-8:30	.10 CH4 20.8 O2	15.			
6.				16.			
7.	1-3	10:-10:30	.20 CH4 20.8 O2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35P	.10 CH4 20.8 O2	6.			
2.				7.			
3.	Return	8:34P	.05 20.8 O2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 20

Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Discussed pg. 5 sect. 2 of Rk Plan and pg. 4 sect. 2 MMU Plan with entire crew 4:05 PM

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant
Paul [illegible]	2044A	T. Moore	33359	

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-19 2010 Section or Area Examined HG 2D

Time of Examination: from 1600 a.m. or p.m. to 1655 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Palucka Time A.M 1105 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1, 20	None Observed	
2.	1R, 20	Post Bolted	Reflectors
3.	#2, 10	Scrap Cut	Reflectors
4.			
5.	#3, 30	None Observed	
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Pob	23560		

Remarks: 30 HV power center, chargers fresh air base
20, 8 intake phone Clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Patrick Palucka (Preshift-Mine Examiner) Certificate No. 2014-A

Countersigned T. Moore (Mine Manager—Mine Foreman) Certificate No. 33359

Kyle Anderson (Assistant Foreman) Certificate No. 33228

(Assistant Foreman)

(Superintendent or Assistant)

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-19 Shift 3rd Area or Section HG 20

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .20	N/O	
2.	1R .20	Part bolted	Reflectors
3.	#2 .10	Scrap Cut	Reflectors
4.			
5.	#3 .30	N/O	
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3 1250	102	.30% CH4	11.			
2.				12.			
3.	1-3 450	520	.30% CH4	13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	130	.30% CH4	6.			
2.				7.			
3.	Return	535	.30% CH4	8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Kyle Anderson	33238	T. Moore	33309	
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-20-10 20__ Section or Area Examined H622

Time of Examination: from 4:50 a.m. or p.m. to 5:30 a.m. or p.m.

Was this report phoned to outside: Yes ___ no ___

By whom Kyle Anderson Time 5:30 A.M ___ P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4 %	Violation or Hazardous Condition	O2	Action Taken	CO
1.	1	.50	needs add chg	20.8	Rep	.0
2.	1 Int	.55	not bolted	20.8	Reflection	.0
3.	2	.20	Scrap cut	20.8	Reflection	.0
4.	3	.20	none obs	20.8	[illegible]	.0
5.						
6.						
7.						
8.						
9.						
10.						

Air Measurements

Location	CFM	Location	CFM
COB	21,474		

Remarks: .0-.55 CH4 20.8 O2 .0 CO detected
Trolleys & Holeys ok at time of Exam
P.C. and Chg ok

Shelter Chamber ok
Intake Phone

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (Preshift-Mine Examiner) 33238 (Certificate No.) [signature] (Assistant Foreman) 3602 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-20-0 Shift Mey Area or Section 1+622

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1	needs all dry	dry
2.	Int	not Bo Hu	Bo Hu
3.	2	Scrap cut	dedup Bo Hu
4.	3	nee OCS	nil
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content %		Location	Time	Methane Content
1.	1-3	7:00 7:00	.20	11.			
2.		9:00		12.			
3.	1-3	9:00	.20	13.			
4.		11:00		14.			
5.	1-3	11:00	.20	15.			
6.		1:00		16.			
7.	1-3	1:00	.20	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content %		Location	Time	Methane Content
1.	Left	8:00	.20	6.			
2.				7.			
3.	Left	12:00	.20	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 6

Number of Bolts Torqued Above Range 0 Below Range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) discussed Rt 4 of Rept 8 at 6:38 Am Dust Control plan 20, 21

[signature] Assistant Mine | 36125 Certificate No. | T. Moore Mine Foreman-Mine Manager | 33389 Certificate No. | Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-20 10 20 10 Section or Area Examined HG 22

Time of Examination: from 1200 a.m. or p.m. to 1200 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom D. Jones Time A.M 225 P.M.

Report received by John A. Bedford (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1	ch4 .35 Needs cleaned	Reported
2.	#1 Rt	.35 Needs cleaned & dusted	Reported
3.	#2	.20 Scrap -10	Reported & Reflectors Hung
4.	#3	.10 None Observed	None
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
L.O.B.	20206		

Remarks: 0% ch4 0% CO + 20.8% O2 detected

Travelways, PC, Chargers OK at time of exam

Shelter + Intake Plow - OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 36028

Countersigned T. Moore Mine Manager—Mine Foreman — Certificate No. 33357 — John A. Bedford Assistant Foreman — Certificate No. 26776

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-20-10 Shift EVE Area or Section HG#22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .35 CH4	needs Cleaned	Cleaned
2.	20.8 O2		
3.	#1R .35 CH4	needs Cleaned+Dusted	cleaned+Dusted
4.	20.8 O2		
5.	# 2 .20 CH4	scrap Cut	Finished & Bolted
6.	20.8 O2		
7.	#3 .10	NONE Observed	NONE
8.	20.8 O2		

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-430	.20 CH4	11.			
2.		20.8 O2		12.			
3.	1-3	6-6:30	.20 CH4	13.			
4.		20.8 O2		14.			
5.	1-3	8:-8:30	.30 CH4	15.			
6.		20.8 O2		16.			
7.	1-3	10-10:30	.20 CH4	17.			
8.		20.8 O2		18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35	.10 CH4	6.			
2.			20.8 O2	7.			
3.	Return	8:34	.10 CH4	8.			
4.			20.8 O2	9.			
5.				10.			

Number of Bolts Tested 30
Number of Bolts Torqued Above Range Ø Below Range Ø

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken ~~Received pg~~

Remarks (Statement as to General Conditions of Mine or Area of Mine) Reveiwed pg. 4 Sect 17 MMU Plan and pg. 4 Sect. 7 RC Plan with entire crew at 405 PM

David R Miller — Assistant Mine Foreman
2014-A — Certificate No.
T. Moore — Mine Foreman-Mine Manager
3339-9 — Certificate No.
Superintendent or Assistant Superintendent

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-20 2010 Section or Area Examined HG 22

Time of Examination: from 1060 a.m. or p.m. to 1055 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Patrick Time A.M 1115 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location		Violation or Hazardous Condition	Action Taken
1.	#1	.20	Part Bolted	Reflectors hung
2.	#2	.10	Scrap Cut	Reflectors
3.	#2R	.20	Needs Cleaned dusted	Reported
4.				
5.	#3	.20	None Observed	
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Pab	21,240		

Remarks: .20 CH4 power center and chargers fresh air base intake phone Clear at time of exam 20.8

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Patrick R Anderson (Preshift-Mine Examiner) Certificate No. 2014A 33359 Assistant Foreman Kyle Anderson Certificate No. 33238

Countersigned T. Moore (Mine Manager—Mine Foreman)

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-20 Shift 3rd Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .20%	Part bolted	Reflectors
2.			
3.	#2 .10%	Scrap Cut	Reflectors
4.	2R .20%	needs cleaned rdusted	Reported
5.			
6.	#3 .20%	N/O	
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3 1245	110	.20%	11.			
2.				12.			
3.	1-3 445	524	.20%	13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	118	.20%	6.			
2.				7.			
3.	Return	530	.20%	8.			
4.				9.			
5.				10.			

Number of Bolts Tested
Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Kyle Anderson — Assistant Mine — 33238 Certificate No.

T. Moore — Mine Foreman-Mine Manager — 33359 Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-21 20 10 Section or Area Examined Headgate #22

Time of Examination: from 445 a.m. or p.m. to 524 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Kyle Anderson Time 438 A.M. P.M.

Report received by Brandon Bowery (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 + 1R CC OCHY!	Needs Cleaned + Dusted	Reported
2.	20.80z		
3.	#2 Entry OCHY!	Not Bolted	Reflectors
4.	20.80z		
5.	#3 Entry OCHY!	None Observed	Reported
6.	20.80z		
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	21,254		

Remarks: Power Center
Chargers
Travelways
Intake Phone
Outby Chamber

All ok at time of exam.
OCHY! 20.80z OPPM C/O

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (Preshift-Mine Examiner) 33238 (Certificate No.) Brandon Bowery (Assistant Foreman) 1122-A (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-21-10 Shift Day Area or Section Headgate #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 + 1R CC .10 CH4, 20.8 O2	Needs Cleaned + Dusted	Cleaned + Dusted
2.			
3.	#2 Entry .15 CH4, 20.8 O2	Not Bolted	Bolted + Reflectors
4.			
5.	Cable bolted #2 INT		
6.	Rib bolting entry's - Ribs		
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7-730 AM	.15 CH4, 20.8 O2	11.			
2.				12.			
3.	1-3	9-930 AM	.15 CH4, 20.8 O2	13.			
4.				14.			
5.	1-3	11-1130 AM	.10 CH4, 20.8 O2	15.			
6.				16.			
7.	1-3	1-150 PM	.15 CH4 to .2 CH4, 20.8 O2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	715 AM	.2 CH4, 20.8 O2	6.			
2.				7.			
3.	Return	1114 AM	.2 CH4, 20.8 O2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 7
Number of Bolts Torqued Above Range ——— Below Range ———

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Pg. 3 MMU sect. 14 PCP pg. 5 Sect 5 at 638 AM. SCSRS OK.

Brad Berg — Assistant Mine; 1122-A — Certificate No.; T. Moore — Mine Foreman-Mine Manager; 33359 — Certificate No.; Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-21 2010 Section or Area Examined HG#22

Time of Examination: from 1:00 a.m. or p.m. to 1:50 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom Brandon Bowling Time ____ A.M 2:33 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 .10 CH4 20.8 O2	Needs Cleaned	Reported
2.			
3.	#2 .15 CH4 20.8 O2	NONE Observed	NONE
4.			
5.	#3 .20 CH4 20.8 O2	Scrap Cut	Reported Reflectorline
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
LOB .0 CH4 20.8 O2	2150		
0 ppm CO			

Remarks: Outby Shelter, intake phone, power center, Chargers, travelways } all ok at time of examination.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 33359 — [signature] Assistant Foreman — Certificate No. 2014-A

Countersigned [signature] Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-21-10 Shift EVE Area or Section HG #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .10 CH4 20.8 O2	Needs Cleaned	Cleaned
2.			
3.	#2 .15 CH4 20.8 O2	NONE Observed	NONE
4.			
5.	#3 .20 CH4 20.8 O2	Scrap cut	finished & Bolted
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-4:30	.20 CH4 20.8 O2	11.			
2.				12.			
3.	1-3	6-6:30	.10 CH4 20.8 O2	13.			
4.				14.			
5.	1-3	8:-8:30	.10 CH4 20.8 O2	15.			
6.				16.			
7.	1-3	10-10:30	.10 CH4 20.8 O2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35	.05 CH4 20.8 O2	6.			
2.				7.			
3.	Return	8:34	.05 CH4 20.8 O2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 15

Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Reviewed pg 4 Sect 9 MMU Plan and pg 4 Sect 9 RC Plan with entire Crew at 4:05 pm

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant
[illegible]	2014-A	[illegible]	33359	

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-21 2010 Section or Area Examined H.G. 22

Time of Examination: from 10:00 a.m. or p.m. to 10:55 a.m. or p.m.

Was this report phoned to outside: Yes ✓ No

By whom [illegible] Pat Hilbert Time A.M 11:15 P.M.

Report received by [illegible] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	1	.20	n/o	—
2.	2	.10	n/o	—
3.	2xr	.10	n/o	—
4.	3	.10	scrap	Reflectored
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
LOB	23,560		

Remarks: Trackways & Haulways clean at Time of Exam
Power Center & Charger — n/o
Air Chamber — OK
Intake Phone — OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [illegible] Preshift-Mine Examiner 2014-A Certificate No. [illegible] Assistant Foreman 32294 Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33354

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-22-10 Shift 3RD Area or Section H.C. 22

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.	3	scrap	Bolted
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

No Production

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant
	32284	T. Moore	33359	

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-22 20 10 Section or Area Examined Headgate #22

Time of Examination: from 330 a.m. or p.m. to 430 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Kenny Farmer Time 435 A.M P.M.

Report received by Branch Boney (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 Entry .2 CH4! 20.802	None Observed	Reported
2.			
3.	#2 + 2R CC .1 CH4! 20.802	None Observed	Reported
4.			
5.	#3 Entry .2 CH4! 20.802	None Observed	Reported
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	23,520		

Remarks: Power Center
Chargers
Travelways
Outby Shelter
Intake Phone
} All ok at time of exam.
.2 CH4. Detected 0 PPM c/o 20.802

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32254 — Branch Boney Assistant Foreman — Certificate No. 1122-A

Countersigned T. Moore Mine Manager—Mine Foreman — 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-22-10 Shift Day Area or Section Headgate #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1-3 Entry's .16 CH4!	None Observed	Reported
2.			
3.	20.80 O2 to .2 CH4!		
4.	Reported		
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7-730am	.2 CH4! 20.8 O2	11.			
2.				12.			
3.	1-3	9-930am	.2 CH4! 20.8 O2	13.			
4.				14.			
5.	1-3	11-1130am	.2 CH4! 20.8 O2	15.			
6.				16.			
7.	1-3	1-200pm	.2 CH4! 20.8 O2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	715am	.05 CH4! 20.8 O2	6.			
2.				7.			
3.	Return	1114pm	.05 CH4! 20.8 O2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 5
Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Pg 1 MMU RB and CM Air and MEAV review. Pg. 5 Sect 1.7 RCR at 645am.

[signature] Assistant Mine — 1122-A Certificate No. — T. Moore Mine Foreman-Mine Manager — 3337 Certificate No. — Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-22 20 10 Section or Area Examined HG #22

Time of Examination: from 1:00 a.m. or p.m. to 2:00 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom Brandon Bowling Time ____ A.M 235 P.M.

Report received by Patrick R Hilliard (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 .10 ch4	Part Bolted	Reported / Reflectors,
2.	20.8 o2		
3.	# 2 .15 ch4	NONE OBserved	NONE
4.	20.8 o2		
5.	#2R .15 ch4	NONE OBserved	NONE
6.	20.8 o2		
7.	#3 .20 ch4	Scrap cct	Reported Reflectorshing
8.	20.8 o2		
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
LOB 0 ch4	22520		
20.8 o2			
0 ppm Co			

Remarks: Power center, Chargers, travelways, outby shelter — all ok at time of examination

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Brandon Bowling (Preshift-Mine Examiner) 1122-A (Certificate No.) Patrick R Hilliard (Assistant Foreman) 2014-A (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 3335-A

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-22-10 Shift EVE Area or Section HG#22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .10 CH4	Part/Bolted	Bolted
2.	20.8 O2		
3.	#2 .15 CH4	NONE observed	NONE
4.	20.8 O2		
5.	#2R .15 CH4	NONE observed	NONE
6.	20.8 O2		
7.	#3 .20 CH4	Scrap cut	Finished & Bolted
8.	20.8 O2		

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-4:30	.15 CH4	11.			
2.			20.8 O2	12.			
3.	1-3	6-6:30	.10 CH4	13.			
4.			20.8 O2	14.			
5.	1-3	8-8:30	.10 CH4	15.			
6.			20.8 O2	16.			
7.	1-3	10-10:30	.10 CH4	17.			
8.			20.8 O2	18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35	.05 CH4	6.			
2.		~~8:35~~	20.8 O2	7.			
3.	Return	8:35	.05 CH4	8.			
4.			20.8 O2	9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) Reviewed pg. 4 Sect. 6 Mine Plan and pg. 5 Sect. 19 Roof control plan with entire crew 4:05 PM

Patrick Miller	2014-A	T. Mu[illegible]	33339	
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-22 2018 Section or Area Examined H.G. 22

Time of Examination: from 10:00 a.m. or p.m. to 1:00 a.m. or p.m.

Was this report phoned to outside: Yes ___ no ___

By whom Patrick Hiller Pt Time ___ A.M 11:15 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	#1	.10	n/o	—
2.	2	.10	n/o	—
3.	2xr	.10	scrap	Reflectorl
4.	3	.20	n/o	—
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
LOB	22,480		

Remarks: Travelways & Haulways clear at time of exam
Power Center - n/o
Changers - n/o
Air Lock - ok
Intake Phone - ok

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Patrick R Hiller (Preshift-Mine Examiner) 2014A (Certificate No.) [signature] (Assistant Foreman) 32291 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Superintendent or Assistant

Date [illegible] Shift [illegible] Area or Section [illegible]

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	2XR	scrap	Refinished
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.				11.			
2.				12.			
3.		NO		13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant
	32294		33389	

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-23 2010 Section or Area Examined Headgate #22

Time of Examination: from 300 a.m. or p.m. to 330 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Kenny Farmer Time 523 A.M. P.M.

Report received by Brandon Bonny (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 Entry, 2 CH4, 20.802	None Observed	Reported
2.			
3.	#2 Entry, 1 CH4, 20.802	Needs Add Cleaning	Reported
4.			
5.	#2 RCC, 1 CH4, 20.802	Scrap Cut	Reflectors
6.			
7.	#3 Entry, 1 CH4, 20.802	None Observed	Reported
8.			
9.	OPPm c/o		
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	15,800		

Remarks: Power Centers, Travelways, Chargers, Intake Phone, Outby Chambers — All ok at time of exam. 2 CH4, detected in face areas, 0 CH4, 20.802 OPPm c/o

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32294 — Brandon Bonny Assistant Foreman — Certificate No. 1122-A

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-23-10 Shift Day Area or Section Headgate #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#2 Entry .10CH4% 20.8oz	Needs Add Cleaning	Cleaned + Dusted
2.			
3.	#2R CC .15CH4% 20.8oz	Scrap Cut	Bolted + Reflectors
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7-730Am	.10CH4% 20.8oz	11.			
2.				12.			
3.	1-3	9-930Am	.10CH4% 20.8oz	13.			
4.				14.			
5.	1-3	11-1130Am	.15CH4% 20.8oz	15.			
6.				16.			
7.	1-3	1-200pm	.25CH4% 20.8oz	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	715Am	.10CH4% 20.8oz	6.			
2.				7.			
3.	Return	1115Am	.10CH4% 20.8oz	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 7

Number of Bolts Torqued Above Range ——— Below Range ———

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Pg. 2 mine sect 3 RCP Pg. 4 Sect 8 at 640 Am

[signature] 1122-A T. Moore 33359

Assistant Mine | Certificate No. | Mine Foreman-Mine Manager | Certificate No. | Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-23 20 10 Section or Area Examined AG 22

Time of Examination: from 1:00 a.m. or p.m. to 2:00 a.m. or p.m.

Was this report phoned to outside: Yes ___ no ___

By whom Brandon Bowling Time ___ A.M ___ P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 .25 ch4 20.8 o2	Needs Cleaned	Reported
2.			
3.	#2 .10 ch4 20.8 o2	Scrap cut	Reflectors Hung
4.			
5.	#3 .10 ch4 20.8 o2	NONE observed	NONE
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
LOB 0 ch4 20.8 o2 0ppm CO	18,050		

Remarks: Power center Chargers intake phone travel ways } all ok at time of examination

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1122-A Certificate No. [signature] Assistant Foreman 2014-A Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33357

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-23-10 Shift EVE Area or Section #6 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1. .25 Ch4	Needs Cleaned	Cleaned
2.	20.8 02		
3.	#2 .10 Ch4	Scrap cut	finished & Bolted
4.	20.8 02		
5.	#3 .10 Ch4	NONE Observed	NONE
6.	20.8 02		
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-4:30	.10	11.			
2.			20.8 02	12.			
3.	1-3	6-6:30	.10	13.			
4.			20.8 02	14.			
5.	1-3	8-8:30	.15	15.			
6.			20.8 02	16.			
7.	1-3	10-10:30	.10	17.			
8.			20.8 02	18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35	.05	6.			
2.		~~8:35~~	20.8 02	7.			
3.	Return	8:35	.05	8.			
4.			20.8 02	9.			
5.				10.			

Number of Bolts Tested 20 Ø

Number of Bolts Torqued Above Range _____ Below Range Ø

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) Reviewed pg 4 Sect 8 MMU and pg 5 Sect 17, 18 with entire crew at 405 pm

Patrick R Hilbert	2014-A	T. Moore	33359	
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-23 2010 Section or Area Examined HG 22

Time of Examination: from 1000 a.m. or p.m. to 1055 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Patrick Time A.M 1115 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 .10%	Scrap Cut	Reflectors hung
2.			
3.	#2 .10%	Needs Cleaned	Reported
4.			
5.	#3 .15%	None Observed	
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Lab	20040		

Remarks: .15 cHY power center, chargers intake, phone fresh air base 208 Clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 20444 — Assistant Foreman — Certificate No. 33238

Countersigned [signature] Mine Manager—Mine Foreman — 33389 — Kyle Anderson

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-23 Shift 3rd Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .10%	Scrap Cut	Reflectors hung
2.			
3.	#2 .10%	needs cleaned	Reported
4.			
5.	#3 .10%	N/O	Reported
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3 110	138	.10%	11.			
2.				12.			
3.	1-3 430	512	.10%	13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	144	.10%	6.			
2.				7.			
3.	Return	518	.10% CH4	8.			
4.				9.			
5.				10.			

Number of Bolts Tested
Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Kyle Anderson — Assistant Mine
33238 — Certificate No.
T. Moore — Mine Foreman-Mine Manager
3375-9 — Certificate No.
Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-24-10 20___ Section or Area Examined 1H622

Time of Examination: from 4:30 a.m. or p.m. to 5:12 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no_____

By whom Kyle Anderson Time 5:23 A.M _____ P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4%	Violation or Hazardous Condition	O2	Action Taken	
1.	1	.35	none obs	20.8	nil	0
2.	Int	.35	not Bolting	20.8	reflected	0
3.	2	.05	none obs	20.8	nil	0
4.	3	.0	none obs	20.8	nil	0
5.						
6.						
7.						
8.						
9.						
10.						

Air Measurements

Location	CFM	Location	CFM
Cub	20,660		

Remarks: .0-.35 CH4 20.8 O2 .0 CO detected Trailings & Heavy OK at time of Exam P.C. and Chargers OK.

Shelter Chamber OK
Intake Plane

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (Preshift-Mine Examiner) 33238 (Certificate No.) [signature] (Assistant Foreman) 36025 (Certificate No.)

Countersigned [signature] (Mine Manager—Mine Foreman) 33389

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-24-10 Shift Mg Area or Section H622

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1	none obs	Mg
2.	1 Int	not Bolted	Bolted
3.	2	none obs	Mg
4.	3	none obs	Mg
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7:00 7:00	.20	11.			
2.		9:00		12.			
3.	1-3	9:00	.20	13.			
4.		11:00		14.			
5.	1-3	11:00	.20	15.			
6.		1:00		16.			
7.	1-3	1:00	.20	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Int	8:00	.20	6.			
2.				7.			
3.	Int	12:00	.20	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 10

Number of Bolts Torqued Above Range 0 Below Range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) discussed rpt #5 of Rep #29 at 6:40 Am Dust control/pm 18,19.

[signature] Assistant Mine | 36025 Certificate No. | T. [signature] Mine Foreman-Mine Manager | 33354 Certificate No. | Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-24 20 10 Section or Area Examined Headgate #22

Time of Examination: from 1200 a.m. or p.m. to 200 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Deano Jones Time A.M 240 P.M.

Report received by Brian Berry (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 Entry .35 CH4.	Needs Cleaned + Dusted	Reported
2.	20.8 O2		
3.	#1R CC .35 CH4.	Part Bolted	Reported
4.	20.8 O2		
5.	#2R CC .20 CH4.	Scrap Cut	Reflectors
6.	20.8 O2		
7.	#3 Entry .20 CH4.	Needs Cleaned + Dusted	Reported
8.	20.8 O2		
9.	OPPMC/O		
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	22,346		
20.8 O2			
OPPMC/O			

Remarks: Power Center
Travelways
Chargers
Intake Phone
Outby Charger
.35 CH4. detected face areas -

All ok at time of exam
0 CH4, 20.8 O2 OPPMC/O

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 36052 — Brian Berry Assistant Foreman — Certificate No. 1122-A

Countersigned T. Moore Mine Manager—Mine Foreman — 33757

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-24-10 Shift EVE Area or Section Headgate #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 Entry .25CH4% 20.8oz	Needs Cleaned & Dusted	Cleaned & Dusted
2.			
3.	#1RCC .3CH4% 20.8oz	Part Bolted	
4.			
5.	#2RCC .25CH4% 20.8oz	Scrap Cut	
6.			
7.	#3 Entry .3CH4% 20.8oz	Needs Cleaned & Dusted	
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-430pm	.3CH4% 20.8oz	11.			
2.				12.			
3.	1-3	6-630pm	.3CH4% 20.8oz	13.			
4.				14.			
5.	1-3	8-830pm	.3CH4% 20.8oz	15.			
6.				16.			
7.	1-3	10-1100pm	.3CH4% 20.8oz	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	415pm	.10CH4% 20.8oz	6.			
2.				7.			
3.	Return	814pm	.10CH4% 20.8oz	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 10

Number of Bolts Torqued Above Range ——— Below Range ———

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Bottom Busted - Roadways, Soft Ribs Pg. 2 MMV Sect 5 Pg. 4 Sect 10 RCP at 340pm.

Brad Bong — Assistant Mine; 1122-A — Certificate No.; T. Moore — Mine Foreman-Mine Manager; 33357 — Certificate No.; Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-24 2010 Section or Area Examined HG 22

Time of Examination: from 1000 a.m. or p.m. to 400 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Brandon Time A.M 1118 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location		Violation or Hazardous Condition	Action Taken
1.	#1	.25	Part Bolted	Reflectors hung
2.	R	.30	Scrap Cut	Reflectors hung
3.	#2	.25	None Observed	
4.	R	.25	None observed	
5.	#3	.30	Part Bolted	Reflectors hung
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Job	21727		

Remarks: 30% power center & charger intake phone fresh air base 208 Clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Brad [signature] Preshift-Mine Examiner 1122-A Certificate No. Assistant Foreman Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33359 Kyle Anderson 33238

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-24 Shift 3rd Area or Section HC 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .25%	Part bolted	Reflectors hung
2.	1R .30%	Scrap Cut	Reflectors hung
3.	#2 .25%	None observed	
4.	2R .25%	none observed	
5.	#3 .30%	Part bolted	Reflectors hung
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3 1240	115	30%	11.			
2.				12.			
3.	1-3 450	535	30%	13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	122	.30%	6.			
2.				7.			
3.	Return	941	.30%	8.			
4.				9.			
5.				10.			

Number of Bolts Tested
Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Kyle Anderson — Assistant Mine
33238 — Certificate No.
T. Moore — Mine Foreman-Mine Manager
33357 — Certificate No.
Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-25-10 20___ Section or Area Examined H622

Time of Examination: from 4:50 a.m. or p.m. to 5:35 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no ___

By whom Kyle Anderson Time 5:40 A.M ___ P.M.

Report received by Dean Jones (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CHY %	Violation or Hazardous Condition	O2	Action Taken	CO
1.	1	.05	not Bolted	20.80	reflecter	0
2.	2	.0	none obs	20.8	nil	0
3.	2nd	.05	none obs	20.8	nil	0
4.	3	.25	not Bolted	20.8	reflecter	0
5.						
6.						
7.						
8.						
9.						
10.						

Air Measurements

Location	CFM	Location	CFM
LOB	18,208		

Remarks: .0 - .25 CHY 20.8 O2 .0 CO detectors Trailings 2 Hrlings ok at time of Exm p.c. and Chargers ok.

Shelter Chamber
Intake phone } ok

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (Preshift-Mine Examiner) 33238 (Certificate No.) [signature] (Assistant Foreman) 36526 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33357

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-25-10 Shift Day Area or Section H622

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1	Not Bolted	Bolted
2.	2	none obs	nil
3.	2nt	nee obs	nil
4.	3	not Bolted	Bolted
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

10

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7:00 7:00	.20	11.			
2.		9:00		12.			
3.	1-3	9:00	.20	13.			
4.		11:00		14.			
5.	1-3	11:50	.20	15.			
6.		7:00		16.			
7.	1-3	11:50	.20	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

8 10

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Ret	8:00	.20	6.			
2.				7.			
3.	Ret.	12:00	.20	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 10

Number of Bolts Torqued Above Range 0 Below Range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) discussed rept # 15 Dt Rep #1,2 Niche at 6:40 AM Dust control Plan 13,

[signature] Assistant Mine — 36525 Certificate No. — [signature] Mine Foreman-Mine Manager — 38759 Certificate No. — Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-25 20 10 Section or Area Examined Headgate #22

Time of Examination: from 1200 a.m. or p.m. to 200 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Deano Jones Time A.M 240 P.M.

Report received by Brian Berry (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. #1 Entry . 20 CH4	Scrap Cut	Reflectors
2. 20.8 O2		
3. #2 Entry . 10 CH4	None Observed	Reported
4. 20.8 O2		
5. #2 R CC . 10 CH4	Part Bolted	Reflectors
6. 20.8 O2		
7. #3 Entry . 20 CH4	Needs Cleaned + Dusted	Reported
8. 20.8 O2		
9. OPPn c/o		
10.		

Air Measurements

Location	CFM	Location	CFM
LOB	22,985		
20.8 O2			
OPPn c/o			

Remarks: Power Center
Chargers
Traveloways
Outby Shelter
Intake Phone
All ok at time of exam.
. 20 CH4, detected in faces
0 CH4, 20.8 O2 OPPn c/o

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner Certificate No. _____ Brian Berry Assistant Foreman 1122-A Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman Certificate No. 33389

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-25-10 Shift EVE Area or Section Headgate #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 Entry .20CH4, 20.8oz	Scrap Cut	Bolted + Reflectors
2.			
3.	#2R CC .10CH4, 20.8oz	Part Bolted	Bolted + Reflectors
4.			
5.	#3 Entry .20CH4, 20.8oz	Needs Cleaned + Dusted	Cleaned + Dusted
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-430pm	.20CH4, 20.8oz	11.			
2.				12.			
3.	1-3	6-630pm	.20CH4, 20.8oz	13.			
4.				14.			
5.	1-3	8-830pm	.25CH4, 20.8oz	15.			
6.				16.			
7.	1-3	10-1100	.25CH4, 20.8oz	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	415pm	.10 CH4 20.8oz	6.			
2.				7.			
3.	Return	814pm	.05 CH4 20.8oz	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 8

Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Pg. 2 MMU sect 5

Pg. 3 sect A RCP at 340 pm.

[signature] Assistant Mine — 1122-A Certificate No. — [signature] Mine Foreman-Mine Manager — 33359 Certificate No. — Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-25 2010 Section or Area Examined #6 22

Time of Examination: from 1000 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Brandon Time A.M 1120 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 , 25	Water in face	Reported
2.			
3.	#2 , 20	Scrap Cut	Reflectors hung
4.			
5.	#3 , 20	None Observed	
6.			
7.		Roadway heated up	Reported
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Pot	21786		

Remarks: 25 cfm power center & charging fresh air base intake phone 208 Clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 1122-A

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 37389

Kyle Anderson Assistant Foreman — Certificate No. 33238

Assistant Foreman

Superintendent or Assistant

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

[illegible] Shift 3rd Area or Section HG22

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
#1 .25	Water in face	Reported
#2 .20	Scrap Cut	Reflectors hung
#3 .20	N/O	

Examinations for Methane in Working Places

Location	Time	Methane Content		Location	Time	Methane Content
1-3 118	144	.25%	11.			
			12.			
1-3 450	535	.25%	13.			
			14.			
			15.			
			16.			
			17.			
			18.			
			19.			
			20.			

Examinations for Methane in Return Aircourses

Location	Time	Methane Content		Location	Time	Methane Content
Return	150	.25%	6.			
			7.			
Return	538	.25%	8.			
			9.			
			10.			

[illegible] of Bolts Tested _____

[illegible] of Bolts Torqued Above Range _____ Below Range _____

[illegible] majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

[illegible] (Statement as to General Conditions of Mine or Area of Mine) _____

[illegible] Anderson	33238	T. Moore	33389	
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-26-10 20.... Section or Area Examined H622

Time of Examination: from 4:00 a.m. or p.m. to 5:30 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no.....

By whom Kyle Anderson Time 5:42 A.M ..... P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4 %	Violation or Hazardous Condition		Action Taken	
1.	1	.20	H2O	20.8 O2	non	.0
2.	2	.0	part Bolted	20.8	reflective	.0
3.	3	.0	none JCU	20.8	none	.0
4.						
5.						
6.						
7.						
8.						
9.						
10.						

Air Measurements

Location	CFM	Location	CFM
COB	29,680		

Remarks: .0-.20 CH4 20.8 O2 .0 CO detected
Trailings: Hillings ok at time of Exam
p.c. and Clean ok,

Shelter Chamber JOK
Intake Phone

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (Preshift-Mine Examiner) 33238 (Certificate No.) [signature] (Assistant Foreman) 3682 (Certificate No.)

Countersigned [signature] (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-26-10 Shift Nuy Area or Section H622

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1	H2O	Loaded Heart
2.	2	Part Bolting	Bolting
3.	3	Nee CGS	Nuy
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7:00 7:50	.20	11.			
2.		9:00		12.			
3.	1-3	9:50	.20	13.			
4.		11:00		14.			
5.	1-3	11:50	.20	15.			
6.		1:00		16.			
7.	1-3	1:50	.20	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Let	8:00	.20	6.			
2.				7.			
3.	Let	12:00	.20	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 14
Number of Bolts Torqued Above Range 0 Below Range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) discussed page # 4 of Rep #7 at 6:36 A.m. Dust Control Plan 3.

[signature] Assistant Mine | 3652r Certificate No. | T. Moore Mine Foreman-Mine Manager | 33357 Certificate No. | Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-26 20 10 Section or Area Examined Headgate #22

Time of Examination: from 1200 a.m. or p.m. to 200 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Reano Jones Time A.M P.M.

Report received by Brandon Bonny (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 Entry . 20 CH4	Part Bolted	Reflectors
2.	20.8 O2		
3.	#2 Entry . 10 CH4	Needs cleaned + dusted	Reported
4.	20.8 O2		
5.	#3 Entry . 30 CH4	Scrap Cut	Reflectors
6.	20.8 O2		
7.	OPPM C/O		
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	21,976		
20.8 O2			
OPPM C/O			

Remarks: Power Center
Chargers
Travelways
Intake Phone
Outby Chamber

All OK at time of exam.
0 CH4 20.8 O2 OPPM C/O

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 36826 — Brandon Bonny Assistant Foreman — Certificate No. 1122-A

Countersigned [signature] Mine Manager—Mine Foreman — 53389

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-26-10 Shift EVE Area or Section Headgate #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 Entry .20CH4% 20.8O2	Part Bolted	Bolted + Reflectors
2.			
3.	#2 Entry .10CH4% 20.8O2	Needs Cleaned + Dusted	Cleaned + Dusted
4.			
5.	#3 Entry .30CH4% 20.8O2	Scrap Cut	Bolted + Reflectors
6.			
7.	#2 Int. .10CH4% 20.8O2	L-Inby Corner not Bolted	spotted 3 Torque bolts in ribs
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-430pm	.20CH4% 20.8O2	11.			
2.				12.			
3.	1-3	6-630pm	.20CH4% 20.8O2	13.			
4.				14.			
5.	1-3	8-830pm	.20CH4% 20.8O2	15.			
6.				16.			
7.	1-3	10-1050pm	.20CH4% 20.8O2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	410PM	.10CH4% 20.8O2	6.			
2.				7.			
3.	Return	810pm	.10CH4% 20.8O2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 10
Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Pg. 3 sect c RCP at 350pm
MMU Plan Pg. 2 Sect 5 341pm.

Assistant Mine — Certificate No. 1122-A — Mine Foreman-Mine Manager — Certificate No. 3787 — Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-26 2010 Section or Area Examined HG 22

Time of Examination: from 1000 a.m. or p.m. to 1050 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Brandon Time A.M 1110 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location		Violation or Hazardous Condition	Action Taken
1.	1	.20	Needs cleaned dusted	Reported
2.	R	.20	Not Bolted	Reflectors hung
3.	2	.10	None Observed	
4.				
5.	3	.10	None Observed	
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Job	21,170		

Remarks: .20 cHx power center & chargers intake phone fresh air base Clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 1122-A — Assistant Foreman — Certificate No.

Countersigned T. Maine Mine Manager—Mine Foreman — 33357 — Kyle Anderson — 33238

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-26 Shift 3rd Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location		Violation or Hazardous Condition	Action taken
1.	1	.20	needs cleaned & dusted	Reported
2.	1R	.20	not bolted	Reflectors
3.	2	.10	N/O	
4.	3	.10	N/O	
5.				
6.				
7.				
8.				

Examinations for Methane in Working Places

	Location		Time	Methane Content		Location	Time	Methane Content
1.	1-3	112	136	.20%	11.			
2.					12.			
3.	1-3	403	447	.45%	13.			
4.					14.			
5.					15.			
6.					16.			
7.					17.			
8.					18.			
9.					19.			
10.					20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	140	.20%	6.			
2.				7.			
3.	Return	450	.0% cH4	8.			
4.				9.			
5.				10.			

Number of Bolts Tested

Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant
Kyle Anderson	33238	T. Moore	33357	

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-27-10 20___ Section or Area Examined H622

Time of Examination: from 4:02 a.m. or p.m. to 4:47 a.m. or p.m.

Was this report phoned to outside: Yes ___ no ___

By whom Kyle Anderson Time 5:10 A.M ___ P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CHY%	Violation or Hazardous Condition	O2	Action Taken	
1.	1	.05	none obs	20.8	none	.0
2.	Int	.45	part Bolters	20.8	reflector	.0
3.	2	.0	none obs	20.8	none	.0
4.	3	.0	none obs	20.8	none	.0
5.						
6.						
7.						
8.						
9.						
10.						

Air Measurements

Location	CFM	Location	CFM
Cob	20,970		

Remarks: .0 - .45 CHY 20.8 O2 .0CO detected Trolleys & Hillers OK at time of Exm p.c. and Charger OK.

Shelter Chamber OK
Intake Plane

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 33238 Certificate No. [signature] Assistant Foreman 36022 Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-27-10 Shift Ny Area or Section H622

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1	None obs	None
2.	1 Ht	part Bolting	Bolting
3.	2	None obs	None
4.	3	None obs.	None
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content %		Location	Time	Methane Content
1.	1-3	7:00 7:50	.20	11.			
2.		9:00		12.			
3.	1-3	9:50	.20	13.			
4.				14.			
5.	1-3	11:00 11:50	.20	15.			
6.				16.			
7.	1-3	1:00 1:50	.20	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content %		Location	Time	Methane Content
1.	Ht	8:00	.20	6.			
2.				7.			
3.	Ht	12:00	.20	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 10
Number of Bolts Torqued Above Range 0 Below Range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) discussed rgt # 4 of RCP #3 at 6:40 AM Dust Control Plan #3

[signature] Assistant Mine — 36525 Certificate No. — [signature] Mine Foreman-Mine Manager — 33337 Certificate No. — Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-27-10 2010 Section or Area Examined HG 22

Time of Examination: from 12:00 a.m. or p.m. to 2:00 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom Dean Jones Time A.M. 2:40 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 .20 ch4 20.8 o2	Needs additional Cleaning/Dusting	Reported
2.			
3.	#1R .20 ch4 20.8 o2	Needs additional Cleaning/Dusting	Reported
4.			
5.	#2 .20 ch4 20.8 o2	Scrap Cut	Reflectors Hung
6.			
7.	#3 .20 ch4 20.8 o2	Part Bolted	Reflectors Hung
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
LOB .20 ch4 20.8 o2	22263		

Remarks: Powercenters, chargers, intake phone, travelways — ok at time of examination

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 3602 — [signature] Assistant Foreman — Certificate No. 2014-A

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-27-10 Shift EVE Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .20 ch4	needs add. Cleaning + Dusting	Cleaned + Dusted
2.	20.8 o2		
3.	#1R .20 ch4	Needs add. Cleaning + Dusting	Cleaned + Dusted
4.	20.8 o2		
5.	#2 .20 ch4	S Crap Cut	Finished + Bolted
6.	20.8 o2		
7.	#3 .20 ch4	Part Bolted	Bolted
8.	20.8 o2		

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-4:30	.20 ch4	11.			
2.			20.8 o2	12.			
3.	1-3	6-6:30	.20 ch4	13.			
4.			20.8 o2	14.			
5.	1-3	8-8:30	.20 ch4	15.			
6.			20.8 o2	16.			
7.	1-3	10-10:30	.20 ch4	17.			
8.			20.8 o2	18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35	.05	6.			
2.			20.8 o2	7.			
3.	Return	8:33	.05	8.			
4.			20.8 o2	9.			
5.				10.			

Number of Bolts Tested 10

Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken ~~and pg~~

Remarks (Statement as to General Conditions of Mine or Area of Mine) Reveiwed pg 4 sect. 6 of MMO and pg 5 sect. 3 of RC Plan with entire crew @ 4:05 P

[signature] 2014 A [signature] 33357

Assistant Mine — Certificate No. — Mine Foreman-Mine Manager — Certificate No. — Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-27-10 20 00 Section or Area Examined Hg 22

Time of Examination: from 10:00 a.m. or p.m. to 11:00 a.m. or p.m.

Was this report phoned to outside? Yes ✓ no

By whom [signature] Time A.M 1105 P.M.

Report received by Pat Hilbert (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location		Violation or Hazardous Condition	Action Taken
1.	1	.20	None observed	Reported
2.	1R	.20	additional cleaning	Reported
3.	2	.20	None observed	Reported
4.	2R	.20	needs clean and dusted	Reported
5.	3	.20	None observed	Reported
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
LOD	22150		

Remarks: Travel ways intake phone power center OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 2014-A Certificate No. [signature] Assistant Foreman 1412-A Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-28-10 Shift 3rd Area or Section H.G. 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1 XR	add clasping	Reported
2.	2 XR	" C/D	Reported
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.				11.			
2.				12.			
3.		NO		13.			
4.				14.			
5.				15.			
6.		Production		16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested

Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

[signature]	32294	T. Moore	33357	
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-28-10 20___ Section or Area Examined H622

Time of Examination: from 4:00 a.m. or p.m. to 5:00 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no ___

By whom Kenney Farmer Time 5:21 A.M ___ P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CHY %	Violation or Hazardous Condition	O_2	Action Taken	
1.	1	.08	1 needs add chg	20.8	rep	.0
2.	1 Int	.08	needs add chg	20.8	rep	.0
3.	2	.20	needs add chg	20.8	rep	.0
4.	2 int	.10	needs add chg.	20.8	rep	.0
5.	3	.10	none obs	20.8	rep	.0
6.						
7.						
8.						
9.						
10.						

Air Measurements

Location	CFM	Location	CFM
Cos	17,800		

Remarks: .0 - .10 CHY 20.8 O_2 .0CO detected Trolley & Hulleys OK at time of Exm p.c. and Charger OK.

Shelter Chamber OK
Intake phone

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 32294 Certificate No. [signature] Assistant Foreman 36020 Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-28-10 Shift Ray Area or Section H622

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1	needs add clg	clear
2.	1 nt	needs add clg	clear
3.	2	needs add clg	clearing
4.	2 nt	needs add clg	clear
5.	3	nil obs	nil
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7:00 7:50	.20	11.			
2.		9:00		12.			
3.	1-3	9:50	.20	13.			
4.		11:00		14.			
5.	1-3	11:50	.20	15.			
6.		11:00		16.			
7.	1-3	1:50	.20	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Left	8:00	.60	6.			
2.				7.			
3.	Left	12:00	.20	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 14
Number of Bolts Torqued Above Range 0 Below Range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) discussed page # 4 of Rep #2 at 6:41 Am Dust Control plan #1

[signature] Assistant Mine | 36125 Certificate No. | T. Moore Mine Foreman-Mine Manager | 33257 Certificate No. | Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-28 10 Section or Area Examined H6 22

Time of Examination: from ____ a.m. or p.m. to ____ a.m. or p.m.

Was this report phoned to outside: Yes ✓ no ____

By whom Dean Jones Time ____ A.M ____ P.M.

Report received by Patrick Killen (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 30 cn4 20.800	Part Bolted	Reflectors Hung
2.			
3.	#2 .20 cn4 20.803	None Observed	NONE
4.			
5.	#2R .25 cn4 20.802	Scrap Cut	Reflectors Hung
6.			
7.	#3 .20 20.802	NONE Observed	NONE
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	21,836		

Remarks: .20 cn4 .20.802 ppm CO
Power center
Chargers
Intake phone
travel ways
all ok at time of examination

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 36526 — Patrick Killen Assistant Foreman — Certificate No. 2014-A

Countersigned [signature] Mine Manager—Mine Foreman — 33357

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-28-10 Shift EVE Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .30 CH4 20.8 O2	Part Bolted	Bolted
2.			
3.	#2 .20 CH4 20.8 O2	NONE Observed	NONE
4.			
5.	#2R .25 CH4 20.8 O2	Scrap Cut	Finished + Bolted
6.			
7.	#3 .20 CH4 20.8 O2	NONE OBSERVED	NONE
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-4:30	.25 CH4 20.8 O2	11.			
2.				12.			
3.	1-3	6-6:30	.25 CH4 20.8 O2	13.			
4.				14.			
5.	1-3	8-8:30	.20 CH4 20.8 O2	15.			
6.				16.			
7.	1-3	10-10:30	.20 CH4 20.8 O2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35	.05 20.8 O2	6.			
2.				7.			
3.	Return	8:35	.05 20.8 O2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 30
Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Reviewed pg 5 Sect 19 MMU Plan and pg 5 Sect 23 RC Plan with entile crew at 405 PM

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant
[illegible]	2014	T. [illegible]	33357	

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3 - 28 2010 Section or Area Examined HG 22

Time of Examination: from 1000 a.m. or p.m. to 1105 a.m. or p.m.

Was this report phoned to outside: Yes ___ no ___

By whom Patrick Hilbert Time ___ A.M 1110 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 P .25%	Part Bolted	Reflectors
2.			
3.	#2 .20%	Scrap Cut	Reflectors
4.			
5.	#3 .20%	None Observed	
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Pab	21,530		

Remarks: .25 cHy power center chargers intake phone fresh air base
208 Clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Patrick R Hilbert (Preshift-Mine Examiner) 2014A (Certificate No.) Kyle Anderson (Assistant Foreman) 33238 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-28 Shift 3rd Area or Section HGDD

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .25%	Part bolted	Reflectors hung
2.			
3.	#2 .20%	Scrap Cut	Reflectors hung
4.			
5.	#3 .20%	None observed	
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3 140	129	.25%	11.			
2.				12.			
3.	1-3 445	521	.25%	13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	136	.25%	6.			
2.				7.			
3.	Return	530	.25%	8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Kyle Anderson — Assistant Mine
33238 — Certificate No.
T. Moore — Mine Foreman-Mine Manager
[illegible] — Certificate No.
Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-29-10 20___ Section or Area Examined HG22

Time of Examination: from 5:00 a.m. or p.m. to 5:21 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no ___

By whom Kyle Anderson Time 5:40 A.M ___ P.M.

Report received by Dean Jones (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CHY %	Violation or Hazardous Condition	O2	Action Taken	
1.	1	.10	none UGS	20.8	none	.0
2.	1 Int	.40	needs dust	20.8	Nep	.0
3.	2	.0	not bolted	20.8	reflects	.0
4.	2 Int	.10	needs dust	20.8	Nep	.0
5.	3	.0	none UGS		none	.0
6.						
7.						
8.						
9.						
10.						

Air Measurements

Location	CFM	Location	CFM
COB	20,380		

Remarks: .0 - .40 CHY 20.8 O2 .0 CO detected
Trolleys - Hurleys ok at time of Exam
P.C. and Chyn ok.

Shelter Chilen OK
Intake phone

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (Preshift-Mine Examiner) 33238 (Certificate No.) ___ (Assistant Foreman) ___ (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33389

___ (Assistant Foreman) ___

___ (Superintendent or Assistant)

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-29-15 Shift Mary Area or Section HG22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1	Me OGS	None
2.	1 Wt	Needs Clay	Clean
3.	2	Not Bolted	Bolted
4.	2 Wt	Needs Water	Cleaned & Rubber
5.	3	Me OGS	None
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7:00 7:00	.20	11.			
2.		9:00		12.			
3.	1-3	9:50	.20	13.			
4.		11:00		14.			
5.	1-3	11:50	.20	15.			
6.		1:00		16.			
7.	1-3	1:50	.20	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Net	8:00	.20	6.			
2.		1		7.			
3.	Net	12:00	.20	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 10
Number of Bolts Torqued Above Range 0 Below Range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) discussed rpt # 5 of Rep #17 at 6:34 Am Dust Control Plan #9.

[signature] Assistant Mine | 36526 Certificate No. | [signature] Mine Foreman-Mine Manager | 33305 Certificate No. | Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-29 20 10 Section or Area Examined HG 22

Time of Examination: from 12 a.m. or p.m. to 2 a.m. or p.m.

Was this report phoned to outside: Yes ___ no ___

By whom Dean Jones Time ___ A.M 2:35 P.M.

Report received by Patrick R Hilliers (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	tripper Area .20	Not Bolted	Reflectors Hung
2.	20.8 02		
3.	#1 .20 ch4	Needs Cleaned	Reported
4.	20.8 02		
5.	#2 .20 ch4	NONE OBserved	NONE
6.	20.8 02		
7.	#2R .20 ch4	Part Bolted	Reflectors Hung
8.	20.8 02		
9.	#3 .20 ch4	water in face	Reported
10.	20.8 02		

Air Measurements

Location	CFM	Location	CFM
LOB	20145		

Remarks: power center
intake phone
outby shetter
travel way
} all OK at time of examination

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 36526 Certificate No. Patrick R Hilliers Assistant Foreman 2014-A Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33389

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-29-10 Shift EU E Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	Tripper Area .20 ch4 20.8 o2	Not Bolted	Bolted
2.	#1 .20 ch4 20.8 o2	Needs Cleaned	Cleaned
3.	#2 .20 ch4 20.8 o2	NONE OBSERVED	NONE
4.	#2R .20 ch4 20.8 o2	Part Bolted	Bolted
5.	#3 .20 ch4 20.8 o2	water in face	Reported
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-4:30	.20 ch4	11.			
2.			20.8 o2	12.			
3.	1-3	6-6:30	.25 ch4	13.			
4.			20.8 o2	14.			
5.	1-3	8-8:30	.25 ch4	15.			
6.			20.8 o2	16.			
7.	1-3	10-10:30	.20 ch4	17.			
8.			20.8 o2	18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35	.05 ch4 20.8 o2	6.			
2.				7.			
3.	Return	8:35	.05 20.8 o2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 10

Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Reveiwed pg 5 sect 26 RC Plan and pg 4 Sect 3 with entire crew at 405 PM

Patrick R Culyat — Assistant Mine
2014-A — Certificate No.
T. Moore — Mine Foreman-Mine Manager
33359 — Certificate No.
Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-29 20/0 Section or Area Examined HG 22

Time of Examination: from 1000 a.m. or p.m. to 1055 a.m. or p.m.

Was this report phoned to outside: Yes ✓ No

By whom Patrick Miller Time A.M. 1115 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 ,20	Scrap Cut Tuppes Drive	Reflectors hung
2.			
3.	#2 ,20	None Observed	
4.	2R ,20	Part Bolted	Reflectors hung
5.	#3 ,20	None Observed	
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Pob	21,735		

Remarks: #1 powercenter & chargers w/telephone fresh air base 20.8 Clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Patrick Miller (Preshift-Mine Examiner) Certificate No. 2014A Assistant Foreman Kyle Anderson Certificate No. 33238

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-29 Shift 3rd Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 .20	Scrap Cut Trippy Drive	Reflectors
2.			
3.	#2 .20	N/O	
4.	2R .20	Part bolted	Reflectors
5.	#3 .20	N/O	
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3 110	131	.20	11.			
2.				12.			
3.	1-3 450	525	.20	13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	135	.20	6.			
2.				7.			
3.	Return	531	.20	8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Kyle Anderson — Assistant Mine — 33238 Certificate No.

T. Moore — Mine Foreman-Mine Manager — 33569 Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-30 20.10 Section or Area Examined Headgate #22

Time of Examination: from 450 a.m. or p.m. to 525 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Kyle Anderson Time 525 A.M. P.M.

Report received by Brandon Boggs (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 Tripper Hole OCH2, 20.8O2	Scrap Cut	Reflectors
2.			
3.	#2 Entry. OCH2, 20.8O2	None Observed	Reported
4.			
5.	#2R CC .05 water 20.8O2	Water in face	Pumping water
6.			
7.	#3 Entry, OCH2, 20.8O2	Water in Entry	Pumping water
8.			
9.	OPPn C/O		
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	20,970		

Remarks: Power Center
Travelways
Chargers
Intake Phone
Outby Shelter
OCH2, 20.8O2 OPPn C/O

All items + areas OK at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (Preshift-Mine Examiner) 33238 (Certificate No.) Brandon Boggs (Assistant Foreman) 1122-A (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33357

(Assistant Foreman)

(Superintendent or Assistant)

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-30-10 Shift Day Area or Section Headgate # 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 Tripper Hole .20 CHY. 20.8 O2	Scrap Cut	Bolted + Reflectors
2.	.25 CHY.		
3.	#2R-3 .20 CHY. 20.8 O2	Water in faces	Pumping Water
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7-730Am	.25 CHY. 20.8 O2	11.			
2.				12.			
3.	1-3	9-930Am	.25 CHY. 20.8 O2	13.			
4.				14.			
5.	1-3	11-1130Am	.2 CHY. 20.8 O2	15.			
6.				16.			
7.	1-3	1-145Pm	.25 CHY. 20.8 O2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	715Am	.05 CHY. 20.8 O2	6.			
2.				7.			
3.	Return	1115Am	.10 CHY. 20.8 O2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 5

Number of Bolts Torqued Above Range ——— Below Range ———

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Pg. 2 MMU sect 7 at 639 Am. Pg. 3 Sect A RCP at 641 Am.

[signature] Assistant Mine | 1122A Certificate No. | T. [signature] Mine Foreman-Mine Manager | 33359 Certificate No. | Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-30 20 10 Section or Area Examined HG 22

Time of Examination: from 1:00 a.m. or p.m. to 1:45 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Brandon Bowling Time A.M 2400 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	tripper Hole	Part Bolted	Reflectors Hung
2.	1 .20 ch4	NONE Observed	NONE
3.	20.8 o2		
4.	2 .20 ch4	NONE Observed	NONE
5.	20.8 o2		
6.	2R .25 ch4	Scrap Cut	Reflectors Hung
7.	20.8 o2		
8.	3 .20 ch4	water	Being Pumped
9.	20.8 o2		
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	21,440		

Remarks: power center
Chargers
Intake phone
Haul ways
all ok at time of examination

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1122A Certificate No. [signature] Assistant Foreman 2014-A Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-30-10 Shift EVE Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	tripper Hole	Part Bolted	Bolted
2.			
3.	1 .20 ch4 20.8 o2	NONE	NONE
4.	2 .20 ch4 20.8 o2	NONE	NONE
5.	2R .25 ch4 20.8 o2	Scrap cut	finished & Bolted
6.	3 .20 ch4 20.8 o2	water	Pumped & Loaded out
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-4:30	.20 ch4 20.8 o2	11.			
2.				12.			
3.	1-3	6-6:30	.20 ch4 20.8 o2	13.			
4.				14.			
5.	1-3	8-8:30	.25 ch4 20.8 o2	15.			
6.				16.			
7.	1-3	10-10:30	.20 ch4 20.8 o2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35	.05 20.8 o2	6.			
2.				7.			
3.	Return	8:35	.10 20.8 o2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 10 Ø

Number of Bolts Torqued Above Range Ø Below Range Ø

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Reveiwed pg 4 Sect 1 mmu Plan and pg 4 Sect 5 RC Plan with entire crew at 4:05 PM

Patrick R [illegible] 2014-A T. Moore 33857

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-30 2010 Section or Area Examined HG 22

Time of Examination: from 1000 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Patrick Time A.M 1115 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 .20	None Observed	
2.			
3.	#2 .20	None Observed	
4.	2R .25	None Observed	
5.	#3 .20	Scrap Cut	Reflectors
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Pob	20,415		

Remarks: .20 cH4 power center & chargers inlake phone fresh air base 20.8 Clear at time of exam

This is to certify that (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Patrick R Mattress 2014-A
Preshift-Mine Examiner — Certificate No. — Assistant Foreman — Certificate No.

Countersigned T. Moore 33357 Kyle Anderson 33238
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-30 Shift 3rd Area or Section H622

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 ,20	N/O	
2.			
3.	#2 ,20	N/O	
4.	2R ,25	N/O	
5.	#3 ,20	Scrap Cut	Reflectorizing
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3 130	200	20%	11.			
2.				12.			
3.	1-3 450	528	.20%	13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	206	.20%	6.			
2.				7.			
3.	Return	531	.20%	8.			
4.				9.			
5.				10.			

Number of Bolts Tested
Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Kyle Anderson — Assistant Mine
33238 — Certificate No.
T. Moore — Mine Foreman-Mine Manager
3335-1 — Certificate No.
Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-31 2010 Section or Area Examined Headgate #22

Time of Examination: from 450 a.m. or p.m. to 528 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Kyle Anderson Time 528 A.M. P.M.

Report received by Brad Bowy (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 Entry OCH4 20.802	None Observed	Reported
2.			
3.	#1 Tripper Hole. OCH4. 20.802	Needs Add Cleaning	Reported
4.			
5.	#2-2RCC. 40CH4. 20.802	None Observed	Reported
6.			
7.	#3 Entry .05CH4. 20.802	Scrap Cut	Reflectors
8.			
9.	OPPM c/o		
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	20,120		

Remarks: Power Center
Chargers
Travelways
Intake Phone
Outby Shelter
.4 CH4, detected-Faces

All ok at time of exam
OCH4, 20.8 OK OPPM c/o

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (Preshift-Mine Examiner) 33238 (Certificate No.) Brad Bowy (Assistant Foreman) 1122-A (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33357

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-31-10 Shift Day Area or Section Headgate #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 Tripper Hole OCH4 20.8 O2	Needs Add Cleaning	Cleaned + Dusted
2.			
3.	#3 Entry .3 CH4 20.8 O2	Scrap Cut	Bolted + Reflectors
4.			
5.	#1 Entry Tripper Hole	Rib Bolts Cut out Corner not Bolted	Spotted Rib bolts 6 Ft. Ribs
6.			Spotted Corner
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7-730Am	.2 CH4 20.8 O2	11.			
2.				12.			
3.	1-3	9-930Am	.2 CH4 20.8 O2	13.			
4.				14.			
5.	1-3	11-1130Am	.3 CH4 20.8 O2	15.			
6.				16.			
7.	1-3	1-150Pm	.3 CH4 20.8 O2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	715Am	.10 CH4 20.8 O2	6.			
2.				7.			
3.	Return	1115Am	.10 CH4 20.8 O2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 8

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) Dg. 2 MMU Sect 10 Dg. 3 Sect B RLP at 635 Am.

[signature] Assistant Mine — 1122-A Certificate No. — T. Moore Mine Foreman-Mine Manager — 33327 Certificate No. — Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-31- 2010 Section or Area Examined HG 22

Time of Examination: from 1:00 a.m. or p.m. to 150 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom Brandon Bowling Time ____ A.M 2:35 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	Tripper Hole wich	Dangered off	Dangered off
2.	1F .20 cm4	Part Bolted	Reflectors Hung
3.	20.8 oz		
4.	2F .20 cm4	Scrap Cut	Reflectors Hung
5.	20.8 oz		
6.	2R .30 cm4	NONE Observed	NONE
7.	20.8 oz		
8.	3F .30 cm4	Needs Cleaned	
9.	20.8 oz		
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	20,822		

Remarks: intake phone
Power center
Chargers
travelways
Out by shelter
} all ok at time of Examinaton

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1122-A Certificate No. [signature] Assistant Foreman 2014-A Certificate No.

Countersigned T. [signature] Mine Manager—Mine Foreman 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-31-10 Shift EVE Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	Tripper Hole Nich	Dangerd off	Finished Bolted Nitchin Rib
2.	1F .20 ch4 20.8 o2	Part Bolted	Bolted
3.			
4.	2F .20 ch4 20.8 o2	Scrap Cut	Finished & Bolted
5.			
6.	2R .30 ch4 20.8 o2	NONE OBServed	NONE
7.			
8.	3F .30 ch4 20.8 o2	Needs Cleaned	Cleaned

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-4:30	.25 ch4 20.8 o2	11.			
2.				12.			
3.	1-3	6-6:30	.20 ch4 20.8 o2	13.			
4.				14.			
5.	1-3	8-8:30	.25 ch4 20.8 o2	15.			
6.				16.			
7.	1-3	10-10:30	.25 ch4 20.8 o2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35	.05 ch4 20.8 o2	6.			
2.				7.			
3.	Return	8:35	.10 20.8 o2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 15

Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Reveieved pg 5 Sect 27 RC Plan and pg 4 Sect. 11 MMU with entire crew at 4:01 P

Randy Robinson — Assistant Mine; 2014-A — Certificate No.; T. Moore — Mine Foreman-Mine Manager; 33359 — Certificate No.; Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3 - 31 2010 Section or Area Examined HG 22

Time of Examination: from 1000 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Patrick Hilbert Time A.M 1110 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 .30	None Observed	
2.			
3.	#2 .20	None Observed	
4.	2R .20	None Observed	
5.	#3 .25	Part Bolted	Reflectors hung
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Job	20,890		

Remarks: 25 cHY power center, chargers intake phone fresh air base
208 Clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Patrick Hilbert 2014A
Preshift-Mine Examiner — Certificate No. — Assistant Foreman — Certificate No.

Countersigned T. Moore 33359 Kyle Anderson 33238
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 3-31 Shift 3rd Area or Section #6 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 ,30	N/O	
2.			
3.	#2 ,20	N/O	
4.	2R ,20	N/O	
5.	#3 ,25	Part bolted	Reflectors hung
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3 130	206	.25%	11.			
2.				12.			
3.	1-3 446	522	0%	13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	210	.25%	6.			
2.				7.			
3.	Return	530	0%	8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Kyle Anderson — Assistant Mine

33238 — Certificate No.

F. Mann — Mine Foreman-Mine Manager

1117 — Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-1 20 10 Section or Area Examined Headgate #22

Time of Examination: from 446 a.m. or p.m. to 522 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Kyle Anderson Time 535 A.M. P.M.

Report received by Brandt Bowing (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 Entry OCH4%	None Observed	Reported
2.	20.8 oz		
3.	#2 Entry .30 CH4%	None Observed	Reported
4.	20.8 oz		
5.	#2R CC .20 CH4%	None Observed	Reported
6.	20.8 oz		
7.	#3 Entry OCH4%	Needs Dusted	Reported
8.	20.8 oz		
9.	OPPM c/o		
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	20,864		

Remarks: Power Center
Chargers
Intake Phone
Outby Chamber
Intake Phone
Travelways

All OK at time of exam.
OCH4% 20.8 oz OPPM c/o

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (Preshift-Mine Examiner) 33238 (Certificate No.) Brandt Bowing (Assistant Foreman) 1122-A (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33357

Assistant Foreman

Superintendent or Assistant

Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 4-1-10 Shift Day Area or Section Headgate # 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#3 Entry 13 CH4! 20.8 O2	Needs Dusted	Cleaned + Dusted
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7-730Am	.3 CH4! 20.8 O2	11.			
2.				12.			
3.	1-3	9-930Am	.2 CH4! 20.8 O2	13.			
4.				14.			
5.	1-3	11-1130Am	.2 CH4! 20.8 O2	15.			
6.				16.			
7.	1-3	1-200Pm	.3 CH4! 20.8 O2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	713Am	.10 CH4! 20.8 O2	6.			
2.				7.			
3.	Return	1114Am	.10 CH4! 20.8 O2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 5 Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Pg. 3 MMV Sect 16 Pg. 5 Sect. 21 RCP at 642 AM.

Brock Berry — Assistant Mine
1122-A — Certificate No.
T. Maner — Mine Foreman-Mine Manager
33359 — Certificate No.
Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-1 2010 Section or Area Examined HG 22

Time of Examination: from 1 a.m. or p.m. to 2 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Brandon Bowling Time A.M 2:35 P.M.

Report received by Patrick R Hilbert (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	1 .20 ch4 20.8 o2	Scrap Cut	Reflectors Hung
2.			
3.	2 .30 ch4 20.8 o2	NONE Observed	NONE
4.			
5.	2R .30 ch4 20.8 o2	NONE Observed	NONE
6.			
7.	3 .30 ch4 20.8 o2	Part Bolted	Reflectors Hung
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	20,750		

Remarks: Intake phone
Power center
Chargers
Outby shelter
travel ways

all OK at time of examination
0% ch4 20.8 o2 0ppm CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Brandon Bowling (Preshift-Mine Examiner) 1122-A (Certificate No.) Patrick R Hilbert (Assistant Foreman) 2014-A (Certificate No.)

Countersigned [signature] (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 4-4-10 Shift EVE Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1 .20 ch4	Scrap cut	Finished & Bolted
2.	20.8 o2		
3.	2 .30 ch4	NONE Observed	NONE
4.	20.8 o2		
5.	2R .30 ch4	None observed	NONE
6.	20.8 o2		
7.	3 .30 ch4	Part Bolted	Bolted
8.	20.8 o2		

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-4:30	.25	11.			
2.			20.8 o2	12.			
3.	1-3	6-6:30	.20	13.			
4.			20.8 o2	14.			
5.	1-3	8-8:30	.20	15.			
6.			20.8 o2	16.			
7.	1-3	10-10:30	.25	17.			
8.			20.8 o2	18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	4:35	.05	6.			
2.			20.8 o2	7.			
3.	Return	8:35	.05	8.			
4.			20.8 o2	9.			
5.				10.			

Number of Bolts Tested 20

Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Reviewed pg 4 Sect 1 MMU pg 6 Sect 2R RC Plan with entire crew at 405 P

[signature] Assistant Mine — 2014-A Certificate No. — [signature] Mine Foreman-Mine Manager — Certificate No. — Superintendent or Assistant

T. Moore 33357

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-1 2010 Section or Area Examined HG 22

Time of Examination: from 1000 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Patrick Time A.M. 1110 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location		Violation or Hazardous Condition	Action Taken
1.	#1	.20%	None observed	
2.				
3.	#2	.25%	Scrap Cut	Reflectors hung
4.	2R	.25%	None observed	
5.	#3	.30%	needs cleaned & dusted	Reported
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Job	20225		

Remarks: .30% power center & chargers in lake phone fresh air base
208 clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Patrick R Miller 6014A
Preshift-Mine Examiner — Certificate No. 33359 — Assistant Foreman Kyle Anderson — Certificate No. 33238

Countersigned T. Moore
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 4-1 Shift 3rd Area or Section #6 DD

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 1200	N/O	
2.			
3.	#2 1250	Scrap Cut	Reflectors hung
4.	2R 1250	N/O	
5.	#3 1300	roads cleaned & dusted	Reported
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3 120	154	30%	11.			
2.				12.			
3.	1-3 452	527	0%	13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	200	.30%	6.			
2.				7.			
3.	Return	530	0%	8.			
4.				9.			
5.				10.			

Number of Bolts Tested
Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Kyle Anderson — Assistant Mine
33238 — Certificate No.
T. Moore — Mine Foreman-Mine Manager
33359 — Certificate No.
Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-2-10 20___ Section or Area Examined 4622

Time of Examination: from 4:50 a.m. or p.m. to 5:20 a.m. or p.m.

Was this report phoned to outside: Yes ___ no ___

By whom Kyle Anderson Time 5:30 A.M ___ P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4 %	Violation or Hazardous Condition	O2	Action Taken	CO
1.	1	.0	needs add clay		nep	
2.	2	.05	not Bolted		reflective	
3.	2A	.20	none obs		nep	
4.	3	.10	none obs		nep	
5.	2-3		needs add clay		nep	
6.						
7.						
8.						
9.						
10.						

Air Measurements

Location	CFM	Location	CFM
COB	20,180		

Remarks: .0 - .20 CH4 20.8 O2 .0 CO detected
Trolleys & Hoists ok at time of Exam
P.C. and clean ok.

Shelter chamber ok
Intake phone

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson 33238 [signature] 3612
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.

Countersigned T. Mann 33359
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 4-2-10 Shift Mey Area or Section 1H622

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1	needs added dry	Dust
2.	2	not Bolted	Bolted
3.	2nd	nice dry	nice
4.	3	nice dry	nice
5.	2-3	needs added dry	Dust
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content %		Location	Time	Methane Content
1.	1-3	7:00 7:00	.20	11.			
2.		9:00		12.			
3.	1-3	9:00	.20	13.			
4.		11:00		14.			
5.	1-3	11:00	.20	15.			
6.		1:00		16.			
7.	1-3	1:00	.20	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content %		Location	Time	Methane Content
1.	net	8:00	.20	6.			
2.				7.			
3.	net	12:00	.20	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 16
Number of Bolts Torqued Above Range 0 Below Range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) discussed rpt # 5 of Rep # 29 At 6:36 Dust control plan #7

[signature] Assistant Mine | 36026 Certificate No. | T. Moore Mine Foreman-Mine Manager | 33359 Certificate No. | Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-2 20 10 Section or Area Examined Headgate #22

Time of Examination: from 1200 a.m. or p.m. to 200 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Deano Jones Time A.M 235 P.M.

Report received by Brooks Berry (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	# 1 Entry .20 CHGL.	None Observed	Reported
2.	20.802		
3.	#1 R CC .20 CHGL	Not Bolted	Reflectors
4.	20.802		
5.	#2 Entry .20 CHGL	Part Bolted	Reflectors
6.	20.802		
7.	#3 Entry .20 CHGL.	Scrap - Cut	Reflectors
8.	20.802		
9.	OPPM c/o		
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	20,126		

Remarks: Power Center
Chargers
Travelways
Intake Phone
Outby Chamber

All ok at time of exam. 0 CHGL. 20.802 OPPM c/o

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 36525 Certificate No. Brooks Berry Assistant Foreman 11224 Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33259

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 4-2-10 Shift EVE Area or Section Headgate #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#1 RCC .2 CH4% 20.8 O2	Not Bolted	Bolted + Reflectors
2.			
3.	#2 Entry .3 CH4% 20.8 O2	Part Bolted	Bolted + Reflectors
4.			
5.	#3 Entry .3 CH4% 20.8 O2	Scrap Cut	Bolted + Reflectors
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-430pm	.3 CH4% 20.8 O2	11.			
2.				12.			
3.	1-3	6-630pm	.3 CH4% 20.8 O2	13.			
4.				14.			
5.	1-3	8-830pm	.3 CH4% 20.8 O2	15.			
6.				16.			
7.	1-3	10-1100pm	.3 CH4% 20.8 O2	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	415pm	.10 CH4% 20.8 O2	6.			
2.				7.			
3.	Return	814pm	.10 CH4% 20.8 O2	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 5

Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) Pg. 1 MMU RB MEAV Dust Paramaters Pg. 5 RCP sect 18 RCP 338pm

[signature]	1122-A	[signature]	33357	
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-2 20 10 Section or Area Examined H622

Time of Examination: from 1000 a.m. or p.m. to 1110 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Brandon Time A.M 1116 P.M.

Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	1 .20%	None observed	
2.	1R	Roof bolted	Reflectorizing
3.	2 and 3 .30%	none observed	
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Pob	29,200		

Remarks: .30% dH4 power center & chargers intake phone fresh air base 208 Clean at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 11224

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 33389 — Kyle Anderson Assistant Foreman — Certificate No. 33030

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 4-2 Shift 3rd Area or Section HG 22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1 20%	N/O	
2.	1R 20%	Part bolted	Reflectors
3.	2 and 3 30%	N/O	
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3 112	136	30%	11.			
2.				12.			
3.	1-3 448	528	30%	13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	140	30% CH4	6.			
2.				7.			
3.	Return	531	0% CH4	8.			
4.				9.			
5.				10.			

Number of Bolts Tested
Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Kyle Anderson — Assistant Mine — 33238 Certificate No.

T. Moore — Mine Foreman-Mine Manager — 33357 Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-3-10 20___ Section or Area Examined H622

Time of Examination: from 4:48 a.m. or p.m. to 5:20 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no ___

By whom Kyle Anderson Time 5:35 A.M ___ P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4%	Violation or Hazardous Condition	O2	Action Taken	CO
1.	1	.20	none obs	20.8	none	.0
2.	1 int	.25	needs dust	pulled 20.8	nep	.0
3.	2	.20	none obs	20.8	none	.0
4.	3	.0	H2O	20.8	nep	.0
5.						
6.						
7.						
8.						
9.						
10.						

Air Measurements

Location	CFM	Location	CFM
LOB	20,208		

Remarks: .0 - .25 CH4 20.8 O2 .0 CO detected
Trolleys & Hulys ok at time of Ex
P.C. and Charger ok.

Shelter Chamber
Intake Phone
OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (Preshift-Mine Examiner) 33238 (Certificate No.) [signature] (Assistant Foreman) 36020 (Certificate No.)

Countersigned [signature] (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 4-3-10 Shift Rwy Area or Section H622

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	1	nil (6)	nil
2.	rnt	needs add dry ints	Dead rates
3.	2	nil (6)	nil
4.	3	H2O	nil
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	7:00 7:00	.20	11.			
2.				12.			
3.	1-3	9:00 9:00	.20	13.			
4.		11:00		14.			
5.	1-3	11:50	.20	15.			
6.		1:00		16.			
7.	1-3	1:00	.20	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Let	8:00	.20	6.			
2.				7.			
3.	Let	12:00	.20	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 17
Number of Bolts Torqued Above Range 0 Below Range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) discussed posted 508 Rev #20 at 6:40 Am Dust Control Plan 14

[signature] 36525
Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-3 2010 Section or Area Examined Headgate #22

Time of Examination: from 1200 a.m. or p.m. to 200 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Deano Jones Time A.M 340 P.M.

Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 Entry, 20 CH4, 20.8 O2	None Observed	Reported
2.			
3.	#2 RCC. 20 CH4, 20.8 O2	Part Bolted	Reflectors
4.			
5.	#2 Entry, 20 CH4, 20.8 O2	None Observed	Reported
6.			
7.	#3 Entry. 40 CH4, 20.8 O2	Scrap Cut	Reflectors
8.			
9.	OPPM C/O		
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	20,104		

Remarks: Power Center
Chargers
Travelways
Outby Shelter
Intake Phone

All OK at time of exam
0 CH4, 20.8 O2 OPPM C/O

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 36525 Certificate No. [signature] Assistant Foreman 1120A Certificate No.

Countersigned Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 4-3-10 Shift EVE Area or Section Headgate #22

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	#2R CC .3CH4% 20.8oz	Part Bolted	Bolted + Reflectors
2.			
3.	#3 Entry .3CH4% 20.8oz	Scrap cut	Bolted + Reflectors
4.			
5.			
6.	Rock dusted Return - Section machine duster		
7.			
8.			

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	1-3	4-430pm	.3CH4% 20.8oz	11.			
2.				12.			
3.	1-3	6-630pm	.3CH4% 20.8oz	13.			
4.				14.			
5.	1-3	8-830pm	.3CH4% 20.8oz	15.			
6.				16.			
7.	1-3	10-11pm	.3CH4% 20.8oz	17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	Return	414pm	.10CH4% 20.8oz	6.			
2.				7.			
3.	Return	812pm	.10CH4% 20.8oz	8.			
4.				9.			
5.				10.			

Number of Bolts Tested 6

Number of Bolts Torqued Above Range — Below Range —

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine) MMU Pg. 2 sect 6
RCP Pg. 5 sect 18 338pm

[signature] 1122-A

Assistant Mine | Certificate No. | Mine Foreman-Mine Manager | Certificate No. | Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-3- 20 10 Section or Area Examined HG#22

Time of Examination: from 1000 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes ____ no X

By whom Brought out Time 100 A.M. P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	#1 Entry, 3 CH4% 20.8 O2	None Observed	Reported
2.			
3.	#2 Entry, 3 CH4% 20.8 O2	None Observed	Reported
4.			
5.	#2 RCC, 3 CH4% 20.8 O2	Needs Cleaned	Reported
6.			
7.	#3 Entry, 3 CH4% 20.8 O2	Needs Cleaned	Reported
8.			
9.	OPPM C/O		
10.			

Air Measurements

Location	CFM	Location	CFM
LOB	20,100		
20.8 O2			
OPPM C/O			

Remarks: Power Center
Chargers
Travelways
Outby Shelter
Intake Phone
All ok at time of exam.

Haul Roads need Add cleaning. Soft Ribs 1-3 Entrys

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Brad Bowy (Preshift-Mine Examiner) 1122-A (Certificate No.) _____ Assistant Foreman _____ Certificate No.

Countersigned _____ Mine Manager—Mine Foreman

_____ Assistant Foreman

_____ Superintendent or Assistant