

# Preliminary Report of Accident



1. Accident Type: Fatal Injury	2. Accident Classification Fall of Roof or Back	3. Date/Time of Accident 02/20/2015 02:00 PM	4. Date/Time of Death 02/20/2015 02:00 PM	5. Fatal Case No 2
6. Mine Information :				
a) Mining Company Name Rosebud Mining Company	b) Mine Name Heilwood	c) Parent of Mining Company J Clifford Forrest III		
7. Mine Location :	a) City Heilwood	b) County Indiana	c) State PA	8. Mine ID Number: 36-09407
9. Union: NO				
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND	11. Number of Mine Employees:	a) Total 40	b) Underground 35	c) Open Pit/Quarry 0
12. Contractor Name:		13. Union		14. Contractor ID Number:
15. Contractor Address:				
16. Number of Contractor Employees:				
17. Number of Persons in Mine at Time of Accident:				
a) Mine Employees: 15	b) Contractor Employees: 0		18. Number of Persons Unaccounted For:	
a) Mine Employees: 0		b) Contractor Employees: 0		
19) Location of Accident				20. Mining Height:
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit	<input checked="" type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility	Feet 8
21. Nonfatal Injuries:		22. Fatal Injuries: 1		
23. Victim Information :				
a) Name Todd Trimble		b) Age 29		
c) Regular Job Title: Roof Bolter Helper		d) Activity at Time of Accident: Bolting		<input checked="" type="checkbox"/> Mine Employee
24. Experience :				
Years Weeks Days		Years Weeks Days		Years Weeks Days
a) Total:	3 48 0	b) at the mine:	1 12 0	c) at activity (23d)
d) with Contractor		0 0 0		
25. Autopsy Performed: If Yes, Location YES				26. Mine Telephone No.: (814) 948-6390

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

On February 20, 2015, at approximately 2:00 p.m., a 29 year old roof bolter helper received fatal crushing injuries when he was pinned between a piece of roof rock and the top of the drill canopy in the No. 2 Slope Entry, 180 feet inby survey station No. 4794 in the A Mains, MMU 001. The victim was repositioning roof mesh for the next row of permanent supports to be installed when the accident occurred.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Fletcher		29. Model: DDR-13-B S/N 2011019		
30. District: C0200 New Stanton	32. Field Office: Indiana PA		33. Event Number: 4011113	
34. Accident Investigator: Kerry J. Miller		35. MSHA Person Notified: Deborah A. Moberg		Date 02/20/2015
				Time 02:38 PM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Kerry J. Miller		Date 02/21/2015
38. Reason For Amendment:				