

**PRE-SHIFT
BELTS**

2MSHA03794

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-11-07 SECTION/AREA BELTS

Time of Examination Start 7:02 AM/PM AM End 9:20 AM/PM PM Examiners Initials SM

Time of Examination Start 7:00 AM/PM AM End 8:55 AM/PM PM Examiners Initials LD

Time of Examination Start _____ AM/PM _____ End _____ AM/PM _____ Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	SW	OK	none observed	
#2	20.9	0	0	SW	OK	none observed	
#3	20.9	0	0	SW	OK	none observed	
#4	20.7	0	0	SW	OK	none observed	
#5	20.9	0	0	SW	OK	none observed	
#6	20.9	0	0	SW	OK	none observed	
#7	20.9	0	0	SW	OK	142 1/2 ALUM / 139 ALUM	WORKING ON none LD
Belt Kitcher	20.9	0	0	SW	OK	none observed	
TRANSFORMERS	20.9	0	0	SW	OK	none observed	
CO SENSORS	VED EXAM			SW	OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All AREAS appear SAFE AT THE TIME OF EXAM
except those noted above.

Pre-Shift/Mine Examiner **Signature** _____ Certificate # 9759

Pre-Shift/Mine Examiner _____ Certificate # 9660

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature **SIGNATURE** _____ 2MSHA03795 Certificate # 7488

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-12-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM PM End 4:55 AM PM Examiners Initials LD

Time of Examination Start 3:00 AM/PM End 4:15 AM/PM Examiners Initials LD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	Acc at tail and Dust	Sent people to clean Ct Done 7/20/07 Ct
#5	20.9	0	0	ok	None observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Belt kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Sensors visual exam				ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all Areas appeared safe at the time of exam except those noted above.

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 9660

Certificate # 9989

Certificate # _____

Certificate # _____

2MSHA03796

SIGNATURE _____

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-12-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM PM

End 1:25 AM PM

Examiners Initials RC

Time of Examination Start 11:00 AM PM

End 1:15 AM PM

Examiners Initials TC

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Accum Tailpiece	Sent man to clean & Done 7-12-07
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	None observed	
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
Transformers	20.9	0	0	OK	None observed	
CO monitors				Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # 9362

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA03797

SIGNATURE

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-12-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM (PM)

End 9:02 AM/PM (PM)

Examiners Initials LD

Time of Examination Start 7:03 AM/PM (PM)

End 9:15 AM/PM (PM)

Examiners Initials Sm

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	ACC Tail	SENT MAN TO CLEAN Done LD
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	Roller piles 106-Head	WORKING ON Done LD
#6	20.9	0	0	ok	Roller piles 1-2	WORKING ON Done LD
#7	20.9	0	0	ok	none observed	
Belt Kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Monitor	visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas Approved Safe at the time of exam except those noted above

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9660
 Certificate # 9759
 Certificate # _____
 Certificate # _____

Counter Signature **Signature** _____

Certificate # 7485

2MSHA03798

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-13-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM

End 5:10 AM/PM

Examiners Initials LD

Time of Examination Start 3:15 AM/PM

End 5:19 AM/PM

Examiners Initials Sm

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	Dust Head to tail	3 on + men to work on Dusted 7-13-07
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	Dust 39-42	3 on + men to dust Dusted 7-13-07
Belt kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O monitors	visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 8759

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

2MSHA03799

Counter Signature

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-13-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:46 AM/PM Examiners Initials LH

Time of Examination Start 11:04 AM/PM End 1:46 AM/PM Examiners Initials AB

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	none obs	
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	21	0	0	OK	none obs	
#6	20	0	0	OK	ALL AT Handroller	Cleaned 7-13-07
#7	20	0	0	OK	none obs	
Transformers	21	0	0	OK	none obs	
Kitchen	21	0	0	OK	none obs	
CD sensors			Visual	exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & travel at
Time of exam.

Signature

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 8703

Certificate # 8914

Certificate # _____

Certificate # _____

SIGNATURE

2MSHA03800

Counter Signature

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-13-07

SECTION/AREA Belts
 Examiners Initials KK/PL

Time of Examination Start 7:00 AM/PM

End 9:50 AM/PM

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Report Received by _____

Called Out By _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0		OK	none obs.	
#2	20.9	0.0		OK	none obs.	
#3	20.9	0.0		OK	none obs.	
#4	20.9	0.0		OK	none obs.	
#5	20.9	0.0		OK	none obs.	
#6	20.9	0.0		OK	none obs.	
#7	20.9	0.0		OK	none obs.	
Kitchen	20.9	0.0		OK	none obs.	
Trans.	20.9	0.0		OK	none obs.	
C.O. Monitor <u>exam OK</u>						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of exam

Signature

Pre-Shift/Mine Examiner _____

Certificate # 7959

Pre-Shift/Mine Examiner _____

Certificate # 640

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

2MSHA03801

Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-14-07 SECTION/AREA Belts
 Time of Examination Start 300 AM/PM End 550 AM/PM Examiners Initials RLK
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0	OK	no obs	
#2	20.9	0.0	0	OK	accum tail	3000 man to shovel DONE 7-14-07
#3	20.9	0.0	0	OK	none obs	
#4	20.9	0.0	0	OK	none obs	
#5	20.9	0.0	0	OK	none obs	
#6	20.9	0.0	0	OK	none obs	
#7	20.9	0.0	0	OK	none obs	
Kitchen	20.9	0.0	0	OK	none obs	
truss	20.9	0.0	0	OK	none obs	
C.O. Monitor <u>visual exam</u>						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe

Signature

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 795P

Certificate # 6801

Certificate # _____

Certificate # _____

Signature

2MSHA03802

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-14-07

SECTION/AREA Belts

Time of Examination Start 11:03 AM PM End 1:40 AM PM Examiners Initials ML

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	none observed	
#2	20.9	0	0		OK	none observed	
#3	20.9	0	0		OK	none observed	
#4	20.9	0	0		OK	none observed	
#5	20.9	0	0		OK	none observed	
#6	20.9	0	0		OK	none observed	
#7	20.9	0	0		OK	none observed	
TRANSFORMERS	20.9	0	0		OK	none observed	
KITCHEN	20.9	0	0		OK	none observed	
COMPOSTERS					VISUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Pre-Shift/Mine Examiner **Signature** _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA03803

Certificate # _____

Counter Signature **SIGNATURE** _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-14-07

SECTION/AREA Belts

Time of Examination Start 7:12 AM/PM AM End 9:05 AM/PM PM Examiners Initials PG

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.8	0	0	OK	None observed	
#2	20.8	0	0	OK	None observed	
#3	20.8	0	0	OK	None observed	
#4	20.8	0	0	OK	accumulation at Tail	and must be clear Done 7-15-07
#5	20.8	0	0	OK	accumulation at Tail	and must be clear Done 7-15-07
#6	20.8	0	0	OK	None observed	
#7	20.8	0	0	OK	None observed	
Ketchers	20.8	0	0	OK	None observed	
Transformers	20.8	0	0	OK	None observed	
CO Sensors	20.8	0	0	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Pre-shift

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9585
 Certificate # 7954
 Certificate # _____
 Certificate # _____

2MSHA03804

Counter Signature **SIGNATURE** _____

Certificate # N/A

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-15-07

SECTION/AREA Belts

Time of Examination Start 3:14 AM PM End 5:16 AM PM Examiners Initials DS/PL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.8	0	0	OK	none observed	
#2	20.8	0	0	OK	none observed	
#3	20.8	0	0	OK	none observed	
#4	20.8	0	0	OK	none observed	
#5	20.8	0	0	OK	none observed	
#6	20.8	0	0	OK	none observed	
#7	20.8	0	0	OK	none observed	
Belt Kitchen	20.8	0	0	OK	none observed	
Belt Trans.	20.8	0	0	OK	none observed	
<i>C.G. Monitors covered</i>						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of exam

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9585
 Certificate # 6401
 Certificate # _____
 Certificate # _____

2MSHA03805

Counter Signature **SIGNATURE** _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-15-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM AM PM End 1:39 AM/PM AM PM Examiners Initials MC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	OK	None observed	
#2	20.9	0.0	0.0	OK	Loose top 25-24	Prayed down 7-15-07
#3	20.9	0.0	0.0	OK	None observed	
#4	20.9	0.0	0.0	OK	None observed	
#5	20.9	0.0	0.0	OK	None observed	
#6	20.9	0.0	0.0	OK	None observed	
#7	20.9	0.0	0.0	OK	Accum TA: piece	Cleaned 7-15-07
Transformers	20.9	0.0	0.0	OK	None observed	
Kitchen	20.9	0.0	0.0	OK	None observed	
CO monitors				Visual Exam	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE _____

2MSHA03806

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-15-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM PM End 940 AM/PM AM PM Examiners Initials KK/PL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	none observed	
#3	21	0	0	OK	none observed	
#4	21	0	0	OK	roller pulley 70-72	sawd men to clean done 7-15-07
#5	21	0	0	OK	roller pulley 105-108	sawd men to clean done 7-15-07
#6	21	0	0	OK	none observed	
#7	21	0	0	OK	none observed	
Transformer	21	0	0	OK	none observed	
Kilchers	21	0	0	OK	none observed	
CO sensor	checked every					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appear safe at time of EXAM except as noted

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____ 2MSHA03807

Certificate # 6401
 Certificate # 7954
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-16-07

SECTION/AREA Belts

Time of Examination Start 3:00 (AM)PM End 5:40 (AM)PM Examiners Initials RL/LL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none observed	
#2	21	0	0	OK	none observed	
#3	21	0	0	OK	acc. talk piece	sent people to clean it Done 7/16/07
#4	21	0	0	OK	none observed	
#5	21	0	0	OK	none observed	
#6	21	0	0	OK	none observed	
#7	21	0	0	OK	none observed	
Belt Trans.	21	0	0	OK	none obs	
Belt Kitchen	21	0	0	OK	none obs	
CO Monitor						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Signature

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6406
 Certificate # 7959
 Certificate # _____
 Certificate # _____

2MSHA03808

SIGNATURE

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-16-07 SECTION/AREA BELTS

Time of Examination Start 11:10 AM PM End 1:35 AM PM Examiners Initials BP

Time of Examination Start 11:00 AM PM End 1:35 AM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	none observed	
#2	20	0	0	OK	none observed	
#3	20	0	0	OK	none observed	
#4	20	0	0	OK	none observed	
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	none observed	
#7	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
CO Sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe
cut time of Exam

SIGNATURE

Pre-Shift/Mine Examiner _____ Certificate # 9399

Pre-Shift/Mine Examiner _____ Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA03809 Certificate # _____

SIGNATURE

Counter Signature _____ Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-16-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:00 AM/PM PM Examiners Initials LD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	Dust Head-tail	BEING DISTED DONE LD
#7	20.9	0	0	ok	none observed	
Belt kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Sensors	Visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appear safe at the time of exam excepts those noted above

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9660
 Certificate # 7954
 Certificate # _____
 Certificate # _____

2MSHA03810

Counter Signature **SIGNATURE** _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-17-07

SECTION/AREA Belts

Time of Examination Start 3:03 AM/PM End 5:12 AM/PM Examiners Initials EG

Time of Examination Start 7:00 AM/PM End 9:00 AM/PM Examiners Initials LD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.8	0	0	Ok	ACC Tail and 1XC Out by	Sent people to clean. CA
#2	20.8	0	0	Ok	none observed	
#3	20.8	0	0	Ok	none observed	
#4	20.8	0	0	Ok	ACC Tail	Sent people to clean. CA Done 7-17-07
#5	20.8	0	0	Ok	none observed	
#6	20.8	0	0	Ok	none observed	
#7	20.8	0	0	Ok	none observed	
Belt Kitchen	20.8	0	0	Ok	none observed	
Transformers	20.8	0	0	Ok	none observed	
C/D Sensors	20.8	0	0	Ok	visual exam	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9585
 Certificate # 9660
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____ 2MSHA03811

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-17-07

SECTION/AREA BELTS

Time of Examination Start 11:10 AM/PM End 1:40 AM/PM Examiners Initials BP

Time of Examination Start 11:05 AM/PM End 1:49 AM/PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	ACC AT TA. 11 RE OUTBY SEE BELOW	People working on it
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	ACC UNDER DRIVE AND NEEDS DUSTED AROUND DRIVE	people working on it
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	need dust xc UTIL 4 TOP/ACC AT HEAD	people working on it
Kitchen	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
CO SENSORS				WISAO / Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS #1 Belt Roller piles just outby drive & needs Dusted Done
VL6-13 And (25-34) ACC xc 8. Other than Listed Above All AREAS
Assessed safe at time of Exam Done 7/17/07 CA

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Certificate # 9599

Pre-Shift/Mine Examiner _____

Certificate # 9362

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA03812

Certificate # _____

SIGNATURE _____

Counter Signature _____

Certificate # 05942

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-17-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:00 AM/PM PM Examiners Initials SD/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	Acc tail 11x9 out by accomplished in by 2 BELTS	WORKING ON DONE SD
#2	20.9	0	0	ok	Xc 2 Trash Acc Cool needs dust	SENT MAN TO CLEAN DONE SD
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	Acc under Drive and needs dusted Around drive	BEING CLEANED DUSTED DONE CG
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	needs dust 114-tail Acc Head	WORKING ON DONE SD Acc Head Done SD
Kitchen	20.9	0	0	ok	none observed	
transformer	20.9	0	0	ok	none observed	
C/O Sensors	V. Seal			exam ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe except as noted above.

Pre-Shift/Mine Examiner **Signature** _____ Certificate # 9660
 Pre-Shift/Mine Examiner _____ Certificate # 7954
 Pre-Shift/Mine Examiner _____ Certificate # _____
 Pre-Shift/Mine Examiner _____ 2MSHA03813 Certificate # _____

Counter Signature **Signature** _____ Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-18-07

SECTION/AREA Belt's

Time of Examination Start 4:00 (AM/PM)

End 5:03 (AM/PM)

Examiners Initials DB

Time of Examination Start 3:00 (AM/PM)

End 5:15 (AM/PM)

Examiners Initials LD

Time of Examination Start 3:00 (AM/PM)

End 5:15 (AM/PM)

Examiners Initials SW

Exam. Called Out - Yes No

Called Out By Dale Black #7 Belt Only

Called Out By _____

Report Received by [Signature]

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	Dust 19-tail	Sent men to dust of Done 7-18-07 TC
#2	20.9	0	0	ok	Dust 0-Head	Sent men to dust of Done 7-18-07 TC
#3	20.9	0	0	ok	Dust Head-40	Sent men to dust of Done 7-18-07 TC
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	OK	134-tail piece need dust	Sent duster & people Done 7-18-07
Belt kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Sensors	visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appear safe at the time of exam except those noted above.

Pre-Shift/Mine Examiner [Signature]
 Pre-Shift/Mine Examiner [Signature]
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9660
 Certificate # 9548
 Certificate # 7485
 Certificate # _____

2MSHA03814

Counter Signature [Signature]

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7/18/07 SECTION/AREA Belts.

Time of Examination Start 11:15 AM/PM AM End 1:30 AM/PM PM Examiners Initials TC

Time of Examination Start 11:00 AM/PM AM End 1:30 AM/PM PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.0	0	0	OK	NEEDS DUSTED 7419-32	Men working on DUNE 35
#2	20.9	0	0	OK	ACC AT Tail piece	Men working on DUNE 20
#3	20.9	0	0	OK	none obs.	
#4	20	0	0	OK	none observed	
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	none observed	
#7	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
Transformers	20.9	0	0	OK	none obs.	
Clo sensor				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at
Time of Exam Excepted Noted Above.

Pre-Shift/Mine Examiner **Signature** _____ Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # 9599

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA03815

Counter Signature **Signature** _____ Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-18-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:05 AM/PM PM Examiners Initials LD

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	Dust 19-32 ACC XLS Box check	WORKING ON DONE SG
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	acc at tail	Done LD
#5	20.9	0	0	ok	tail needs dusting	BEING DUSTED Done LD
#6	20.9	0	0	ok	tail needs dusting	BEING DUSTED Done LD
#7	20.9	0	0	ok	none observed	
Belt kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Sensors	visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe at time of exam except noted above.

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 9548

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA03816

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 7488

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-19-07

SECTION/AREA Belts

Time of Examination Start 3:00 AMPM End 5:05 AMPM Examiners Initials LD

Time of Examination Start 3:00 AMPM End 5:35 AMPM Examiners Initials EW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	Dust 30-34	Sent people to dust at Done 7/19/07
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	Dust 90-tail	Dusting with bulk duster Done 7/19/07 CA
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Belt kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Sensors	visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9660
 Certificate # 9548
 Certificate # _____
 Certificate # _____

2MSHA03817

Counter Signature **SIGNATURE** _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-19-07

SECTION/AREA Belts

Time of Examination Start 11:10 ~~AM~~/PM End 1:45 AM/~~PM~~ Examiners Initials TK

Time of Examination Start 11:00 ~~AM~~/PM End 1:40 AM/~~PM~~ Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none obs	
#4	20.9	0	0	OK	ACC AT TAIL	sent people to clean. CA None 7/19/07
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	none observed	
Belt Kitchen	20.9	0	0	OK	none observed	
Belt transformer	20.9	0	0	OK	none obs.	
CO Monitors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS: All areas appeared safe at time of exam. except noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9588

Pre-Shift/Mine Examiner _____

Certificate # 9362

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA03818

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-19-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:20 AM/PM PM Examiners Initials LR

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	roller piles head to tail of 68	SENT MEN TO CLEAN Done 7-20-07 SW
#5	20.9	0	0	ok	Acc. tail	SENT MEN TO CLEAN Done 7-20-07 SW
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Belt kitchen	20.9	0	0	ok	none observed	
Belt transformers	20.9	0	0	ok	none observed	
C/O Sensors	Visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam except noted above.

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9660
 Certificate # 9548
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____ 2MSHA03819

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-20-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:25 AM/PM Examiners Initials ZD

Time of Examination Start 3:00 AM/PM End 5:50 AM/PM Examiners Initials SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Dust 7-8 Box Check	Ass. men to Dust done 7-20-07
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	Dust Tail	Ass. men to Dust done 7-20-07
#4	20.9	0	0	OK	ACC Tail	Ass men to clean done 7-20-07
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	ACC 7 Dump point - 20' out by	Ass men to clean done 7-20-07
#7	20.9	0	0	OK	none observed	
Belt Kitchen	20.9	0	0	OK	none observed	
Belt transformer	20.9	0	0	OK	none observed	
C/O Sensors	Visual exam					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all Areas appear safe at the time of exam except those noted above

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9660
 Certificate # 9548
 Certificate # _____
 Certificate # _____

2MSHA03820

Counter Signature **SIGNATURE** _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-20-07

SECTION/AREA Belts

Time of Examination Start 1100 AM PM End 1:30 AM PM Examiners Initials LR/WR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None observed	
#2	20.9	0	0		OK	None observed	
#3	20.9	0	0		OK	None observed	
#4	20.9	0	0		OK	accum 99-105 off working collects 92-95	
#5	20.9	0	0		OK	accum tail off working	done 7-20-07
#6	20.9	0	0		OK	accum cross under in by hand	done 7-20-07
#7	20.9	0	0		OK	None observed	
Belt Kicker	20.9	0	0		OK	None observed	
Belt Transfer	20.9	0	0		OK	None observed	
CO Sensor						Visual error	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area beyond Scope at time of Exam except as noted above

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4375
 Certificate # 7954
 Certificate # _____
 Certificate # _____

2MSHA03821

Counter Signatur **Signature** _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-20-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 943 AM/PM PM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	ALL 100-102 OFF WALKWAY Roller piles 92-95	Working on pave 7-21-07
#5	20.9	0	0	ok	Coal acc. At tail-piece	Working on pave 7-21-07
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Belt Trans.	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CO Sensors				Misual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 7375
 Certificate # _____
 Certificate # _____

2MSHA03822

Counter Signature **Signature** _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-21-07 SECTION/AREA Belts

Time of Examination Start 3:01 AM/PM End 5:40 AM/PM Examiners Initials MC/PO

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
TP Performers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO mon:tors				Visual Exam	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of pre-shift

Pre-Shift/Mine Examiner **Signature** _____ Certificate # 7325

Pre-Shift/Mine Examiner _____ Certificate # 8058

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA03823 _____ Certificate # _____

SIGNATURE _____ Certificate # 4135

Counter Signature _____

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-21-07 SECTION/AREA Belts

Time of Examination Start 11:00 ~~AM~~/PM End 2:00 AM/~~PM~~ Examiners Initials LR/IKR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	Oil Acc at drive	degreased 7-21-07
#5	20.9	0	0	OK	None observed	
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None observed	
Belt Tensioners	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
CO Sensors v. 5 unit Exam OK						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner **Signature** _____ Certificate # 4325

Pre-Shift/Mine Examiner **Signature** _____ Certificate # 7954

Pre-Shift/Mine Examiner _____ 2MSHA03824 Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature **SIGNATURE** _____ Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-21-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM (M) End 935 AM/PM (M) Examiners Initials DD mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	x 101-102 coal in walkway 99-100 coal acc off walkway	working on
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	none observed	
TRANS.	20.9	0	0	ok	none observed	
CO Sensors		Visual	ok			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe at time of exam

Signature

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

2MSHA03825

Certificate # 8058

Certificate # 7375

Certificate # _____

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-22-07 SECTION/AREA BELTS

Time of Examination Start 3:00 AM/PM End 5:30 AM/PM Examiners Initials MC/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	OK	Accum xcut 34	Done 7-22-07
#2	20.9	0.0	0.0	OK	none observed	
#3	20.9	0.0	0.0	OK	none observed	
#4	20.9	0.0	0.0	OK	88 to 89 coal Accum offside 99 to 100 coal Accum offside	Ass new to clean Done 7-22-07
#5	20.9	0.0	0.0	OK	none observed	
#6	20.9	0.0	0.0	OK	none observed	
#7	20.9	0.0	0.0	OK	none observed	
Transformers	20.9	0.0	0.0	OK	none observed	
Kitchen	20.9	0.0	0.0	OK	none observed	
CO monitors				Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared reasonably safe
at time of pre-shift

Signature

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 7375

Certificate # 8058

Certificate # _____

Certificate # _____

SIGNATURE

2MSHA03826

Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-22-07

SECTION/AREA Beeth

Time of Examination Start 11:00 AM End 1:10 AM Examiners Initials UR/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	96 to 97 1/2 coal Acc.	Ass. mem to Clean done 7-22-07
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Trano	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
LiO. monitors used						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner **Signature** _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

2MSHA03827

Certificate # 4375

Certificate # 6406

Certificate # _____

Certificate # _____

Counter Signature **SIGNATURE** _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-22-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM PM End 945 AM/PM AM PM Examiners Initials DD/mz

Time of Examination Start _____ AM/PM _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Report Received by _____

Called Out By _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	COAL ACC AT TAIL	ASS. MEN TO WORK ON DONE 7-23-07
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	COAL ACCUMULATIONS AT TAIL	ASS. MEN TO WORK ON DONE 7-23-07
#5	20.9	0	0	ok	Accumulations AT Drive	ASS. MEN TO WORK ON DONE 7-23-07
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
TRANS.	20.9	0	0	ok	none observed	
CO Sensors		Visual	ok			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner Signature
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 7525
 Certificate # _____
 Certificate # _____

2MSHA03828

Counter Signature SIGNATURE

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-23-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:25 AM/PM Examiners Initials MG/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Accum TRASH + OIL AT XCUTS	done 7-23-07
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	Accum 101 TO TRAILPIECE	done 7-23-07 TO Trailpiece
#5	20.9	0	0	OK	AS Accum 106 TO DRIVE CROSSUNDER NEEDS PUT UP	done 7-23-07
#6	20.9	0	0	OK	Accum DRIVE need dust DRIVE AREA	cleaned drive
#7	20.9	0	0	OK	Accum Headroller	done 7-23-07
TransPremiers	20.9	0	0	OK	none observed	
R: Ehen	20.9	0	0	OK	none observed	
CO sensors				VISUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT
Time of pre-shift

Pre-Shift/Mine Examiner [Signature] Certificate # 7375

Pre-Shift/Mine Examiner [Signature] Certificate # 8058

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA03829

Counter Signature [Signature] Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-23-07

SECTION/AREA Belts

Time of Examination Start 11:05 AM PM End 1:15 AM PM Examiners Initials LR/RK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0.0	0.0	OK	None observed	
#2	21.0	0.0	0.0	OK	Need to dust Headroll to 50' in by & dust under belt	Dusted Headroll to 50' in by 7-20-26 Done
#3	21.0	0.0	0.0	OK	None observed	
#4	21.0	0.0	0.0	OK	Tail piece Needs Cleaned	0551 AM to work on
#5	21.0	0.0	0.0	OK	None observed	
#6	21.0	0.0	0.0	OK	Need to dust Headroll Area	Working on Done 7-23-07
#7	21.0	0.0	0.0	OK	Need to dust Headroll to drive	Done 7-23-07
Kitchen	21.0	0.0	0.0	OK	None observed	
TRANSFORMERS	21.0	0.0	0.0	OK	None observed	
CO SENSORS VISUAL Ekan			OK			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 4325

Certificate # 6401

Certificate # _____

Certificate # _____

2MSHA03830

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-23-07

SECTION/AREA Belts

Time of Examination Start 700 AM End 935 AM Examiners Initials PD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.8	0	0	ok	none obs.	
#2	20.8	0	0	ok	none obs.	
#3	20.8	0	0	ok	Deep water @ 45	working on done 7-24-07
#4	20.8	0	0	ok	coal acc. at tail oil acc. at Drive	working on done 7-24-07
#5	20.8	0	0	ok	coal acc. under drive	working on done 7-24-07
#6	20.8	0	0	ok	none obs.	
#7	20.8	0	0	ok	none obs.	
Kitchen	20.8	0	0	ok	none obs.	
Trans.	20.8	0	0	ok	none obs.	
CO Sensors		Visual	ok			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe at time of exam

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 7375
 Certificate # _____
 Certificate # _____

2MSHA03831

SIGNATURE
 Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-24-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:30 AM/PM Examiners Initials MC/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	Rather piling handrails to drive	WORKING ON Done 7-24-07 SWS/KIK
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	Accum Hand to Tail	Working on Done 7-24-07
#7	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO monitors					Visual Exam OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared reasonably safe
at time of pre-shift

SIGNATURE
Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 7375

Certificate # 8058

Certificate # _____

Certificate # _____

2MSHA03832

Counter Signature **Signature** _____

Certificate # 7488

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-24-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM AM End 1:00 AM/PM PM Examiners Initials SJ/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1 Belt	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	scraper pile	SENT MAN TO CLEAN DONE ✓
#6	20.9	0	0	OK	acc. head to fail	WORKING ON DONE ✓
#7	20.9	0	0	OK	roller piles vent 112-vent 114	WORKING ON DONE ✓
Transformers	20.9	0	0	OK	none observed	
kitchen	20.9	0	0	OK	none observed	
CO monitors	(VISUAL EXAM)			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appear safe at time of exam except noted above.

Pre-Shift/Mine Examinee **Signature** _____
 Pre-Shift/Mine Examinee _____
 Pre-Shift/Mine Examinee _____
 Pre-Shift/Mine Examiner _____

Certificate # 9548
 Certificate # 7955
 Certificate # _____
 Certificate # _____

2MSHA03833

Counter Signature **SIGNATURE** _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-24-07

SECTION/AREA Belts

Time of Examination Start 7:01 AM/PM AM End 9:35 AM/PM PM Examiners Initials BP

Time of Examination Start 7:05 AM/PM AM End 9:40 AM/PM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.7	0	0	OK	none observed	
#2	20.9	0	0	OK	none obs.	
#3	20.3	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	Drive Area Needs Dusted	Sent men to dust Done at 7:24:07
#7	20.5	0	0	OK	none obs.	
Transformers	20.0	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none observed	
CO SENSORS				VIGOR Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted above All Areas safe
AT Time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9589
 Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9362
 Pre-Shift/Mine Examiner _____ Certificate # _____
 Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA03834

Counter Signature **SIGNATURE** _____ Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-25-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM PM End 5:20 AM PM Examiners Initials TC

Time of Examination Start 3:00 AM PM End 5:15 AM PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Coal Acc x c 8	SENT MEN TO CLEAN done 7-25-07
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	ACC AT TAIL	SENT MEN TO CLEAN done 7-25-07
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	need fire suppression caps on DRIVE	SENT MEN TO REPLACE done 7-25-07
#7	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
Transformers	20.9	0	0	OK	none obs.	
Closets				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted above all areas appeared safe at time of exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____ Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # 9599

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA03835

SIGNATURE _____

Counter Signature _____ Certificate # 7488

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-25-07 SECTION/AREA Belts

Time of Examination Start 11:00 AM PM End 1:15 AM PM Examiners Initials AR/SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CR/M/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	None observed	
#2	21.0	0	0	OK	xcut 7 to vent 15 needs dust	BEING DUSTED DATE 7-25-07 SW
#3	21.0	0	0	OK	None observed	
#4	21.5	0	0	OK	None observed	
#5	21.0	0	0	OK	103 to 104 Needs dusted	BEING DUSTED DATE 7-25-07 SW
#6	21.0	0	0	OK	None observed	
#7	21.0	0	0	OK	None observed	
Kitchen	21.0	0	0	OK	None observed	
TRANSFORMERS	21.0	0	0	OK	None observed	
CO SENSORS V. SMOKE EXAM				OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 4325

Pre-Shift/Mine Examiner _____ Certificate # 9548

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA03836

Counter Signature **SIGNATURE** _____ Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-25-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials TC

Time of Examination Start 7:00 AM/PM AM End 9:35 AM/PM PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
#3	20.5	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.5	0	0	OK	Needs Dusted 109-MO ACC AT Tail Piece	Sent man to dust & clean OK Done 7-26-07
#6	20.5	0	0	OK	None obs.	
#7	20.5	0	0	OK	None obs.	
Kitchen	20.5	0	0	OK	None obs.	
Transformers	20.0	0	0	OK	None obs.	
CD Sensors	Visual Exam					

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted Above All AREAS APPEARED SAFE AT TIME OF EXAM

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9362

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9598

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA03837 _____ Certificate # _____

Counter Signature SIGNATURE Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-26-07 SECTION/AREA Belts.

Time of Examination Start 3:00 AM PM End 5:30 AM PM Examiners Initials TC

Time of Examination Start 3:00 AM PM End 5:30 AM PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

Called Out By _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	ACC AT TAIL	Done 20
#2	20.9	0	0	OK	None obs	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs	
#5	20.9	0	0	OK	None obs	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
Transformers	20.9	0	0	OK	None obs.	
Cl sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS: Other than noted above all Area appeared safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9362

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9599

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA03838 Certificate # _____

Counter Signature **SIGNATURE** _____ Certificate # 8725

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-26-07

SECTION/AREA Belts

Time of Examination Start 11:11 AM/PM End 12:58 AM/PM Examiners Initials P6

Time of Examination Start 11:00 AM/PM End 1:05 AM/PM Examiners Initials JD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	ACC Box check XCS	Sent men to clean PA Done 7/26/07
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	accumulation at Tail	Sent men to clean PA Done 7/26/07
#5	20.9	0	0	ok	accumulations at head roller	Sent men to clean PA Done 7/26/07
#6	20.9	0	0	ok	Need Dust Headroller in by 2XC accumulations at belt crossing	Sent men to clean and dust PA Done 7/26/07
#7	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	none observed	
Transformers	20.9	0	0	ok	none observed	
C/O Sensors	Visual Exam					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#6 Head roller	Needs Dusted	
#6 Head roller belt crossing	accumulations	
#5 Head roller zone	accumulations	

PRE-SHIFT REMARKS all areas appear safe at the time of exam except those noted above

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9660
 Certificate # 9895
 Certificate # _____
 Certificate # _____

2MSHA03839

SIGNATURE

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-26-07 SECTION/AREA Belts

Time of Examination Start 7:01 ~~AM/PM~~ End 9:30 AM/PM Examiners Initials BP

Time of Examination Start 7:00 AM/PM End 9:20 AM/PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Belted Piles X 8 1/2	Sent people to clean of done 7/27/07
#2	20.9	0	0	OK	ACC AT TAIL	Sent people to clean of done 7/27/07
#3	20.9	0	0	OK	CONT SPILL 2L 39 1/2 + 67 1/2	Sent people to clean of done 7/27/07
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	Needs 5 Bag AT Tail none observed	Put dust there. of done
Transformers	20.9	0	0	OK	none observed	
KITCHEN	20.9	0	0	OK	none observed	
CO SENSORS	20.9	0	0	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS other than noted above all AREAS
SAFE AT TIME OF EXAM

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9599

Pre-Shift/Mine Examiner _____ Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA03840 Certificate # _____

Counter Signature **SIGNATURE** _____ Certificate # 03692

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-27-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM PM End 5:16 AM PM Examiners Initials BP

Time of Examination Start 3:00 AM PM End 5:20 AM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	OK	Coal Acc INBY Takeup	Sent men in / Done 7-27-07
#2	20.9	0.0	0.0	OK	Needs Dusted x CO TO HEAD ROLLER	Sent men in / Done 7-27-07
#3	20.9	0.0	0.0	OK	none obs.	
#4	20.9	0.0	0.0	OK	none observed	
#5	20.9	0.0	0.0	OK	none observed	
#6	20.9	0.0	0.0	OK	none observed	
#7	20.9	0.0	0.0	OK	Call in walk way x cut 130 to 131	Sent men in / Done 7-27-07
Transformer	20.9	0.0	0.0	OK	none observed	
Kitchen	20.9	0.0	0.0	OK	none observed	
CO SENSORS	20.9	0.0	0.0	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted above ALL AREAS APPEARED
Safe AT Time of Exam

Pre-Shift/Mine Examiner [Signature]

Pre-Shift/Mine Examiner [Signature]

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 9599

Certificate # 9362

Certificate # _____

Certificate # _____

2MSHA03841

Counter Signature [Signature]

Certificate # 7483

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-27-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:00 AM/PM Examiners Initials SW

Time of Examination Start 11:02 AM/PM End 1:00 AM/PM Examiners Initials PL

Time of Examination Start 11:02 AM/PM End 2:50 AM/PM Examiners Initials AB

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.7	0	0	OK	Pantal to Drive needs dust #1 Tail out by 1XC	working on it Done 7-27-07
#2	20.0	0	0	OK	none observed	
#3	20.7	0	0	OK	roller piles XL 65-66 Roller pile XL 50	working on Done 7-27-07
#4	20.0	0	0	OK	none observed	
#5	20.0	0	0	OK	roller piles east 104 - east 106 + all pieces needs dust	working on 7-27-07 Done
#6	20.0	0	0	OK	roller piles east 3 - east 4	working on 7-27-07 Done
#7	20.7	0	0	-OK	none observed	
Transformers	20.0	0	0	OK	none observed	
kitchen	20.0	0	0	OK	none observed	
Comonitors	(Wishal exam)			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe at time of exam except noted above.

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____ 2MSHA03842

Certificate # 9548
 Certificate # 9895
 Certificate # 7483
 Certificate # _____

Counter Signature **SIGNATURE** _____

Certificate # _____

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-27-07 SECTION/AREA Belts.

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials TC

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	oil Acc at Drive	Done 7/27/07 Sent man to clean it
#2	20.9	0	0	OK	ACC AT Tail Piece	Sent people to clean it Done 7/27/07
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	DEEP water 73 xc	Sent man to pump it Done 7/27/07
#5	20.9	0	0	OK	None observed	
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
Transformers	20.9	0	0	OK	None obs.	
CO/montags				Visual EXA-		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Except noted Above All AREAS safe
At time of EXA-

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9562
 Certificate # 9599
 Certificate # _____
 Certificate # _____

2MSHA03843

SIGNATURE

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-28-07 SECTION/AREA Belts

Time of Examination Start 3:11 AM PM End 5:30 AM PM Examiners Initials BP

Time of Examination Start 3:00 AM PM End 5:20 AM PM Examiners Initials TR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____
 Called Out By _____
 Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CR/M/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20	0	0	OK	Deep water XLUTS working on	working on
#3	20	0	0	OK	none observed	
#4	20	0	0	OK	Deep water XLUTS	working on
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	none observed	
#7	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
CO sensors	20	0	0	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted above All Areas Appeared
SAFE AT TIME OF EXAM

SIGNATURE _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9599
 Certificate # 9362
 Certificate # _____
 Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA03844

Counter Signature **Signature** _____

Certificate # 9483

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-28-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM End 1:00 AM Examiners Initials SW

Time of Examination Start 11:00 AM End 1:00 AM Examiners Initials AR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	None observed	
#2	21.0	0	0	OK	Deep water x-cut 3 to cut 4	Working on
#3	21.0	0	0	OK	None observed	
#4	21.0	0	0	OK	None observed ^{x-cut 73} deep water	Working on
#5	21.0	0	0	OK	Acc. box to cut 107	Working on Date 7-28-07 SW
#6	21.0	0	0	OK	Acc. At dump point	Working on Date 7-28-07 SW
#7	21.0	0	0	OK	None observed	
Kitchen	21.0	0	0	OK	None observed	
Transformers	21.0	0	0	OK	None observed	
CO Monitors	Visual				114 Cable pulled out of Box	Working on Date 7-28-07

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam except as noted above. All Belts were idle at time of Pre-shift.

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9548

Pre-Shift/Mine Examiner _____

Certificate # 4375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA03845

SIGNATURE

Counter Signature _____

Certificate # 74183

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-28-07 SECTION/AREA BELTS

Time of Examination Start 7:01 AM/PM AM End 9:30 AM/PM PM Examiners Initials BP

Time of Examination Start 7:00 AM/PM AM End 9:20 AM/PM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	none observed	
#2	20	0	0	OK	2C3 needs water pumped	Being pumped Done 72907
#3	20	0	0	OK	need 5 Bag Dust a fine Ex Tail piece	
#4	20	0	0	OK	Deep water at 2C3	Being pumped Done 72907
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	ALL AT TAIL piece	Sent people to clean it Done 72907
Transformers	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
CO SENSORS				VISA Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All AREA appeared safe AT TIME OF EXAM
Except noted above

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

2MSHA03846

Certificate # 9599

Certificate # 9362

Certificate # _____

Certificate # _____

SIGNATURE _____

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-29-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM PM End 5:30 AM PM Examiners Initials BP

Time of Examination Start 3:00 AM PM End 5:25 AM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#2	20	0	0	OK	Roller Piles xc 1 to 2 3rd north Transfer to Fire Doors	Working on Date 7-29-07 NCCOs Dusted
#2	20	0	0	OK	ACC AT Tail piece	Working on Date 7-29-07
#3	20	0	0	OK	none observed	
#4	20	0	0	OK	none observed	
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	none observed	
#7	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
CO sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted Above All Areas
Appeared safe at time of Exam

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9599

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature SIGNATURE Certificate # 7483

2MSHA03847

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-29-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:00 AM/PM Examiners Initials SW

Time of Examination Start 11:51 AM/PM End 12:38 AM/PM Examiners Initials DB

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	none observed	
#2	21.0	0	0	OK	none observed	
#3	21.0	0	0	OK	none observed	
#4	21.0	0	0	OK	roller piles x-out 80 - x-out 81	working on Date 7-29-07 SW
#5	21.0	0	0	OK	scraper piles	working on Date 7-29-07 SW
#6	21.0	0	0	OK	scraper pile - acc. outty exchange	working on Date 7-29-07
#7	21.0	0	0	OK	roller piles x-out 120 - x-out 131	working on Date 7-29-07 SW
Transformers	21.0	0	0	OK	none observed	
kitchen	21.0	0	0	OK	none observed	
CD Monitors	(visual exam)			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#1 Belt x-out 31	bad bottom roller	changed

PRE-SHIFT REMARKS All areas appeared safe at time of exam except noted above.

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9548

Pre-Shift/Mine Examiner _____

Certificate # 7483

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

2MSHA03848

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 7483

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-29-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials BP

Time of Examination Start 7:00 AM/PM AM End 9:18 AM/PM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.3	0	0	OK	Acc at Tail	Sent people to clean up Done 7:30P
#2	20.0	0	0	OK	Needs Dusted 4C 21-27	Sent people to dust Done 7:30P
#3	20.4	0	0	OK	none observed	
#4	20.0	0	0	OK	none observed	
#5	20.0	0	0	OK	none observed	
#6	20.0	0	0	OK	none observed	
#7	20.0	0	0	OK	none observed	
Transformers	20.0	0	0	OK	none observed	
Kitchen	20.0	0	0	OK	none observed	
CO Sensors					Visual Exam	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe at time of Exam except noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 9589

Certificate # 9562

Certificate # _____

Certificate # _____

2MSHA03849

SIGNATURE

Counter Signature _____

Certificate # 05892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-30-07 SECTION/AREA Belts

Time of Examination Start 3:11 AM PM End 5:30 AM PM Examiners Initials BP

Time of Examination Start 3:07 AM PM End 5:20 AM PM Examiners Initials TR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none observed	
#2	20	0	0	ok	ACC Roller P. 1.05 Head To Drive	Ass. men to clean done 7-30-07
#3	20	0	0	ok	none observed	
#4	20	0	0	ok	ACC AT TAIL none observed	Ass. men to clean done 7-30-07
#5	20	0	0	ok	need dusted none observed	Ass TO DUST
#6	20	0	0	ok	none obs.	
#7	20	0	0	ok	none observed	
Transfer area	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
CO Sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS other than noted above ALL AREAS
appeared safe AT time of exam

Signature

Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____

Certificate # 9599
Certificate # 9362
Certificate # _____
Certificate # _____

SIGNATURE

2MSHA03850

Counter Signature _____

Certificate # 4135

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-30-07

SECTION/AREA Belts
 Examiners Initials KM/RL

Time of Examination Start 1100 AM/PM End 138 AM/PM

Time of Examination Start _____ AM/PM End _____ AM/PM

Time of Examination Start _____ AM/PM End _____ AM/PM

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none observed	
#2	20.9	0	0	OK	none obs	
#3	21	0	0	OK	none obs.	
#4	21	0	0	OK	none obs.	
#5	20.9	0	0	OK	Needs DUS Fed	Working on Suit 7-30-07
#6	21	0	0	OK	none obs.	
#7	21	0	0	OK	none obs.	
Transformers	21	0	0	OK	none obs.	
Kitchen	21	0	0	OK	none obs.	
CO Sensors	Visual Exam					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at end of exam

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6401
 Certificate # 7959
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____
 2MSHA03851

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-30-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 935 AM/PM AM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	Acc. @ Tail Piece	working on Done ^{7:30}
#5	20.9	0	0	ok	COAL Acc at Drive	working on Done ^{7:30}
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Trans.	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CO Sensors					not working	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 7325
 Certificate # _____
 Certificate # _____

Counter Signature SIGNATURE

2MSHA03852

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-31-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM PM End 5:10 AM PM Examiners Initials MC/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	Accum xcuts	Sent maintenance clean done 7-31-07
#7	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO-SENSORS						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 7375

Certificate # 8058

Certificate # _____

Certificate # _____

SIGNATURE _____

2MSHA03853

Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-31-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM PM End 1:30 AM PM Examiners Initials LR/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	Acc. At Tail Drive Area Needs dusted	Dusted on Tail Drive Area
#2	21.0	0	0	OK	Need Timber between 22223	Set timber
#3	21.0	0	0	OK	None observed	
#4	21.0	0	0	OK	None observed	
#5	21.0	0	0	OK	None observed	
#6	21.0	0	0	OK	None observed	
#7	21.0	0	0	OK	None observed	
Transformers	21.0	0	0	OK	None observed	
Kitchen	21.0	0	0	OK	None observed	
CO Sensors	Visual	Exam	OK	OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4325
 Certificate # 7954
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____ 2MSHA03854

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-31-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM ~~AM~~ End 240 AM/PM ~~AM~~ Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	coal acc. @ tail	working on ^{Cleaned} 7-31-07
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	none obs.	
#4	21	0	0	ok	Deep water cut 73 coal acc. at tail	working on ^{pumped} 7-31-07 cleaned & pumped
#5	21	0	0	ok	none obs.	
#6	21	0	0	ok	none obs.	
#7	21	0	0	ok	none obs.	
TRANS	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
CO Sensors		VISUAL OK				

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe at time of exam

SIGNATURE [Redacted]

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

Signature [Redacted]

2MSHA03855

Counter Signature

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-1-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:15 AM/PM Examiners Initials MC/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	NONE OBSERVED	
#2	20.9	0	0	OK	NONE OBSERVED	
#3	20.9	0	0	OK	Accum Tailpiece	Ass men to clean Done 8/1/07
#4	20.9	0	0	OK	Accum Tailpiece offside	Ass men to clean None 8/1/07
#5	20.9	0	0	OK	NONE OBSERVED	
#6	20.9	0	0	OK	NONE OBSERVED	
#7	20.9	0	0	OK	COAL ACC. 138-139	Ass men to clean None 8/1/07
TRUCKS PARKING	20.9	0	0	OK	NONE OBSERVED	
Kitchen	20.9	0	0	OK	NONE OBSERVED	
CO monitors				W/USM EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE
AT TIME OF PRE-SHIFT

SIGNATURE [Redacted]

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 7375

Certificate # 8058

Certificate # _____

Certificate # _____

SIGNATURE [Redacted]

2MSHA03856

Counter Signature

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 308-01-07 SECTION/AREA Belts

Time of Examination Start 11:00 AM PM End 1:30 AM PM Examiners Initials LR/KR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None observed	
#2	20.9	0	0		OK	Acc. AT TRIL	sent men to work on done 8-1-07
#3	20.9	0	0		OK	None observed	
#4	20.9	0	0		OK	Acc. Tripup To Brake	sent men to work on done 8-1-07
#5	20.9	0	0		OK	None observed	
#6	20.9	0	0		OK	None observed	
#7	20.9	0	0		OK	None observed	
Transformers	20.9	0	0		OK	None observed	
Kitchens	20.9	0	0		OK	None observed	
CO Sensors	Visual		OK		OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of exam except as noted above

SIGNATURE _____

Pre-Shift/Mine Examiner _____ Certificate # 4375

Pre-Shift/Mine Examiner _____ Certificate # 7954

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

SIGNATURE _____ 2MSHA03857

Counter Signature _____ Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-1-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM PM End 930 AM/PM AM PM Examiners Initials DD mc

Time of Examination Start _____ AM/PM AM PM End _____ AM/PM AM PM Examiners Initials _____

Time of Examination Start _____ AM/PM AM PM End _____ AM/PM AM PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0		ok	none observed	
#2	21	0	0		ok	none observed	
#3	21	0	0		ok	none observed	
#4	21	0	0		ok	none observed	
#5	21	0	0		ok	none observed	
#6	21	0	0		ok	none observed	
#7	21	0	0		ok	none observed	
TRAWS	21	0	0		ok	none observed	
Kitchen	21	0	0		ok	none observed	
CO Sensors		Visual			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe at time of exam

Pre-Shift/Mine Examiner **Signature** _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 8058

Certificate # 7375

Certificate # _____

Certificate # _____

Counter Signature **Signature** _____

2MSHA03858

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-2-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:15 AM/PM Examiners Initials MC/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none obs	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none obs.	
Transformers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
COM monitors				visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of pre-shift

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7375
 Certificate # 8058
 Certificate # _____
 Certificate # _____

SIGNATURE
 Counter Signature _____

2MSHA03859

Certificate # 4135

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-20-07 SECTION/AREA Belts

Time of Examination Start 11:00 AM PM End 1:15 AM PM Examiners Initials KLR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	8 to 12 Needs dusted	workments done done 8-2-07
#2	20.9	0	0	OK	none obs	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	none obs	
#6	20.9	0	0	OK	accumulation 1-2 ft	Ass. men to clean done 8-2-07
#7	20.9	0	0	OK	None observed	
Transformers	20.9	0	0	OK	none obs	
Kitchens	20.9	0	0	OK	none obs	
CO Sensors	visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM Except as noted above.

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7954
 Certificate # 4325
 Certificate # _____
 Certificate # _____

SIGNATURE

2MSHA03860

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-2-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM End 935 AM/PM Examiners Initials DD MC

Time of Examination Start _____ AM/PM _____ End _____ AM/PM _____ Examiners Initials _____

Time of Examination Start _____ AM/PM _____ End _____ AM/PM _____ Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	COAL ACC. @ TAILPIECE	ass. men to shovel cleaned 8-2-07
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	COAL ACC. AT X-76 & 157	ass. men to shovel Done 8-2-07
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Trans.	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CO Sensors		Visual	ok			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA03861

Certificate # _____

SIGNATURE _____

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-3-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:15 AM/PM Examiners Initials MC/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	need dust drive to BRAKE	BEING DUSTED Done DD 8-3-07
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	need dust w/ty to trail	BEING DUSTED Done DD 8-3-07
#7	20.9	0	0	OK	none observed	
TRANSFORMERS	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO MONITORS				VISUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

2MSHA03862

Certificate # 7375
 Certificate # 8058
 Certificate # _____
 Certificate # _____

Counter Signature **Signature**

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-3-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 12:50 AM/PM Examiners Initials LD

Time of Examination Start 11:00 AM/PM End 1:00 AM/PM Examiners Initials SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	none observed	
#2	21.0	0	0	OK	none observed	
#3	21.0	0	0	OK	none observed	
#4	21.0	0	0	OK	none observed	
#5	21.0	0	0	OK	scraper pile out by drive	working on Done LD 8-3-07
#6	21.0	0	0	OK	scraper pile out by drive	working on Done LD 8-3-07
#7	21.0	0	0	OK	5 bags dust needed tail AC 138 need guarding cable	working on Done LD 8-3-07
trans formers	21.0	0	0	OK	none observed	
kitchen	21.0	0	0	OK	none observed	
C/O SerDang (visual exam)				OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam except noted above.

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9548
 Certificate # 9660
 Certificate # _____
 Certificate # _____

2MSHA03863

Counter Signature Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-3-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials BP

Time of Examination Start 7:00 AM/PM AM End 9:25 AM/PM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none observed	
#2	20	0	0	ok	none observed	
#3	20	0	0	ok	none observed	
#4	20	0	0	ok	none observed	
#5	20	0	0	ok	none observed	
#6	20	0	0	ok	none observed	
#7	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
CO Sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 9599

Certificate # 9362

Certificate # _____

Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA03864

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-4-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM PM End 5:30 AM PM Examiners Initials BP

Time of Examination Start 3:00 AM PM End 5:25 AM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none observed	
#2	20	0	0	ok	none observed	
#3	20	0	0	ok	none observed	
#4	20	0	0	ok	none observed	
#5	20	0	0	ok	none observed	
#6	20	0	0	ok	none observed	
#7	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
CO SENSORS	20	0	0	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All AREAS APPEARED SAFE AT TIME OF EXAM

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9599

Pre-Shift/Mine Examiner _____ Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature SIGNATURE 2MSHA03865 Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-4-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 120 AM/PM Examiners Initials LD

Time of Examination Start 11:03 AM/PM End 1:26 AM/PM Examiners Initials LD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		ok	none observed	
#2	20.9	0	0		ok	none observed	
#3	20.9	0	0		ok	none observed	
#4	20.9	0	0		ok	none observed	
#5	20.9	0	0		ok	none observed	
#6	20.9	0	0		ok	acc cross under acc head	working on done 5G
#7	20.9	0	0		ok	none observed	
Belt kitchen	20.9	0	0		ok	none observed	
transformers	20.9	0	0		ok	none observed	
CO/Sensors	visual exam						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at the time of exam.
All Belts Idle at the time of exam

Pre-Shift/Mine Examine **Signature** _____
 Pre-Shift/Mine Examine **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9660
 Certificate # 7999
 Certificate # _____
 Certificate # _____

Counter Signature **Signature** _____

2MSHA03866

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-4-07 SECTION/AREA Belts

Time of Examination Start 7:30 AM/PM AM End 9:05 AM/PM PM Examiners Initials TC

Time of Examination Start 7:30 AM/PM AM End 9:15 AM/PM PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	none obs.	
Kitchen	20.7	0	0	OK	none obs.	
TRANSFORMERS	20.9	0	0	OK	none obs.	
Closets				Visual EXA-		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared reasonably safe
at time of exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____ Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # 9599

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

SIGNATURE _____ 2MSHA03867

Counter Signature _____ Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-5-07 SECTION/AREA Belts

Time of Examination Start 3:24 AM PM End 5:29 AM PM Examiners Initials TC

Time of Examination Start 3:20 AM PM End 5:30 AM PM Examiners Initials RP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	Needs Dusted Herotox100	SENT MEN TO DUST DANGER 8-5-07
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
TRANSFORMERS	20.9	0	0	OK	None obs.	
Gas Sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

All Areas appeared safe at
Time of Exam except noted above

Signature

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 9362

Certificate # 9599

Certificate # _____

Certificate # _____

2MSHA03868

Counter Signature SIGNATURE

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-5-07

SECTION/AREA belts

Time of Examination Start 11:00 AM PM End 11:18 AM PM Examiners Initials C.W

Time of Examination Start 11:00 AM PM End 1:25 AM PM Examiners Initials LD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	#8 TO 10 need dust	work on ^{done} 8-5
#2	20.9	0	0	OK	#4 ACC track need dust	working on ^{done} 8-5
#3	20.9	0	0	OK	none ob	
#4	20.9	0	0	OK	none ob	
#5	20.9	0	0	OK	none ob	
#6	20.9	0	0	OK	none ob	
#7	20.9	0	0	OK	none ob	
Kitchen	20.9	0	0	OK	none ob	
Trem for mats	20.9	0	0	OK	none ob	
G/O sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam, except noted above

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Certificate # 7999

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE _____

2MSHA03869

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-5-07 SECTION/AREA Belts

Time of Examination Start 7:20 AM/PM (M) End 9:20 AM/PM (M) Examiners Initials TK

Time of Examination Start 7:30 AM/PM (M) End 9:15 AM/PM (M) Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	OK	none obs.	Handwritten note
#2	20.9	0.0	0.0	OK	none obs.	Handwritten note
#3	20.9	0.0	0.0	OK	none obs.	Handwritten note
#4	20.9	0.0	0.0	OK	none obs.	Handwritten note
#5	20.9	0.0	0.0	OK	none obs.	
#6	20.9	0.0	0.0	OK	none obs.	
#7	20.9	0.0	0.0	OK	none obs.	
Kitchen	20.9	0.0	0.0	OK	none obs.	
Transformers	20.9	0.0	0.0	OK	none obs.	
Cp sensors		Visual exam				

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9362
 Certificate # 9199
 Certificate # _____
 Certificate # _____

2MSHA03870

Counter Signature **SIGNATURE** _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-6-07 SECTION/AREA Belts

Time of Examination Start 3:30 AM/PM AM End 5:15 AM/PM PM Examiners Initials MC/EM

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	July xcut 64 needs 4 Timbers	
#4	20.9	0	.16		see below	
#5	20.9	0	.05		see below	
#6	20.9	0	.08		see below	
#7	20.9	0	.08	OK	see below ^{His slings to 1 place} _{outside 2 Baskets}	
Kitchen	20.9	0	0	OK	none observed	
TRANSFORMERS	20.9	0	0		see below	
CO sensors				usual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Stopping #93 in by ALL down Temp stopping in Place
All other AREAS Appeared Reasonably safe AT time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 7375

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 8797

Pre-Shift/Mine Examiner _____ 2MSHA03871 Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature **Signature** _____ Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-6-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM PM End 9:05 AM/PM PM Examiners Initials MLL

Time of Examination Start 8:25 AM/PM PM End 9:05 AM/PM PM Examiners Initials BM

Time of Examination Start 8:38 AM/PM PM End 9:07 AM/PM PM Examiners Initials TC

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CR/M/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	in by 64 in Nooks of Timber none obs.	Working and DONE 8-7-07
#4	20.9	0	0	OK	SEE below	
#5	20.9	0	0	OK	SEE below	
#6	20.9	0	0	OK	SEE below	
#7	20.9	0	0	OK	Rib sluffage 2 Brakes out by Tailpiece	Working on
Kitchen	20.9	0	0	OK	none obs.	
Trans.	20.9	0	0	OK	none obs.	
C.D. Monitor manual EXAM						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS intake Belts stepping out from 96, 97, 98, 99, 100, 102, 104, 106, 107, 108, 109 + 6 Belts, 1, 2, 3, 4 all other areas appeared safe at time of exam.

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7954
 Certificate # 8395
 Certificate # 4355
 Certificate # 9362

2MSHA03872

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-7-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM

End 5:20 AM/PM

Examiners Initials KK/RR

Time of Examination Start 4:00 AM/PM

End 5:30 AM/PM

Examiners Initials TC

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	7- cut 64 inches timber	sent man to timber Done 20 8-7-07
#4	20.9	0	0	OK	none obs SEE below	
#5	20.9	0	0	OK	SEE below	
#6	20.9	0	0	OK	SEE below	
#7	20.9	0	0	OK	ATC cum out by tail	
BSH Kitchen	20.9	0	0	OK	none obs.	
Trans.	20.9	0	0	OK	none obs	
C.O. Monitor	visual	ESM	OK			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

*personal moved BMR for cut 4 on 6 belt to build
 stopping all other areas appeared safe at time of EX AM.
 intake Belt Stopping #4 93, 98, 99, 100, 102 #5 104, 106, 107, 108, 109 # 1, 2, 3, 4, 5*

Pre-Shift/Mine Examiner

Signature

Certificate # 7954

Pre-Shift/Mine Examiner

Certificate # 9362

Pre-Shift/Mine Examiner

Certificate # 8395

Pre-Shift/Mine Examiner

Certificate # 4325

SIGNATURE

Counter Signature

2MSHA03873

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-7-07

SECTION/AREA Belts

Time of Examination Start 1100 AM PM End 145 AM PM Examiners Initials DD/SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0		ok	none obs.	
#2	21	0	0		ok	none obs.	
#3	21	0	0		ok	none observed	
#4	21	0	0		ok	none observed	
#5	21	0	0		ok	none observed	
#6	21	0	0		ok	none observed	
TRANS -	21	0	0		ok	none observed	
Kitchen	21	0	0		ok	none observed	
CO monitors					Visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

Pre-Shift/Mine Examiner **Signature** _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 9548

Pre-Shift/Mine Examiner _____ 2MSHA03874

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

Counter Signature **SIGNATURE** _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-7-07 SECTION/AREA Belts

Time of Examination Start 8:30 AM/PM (M) End 9:04 AM/PM (M) Examiners Initials TC

Time of Examination Start 8:18 AM/PM (M) End 8:51 AM/PM (M) Examiners Initials BH

Time of Examination Start 7:00 AM/PM (M) End 9:30 AM/PM (M) Examiners Initials BK/LR

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs.	
#7					SEE Below	
Kitchen	20.9	0	0	OK	none obs.	
Transformers	20.9	0	0	OK	none obs.	
Comonitors						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

wrecking dangled off 2 other areas appeared safe at end of EXAM working on ventilator

Pre-Shift/Mine Examiner

Signature

Certificate #

9362

Pre-Shift/Mine Examiner

Certificate #

8395

Pre-Shift/Mine Examiner

Certificate #

7954

Pre-Shift/Mine Examiner

2MSHA03875

Certificate #

4375

Counter Signature

Signature

Certificate #

03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-8-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:40 AM/PM Examiners Initials WR/XK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0.0	0.0	OK	None observed	
#2	21.0	0.0	0.0	OK	None observed	
#3	21.0	0.0	0.0	OK	None observed	
#4	21.0	0.0	0.0	OK	None observed	
#5	21.0	0.0	0.0	OK	None observed	
#6	21.0	0.0	0.0	OK	None observed	
#7	21.0	0.0	0.0	OK	None observed	
Travis Semmes	21.0	0.0	0.0	OK	None observed	
Witcher	21.0	0.0	0.0	OK	None observed	
CO Monitor	21.0	Visual Exam OK		OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4325
 Certificate # 7954
 Certificate # _____
 Certificate # _____

2MSHA03876

Counter Signature **Signature** _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8/8/7 SECTION/AREA belts

Time of Examination Start 11:02 (AM) End 1:00 (AM) Examiners Initials LH

Time of Examination Start 1105 (AM) End 119 (AM) Examiners Initials DD

Time of Examination Start 1140 (AM) End 1:08 (AM) Examiners Initials D13

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

Called Out By _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	None obs	
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	20.9	0	0	OK	none obs	
#6	20.9	0	0	OK	wash head roller None obs	working on it
#7	20.9	0	0	OK	Tripping hazards 118-119	working on it
Transformers	21	0	0	ok	none obs,	
Kitchen	21	0	0	ok	none obs,	
CO Sensors				Visual exam ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & Travel at
Time of exam.

Pre-Shift/Mine Examinee **Signature** _____ Certificate # 8703

Pre-Shift/Mine Examinee _____ Certificate # 8058

Pre-Shift/Mine Examinee _____ Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA03877 Certificate # _____

Counter Signature **Signature** _____ Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-8-07

SECTION/AREA Belts

Time of Examination Start 7:21 AM/PM (AM)

End 8:58 AM/PM (AM)

Examiners Initials BJ

Time of Examination Start 7:25 AM/PM (AM)

End 9:05 AM/PM (AM)

Examiners Initials TC

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None Observed	
#2	20.9	0	0	OK	None Observed	
#3	20.9	0	0	OK	None Observed	
#4	20.9	0	0	OK	None Observed	
#5	20.9	0	0	OK	None Observed	
#6	20.9	0	0	OK	None Observed	
#7	20.9	0	0	OK	None Observed	
Transformers	20.9	0	0	OK	None Observed	
Kitchen	20.9	0	0	OK	None Observed	
CO monitors				Visual exam	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 8395

Certificate # 9362

Certificate # _____

Certificate # _____

SIGNATURE

2MSHA03878

Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-9-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:02 AM/PM Examiners Initials BH
 Time of Examination Start 3:00 AM/PM End 5:05 AM/PM Examiners Initials JR
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	α	None observed	
#2	20.9	0	0	α	None observed	
#3	20.9	0	0	α	None observed	
#4	20.9	0	0	α	None observed	
#5	20.9	0	0	α	None observed	
#6	20.9	0	0	α	None observed	
#7	20.9	0	6	α	None observed	
Transformers	20.9	0	0	α	None observed	
Kitchen	20.9	0	0	α	None observed	
CO monitors	Usual			exam	α	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8385
 Certificate # 9362
 Certificate # _____
 Certificate # _____

SIGNATURE
 Counter Signature _____

2MSHA03879

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-9-07

SECTION/AREA Belts

Time of Examination Start 11:01 AM/PM

End 1:22 AM/PM

Examiners Initials CC

Time of Examination Start 11:00 AM/PM

End 1250 AM/PM

Examiners Initials DD

Time of Examination Start 11:00 AM/PM

End 12:39 AM/PM

Examiners Initials LH

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1 Belt	20.9	0	0	OK	Roller Piles X 6 E X-2-X-1/Sec Below	#6 Done 8-9-07 Cleaning
#2	21	0	0	OK	Need rock dust Around drive	Working on Done 8-9-07
#3	21	0	0	OK	None obs.	
#4	21	0	0	OK	None obs.	
#5	21	0	0	OK	None obs.	
#6	21	0	0	OK	None obs.	
#7	21	0	0	OK	None obs.	
Transformers	21	0	0	OK	None obs.	
Kitchen	21	0	0	OK	None obs.	
CO Sensors	Visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe at time of exam except what is noted.

(Bad Rollers Reported & Being Replaced on #1 Belt X-2-X-1 Belt missing, Not in walkway, Reported & Flagged off) WORKING ON

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4822
 Certificate # 8058
 Certificate # 8703
 Certificate # _____

Counter Signature _____

2MSHA03880

Certificate # 7485

Signature

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-9-07 SECTION/AREA Belt

Time of Examination Start 7:06 AM/PM AM End 8:55 AM/PM PM Examiners Initials BH

Time of Examination Start 7:00 AM/PM AM End 9:00 AM/PM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs	
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	none obs	
#4	20.9	0	0	OK	none obs	
#5	20.9	0	0	OK	None observed	
#6	20.9	0	0	OK	None observed	
#7	20.9	0	8	OK	None observed	
Belt kitchen	20.9	0	0	OK	None observed	
Trans.	20.9	0	0	OK	None observed	
C.O. Monitor	20.9	0	0	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # 8395

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature **SIGNATURE** _____ 2MSHA03881 Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-10-07

SECTION/AREA Betts

Time of Examination Start 3:04 AM/PM End 5:15 AM/PM Examiners Initials BH

Time of Examination Start 3:00 AM/PM End 5:05 AM/PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	acc. tail	SENT MEN TO CLEAN DONE
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	None Observed	
#4	20.9	0	0	OK	None Observed	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	Acc in walkway at tail	WORKING ON DONE JB
Trans	20.9	0	0	OK	None Observed	
Kitchen	20.9	0	0	OK	None Observed	
CO monitors				Visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted Above ALL AREA SAFE
AT TIME OF EXAM

Pre-Shift/Mine Examiner SIGNATURE _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8395
 Certificate # 9362
 Certificate # _____
 Certificate # _____

2MSHA03882

Counter Signature SIGNATURE _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-10-07

SECTION/AREA Belts

Time of Examination Start 11:01 AM/PM

End 11:40 AM/PM

Examiners Initials CC

Time of Examination Start 11:00 AM/PM

End 108 AM/PM

Examiners Initials DD

Time of Examination Start 11:10 AM/PM

End 1:03 AM/PM

Examiners Initials LH

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.1	0	OK	ACC AT PORTAL BOX & ACC 50' out by drive	men cleaning Done
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	ACC of COAT X-91 in walk-way	WORKING ON IT BEING DUSTED
#5	20.9	0	0	ok	needs dust on off-side at drive-headroller	BEING DUSTED DONE
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Trans.	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	none observed	
CO sensors				Visual exam ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner Signature _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4822
 Certificate # 8058
 Certificate # 8703
 Certificate # _____

2MSHA03883

Counter Signature SIGNATURE _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-10-07

SECTION/AREA Belts

Time of Examination Start 7:04 AM/PM AM

End 9:28 AM/PM PM

Examiners Initials BH

Time of Examination Start 7:10 AM/PM AM

End 9:30 AM/PM PM

Examiners Initials SC

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out -- Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None Observed	
#2	20.9	0	0	OK	None Observed	
#3	20.9	0	0	OK	None Observed	
#4	20.9	0	0	OK	acc. tail	working on Done 8-11-07 BH
#5	20.9	0	0	OK	None Observed	
#6	20.9	0	0	OK	None Observed	
#7	20.9	0	0	OK	None Observed	
Frams.	20.9	0	0	OK	None Observed	
Belt Ketcher	20.9	0	0	OK	None Observed	
C.O. Monitors	visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS except as noted above all areas appeared reasonably safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 8385

Pre-Shift/Mine Examiner _____

Certificate # 9362

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA03884

SIGNATURE

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-11-07

SECTION/AREA Belts

Time of Examination Start 3:05 AM/PM

End 5:00 AM/PM

Examiners Initials TC

Time of Examination Start 3:02 AM/PM

End 5:10 AM/PM

Examiners Initials BM

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	none obs.	
#2	20.9	0	0		OK	none obs.	
#3	20.9	0	0		OK	none obs.	
#4	20.9	0	0		OK	Return side stopping 1's Damaged Xant 100	REPAIRED 8-11-07
#5	20.9	0	0		OK	none obs.	
#6	20.9	0	0		OK	none obs.	
#7	20.9	0	0		OK	none obs.	
Trans.	20.9	0	0		OK	none obs.	
Belt Kitchen	20.9	0	0		OK	none obs.	
<i>C.O. Monitor removed</i>							

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted above all areas appeared safe at time of exam

Pre-Shift/Mine Examiner: **SIGNATURE** _____
 Pre-Shift/Mine Examiner: **SIGNATURE** _____
 Pre-Shift/Mine Examiner: _____
 Pre-Shift/Mine Examiner: _____

2MSHA03885

Certificate # 9362
 Certificate # 8395
 Certificate # _____
 Certificate # _____

Counter Signature: **SIGNATURE** _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-11-07

SECTION/AREA Belts

Time of Examination Start 11 AM/PM

End 1150 AM/PM

Examiners Initials CG

Time of Examination Start 11:00 AM/PM

End 1:30 AM/PM

Examiners Initials LH

Time of Examination Start 1100 AM/PM

End 130 AM/PM

Examiners Initials DD

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None ob	
#2	21	0	0	OK	None obs	
#3	21	0	0	OK	None obs	
#4	21	0	0	OK	As x-cut 97-99 needs timber set in the wide area's	SENT MEN TO WORK ON
#5	21	0	0	OK	None obs	
#6	21	0	0	OK	None obs	DONE
#7	21	0	0	OK	None obs	Corylka/Burn
Trans	21	0	0	OK	None obs	
Kitchen	21	0	0	OK	None obs	
C.O. mon			visual	exam ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

All areas appeared to be safe at time of exam.

Cleaning & Rock dusting on going out #1 Belt, appeared safe at time of ex

Pre-Shift/Mine Examiner

SIGNATURE

Certificate # 4822

Pre-Shift/Mine Examiner

SIGNATURE

Certificate # 8703

Pre-Shift/Mine Examiner

SIGNATURE

Certificate # 8058

Pre-Shift/Mine Examiner

SIGNATURE

Certificate # _____

2MSHA03886

Counter Signature

SIGNATURE

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-11-07 SECTION/AREA Belts

Time of Examination Start 7:15 AM/PM AM End 9:08 AM/PM PM Examiners Initials BH

Time of Examination Start ~~7:15~~ 7:27 AM/PM AM End 9:23 AM/PM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	None Observed	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	None Observed	
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None Observed	
Belt Trans.	20.9	0	0	OK		
Belt Ketcher	20.9	0	0	OK	None observed	
C.O. Monitor				OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe AT TIME OF EXAM

SIGNATURE _____

Pre-Shift/Mine Examiner _____ Certificate # 8395

Pre-Shift/Mine Examiner _____ Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA03887

SIGNATURE _____

Counter Signature _____ Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-12-07

SECTION/AREA Belts

Time of Examination Start 3:08 AM PM End 5:15 AM PM Examiners Initials BH

Time of Examination Start 3:05 AM PM End 5:12 AM PM Examiners Initials K

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
1#	20.9	0	0	OK	Oil acc. at drive	SENT MAN TO CLEAN DONE
2#	20.9	0	0	OK	None Observed	
3#	20.9	0	0	OK	None Observed	
4#	20.9	0	0	OK	None Observed	
5#	20.9	0	0	OK	None observed	
6#	20.9	0	0	OK	None Observed	
7#	20.9	0	6	OK	None Observed	
Belt Kitcher	20.9	0	0	OK	None Observed	
Belt trans.	20.9	0	0	OK	None Observed	
C.O. Monitors visual exam				OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS except as noted above all areas appeared reasonably safe at time of exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 8395

Certificate # 9362

Certificate # _____

Certificate # _____

2MSHA03888

SIGNATURE _____

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-12-07

SECTION/AREA BELTS

Time of Examination Start 11:00 AM/PM AM

End 12:03 AM/PM PM

Examiners Initials CC

Time of Examination Start 11:07 AM/PM AM

End 1:45 AM/PM PM

Examiners Initials W

Time of Examination Start 11:05 AM/PM AM

End 1:25 AM/PM PM

Examiners Initials B.G.

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0%	0	OK	Acc #8 Box ✓ see below	men cleaning see Done
#2	20.9	0%	0	Correct	Accumulations under Belt at 19-22 X cut	Men Shoveling
#3	20.9	0%	off	Correct	Coal + Silt accumulations under belt From xc# 40-47 + 50-68	men working on
#4	20.9	0%	0	Correct	accumulations 72-73 84-Tail under belt	Men Shoveling
#5	20.9	0%	off	Correct	NONE	REPORTED AND CONTINUED ON TO NEXT SHIFT
#6	20.9	0%	off	Correct	NONE	
#7	20.9	0%	off	Correct	NONE	
Belt Kitchens	20.9	0%	off	Correct	NONE	
Belt Transformers	20.9	0%	off	Correct	NONE	
Conspec OK						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#2 Belt	Rock Dust + Belt Rollers Blocking Walkway at xc#16	moved out of way
#7 Belt	Stopping Leaking at xc#111	Foamed
#4 Belt	Coal + Silt accumulations from xc#26 to Tail Roller	Shoveled
#8 Belt	2 bottom rollers on ground on one side	Fixed one roller and removed other one

PRE-SHIFT REMARKS

Cleaning & Rock dusting ongoing on #1 Belt, Appered safe at time of EX

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4822
 Certificate # 8228
 Certificate # 9212
 Certificate # _____

2MSHA03889

Counter Signature **SIGNATURE** _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-12-07

SECTION/AREA Belt

Time of Examination Start 7:00 AM/PM PM End 9:15 AM/PM PM Examiners Initials JW

Time of Examination Start 7:10 AM/PM PM End 9:27 AM/PM PM Examiners Initials TL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
1#	20.8	0%	0	correct	None	
2#	20.9	0	0	OK	OC 14 need 2 timber set Rec overcast XC 35	sent men to work on Done 8-13-07 TL
3#	20.9	0	0	OK	None obs.	
4#	20.9	0	0	OK	None obs.	
5#	20.8	0%	0	correct	SCM Per M/L 403	sent men to work on Done 8-13-07 TL
6#	20.8	0%	0	correct	None obs	
7#	20.8	0%	0	correct	None obs	
Trans. Belts	20.8	0%	0	OK	None obs	
Kitchen Belts	20.8	0%	0	OK	None obs	
C. O. Monitors	Visual Exam OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
xc 27 1/2	Fire Valve need installed	install valve

PRE-SHIFT REMARKS other than noted above All Areas

Seemed safe at time of Exam

Pre-Shift/Mine Exam **Signature** _____

Certificate # 9690

Pre-Shift/Mine Exam _____

Certificate # 9302

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

2MSHA03890

Certificate # _____

Counter Signature **SIGNATURE** _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-13-07 SECTION/AREA Belts

Time of Examination Start 3:00 (AM/PM) End 5:25 (AM/PM) Examiners Initials TC

Time of Examination Start 3:00 (AM/PM) End 5:14 (AM/PM) Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
1#	20.9	0	0	OK	none obs.	
2#	20.9	0	0	OK	needs dusted XC36-TAIL	BEING DUSTED DONE
3#	20.9	0	0	OK	none obs.	
4#	20.9	0	0	OK	none obs.	
5#	20.9	0	0	OK	none obs.	
6#	20.9	0	0	OK	none obs.	
7#	20.9	0	0	OK	none obs.	
Belt Kitchen	20.9	0	0	OK	none obs.	
Belt Tunnels	20.9	0	0	OK	none obs.	
C.O. Monitors	normal					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Area appeared Reasonably safe at
Time of Exam Except noted Above

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____ 2MSHA03891

Certificate # 9362
 Certificate # 9690
 Certificate # _____
 Certificate # _____

Counter Signature **Signature** _____

Certificate # 7488

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-13-07

SECTION/AREA BELTS

Time of Examination Start 11:38 AM PM End 1245 AM PM Examiners Initials CC
 Time of Examination Start 1130 AM PM End 122 AM PM Examiners Initials TSS
 Time of Examination Start _____ AM PM End _____ AM PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0%	0	Correct	23-24' cut accumulations in walk way	walking on Done
#2	20.9	0%	0	OK	ACC X 14-215 X31-X33 needs Rock dust	work in on Done
#3	20.9	0%	0	Correct	48-53' cut accumulations under belt	Men Shoveling DONE
#4	20.9	0%	0	OK	ACC X 92 Roller Piles X 78-X 80	sent men to work on Done
#5	20.9	0	0	Correct	NONE observed	
#6	20.9	0	0	Correct	NONE observed	
#7	20.9	0	0	Correct	NONE observed	
Belt Kitchen	20.9	0%	0	OK	NONE observed	
Belt Transformers	20.9	0%	0	OK	NONE observed	
CO Monitors						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS _____

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7822
 Certificate # 9212
 Certificate # _____
 Certificate # _____

2MSHA03892

Counter Signature **SIGNATURE** _____

Certificate # 7488

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-13-07 SECTION/AREA Belts

Time of Examination Start 7:10 AM/PM AM End 9:50 AM/PM PM Examiners Initials LR/JN

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

Called Out By _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>1#</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>OK</u>	<u>None observed</u>	
<u>2#</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>OK</u>	<u>None observed</u>	
<u>3#</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>OK</u>	<u>None observed</u>	
<u>4#</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>OK</u>	<u>Need dust 95 to TAIL</u>	<u>Working on belt 8-13-07</u>
<u>5#</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>OK</u>	<u>None observed</u>	
<u>6#</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>OK</u>	<u>None observed</u>	
<u>7#</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>OK</u>	<u>None observed</u>	
<u>Belt Kitchen</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>OK</u>	<u>None observed</u>	
<u>Belt Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>OK</u>	<u>None observed</u>	
<u>C.O. Monitor</u>	<u>normal</u>					

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of exam except as noted above

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 4375

Pre-Shift/Mine Examiner _____ Certificate # 9690

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA03893

Counter Signature **SIGNATURE** _____ Certificate # 8308

PRE-SHIFT BELTS

DATE OF EXAMINATION 8-14-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:30 AM/PM Examiners Initials RTN

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
1#	21.0	0	0	OK	ACCEL ACC. #8 Need dusted ACC. AT TAIL	SENT MAN TO CLEAN DANE
2#	21.0	0	0	OK	None observed	
3#	21.0	0	0	OK	None observed	
4#	21.0	0	0	OK	None observed	
5#	21.0	0	0	OK	None observed	
6#	21.0	0	0	OK	None observed	
7#	21.0	0	0	OK	None observed	
Belt Traps	21.0	0	0	OK	None observed	
Belt Kitcher	21.0	0	0	OK	None observed	
C.O. Monitors	normal					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Exam except as noted above

SIGNATURE

 Pre-Shift/Mine Examiner

 Pre-Shift/Mine Examiner

 Pre-Shift/Mine Examiner

 Pre-Shift/Mine Examiner

Certificate # 4375
 Certificate # 9690
 Certificate # _____
 Certificate # _____

2MSHA03894

SIGNATURE

 Counter Signature

Certificate # 7485

2MSHA03895