

**PRE-SHIFT
BELTS**

2MSHA04304

PRE-SHIFT BELTS

DATE OF EXAMINATION 12.19.06

SECTION/AREA Belts
 Examiners Initials KK/DR

Time of Examination Start 300 AM/PM End 550 AM/PM

Time of Examination Start _____ AM/PM End _____ AM/PM

Time of Examination Start _____ AM/PM End _____ AM/PM

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	accum. of fuel by cut off	5000 man to work on cleaned 12-19-06
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	none obs.	
Belt Kitcher	20.9	0	0	OK	none obs.	
Trans.	20.9	0	0	OK	none obs.	
L.O. Monitor						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at pre-shift

SIGNATURE
 Pre-Shift/Mine Examiner _____

Certificate # 7954

Pre-Shift/Mine Examiner _____

Certificate # 4375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA04305

Certificate # _____

SIGNATURE
 Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-19-06

SECTION/AREA Belts

Time of Examination Start 1100 AM PM End 130 AM PM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	none obs.	
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	none obs.	
#4	21	0	0	ok	none obs.	
#5	21	0	0	ok	none obs.	
#6	21	0	0	ok	COAL Acc. @ Headroller	working on Cleared 12-19-06
#7	21	0	0	ok	COAL Acc. Headroller	working on Cleared 12-19-06
TRANS.	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
CO monitors						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 7375
 Certificate # _____
 Certificate # _____

2MSHA04306

Counter Signature **SIGNATURE** _____

Certificate # 9735

PRE-SHIFT BELTS

DATE OF EXAMINATION 12 19 86

SECTION/AREA Belts

Time of Examination Start 7.00 AM/PM AM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<i>all Belts Fd/E.</i>						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS _____

SIGNATURE

Pre-Shift/Mine Examiner _____ Certificate # _____
 Pre-Shift/Mine Examiner _____ Certificate # _____
 Pre-Shift/Mine Examiner _____ Certificate # _____
 Pre-Shift/Mine Examiner _____ 2MSHA04307 Certificate # _____

Counter Signature SIGNATURE _____ Certificate # 4135

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-20-06

SECTION/AREA Belts

Time of Examination Start 300 AM PM End 535 AM PM Examiners Initials DLK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Acc Oil at drive	Sent men to work on done
#2	20.9	0	0	OK	None	
#5	20.9	0	0	OK	None	
#4	20.9	0	0	OK	Deep Water # 73	Sent men to work on done
#5	20.9	0	0	OK	Coal Acc 104 to drive	Sent men to work on done
#6	20.9	0	0	OK	None	
#7	20.9	0	0	OK	None	
Trans.	20.9	0	0	OK	None	
Kitchen	20.9	0	0	OK	None	
C.O. Sensors would EXAMINER OK						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner **SIGNATURE** _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 4375

Certificate # 7954

Certificate # _____

Certificate # _____

Counter Signature **SIGNATURE** _____

2MSHA04308

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-20-06

SECTION/AREA Belts

Time of Examination Start 1100 AM/PM End 1250 AM/PM Examiners Initials FD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	None obs	
#2	21	0	0	OK	None obs.	
#3	21	0	0	OK	None obs.	
#4	21	0	0	OK	None obs.	
#5	21	0	0	OK	None obs	
#6	21	0	0	OK	None obs.	
#7	21	0	0	OK	None obs.	
Transformers	21	0	0	OK	None obs.	
Kitchens	21	0	0	OK	None obs.	
C.D. SENSORS	VISUAL EXAM OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe at the time of exam.

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9458
 Certificate # 7375
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____

Certificate # 4735

2MSHA04309

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-30-06

SECTION/AREA Belts

Time of Examination Start 700 AM/PM (M) End 1000 AM/PM (M) Examiners Initials PK/LR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs	
#2	20.9	0	0	OK	accing at #2 head roller	sent in to check done 12-20-06 LR
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs	
#5	20.9	0	0	OK	None obs	
#6	20.9	0	0	OK	None obs	
#7	20.9	0	0	OK	sub-stalling between x-cut 18.43/35	sent in to check done 12-30-06 LR
Belt Kitchens	20.9	0	0	OK	None obs.	
Trams	20.9	0	0	OK	None obs.	
C.O. Monitors, record				OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM except as noted above

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7959
 Certificate # 4325
 Certificate # _____
 Certificate # _____

2MSHA04310

SIGNATURE
 Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-21-06

SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 540 AM/PM Examiners Initials PR/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None obs	
#2	20.9	0	0		OK	Deep Water between 3#4	working on pumped 12-21-06
#3	20.9	0	0		OK	None obs.	
#4	20.9	0	0		OK	None obs.	
#5	20.9	0	0		OK	None obs.	
#6	20.9	0	0		OK	None obs	
#7	20.9	0	0		OK	None obs	
V. Johnson	20.9	0	0		OK	None obs.	
Towns.	20.9	0	0		OK	None obs	
CO Monitors	U	S	U	Exam	OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#7 Handover	Coal Acc.	cleaned 12-21-06 ZR
#5 drive	Coal Acc.	cleaned 12-21-06 ZR

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 4375

Certificate # 7954

Certificate # _____

Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA04311

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-21-06

SECTION/AREA Belts

Time of Examination Start 1100 AM PM End 130 AM PM Examiners Initials DD/FD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	none obs.	
#2	21	0	0	ok	needs dust headroller to Box 4	working on Dusted 12-21-06
#3	21	0	0	ok	none obs	
#4	21	0	0	ok	none obs.	
#5	21	0	0	ok	none obs	
#6	21	0	0	ok	none obs	
#7	21	0	0	ok	coal acc. at headroller	working on cleaned 12-21-06
TRANS.	21	0	0	ok	none obs	
Kitchen	21	0	0	ok	none obs.	
CD monitors				Visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe At time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 9458
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____

2MSHA04312

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-21-06

SECTION/AREA D. 2nd

Time of Examination Start 7:00 AM/PM (PM) End 9:45 AM/PM (PM) Examiners Initials KK/LR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None	
#2	20.9	0	0	OK	None	
#3	20.9	0	0	OK	None	
#4	20.9	0	0	OK	None	
#5	20.9	0	0	OK	None	
#6	20.9	0	0	OK	None	
#7	20.9	0	0	OK	None	
Belt Kitchen	20.9	0	0	OK	None	
Trans.	20.9	0	0	OK	None	
C.O. Monitor	Sound			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of Exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Certificate # 7954

Pre-Shift/Mine Examiner _____

Certificate # 4375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE _____

2MSHA04313

Counter Signature

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-22-06

SECTION/AREA Belt

Time of Examination Start 300 (A) AM/PM End _____ AM/PM Examiners Initials SLP
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	A	0	OK	None obs	
#2	20.9	A	0	OK	Coal Roc at tail piece	working on it Done 12-22-06 SL
#3	20.9	A	0	OK	None obs.	
#4	20.9	A	0	OK	None obs.	
#5	20.9	A	0	OK	None obs	
#6	20.9	A	0	OK	None obs	
#7	20.9	A	0	OK	None obs	
Trams	20.9	A	0	OK	None obs	
C.O. monitors room						
Kitchen	20.9	A	0	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of pre-shift except as noted above

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 7954

Certificate # 4825

Certificate # _____

Certificate # _____

SIGNATURE _____

Counter Signature _____

2MSHA04314

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-22-06 SECTION/AREA Belts

Time of Examination Start 12:00 AM/PM AM End 1:10 AM/PM PM Examiners Initials BH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	NONE Observed	
#2	20.9	0	0	OK	NONE Observed	
#3						
#4						
#5						
#6						
#7						
Transformers						
Kitchen						
CO monitors						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

SIGNATURE

Pre-Shift/Mine Examiner _____ Certificate # 8395

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04315

Counter Signature _____ Certificate # _____

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-22-06

SECTION/AREA Belts

Time of Examination Start 11:00 AM PM

End 1:40 AM PM

Examiners Initials BA

Time of Examination Start 12:00 AM PM

End 1:10 AM PM

Examiners Initials BH

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	OK	none observed	
#2	20.9	0.0	0.0	OK	none observed	
#3	20.9	0.0	0.0	OK	none observed	
#4	20.9	0.0	0.0	OK	none observed	
#5	20.9	0.0	0.0	OK	none observed	
#6	20.9	0.0	0.0	OK	none observed	
#7	20.9	0.0	0.0	OK	none observed	
Kitchen	20.9	0.0	0.0	OK	none observed	
Transformers	20.9	0.0	0.0	OK	none observed	
CO sensors				LISAU Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

All areas appeared safe at time of Exam.

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9399

Pre-Shift/Mine Examiner _____

Certificate # 8395

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04316

SIGNATURE

Counter Signature _____

Certificate # 03992

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-22-06

SECTION/AREA B/Hs.

Time of Examination Start 7:00 AM/PM PM

End 9:30 AM/PM PM

Examiners Initials SW

Time of Examination Start 7:00 AM/PM PM

End 9:17 AM/PM PM

Examiners Initials TC

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	30%	0	0	OK	none observed	
#2	30%	0	0	OK	none observed	
#3	30%	0	0	OK	none observed	
#4	30%	0	0	OK	none observed	
#5	30%	0	0	OK	none observed	
#6	30%	0	0	OK	none observed	
#7	30%	0	0	OK	none observed	
kitchen	30%	0	0	OK	none observed	
transformers	30%	0	0	OK	none observed	
CO Monitors	(used exam)			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Pre-shift.

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9548

Pre-Shift/Mine Examiner _____

Certificate # 9362

Pre-Shift/Mine Examiner _____

2MSHA04317

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-23-06

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:35 AM/PM Examiners Initials JW

Time of Examination Start 3:00 AM/PM End 5:05 AM/PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1 Belt	20.5	0	0	OK	dust portal to extent 9	Working on CT Done 122306
#2	20.5	0	0	OK	none observed	
#3	20.5	0	0	OK	none observed	
#4	20.5	0	0	OK	none observed	
#5	20.5	0	0	OK	none observed	
#6	20.5	0	0	OK	acc. at head roller	Working on CT Done 122306
#7	20.5	0	0	OK	acc. head roller to drive	Working on CT Done 122306
Kitchen	20.5	0	0	OK	none observed	Working on CT
Transformers	20.5	0	0	OK	none observed	
CO Monitors	(visual exam)			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of exam except above notes.

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9548
 Certificate # 9362
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____

2MSHA04318

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-23-06 SECTION/AREA BELTS

Time of Examination Start 10:00 AM/PM AM End 12:46 AM/PM PM Examiners Initials BP

Time of Examination Start 12:45 AM/PM AM End 1:45 AM/PM PM Examiners Initials BU

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None Observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
CO sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe
at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____ 2MSHA04319

Certificate # 9599
 Certificate # 8395
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-23-06

SECTION/AREA Belts

Time of Examination Start 7:05 AM/PM AM End 9:20 AM/PM PM Examiners Initials SW

Time of Examination Start 7:00 AM/PM AM End 9:00 AM/PM PM Examiners Initials TL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	28	0	0	OK	none observed	
#2	28	0	0	OK	none observed	
#3	28	0	0	OK	none observed	
#4	28	0	0	OK	none observed	
#5	28	0	0	OK	none observed	
#6	28	0	0	OK	none observed	
#7	28	0	0	OK	none observed	
Kitchen	28	0	0	OK	none observed	
Transformers	28	0	0	OK	none observed	
CO monitors	(Visual Exam)			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Pre-shift

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9548
 Certificate # 9362
 Certificate # _____
 Certificate # _____

2MSHA04320

Counter Signature **SIGNATURE** _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-26-06

SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 455 AM/PM Examiners Initials FD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	Acc. at the tail	Working on it
#2	21	0	0	OK	Needs dust from x-cut	Working on it 2-to drive Dusted 12-26-06
#3	21	0	0	OK	None obs.	
#4	21	0	0	OK	None obs.	
#5	21	0	0	OK	None obs.	
#6	21	0	0	OK	None obs.	
#7	21	0	0	OK	None obs.	
Transformers	21	0	0	OK	None obs.	
C.O Sensors	Visual exam			OK		
Kitchen	21	0	0	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe, except what's noted above.

SIGNATURE
 Pre-Shift/Mine Examiner _____

Certificate # 9458

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04321

SIGNATURE
 Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-26-06

SECTION/AREA Belts

Time of Examination Start 1100 ~~AM~~/PM End 130 AM/~~PM~~ Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	Acc. @ Tail	working on it Done 12-26-06
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	none obs.	
#4	21	0	0	ok	need dust from x-cut go to tail piece	Assigned man to Dust
#5	21	0	0	ok	none obs.	
#6	21	0	0	ok	Acc. COAL @ Headroller	working on cleaned 12-26-06
#7	21	0	0	ok	Acc. COAL @ Headroller	working on cleaned 12-26-06
Kitchen	21	0	0	ok	none obs.	
Trans.	21	0	0	ok	none obs.	
CO monitors				Visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

2MSHA04322

Certificate # 8058

Certificate # 7375

Certificate # _____

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 478

PRE-SHIFT BELTS

DATE OF EXAMINATION 12.26.06 SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 935 AM/PM PM Examiners Initials RR/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None	
#2	20.9	0	0	OK	None	
#3	20.9	0	0	OK	None	
#4	20.9	0	0	OK	Need dust from cut go to Tailpiece	Assignment to Dust dusted 12.27.06 RR
#5	20.9	0	0	OK	None	
#6	20.9	0	0	OK	None	
#7	20.9	0	0	OK	None	
Kitchen	20.9	0	0	OK	None	
TUNNS	20.9	0	0	OK	None	
COMMITTEES	V: Suppl Exam			OK		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area approved Safe at time of Exam except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4325
 Certificate # 6401
 Certificate # _____
 Certificate # _____

SIGNATURE

2MSHA04323

Counter Signature _____

Certificate # 4935

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-27-06

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:40 AM/PM Examiners Initials RR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Acc. Mud & Ice at Portal	working on
#2	20.9	0	0	OK	None	
#3	20.9	0	0	OK	None	
#4	20.9	0	0	OK	None	
#5	20.9	0	0	OK	None	
#6	20.9	0	0	OK	None	
#17	20.9	0	10	OK	123 to 124 Rib Roll	working on
Kitchen	20.9			OK	None	
TUNNS	20.9			OK	None	
COMputer	V'sust Exam OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 Drive	Acc. coal	Washed 12-27-06 RR
#17 Headroll	Acc. Coal	Washed 12-27-06 RR

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 4375

Certificate # 6981

Certificate # _____

Certificate # _____

2MSHA04324

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-27-06

SECTION/AREA Belts

Time of Examination Start 1130 AM/PM End 140 AM/PM Examiners Initials SP-DJ

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	21	0	0	OK	Acc. at the tail & this is done 12-27-06 Acc. of mud and Ice at the partal working and awe	
# 2	21	0	0	OK	None obs.	
# 3	21	0	0	OK	None obs.	
# 4	21	0	0	OK	None obs.	
# 5	21	0	0	OK	None obs.	
# 6	21	0	0	OK	None obs.	
# 7	21	0	0	OK	123- to 124 Rib Roll	stowed 3' walkway 12-27-06 MC
Transformers	21	0	0	OK	None obs.	
Kitchen	21	0	0	OK	None obs.	
CO sensors				Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe, except what's above.

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9458
 Certificate # 8058
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____
 2MSHA04325

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-27-06

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 945 AM/PM PM Examiners Initials R/SR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0		Q	none observed	
#2	21	0	0		Q	none observed	
#3	21	0	0		Q	none "	
#4	21	0	0		Q	none "	
#5	21	0	0		Q	none "	
#6	21	0	0		Q	none "	
#7	21	0	0		Q	none observed	
Kitchens	21	0	0		Q	none	
Transformers	21	0	0		Q	none	
CO Sensors	visual exam				Q		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6401
 Certificate # 4375
 Certificate # _____
 Certificate # _____

SIGNATURE

2MSHA04326

Counter Signature _____

Certificate # 4135

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-28-06

SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 540 AM/PM Examiners Initials RR/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None	
#2	20.9	0	0	OK	None	
#3	20.9	0	0	OK	None	
#4	20.9	0	0	OK	None	
#5	20.9	0	0	OK	None	
#6	20.9	0	0	OK	None	
#7	20.9	0	0	OK	None	
Kitchen	20.9	0	0	OK	None	
Transter	20.9	0	0	OK	None	
CO Sensor	Visual Exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 Drive	Coal Acc.	Cleaned TX
#6 Handler	Coal Acc.	Cleaned TX
#7 Handler	Coal Acc.	Cleaned TX

PRE-SHIFT REMARKS Area appeared safe at time of Exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 4325

Certificate # 6401

Certificate # _____

Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA04327

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-28-06

SECTION/AREA Belts

Time of Examination Start 1100 AM PM End 200 AM PM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		ok	none obs.	
#2	20.9	0	0		ok	none obs.	
#3	20.9	0	0		ok	none obs.	
#4	20.9	0	0		ok	none obs.	
#5	20.9	0	0		ok	none obs.	
#6	20.9	0	0		ok	none obs.	
#7	20.9	0	0		ok	none obs.	
Kitchen	20.9	0	0		ok	none obs.	
Trans.	20.9	0	0		ok	none obs.	
CO Sensors		Visual			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 7375
 Certificate # _____
 Certificate # _____

2MSHA04328

SIGNATURE

Counter Signature _____

Certificate # DA62

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-28-06

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 940 AM/PM PM Examiners Initials RR/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None	
#2	20.9	0	0		OK	None	
#3	20.9	0	0		OK	Acc At Tailpiece	Worked 12-28-06 RR
#4	20.9	0	0		OK	None	
#5	20.9	0	0		OK	Acc. At Tailpiece	Worked 12-28-06 RR
#6	20.9	0	0		OK	None	
#7	20.9	0	5		OK	None	
Kitchen	20.9	0	0		OK	None	
TUNNS	20.9	0	0		OK	None	
CO SENSORS	VISUAL EXAM				OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above.

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4375
 Certificate # 6401
 Certificate # _____
 Certificate # _____

SIGNATURE

2MSHA04329

Counter Signature _____

Certificate # 4785

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-29-06 SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 535 AM/PM Examiners Initials LR/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	oil Acc At drive. ACC. At Tailpiece and #8 xc	working on 29 cleaned 12-29
2	20.9	0	0	OK	None	
3	20.9	0	0	OK	None	
4	20.9	0	0	OK	None	
5	20.9	0	0	OK	None	
6	20.9	0	0	OK	None	
7	20.9	0	0	OK	None	
Kitchen	20.9	0	0	OK	None	
TRAPS	20.9	0	0	OK	None	
CO Monitors	Visual Exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Dress approval Scribe at time of Exam except as
Noted above

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 4325

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 6401

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature **SIGNATURE** Certificate # 9279

2MSHA04330

PRE-SHIFT BELTS

DATE OF EXAMINATION 12/29/06

SECTION/AREA belts

Time of Examination Start 11:24 AM/PM

End 11:55 AM/PM

Examiners Initials LH

Time of Examination Start 11:35 AM/PM

End 1:40 AM/PM

Examiners Initials BH

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Roller piles x-cut 12 ¹ / ₂ 10' below ^(see 3rd north dump point)	Done 12-29-06 BH working on it
#2	20.9	0	0	OK	acc. overcast need dust box and 65 to tail	Done 12-29-06 BH working on it
#3	20.9	0	0	OK	need dust head roller x-cut 42	working on it
#4	20.9	0	0	OK	need rock dust head roller to brake	Done 12-29-06 BH working on it
#5	20.9	0	0	OK	needs DUST AT Tail.	working on it 12:30:06
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	None Observed	
TRANSFORMERS	20.9	0	0	OK	None Observed	
C.O. sensors	20.9	0	0	OK	Visual exam OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS #1 belt needs several rollers replaced and trained where belt into structure, bad rollers on 1, 2, 3, 4 belt need changed out all belts need trained

Pre-Shift/Mine Examiner SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8703
 Certificate # 8395
 Certificate # _____
 Certificate # _____

2MSHA04331

Counter Signature SIGNATURE

Certificate # 9279

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-29-06 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM End 9:12 AM/PM Examiners Initials JC

Time of Examination Start 7:10 AM/PM End 9:05 AM/PM Examiners Initials JW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20.9	0	0	OK	Needs Dusted	BEING DUSTED 1-16 X-CUTS DONE
# 2	20.9	0	0	OK	NONE OBS.	
# 3	20.9	0	0	OK	Needs Dusted From H.R.-XC 42 And 65-Tail	BEING DUSTED Done 12-30-06
# 4	20.9	0	0	OK	NONE OBS. - see below	
# 5	20.9	0	0	OK	Acc 109-110	Working on ^{room 2-10} 12-30-06
# 6	20.9	0	0	OK	NONE OBS.	
# 7	20.9	0	0	OK	Roller Piles TAKE-UP TO TAIL & HEAD ROLL HAS ACC	WORKING ON 12-30-06 TAKE-UP AND DRIVE CLEARED
Kitchen	20.9	0	0	OK	NONE OBS.	
Transformers	20.9	0	0	OK	NONE OBS.	
Chinowets				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted Above All Areas
Seemed Reasonably safe AT Time of Exam Need Rollers
Changed 1-2-3-4 And All Belts need Trained - WORKING ON

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9362

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9548

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04332

Counter Signature **SIGNATURE** _____ Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-30-06 SECTION/AREA Belts.

Time of Examination Start 3:00 AM/PM End 5:05 AM/PM Examiners Initials TK

Time of Examination Start 3:15 AM/PM End 5:30 AM/PM Examiners Initials SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Needs Dusted	working on it ^{Done}
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	roller piles	working on it ^{Done}
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	Roller Piles Takeup to Tail Piece	working on it ^{Done}
Kitchen	20.9	0	0	OK	none obs.	
TRANSFORMERS	20.9	0	0	OK	none obs.	
Commanders	VISUAL EXAM					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Need Rollers Changed on 1-2-3-4 Belts & All Belts need to Be Trained - Other Than Noted Above All AREAS beened Reasonably safe AT Time of EXAM working on

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9362

Pre-Shift/Mine Examiner _____

Certificate # 9548

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA04333

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 9299

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-30-06

SECTION/AREA Belts

Time of Examination Start 1122 AM PM End 114 AM PM Examiners Initials BP

Time of Examination Start 1120 AM PM End 1150 AM PM Examiners Initials LJZ

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs Needs Dusted	working on it ^{done}
#2	20.9	0	0	OK	none obs	
#3	20.9	0	0	OK	none obs	
#4	20.9	0	0	OK	none obs	
#5	20.9	0	0	OK	Boller Piles Head raised	working on it ^{done}
#6	20.9	0	0	OK	none obs	
#7	20.9	0	0	OK	Acc 114 to 127.	working on it ^{done} 12:30
Kitchen	20.9	0	0	OK	none obs	
Transformers	20.9	0	0	OK	none obs	
CO Sensors	Visual Exam					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared sat at time of Exam except those above

SIGNATURE _____

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9599
 Certificate # 8703
 Certificate # _____
 Certificate # _____

2MSHA04334

Counter Signature **SIGNATURE** _____

Certificate # 9279

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-30-06

SECTION/AREA Belts

Time of Examination Start 7:10 AM/PM End 9:00 AM/PM Examiners Initials LD

Time of Examination Start 7:05 AM/PM End 8:55 AM/PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	Needs dusted	working on it ^{Done} 12-31
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	Roller piles 10 5 -109	working on it DONE 123006
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	none observed	
Transformers	20.9	0	0	ok	none observed	
CO sensors	visual	exam		ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas Appear Safe at time of exam except as noted above

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 9660

Certificate # 9367

Certificate # _____

Certificate # _____

SIGNATURE _____

2MSHA04335

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-31-06 SECTION/AREA Belts

Time of Examination Start 3:00 AM PM End 5:05 AM PM Examiners Initials TC

Time of Examination Start 3:10 AM PM End 4:55 AM PM Examiners Initials LD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Acco Soil AT Drive	working on it done 12-31-06
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	ACC under Drive	working on it done 12-31-06
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	NEEDS Dusted	working on it done 12-31-06
Kitchen	20.9	0	0	OK	None obs.	
Transformer	20.9	0	0	OK	None obs.	
Chimney				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas other than noted Above
were Reasonably safe AT Time of EXA

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 9362

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 9660

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04336

Counter Signature **SIGNATURE** Certificate # 9279

PRE-SHIFT BELTS

DATE OF EXAMINATION 12/31/06 SECTION/AREA belts

Time of Examination Start 11:05 AM/PM End 12:30 AM/PM Examiners Initials LH

Time of Examination Start ~~11:05~~ 12/16 AM/PM End 1246 AM/PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	Ice in the Portal	working on it. Done 12/31/06
#2	21	0	0	OK	none observed	
#3	21	0	0	OK	none observed	
#4	21	0	0	OK	none observed	
#5	21	0	0	OK	none observed	
#6	21	0	0	OK	none observed	
#7	21	0	0	OK	needs dusted Head to tail	Done. LH, BP.
Kitchen	21	0	0	OK	none observed	
Trans	21	0	0	OK	none observed	
C.O. monitors				visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & travel at
Time of exam.

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8703
 Certificate # 9599
 Certificate # _____
 Certificate # _____

2MSHA04337

SIGNATURE

Counter Signature _____

Certificate # 9279

PRE-SHIFT BELTS

DATE OF EXAMINATION 12-31-06

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM (M)

End 8:35 AM/PM (M)

Examiners Initials LJ

Time of Examination Start 7 AM/PM (M)

End 8:40 AM/PM (M)

Examiners Initials dy

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
CO monitors v:sha/exam				ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all Areas appeared safe at time of exam.

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 6622

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

2MSHA04338

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-1-07

SECTION/AREA Belts

Time of Examination Start 3:10 AM/PM

End 5:05 AM/PM

Examiners Initials LD

Time of Examination Start 3 AM/PM

End 5:10 AM/PM

Examiners Initials dy

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
CO monitors	visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

SIGNATURE [Redacted]

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 6622

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE [Redacted]

2MSHA04339

Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-1-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:15 AM/PM Examiners Initials ER/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	OK	None	
#2	20.9	0	0	OK	OK	None	
#3	20.9	0	0	OK	OK	None	
#4	20.9	0	0	OK	OK	None	
#5	20.9	0	0	OK	OK	None	
#6	20.9	0	0	OK	OK	None	
#7	20.9	0	0	OK	OK	None	
Best Kitchens	20.9	0	0	OK	OK	None	
Trams	20.9	0	0	OK	OK	None	
C.O. Monitors	20.9	0	0	OK	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 4325

Certificate # 6401

Certificate # _____

Certificate # _____

Counter Signature **SIGNATURE** _____

2MSHA04340

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-1-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 855 AM/PM PM Examiners Initials SD/BD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	cool acc. at the tail	working on Done 1-1-07
#2	21	0	0	OK	Cool acc at the tail	working on Done 1-1-07
#3	21	0	0	OK	None obs.	
#4	21	0	0	OK	None obs.	
#5	21	0	0	OK	None obs.	
#6	21	0	0	OK	None obs.	
#7	21	0	0	OK	Needs dust 150' out ^{tail}	working on Done 1-1-07
Transformers	21	0	0	OK	None obs.	
Kitchen	21	0	0	OK	None obs.	
CO Sensors	Visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe, except what's above

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 2458

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

Counter Signature

2MSHA04341

Certificate # 7462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-2-07

SECTION/AREA BELTS

Time of Examination Start 3:00 AMPM End 5:05 AMPM Examiners Initials MC/KO

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Accum xcut #8	Cleaned 1-2-07 DR
#2	20.9	0	0	OK	need dust Header to xcut	dusted 1-2-07 DR
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed see below	Work may be done 1-2-07
#5	20.9	0	0	OK	Accum out under drive	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS (need stopping built on top of main ^{south} overcast
at xcut 90) Done PL other Areas Appeared Reasonably safe

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7575
 Certificate # 9458
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____

2MSHA04342

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1.207 SECTION/AREA Belts

Time of Examination Start 11:00 ~~AM~~/PM End 2:00 AM/~~PM~~ Examiners Initials LR/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None	
#2	20.9	0	0	OK	None	
#3	20.9	0	0	OK	None	
#4	20.9	0	0	OK	OIL Acc at drive Need Stopping on Overcast 90M	Cleaned drive 1-2-07 LR Working on 1-3-07 KK
#5	20.9	0	0	OK	Acc. at drive Acc. 10.9 to 110	Working on done 1-2-07 LR
#6	20.9	0	0	OK	None	
#7	20.9	0	5	OK	None	
Kitchen	20.9	0	0	OK	Trash #17	Working on done 1-2-07 LR
TRANS.	20.9	0	0	OK	None	
CO Monitors	Visual Exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner **SIGNATURE** _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 4375

Certificate # 1954

Certificate # _____

Certificate # _____

Counter Signature **SIGNATURE** _____

2MSHA04343

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-2-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM End 930 AM/PM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	none obs.	
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	none obs.	
#4	21	0	0	ok	none obs.	
#5	21	0	0	ok	none obs.	
#6	21	0	0	ok	none obs.	
#7	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
Trans.	21	0	0	ok	none obs.	
CO monitors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 7375
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____

2MSHA04344

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-3-07

SECTION/AREA Belts

Time of Examination Start 300 ~~AM~~/PM End 530 ~~AM~~/PM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	oil Acc. @ Drive	sent people to clean Done DG
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	none obs.	
#4	21	0	0	ok	none obs.	
#5	21	0	0	ok	COAL fines Around Drive rollers	Assigned people to clean Cleared 1-3-07 RR
#6	21	0	0	ok	none obs.	
#7	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
TRANS.	21	0	0	ok	none obs.	
CO monitors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

2MSHA04345

Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-3-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:24 AM/PM Examiners Initials RS/R2

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed.	
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	acc head roller	changed op. R
Kitchen	20.9	0	0	OK	None obs.	
Turns	20.9	0	0	OK	None obs.	
CO Monitors	NORMAL EXAM					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM

Pre-Shift/Mine Examiner **SIGNATURE**
 Pre-Shift/Mine Examiner **SIGNATURE**
 Pre-Shift/Mine Examiner **SIGNATURE**
 Pre-Shift/Mine Examiner _____

Certificate # 7954
 Certificate # 6401
 Certificate # _____
 Certificate # _____

2MSHA04346

Counter Signature **SIGNATURE**

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-3-07

SECTION/AREA Belts

Time of Examination Start 700 AM/~~PM~~ End 930 AM/~~PM~~ Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	none obs.	
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	contl acc. @ Tail	working on
#4	21	0	0	ok	none obs.	
#5	21	0	0	ok	none obs.	
#6	21	0	0	ok	none obs.	
#7	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
TRANS	21	0	0	ok	none obs.	
CD monitors		Visual		ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 8058

Certificate # 7375

Certificate # _____

Certificate # _____

2MSHA04347

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-4-07

SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 458 AM/PM Examiners Initials JRM

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	None obs.	
#2	21	0	0	OK	None obs.	
#3	21	0	0	OK	None obs.	
#4	21	0	0	OK	None obs.	
#5	21	0	0	OK	None obs.	
#6	21	0	0	OK	None obs.	
#7	21	0	0	OK	None obs.	
Transformers	21	0	0	OK	None obs.	
Kitchen	21	0	0	OK	None obs.	
CO Sensors				Visual exam	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared to be safe at the time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9458
 Certificate # 7375
 Certificate # _____
 Certificate # _____

2MSHA04348

Counter Signature **SIGNATURE** _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-4-07 SECTION/AREA Belts

Time of Examination Start 11:00 AM PM End 12:30 AM PM Examiners Initials LR/FM

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	None observed	
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None observed	
TRANSFORMERS	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
C.O Monitors	Visual		Exam	OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe At time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 8297

Certificate # 4325

Certificate # _____

Certificate # _____

2MSHA04349

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-4-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 930 AM/PM PM Examiners Initials DD/FO

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	none obs.	
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	none obs.	
#4	21	0	0	ok	none obs.	
#5	21	0	0	ok	needs dust from 109 to fall	working on Done 1-4-07
#6	21	0	0	ok	none obs.	
#7	21	0	0	ok	none obs.	
Trans.	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
CO Sensors		Visual ok				

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas safe at time of exam

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 9458
 Certificate # _____
 Certificate # _____

2MSHA04350

SIGNATURE
 Counter Signature _____

Certificate # 8262

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-5-07

SECTION/AREA Belts

Time of Examination Start 300 AM PM End 530 AM PM Examiners Initials DP/MC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	none obs.	
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	none obs.	
#4	21	0	0	ok	none obs.	
#5	21	0	0	ok	none obs.	
#6	21	0	0	ok	none obs.	
#7	21	0	0	ok	COAL ACCO Headroller	SENTE MEN TO CLEAN DONE 1-5-07 JS
Trans.	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
CO Sensors				Visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 7375
 Certificate # _____
 Certificate # _____

2MSHA04351

Counter Signature **SIGNATURE** _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-5-07

SECTION/AREA Belts

Time of Examination Start 11:10 ~~AM~~ ~~PM~~

End 1:05 AM/PM

Examiners Initials TK

Time of Examination Start 11:15 ~~AM~~ ~~PM~~

End 1:00 AM/PM

Examiners Initials SW

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None obs.	
#2	20.9	0	0		OK	None obs.	
#3	20.9	0	0		OK	None obs.	
#4	20.9	0	0		OK	None obs.	
#5	20.9	0	0		OK	None obs.	
#6	20.9	0	0		OK	None obs.	
#7	20.9	0	0		OK	None obs.	
Kitchen	20.9	0	0		OK	None obs.	
Transformers	20.9	0	0		OK	None obs.	
C/o sensors					Visual EXAM		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas seemed safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9362
 Certificate # 9548
 Certificate # _____
 Certificate # _____

2MSHA04352

Counter Signature **SIGNATURE** _____

Certificate # 7488

PRE-SHIFT BELTS

DATE OF EXAMINATION 1/5/07 SECTION/AREA Belts

Time of Examination Start 7:02 AM/PM AM End 8:20 AM/PM PM Examiners Initials LH

Time of Examination Start 7:10 AM/PM AM End 9:17 AM/PM PM Examiners Initials BH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	Acc At tail	Shaveled & dusted @ 1507
#2	21	0	0	OK	none obs	
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	20.9	0	0	OK	none obs	
#6	20.9	0	0	OK	none obs	
#7	20.9	0	0	OK	none obs	
Kitchen	21	0	0	OK	none obs	
Transformer	21	0	0	OK	none obs	
C.O. Sensor				Visual exam ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & Travel at Time of exam.

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8703
 Certificate # 8395
 Certificate # _____
 Certificate # _____

2MSHA04353

SIGNATURE

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 1/6/07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM

End 4:59 AM/PM

Examiners Initials LH

Time of Examination Start 4:40 AM/PM

End 5:20 AM/PM

Examiners Initials VBH

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	none obs	
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	21	0	0	OK	Roller Piles 103-104	WORKING ON DONE 1-6-07 JG
#6	20.9	0	0	OK	none obs	
#7	20.9	0	0	OK	none obs	
Kitchen	20.9	0	0	OK	none obs	
Transformer	20.9	0	0	OK	none obs	
C.O. sensor		visual		exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & Travel at time of exam.

Pre-Shift/Mine Examiner SIGNATURE _____

Certificate # 8703

Pre-Shift/Mine Examiner _____

Certificate # 8395

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04354

Counter Signature SIGNATURE _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1/6/07 SECTION/AREA Belts

Time of Examination Start 11:10 AM End 1:15 AM Examiners Initials: SW

Time of Examination Start 11:05 AM End 1:25 AM Examiners Initials: RC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20%	0	0	OK	none observed	
#2	20%	0	0	OK	ACE At tail	SENT MEN TO CLEAN DONE 1-6-07 J
#3	20%	0	0	OK	none observed	
#4	20%	0	0	OK	none observed	
#5	20%	0	0	OK	none observed	
#6	20%	0	0	OK	none observed	
#7	20%	0	0	OK	none observed	
Kitchen	20%	0	0	OK	none observed	
Transformers	20%	0	0	OK	none observed	
CO Monitors				USUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of exam except above notes.

Pre-Shift/Mine Examiner [Signature] Certificate # 9548

Pre-Shift/Mine Examiner [Signature] Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA04355 Certificate # _____

Counter Signature [Signature] Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1/6/07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM (PM) End 8:15 AM/PM (PM) Examiners Initials BH

Time of Examination Start 7:09 AM/PM (PM) End 9:08 AM/PM (PM) Examiners Initials LH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	none obs	
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	21	0	0	OK	none obs	
#6	20.9	0	0	OK	none obs	
#7	20.9	0	0	OK	none obs	
Kitchen	21	0	0	OK	none obs	
Trans	21	0	0	OK	none obs	
C.O. sensor				Visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & Travel
at time of exam.

SIGNATURE _____

Pre-Shift/Mine Examiner _____ Certificate # 8703

Pre-Shift/Mine Examiner _____ Certificate # 8395

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

SIGNATURE _____ 2MSHA04356

Counter Signature _____ Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 1/7/7 SECTION/AREA Belts

Time of Examination Start 3:01 AM/PM End 4:48 AM/PM Examiners Initials LH

Time of Examination Start 4:50 AM/PM End 5:20 AM/PM Examiners Initials BH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

Called Out By _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	X-cut 35. All on top of overcast.	SENT MAN TO CLEAN DOME 1-7-67 ED
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	21	0	0	OK	none obs	
#6	21	0	0	OK	none obs	
#7	20.9	0	0	OK	none obs	
Kitchen	21	0	0	OK	none obs	
Thurs	21	0	0	OK	none obs	
C. O. sensor						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & Travel at time of exam.

Pre-Shift/Mine Examiner SIGNATURE Certificate # 8703

Pre-Shift/Mine Examiner SIGNATURE Certificate # 8395

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04357

Counter Signature SIGNATURE Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-7-07 SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:18 AM/PM Examiners Initials TC

Time of Examination Start 11:00 AM/PM End 1:35 AM/PM Examiners Initials JW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20.9	0	0	OK	None obs.	
# 2	20.9	0	0	OK	None obs.	
# 3	20.9	0	0	OK	None obs.	
# 4	20.9	0	0	OK	None obs.	
# 5	20.9	0	0	OK	None obs.	
# 6	20.9	0	0	OK	None obs.	
# 7	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
Transformers	20.9	0	0	OK	None obs.	
Chiller				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas seemed safe at time
2nd Exam

Pre-Shift/Mine Examiner **SIGNATURE**

Pre-Shift/Mine Examiner **SIGNATURE**

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____ 2MSHA04358

Certificate # 9362

Certificate # 9548

Certificate # _____

Certificate # _____

Counter Signature **SIGNATURE**

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1/7/07 SECTION/AREA Belts

Time of Examination Start 7:01 AM/PM End 8:04 AM/PM Examiners Initials LH

Time of Examination Start 7:05 AM/PM End 9:05 AM/PM Examiners Initials LH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	none obs	
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	21	0	0	OK	none obs	
#6	21	0	0	OK	none obs	
#7	20.9	0	0	OK	none obs	
Transformers	21	0	0	OK	none obs	
Kitchen	21	0	0	OK	none obs	
C.O. Sensor				Visual exam	OK	

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & Travel at
Time of exam.

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 8703

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04359

Counter Signature **SIGNATURE** Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-8-07 SECTION/AREA Belts

Time of Examination Start 3:06 AM/PM End 4:55 AM/PM Examiners Initials BH

Time of Examination Start 4:20 AM/PM End 4:49 AM/PM Examiners Initials LH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None Observed	
#2	20.9	0	0	OK	None Observed	
#3	20.9	0	0	OK	acc. Tail	ass. men to clean cleaned LR
#4	20.9	0	0	OK	None Observed	
#5	20.9	0	0	OK	acc Drive to exit job	ass. men to clean cleaned LR/RL
#6	20.9	0	0	OK	None Observed	
#7	20.9	0	0	OK	None Observed	
Transformers	20.9	0	0	OK	None Observed	
Kitchen	20.9	0	0	OK	None Observed	
CO monitors				Visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Except as noted above all areas safe
at time of exam

Pre-Shift/Mine Examiner [Signature] Certificate # 8395

Pre-Shift/Mine Examiner [Signature] Certificate # 8703

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04360

Counter Signature [Signature] Certificate # 4235

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-8-07

SECTION/AREA Belts

Time of Examination Start 1100 AM/PM End 145 AM/PM Examiners Initials R/SR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none "	
#3	20.9	0	0	OK	none "	
#4	20.9	0	0	OK	none "	
#5	20.9	0	0	OK	none "	
#6	20.9	0	0	OK	dust Head to tail.	extended to next shift
#7	20.9	0	0	OK	none obs.	
Transformer	20.9	0	0	OK	none obs.	
Kitchens	20.9	0	0	OK	none	
CO Abatement	visual	spans		OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All other areas appeared safe at time of exams.

Pre-Shift/Mine Examiner SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6401
 Certificate # 4325
 Certificate # _____
 Certificate # _____

Counter Signature SIGNATURE

2MSHA04361

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1/8/07 SECTION/AREA belts

Time of Examination Start 7:00 AM/PM AM End 8:29 AM/PM PM Examiners Initials LH

Time of Examination Start 7:11 AM/PM PM End 8:37 AM/PM PM Examiners Initials KM

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	none obs	
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	21	0	0	OK	none obs	
#6	21	0	0	OK	needs dust, Head to Tail	working on Done 1/8/07 CA
#7	20.9	0	0	OK	none obs	
Kitchen	21	0	0	OK	none obs	
Transformers	21	0	0	OK	none obs	
C.O. sensor				visual exam	OK	

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & travel at time of exam.

Pre-Shift/Mine Examiner [Signature] Certificate # 8703

Pre-Shift/Mine Examiner [Signature] Certificate # 9379

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature [Signature] Certificate # 05892

2MSHA04362

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-9-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 4:01 AM/PM Examiners Initials LH

Time of Examination Start 3:00 AM/PM End 3:58 AM/PM Examiners Initials [Signature]

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	none obs	
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	Return stoping leaking Need re mudded xcutting	Ass. man to fix mudded 1-9-07 KK
#5	21	0	0	OK	All at stoping ^{issue} stoping	cleared
#6	21	0	0	OK	none obs	
#7	21	0	0	OK	none obs	
Kitchen	21	0	0	OK	none obs	
transformer	21	0	0	OK	none obs	
CO monitor	3			visual exam	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
X-cut 89	stoping leaking	

PRE-SHIFT REMARKS All areas safe for work & travel at time of exam

SIGNATURE [Redacted]

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 8702

Certificate # 9379

Certificate # _____

Certificate # _____

SIGNATURE [Redacted]

2MSHA04363

Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-9-07

SECTION/AREA Belts

Time of Examination Start 1100 AM/PM End 1:20 AM/PM Examiners Initials AK/Em

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	OK	None obs	
#2	20.9	0.0	0.0	OK	accum belts out 3334	155. man to clean cleaned 1-9-07 AK
#3	20.9	0.0	0.0	OK	None obs	
#4	20.9	0.0	0.0	OK	None obs	
#5	20.9	0.0	0.0	OK	None obs.	
#6	20.9	0.0	0.0	OK	None obs	
#7	20.9	0.0	0.0	OK	None obs.	
Belt Kitcher	20.9	0.0	0.0	OK	None obs	
Trms.	20.9	0.0	0.0	OK	None	
L.O. Monitor						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas seemed reasonably safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7054
 Certificate # 8297
 Certificate # _____
 Certificate # _____

SIGNATURE

Counter Signature _____ 2MSHA04364

Certificate # 4733

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-9-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 850 AM/PM PM Examiners Initials FDMC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	None obs.	
#2	21	0	0	OK	None obs.	
#3	21	0	0	OK	None obs.	
#4	21	0	0	OK	None obs.	
#5	21	0	0	OK	None obs.	
#6	21	0	0	OK	None obs.	
#7	21	0	0	OK	None obs.	
Transformers	21	0	0	OK	None obs.	
Kitchen	21	0	0	OK	None obs.	
CO Sensors				Visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe at the time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

2MSHA04365

Certificate # 9958

Certificate # 7375

Certificate # _____

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-10-07

SECTION/AREA Belt's

Time of Examination Start 300 AM/PM End 500 AM/PM Examiners Initials FD-00

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
A#1 #1	21	0	0	OK	None obs. See below	Ass Mon to Dust Done 1-10-07 JR
#2	21	0	0	OK	None obs.	
#3	21	0	0	OK	None obs.	
#4	21	0	0	OK	None obs.	
#5	21	0	0	OK	None obs.	
#6	21	0	0	OK	None obs.	
#7	21	0	0	OK	None obs.	
Transferrmus	21	0	0	OK	None obs.	
Kitchen	21	0	0	OK	None obs.	
CO Sensors	Visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS #1 belt needs dust from X-cut 26 to tail, everything else appeared to be safe at the time of exam. done 1-10-07 JR

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9158
 Certificate # 8058
 Certificate # _____
 Certificate # _____

2MSHA04366

Counter Signature **SIGNATURE** _____

Certificate # 4135

PRE-SHIFT BELTS

DATE OF EXAMINATION 1.10.07 SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:15 AM/PM Examiners Initials RR/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	COAL ACC. #8 offside	ASS MAN to clean DONE 1-10-07 RR
#2	20.9	0	0	OK	OIL & COAL ACC. AT drive offside	ASS MAN to clean done 1-10-07 RR
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	COAL ACC. AT drive	ASS MAN to clean 1-10-07 RR
#6	20.9	0	0	OK	None obs	
#7	20.9	0	0	OK	None obs	
Belt Kitchen	20.9	0	0	OK	None obs.	
Trans.	20.9	0	0	OK	None obs.	
C.O. Monitors <u>checked OK</u>						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4375
 Certificate # 6401
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____
 2MSHA04367

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-10-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM PM End 920 AM/PM AM PM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	oil Accumulations @ Drive	working on cleaned 1-10-07
#2	21	0	0	ok	coal Accumulations @ Tail	working on Done 1-10-07
#3	21	0	0	ok	needs dust from Headroller to Drive	working on Dusted 1-10-07
#4	21	0	0	ok	none obs.	
#5	21	0	0	ok	none obs.	
#6	21	0	0	ok	none obs.	
#7	21	0	0	ok	none obs.	
TRANS.	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
CO Sensors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____ 2MSHA04368

Certificate # 8058
 Certificate # 7375
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-11-07

SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 455 AM/PM Examiners Initials JD-MC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	None Obs.	
#2	21	0	0	OK	None Obs.	
#3	21	0	0	OK	None Obs.	
#4	21	0	0	OK	None Obs.	
#5	21	0	0	OK	None Obs.	
#6	21	0	0	OK	None Obs.	
#7	21	0	0	OK	None Obs.	
CO Sensors	Visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe at the time of exam.

Pre-Shift/Mine Examiner Signature
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9458
 Certificate # 7375
 Certificate # _____
 Certificate # _____

2MSHA04369

Counter Signature SIGNATURE

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-11-07 SECTION/AREA Belts

Time of Examination Start 11:00 AM PM End 1:15 AM PM Examiners Initials JK/FM

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
TRANS SENSORS	20.9	0	0	OK	None obs.	
CO Sensors	Visual	OK	Exam	OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 4325

Certificate # 8297

Certificate # _____

Certificate # _____

Counter Signature **SIGNATURE** _____

2MSHA04370

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-11-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 900 AM/PM PM Examiners Initials FD-DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	None obs.	
#2	21	0	0	OK	None obs.	
#3	21	0	0	OK	None obs.	
#4	21	0	0	OK	None obs. See below	Working on dusted 1/10/07
#5	21	0	0	OK	None obs.	
#6	21	0	0	OK	Needs dust from tail to	Working on dusted 1/10/07
#7	21	0	0	OK	None obs.	
Transformers	21	0	0	OK	None obs.	
Kitchen	21	0	0	OK	None obs.	
CO Sensors	VISUAL exam.			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS #4 Belt needs dust from tail to x-cut 100
The rest of the areas appeared to be safe.

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

2MSHA04371

Certificate # 9458
 Certificate # 8058
 Certificate # _____
 Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-12-07

SECTION/AREA Belts

Time of Examination Start 300 ~~AM~~ PM End 525 ~~AM~~ PM Examiners Initials DDMC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	none obs.	
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	none obs.	
#4	21	0	0	ok	none obs.	
#5	21	0	0	ok	none obs.	
#6	21	0	0	ok	none obs.	
#7	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
Trans.	21	0	0	ok	none obs.	
CO sensors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04372

SIGNATURE

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-12-07

SECTION/AREA Belts

Time of Examination Start 11:15 AM/PM End 1:00 AM/PM Examiners Initials LD

Time of Examination Start 11:10 AM/PM End 1:15 AM/PM Examiners Initials SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
CO sensors	visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all Areas appeared safe at the time of exam.

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9660
 Certificate # 9548
 Certificate # _____
 Certificate # _____

2MSHA04373

Counter Signature **SIGNATURE** _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-12-08

SECTION/AREA BELTS

Time of Examination Start 7:00 AM/PM AM End 9:00 AM/PM PM Examiners Initials BP

Time of Examination Start 7:00 AM/PM AM End 7:40 AM/PM PM Examiners Initials LH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	none observed	
Transformers	20.9	0	0	ok	none observed	
CO Sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

All areas appeared safe at time of Exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9599

Pre-Shift/Mine Examiner _____

Certificate # 8703

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04374

SIGNATURE

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 1/13/07 SECTION/AREA belts

Time of Examination Start 3:00 (AM/PM) End 5:20 (AM/PM) Examiners Initials LH

Time of Examination Start 3:00 (AM/PM) End 3:35 (AM/PM) Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	All. sec below	SENT MAN TO CLEAN DONE 1-13-07 JC
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	21	0	0	OK	none obs	
#6	20.9	0	0	OK	none obs	
#7	20.9	0	0	OK	none obs	
Trans	21	0	0	OK	none obs	
Kitchen	21	0	0	OK	none obs	
CO sensor				Visual exam ok		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION
	#2 belt	All on top of 3rd north overcast	CLEANED 1-13-07 JC

PRE-SHIFT REMARKS All areas safe for work & travel at time of exam.

Pre-Shift/Mine Examiner [Signature] Certificate # 8703

Pre-Shift/Mine Examiner [Signature] Certificate # 9599

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04375

Counter Signature [Signature] Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-13-07

SECTION/AREA Belts

Time of Examination Start 11:15 AM/PM End 1:00 AM/PM Examiners Initials SW
 Time of Examination Start 11:15 AM/PM End 1:11 AM/PM Examiners Initials TC
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	none observed	
#2	20.9	0	0		OK	none observed	
#3	20.9	0	0		OK	none observed	
#4	20.9	0	0		OK	none observed	
#5	20.9	0	0		OK	none observed	
#6	20.9	0	0		OK	Belt Trans has cable in vent	Working on Done 1-13-07 TC
#7	20.9	0	0		OK	none observed	
Kitchen	20.9	0	0		OK	none obs.	
Transformers	20.9	0	0		OK	none observed	
CO Monitors.	(Visual exam)						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas seemed reasonably safe
at time of exam

Pre-Shift/Mine Examiner SIGNATURE _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9548
 Certificate # 9362
 Certificate # _____
 Certificate # _____

2MSHA04376

Counter Signature SIGNATURE _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1/13/07 SECTION/AREA belts

Time of Examination Start 7:13 AM/PM (M) End 9:07 AM/PM (M) Examiners Initials LH

Time of Examination Start 7:00 AM/PM (M) End 7:35 AM/PM (M) Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	none obs	
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	21	0	0	OK	none obs	
#6	20.9	0	0	OK	none obs	
#7	20.9	0	0	OK	none obs	
TRAILS	21	0	0	OK	none obs	
Kitchen	21	0	0	OK	none obs	
C.O. Sensor			Visual	exam OK		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & travel at
Time of exam.

Pre-Shift/Mine Examiner SIGNATURE Certificate # 8703

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9529

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04377

Counter Signature SIGNATURE Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-14-07

SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 505 AM/PM Examiners Initials BP

Time of Examination Start 300 AM/PM End 329 AM/PM Examiners Initials LH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	none obs	
#2	20	0	0	OK	none obs	
#3	20	0	0	OK	none obs	
#4	20	0	0	OK	none obs Acc of Tail	DONE LD GETTING MINOR IT
#5	20	0	0	OK	none obs	
#6	20	0	0	OK	none obs	
#7	20	0	0	OK	none obs	
Kitchen	20	0	0	OK	none obs	
Trans	20	0	0	OK	none obs	
CO SENSORS				VISUAL Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9598
 Certificate # 8707
 Certificate # _____
 Certificate # _____

2MSHA04378

Counter Signature **SIGNATURE** _____

Certificate # 7488

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-14-07

SECTION/AREA Belt

Time of Examination Start 11:00 AM/PM End 12:45 AM/PM Examiners Initials SW

Time of Examination Start 11:00 AM/PM End 12:50 AM/PM Examiners Initials RC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Bad top #1 Tail #2 Hem ACC AT Tail	Beltman SENT MAN TO CLEAN DONE JS
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	none observed	
kitchen	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
CO Monitors (visual exam)				OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted above all other AREAS seemed
SAFE AT TIME of Pre-shift

SIGNATURE

Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____

Certificate # 9548
Certificate # 9362
Certificate # _____
Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA04379

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-14-07

SECTION/AREA Belts

Time of Examination Start 730 AM/PM AM End 935 AM/PM PM Examiners Initials BP

Time of Examination Start 730 AM/PM AM End 801 AM/PM PM Examiners Initials GH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none obs	
#2	20	0	0	ok	none obs	
#3	20	0	0	ok	none obs	
#4	20	0	0	ok	none obs	
#5	20	0	0	ok	none obs	
#6	20	0	0	ok	none obs	
#7	20	0	0	ok	none obs	
Kitchen	20	0	0	ok	none obs	
Transformers	20	0	0	ok	none obs	
CO CO monitors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 958
 Certificate # 870
 Certificate # _____
 Certificate # _____

2MSHA04380

Counter Signature **SIGNATURE** _____

Certificate # 05892

PRE-SHIFT BELTS

DATE OF EXAMINATION 1/15/07

SECTION/AREA belts

Time of Examination Start 3:10 AM/PM

End 5:29 AM/PM

Examiners Initials LH

Time of Examination Start 3:10 AM/PM

End 3:35 AM/PM

Examiners Initials BP

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	none obs	
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	21	0	0	OK	none obs	
#6	21	0	0	OK	none obs	
#7	21	0	0	OK	All in walkway. x-cut 130	sent men to work on cleared 2' walkway 1-15-07
Trans	21	0	0	OK	none obs	
Kitchen	21	0	0	OK	none obs	
L.O. Sensor				visual exam	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & travel at
Time of exam.

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8703
 Certificate # 2699
 Certificate # _____
 Certificate # _____

2MSHA04381

Counter Signature **SIGNATURE** _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION Belts 1-15-07 SECTION/AREA Belts

Time of Examination Start 11:05 ~~AM~~/PM End 1:25 AM/~~PM~~ Examiners Initials TC

Time of Examination Start 11:00 ~~AM~~/PM End 1:20 AM/~~PM~~ Examiners Initials DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20.9	0	0	OK	Oil ACC. AT Drive	^{working on} cleaned 1-15-07
# 2	20.9	0	0	OK	ACC. AT Tail	^{working on} cleaned 1-15-07
# 3	20.9	0	0	OK	none obs.	
# 4	20.9	0	0	OK	None obs.	
# 5	20.9	0	0	OK	None obs.	
# 6	20.9	0	0	OK	None obs.	
# 7	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
Transformers	20.9	0	0	OK	None obs.	
C/O sensor				Visual exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted above All ALER's appeared

Safe AT time of exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 9362

Certificate # 8058

Certificate # _____

Certificate # _____

SIGNATURE _____

Counter Signature _____

2MSHA04382

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-15-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM PM End _____ AM/PM Examiners Initials KK/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0		OK	none obs.	
#2	20.9	0	0		OK	accum at tail	sent info to worker cleaned 1-15-07
#3	20.9	0	0		OK	none obs.	
#4	20.9	0	0		OK	none obs.	
#5	20.9	0	0		OK	none obs.	
#6	20.9	0	0		OK	none obs.	
#7	20.9	0	0		OK	none obs.	
Kitchew	20.9	0	0		OK	none obs.	
Transformers	20.9	0	0		OK	none obs.	
CO Sensors	VISUAL Exam						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared reasonably safe except as noted above at time of pre-shift.

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

2MSHA04383

Certificate # 7954

Certificate # 6401

Certificate # _____

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-16-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM PM End 5:30 AM PM Examiners Initials KR/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs	
#2	20.9	0	0	OK	none obs	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs	
#5	20.9	0	0	OK	None obs	
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	accum. head roller	sent men to work in Cleaned 1-16-07
Witcham	20.9	0	0	OK	None obs.	
Turnover	20.9	0	0	OK	none obs	
CO Sensors	normal	0	0	OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

SIGNATURE

Pre-Shift/Mine Examiner
 Pre-Shift/Mine Examiner
 Pre-Shift/Mine Examiner
 Pre-Shift/Mine Examiner

2MSHA04384

Certificate # 7954
 Certificate # 6401
 Certificate # _____
 Certificate # _____

SIGNATURE

Counter Signature

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-16-07

SECTION/AREA BELTS

Time of Examination Start 11:05 AM PM End 1:00 AM PM Examiners Initials ME

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	Accum tailpiece	cleaned by
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	hole in stoping xc 126, 134	34th & men to work on fixed by

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRESHIFT

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # 9379

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04385

SIGNATURE _____

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-16-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM PM End 9:30 AM/PM AM PM Examiners Initials JR/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None obs.	
#2	20.9	0	0		OK	Flint dust & Need dusted w/ Hand roller	done 1-16-07 JR
#3	20.9	0	0		OK	None obs.	
#4	20.9	0	0		OK	None obs.	
#5	20.9	0	0		OK	None obs.	
#6	20.9	0	0		OK	None obs.	
#17	20.9	0	0		OK	None obs.	
Kitchen	20.9	0	0		OK	None obs.	
Transfermers	20.9	0	0		OK	None obs.	
CO Monitors	Visual	Exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 drive	Coat Acc.	Washed
#6 hand roller	seal acc.	Washed

PRE-SHIFT REMARKS Press appended Safe at time of Exam except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4375
 Certificate # 7954
 Certificate # _____
 Certificate # _____

2MSHA04386

SIGNATURE

Counter Signature: _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-17-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:30 AM/PM Examiners Initials KK/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs	
#2	21.0	0	0	OK	None obs	
#3	20.9	0	0	OK	None obs	
#4	20.9	0	0	OK	none obs	
#5	20.9	0	0	OK	none obs	
#6	20.9	0	0	OK	none obs	
#7	20.9	0	0	OK	accum in take-up	sent men to work on zone
Kitchen	20.9	0	0	OK	none obs	
Turners Somers	20.9	0	0	OK	none obs	
CO Monitors	manual exam OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe except as noted

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 7954

Pre-Shift/Mine Examiner _____

Certificate # 6421

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

2MSHA04387

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-17-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 12:45 AM/PM Examiners Initials EM/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		α	None observed	
#2	20.9	0	0		α	None observed	
#3	20.9	0	0		α	None observed	
#4	20.9	0	0		α	None observed	
#5	20.9	0	0		α	None observed	
#6	20.9	0	0		α	None observed	
#7	20.9	0	0		α	Acc at takeup	Done KM/DO
Kitchen	20.9	0	0		α	None observed	
Transformers	20.9	0	0		α	None observed	
C.O Monitors	visual Exam				α		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of exam - except as noted

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

2MSHA04388

Certificate # 8297

Certificate # 7378

Certificate # _____

Certificate # _____

SIGNATURE

Counter-Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-17-09

SECTION/AREA Belts

Time of Examination Start 845 AM/PM AM PM End 11:00 AM/PM AM PM Examiners Initials KK/LR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		↻	None obs.	
#2	20.9	0	0		↻	None obs.	
#3	20.9	0	0		↻	None obs.	
#4	20.9	0	0		↻	None obs.	
#5	20.9	0	0		↻	None obs.	
#6	20.9	0	0		↻	None obs.	
#7	20.9	0	0		↻	None obs.	
Kitchens	20.9	0	0		↻	None obs.	
Transformers	20.9	0	0		↻	None obs.	
CO Louvers	Natural exom				↻		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS From approval safe at time of Exam
All Belts were off until 9:30 pm before preshift

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4375
 Certificate # 7954
 Certificate # _____
 Certificate # _____

2MSHA04389

SIGNATURE

Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-18-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:30 AM/PM Examiners Initials AK/R2

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0		OK	acc at xcs	working on cleaned & dusted
#2	20.9	0.0	0.0		OK	none obs	
#3	20.9	0.0	0.0		OK	none obs	
#4	20.9	0.0	0.0		OK	none obs	
#5	20.9	0.0	0.0		OK	accum 10' top	sent man to work on cleaned 1-18-07 mc
#6	20.9	0.0	0.0		OK	none obs	
#7	20.9	0.0	0.0		OK	none obs	
Kitchen	20.9	0.0	0.0		OK	none obs	
Trams	20.9	0.0	0.0		OK	none obs	
C.O. Member					OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas seemed reasonably safe at pre-shift

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7154
 Certificate # 6401
 Certificate # _____
 Certificate # _____

2MSHA04390

Counter Signature **SIGNATURE** _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-18-07

SECTION/AREA Belts

Time of Examination Start 1100 AM PM End 130 AM PM Examiners Initials DD

Time of Examination Start 11:00 AM PM End 1:20 AM PM Examiners Initials FW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	Acc. portal	working on
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	Acc. Headroller-Drive	Cleaned 1-18-07
#4	20.9	0	0	ok	need dust drive ext	dusted KM
#5	20.9	0	0	ok	none obs	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	COAL ACC. @ Tail	cleaned 1-18-07
Kitchen	20.9	0	0	ok	none obs.	
Trans.	20.9	0	0	ok	none obs.	
CD monitors				Visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas safe at time of exam.

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 9379
 Certificate # _____
 Certificate # _____

2MSHA04391

SIGNATURE

Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-18-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM PM End 930 AM/PM AM PM Examiners Initials PL/RR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		⊙	None obs.	
#2	20.9	0	0		⊙	none observed	
#3	20.9	0	0		⊙	None obs.	
#4	20.9	0	0		⊙	none obs.	
#5	20.9	0	0		⊙	None obs.	
#6	20.9	0	0		⊙	belt chain broken	working on Done 05
#7	20.9	0	0		⊙	none obs. X 130	
Kitchen	20.9	0	0		⊙	none obs.	
Transformer	20.9	0	0		⊙	none obs.	
CO Sensors					⊙	actual span	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 0401
 Certificate # 4375
 Certificate # _____
 Certificate # _____

2MSHA04392

Counter Signature **SIGNATURE** _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-19-07

SECTION/AREA Belt

Time of Examination Start 300 AM/PM

End 548 AM/PM

Examiners Initials PL/SR

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Report Received by _____

Called Out By _____

Signature

Called Out By _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none "	
#3	20.9	0	0	OK	none "	
#4	20.9	0	0	OK	acc 102 to tail	working on Dum 1-19-07 BY
#5	20.9	0	0	OK	acc head	working on Dum 1-19-07 BY
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none	
Trans.	20.9	0	0	OK	none	
C.O. Monitor's manual						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All other areas appeared safe at time of exam.

Pre-Shift/Mine Examiner [Signature]
 Pre-Shift/Mine Examiner [Signature]
 Pre-Shift/Mine Examiner _____ 2MSHA04393
 Pre-Shift/Mine Examiner _____

Certificate # 6401
 Certificate # 4325
 Certificate # _____
 Certificate # _____

Counter Signature [Signature]

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-19-07

SECTION/AREA Belts

Time of Examination Start 1105 AM End 103 AM Examiners Initials BP

Time of Examination Start 1107 AM End 1130 AM Examiners Initials LH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	28	0	0	ok	none obs	
#2	28	0	0	ok	none obs	
#3	28	0	0	ok	none obs	
#4					tec at local Roller to 101 working on it	
#5	28	0	0	ok	none obs	Done &
#6	28	0	0	ok	none obs	
#7	28	0	0	ok	none obs	
Kitchen	28	0	0	ok	none obs	
Transformer	28	0	0	ok	none obs	
CO sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9589
 Certificate # 803
 Certificate # _____
 Certificate # _____

2MSHA04394

Counter Signature **SIGNATURE** _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-19-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:12 AM/PM PM Examiners Initials TC

Time of Examination Start 7:00 AM/PM AM End 9:00 AM/PM PM Examiners Initials SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	none obs.	
#2	20.9	0	0		OK	none obs.	
#3	20.9	0	0		OK	none obs.	
#4	20.9	0	0		OK	none obs.	
#5	20.9	0	0		OK	none obs.	
#6	20.9	0	0		OK	none obs.	
#7	20.9	0	0		OK	none obs.	
Kitchen	20.9	0	0		OK	none obs.	
Transformers	20.9	0	0		OK	none obs.	
Clo sensor				Visual	EXAM		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas scanned Reasonably safe AT
Time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9362

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9548

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature **SIGNATURE** _____ Certificate # _____

2MSHA04395

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-20-07

SECTION/AREA Belts.

Time of Examination Start 3:05 AM/PM End 5:10 AM/PM Examiners Initials JL

Time of Examination Start 3:10 AM/PM End 5:25 AM/PM Examiners Initials JW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20 ⁹	0	0		OK	none observed	
#2	20 ⁹	0	0		OK	needs dust vent 35 to 38	Done GA 12007
#3	20 ⁹	0	0		OK	none observed	
#4	20 ⁹	0	0		OK	oil ACC. AT Drive	Done GA 12007
#5	20 ⁹	0	0		OK	none observed	
#6	20 ⁹	0	0		OK	none observed	
#7	20 ⁹	0	0		OK	none observed	
Kitchen	20 ⁹	0	0		OK	none observed	
Transformer	20 ⁹	0	0		OK	none observed	
Clo sensors					VISUAL EXAM		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Pre-shift except above notes.

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9548
 Certificate # 9362
 Certificate # _____
 Certificate # _____

2MSHA04396

SIGNATURE

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-20-07 SECTION/AREA Belts

Time of Examination Start 11:20 AM PM End 103 AM PM Examiners Initials BP

Time of Examination Start 11:30 AM PM End 12:04 AM PM Examiners Initials LH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none obs	
#2	20	0	0	ok	none obs	
#3	20	0	0	ok	none obs	
#4	20	0	0	ok	none obs	
#5	20	0	0	ok	none obs	
#6	20	0	0	ok	none obs	
#7	20	0	0	ok	none obs	
Kitchen	20	0	0	ok	none obs	
Transformers	20	0	0	ok	none obs	
CO SENSORS				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

All areas appeared safe at time of Exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9599

Pre-Shift/Mine Examiner _____

Certificate # 8705

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04397

SIGNATURE

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-20-07 SECTION/AREA Belts

Time of Examination Start 7:03 AM/PM End 9:17 AM/PM Examiners Initials TC

Time of Examination Start 7:00 AM/PM End 9:35 AM/PM Examiners Initials JW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
Transformers	20.9	0	0	OK	None obs.	
Cp sensor				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#4 Belt	ACC AT 4 Tail	Cleaned 1-20-07 TC

PRE-SHIFT REMARKS All Areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____

Pre-Shift/Mine Examiner **SIGNATURE** _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 9367

Certificate # 9548

Certificate # _____

Certificate # _____

2MSHA04398

Counter Signature **SIGNATURE** _____

Certificate # 7488

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-22-07 SECTION/AREA Belts

Time of Examination Start 3:10 ~~AM~~/PM End 5:16 ~~AM~~/PM Examiners Initials TC

Time of Examination Start 3:05 ~~AM~~/PM End 5:35 ~~AM~~/PM Examiners Initials SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____


Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	NEED Dusted TAKEUP-XCC	Dusting Done 1-21-07 BH
#2	20.9	0	0	OK	NONE OBS.	
#3	20.9	0	0	OK	NONE OBS.	
#4	20.9	0	0	OK	NONE OBS.	
#5	20.9	0	0	OK	NONE OBS.	
#6	20.9	0	0	OK	NONE OBS.	
#7	20.9	0	0	OK	NONE OBS.	
Kitchen	20.9	0	0	OK	NONE OBS.	
TRANSFORMERS	20.9	0	0	OK	NONE OBS.	
Closcissor				Jisaul EXAM		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION
	#4 belt	XC 92 tags HAD HOT Bottom Roller	Dropped Roller hosed Down AT FIRE VALVE 1-21-07 TC

PRE-SHIFT REMARKS ALL AREAS ARE SAFE AT TIME OF EXAM

Pre-Shift/Mine Examiner  Certificate # 9362

Pre-Shift/Mine Examiner  Certificate # 9548

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA04399 _____ Certificate # _____

Counter Signature  Certificate # 03893

PRE-SHIFT BELTS

DATE OF EXAMINATION 11/21/06 SECTION/AREA belts

Time of Examination Start 11:00 AM/PM End 1256 AM/PM Examiners Initials LH

Time of Examination Start 11 AM/PM End 11 AM/PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

Called Out By _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	OK	none obs	
#2	21	0	0	OK	none obs	
#3	21	0	0	OK	none obs	
#4	21	0	0	OK	none obs	
#5	21	0	0	OK	none obs	
#6	21	0	0	OK	none obs	
#7	21	0	0	OK	none obs	
Kitchen	21	0	0	OK	none obs	
Trans	21	0	0	OK	none obs	
C.O. sensor				visual exam ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe for work & travel at time of exam.

SIGNATURE _____

Pre-Shift/Mine Examiner _____ Certificate # 8702

Pre-Shift/Mine Examiner _____ Certificate # 9599

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04400

SIGNATURE _____

Counter Signature _____ Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-24-07 SECTION/AREA Belts

Time of Examination Start 7:10 AM/PM AM End 9:20 AM/PM PM Examiners Initials TC

Time of Examination Start 7:00 AM/PM AM End 9:40 AM/PM PM Examiners Initials SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	ACC AT TAIL	Working on Done 1-22-07 TC
Kitchen	20.9	0	0	OK	None obs.	
Transformers	20.9	0	0	OK	None obs.	
Closet area				Visual EXA		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All AREAS APPEARED safe at time of EXA

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9362
 Certificate # 9548
 Certificate # _____
 Certificate # _____

2MSHA04401

SIGNATURE

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-22-07

SECTION/AREA Belts

Time of Examination Start 3:00 ~~AM~~/PM End 5:09 ~~AM~~/PM Examiners Initials JR

Time of Examination Start 3:00 ~~AM~~/PM End 5:40 ~~AM~~/PM Examiners Initials JW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	needs Dust xc20-26	Sent man to dust BT Done KM DD
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	ACL AT Tail piece	Sent man to shovel BT
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	Needs Timbers xc131-132 Walkway side	Sent men to timber BT Done 1-22-07 MC
Kitchen	20.9	0	0	OK	None obs.	
Transference	20.9	0	0	OK	None obs.	
Closet				Visual EXAM		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas scanned. Safe AT Time of Exam
Excepted noted above

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9362
 Certificate # 9548
 Certificate # _____
 Certificate # _____

2MSHA04402

Counter Signature **SIGNATURE** _____

Certificate # 8925

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-22-07

SECTION/AREA Belts

Time of Examination Start 11:25 AM/PM AM End 12:52 AM/PM PM Examiners Initials KM

Time of Examination Start 1:00 AM/PM AM End 1:30 AM/PM PM Examiners Initials DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	AFC	none observed	
#3	20.9	0	0	AFC	none obs.	
#4	20.9	0	0	OK	Acc. @ Head roller	sent men to work on cleaned 1-22-07
#5	20.9	0	0	OK	Acc. head roller	sent men to work on cleaned 1-22-07
#6	20.9	0	0	AFC	Acc head roller	sent men to work on Done 1-22-07
#7	20.9	0	0	AFC	Acc tail piece	sent men to work on Done 1-22-07
Kitchen	20.9	0	0	AFC	none observed	
Transformer	20.9	0	0	AFC	none observed	
CO monitors	✓ 2MSHA			exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9329

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04403

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 1-22-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 925 AM/PM PM Examiners Initials TR/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None obs.	
#2	20.9	0	0		OK	None obs.	
#3	20.9	0	0		OK	None obs.	
#4	20.9	0	0		OK	None obs.	
#5	20.9	0	0		OK	None obs.	
#6	20.9	0	0		OK	None obs.	
#7	20.9	0	0		OK	None obs.	
Belt Kitchen	20.9	0	0		OK	None obs.	
Trans.	20.9	0	0		OK	None obs.	
L.O. Monitor						normal	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area approved safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4375
 Certificate # 6909
 Certificate # _____
 Certificate # _____

2MSHA04404

Counter Signature **SIGNATURE** _____

Certificate # 4735

2MSHA04405