## Mine Citation/Order

## U.S. Department of Labor a Sofoty and Hoalth Administration



23908

	wille Safety and Health Administration
Section IViolation Data	
1. Date Mo Da Yr 2. Time (24 Hr. Clock) 12/06/2011 0800	3. Citation/ Order Number 4900593
4. Served To	5. Operator
Berman Cornett (Safety Director)	PERFORMANCE COAL COMPANY, et al
6. Mine	7. Mine ID 46-08436 (Contractor)
UPPER BIG BRANCH MINE-SOUTH	8a. Written Notice (103g)
8. Condition or Practice	
Addendum to the Methane and Dust Contrequires that 029/MMU (HG 22 or #1 sec 15,000 CFM in the last open break (crowd-04.05.2010, preshift records from 47 swithout the required minimum velocity working on all three shifts, completed the hazard is never shown, indicating	ction) be ventilated with a minimum of osscut). From 01.27.2010 through shifts show that the 029/MMU was operated. At least seven different foremen, d their preshift records, a correction of that the miners worked without the y mine examiner recorded at least three iod which further reflects different rd.
9. Violation A. Health ✓ B. Section of Act Cher	Part/Section of Title 30 CFR 75.370(e)
Section IIInspector's Evaluation	
10. Gravity: A. Injury or Illness (has) (is): No Likelihood Unlikely	Reasonably Likely Highly Likely 🗸 Occurred 📗
B. Injury or illness could rea-	kdays Or Restricted Duty Permanently Disabling Fatal
Sonably be expected to be: No Lost Workdays	D. Number of Persons Affected: 010
11. Negligence (check one) A. None B. Low C.	Moderate ☐ D. High ✔ E. Reckless Disregard ☐
12. Type of Action 104(d)(2) 13. Type of Issuan	ce (check one) Citation Order 🗹 Safeguard Written Notice
14. Initial Action A. Citation ☐ B. Order ✔ C. Safeguard ☐ D. Written Notice ☐	E. Citation/ Order Number 8082692 F. Dated Mo Da Yr 03/17/2009
15. Area or Equipment 029/MMU (HG 22 or #1 sec	tion)
16. Termination Due A. Date Mo Da Yr B. Time (24 Hr. Clock)	
Section IIITermination Action	
17. Action to Terminate	
18. Terminated A. Date Mo Da Yr B. Time (24 Hr. Clock	
Section IVAutomated System Data	
19. Type of Inspection (activity code) E16 20. Event Number 4440348	21. Primary or Mill
22. Signature Potrick Alon Stanfield	23. AR Number 23008

MSHA Form 7000-3, Apr 08 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small business about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

Patrick Alan Stanfield

## Mine Citation/Order Continuation

## **U.S. Department of Labor**Mine Safety and Health Administration



Section ISubsequent Action/Continuation Data								
1. Subsequent Action 1a. Continuation	2. Dated (Original Issue)	Mo 12/0	Da 06/201	Yr 1	3. Citation/ Order Number	4900593		
4. Served To			:	5. Operator				
Berman Cornett (Safety Director)				PERFORMANCE COAL COMPANY, et al				
6. Mine				7. Mine ID		(Contractor)		
<b>UPPER BIG BRANCH MINE-SO</b>	UTH				46-08436	<b>o</b>		
Section IIJustification for Action					_	· -		

Continuation of 8. Condition or Practice

is a highly dangerous condition. The operator has engaged in aggravated conduct constituting more than ordinary negligence. The mine is on a 103 (i) spot for methane liberation. This is an unwarrantable failure to comply with a mandatory standard.

This citation is being issued to the following entities as a unitary operator: Performance Coal Company, Massey Coal Services, Inc., A.T. Massey Coal Company, Inc., and Massey Energy Company.

<u> </u>						See Continuation Form
Section IIISubsequent Action Taken						
8. Extended To A. Date Mo Da	Yr B. Time	B. Time (24 Hr. Clock)			D. Terminated	E. Modified
Section IVInspection Data						<del>-</del>
9. Type of Inspection E16	10. Event Num	ber 4440348				
11. Signature	<b></b>	AR Number	12. Date	Mo Da Yr	13. Time (24 Hr. Clo	ock)
Patrick Alan Stanfield		23908		12/06/2011	0800	