

Pumps PRESHIFT - ONSHIFT and DAILY REPORT

Started - 3.21.10

Company Performance Coal
Mine LIBB
SECTION Pumps
LOCATION Naoma Raleigh NV
Post Office County State

Form 6-1489
(March 1970)

Budget Bureau No. 42-R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 3.21.10 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom F. Neely Time A.M. 2:30 P.M.
Report received by John B. Beckford (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows 1-10. Handwritten entries: 1. North Main 0% None Observed None; 2. Heavy Hole 0% None Observed None; 3. Ellis 0% None Observed None.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Handwritten entry: Good Air Movement.

Remarks: 0% CH4 0% CO2 20.8% O2 detected at time of exam

Traverseways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John B. Beckford 26176 Certificate No. 33359 Assistant Foreman
Countersigned F. Neely Mine Manager - Mine Foreman
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

6

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-21-19 20. Section or Area Examined Pumps
 Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
 Was this report phoned to outside: Yes no no Y
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>NORTH MAINS</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>GLORY HOLE</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>KILLIS</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4 0% CO 20.8% O2 AT TIME OF EXAM
TRAVELWAY OK AT TIME OF EXAM.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 32476 Certificate No. William Campbell Assistant Foreman 135419 Certificate No.
 Countersigned [Signature] Mine Manager—Mine Foreman 33389
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indefinite
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination: 3-22-10 Section or Area Examined: Run-Ins
 Time of Examination: from 3:30 a.m. or p.m. to 4:30 a.m. or p.m.
 Was this report phoned to outside? Yes No
 By whom: _____ Time: _____ A.M. _____ P.M.
 Report received by: _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>MATH PLAINS</u> <u>CH₄</u> <u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>GLORY HOLE</u> <u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>KILLIS</u> <u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Local Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0% CO, 20.8% O₂ AT TIME OF EXAM
TRAVEL WAYS D-BOX, P.C. OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By: [Signature] 32476 William Campbell 13544
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
 Countersigned: [Signature] 3352 Johnny Neely 33472
 Mine Manager—Mine Foreman Assistant Foreman Superintendent or Assistant

Richard N. [Signature] 1536-A Scott Halstead 37567

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-22 2010 Section or Area Examined Pumps
 Time of Examination: from 12:00 a.m. or 0:00 p.m. to 3:00 a.m. or 0:00 p.m.
 Was this report phoned to outside: Yes no
 By whom John Neely Time 2:45 A.M. P.M.
 Report received by Russell Dumroe
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u> <u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>Glory Hole</u> <u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Ellis</u> <u>0%</u>	<u>None Observed</u>	<u>None</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways, Power centers, D-Boxes OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dumroe 1536-A John Shroy 32476
 Preshift-Mine Examiner Certificate No. Assistant Foreman
 Countersigned T. Moore 33357 Scott Holstead 37567
 Mine Manager—Mine Foreman Assistant Foreman
John Neely 33472
 Superintendent or Assistant
Willie Campbell, 135440

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-22-10 20 Section or Area Examined Pumps
Time of Examination: from 8:00 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10. Handwritten entries: 1. NORTH MAINS, NONE OBSERVED, None; 2. Glory Hole, NONE OBSERVED, None; 3. Killis, NONE OBSERVED, None.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Handwritten entry: Good Air Movement.

Remarks: % CH4 0% CO 20.2% O2. TRAVELWAYS PC D-BOXES OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift-Mine Examiner Certificate No. 32426
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33757
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-23 2010 Section or Area Examined Pumpi
Time of Examination: from 7:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no X
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. Ellis	0%	N/A	none
2. Glory Hole	0%	N/A	none
3. North Main	0%	N/A	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH₄, 0% CO, 20.89% O₂ detected
Travelways - D.B.'s, Pumps clear at 8am

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Russell Campbell 175470 Certificate No. 32476
Preshift-Mine Examiner Assistant Foreman
Countersigned T. Moore 33327 Certificate No. 33472
Mine Manager-Mine Foreman Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman / Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-23 2010 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or (P.M.) to 3:00 a.m. or (P.M.)
Was this report phoned to outside: Yes no
By whom John Neely Time A.M. 2:40 (P.M.)
Report received by Russell Gurnoe
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% Ch₄, 20.8% O₂, 0 ppm CO at time of exam
TRavelways, Power Centers, D-Boxes OK at time of exam

Don Ull 1539A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gurnoe 1536-A Certificate No. _____
Preshift-Mine Examiner
Countersigned T. Moore 33357 Certificate No. _____
Mine Manager—Mine Foreman
Assistant Foreman

Scott Halstead 32476 Certificate No. _____
Assistant Foreman
Johnny Neely 37567 Certificate No. _____
33472
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-23-10 20 Section or Area Examined Pumps
Time of Examination: from 2:00 a.m. or 11:00 p.m. to 11:00 a.m. or 11:00 p.m.
Was this report phoned to outside: Yes no no no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>NORTH MAINS</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>GLORY HOLE</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>KILLS</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>GOOD AIR MOVEMENT</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4 0% CO 20.8% O2 - AT TIME EXAM
TRAVELWAYS D-BOXES P.C. OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift-Mine Examiner Certificate No. 5391
Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 33387
Assistant Foreman Certificate No. 32476
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-24 2010 Section or Area Examined Pumps
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no no X
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported			
Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>North Main</u>	<u>0%</u>	<u>N/A</u>	<u>none</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>N/A</u>	<u>none</u>
3. <u>Ellis</u>	<u>0%</u>	<u>N/A</u>	<u>none</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements			
Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0 ppm CO, 20.8% O₂ detected
Travellers, Pumps, D-Box detected

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell 1354 John [Signature] 32176
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.

Countersigned F. [Signature] 32239 John [Signature] 1599A
Mine Manager—Mine Foreman Assistant Foreman

Russell Dunnoe 1536A John L. Bickford 2617d Scott Halstead 37507
Superintendent or Assistant John J. Deely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-24 2010 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes [X] no
By whom John Bickford, John Neely Time A.M. 2:20 P.M.
Report received by Russell Gunnel (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include North Mains, Glory Hole, Ellis, all with 0% CH4 and 'None Observed'.

Air Measurements

Location CFM Location CFM

Good Air movement

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways, Power Centers, D-Boxes OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnel 1536-19 Preshift-Mine Examiner
Countersigned T. Moore 33359 Mine Manager-Mine Foreman
Assistant Foreman: John A. Bickford 72476
Assistant Foreman: Scott Halstead 37567
Superintendent or Assistant: Johnny Neely 33472
Willie Campbell 1354-22

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-24 2010 Section or Area Examined Pumps
Time of Examination: from 8:00 a.m. or 6:00 p.m. to 11:00 a.m. or 4:00 p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Table with 3 columns: Location, Violations and other Hazardous Conditions Observed and Reported, Action Taken. Rows include North Mains, Glory Hole, and Ellis, all with 0% violations and 'none' action taken.

Table for Air Measurements with columns for Location, CFM, Location, and CFM. Entry: Cool air Movement.

Remarks: CH4 0%, O ppm CO, 20.5% O2 Detected
Taped ways, D BOX, Pumps clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift-Mine Examiner
Countersigned [Signature] Mine Manager-Mine Foreman
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-24-10 Section or Area Examined Pump
Time of Examination: from 8:00 a.m. or (p.m.) to 11:00 a.m. or (p.m.)
Was this report phoned to outside: Yes no
By whom
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include North Mains, Glory Hole, Ellis, with 'NONE OBSERVED' and 'NONE' entries.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4, 0% CO, 20.8% O2. AT TIME OF EXAM
TRUCKWAYS CLEAR AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 22476
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33389
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-25-10 20 Section or Area Examined Pump
Time of Examination: from 3:00 p.m. to 6:00 p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10. Locations include North Mains, Glory Hole, Ellis. All violations listed as 'N/A' and actions as 'none'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Goos A-R Movement.

Remarks: O2 20.4%, O2 CO2, 20.8% O2 - Detected
Travelways, D-Box's, and clear at cross

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift Mine Examiner 1354-12
Countersigned [Signature] Mine Manager - Mine Foreman 32476
Assistant Foreman 33369

Superintendent or Assistant

John A. Bickel 261 Th Russell Gunnar 1536-A Scott Halstead 37567

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-25- 2010 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom John Bickford Time 2:25 P.M.
Report received by Russell Durrane
(Signed)

Violations and other Hazardous Conditions Observed and Reported			
Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>North mains</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
4. _____			
5. _____			
6. _____			
7. _____			
8. _____			
9. _____			
10. _____			

Air Measurements			
Location	CFM	Location	CFM
<u>Good Air movement</u>			

Remarks: 0% CH₄, 20.8% O₂, 0ppm CO at time of exam
Travelways, Power Centers, D-Boxes OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Durrane 1536-A John A. Bickford 33476
Pre-shift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
Countersigned T. Moore 22767 Scott Halstead 37667
Mine Manager—Mine Foreman Certificate No.
John A. Bickford 26176
Assistant Foreman
John A. Bickford
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-25-10 20____ Section or Area Examined Pumps
 Time of Examination: from 8:50 a.m. or (p.m.) to 11:00 a.m. or (p.m.)
 Was this report phoned to outside: Yes no
 By whom Brought out Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North MAINS CB</u>	<u>none</u>	<u>none</u>
2. <u>Coory Hole CB</u>	<u> </u>	<u> </u>
3. <u>Ellis CB</u>	<u> </u>	<u> </u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Coory Hole</u>	<u>20.8602</u>		
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: CB CUY CB CO 20.8602
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1539A Certificate No. [Signature] Assistant Foreman Certificate No. 32476
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 33329
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-26-10 Section or Area Examined Pump
Time of Examination: from 8:00 a.m. or p.m. to 9:20 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Entries include NORTH MAINS, GLOVE HOLE, and GHC Ellis, all with 'NONE' or 'NONE OBSERVED' noted.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4 0% CO 20.9% O2
TRAVELWAYS OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 32476
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33359
Assistant Foreman [Signature] Certificate No. 1842-A

Superintendent or Assistant

Russell Gunnoe 1536-A

Scott Halstead 37567

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

	<i>Location</i>	<i>Violations and other Hazardous Conditions Observed and Reported</i>	<i>Action taken</i>
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	11.	_____	_____
2.	_____	_____	12.	_____	_____
3.	_____	_____	13.	_____	_____
4.	_____	_____	14.	_____	_____
5.	_____	_____	15.	_____	_____
6.	_____	_____	16.	_____	_____
7.	_____	_____	17.	_____	_____
8.	_____	_____	18.	_____	_____
9.	_____	_____	19.	_____	_____
10.	_____	_____	20.	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	6.	_____	_____
2.	_____	_____	7.	_____	_____
3.	_____	_____	8.	_____	_____
4.	_____	_____	9.	_____	_____
5.	_____	_____	10.	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-26-2010 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include North MAINS, Glory Hole, Ellis, all with 0% CH4 and 'None Observed' violations, and 'Reported' actions.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways, Power Centers, D-Boxes OK at time of exam

Ben Wilson 1539A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell G. Moore Preshift-Mine Examiner
Countersigned T. Moore Mine Manager-Mine Foreman
Assistant Foreman Scott Halstead
Certificate No. 1536-A 37567

Superintendent or Assistant
Walter Campbell 13567A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content, Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content, Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-26 2010 Section or Area Examined Pumps
 Time of Examination: from 800 a.m. or pm to 1100 a.m. or pm
 Was this report phoned to outside: Yes No
 By whom Brought out Time A.M. P.M.
 Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>North Meins</u>	<u>0%</u>	<u>N/A</u>	<u>none</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>N/A</u>	<u>none</u>
3. <u>Ellis</u>	<u>0%</u>	<u>N/A</u>	<u>none</u>
4. <u> </u>	<u> </u>	<u> </u>	<u> </u>
5. <u> </u>	<u> </u>	<u> </u>	<u> </u>
6. <u> </u>	<u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: 0% CH₄, 0ppm CO, 20.8% O₂ detected
Track/Travelways D-Box, Power centers & Pumps clear at Exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell 13544 Assistant Foreman Certificate No.
 Countersigned T. M. M... Mine Foreman 33357
John Richard 21171 Superintendent or Assistant

Use Indefilble
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-27 2010 Section or Area Examined Pumps

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes no

By whom Time A.M. P.M.

Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows 1-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Goos, Air Movement.

Remarks: 0% CH4, 0 ppm CO, 20.8% O2 detected. Tracks/Travelways cleared Exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By: Wilton Campbell, Preshift-Mine Examiner, Certificate No. 13542. Assistant Foreman: T. Moore, Certificate No. 33359. Superintendent or Assistant: Dan Miller, Certificate No. 15377.

John B. Buckford 21176

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3.27.10 Section or Area Examined Pumps

Time of Examination: from 1200 a.m. or 0 p.m. to 300 a.m. or 0 p.m.

Was this report phoned to outside: Yes no

By whom _____ Time _____ A.M. _____ P.M.

Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH ₄	Violation or Hazardous Condition	Action Taken
1.	North Main	0%	None observed	None
2.	Flour Hob	0%	None observed	None
3.	Elles	0%	None observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH₄ 0% CO & 20.8% O₂ detected

Trenchways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Beckford 26176
Preshift-Mine Examiner Certificate No.

Countersigned T. Moore 33327
Mine Manager—Mine Foreman Assistant Foreman Certificate No.

[Signature]
Superintendent or Assistant

37088-08

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-27-10 20. Section or Area Examined Ramps
Time of Examination: from 8 a.m. or Am. to 1100 a.m. or pm.
Was this report phoned outside: Yes no
By whom Brought outside Time AM P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH ₄	Violation or Hazardous Condition	Action Taken
1.	<u>Nearby Main</u>	<u>0%</u>	<u>none observed</u>	
2.	<u>Quarry Hall</u>	<u>0%</u>	<u>none observed</u>	
3.	<u>Ellis</u>	<u>0%</u>	<u>none observed</u>	
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>			

Remarks: 0% CH₄ 0 ppm CO 20.8% O₂ at time of exam
Trucks always clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Bruce Collins Certificate No. 1343-A
Countersigned T. Masone Mine Manager—Mine Foreman Certificate No. 33327
Jack Masone Assistant Foreman Certificate No. 58699
57723
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-28-10 20 Section or Area Examined Pumped
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Table with 4 columns: Location, Violations and other Hazardous Conditions Observed and Reported, Violation or Hazardous Condition, Action Taken. Rows 1-10.

Table with 4 columns: Location, CFM, Location, CFM under the heading Air Measurements.

Remarks: 20.8% O2 0% CH4 0 ppm CO at time of exam
Timberways clean at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift-Mine Examiner Certificate No. 1543-11
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33357
Assistant Foreman [Signature] Certificate No. 38699
Superintendent or Assistant [Signature] Certificate No. 37713, 33472

John A. Burkhard 2017

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

Examinations for Methane in Working Places

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	11.	_____	_____	_____
2.	_____	_____	_____	12.	_____	_____	_____
3.	_____	_____	_____	13.	_____	_____	_____
4.	_____	_____	_____	14.	_____	_____	_____
5.	_____	_____	_____	15.	_____	_____	_____
6.	_____	_____	_____	16.	_____	_____	_____
7.	_____	_____	_____	17.	_____	_____	_____
8.	_____	_____	_____	18.	_____	_____	_____
9.	_____	_____	_____	19.	_____	_____	_____
10.	_____	_____	_____	20.	_____	_____	_____

Examinations for Methane in Return Aircourses

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	6.	_____	_____	_____
2.	_____	_____	_____	7.	_____	_____	_____
3.	_____	_____	_____	8.	_____	_____	_____
4.	_____	_____	_____	9.	_____	_____	_____
5.	_____	_____	_____	10.	_____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

PRESHIFT-MINE EXAMINER'S REPORT

Use Indelible Pencil or Ink

Report shall be signed when made

Date of Examination 3-28-10 Section or Area Examined Pumps
Time of Examination: from 2:00 a.m. or 3:00 a.m. or 4:00 a.m. or 5:00 a.m. or 6:00 a.m. or 7:00 a.m. or 8:00 a.m. or 9:00 a.m. or 10:00 a.m. or 11:00 a.m. or 12:00 p.m. or 1:00 p.m. or 2:00 p.m. or 3:00 p.m. or 4:00 p.m. or 5:00 p.m. or 6:00 p.m. or 7:00 p.m. or 8:00 p.m. or 9:00 p.m. or 10:00 p.m. or 11:00 p.m. or 12:00 a.m.
Was this report planned to outside? Yes No
By whom John H. Befford Time 2:00 P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. North Main	0% ch4 None Observed	None
2. Glory Hole	0% None Observed	None
3. Ellis	0% None Observed	None
4.		
5.		
6.		
7.		
8.		
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% ch4, 0% CO & 20.8% O2 detected

Travelways clear at time of exam

Dlen Mhm 1539A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John H. Befford 26176 Preshift-Mine Examiner Certificate No. 33359
Countersigned T. M. M... Mine Manager - Mine Foreman
Assistant Foreman
Assistant Foreman
John J. Peely 33472
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-28-10 Section or Area Examined Pumps
Time of Examination: from 8:00 a.m. or 9:00 a.m. to 11:00 a.m. or 6:00 p.m.
Was this report phoned to outside: Yes no X
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10. Handwritten entries: 1. North MAINS OB, 2. Gary Hole OB, 3. Ellis OB. All violations listed as 'none'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Handwritten entry: Good A'ment.

Remarks: OB CH4, OB CO, 20.8802
TRAVEL WAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dan [Signature] 153972 Assistant Foreman Certificate No. 32476
Countersigned T. [Signature] Mine Manager - Mine Foreman Certificate No. 33254
Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date ----- Shift ----- Area or Section -----

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. -----	-----	-----
2. -----	-----	-----
3. -----	-----	-----
4. -----	-----	-----
5. -----	-----	-----
6. -----	-----	-----
7. -----	-----	-----
8. -----	-----	-----

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. -----	-----	-----	11. -----	-----	-----
2. -----	-----	-----	12. -----	-----	-----
3. -----	-----	-----	13. -----	-----	-----
4. -----	-----	-----	14. -----	-----	-----
5. -----	-----	-----	15. -----	-----	-----
6. -----	-----	-----	16. -----	-----	-----
7. -----	-----	-----	17. -----	-----	-----
8. -----	-----	-----	18. -----	-----	-----
9. -----	-----	-----	19. -----	-----	-----
10. -----	-----	-----	20. -----	-----	-----

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. -----	-----	-----	6. -----	-----	-----
2. -----	-----	-----	7. -----	-----	-----
3. -----	-----	-----	8. -----	-----	-----
4. -----	-----	-----	9. -----	-----	-----
5. -----	-----	-----	10. -----	-----	-----

Number of Bolts Tested -----
Number of Bolts Torqued Above Range ----- Below Range -----

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken -----

Remarks (Statement as to General Conditions of Mine or Area of Mine) -----

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-29-10 20 Section or Area Examined Pumps
Time of Examination: from 3:00 or p.m. to 6:00 or p.m.
Was this report phoned to outside: Yes No
By whom brought out Time A.M. P.M.
Report received by (Signed)

Table with 3 columns: Location, Violation or Hazardous Condition Observed and Reported, Action Taken. Contains handwritten entries for locations like 'AIR MAINS', 'Cory Hole', and 'Ellis'.

Table for Air Measurements with columns for Location, CFM, Location, CFM. Contains handwritten entry 'Good Air int'.

Remarks: OB CHY OB CO 2018802
TRAULRUPS etc

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Certificate No. 1539A
Assistant Foreman [Signature] Certificate No. 32476
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33357
Assistant Foreman [Signature] Certificate No. 33472
Superintendent or Assistant [Signature]

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-29-10 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or 3:00 a.m. or
Was this report phoned to outside: Yes [x] no
By whom J. Neely Time A.M. 2:47 P.M.
Report received by S. Halstead (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include N. Mains, Glory Hole, and Ellis, all with 0% CH4 and None Observed.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4, 20.8% O2, 0ppm CO Detected at EXAM
Power Centers, D-Box's, TRACK & TRAVELWAYS Clear at EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead Preshift-Mine Examiner Certificate No. 37567
Countersigned T. M... Mine Manager-Mine Foreman Certificate No. 33359
Johnny Neely Assistant Foreman Certificate No. 32476
Johnny Neely Superintendent or Assistant Certificate No. 33472

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-29-10 20. Section or Area Examined Pumps
Time of Examination: from 8:00 a.m. or 11:00 p.m. to 11:00 a.m. or 8:00 p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>NORTH MAINS</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>Gloxy Hole</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>Kills</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 90CH4 0% CO 20.8% O2 AT TIME OF EXAM
TRAVELWAY OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 32476
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 83389
[Signature] Assistant Foreman Certificate No. 135412
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

Examinations for Methane in Working Places

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	11.	_____	_____	_____
2.	_____	_____	_____	12.	_____	_____	_____
3.	_____	_____	_____	13.	_____	_____	_____
4.	_____	_____	_____	14.	_____	_____	_____
5.	_____	_____	_____	15.	_____	_____	_____
6.	_____	_____	_____	16.	_____	_____	_____
7.	_____	_____	_____	17.	_____	_____	_____
8.	_____	_____	_____	18.	_____	_____	_____
9.	_____	_____	_____	19.	_____	_____	_____
10.	_____	_____	_____	20.	_____	_____	_____

Examinations for Methane in Return Aircourses

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	6.	_____	_____	_____
2.	_____	_____	_____	7.	_____	_____	_____
3.	_____	_____	_____	8.	_____	_____	_____
4.	_____	_____	_____	9.	_____	_____	_____
5.	_____	_____	_____	10.	_____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-30 2010 Section or Area Examined Pumps
Time of Examination: from 3:00 a.m. or p.m. to 6:55 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
<u>North Mains</u>	<u>w/o</u>	<u>none</u>
<u>Glory Hole</u>	<u>w/o</u>	<u>none</u>
<u>Ellis</u>	<u>w/o</u>	<u>none</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4, 0ppm CO, 20.8% O2 detected
Travelways, D-Box's, Powercenters & Pumps clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Willie Campbell 13540
Preshift-Mine Examiner Certificate No.
Countersigned T. M. Moore 33359
Mine Manager—Mine Foreman
Assistant Foreman
Johnny Neely 33472
Superintendent or Assistant

Russell Gannon 1536-A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-30-20 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom John Neely Time 2:50 P.M.
Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include N. MAINS, Glory Hole, Ellis, all with 0% CH4 and None Observed, Reported.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4, 20.8% O2, 0 ppm CO at time of exam
TRAVELWAYS, Power Centers, D-Boxes OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe Preshift-Mine Examiner Certificate No. 1536-A
Countersigned T. M. Mine Manager - Mine Foreman Certificate No. 33357
Assistant Foreman Scott Halstead Certificate No. 32476
Superintendent or Assistant Johnny Neely Certificate No. 37567, 33472

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-30-10 20. Section or Area Examined Pumps
Time of Examination: from 8:00 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes X no
By whom Campbell, Steve Time A.M. 11:00 P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10. Handwritten entries: 1. N. MAINS C44 CE, none, none; 2. Gory Hole CE, none, none; 3. Ellis CE, none, none.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Handwritten entry: Good Lion A.

Remarks: CE C44 CE CO 20.86 CE
Travel was OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell Preshift-Mine Examiner Certificate No. 1354-1A
Countersigned T. W. Moore Mine Manager-Mine Foreman Certificate No. 33359
Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-31 2010 Section or Area Examined Pumps
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Location	Violations and other Hazardous Conditions Observed and Reported	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u>	<u>CH₄</u>	<u>N/A</u>	<u>none</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>N/A</u>	<u>none</u>
3. <u>Ellis</u>	<u>0%</u>	<u>N/A</u>	<u>none</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements		Air Measurements	
Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0ppm CO, 20.8% O₂ Detected
Travelways Clearcut Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell 135410
Preshift-Mine Examiner Certificate No.
Countersigned T. Moore 33359
Mine Manager—Mine Foreman Assistant Foreman Certificate No.
Dan Miller 15397B
Assistant Foreman Superintendent or Assistant

Russell Dunne 15367A John Bickel 26171 Scott Halstead 37567

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 3-31- 2010 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom John Bickford, John Neely Time 2:30 P.M.
Report received by Russell Gurnee
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North mains</u> <u>CH₄ 0%</u>	<u>None Observed</u>	<u>Reported</u>
2. <u>Glory Hole</u> <u>0%</u>	<u>None Observed</u>	<u>Reported</u>
3. <u>Ellis</u> <u>0%</u>	<u>None Observed</u>	<u>Reported</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 20.8% O₂, 0ppm CO at time of exam
Travelways, Power Centers, D-Boxes OK at time of exam

Don Munn 1539A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gurnee 1536-A John Neely 32476
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
 Countersigned T. Munn 35359 Scott Halstead 37567
Mine Manager—Mine Foreman Assistant Foreman
John Bickford 26176
Superintendent or Assistant
Johnny Neely 33472

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 3-31-10 20__ Section or Area Examined Pumps
 Time of Examination: from 8:00 a.m. or 8:00 p.m. to 2:00 a.m. or 2:00 p.m.
 Was this report phoned to outside: Yes ___ no ✓ Time ___ A.M. ___ P.M.
 By whom _____
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>NORTH MAINS</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>GLORY HOLE</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>KILLIS</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4, 0% CO, 20.7% O2 AT TIME OF EXAM
TRAVELWAYS OK P.C. D-BOX OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 32476 Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] Mine Manager—Mine Foreman Assistant Foreman _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-1-10 20... Section or Area Examined Pump
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes _____ no _____ Time _____ A.M. _____ P.M.
 By whom _____
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>NORTH MAINS</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>Glory Hole</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>Ellis</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Good, O₂ 20.8% O₂ AT TIME OF EXAM
HAULWAYS, D-BOXES, POWER CENTER O.K. AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 32476
 Countersigned [Signature] Mine Manager—Mine Foreman Assistant Foreman [Signature] Certificate No. 15399
 Superintendent or Assistant [Signature]

4-1-10 Russell Avenue 1536-A Scott Holstad 37567

Use Indefinible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-1 20 10 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom John Bickford, Mike Elswick Time A.M. 2:30 P.M.
Report received by Russell Dunning (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include North Mains, Glory Hole, Ellis, all with 0% CH4 and 'None Observed' violations, and 'Reported' actions.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks:

0% CH4, 20.8% O2, Oppen CO at time of exam
Travelways, Power Centers, D-Boxes OK at time of exam

Blair Wilson 1539-A

John Elledge 32476

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dunning 1536-A Certificate No. 33359
Countersigned T. Elwood Mine Manager-Mine Foreman
Assistant Foreman Scott Halstead 31567
Assistant Foreman John Bickford
Superintendent or Assistant Michael Elswick 3

28176
31521

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported		
Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 4-1-10 20. Section or Area Examined Pumps
 Time of Examination: from 8:00 a.m. or pm to 11:00 a.m. or pm
 Was this report phoned to outside: Yes no no X Time A.M. P.M.
 By whom
 Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. North mains <u>CH4</u>	<u>none</u>	<u>none</u>
2. Gray Hole <u>OG</u>	<u>none</u>	<u>none</u>
3. Ellis <u>OG</u>	<u>none</u>	<u>none</u>
4. <u> </u>	<u> </u>	<u> </u>
5. <u> </u>	<u> </u>	<u> </u>
6. <u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Point</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: OG CH4, OG CO, 20, 8202
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By D. M. Miller Preshift-Mine Examiner Certificate No. 15399
 Countersigned T. J. Moore Mine Manager—Mine Foreman Certificate No. 33359
 Assistant Foreman Superintendent or Assistant

Use Indefilible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-1-10 20. Section or Area Examined Pumps
 Time of Examination: from 8:00 a.m. or (p.m.) to 11:00 a.m. or (p.m.)
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>NORTH MAINS</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>GLORY HOLE</u>	<u>NONE OBSERVED</u>	<u> </u>
3. <u>ELLIS</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0% CO, 20.8% O₂ AT TIME OF EXAM
TRAVEL WAYS OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 32476
 Countersigned T. Moore Mine Manager—Mine Foreman Certificate No. 33359
 Assistant Foreman _____ Superintendent or Assistant _____

[Signature] 1579A

Use Indefinite Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No. _____

Mine Foreman-Mine Manager

Certificate No. _____

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-2-10 20: Section or Area Examined Ramps

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes no X

By whom Time A.M. P.M.

Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for 'north main 0', 'C602 Hole', and 'WHS 076 C44'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air'.

Remarks: 076 chf 076 CO 20.802

Transects ok

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1539A Certificate No. 32476 Assistant Foreman

Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33357

Russell Dunnoe 1536A Superintendent or Assistant Mike Ekanick 31521 Scott Holstead 37567

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 4-2- 2010 Section or Area Examined Pumps
 Time of Examination: from 12:00 a.m. or 0 p.m. to 3:00 a.m. or 0 p.m.
 Was this report phoned to outside: Yes no
 By whom Mike Elswick Time A.M. 2:20 P.M.
 Report received by Russell Dunsell (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North MAINS</u> <u>CH4 0%</u>	<u>None Observed</u>	<u>Reported</u>
2. <u>Glory Hole</u> <u>0%</u>	<u>None Observed</u>	<u>Reported</u>
3. <u>Ellis</u> <u>0%</u>	<u>None Observed</u>	<u>Reported</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4, 20.8% O2, Oppm CO at time of exam
TRAVELWAYS, Power Centers, D-Boxes OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dunsell 1536-A
Preshift Mine Examiner 31571 Certificate No.
 Countersigned Michael Dunsell Scott Halstead Assistant Foreman
Mine Manager—Mine Foreman Certificate No. 37567
T. Moore Assistant Foreman 33359
Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 4-2 2010 Section or Area Examined Pumps
Time of Examination: from 8:00 a.m. or 9 a.m. to 11:00 a.m. or 12:00 p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows 1-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement.

Remarks: 0% CH4, 0 ppm CO, 20.8% O2 detected
Travelways/Track, D-Boxes, Power Lines & Pumps clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1354A
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 53389
[Signature] Assistant Foreman Certificate No. 1539A
[Signature] Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 4-3-10 20. Section or Area Examined Reps
 Time of Examination: from 3:00 a.m. or p.m. to 4:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North Mans ^{CH4} _{OK}</u>	<u>none</u>	<u>none</u>
2. <u>Gray hole _{OK}</u>	<u>/</u>	<u>/</u>
3. <u>Ellis _{OK}</u>	<u>/</u>	<u>/</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: OK CH4 OK CO 20.8% OK
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 15392 William Campbell Assistant Foreman 135472 Certificate No.
 Countersigned T. M. [Signature] 33359 Johnny Neely Assistant Foreman 33472
 _____ Superintendent or Assistant

Russell Munroe 1536-A Mike Glink 31521 Scott Halstead 37567

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 4-3- 20¹⁰ Section or Area Examined Pumps
 Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom John Neely, Mike Elsworth Time 2:15 P.M.
 Report received by Russell Dunne
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>North mains</u>	<u>0%</u>	<u>None Observed</u>	<u>Reported</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>None Observed</u>	<u>Reported</u>
3. <u>Ellis</u>	<u>0%</u>	<u>None Observed</u>	<u>Reported</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 20.8% O₂, 0ppm CO at time of exam
TRAVELWAYS, Power Centers, D-Boxes OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dunne Preshift-Mine Examiner Certificate No. 1536-A
 Countersigned _____ Mine Manager—Mine Foreman Assistant Foreman
 _____ Assistant Foreman
 _____ Superintendent or Assistant
 Mike Elsworth Assistant Foreman Certificate No. 31521
 Scott Halstead
 Johnny Neely Certificate No. 37567
33472

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 4-3-10 20 Section or Area Examined Pumps
 Time of Examination: from 800 a.m. or 800 p.m. to 1100 a.m. or 1100 p.m.
 Was this report phoned to outside: Yes _____ no X
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>N. MAINS</u> <u>CH4</u> <u>0%</u>	<u>NONE</u>	<u>NONE</u>
2. <u>Core Hole</u> <u>0%</u>	<u>NONE</u>	<u>NONE</u>
3. <u>ELLIS</u> <u>0%</u>	<u>NONE</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4 0% CO 20.8% O2
TRAVEL WAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 15329 William Campbell 133477
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
 Countersigned _____ Mine Manager—Mine Foreman
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 4/4 20 10 Section or Area Examined Pumps
 Time of Examination: from 8:00 a.m. or 11:00 p.m. to 11:00 a.m. or 8:00 p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>N. MAINS</u>	<u>chy 0%</u> <u>None Observed</u>	<u>None</u>
2. <u>Clay Hole</u>	<u>0%</u> <u>None Observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>0%</u> <u>None Observed</u>	<u>None</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Lead Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% chy 0% CO + 20.8% O2 checked

Travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John B. Budjed 26176 [Signature]
 Preshift-Mine Examiner Certificate No. Assistant Foreman
 Countersigned _____ Mine Manager--Mine Foreman
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Certificate No. 32476
Certificate No. 33472

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 4-5 10 Section or Area Examined Pumps
Time of Examination: from 3:00 or p.m. to 6:00 or p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0% CO & 20.8% O₂ detected at time of exam

Travelways clear at time of exam.

Pumps at 12, 17, 36, 38, 40 + 137 Brds.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John B. Buckford Certificate No. 26176
 Preshift-Mine Examiner
 Countersigned Scott Halstead Mine Manager—Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

32476
Certificate No.
31521
37567

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 4-5 2010 Section or Area Examined PUMPS
 Time of Examination: from 2:00 a.m. or p.m. to 3:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Mike Elswick Time 3:30 A.M. P.M.
 Report received by Charles James 31292
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. North Mains <u>CH4 0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. Glory Hole <u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. Ellis <u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4, 20.8% O2, 0ppm CO detected at EXAM
TRACK & TRAVELWAYS Clean
Power Centers & D-Boxes Clean

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead Pre-shift-Mine Examiner Certificate No. 37567
 Assistant Foreman _____ Certificate No. _____
 Countersigned _____ Mine Manager—Mine Foreman
 Assistant Foreman _____
 Superintendent or Assistant _____

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant