

started 11-5-09

PRESHIFT - ONSHIFT and DAILY REPORT

Longwall Construction

Company Performance Coal CO

Mine UBB

SECTION Longwall out by construction

LOCATION Utoma Raleigh W Va
Post Office County State

Finished 11-22-09

Form 6-1489
(March 1970)

Bureau No. 4 R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-5-09 20 Section or Area Examined Low construction
Time of Examination: from 800 a.m. or p.m. to 1100 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for O2, CH4, SO2, and work area.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Airway'.

Remarks: O2 CH4, O2 CO, 20.8202
Track, Travelways, OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 15394
Countersigned [Signature] Mine Manager-Mine Foreman
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-6-09 20 Section or Area Examined Longwall Construction
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include D-Bores, Chargers, 255 Chargers, Work Area.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air movement.

Remarks: O2 CH4, O2 CO, 20.82 O2
PC, Chargers, D-Bores OK
Track, Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 153489 Certificate No.
Assistant Foreman Certificate No.
Countersigned [Signature] 35000 Mine Manager-Mine Foreman
Assistant Foreman
Superintendent or Assistant

John Bickford 26172

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-6-09 20 Section or Area Examined Longwall Const.
Time of Examination: from 12:00 or p.m. to 3:00 or p.m.
Was this report phoned to outside: Yes no
By whom John Beckford Time A.M 3:10 P.M.
Report received by [Signature] 32261 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include D-Boxer, Charger, 255 chargers, Work Area.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good air movement.

Remarks: 0% CH4 0% CO 20.8% O2 detected. Track, travelways, chargers, power lines safe at exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Beckford 26176 Preshift-Mine Examiner Certificate No.
Countersigned [Signature] 37000 Mine Manager-Mine Foreman Assistant Foreman Certificate No.
Mike Bailey 27085 Assistant Foreman Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 1-6-09 Shift Day Area or Section LW Const

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. <u>D Boxes</u>	<u>None</u>	<u>Reported</u>
2. <u>184 Charger</u>	}	}
3. <u>255 Charger</u>		
4. <u>5eep Charger</u>		
5. <u>WORK Area</u>		
6. _____		
7. _____		
8. _____		

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. <u>work Area</u>	<u>9:00 AM</u>	<u>.0%</u>	11. _____		
2. _____	<u>1:00 PM</u>	<u>.0%</u>	12. _____		
3. _____			13. _____		
4. _____			14. _____		
5. _____			15. _____		
6. _____			16. _____		
7. _____			17. _____		
8. _____			18. _____		
9. _____			19. _____		
10. _____			20. _____		

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____			6. _____		
2. _____			7. _____		
3. _____			8. _____		
4. _____			9. _____		
5. _____			10. _____		

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) walk ways & travel ways

in fair shape
M. H. Pender
Assistant Mine

37004
Certificate No.

Carl [Signature]
Mine Foreman-Mine Manager

380000
Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-6-09 20 Section or Area Examined L121111
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside? Yes no
By whom Time A.M. 1100 P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Includes handwritten entries for D-Box, Chargers, 2SS Charges, and work Area.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Includes handwritten entry 'Good Air now'.

Remarks: O2 CH4 O2 CO 208202
Track Trailing OK.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 21085
Countersigned Assistant Foreman Certificate No. 39000
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date H-7-09 Shift Day Area or Section LW Const

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. <u>1 Boxes</u>	<u>None</u>	<u>Reported</u>
2. <u>184 charger</u>	}	}
3. <u>255 charger</u>		
4. <u>WORK AREA</u>		
5. _____		
6. _____		
7. _____		
8. _____		

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. <u>WORK AREA</u>	<u>9:05 AM</u>	<u>1.0%</u>	11. _____		
2. _____	<u>1:00 PM</u>	<u>1.0%</u>	12. _____		
3. _____			13. _____		
4. _____			14. _____		
5. _____			15. _____		
6. _____			16. _____		
7. _____			17. _____		
8. _____			18. _____		
9. _____			19. _____		
10. _____			20. _____		

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____			6. _____		
2. _____			7. _____		
3. _____			8. _____		
4. _____			9. _____		
5. _____			10. _____		

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) walkways & Roadway

clear at time of exam

Went Fudge Assistant Mine 37004 Certificate No. [Signature] Mine Foreman-Mine Manager J. [Signature] Certificate No. [Signature] Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-7-2009 Section or Area Examined L/Wall const.
Time of Examination: from 1200 a.m. or (p.m) to 300 a.m. or (p.m)
Was this report phoned to outside: Yes [X] no
By whom J. Weeley Time A.M 244 P.M
Report received by George Curry 27429 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: D-Bel 0% CH4 none observed, none taken.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Local Air Movement.

Remarks: 0% CH4 - 0% CO2 20.8% O2 tracks, travelways clean at all

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Deely 33472 Certificate No.
Countersigned [Signature] 354604 Assistant Foreman Certificate No.
Mike Bailey 27085 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-7 2009 Section or Area Examined Long wall Construction
 Time of Examination: from 8:30 a.m. or (p.m.) to 11:30 a.m. or (p.m.)
 Was this report phoned to outside: Yes (X) no _____
 By whom Mike Bailey Time 11:20 A.M. P.M.
 Report received by Greg Cole 1947-A
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>D-Boxes</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
2. <u>Chargers</u>	<u>0%</u>	<u>"</u>	<u>"</u>
3. <u>255 charger</u>	<u>0%</u>	<u>"</u>	<u>"</u>
4. <u>Work Area</u>	<u>0%</u>	<u>"</u>	<u>"</u>
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄ 20.8% O₂ Oppm C.O. Track Travelways Clear
At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey 27085 Assistant Foreman Certificate No. _____
 Countersigned Greg Cole 1947-A Mine Manager—Mine Foreman Certificate No. _____
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-6 2009 Section or Area Examined 1st Conat.
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D Box</u>	<u>0% CH₄ None observed</u>	<u>Reported</u>
2. <u>Charger</u>	<u>" "</u>	
3. <u>Work Area</u>	<u>" "</u>	
4. <u>255 Charger</u>	<u>" "</u>	
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄ 20.8% O₂ 0 CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Reilly Preshift-Mine Examiner Certificate No. 27085
Countersigned Charles [Signature] Mine Manager—Mine Foreman Assistant Foreman Certificate No. 33472
Johnny Reilly Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-8 2099 Section or Area Examined L1W Const.
 Time of Examination: from 12 a.m. or p.m. to 6 a.m. or 6 p.m.
 Was this report phoned to outside: Yes no
 By whom John Neely Time A.M. 245
 Report received by Jay Stewart 39199
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D-Box</u> <u>0% CH4</u>	<u>none observed</u>	<u>none</u>
2. <u>Charger</u>	<u>⚡</u>	<u>⚡</u>
3. <u>Work Area</u>	<u>⚡</u>	<u>⚡</u>
4. <u>255 Charger</u>	<u>⚡</u>	<u>⚡</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4, 0% CO, 20.8% O2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John Neely 33472
 Preshift-Mine Examiner Certificate No.

Countersigned Jay Stewart _____
 Mine Manager—Mine Foreman Assistant Foreman Certificate No.

Mike Bailey _____
 Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-8 2029 Section or Area Examined Long wall construction
Time of Examination: from 8:30 a.m. or P.M. to 11:30 a.m. or P.M.
Was this report phoned to outside: Yes no
By whom Mike Bailey Time A.M. 10:40 P.M.
Report received by [Signature] 1947-A
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. D-Box	0%	None observed	None
2. Chargers	0%	" "	" "
3. work Area	0%	" "	" "
4. 255 charger	0%	" "	" "
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH₄ 20.8% O₂ 0ppm C.O. Track Travelways
Clear At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Mike Bailey 27025 Certificate No. Assistant Foreman Certificate No.
Countersigned [Signature] Mine Manager—Mine Foreman
Assistant Foreman
Superintendent or Assistant

11/08/47 Col 1947-A

Use Indefilible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman/Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-9 2009 Section or Area Examined LA Const.
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D-Basis</u>	<u>None Observed</u>	<u>Reported</u>
2. <u>Charges</u>	<u>" "</u>	<u>"</u>
3. <u>Work Area</u>	<u>" "</u>	<u>"</u>
4. <u>255 Charges</u>	<u>" "</u>	<u>"</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Coal Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4 20.8% O2 0 CO
Track Translamps OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
Countersigned Arthur Cook Mine Manager—Mine Foreman Assistant Foreman Certificate No. 380000
Johnny Neely 33472 Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 11-9-09 Shift Day Area or Section LW Const

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. <u>0 Boxes</u>	<u>None</u>	<u>Reported</u>
2. <u>184 Charger</u>	}	}
3. <u>255 Charger</u>		
4. <u>WORK AREA</u>		
5. _____		
6. _____		
7. _____		
8. _____		

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. <u>WORK AREA</u>	<u>10%</u>	<u>9:00 AM</u>			
2. _____	<u>10%</u>	<u>1:00 PM</u>			
3. _____			13. _____		
4. _____			14. _____		
5. _____			15. _____		
6. _____			16. _____		
7. _____			17. _____		
8. _____			18. _____		
9. _____			19. _____		
10. _____			20. _____		

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____			6. _____		
2. _____			7. _____		
3. _____			8. _____		
4. _____			9. _____		
5. _____			10. _____		

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) walkways & handways

Man P. P. P. Assistant Mine Certificate No. 37004 Carl Cook Mine Foreman-Mine Manager Certificate No. 35000 Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-9 2009 Section or Area Examined H/W Construct

Time of Examination: from 12:00 a.m. or P.M. to 3:00 a.m. or P.M.

Was this report phoned to outside: Yes no no X

By whom _____ Time _____ A.M. _____ P.M.

Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D. Boxes</u>	<u>None observed</u>	<u>Reported</u>
2. <u>Chargers</u>	<u>" "</u>	<u>"</u>
3. <u>Work Area</u>	<u>" "</u>	<u>"</u>
4. <u>255 Charger</u>	<u>" "</u>	<u>"</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4 0% CO 20.8 O2
TRACK, TRACKWAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely Certificate No. 33472
Preshift Mine Examiner Assistant Foreman Certificate No. _____

Countersigned Carl [Signature] Mine Manager—Mine Foreman Certificate No. _____

Phil Bailey Assistant Foreman Certificate No. 27085
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-9 2009 Section or Area Examined _____
 Time of Examination: from 11:30 a.m. or 9 p.m. to 11:30 a.m. or 6:00 p.m.
 Was this report phoned to outside: Yes _____ no _____
 By whom Mike Bailey Time 11:10 A.M. _____ P.M.
 Report received by Greg Cole 1247-A
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Ch ₄	Violation or Hazardous Condition	Action Taken
1.	D-Boxes	0%	NONE OBSERVED	NONE
2.	Chargers	0%	"	"
3.	Work Area	0%	"	"
4.	255 Charger	0%	"	"
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH₄ 20.8% O₂ 0ppm C.O.
Track, Travelways, OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Freshift-Mine Examiner Certificate No. 27085
 Countersigned Greg Cole 1247-A Mine Manager—Mine Foreman Assistant Foreman Certificate No. _____
 Assistant Foreman Superintendent or Assistant

Greg Cole 1247-A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-10 2009 Section or Area Examined L/W Construct

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes no

By whom _____ Time _____ A.M. _____ P.M.

Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D. Boxes</u>		<u>Reported</u>
2. <u>CHARGERS</u>		
3. <u>Work Area</u>	<u>Idle</u>	
4. <u>255 charger</u>	<u>No Power</u>	
5. _____		
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			

Remarks: 0% CH₄ 0% CO 20.8 O₂ at time of Exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Deely 33472 Certificate No. Assistant Foreman Certificate No.

Countersigned [Signature] Mine Manager—Mine Foreman 390000

Mike Bailey Assistant Foreman 27085 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-10-09 20____ Section or Area Examined LIVAN Consta
 Time of Examination: from 8:32 a.m. or 9:32 p.m. to 11:32 a.m. or 11:32 p.m.
 Was this report phoned to outside: Yes no
 By whom Mike Bailey Time 10:28 A.M. P.M.
 Report received by Steve (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D-Bikes</u>		
2. <u>Charger</u>	<u>NO DIE</u>	
3. <u>Work Area</u>		
4. <u>255 charger</u>	<u>NO POWER</u>	
5.		
6.		
7.		
8.		
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Maxima</u>			

Remarks: OT CHY oppm co, 22-01102 detected at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
 Assistant Foreman Certificate No. _____
 Countersigned Steve Mine Manager—Mine Foreman Certificate No. 27060
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-11 20:09 Section or Area Examined L.W. Carnot, Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m. Was this report phoned to outside: Yes no Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for D-Base, Charges, Work Area, and 255 Charges.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry for Road Air Movement.

Remarks: D% CH+ 20.8% O2 0 CO Track Transways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 27085 Assistant Foreman [Signature] Certificate No. 33472 Countersigned [Signature] Mine Manager-Mine Foreman Assistant Foreman [Signature] Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-11-09 20 Section or Area Examined 2/ Wall construction
 Time of Examination: from 1200 a.m. or P.M. to 300 a.m. or P.M.
 Was this report phoned to outside: Yes no
 By whom J. Maly Time A.M. 3:00 P.M.
 Report received by Rick Foster
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
<u>Hoboken, Okchy</u>	<u>none observed</u>	<u>none</u>

Air Measurements

Location	CFM	Location	CFM
<u>Good air movement</u>			

Remarks: 20.8% O₂, 0.6% O₂, 0% CO₂, track, trackways, power cables, sweep chaper show at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely 33472 Rick Foster 2875L
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
 Countersigned John Cook 39000-08
 Mine Manager—Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-11-09 20. Section or Area Examined Wall construction
Time of Examination: from 8:30 a.m. or 6:00 to 11:00 a.m. or 6:00 p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by Proyhted (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>work Area O2C4</u>	<u>none observed</u>	<u>none</u>
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Airment</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: O2C4 O2 CO 20.8 20.2
scoop PC Charges clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 15377
Preshift-Mine Examiner Assistant Foreman Certificate No.
Countersigned [Signature] Certificate No. 3906000
Mine Manager—Mine Foreman
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-12-07 20 Section or Area Examined L-1 Wash Constructions
Time of Examination: from 3:32 a.m. or p.m. to 9:00 a.m. or p.m.
Was this report phoned to outside: Yes no [checked]
By whom Gough OVT Time 5:20 AM P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Row 1: D-Goxe's, 0%, None observed, None. Row 2: Charger's, 0%, "", "". Row 3: Work Area, 0%, "", "". Row 4: 255 Charger, 0%, "", "".

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement, blank, blank, blank.

Remarks: 0% CH4 oppm co, 20.8% O2 detected at time of exam
Track & Travelways OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Freshift-Mine Examiner Certificate No. 15397
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 39060-08
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-12-09 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 a.m. or P.M. to 3:00 a.m. or P.M.
Was this report phoned to outside: Yes [checked] no
By whom John Bickford Time A.M. 2:43 P.M.
Report received by Harley Taylor 37002 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include D-BOXES, CHARGERS, WORK AREA, 255 CHARGER, all with 0% CH4 and NONE OBSERVED/Action Taken.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4 0% CO 20.8% O2 TRACK & TRAVELWAYS OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me; (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 15397
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 3500009X

Assistant Foreman Superintendent or Assistant John A. Bickford 26176

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-12-09 20 Section or Area Examined L1WALL
Time of Examination: from 830 a.m. or p.m. to 1130 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. O Boxes OK	none observed	none
2. Chargers OK	none observed	none
3. work area OK	none observed	none
4. 255 Charger OK	none observed	none
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good Airment	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: OK Ch. Y OK CO 208202
Track Travelway OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift-Mine Examiner Certificate No. 1537A
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 35060004
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-13-09 20 Section or Area Examined 2/Wall construction
Time of Examination: from 3:40 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D-13 98</u>	<u>none observed</u>	<u>none</u>
2. <u>Chargers</u>	<u>none observed</u>	<u>none</u>
3. <u>Wk Area</u>	<u>none observed</u>	<u>none</u>
4. <u>255 charger</u>	<u>none observed</u>	<u>none</u>
5. <u> </u>	<u> </u>	<u> </u>
6. <u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: 22064 2200 208802
Tracks Travel ways ok

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift-Mine Examiner Certificate No. 13941
Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 3800028
Assistant Foreman
Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-13 2009 Section or Area Examined L/W Const
 Time of Examination: from 12 a.m. or 6 p.m. to 3 a.m. or 6 p.m.
 Was this report phoned to outside: Yes no
 By whom John B Semenske Time 256 A.M. P.M.
 Report received by C Semenske 31292
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D-Box</u>	<u>NONE observed</u>	<u>NONE</u>
2. <u>Changers</u>	<u>NONE observed</u>	<u>NONE</u>
3. <u>Work Area</u>	<u>NONE observed</u>	<u>NONE</u>
4. <u>255 Changer</u>	<u>NONE observed</u>	<u>NONE</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0% CO, 20.89 oz Detected at exam
Track, Truvelway OK at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John B Semenske Certificate No. 26176
 Preshift-Mine Examiner Assistant Foreman Certificate No. _____
 Countersigned John B Semenske Certificate No. 31000-224
 Mine Manager—Mine Foreman
Mike Bailey Assistant Foreman Certificate No. 27085
 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-13-09 20 Section or Area Examined LIW construction
Time of Examination: from 8:30 a.m. or (p.m.) to 1:00 a.m. or (p.m.)
Was this report phoned to outside: Yes [checked] no
By whom Bailey Time A.M. 11:00 P.M.
Report received by [Signature] 15391A (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10. Handwritten entries: 1. D-Box, none observed, none; 2. Charger, none observed, none; 3. Work Area, none observed, none; 4. 255 Charger, none observed, none.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Handwritten entry: Good Airment.

Remarks: OB CUY 0200 2018202
Travelways Track OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 27021
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No. _____

Mine Foreman-Mine Manager

Certificate No. _____

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-14 2009 Section or Area Examined LW Panat.
 Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D Boxes</u>	<u>None Observed</u>	<u>Reported</u>
2. <u>Chargers</u>	<u>" "</u>	<u>"</u>
3. <u>Work Area</u>	<u>" "</u>	<u>"</u>
4. <u>255 Chargers</u>	<u>" "</u>	<u>"</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Gravel Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: OTO Cotts 20.0% O2 0 CD
Tramways Track OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Certificate No. 27085
 Preshift-Mine Examiner
 Countersigned Johny Neely Certificate No. 33472
 Mine Manager—Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-14-09 20 Section or Area Examined L-WALL CONSTRUCTION
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom J Neely Time 2:50 A.M. P.M.
Report received by George Curry 27429 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>D-Boxes</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>CHARGERS</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>WORK AREA</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. <u>255 CHARGER</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 20.8% O₂, 0ppm CO Detected at EXAM time
TRACK & TRAVELWAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely 33472 Certificate No. Assistant Foreman
Countersigned Mike Bailey 27060-07 Certificate No. Mine Manager—Mine Foreman
Mike Bailey 27085 Assistant Foreman Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-14-09 20 Section or Area Examined Wall Construction
 Time of Examination: from 8:20 a.m. or p.m. to 1:20 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Billy Time 11:00 A.M. P.M.
 Report received by Alan Wynn 15397
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D-Boxes</u> <u>CHY</u> <u>02</u>	<u>none observed</u>	<u>none</u>
2. <u>Chargers</u> <u>03</u>	<u>none observed</u>	<u>none</u>
3. <u>Work Area</u> <u>02</u>	<u>none observed</u>	<u>none</u>
4. <u>255 Chargers</u> <u>02</u>	<u>none observed</u>	<u>none</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Amount</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 02 CHY 26 CO 20158 02
Travellways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By M. L. Bailey 27085
 Preshift-Mine Examiner Certificate No.
 Countersigned Alan Wynn 15396-01
 Mine Manager—Mine Foreman Assistant Foreman Certificate No.
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-15 2009 Section or Area Examined LW Const.
 Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D Bases</u>	<u>None Observed</u>	<u>Reported</u>
2. <u>Charges</u>	<u>None Observed</u>	<u>"</u>
3. <u>Work Area</u>	<u>" "</u>	<u>"</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Grand Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Track Trackage OK
0% CH₄ 0 CO 20.8% O₂

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey 27085
 Preshift-Mine Examiner Certificate No.
 Countersigned John Cook 3506000
 Mine Manager—Mine Foreman Certificate No.
 Assistant Foreman
Johnny Neely 33472
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 10-15 2009 Section or Area Examined L/W Corra
 Time of Examination: from 12 a.m. or 00 p.m. to 3 a.m. or 00 p.m.
 Was this report phoned to outside: Yes no
 By whom John N Time A.M. 2:15 P.M.
 Report received by John N 39199
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D-Boxes</u>	<u>NONE observed</u>	<u>NONE</u>
2. <u>Chargers</u>	<u>NONE observed</u>	<u>NONE</u>
3. <u>Work Area</u>	<u>NONE observed</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Track, Tracelway clear
0% CH4, 0% CO, 20.8% O2 Detected at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely 33472
 Preshift-Mine Examiner Certificate No.
 Countersigned John N 39199
 Mine Manager—Mine Foreman Assistant Foreman Certificate No.
Mike Bailey 27085
 Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-15-09 20. Section or Area Examined L/WALL Conds.
 Time of Examination: from 8:30 a.m. or 6 p.m. to 11:05 a.m. or 6 p.m.
 Was this report phoned to outside: Yes no
 By whom Mike Bailey Time A.M. 11:05 P.M.
 Report received by Stan Goh 27042
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>D-Boxe's</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
2. <u>Charger's</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
3. <u>Work Area</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0 ppm CO, 20.8% O₂ detected at time of exam
Track & Travelways ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
 Assistant Foreman _____ Certificate No. _____
 Countersigned Stan Goh Mine Manager—Mine Foreman Certificate No. 37000-01
 Assistant Foreman _____
 Superintendent or Assistant _____

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-16 20 09 Section or Area Examined L.W. Conest.
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: D-Bases, None Observed, Reported. Row 2: Work Area, "", "". Row 3: Charges, "", "".

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Measurement, "", "", "".

Remarks: Track Transducers OK
0% CH4 20.8% O2 0 CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33472
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working-place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-16 2009 Section or Area Examined L/W Construction
Time of Examination: from 1200 a.m. or 6:00 to 3:00 a.m. or 6:00
Was this report phoned to outside: Yes no
By whom Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: D Boxes, None observed, Reported. Row 2: Work AREA, "", "". Row 3: Chargers, "", "".

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement, "", "", "".

Remarks: TRACK, TRAVELWAYS OK
0% CH4 0% CO 20.8 O2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely 33472 Certificate No.
Countersigned Mike Daily 27085 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-16-07 20 11 Section or Area Examined Longwall Conste.
 Time of Examination: from 8:32 a.m. or 0 p.m. to 11:32 a.m. or 0 p.m.
 Was this report phoned to outside: Yes no
 By whom Mike Bailey Time A.M. P.M.
 Report received by John Lee 31042
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CFM	Violation or Hazardous Condition	Action Taken
1. <u>D. Cox's</u>	<u>0</u>	<u>None observed</u>	<u>None</u>
2. <u>Work Area</u>	<u>0</u>	<u>None observed</u>	<u>None</u>
3. <u>Charger's</u>	<u>0</u>	<u>None observed</u>	<u>None</u>
4. <u> </u>	<u> </u>	<u> </u>	<u> </u>
5. <u> </u>	<u> </u>	<u> </u>	<u> </u>
6. <u> </u>	<u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: 0.5% open co₂ 0.25% O₂ detected at time of exam
Truck & Roadway's ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey 27085
Preshift-Mine Examiner Certificate No.
 Countersigned John Lee 37060-08
Mine Manager—Mine Foreman Assistant Foreman Certificate No.

Superintendent or Assistant Johnny Reilly 33472

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-17 2009 Section or Area Examined LW Conat
 Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D-Basis</u>	<u>None Observed</u>	<u>Reported</u>
2. <u>Work Area</u>	<u>" "</u>	<u>" "</u>
3. <u>Charges</u>	<u>" "</u>	<u>" "</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Track Trunkways OK
0.7% CH₄ 20.8% O₂ 0 CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 21085
 Countersigned John Cook Mine Manager—Mine Foreman Certificate No. 384000
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-17 2009 Section or Area Examined L/W Construct
 Time of Examination: from 1200 a.m. or 6.00 to 300 a.m. or 6.00
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D. Boxes</u>	<u>None observed</u>	<u>Reported</u>
2. <u>Work Area</u>	<u>" "</u>	
3. <u>Changers</u>	<u>" "</u>	
4. _____		
5. _____		
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			

Remarks: TRACK, TRAVELWAYS OK
0% CH⁴ 0% CO 20.802

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely 33472
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
 Countersigned Charles Smith 390001
 Mine Manager—Mine Foreman
Mike Barley 27085
 Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-17-05 20. Section or Area Examined L1 WALL Conster
Time of Examination: from 8:22a.m. or P.M. to 11:22a.m. or P.M.
Was this report phoned to outside: Yes no
By whom Mike Bailey Time A.M. 11:25 P.M.
Report received by Steve Glick 3974
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>D-Coxe's</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
2. <u>Work Area</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
3. <u>Charger's</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0 ppm CO₂, 20.8% O₂ detected at time of exam
Track & Travelways ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Mike Bailey Preshift Mine Examiner Certificate No. 27085
Countersigned Steve Glick Mine Manager—Mine Foreman Certificate No. 3974
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-18 2089 Section or Area Examined LA Comet
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D. Boxes</u>	<u>None Observed</u>	<u>Reported</u>
2. <u>Walk Area</u>	<u>" "</u>	<u>"</u>
3. <u>Charges</u>	<u>" "</u>	<u>"</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Gravel Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Track Travelways OK
0% CH₄ 20.8% O₂ 0 CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By White Bailey 27085 Certificate No. Assistant Foreman
Countersigned John Bailey 37060 Certificate No. Mine Manager—Mine Foreman
Johnny Nelly 33472 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-18-09 20 Section or Area Examined 4th construction
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no no.
By whom John Neely Time 2:50 A.M. P.M.
Report received by Paul Taylor (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Chargers, Oshby</u>	<u>None observed</u>	<u>None</u>
2. <u>D-bones, Oshby</u>	<u>None observed</u>	<u>None</u>
3. <u>Track, Oshby</u>	<u>None observed</u>	<u>None</u>
4. <u>Power Center, Oshby</u>	<u>None observed</u>	<u>None</u>
5. <u>Work area, Oshby</u>	<u>None observed</u>	<u>None</u>
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 20.8% O2, 0% CH4, 0% CO, track, trackways, power center, scoops chargers, clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John Neely 33472 Certificate No. Assistant Foreman
Countersigned Paul Taylor 390602 Certificate No. Mine Manager—Mine Foreman

Assistant Foreman: Rick Foster 28736
Superintendent or Assistant: Don Williams 1539A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11/20/09 20 Section or Area Examined 4w const
 Time of Examination: from 8:30 a.m. or 10:00 p.m. to 10:00 a.m. or 8:30 p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Chairs 0244</u>	<u>none</u>	<u>none</u>
2. <u>Boxes 0244</u>	<u>none</u>	<u>none</u>
3. <u>Track 0244</u>	<u>none</u>	<u>none</u>
4. <u>PC'S 0244</u>	<u>none</u>	<u>none</u>
5. <u>Work Area 0244</u>	<u>none</u>	<u>none</u>
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Card Arm</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 208202 0244 0200
Track Travelways ok

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Sam Williams 15399 Preshift-Mine Examiner Certificate No. _____ Assistant Foreman Certificate No. _____
 Countersigned Carl Cook Mine-Manager-Mine Foreman Certificate No. _____
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-19-09 20. Section or Area Examined L1 wall
Time of Examination: from 3:00 a.m. or 6:00 a.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: yes no no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Charger</u>	<u>none observed</u>	<u>none</u>
2. <u>O Box</u>	<u>none observed</u>	<u>none</u>
3. <u>Track</u>	<u>none observed</u>	<u>none</u>
4. <u>PC's</u>	<u>none observed</u>	<u>none</u>
5. <u>work Area</u>	<u>none observed</u>	<u>none</u>
6. <u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Diamond</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: 2088 02 02 CO 02 Chy
Track Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dan Miller 1579A Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
Countersigned Carl [unclear] 3900000 Mine Manager—Mine Foreman Assistant Foreman
Superintendent or Assistant

John A. Burkhardt 2476

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-19 20 07 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom John Bickford Time A.M. 2:36 P.M.
Report received by Rick Tate 28736 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH4	Violation or Hazardous Condition	Action Taken
1. CHARGER	0%	NONE OBSERVED	NONE
2. D. BOX	0%	NONE OBSERVED	NONE
3. POWER CENTERS	0%	NONE OBSERVED	NONE
4. WORK AREA	0%	NONE OBSERVED	NONE
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
GOOD AIR MOVEMENTS			

Remarks: 0% CH4 0% CO 20-8% O2
TRACK, TRAVELWAYS OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford 26176 Certificate No. Assistant Foreman Certificate No.
Countersigned Carl Tate 3500000
Assistant Foreman Superintendent or Assistant 15391

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range: _____ Below Range: _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-19-09 20. Section or Area Examined Luft constant

Time of Examination: from 8:00 a.m. or 8:00 p.m. to 1:00 a.m. or 1:00 p.m.

Was this report phoned to outside: Yes no

By whom Doug West Time A.M. P.M.

Report received by

(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Charger</u> <u>OK</u>	<u>none observed</u>	<u>none</u>
2. <u>D-Box</u> <u>OK</u>	<u>none observed</u>	<u>none</u>
3. <u>PC</u> <u>OK</u>	<u>none observed</u>	<u>none</u>
4. <u>work Area</u> <u>OK</u>	<u>none observed</u>	<u>none</u>
5. <u> </u>	<u> </u>	<u> </u>
6. <u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Area</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: 07 cut OK CO 20-88 OK
Trails OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dan Miller 1997 Certificate No.
Preshift-Mine Examiner Assistant Foreman Certificate No.

Countersigned Andy Cook Certificate No. 350602
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-20-09 20 Section or Area Examined Longwall Constr.
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time 5:05 A.M. P.M.
Report received by (Signed)

Table with 4 columns: Location, CH4, Violations and other Hazardous Conditions Observed and Reported, Action Taken. Rows include D-Sax's, Chargers, Work Area, Power Center.

Table for Air Measurements with columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4 open co, 20.8% O2 detected at time exam
Track's Travelways ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] 1539A Certificate No.
Countersigned [Signature] 350600 Assistant Foreman Certificate No.

John A. Bueford 26176

Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-20 2009 Section or Area Examined Longwall Construction

Time of Examination: from 12:00 a.m. or 00:00 to 3:00 a.m. or 03:00

Was this report phoned to outside: Yes no

By whom John Bickford Time 2:41 A.M. P.M.

Report received by Rick Fahn (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include D. BOXES, CHARGERS, WORK AREA, POWER CENTER, and empty rows 5-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4 0% CO 20.8% O2 TRACK, TRAVELWAYS OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John G. Bickford 26176 Freshift-Mine Examiner Assistant Foreman Certificate No. Countersigned Mike Bailey 27085 Mine Manager-Mine Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-20-09 Section or Area Examined LW411
 Time of Examination: from 8:30 a.m. or 9 p.m. to 11:00 a.m. or 10 p.m.
 Was this report phoned to outside: Yes no no
 By whom only Time 11:00 A.M. 11:00 P.M.
 Report received by [Signature] 11-20-09
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D Boxes</u> <u>chf</u>	<u>none Observed</u>	<u>none</u>
2. <u>Charges</u> <u>O2</u>	<u>none Observed</u>	<u>none</u>
3. <u>workman's</u> <u>O2</u>	<u>none Observed</u>	<u>none</u>
4. <u>PC</u> <u>O2</u>	<u>none Observed</u>	<u>none</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: O2 chf O2 CO 208802
Trailing OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
 Countersigned [Signature] Mine Manager—Mine Foreman Assistant Foreman Certificate No. 35000
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-21 2009 Section or Area Examined LW Conest
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: D-bases, None Observed, Reported. Row 2: Charges, u, u, u. Row 3: Work Area, u, u, u. Row 4: Power Lines, u, u, u.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement, [blank], [blank], [blank].

Remarks: Track Travelways OK
R To CH2 20.8 To O2 0.00

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33472
Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-21 2009 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 a.m. or (P.M) to 3:00 a.m. or (P.M)
Was this report phoned to outside: Yes no
By whom John Neely Time 2:37 A.M. P.M.
Report received by Harley Taylor 37002
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>D. BOXES</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>CHARGERS</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>WORK AREA</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. <u>POWER CENTERS</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄ 0% CO 20.8% O₂
TRACK & TRAVELWAYS OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John Neely Certificate No. 33472
Preshift-Mine Examiner Assistant Foreman Certificate No. _____
Countersigned Harley Taylor Mine Manager—Mine Foreman Certificate No. 37002
Wale Rainey Assistant Foreman Certificate No. 27005
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11/21/09 20 Section or Area Examined Luettl cont
 Time of Examination: from 8:30 a.m. or PM to 11:00 a.m. or PM
 Was this report phoned to outside: Yes no
 By whom Billy Time 11:00 PM
 Report received by Don Williams 15397
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. D-Boxes <u>CHY</u>	<u>none observed</u>	<u>none</u>
2. Chargers <u>OE</u>	<u>none observed</u>	<u>none</u>
3. work Area <u>OE</u>	<u>none observed</u>	<u>none</u>
4. Power Center <u>OE</u>	<u>none observed</u>	<u>none</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Airway</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 02 CHY 02CO 20202
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Reilly 27029 Assistant Foreman Certificate No.
 Countersigned Don Williams Mine Manager—Mine Foreman
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-22 2009 Section or Area Examined LW Canast.
Time of Examination: from 8 a.m. or p.m. to 6 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for 'D Kaxo', 'Chargus', 'Work Area', and 'Power Center'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Measurement'.

Remarks: Track Translucency OK
O2 to C/H 20.8% O2 OGD

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
Countersigned [Signature] Mine Manager-Mine Foreman Assistant Foreman Certificate No. 33472
Johnny Neely Superintendent or Assistant