

3 & 4 SECTION RETURN EP, MP, DPP Weekly Examinations For Methane And Hazardous Conditions STARTED 1-6-10

Company PERFORMANCE COAL

Mine UBB

Location NAOMA Raleigh WV
Post Office County State

	Date	EP	CH	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
	1-6-10	EP-62	0%	20.8%	0%	1,875	to outside	<i>[Signature]</i>	1659-A
	1-6-10	EP-59	0%	20.8%	0%	20,336	To outside	<i>[Signature]</i>	1659-A
	1-6-10	EP-60	0%	20.8%	0%	4,200	To outside	<i>[Signature]</i>	1659-A
	1-6-10	61R	0%	20.8%	0%	3,122	into dell panel, outside	<i>[Signature]</i>	1659-A
	1-6-10	61L	0%	20.8%	0%	2,916	into dell panel, outside	<i>[Signature]</i>	1659-A
1P	1-6-10	6	0%	20.8%	0%	496	to RETURN	<i>[Signature]</i>	27429
1P	1-6-10	7	0%	20.8%	0%	258	to RETURN	<i>[Signature]</i>	27429
1P	1-6-10	8	0%	20.8%	0%	111	to return	<i>[Signature]</i>	27429
1P	1-6-10	9	0%	20.8%	0%	332	to return	<i>[Signature]</i>	27429
P	1-6-10	10	0%	20.8%	0%	231	to return	<i>[Signature]</i>	27429
P	1-6-10	12	0%	20.8%	0%	482	to return	<i>[Signature]</i>	27429
P	1-6-10	11	0%	20.8%	0%	981	to return	<i>[Signature]</i>	27429
PP	1-6-10	6	0%	20.8%	0%	1453	to outside	<i>[Signature]</i>	27429
PP	1-6-10	7	0%	20.8%	0%	2493	to outside	<i>[Signature]</i>	27429
PP	1-6-10	8	0%	20.8%	0%	4340	to outside	<i>[Signature]</i>	27429
PP	1-6-10	9	0%	20.8%	0%	2210	To outside	<i>[Signature]</i>	27429
PP	1-6-10	10	0%	20.8%	0%	1570	to outside	<i>[Signature]</i>	27429
PP	1-6-10	11	0%	20.8%	0%	10205	to outside	<i>[Signature]</i>	27429

Rest Test 28736

Hazardous Conditions

DPP 9 Blocked by water (ASC) George Curry 27429

Multiple horizontal lines for recording hazardous conditions.

Corrections From Week of _____

Signature *Rick [unclear]* Mine Foreman 28734 Certificate No. _____ Superintendent of Company

Air Readings

Lined area for recording air readings.

Signature _____
Mine Foreman

Certificate No. _____

Superintendent of Company _____

Air Way Travels

1-6-10 TRAVELED 3 SECTION #1 Portal to sec (TW)
 1-6-10 TRAVELED 3 SECTION Right Return FROM SECTION ABOVE old Panels to EP59 (TW)
 1-6-10 TRAVELED 3 SECTION Right Return FROM EP59, BELOW old Panels, back to SECTION T2
 1-6-10 TRAVELED 3 SECTION Primary FROM SECTION to 15 BRM (TW)
 1-7-10 TRAVELED old panels at 4 SECTION Right Return (TW)

Don W. [Signature] 1659-A

Signature *Rick [Signature]*
Mine Foreman

28236
Certificate No.

Superintendent of Company

Date	EP	CH	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
1-11-10	62	0%	20.8%	0%	7700	To outside	<i>[Signature]</i>	1659-A
1-11-10	59	0%	20.8%	0%	20,460	To outside	<i>[Signature]</i>	1659-A
1-11-10	60	0%	20.8%	0%	3,472	To outside	<i>[Signature]</i>	1659-A
1-11-10	61R	0%	20.8%	0%	3,164	To outside	<i>[Signature]</i>	1659-A
1-11-10	61L	0%	20.8%	0%	2280	To outside	<i>[Signature]</i>	1659-A
MP	6	0%	20.9	0%	17670	To Return	<i>[Signature]</i>	37222
MP	7	0%	20.9	0%	212	To Return	<i>[Signature]</i>	37222
MP	8	0%	20.8	0%	115	To Regulator	<i>[Signature]</i>	37222
MP	9	0%	20.8	0%	213	To Regulator	<i>[Signature]</i>	37222
MP	10	0%	20.9	0%	180	To Regulator	<i>[Signature]</i>	37222
MP	12	0%	20.9	0%	361	To Regulator	<i>[Signature]</i>	37222
MP	11	0%	20.8	0%	4068	To Regulator	<i>[Signature]</i>	37222
DPP	6	0%	20.9	0%	1670	To Regulator	<i>[Signature]</i>	37222
DPP	7	0%	20.8	0%	3696	To Regulator	<i>[Signature]</i>	37222
DPP	8	0%	20.8	0%	4665	To Regulator	<i>[Signature]</i>	37222
DPP	9	0%	20.8	0%	10850	To Regulator	<i>[Signature]</i>	37222
DPP	10	0%	20.8	0%	1090	To Regulator	<i>[Signature]</i>	37222
DPP	11	0%	20.8	0%	4068	To Regulator	<i>[Signature]</i>	37222

Rec'd Data 08736

Hazardous Conditions

Corrections From Week of _____

Signature Rick Fortin
Mine Foreman

28236
Certificate No.

Superintendent of Company

	Date	EP	CH	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
	1-18-10	62	0%	20.8%	0%	60,096	To outside	<i>[Signature]</i>	1659-A
	1-18-10	59	0%	20.8%	0%	17,980	" "	<i>[Signature]</i>	1659-A
	1-18-10	60	0%	20.8%	0%	31,444	" "	<i>[Signature]</i>	1659-A
	1-18-10	61R	0%	20.8%	0%	3,052	" "	<i>[Signature]</i>	1659-A
	1-18-10	61C	0%	20.8%	0%	2,610	" "	<i>[Signature]</i>	1659-A
MP	1-26-10	6	8%	20.8%	0%	496	To return	<i>[Signature]</i>	27429
MP	1-26-10	7	8%	20.8%	0%	259	To return	<i>[Signature]</i>	27429
MP	1-26-10	8	8%	20.8%	0%	115	To return	<i>[Signature]</i>	27429
MP	1-26-10	9	8%	20.8%	0%	329	To return	<i>[Signature]</i>	27429
MP	1-26-10	10	8%	20.8%	0%	228	To return	<i>[Signature]</i>	27429
MP	1-26-10	12	8%	20.8%	0%	471	To return	<i>[Signature]</i>	27429
MP	1-26-10	11	8%	20.8%	0%	852	To return	<i>[Signature]</i>	27429
DPP	1-26-10	1	8%	20.8%	0%	1392	To outside	<i>[Signature]</i>	27429
DPP	1-26-10	7	8%	20.8%	0%	3990	To outside	<i>[Signature]</i>	27429
DPP	1-26-10	8	8%	20.8%	0%	4277	To outside	<i>[Signature]</i>	27429
DPP	1-26-10	9	8%	20.8%	0%	285	To outside	<i>[Signature]</i>	27429
DPP	1-26-10	10	8%	20.8%	0%	1610	To outside	<i>[Signature]</i>	27429
DPP	1-26-10	11	8%	20.8%	0%	9880	To outside	<i>[Signature]</i>	27429

Reel #10 28284

Hazardous Conditions

Corrections From Week of _____

Signature _____
Mine Foreman

_____ Certificate No.

_____ Superintendent of Company

	Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
	1-25-10	62	0%	20.8%	0%	6,917	To outside	Jim Wilkins	1659-A
	1-25-10	59	0%	20.8%	0%	17,980	" "	Jim Wilkins	1659-A
	1-25-10	60	0%	20.8%	0%	3,332	" "	Jim Wilkins	1659-A
	1-25-10	61R	0%	20.8%	0%	3,192	" "	Jim Wilkins	1659-A
	1-25-10	61L	0%	20.8%	0%	2,748	" "	Jim Wilkins	1659-A
MP	1-27-10	2	0%	20.8%	0%	493	to return	George Curry	27429
MP	1-27-10	7	0%	20.8%	0%	121	to return	George Curry	27429
MP	1-27-10	8	0%	20.8%	0%	113	to return	George Curry	27429
MP	1-27-10	9	0%	20.8%	0%	324	to return	George Curry	27429
MP	1-27-10	10	0%	20.8%	0%	225	to return	George Curry	27429
MP	1-27-10	12	0%	20.8%	0%	474	to return	George Curry	27429
MP	1-27-10	11	0%	20.8%	0%	844	to return	George Curry	27429
DPP	1-27-10	2	0%	20.8%	0%	1251	to outside	George Curry	27429
DPP	1-27-10	7	0%	20.8%	0%	2763	to outside	George Curry	27429
DPP	1-27-10	8	0%	20.8%	0%	4551	to outside	George Curry	27429
DPP	1-27-10	9	0%	20.8%	0%	2192	to outside	George Curry	27429
DPP	1-27-10	10	0%	20.8%	0%	1711	to outside	George Curry	27429
DPP	1-27-10	11	0%	20.8%	0%	9765	to outside	George Curry	27429

Reg left return 1735

Travelled all interiors of old panels on 4 section

1-25-10 Jim Boyer 32861, fog detector 39199

(Some water is beginning to build up in #1 testing of last panel ^{3B} and

Rest tests 28734

	Date	EP	CH	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
	2-1-10	62	0%	20.8%	0%	8576	To outside	Jim Wilkins	1659-A
	2-1-10	59	0%	20.8%	0%	19964	To outside	Jim Wilkins	1659-A
	2-1-10	60	0%	20.8%	0%	3808	To outside	Jim Wilkins	1659-A
	2-1-10	61L	0%	20.8%	0%	3484	To outside	Jim Wilkins	1659-A
	2-1-10	61R	0%	20.8%	0%	3772	To outside	Jim Wilkins	1659-A
mP	2-3-10	6	0%	20.8%	0%	482	To return	George Curry	27429
mp	2-3-10	7	0%	20.8%	0%	213	To return	George Curry	27429
mp	2-3-10	8	0%	20.8%	0%	121	To return	George Curry	27429
mp	2-3-10	9	0%	20.8%	0%	328	To return	George Curry	27429
mp	2-3-10	10	0%	20.8%	0%	225	To return	George Curry	27429
mp	2-3-10	12	0%	20.8%	0%	219	To return	George Curry	27429
mp	2-3-10	11	0%	20.8%	0%	841	To return	George Curry	27429
DPP	2-3-10	6	0%	20.8%	0%	1433	To outside	George Curry	27429
DPP	2-3-10	7	0%	20.8%	0%	2333	To outside	George Curry	27429
DPP	2-3-10	8	0%	20.8%	0%	4190	To outside	George Curry	27429
DPP	2-3-10	9	0%	20.8%	0%	2170	To outside	George Curry	27429
DPP	2-3-10	10	0%	20.8%	0%	1120	To outside	George Curry	27429
DPP	2-3-10	11	0%	20.8%	0%	8740	To outside	George Curry	27429

Traveled all interiors of old Panels on 4 Section 2-1-10

Joey Stewart 39199

Traveled Interior of old 3 section Mains Heading 2-2-10

Knacked Interior Steppings and made Common 2743222

Traveled Left & Right return Airways for Barrier Section; Barrier Room

2-3-10 JDC

Rick Foster 28734

	Date	EP	CH	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
	2-8-10	60	0%	20.8%	0%	3934	To outside	Jim Wilks	1659-A
	2-8-10	59	0%	20.8%	0%	3088	" "	Jim Wilks	1659-A
	2-8-10	61R	0%	20.8%	0%	3696	" "	Jim Wilks	1659-A
	2-8-10	61L	0%	20.8%	0%	3384	" "	Jim Wilks	1659-A
	2-8-10	62	0%	20.8%	0%	8501	" "	Jim Wilks	1659-A
MP	2-10-10	10	0%	20.8%	0%	182	Return return	George Curry	27429
MP	2-10-10	9	0%	20.8%	0%	1414	To return	George Curry	27429
MP	2-10-10	12	0%	20.8%	0%	1617	To return	George Curry	27429
MP	2-10-10	7	0%	20.8%	0%	1680	To return	George Curry	27429
MP	2-10-10	8	0%	20.8%	0%	8555	To return	George Curry	27429
MP	2-10-10	11	0%	20.8%	0%	10615	To return	George Curry	27429
DPP	2-10-10	10	0%	20.8%	0%	1224	To outside	George Curry	27429
DPP	2-10-10	9	0%	20.8%	0%	1505	To outside	George Curry	27429
DPP	2-10-10	7	0%	20.8%	0%	1731	To outside	George Curry	27429
DPP	2-10-10	8	0%	20.8%	0%	4535	To outside	George Curry	27429
OPP	2-10-10	11	0%	20.8%	0%	4865	To outside	George Curry	27429
MP	2-10-10	6	0%	20.8%	0%	501	To return	George Curry	27429
DPP	2-10-10	6	0%	20.8%	0%	1441	To outside	George Curry	27429

Travelling interior of all panels on 4 section (Barrier)
 some water build up in #1 of last panel mined
 Jim Wilks 32267 2-8-10

Traveled return airway from 4BK North to Barrier section; Barrier room
 back to 4BK W George Curry 27429

Rock Test 28734

Air Way Travels

Multiple horizontal lines provided for recording Air Way Travels.

Signature _____
Mine Foreman

Certificate No.

Superintendent of Company

	Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
MP	2-16-10	59	0	20.8	0	21452	To Outside #4 Panel ^{ENST} _{main}	Harley Taylor	37052
MP	2-17-10	10	0	20.8	0	144	To return	George Curry	27429
MP	2-17-10	9	0	20.8	0	951	To return	George Curry	27429
MP	2-17-10	12	0	20.8	0	380	To return	George Curry	27429
MP	2-17-10	7	0	20.8	0	1062	To return	George Curry	27429
MP	2-17-10	6	0	20.8	0	1221	To return	George Curry	27429
MP	2-17-10	8	0	20.8	0	1005	To return	George Curry	27429
MP	2-17-10	11	0	20.8	0	10420	To return	George Curry	27429
OPP	2-17-10	10	0	20.8	0	1312	To outside	George Curry	27429
OPP	2-17-10	9	0	20.8	0	1123	To outside	George Curry	27429
OPP	2-17-10	7	0	20.8	0	1062	To outside	George Curry	27429
OPP	2-17-10	6	0	20.8	0	1441	To outside	George Curry	27429
OPP	2-17-10	8	0	20.8	0	4235	To outside	George Curry	27429
OPP	2-17-10	11	0	20.8	0	4633	To outside	George Curry	27429
	2-18-10	60	0	20.8	0	3867	To outside	Jay Stewart	39199
	2-18-10	61R	0	20.8	0	2844	To Outside	Jay Stewart	39199
	2-18-10	61L	0	20.8	0	3441	To Outside	Jay Stewart	39199
	2-18-10	62	0	20.8	0	8263	To Outside	Jay Stewart	39199

Traveled interior of old Panels on Banner Section "Old 4 Section"
 Jay Stewart 39199 2-15-10

Ruck Test 28731

	Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
MPD	2-24-10	90	20.8	20.8	0	Water	To return	George Curry	27479
MPQ		9	20.8	20.8	0	412	To return	George Curry	27479
MPZ		12	20.8	20.8	0	427	To return	George Curry	27479
MP		7	20.8	20.8	0	581	To return	George Curry	27479
MP		6	20.8	20.8	0	496	To return	George Curry	27479
MP		8	20.8	20.8	0	1015	To Return	George Curry	27479
MP		11	0	20.8	0	775	To Return	George Curry	27479
DPP		10	0	20.8	0	Water		George Curry	27479
DPP		9	0	20.8	0	Water		George Curry	27479
DPP		7	0	20.8	0	1282	To outside	George Curry	27479
DPP		8	0	20.8	0	4235	To outside	George Curry	27479
DPP		11	0	20.8	0	3956	To outside	George Curry	27479
DPP		6	0	20.8	0	1392	To outside	George Curry	27479
	2-25-10	59	0	0	0	16740	to outside	Jay Stewart	39199
	2-25-10	60	0	0	0	3242	to outside	Jay Stewart	39199
	2-25-10	61L	0	0	0	3833	to Outside	Jay Stewart	39199
	2-25-10	61R	0	0	0	3816	to Outside	Jay Stewart	39199
	2-25-10	62	0	0	0	9043	to Outside	Jay Stewart	39199

Traveled interior of old Panels on 4 Section "Barrier" 2-22-10
 Some water building up in #1 of last panels mined. JB

Jay Stewart 39199 Jim Dwyer 32261

Rick Foster 28736

Traveled Left & Right returns for Barrier Section Barrier Row - from 14 to 4A

George Curry 27479

Traveled Left and Right Returns on Portal Section

Jay Stewart 39199

Rick Foster
28736

Hazardous Conditions

Water starting to build in old 3 section panel. in Faces,
Pumps are being set.

Corrections From Week of _____

Signature

Rich Jeter
Mine Foreman

Certificate No.

28731

Superintendent of Company

Jay Stewart 39199

Air Readings

Lined area for recording air readings.

Signature _____
Mine Foreman

Certificate No. _____

Superintendent of Company _____

Air Way Travels

Multiple horizontal lines for data entry.

Signature _____
Mine Foreman

Certificate No.

Superintendent of Company

	Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
NP	3-3-10	10	0	20.8	0	132	To Return	George Curry	27429
NP	3-3-10	9	0	20.8	0	734	To Return	George Curry	27429
NP	3-3-10	12	0	20.8	0	503	To Return	George Curry	27429
MP	3-3-10	26	0	20.8	0	1650	To Return	George Curry	27429
NP	3-3-10	7	0	20.8	0	845	To Return	George Curry	27429
NP	3-3-10	8	0	20.8	0	8547	To Return	George Curry	27429
MP	3-3-10	11	0	20.8	0	8838	To Return	George Curry	27429
PP	3-3-10	10	0	20.8	0	821	To outside	George Curry	27429
PP	3-3-10	9	0	20.8	0	911	To outside	George Curry	27429
PP	3-3-10	7	0	20.8	0	1462	To outside	George Curry	27429
PP	3-3-10	16	0	20.8	0	1584	To outside	George Curry	27429
PP	3-3-10	8	0	20.8	0	5231	To outside	George Curry	27429
PP	3-3-10	11	0	20.8	0	3262	To outside	George Curry	27429
	3-4-10	62	6	20.8	0	7,768	To Outside	Jay Stewart	39199
	3-4-10	61L	0	20.8	0	3,086	To outside	Jay Stewart	39199
	3-4-10	61R	0	20.8	0	3,575	To Outside	Jay Stewart	39199
	3-4-10	60	0	20.8	0	3,693	To Outside	Jay Stewart	39199
	3-4-10	59	0	20.8	0	15,500	To Outside	Jay Stewart	39199

3-1-10 Traveled interior of old 4 section panels. found water dripping upon head end of last 2 panels mined. Jim Bayne 32261
Jay Stewart 39199

3-3-10 Traveled Return Airway for old Barrier Section / Barrier Rooms from 14W @ ABOVE and back to 14W - George Curry 27429

Traveled Left and Right Return on Portal Section 3-4-10 LS

Traveled Old Portal Portal EP 62 3-4-10 LS Jay Stewart 39199

Rick York
28737

Hazardous Conditions

*scalloped top in various places in ~~last~~ interior of last
2 yards mined on old #4 (Barnier section) Jim Boyer 32261*

Water building up in Old Portal Section Faces, Pumps being sit.
Doors need repaired in left return 19 BK. Jay Stenat 39199

Corrections From Week of _____

Signature *Rick Foster*
Mine Foreman

28732
Certificate No.

Superintendent of Company

Air Readings

A series of 25 horizontal lines for recording air readings.

Signature _____
Mine Foreman

_____ Certificate No.

_____ Superintendent of Company

Air Way Travels

Traveled Right and left Return on Portal Section
Traveled Old Portal Portal to EP 62.1h51 3-4-10 Jacq Stewart 39199

Signature *Rich Jata*
Mine Foreman

28732
Certificate No.

Superintendent of Company

	Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
NP	3-10-10	10	0	0	0	121	to return	George Curry	27429
NP	3-10-10	9	0	0	0	632	to return	George Curry	27429
NP	3-10-10	6	0	0	0	2510	to return	George Curry	27429
NP	3-10-10	12	0	0	0	2762	to return	George Curry	27429
NP	3-10-10	7	0	0	0	1982	to return	George Curry	27429
NP	3-10-10	8	0	0	0	3526	to return	George Curry	27429
NP	3-10-10	11	0	0	0	4362	to return	George Curry	27429
PP	3-10-10	10	0	0	0	492	to outside	George Curry	27429
PP	3-10-10	9	0	0	0	873	to outside	George Curry	27429
PP	3-10-10	6	0	0	0	1922	to outside	George Curry	27429
PP	3-10-10	7	0	0	0	455	to outside	George Curry	27429
PP	3-10-10	8	0	0	0	4851	to outside	George Curry	27429
PP	3-10-10	11	0	0	0	3142	to outside	George Curry	27429
	3-11-10	62	0	20.8	0	7062	to outside	Jay Stewart	39199
	3-11-10	61L	0	20.8	0	2,695	to outside	Jay Stewart	39199
	3-11-10	61R	0	20.8	0	3,038	to outside	Jay Stewart	39199
	3-11-10	60	0	20.8	0	3,186	to outside	Jay Stewart	39199
	3-11-10	59	0	20.8	0	15,376	to outside	Jay Stewart	39199

3-8-10 Travelled interiors of old 4 ^(Barrier) sections (water in last 2
 panels mined appears no worse than last week) Jim Boyer 32261
 Jay Stewart 39199

3-10-10 Travelled return escape way for old Barrier section of Rooms from
 4BK W around / back to 14BK W George Curry 27429

Traveled Portal Section Left and Right Return. Jay Stewart 39199

Hazardous Conditions

*sealed down loose rock in various places of old 4 (Laminar)
section Jim Boyer 32261 3-8-10*

Water starting to build in old works in faces of old
Pontal Section. Pumps and discharge are being run. Jay Stewart 39199

Water starting to build in faces that Pontal Section last
pulled off of. Jay Stewart 39199

Corrections From Week of _____

Signature *Red Jeter*
Mine Foreman

28734
Certificate No.

Superintendent of Company

Air Way Travels

Horizontal lines for recording air way travels.

Signature _____
Mine Foreman

Certificate No.

Superintendent of Company

	Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
MP	3-17	10	0	0	0	114	To Return	George Curry	27429
MP	3-17	9	0	0	0	557	To Return	George Curry	27429
MP	3-17	10	0	0	0	2009	To Return	George Curry	27429
MP	3-17	12	0	0	0	1017	To Return	George Curry	27429
MP	3-17	7	0	0	0	3440	To Return	George Curry	27429
MP	3-17	8	0	0	0	4773	To Return	George Curry	27429
MP	3-17	11	0	0	0	5334	To Return	George Curry	27429
PP	3-17	10	0	0	0	321	To outside	George Curry	27429
PP	3-17	9	0	0	0	714	To outside	George Curry	27429
PP	3-17	10	0	0	0	971	To outside	George Curry	27429
PP	3-17	7	0	0	0	1521	To outside	George Curry	27429
YPP	3-17	8	0	0	0	1285	To outside	George Curry	27429
YPP	3-17	11	0	0	0	3756	To outside	George Curry	27429
	3-18	62	0	20.8	0	6,672	to Outside	Jay Stewart	39199
	3-18	61L	0	20.8	0	2529	to Outside	Jay Stewart	39199
	3-18	61R	0	20.8	0	2839	to Outside	Jay Stewart	39199
	3-18	60	0	20.8	0	3110	to Outside	Jay Stewart	39199
	3-18	59	0	20.8	0	19,592	to Outside	Jay Stewart	39199

3-15-10 travelled interiors of old Barrier (4 section) Panels
 water quickly up in last 2 panels mined Jim Boyer 3226
 Jay Stewart 39199

3-17-10 Travelled Return Airway of old Barrier Section from 14N
 Around and back to 14N George Curry 27429

3-18-10 Traveled Portal Section Left and Right Return
 Jay Stewart 39199

Ruck Notes 28734

Hazardous Conditions

*scalded down loose top in various places of about
2 panels mined on old Barrier Section Jim Day 32261*

*Water starting to build in faces that Portal Section last
pulled off of. Jac, elevat 39199*

Corrections From Week of _____

Signature *Rick Jata*
Mine Foreman

28284
Certificate No.

Superintendent of Company

Air Way Travels

(This section contains multiple horizontal lines for recording air way travel details.)

Signature _____
Mine Foreman

_____ Certificate No.

_____ Superintendent of Company

	Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
MP	3-24	10	0	0	0	93	to return	George Curry	27429
MP	3-24	9	0	0	0	1114	to return	George Curry	27429
MP	3-24	10	0	0	0	558	to return	George Curry	27429
MP	3-24	12	0	0	0	1075	to return	George Curry	27429
MP	3-24	7	0	0	0	394.3	to return	George Curry	27429
MP	3-24	8	0	0	0	703	to return	George Curry	27429
MP	3-24	11	0	0	0	5073	to return	George Curry	27429
IPP	3-24	10	0	0	0	113	to outside	George Curry	27429
IPP	3-24	9	0	0	0	433	to outside	George Curry	27429
IPP	3-24	10	0	0	0	591	to outside	George Curry	27429
IPP	3-24	12	0	0	0	1032	to outside	George Curry	27429
IPP	3-24	7	0	0	0	1811	to outside	George Curry	27429
IPP	3-24	8	0	0	0	1850	to outside	George Curry	27429
IPP	3-24	11	0	0	0	4802	to outside	George Curry	27429
	3-25-10	62	0	20.8	0	6,312	to outside	Jacy Stewart	39199
	3-25-10	61L	0	20.8	0	2,719	to outside	Jacy Stewart	39199
	3-25-10	61R	0	20.8	0	2,783	to outside	Jacy Stewart	39199
	3-25-10	60	0	20.8	0	3,057	to outside	Jacy Stewart	39199
	3-25-10	59	0	20.8	0	27,032	to outside	Jacy Stewart	39199

3-22-10 Traveled interior of old Barrier (#4 section) of Panels
 water building up in last 2 panels missed & noticed more
 speaking off of ribs & roof in various places
 Jim Bangen 32261, Jacy Stewart 39199

3-24-10 Traveled return airways last 7 miles of Barrier section
 starting at 14W going around and back to 14W George Curry 27429

Traveled Left and Right return on Portal Section. Jacy Stewart 39199

Red Book 2010

Hazardous Conditions

Water starting to build in faces that section last pulled off of at 27 Bk.

Corrections From Week of 3-20-10 set pumps & runing discharge lines to pump water from old pans on floor section using #1 pump on left side now
Jim Dougan 32261
Joey Blum 39199

Signature Robt John
Mine Foreman

78734
Certificate No.

Superintendent of Company

Air Way Travels

A large section of the page consisting of 27 horizontal lines, intended for recording or detailing air way travels.

Signature _____
Mine Foreman

_____ Certificate No.

_____ Superintendent of Company

	Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
MP	3-31	10	0	0	0	710	to return	George Curry	27429
MP	3-31	9	0	0	0	177	to return	George Curry	27429
MP	3-31	10	0	0	0	428	to return	George Curry	27429
MP	3-31	12	0	0	0	1675	to return	George Curry	27429
MP	3-31	7	0	0	0	516.8	to return	George Curry	27429
MP	3-31	8	0	0	0	1623	to return	George Curry	27429
MP	3-31	11	0	0	0	572	to return	George Curry	27429
IPP	3-31	12	0	0	0	419	to outside	George Curry	27429
IPP	3-31	10	0	0	0	89	to outside	George Curry	27429
IPP	3-31	9	0	0	0	323	to outside	George Curry	27429
IPP	3-31	10	0	0	0	321	to outside	George Curry	27429
IPP	3-31	7	0	0	0	1502	to outside	George Curry	27429
IPP	3-31	8	0	0	0	2164	to outside	George Curry	27429
IPP	3-31	11	0	0	0	4814	to outside	George Curry	27429
	4-1-10	62	0	20.8	0	6543	to outside	Jacy Stewart	39199
	4-1-10	61L	0	20.8	0	2481	to outside	Jacy Stewart	39199
	4-1-10	61R	0	20.8	0	2724	to outside	Jacy Stewart	39199
	4-1-10	60	0	20.8	0	2615	to outside	Jacy Stewart	39199
	4-1-10	59	0	20.8	0	16244	to outside	Jacy Stewart	39199

Traveled interior of old Banner Section '4 section'
 Jacy Stewart 39199, went to last panel mined from some
 of water building up in head end. Jim Sawyer 32261
 Traveled old banner section return airway from 1st around
 and back to 4th George Curry 27429

Traveled left and right return on Portal Section Jacy Stewart 39199

Hazardous Conditions

Water starting to build in faces in old panel at 27 BK
Joey Stuart 39199

Corrections From Week of worked on running discharge lines & setting pumps
sealed some loose rock in various places of panel 322 61
(starter pumps are on order)

Signature _____
Mine Foreman

Certificate No. _____

Superintendent of Company _____

Air Readings

Signature _____
Mine Foreman

_____ Certificate No.

_____ Superintendent of Company

Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #

Traveled intum of old 4 section ~~section~~ panels Lamin
 Section. Went to last panel mined water building up head
 Some roof & ~~at~~ sides slumping off. yulled some. done rock
 Jim Sawyer 32261
 Jay Smith 39199