

Started 3-24-10
full 4-1-10

**EXAMINATION OF
BELT CONVEYORS**

South Side Belts

COMPANY Performance Coal
MINE UBB South Side Belts
LOCATION Nadma Ral WV
 Post Office County State

Re-order #9980 from
BJW Printing and
Office Supplies
P. O. Box 1309
Beckley, W. Va. 25802
Phone (304) 253-7361

EXAMINATION OF BELT CONVEYORS

ON SHIFT

DATE 3-24-10 SHIFT DAY TIME OF EXAMINATION: FROM 6:00 A.M. OR P.M. TO 4:00 P.M.

BELT CONVEYOR EXAMINED	Action Taken		EXAMINER
#1 South	cleaned V-plow spillage		JB
#1 North			
#2 North	shoveled tail		LS
#3 North	Set 8 sand jacks beside head & tail washed & dented center behind tail		JB, BC LS
3 Sec # 1			
	HT 97BK outby Refuge chamber OK AT TOE (phone OK)		

SIGNED BY:

Tom Boyer
Belt Examiner

32261
Certificate No.

Harley Taylor 37002
Jack Stenard 39199

COUNTERSIGNED BY:

Rich Ester
Mine Foreman

28734
Certificate No.

Superintendent

Certificate No.

Harley Taylor 29691

EXAMINATION OF BELT CONVEYORS

Preshift

DATE 3-24-10 SHIFT 2nd TIME OF EXAMINATION: FROM 6:00 A.M. OR P.M. TO 11:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLETIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
<u>CH4</u> #1 South 0%	<u>needs spot clean + spot dusted 20-40 ft.</u>	<u>Rep.</u>	<u>TP</u>
#1 North 0%	<u>3-20 ft., need add. dusting off side</u>	<u>Rep.</u>	<u>TP</u>
#2 North 0%	<u>needs spot cleaning 2 North tail needs add dusting to ^{AB} tail</u>	<u>Reports</u>	<u>BB</u>
#3 North 0%	<u>needs add dusting, some spot cleaning</u>	<u>Reports</u>	<u>BB</u>
#3 Sec #1 0%	<u>needs spot dusting, spot cleaning</u>	<u>Reports</u>	<u>BB</u>
LBB 0%	<u>Pumps PLC's track clear at exam</u>	<u>none</u>	<u>BB</u>
Mainline 0%	<u>Pumps PLC's D. Boxes clear at exam.</u>	<u>none</u>	<u>TP</u>
	<u>Rock deck 0% 20.802 COO's</u>		
	<u>Visual on CO's clear at exam</u>		
	<u>Pumps PLC's D. boxes clear at exam.</u>		
	<u>Refuse Chumker 97 ft. + Phone clear at exam.</u>		

SIGNED BY:

Kim Peterson 29611
Belt Examiner Certificate No.

COUNTERSIGNED BY:

Rick Foster 25736
Mine Foreman Certificate No. Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

ON Shift

DATE 3-24-10 SHIFT 2ND TIME OF EXAMINATION: FROM 6:40 A.M. OR P.M. TO 7:40 A.M. OR P.M.

BELT CONVEYOR EXAMINED	Action Taken		EXAMINER
#1 South	cleaned U plow		TW
#1 North	Hand dusted from 208K to 218K Dusted on #1 North tail cleaned on U plow	Reports	BBTP
#2 North	Handled dusted 218K on #2 North Added Hose dusted on #1 tail put dust in dust collector duster	Reports	BB
#3 North			
3 Sec #1	cleaned on section tail	Reports	BB

SIGNED BY: [Signature] 29611
Belt Examiner Certificate No.

COUNTERSIGNED BY: [Signature] 28736
Mine Foreman Certificate No. Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

Pre-Shift

DATE 3-25-10 SHIFT Dwl TIME OF EXAMINATION: FROM 3:00 A.M. OR P.M. TO 6:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South CH4 O%	needs spot cleaning; spot dusting 2:15K to 4:00K	Reported	TP
#1 North O%	3:20 BK need add dusting off ribs	Reported	TP
#2 North O%	needs spot cleaning need some add dusting toward 2nd tail	Reported	BB
#3 North O%	needs add dusting - needs spot cleaning	Reported	BB
#3 Sec #1 O%	needs spot dusting; need spot cleaning	Reported	BB
#3 sec #2 O%	Needs dusted	Reported	GLC
LBB O%	Pump Powercenter travel clear at transfer	none	BB TP
Mainline O%	Pump Powercenter D-Boyer clear at transfer	none	TP
Refuse Chomlee #97BK; phone ok at time of exam			

SIGNED BY: Greg Cole 1947-A Mine Examiner 24611 Certificate No. 37074

COUNTERSIGNED BY: Rick Foster Mine Foreman 28730 Certificate No. 39199 Superintendent

Certificate No. _____

EXAMINATION OF BELT CONVEYORS

On-Shift

DATE 3-25-10

SHIFT owl

TIME OF EXAMINATION:

FROM 1230

A.M. OR P.M. TO 230

A.M. OR P.M.

BELT CONVEYOR EXAMINED

Action Taken

EXAMINER

#1 North

Hand dusted from 206K to 21 BK
~~Hand dusted 206K~~

Reports

BB TD

hooded T. Dustin & Pan

TD

2 North

Hand dusted 206K on 2 North Filled up dusted
 cleaned on 1 tail dusted 1 tail welded hose non cluster

Reports

BB

3 Sec #1

cleaned on section tail Help drill 1 hole on head

Reports

BB

SIGNED BY:

Rene Smith 29611
 Belt Examiner

37074
 Certificate No.

COUNTERSIGNED BY:

Rick Foster
 Mine Foreman

29736
 Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Pre shift

DATE 3-25-10

SHIFT

Day

TIME OF EXAMINATION:

FROM

1:00

A.M. OR P.M. TO

4:00

A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
# 1 South CH4 0%	Needs some spot cleaning, 22-40 needs spot dusted	Reported	JB
# 1 North 0%	3-20 Bk needs add dusting especially offside Walkways need spot clean, wire mesh needs cutdown 26, 36 Bk	Reported	JB/LS
# 2 North	Needs Spot Cleaned, Need Some add Dusting ground tail	Reported	LS
# 3 North	Need add Dusting, Need Spot Cleaned "Wet"	Reported	LS
3 Sec #1	Needs Spot Cleaned and Spot Dusted, Tail needs Add Clang	Reported	LS
3 Sec #2	Needs Dusted	Reported	LS
LBB 0% CH4	Pumps, POWER CONTACTS CLEAR AT TOE	NONE	TW
Mainline 0% CH4	Pumps, POWER CONTACTS, d-boxes clear AT TOE, 0% CH4 0% CO 20.8% O2 detected Track, triambungs, charges, yellow signs safe at exam Visual check of CO monitor ok at exam See board of air meter	NONE	TW

SIGNED BY:

Jim Boyce 32261
Belt Examiner

Certificate No.

Jim Wilton 1659-A
Jacy Stewart 39199

COUNTERSIGNED BY:

Rick Fata
Mine Foreman

28734
Certificate No.

Superintendent

Certificate No.

Rick Fata 79611

On shift

EXAMINATION OF BELT CONVEYORS

DATE 3-25-10

SHIFT Day

TIME OF EXAMINATION: FROM 6:00

A.M. OR P.M. TO 4:00

OR P.M.

BELT CONVEYOR EXAMINED	Action Taken	EXAMINER
#1 South	Put legs under belt rails at 15-16 Brk 3 places, filled 9 non dusts at tail JB	JB
#1 North	put rails back 16-17, Dropped Bottom Roller 10 Brk, dusted tail 2 Brk cleaned off yamur wax at head, non dusts at head area	JB
#2 North		
#3 North		
3 Sec #1	put bottom roller in 23 Brk, dropped bottom roller at 36 Brk JB/LS	JB/LS
3 Sec #2		
	97 Refuge chamber 2 yamur at 1st room TW	

SIGNED BY: Tom Sawyer 32261
Belt Examiner Certificate No.

COUNTERSIGNED BY: Reed Peter
Mine Foreman Certificate No. 23234

Tom Sawyer 1659-A
Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

Pre-SHIFT

DATE 3-25-10 SHIFT 2nd TIME OF EXAMINATION: FROM 8:00 A.M. OR P.M. TO 11:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
# 1 South	need spot clean 22 40 LK. need spot dusted	Rep.	TP
# 1 North	3-20 BK. need add. dusting	Rep.	TP
# 2 North	needs spot cleaning & dusting toward 2 North tail	Reported	BB
# 3 North	needs add dusting; needs spot cleaning wet. 2 places section tail needs cleaned 3N tail		
# 3 Sec. #1	need spot cleaning needs some spot dusting 35 BK to tail needs dusting	Reported	BB
# 2	needs dusting	Reported	BB
LBB	Pumps PLC's tracks clean at exam	none	TP BB
MAINLINE	Pumps PLC's D. boxes clean at exam	none	TP
	MOCH 4 duct - 0% 20.8 or 0%		
	Visual on CO's clean at exam		
	Pumps PLC's D. boxes track clean at exam		

Bruce Burdett 37074

SIGNED BY: *Thyler* 29611
Belt Examiner Certificate No.

COUNTERSIGNED BY: *Rick Foster* 28736
Mine Foreman Certificate No. Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

0W-Shift

P.M. DATE 3-25-10 SHIFT 2nd TIME OF EXAMINATION: FROM 8:00 A.M. OR P.M. TO 11:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	REMARKS AND OTHER FACTORS	EXAMINER
# 1 South	cleaned out rollers at V-plow & washed out impact rollers	TW
# 1 North	dusted at 21 sik,	TW
# 2 North	Got long piece of belt from under 2N belt & put in BK trough	BB
# 3 North	dusted on 1 North tail cleaned up more piece of Belt away from 2 North (Hard Dust) Dusted on 3 North take-up started at track dusted up to starter Box	BB
3 Sec. # 1 # 2	cleaned on V-plow checked splices 3 sec 1 Belt	BB
	Refuse Chamber 97 sik, clean & Phone at exam	

Bruce [Signature] 37074

SIGNED BY:

[Signature]
Belt Examiner

24611
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

23236
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-26-10 SHIFT OWL TIME OF EXAMINATION: FROM 300 A.M. OR P.M. TO 600 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
# 1 South	need spot clean 22-40 blk, need spot dusted	Rep.	TP
# 1 North	3-20 blk need add. dusting	Rep.	TP
# 2 North	needs spot cleaning & dusting toward 2 North tail section tail needs add. cleaning	Reported	BB
# 3 North	needs spot cleaning, need add. dusting wet w/panels	Reported	BB
# 3 Sec #1	needs spot cleaning: spot dusting 35 Blk to tail needs dusting	Reported	BB
# 2	needs dusting	Reported	BB
LBB	Pumps, Truck, powercenter ok at transferer	Reported	TP
Mainline	Pumps, Powercenter, D-PARK, Truck ok at transferer NOCH4 detected CO 0% 20.88.02 Visual checks CO's ok at transferer	Reported	TP

SIGNED BY:

Bruce Buech
Belt Examiner

37074
Certificate No.

COUNTERSIGNED BY:

Beck Foster
Mine Foreman

28732
Certificate No.

Superintendent

Certificate No.

Tom Hansen 32261

Loey Stewart 39199

EXAMINATION OF BELT CONVEYORS

DATE 7-26-10 SHIFT DWL TIME OF EXAMINATION: FROM 12:30 A.M. OR P.M. TO 2:30 A.M. OR P.M.

CONVEYOR EXAMINED	DEFECTS AND OTHER HAZARDOUS CONDITIONS OBSERVED		EXAMINER
South	washed out impact on walkway side cleaned under 2 Bot. rollers in front of V-plow. put 4 rail stands in at 7 Bkl.		TW TW
North			
North	Greased on 2 North cleaned on 2N tail V-Plow Dusted 3N Head 2N tail down to powerbox Pat curtain around 3N Rock Box Reported		BB
North	Pat curtain around 3N Rock box cleaned up trash & pieces of belt at 3N Head Reported		BB
# 1			
# 2			
BB			
MAIN LINE			
	Refuse Chamber & Phone 97BK ok at time of exam	Reporte	JP

SIGNED BY: Donna Brutt Belt Examiner 37074 Certificate No.

COUNTERSIGNED BY: Buck Foster Mine Foreman 28736 Certificate No. _____ Superintendent _____ Certificate No. _____

EXAMINATION OF BELT CONVEYORS

DATE 3-26-10 SHIFT DAY TIME OF EXAMINATION: FROM 1:00 ~~OR P.M.~~ TO 4:00 ~~OR P.M.~~

BELT CONVEYOR EXAMINED		VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
# 1 South	0%	Needs spot cleaning, Needs spot dusted 22-40 Bk	Reported	JB
# 1 North	0%	Needs wire mesh cut down 26, 36, 46, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100. Needs add dusting 3-20 especially offside.	Reported	LS/JB
# 2 North	0%	Needs Spot Dusted and Spot Cleaned	Reported	LS
# 3 North	0%	Need Spot cleaned and Dusted "Wet"	Reported	LS
3 rec # 1	0%	Need Spot cleaned and spot Dusted	Reported	LS
3 rec # 2	0%	Needs Dusted	Reported	LS
LBB	0%	Pumps, track, power lines safe at exam	Reported	TW
Main Lines	0%	Pumps, track, power lines, D-Bone safe at exam	Reported	HT
		Offsite 0% CO 20.8% O ₂ detected		
		track, travel ways, power lines, & charges safe at exam		
		Visual check of crinometer at exam		
		See board for notes		

SIGNED BY: Jim Bauger Belt Examiner Certificate No. 32261

COUNTERSIGNED BY: Rick Foster Mine Foreman Certificate No. 28732

Joey S. Lynat 39199
Harley Taylor 37002
Jim W. 1659-A
 Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

P.M. DATE 3-26-10 SHIFT DAY TIME OF EXAMINATION: FROM 6:00 AM OR P.M. TO 4:00 OR P.M.

BELT CONVEYOR EXAMINED	Action Taken	EXAMINER
# 1 South	put in 15 stands from 5 Bk-10 Bk, put 1 stand in at 22 Bk cleaned plow then, reset cleaned 16-17 Bk	J B
# 1 North		
# 2 North		
# 3 North		
3 rec # 1	Pulled structure over at 36 Bk	J B / L S
3 rec # 2		
MAINLINE	Replaced chamber of phone sk at 97 Bk Reset numerous timbers and tightened ribs From Plumb 4 up to 58 Bk	T W

SIGNED BY: Jim Sawyer Belt Examiner Certificate No. 32261
 COUNTERSIGNED BY: Rick Foster Mine Foreman Certificate No. 28732
 Superintendent: Jay Linn 39199 Tim White 16594
Harley Taylor 37002 Certificate No.

EXAMINATION OF BELT CONVEYORS

PRESHIFT

DATE 3-26-10

SHIFT eve

TIME OF EXAMINATION: FROM 8:30

A.M. OR P.M. TO 11:30

A.M. OR P.M.

DAT

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South	P/C'S Pumps clear At exam	Reported	GLC
#1 North	P/C'S Pumps clear At exam	Reported	GLC
#2 North	P/C'S CLEAR At exam	Reported	GLC
#3 North	P/C'S clear At exam	Reported	GLC
3 sec #1	P/C'S clear At exam	Reported	GLC
3 sec #2	P/C'S chargels clear At exam	Reported	GLC
LBB	PUMPS, Track, PowerBoxes clear At exam	Reported	GLC
Main Line	Pumps, PowerBoxes, Track, D-Boxes clear At exam	Reported	GLC
	Grachy, OPLM C.O., 20.8% O ₂ detected		
	Track, Travelways, PowerBoxes, chargels OK At time of exam		
	visual check of C.O. monitors OK At exam		

SIGNED BY: [Signature]
Belt Examiner

1947-A
Certificate No.

COUNTERSIGNED BY: [Signature]
Mine Foreman

28734
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Pressure

DATE 3-27-10

SHIFT owl

TIME OF EXAMINATION:

FROM 3:00

AM. OR P.M. TO 6:00

AM. OR P.M.

BELT CONVEYOR EXAMINED	CHG	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South	0%	Did Fire Run No smoke No Hot Rollers, No C.O. Found P.C.'s, Track, Travelways, Pumps OK AT exam	GEC Reported	GLC
#1 North	0%			
#2 North	0%			
#3 North	0%			
BSEC #1	0%	Did Fire Run No smoke, No	Reported	GLC
BSEC #2	0%	Hot Rollers, No C.O. Found P.C.'s, Track, Travelways Pumps, OK AT exam		
LBB	0%	Track, Travelways, P.C.'s, Pumps OK AT exam	Reported	GLC
main Line	0%	Pumps, P.C.'s, Track, D-Boxes, clear AT exam	Reported	GLC
		O ₂ ch ₄ , 2.8% O ₂ , 0.1% C.O. Detected		
		Track, Travelways, P.C.'s, charger OK AT exam		

SIGNED BY:

[Signature]
Belt Examiner

1947-A
Certificate No.

[Signature] 1659A

COUNTERSIGNED BY:

[Signature]
Mine Foreman

2873L
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

ON SHIFT

V.

DATE 3-27-10

SHIFT Owl

TIME OF EXAMINATION: FROM 3:00

A.M. OR P.M. TO 6:00

P.M. OR P.M.

BELT CONVEYOR EXAMINED

Action

Acti

Taken

ACTION TAKEN

EXAMINER

97BRK Refuge OK AT TIME OF EXAM

SIGNED BY:

[Signature]
Belt Examiner

1947A
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

2873C
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-27-10 SHIFT Day TIME OF EXAMINATION: FROM 12:00 A.M. OR P.M. TO 2:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 south o/w	belts Idle no production		BD TW
#1 north		BD TW	
#2 north		BD TW	
#3 north		BD TW	
3sec #1	belts Idle No Production		BD TW
3sec #2		BD TW	
LBB	Track, Travel ways, Powercenters, Pumps - clear at time of exam		BD TW
Main Line	Pumps, Powercenters, Track, D-boxes - clear at time of exam		BD TW
	Track, Travelways, Power center		
	clear at time of exam		
	o/w, 20.8%, No CO Found.		

SIGNED BY:

[Signature]
Belt Examiner

1659-A
Certificate No.

[Signature] 1176-A

COUNTERSIGNED BY:

[Signature]
Mine Foreman

28732
Certificate No.

Superintendent


Certificate No.

[Signature] 1947-A


EXAMINATION OF BELT CONVEYORS

P.M. DATE _____ SHIFT _____ TIME OF EXAMINATION: FROM _____ A.M. OR P.M. TO _____ A.M. OR P.M.

SR	BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1				
1				
1				
1				
1				
1				
1				
1				
1				
1				
1				
1		97 BK refuge chamber ok at time of exam		
1				
1		0% ch ₄ , 20.8 ⁰² No CO Found		

SIGNED BY:  _____
Belt Examiner

1176-A
Certificate No.

 _____
Superintendent

COUNTERSIGNED BY:  _____
Mine Foreman

28732
Certificate No.

_____ Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-27-10 SHIFT eve TIME OF EXAMINATION: FROM 8:30 A.M. OR P.M. TO 11:30 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 south 0% CH ₄	Belts IDle No Production P.C.'s OK At exam	Reported	GLC
#1 North 0%			GLC
#2 North 0%			GLC
#3 North 0%			GLC
3 sec #1 0%	Belts IDle. P.C.'s OK At exam No Production	Reported	GLC
3 sec #2 0%			GLC
LBB 0% CH ₄	Track, Travelways, P.C.'s, Pumps clear At exam	Reported	GLC
main Line 0% CH ₄	Pumps, P.C.'s, Track, D-Boxes, clear At exam	Reported	GLC
	Track, Travelways, P.C.'s, OK At exam		
	0% CH ₄ , 20.8% O ₂ , oppm C.O. Detected		

SIGNED BY:

[Signature]
Belt Examiner

1947-A
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

28734
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-28-10

SHIFT 0W1

TIME OF EXAMINATION: FROM 3:00

AM. OR P.M. TO 6:00

AM. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South 0%	Belts IDLE No Production P.C.'S Track OK At TOE	Reported	GLC
#1 North 0%			
#2 North 0%			
#3 North 0%			
sec 3 sec #1 0%			
3 sec #2 0%			
LBB 0%	Track, Travelways, P.C.'S, Pump OK At exam	Reported	GLC
Main Line 0%	Pumps, P.C.'S, Track, D-Boxes, Clear At exam	Reported	GLC
	Track, Travelways, P.C.'S OK At exam		
	0% ch4, 20.8% O ₂ , O ₂ ppm C.O. Detected		

SIGNED BY:

[Signature]
Belt Examiner

1947-A
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

28732
Certificate No.

Superintendent

[Signature] 27429

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-28-10

SHIFT DAY

TIME OF EXAMINATION:

FROM 1200

A.M. OR P.M. TO

300

A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER	
1 south	Belts Idle			
1 north				
2 north		PC's - Track clear at	Reported	JAC
3 north		exam		
3 sec #1		Belts Idle PC's & track clear at TOE		
3 sec #2	No Power, dangled off at 3sec #1 head	Reported	TW	
LBB 5% chg pumps	pc's clear at exam	none	JAC	
Main line 0% chg pump	pc's - D boxes clear at exam	none	JAC	

SIGNED BY:

George Curry
Belt Examiner

27429
Certificate No.

Jim R. Williams 1659-A

COUNTERSIGNED BY:

Beck Foster
Mine Foreman

28735
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-28-10 SHIFT 2nd TIME OF EXAMINATION: FROM 8:00 A.M. OR P.M. TO 11:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLETIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 south ^{CH4} 0% CH4	Needs spot cleaning Needs spot dusting 22-40 PK	Reported	BB
#1 north 0% CH4	Needs wire mesh cut down 26-36 Walkway needs spot cleaning Needs cold dusting 3-20 PK off side needs dusting	Reported	BB
#2 north 0% CH4	Needs spot dusting? spot cleaning tail-V-plow needs cleaning	Reported	BB
#3 north 0% CH4	Needs spot cleaning & dusting under in place needs cleaned section to 1	Reported	BB
3 sec #1 0% CH4	Needs spot cleaning & spot dusting Need dusting toward tail	Reported	TP
#2 0% CH4	Needs dusting		TP
h.B.B. 0% CH4	Pump, power center, Trunk ok at time of exam	Reported	TP
MAIN LINE 0% CH4	Pump power center, D-Boxes trunk ok at time of exam	Reported	TP
	0% CH4 0.20.8% CO2 detected		
	Trunk Trunk pump power center D-Boxes changed		
	Visual check of CO2 all clear at time of exam		

SIGNED BY:

[Signature]
Belt Examiner

37074
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

28734
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

On-shift

P.M. 3-28-10 SHIFT *eve* TIME OF EXAMINATION: FROM _____ TO _____ A.M. OR P.M. TO _____ A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS OR OTHER HAZARDOUS CONDITIONS	ACTION TAKEN	EXAMINER
	<i>Action Taken</i>		
<i>#2 North</i>	<i>cleaned on 2 North V-Plow + Fixed cross under Fencing</i>	<i>Reported cleaned on</i>	<i>TP BB</i>
	<i>Refuse Chamber: Phone 9784 skat transfer</i>	<i>Reported</i>	<i>TP</i>

SIGNED BY:

[Signature]
Belt Examiner

24611
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

28736
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-29-10 SHIFT OWL TIME OF EXAMINATION: FROM 300 A.M. OR P.M. TO 600 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South	need spot cleaning Need spot ducting 22-46 BK	Reported	TP
#1 North	needs wire mesh cut 26-36 BKs walkway need spot cleaning need add ducting 3-20 BK offside need ducting Head area Needs dusting	Reported	TP BB
#2 North	Needs spot cleaning & spot ducting	Reported	BB
#3 North	Needs spot cleaning & ducting wet in places section tail needs add cleaning	Reported	BB
35 Sec #1	Needs spot cleaning & ducting Needs ducting from 35 BK to 1 tail 3 section	Reported	BB
#2	Needs ducting - (connected) B.B.	Dusted	BB
LBB	Pump power center Track ok at time of exam	Reported	TP BB
Mainline	Pump power center D-Boxes track ok at time of exam		
	0% CH ₄ 0.208% CO ₂ 0% Detected at time of exam		
	Visual Checks of CO ₂ all clear at time of exam		

SIGNED BY:

Remy Johnson 29611
Brett Smith
Belt Examiner

37074
Certificate No.

COUNTERSIGNED BY:

Rick Foster
Mine Foreman

28736
Certificate No.

Superintendent

George Curry 27429

Certificate No.

Jim Brown 32261

Joey Steward 39199

EXAMINATION OF BELT CONVEYORS

ON-SHIFT

M. DATE 3-29-10 SHIFT OWL TIME OF EXAMINATION: FROM _____ A.M. OR P.M. TO _____ A.M. OR P.M.

BELT CONVEYOR EXAMINED	ACTION TAKEN	FACTS TAKEN	EXAMINER
* 1 South	we worked on stand on 1 South 7-10 ft.	put in stand	TP BB
2 North	cleaned on 2 North tail	cleaned on tail	TP BB
3 Sec 1 Belt	cleaned on 3 Sec #1 Tail V-plow	Repair	BB
3 Sec 2 Belt	Dusted 3 Sec #2 Belt	Dusted 2 Belt	BB
	Refuse Chamber; Phone 97BK at end of run	Report	TD

SIGNED BY:

[Signature]
Belt Examiner
Dane Bruto

29611
Certificate No.
37074

COUNTERSIGNED BY:

[Signature]
Mine Foreman

2873C
Certificate No.

Superintendent

Certificate No.

10085

EXAMINATION OF BELT CONVEYORS

DATE 3-29-10

SHIFT Day

TIME OF EXAMINATION:

FROM 6:00

A.M. OR P.M. TO

4:00

~~7:00~~ OR P.M.

BELT CONVEYOR EXAMINED

Action Taken

EXAMINER

#1 South

Put bottom rollers in at tail, dusted tail & ran dust

JB

#1 North

Dusted head area

JB

#2 North

#3 North

3 Sec #1

Cleaned on tail

LS

3 Sec #2

Refuge chamber at 97 B/C - OK at exam. Mine phone in working order

Jim Deussen 32261

SIGNED BY:

Scott Cherry
Belt Examiner

27479
Certificate No.

Jacy Stewart 39199

COUNTERSIGNED BY:

Paul Foster
Mine Foreman

28736
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-29-10 SHIFT 2nd TIME OF EXAMINATION: FROM 8:00 A.M. OR P.M. TO 11:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLETIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South 070CH4	need spot clean - need add. R/P at take-up need dusted 2-22-40 etc.	Rep.	TP
#1 North 070	need add. dusting 3-20 etc. need spot clean	Rep.	TP
#2 North 070	need spot clean + spot dusted	Rep.	TP
#3 North 070	water on belt line - (muddy) need spot clean + dusted	Rep.	TP
#3 sec. #1 070	need dusted 35 to tail - need spot clean	Rep.	TP
#2 070	none observed	Rep.	TP
LBB 070	Pumps, P/C's, track clean at exam	none	TP
MAIN Line 070	Pumps, P/C's, D. Boxes clean at exam.	none	TP
	Rocky deck. 20.8 or COO		
	Visual on CO's clean at exam.		
	Pumps P/C's D. Boxes track + Tranchways clean at exam.		

SIGNED BY:

[Signature]
Belt Examiner

29611
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

28734
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-29-10 SHIFT 2ND TIME OF EXAMINATION: FROM 6:20 A.M. OR P.M. TO 7:30 A.M. OR P.M.

BELT CONVEYOR EXAMINED	ACTION TAKEN	ACTION TAKEN	EXAMINER
	<i>Action Taken</i>		
<i>1 mouth head</i>	<i>hooded to dusted & run - dusted at take up</i>		<i>TP</i>
	<i>Refuse Chamber 97 Mt. Clean & Phone at exam</i>		

SIGNED BY:

Cmy [Signature]
Belt Examiner

29611
Certificate No.

COUNTERSIGNED BY:

Rich [Signature]
Mine Foreman

28236
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Pre Shift

DATE 3-30-10 SHIFT Owl TIME OF EXAMINATION: FROM 3:00 A.M. OR P.M. TO 6:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South	need spot clean in place 2-22-40 Belts & spot dusted	Rep.	TP
#1 North	need add. dusting 3-20 Belts off side. need spot clean	Rep.	TP
#2 North	need spot clean - tail at v plow need add. cleaning	Rep.	TP
#3 North	need spot clean & dusted (water - wet & muddy)	Rep.	TP
#3 Sec. #1	need spot clean & dusted 35 to tail - made five run No HAZARDS found		TP
#2	none obsned - Made five run - NO HAZARDS found	Rep.	TP
LBB	Pumps P/c's track clean at exam.	none	TP
MAW Line	Pumps P/c's D. Boxes clean at exam.	none	TP
	No CH4 det. 0% 20.50 or CO 0%		
	Visual on CO's clean at exam.		
	Track & Travelways clean at exam.		
	Pumps P/c's D. Boxes clean at exam.		

SIGNED BY:

[Signature]
Belt Examiner

29611

Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

28736

Certificate No.

Superintendent

[Signature] 27429

Certificate No.

EXAMINATION OF BELT CONVEYORS

ON-Shift

DATE 3-30-10 SHIFT Owl TIME OF EXAMINATION: FROM 8:00 ~~P.M.~~ OR P.M. TO 6:00 A.M. OR ~~A.M.~~

BELT CONVEYOR EXAMINED	DEFECTS OBSERVED	ACTION TAKEN	EXAMINER
#1 South	Duster 3 Bkt. to take-up	Action Taken	TR
#1 north	loaded T. Duster + Run - duster off side take-up		TR

Refuse Chamber 97 Bkt. + Phos. clear of exam.

SIGNED BY: [Signature] Belt Examiner Certificate No. 29611

COUNTERSIGNED BY: [Signature] Mine Foreman Certificate No. 2878 Superintendent Certificate No. _____

EXAMINATION OF BELT CONVEYORS

Pre Shift

DATE 3-30-10 SHIFT DAY TIME OF EXAMINATION: FROM 1:00 ~~AM~~ OR P.M. TO 4:00 ~~AM~~ OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South CH4 0%	Hand some spot cleaning, needs add dusting 22-40 belt	Reported	JB
#1 North 0%	wire mesh 26, 23 hand in down, walkways need spot cleaned Needs add dusting especially off side 3-20,	Reported	JB/TW
#2 North 0%	needs dusted from tail to 56 belt	Reported	TW
#3 North 0%	needs spot dusted	Reported	TW
#3 see #1 & #2	IDLE		
LBB	pic's & pumps clean at eye	none	JSC
Main Line	0% CH4 2% CO 20.8% O2 detected Track, trawlways, choppers, yamco lanes safe at eye Visual check of CD monitor ok at eye See board for notes		

SIGNED BY: Jim Boyer 32261
Belt Examiner Certificate No.

George Curry 27429
1659-A
Superintendent Certificate No.

COUNTERSIGNED BY: Rich Foster 28755
Mine Foreman Certificate No.
Mark Johnson 29611

EXAMINATION OF BELT CONVEYORS

On Shift

DATE 3-30-10

SHIFT DAY

TIME OF EXAMINATION: FROM 6:00

A.M. OR P.M. TO 4:00

OR P.M.

BELT CONVEYOR EXAMINED	Action Taken	EXAMINER
#1 South	cleaned on tail, filled & sand dust at floor thru tail cleaned on floor thru	JB
#1 North	Replaced idler at 19 but strain on belt same	JB
#2 North	TAIL was gobbled out at start of shift, shovelled both sides front & back 3 hours	TL
#3 North	dusted around head	TL

SIGNED BY:

Tom Sawyer
Belt Examiner

32261
Certificate No.

Jim Allen 1659-A
Superintendent

COUNTERSIGNED BY:

Rick Fort
Mine Foreman

28236
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Prestiff

DATE 3-30-10

SHIFT 2ND

TIME OF EXAMINATION:

FROM 8:00

A.M. OR P.M. TO 11:00

A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South	need some spot cleaning - 22-40 ft. need dusted	Rep.	TP
#1 North	3-20 ft. need spot dusted - wire mess need cut down 26-27 ft.	Rep.	TP
#2 North	need dusted 56 to tail	Rep.	TP
#3 North	need spot dusted - water & wet & muddy	Rep.	TP
#3 sec. 1 & 2	edge		
LBB	Pumps H/C's track clear at exam.	Rep. none	TP
Main Line	Pumps H/C's & P. B. S. track clear at exam.	Rep. none	TP
	No one lect. @ 20.800 COO's		
	Visual on CO's clear at exam		
	Pumps H/C's P. B. S. clear at exam		

SIGNED BY:

Ray Peterson
Belt Examiner

2964
Certificate No.

COUNTERSIGNED BY:

Rock Jeter
Mine Foreman

25734
Certificate No.

Superintendent

Certificate No.

Francis Cunniff 27419

EXAMINATION OF BELT CONVEYORS

On Shift

DATE 3-3-10

SHIFT 2nd

TIME OF EXAMINATION:

FROM 8:00

A.M. OR P.M. TO

11:00

A.M. OR P.M.

BELT CONVEYOR EXAMINED

EXAMINER

1 north

cut wire mess down on Belt 27 Bel. need
cut over belt

TR

refuse chamber 97 Belc. Phone clean at exam.

SIGNED BY:

[Signature]
Belt Examiner

29611

Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

28732

Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Free shift

DATE 3-31-10 SHIFT Owl TIME OF EXAMINATION: FROM 3:00 A.M. OR P.M. TO 6:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South 0%	and some spot cleaning in place 22-40 need dusted offside in place	Rps.	TP
#1 North 0%	3-20 box? need spot dusted - wire mess need out down	Rps.	TP
#2 North 0%	need dusted		
#3 North 0%	need spot clean - water in place	Rps.	TP
#3 sec, #1 & 2	sdhe		
LBB 0%	Pumps PLC's track clean at exam	none	TP
MAIN line 0%	Pumps PLC's D. Boxes clean at exam.	none	TP
	NoCH4 det. 0% 20.8 or CO 0%		
	Usual on CO's clean at exam.		
	Pumps PLC's D. Boxes clean at exam.		

SIGNED BY: [Signature] Belt Examiner Certificate No. 29611

COUNTERSIGNED BY: [Signature] Mine Foreman Certificate No. 28735

[Signature] 32261

Superintendent [Signature] Certificate No. 27429

EXAMINATION OF BELT CONVEYORS

Ow-Shift

DATE 3-31

SHIFT Ow/

TIME OF EXAMINATION:

FROM 12:15

(A.M.) OR P.M. TO 2:30

(A.M.) OR P.M.

BELT CONVEYOR EXAMINED	Action Taken	ACTION TAKEN	EXAMINER
# 1 south	dusted at take-up + to 3 Bkt.		TP
# 1 north	cut wire mess down at 26-27 Bkt.		TP
	cleaned rock off P/C at 52 Bkt. TP		
	Repair chamber 97 Bkt. + Phone clean at exam.		

SIGNED BY:

Ray Johnson
Belt Examiner

29611

Certificate No.

COUNTERSIGNED BY:

Rick Foster
Mine Foreman

28736

Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Pre shift

DATE 3-31-10 SHIFT DAY TIME OF EXAMINATION: FROM 1:00 OR P.M. TO 4:00 OR P.M.

BELT CONVEYOR EXAMINED	VIOLETIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South <i>CH4</i>	Needs some spot cleaning, <i>add</i> needs dusted 22-40 bit	Reported	JB
#1 North	Needs dusted 3-20 bit & haul area		JB
#2 North	Needs dusted	Reported	JSC
#3 North	fine valve needs plastic cap	Reported	JSC
#3 sec #1 & #2	out of service	Reported	JSC
LBB	power boxes, pumps, track clean at exam	None	HT
Main line	power boxes, pumps, track clean at exam	None	JSC HT
<i>CH4</i>	<i>CD</i> 50.8% <i>O2</i> detected		
	track, haul ways, chutes, power lines safe at exam		
	Visual check of CD monitor ok at exam		
	See board for rollers		

SIGNED BY: *Jim Boyer* Belt Examiner 3226 Certificate No. *George Jerry 27429* Superintendent *Harley Taylor 37002* Certificate No.

COUNTERSIGNED BY: *Rick Foster* Mine Foreman 28732 Certificate No. *Jim Peterson 29611* Certificate No.

EXAMINATION OF BELT CONVEYORS

On Shift

DATE 3-31-10 SHIFT Day TIME OF EXAMINATION: FROM 6:00 A.M. OR TO 4:00 OR P.M.

BELT CONVEYOR EXAMINED	Action Taken	EXAMINER
# 1 South	greased takeup, idler rollers, cleaned rollers	JB
# 1 North		
# 2 North		
# 3 North		

HT Refuse chamber dislodge at 97 Belt ok at 4pm

SIGNED BY: Jim Sawyer Belt Examiner 32261 Certificate No.

Harley Taylor 37602

COUNTERSIGNED BY: Rick Foster Mine Foreman 28236 Certificate No.

Superintendent _____ Certificate No. _____

EXAMINATION OF BELT CONVEYORS

Pre-Shift

DATE 3-31-10

SHIFT 2nd

TIME OF EXAMINATION:

FROM 8:00

A.M. OR P.M. TO

11:00

A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South O'Leary	need some spot cleaning - need add. rock dust at 22-40 ft.	Rep.	TP
#1 North O'Leary	need dusted 3-20 ft. + head area 36 ft. wire mess need cut down	Rep.	TP
#2 North O'Leary	needs dusting from 2N tail to ^{to} break away	Reported	BB
#3 North O'Leary	needs spot dusting wet + muddy in some places	Reported	BB
#3 sec. #1 + 2 O'Leary	OUT OF SERVICE		
LBB O'Leary	Pumps PLC's track clean at exam	none	TP
MAIN LIND O'Leary	Pumps PLC's D. Boxes clean at exam.	none	TP BB
	NoCH4 det. @ 20.5oz CO2		
	Visual on CO's clean at exam		
	Track + Travelways clean at exam.		
	Pumps PLC's D. Boxes clean at exam.		

SIGNED BY:

Amey Peterson
Belt Examiner
Bone Buehler

29011
Certificate No.
37079

COUNTERSIGNED BY:

Rich Foster
Mine Foreman

28735
Certificate No.

Superintendent

Certificate No.

Ow-Shift

EXAMINATION OF BELT CONVEYORS

DATE 3-31-10 SHIFT 2ND TIME OF EXAMINATION: FROM _____ A.M. OR P.M. TO _____ A.M. OR P.M.

BELT CONVEYOR EXAMINED	ACTION TAKEN		EXAMINER
1 South	add. belt away from bot. hanger Rk. 12		TP
1 North	Lusted on head area		TP
[#] 2 North	cleaned on #2 North V plow up to first bottom roller		BB
	Refuse Chamber 97 Rk. & Phone clear at exam		TP

SIGNED BY: Bruce Byler 37074
[Signature]
Belt Examiner Certificate No. 29611

COUNTERSIGNED BY: [Signature]
Mine Foreman Certificate No. 29736
Superintendent Certificate No. _____

EXAMINATION OF BELT CONVEYORS

Pre-Shift

DATE 4-1-10 SHIFT CWL TIME OF EXAMINATION: FROM 300 A.M. OR P.M. TO 600 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South CH4 0% O2	needs some spot cleaning needs a del Rock dust	Reported	TP
#1 North CH4 0% O2	36BK wire mesh needs cut down needs dusted 3 BK to 20 BK	Reported	TP/BB
#2 North CH4 0% O2	needs dusted from 2 N tail up to 3 BK in by (corrected) BB needs spot cleaning & spot cleaning	Dusted by Hand	BB
3 North CH4 0% O2	needs spot dusting wet in places	Reported	BB
#3 Sec 1 & 2 Belts CH4 0% O2	Out of Service		
LBB CH4 0% O2	Pump Powerbox Track OK at time of exam	Reported	TP
Mainline CH4 0% O2	Pump Powerbox Drive Track OK at time of exam	Reported	TP BB
	Visual chkd CO'S OK at time of exam	Reported	TP BB
	Track, Traxwrap Pump, Powerbox, Drive OK at T O EXAM	Reported	TP

SIGNED BY: [Signature] 37074
 Belt Examiner Certificate No.

[Signature] 1659A

COUNTERSIGNED BY: [Signature] 28736
 Mine Foreman Certificate No.

[Signature] 39199 Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

On-Shift

DATE 4-1-10 SHIFT OWL TIME OF EXAMINATION: FROM _____ A.M. OR P.M. TO _____ A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED <i>ACTION TAKEN</i>	ACTION TAKEN	EXAMINER
#1 south	washed tail out - gobbled out		TD
#1 north	hooped T. Duster 2 X's dusted Head area + tail		TP
#2 North	Cleaned on 2N tail again V-plow Hand Dusted 2N tail & 3BK above 2N tail		BB
	Hung a curtain in front of PowerBox at 2North		BB
	cleaned on 1N V-plow		BB
3 North	Hand dusted 3N Head, take-up down to track Dusted 3N Belt from track to stopping		BB
	Hung up line before 3N Head out of the mantrips way		BB
	Put curtain in front of PowerBox at 3N Head		BB
	cleaned dust off top of Powerbox 3N		
	Refuse Charles 9756's Phone cleaning exam Reported		TP

SIGNED BY:

Bruce Bracker
Belt Examiner

37074
Certificate No.

COUNTERSIGNED BY:

Rich Foster
Mine Foreman

28736
Certificate No.

Superintendent

Certificate No.

