

South Side Belts

Started 3-16-10

**EXAMINATION OF
BELT CONVEYORS**

Started 3-16-10
Full 3-24-10

COMPANY Performance Coal
MINE UBB
LOCATION NAOMA RATERGH WV
Post Office County State

Re-order #9980 from

Quality Forms Printing
P.O. Box 861
Sophia, WV 25921
(304) 252-1363

EXAMINATION OF BELT CONVEYORS

DATE 3-16-10 SHIFT 2ND TIME OF EXAMINATION: FROM 8:00 A.M. OR P.

R-11

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION	
1 SOUTH	need spot clean + add. rock dust	Rep.	
1 NORTH	need dusted 17 ft.	Rep.	TP
2 NORTH	none observed	Rep.	TP
3 NORTH	none observed	Rep.	TP
Sec #3 #1	need spot clean + dusted	Rep.	TP
Sec #3 #2	none observed	none	TP
LBB	P/C's pumps clean at exam. water on rock 4 ft.	being pumped	TP
mine line	pumps P/C's D. Box's charger clean at exam.	none	TP
Visual on co's	clean at exam.		
Pumps P/C's D. Box's Charger	clean at exam.		
Tracks traveling off	clean at exam.		
		Refuse Chamber 97 ft. clean + phone at exam.	TP

SIGNED BY: [Signature] Belt Examiner Certificate No. 29611

COUNTERSIGNED BY: [Signature] Mine Foreman Certificate No. 28732
 Superintendent Certificate No. _____

EXAMINATION OF BELT CONVEYORS

Pre Shift

DATE 3-17-10

SHIFT Owl

TIME OF EXAMINATION:

FROM 3:00

A.M. OR P.M. TO

6:00

A.M. OR P.M.

DATE

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 south	need spot clean + spot dusted in place	Rep.	TP
1 worth	need spot clean + dusted 17 Lk. to 17 Pak.	Rep.	TP
2 north	none observed	none	TP
3 north	none observed	none	TP
3 sec. #1	need spot clean + spot dusted	Rep.	TP
#2	out of service	none	TP
LBB	Pumps Pk's clear at exam. Water on track 4 Lk. - being pumped	being pumped	TP
Main line	Pumps Pk D. Boxes charge clear at exam.	none	TP
	77 Lk. Pump - no power	none	TP
	NOCH4 det. 0% 20.82 CO2		
	Visual on CO's clear at exam.		
	Pumps Pk's D. Boxes charge clear at exam.		
	Track + branchways on main line clear at exam.		
	Water on track 4 Lk. LBB Track need block on 3 sec, 33 Lk.		

SIGNED BY:

[Signature]

Belt Examiner

24611

Certificate No.

COUNTERSIGNED BY:

[Signature]

Mine Foreman

28736

Certificate No.

Superintendent

Certificate No.

[Signature] 32261

[Signature] 27429

EXAMINATION OF BELT CONVEYORS

Pre Shift

DATE 3-17-10

SHIFT DAY

TIME OF EXAMINATION: FROM 1:00

OR P.M. TO 4:00

OR P.M. DATE

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER	BE
1 South	Heads not cleaning, heads not dusted	Reported	JB	1 S
1 North	Heads not cleaning, wire rope cut down 26, 36 & 2 Heads some spot cleaning, heads dusted head-17	Reported	JB	
2 North	none observed	none	JSC	
3 North	none observed	none	JSC	
3 sec #1	Fire Run	Reported	JSC	
#2	Out of service (main section)			
LBB	Jump, power loose, clear at exam	None	HT	
Main line	water over track at 4 Bsk (being pumped)	being pumped		
	Jump, power loose boxes changed safe at exam	None	HT	
	2% CH ₄ 2% CO 20.8% O ₂ detected			
	track, travelways, power loose, changes safe at exam			
	Visual check of CO monitor ok at exam, See head log for rollers			
	track needs blocked 3 sec 27-28 Bsk			

SIGNED BY: George Curry 27479 Certificate No. Jim Sawyer 52261 Harley Taylor 37002
 Belt Examiner
 COUNTERSIGNED BY: Rick Foster 28734 Certificate No. Ray Peterson 29611
 Mine Foreman
 Superintendent
 Certificate No.

EXAMINATION OF BELT CONVEYORS

ON SHIFT

DATE 3-17-10

SHIFT

Day

TIME OF

~~EXAMINATION~~ ON SHIFT

FROM

6:00

A.M. OR P.M. TO

4:00

BELT CONVEYOR EXAMINED

VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED

#1 South

cleaned spillage at floor transfer

greased bearings

JR

SIGNED BY:

Tom Boyer
Belt Examiner

32261
Certificate No.

COUNTERSIGNED BY:

Redd Z...
Mine Foreman

28736
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-18-10 SHIFT owl TIME OF EXAMINATION: FROM 3:00 A.M. OR P.M. TO 6:00 A.M. OR P.M. DATE

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER	B
<u>1 south</u>				
<u>1 north</u>				
<u>2 north</u>	<u>No one inside. Fan down</u>			
<u>3 north</u>				
<u>3 sec. #1</u>				
<u> #2</u>				
<u>LBB</u>				
<u>Main line</u>				

SIGNED BY:

Belt Examiner

Certificate No.

COUNTERSIGNED BY:

Rick Fater

Mine Foreman

28236

Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

1. OR P.

SHIFT _____

TIME OF EXAMINATION: FROM _____

FROM _____

A.M. OR P.M. TO _____

A.M. OR P.M.

MINER _____

CONVEYOR
EXAMINED

VIOLATIONS AND OTHER HAZARDOUS
CONDITIONS OBSERVED

ACTION TAKEN

EXAMINER

SIGNED BY:

Belt Examiner

Certificate No.

COUNTERSIGNED BY:

Mine Foreman

Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-18-10 SHIFT Day TIME OF EXAMINATION: FROM 6:30 A.M. OR P.M. TO 8:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South <u>0%</u>	<u>Needs spot cleaned and additional dusting see board for notes</u>	<u>Reported</u>	<u>J.B.</u>
1 North <u>0%</u>	<u>None observed</u>	<u>None</u>	<u>L.S.</u>
2 North <u>0%</u>	<u>Needs spot cleaned & dusted</u>	<u>Reported</u>	<u>J.W.</u>
3 North <u>0%</u>	<u>Water at head</u>	<u>Reported</u>	<u>J.W.</u>
3 Sect #1 <u>0%</u>	<u>Needs spot cleaned & dusted</u>	<u>Reported</u>	<u>SLC</u>
<u>L.B.B.</u> <u>0%</u>	<u>Clear up to 3x cut. H₂O over track at 3x cut</u>	<u>Dangrad off 3x cut</u>	<u>HT</u>
<u>Mainline</u> <u>0%</u>	<u>Pumps, power center, choppers D-Boxes clear at time of exam. 20800, 0%CH, 0%CO 97x cut refuge chandeliers OK at time of exam. Phone OK.</u>		<u>HT</u>

SIGNED BY:

Greg Cole
Belt Examiner

1947-A
Certificate No.

Jim Bayen 32261
Jay Stamat 39199

COUNTERSIGNED BY:

Rick Fater
Mine Foreman

2873C
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

M. OR P. SHIFT TIME OF EXAMINATION: FROM A.M. OR P.M. TO A.M. OR P.M.

MINER	BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER

SIGNED BY: _____
Belt Examiner Certificate No. _____

COUNTERSIGNED BY: _____
Mine Foreman Certificate No. _____
Superintendent Certificate No. _____

EXAMINATION OF BELT CONVEYORS

PRE shift

DATE 3-18-10 SHIFT DAY TIME OF EXAMINATION: FROM 1:00 A.M. OR (P.M.) TO 4:00 A.M. OR (P.M.) DATE

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER	BE
#1 South <u>Chy</u> <u>0%</u>	<u>Needs spot cleaned, Needs spot dusted 16-tail</u>	<u>Reported</u>	<u>JB</u>	<u>#1</u>
#1 North <u>0%</u>	<u>Needs dusted head-17 Bk, Needs coal brags cleaned various spots, wire mesh needs cut down 26, 36</u>	<u>Reported</u>	<u>JB/LS</u>	<u>#1</u>
#2 North <u>0%</u>	<u>Need Spot Dusted and Spot Cleaned</u>	<u>Reported</u>	<u>LS</u>	<u>#2</u>
#3 North <u>0%</u>	<u>needs dusted from track to tail</u>	<u>Reported</u>	<u>TW</u>	<u>#3</u>
	<u>Water Around take-up</u>	<u>Reported</u>	<u>TW</u>	
3Sec #1 <u>0%</u>	<u>Section Moving, Belt still under construction, Needs Spot Dusted and Spot cleaned</u>	<u>Reported</u>	<u>LS</u>	<u>3J</u>
3Sec #2	<u>out of service</u>			<u>3J</u>
LBB	<u>Powercenter & pump clear at T.O.E.</u>	<u>Reported</u>	<u>TW</u>	
	<u>Water over track at #4 Bk</u>	<u>Damaged off track</u>	<u>TW</u>	
Mainline	<u>Powercenters, pumps, d-boxes, track at travelway's clear at T.O.E.</u>	<u>Reported</u>	<u>TW</u>	
	<u>0% Chy, 20.8% Op, 0% Co See board for rollers</u>			

SIGNED BY:

Jim Williams
Belt Examiner

1659-A
Certificate No.

Jim Boyce 32261
Lacy Stewart 39199

COUNTERSIGNED BY:

Jim Beck Foster
Mine Foreman

2873L
Certificate No.

Superintendent

Certificate No.

Jim Beck Foster
29611

Harley Taylor 37002

EXAMINATION OF BELT CONVEYORS

ON-SHIFT

M

DATE 3-18-10

SHIFT DAY

TIME OF EXAMINATION: FROM 6:00

A.M. OR P.M. TO 4:00

A.M. OR P.M.

BELT CONVEYOR EXAMINED	Action Taken		EXAMINER
#1 South	dusted head - 12, dusted tail area 7 in dust at tail		JB
#1 North	dusted around head area		JB
#2 North			
#3 North	serviced head, dusted at head & power roller		TW
3 Sec #1			
3 Sec #2			
LBB			
MA-Link	water over track at #4 belt safety chamber at 97 belt & phase ed at drum TW	Set 110 pump at 5 belt	TW

SIGNED BY:

Jim Williams
Belt Examiner

1659-A
Certificate No.

Jim Boyner 32261

COUNTERSIGNED BY:

Rick Foster
Mine Foreman

28736
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Preshiff

DATE 3-18-10

SHIFT 2nd

TIME OF EXAMINATION:

FROM 8:00

A.M. OR P.M. TO

11:00

A.M. OR P.M.

DATE

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER	BI
1 North	need spot clean - need spot dusted 16-tail	Rep.	TP	
1 North	need dusted 7 Bk. - 14 Bk.	Rep.	TP	
2 North	need spot clean & spot dusted in place	Rep.	BB	
3 North	need dusted - track to tail	Rep.	BB	30
3 Sec. #1	need spot clean & spot dusted	Rep.	BB	47
Sec. 3 #2	out of service	Rep.	BB	
h BB	Pumps Plc's clear at exam. water on track 4 Bk. - being pumped	Rep. none	BB	
MAIN LINE	Pumps Plc's D. Bors charger clear at exam.	none	TP	
No CH4 det. 0% 20,502 @ 00%				
Visual on CO's clear at exam.				
Pumps Plc's D. Bors Charger clear at exam				

SIGNED BY:

Jim Peterson 29611
Belt Examiner Certificate No.

COUNTERSIGNED BY:

Rick Foster 37074
Mine Foreman Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

On Shift

V. OR P. 18-16 SHIFT ENE TIME OF EXAMINATION: FROM _____ A.M. OR P.M. TO _____ A.M. OR P.M.

MINER CONVEYOR EXAMINED	Action Taken	ACTION	EXAMINER
1 South	Dusted at tail & ground tail		TP
1 north	dusted head & part take-up		TP
	cleaned up rock in walkway in place		TP
3Sec / Belt	Rock dusted in by 27BK to just out by 35BK on 3Sec / Belt (Horn Dusted)		BB
3Sec / Belt	cleaned up trash along 3Sec belt 27BK to 34BK		BB
LBB	moved pump over away from track (water is pumping down) & hung discharge line up away from track so you can get a man tip by discharge line		BB

*Refuse Chamber 97 BK clear at exam
Phone OK*

SIGNED BY:

[Signature]
Belt Examiner

29611

Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

28736

Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Pre-shift

DATE 3-19-10 SHIFT OWL TIME OF EXAMINATION: FROM 3:00 A.M. OR P.M. TO 6:00 A.M. OR P.M. DATE

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
# 1 south	need spot spot cleaning needs dusting 16 tail	Reports	TP
# 1 north	needs dusting 7BR - 14BR	Reports	TP
# 2 north	Needs spot cleaning spot cleaning in places	Reports	BB
# 3 north	needs dusting track to tail	Reports	BB
# 3 sec #1	needs some spot dusting + spot cleaning	Reports	BB
# 3 sec #2	needs out of service	Reports	BB
LBB	Pumps, Powercenter, D Boxes, chargers clear at times of extra LBB water on track being pumped	High up of ischans a moved pump line	BB
Main line	Pumps, P/C's, D Boxes, chargers clear at times of NOCH4 20% CO2 Visual check CO's OK at times of extra	None	TP

SIGNED BY:

Pue Brato 32011
Belt Examiner

Certificate No.

COUNTERSIGNED BY:

Rick Foster
Mine Foreman

23236
Certificate No.

Superintendent

Certificate No.

Tom Stewart 39199

EXAMINATION OF BELT CONVEYORS

Ow-Shift

DATE 3-19-10

SHIFT Owl

TIME OF EXAMINATION:

FROM 11:40

AM. OR P.M. TO 2:30

A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS ACTIONS TAKEN		EXAMINER
1 south	washed nipac roller out & washed tail out hooded & dusted & run - dusted 1 south tail & 1 north hood & take up		TP
1 north	moved rock out of way on walkway side in places 1 north belt cleaned p/c box off 78 BK.		TP
35ae #1 Belt	Rock dusted from 18 BK to just out by 35 BK	Reported	BB
35ae #1 Belt	cleaned trash - up along beltline 27 BK to 34 BK	Reported	BB
LBO	moved pump & rehung discharge line ^{away from track} Hung up signs at 7 & 22 Power boxes	Reported	BB
		Reported	BB
	Refuse Chamber 97 BK clean at times even Phone working OK	Reported	TP

SIGNED BY:

[Signature]
Belt Examiner

29611
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

2873L
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Preshift

DATE 3-19-10 SHIFT DAY TIME OF EXAMINATION: FROM 1:00 A.M. OR P.M. TO 4:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER	BI
1 South ^{CH4} 0%	Needs some spot cleaning, Needs spot dusting 16-tail	Reported	JB	1
1 North 0%	Needs dusted 3-17 Brk, walkways need some cleaning, mine road need cut down, 26, 36 Brks	Reported	JB/LS	3
2 North 0%	Need Spot Dusted and Spot Cleaned	Reported	LS	
3 North 0%	Need Spot Cleaned and Spot Dusted	Reported	LS	
3 Sec #1 0%	Need Spot Cleaned and Spot Dusted	Reported	LS	
3 Sec #2 0%	Out of Service			
LBB	POWER BOXES OK AT TOE TRACK WATER DOWN AT 4BK	Removed DANGER BOARD	HT	
MAINLINE	TRACK, POWER CENTERS, CHANGERS, D. BOXES OK AT TOE	NONE	HT	

SIGNED BY:

Jay Stenat
Belt Examiner

39199
Certificate No.

Jim Boyce 32261 Harley Taylor 37002

COUNTERSIGNED BY:

Rick Foster
Mine Foreman

26731
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

ON Shift

A.M. OR P.M. DATE 3-19-10 SHIFT DAY TIME OF EXAMINATION: FROM 6:00 A.M. OR P.M. TO 4:00 A.M. OR P.M.

AMINER	BELT CONVEYOR EXAMINED	Action Taken		EXAMINER
	<u>1 South</u>	<u>cleaned V-pulley spillage, saw dust at tail</u>		<u>JB</u>
	<u>1 North</u>	<u>ran dust at head</u>		<u>JB</u>
<u>LS</u>	<u>3 Sec # 1</u>	<u>filled & saw dust at 22 B.K</u> <u>put up a guard between track & belt at mouth of section</u>		<u>JB, LS, TU</u>

SIGNED BY: Jim Sawyer Certificate No. 32261
Belt Examiner

COUNTERSIGNED BY: Rich Kater Certificate No. 29736
Mine Foreman Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-19-10 SHIFT EVE TIME OF EXAMINATION: FROM 800 A.M. OR P.M. TO 1100 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South ^{CHY} 0%	needs some spot cleaning, needs spot ducting 16-tail	Reported	BB
1 North 0%	needs ducted 3-17 BK walkway needs some cleaning wire mesh ^{needs} need cut down 26 & 36 BK's	Reported	BB
2 NORTH 0%	Needs spot Ducted and spot cleaning	Reported	BB
3 North 0%	Needs spot cleaned & spot ducted	Reported	BB
3 Sec #1 0%	Needs spot cleaning & spot ducted	Reported	BB
3 Sec #2 0%	Out of Service		
LBB	Powerboxes: pumps ok at time of exam	Reported	BB
		checked pumps at 21 BK	BB
Mainline	Tread, Powercenter, chongare, D-Boxes ok at time of exam	Reported	BB

SIGNED BY: Bruce Brackett 37074
Belt Examiner Certificate No.

COUNTERSIGNED BY: Bush Faler 28736
Mine Foreman Certificate No. Superintendent

EXAMINATION OF BELT CONVEYORS

M. DATE 3-19-10 SHIFT EVE TIME OF EXAMINATION: FROM 800 A.M. OR P.M. TO 1110 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
<u>2 North</u>	<u>checked top roller 56 BK</u>	<u>Reported</u>	<u>BB</u>
<u>2 BB</u>	<u>checked pump at 21 BK kept pump running</u>		
	<u>Refuse Chamber - Phone ok at time of exam</u>	<u>Reported</u>	<u>BB</u>

SIGNED BY: *Bruce Brantley* 37074
 Belt Examiner Certificate No.

COUNTERSIGNED BY: *Resh Foster* 2873 _____
 Mine Foreman Certificate No. Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-20-10 SHIFT OWL TIME OF EXAMINATION: FROM 145 ~~A.M.~~ OR P.M. TO 317 ~~A.M.~~ OR P.M. DATE

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South	Belt's Idle		
1 North	<p>Fire RUN 3-20-10</p> <p>All Belts clear at time of exam</p> <p>0% CH₄ CO₂ OK 20.89% O₂</p>	Reported	BB
2 North			
3 North			
3 Sec #1	<p>3 Sec #1 Belts Idle</p> <p>#1 Belt clear CO₂ OK</p> <p>Fire RUN at time of exam CH₄ 0% O₂ 20.89%</p>	Reported	BB
3 Sec #2	#2 Belt out of service 3-20-10		
LBB			
Mainline			

SIGNED BY:

Bruce Bradett
Belt Examiner

37074
Certificate No.

COUNTERSIGNED BY:

Paul Foster
Mine Foreman

2873
Certificate No.

Superintendent

Certificate No.

Larry D. Wood 39199

George Curry 27429

EXAMINATION OF BELT CONVEYORS

M. OF _____ SHIFT _____ TIME OF EXAMINATION: FROM _____ A.M. OR P.M. TO _____ A.M. OR P.M.

MINER	CONVEYOR	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
3500	#1 Belt	cut flapper off Belt about 18" long 1 clip wide	Reported	SB

SIGNED BY: *Donna Bradlett* 37074
 Belt Examiner Certificate No.

COUNTERSIGNED BY: *Rick Foster* 28236 _____
 Mine Foreman Certificate No. Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-20-10 SHIFT DAG TIME OF EXAMINATION: FROM 1200 A.M. OR P.M. TO 300 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER	BE
1 south	Belt's Idle	Reported	JSC	
1 north	Power Row, pc's - D Boxes		LS	
2 north	clean at rear			
3 north	% CH ₄ - % CO - 20.8% O ₂			
3 sec #1	Belt's Idle power no power	Reported	JSC	
LBB	Tracks, Power Boxes OK AT TOE	NONE	HT	
Mainline	pumps, pc's, D-Boxes clean at rear	none	JSC HT	
	Rezeze chamber at 97BK OK at rear			
	mine phone in working order (JSC)			

SIGNED BY: George Curran Belt Examiner Certificate No. 27429

COUNTERSIGNED BY: Rick Foster Mine Foreman Certificate No. 28732

Jerry Stewart 39199
Harley Taylor 37002

Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

M. OF _____ SHIFT _____ TIME OF EXAMINATION: FROM _____ A.M. OR P.M. TO _____ A.M. OR P.M.

MINER NO.	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER

SIGNED BY:

Belt Examiner _____ Certificate No. _____

COUNTERSIGNED BY:

Mine Foreman _____ Certificate No. _____

Superintendent _____ Certificate No. _____

EVE EXAMINATION OF BELT CONVEYORS

DATE 3-20-10 SHIFT ~~DAY~~ *CP* TIME OF EXAMINATION: FROM 800 A.M. OR P.M. TO 1100 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South 1 North	Belts Idle		
1 North	Power run powerboxes D-Boxes	Reported	BB
2 North	clear at time of exam OUCHA 0900 2089002		
3 North			
 3Sec. #1	Belts Idle No power going to 3 section	Reported	BB
 LBB	Trade powerboxes & pumps ok at time of exam	Reported	BB
 Mainline	pumps powerboxes D-Boxes ok at time of exam	Reported	BB
	Refuge chamber 97BK & phone ok at time of exam	Reported	BB

SIGNED BY: *Bruce Brantley* 37074
Belt Examiner Certificate No.

COUNTERSIGNED BY: *Rick Foster* 28736 Superintendent Certificate No.
Mine Foreman

EXAMINATION OF BELT CONVEYORS

M.

DATE 3-20-10

SHIFT EVE

TIME OF EXAMINATION:

FROM 500

A.M. OR P.M. TO 1100

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
2 North	greased on 2N Head, take-up; 1N tail need to replace grease hoses on 2N take-up roller that doesn't move Hoses won't take grease	Reported	BB

SIGNED BY:

Bruce Brault
Belt Examiner

37074
Certificate No.

COUNTERSIGNED BY:

Rick Foster
Mine Foreman

2873
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-21-10 SHIFT OWL TIME OF EXAMINATION: FROM 300 A.M. OR P.M. TO 600 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South 1 North 2 North 3 North	Belt idle Power Run, powerboxes & D-Boxes & pumps OK at time of exam	Reported	BB
3 Sec #1	Belt idle No power going to #3 Section	Reported	BB
4BB	Track, powerboxes & pumps OK at time of exam	Reported	BB
Mainline	pumps, powerboxes, D-Boxes & pumps OK at time of exam	Reported	BB
	Refuge Chamber 97BK & phone working at time of exam	Reported	BB

SIGNED BY: Bruce Bradlett 37074
Belt Examiner Certificate No.

COUNTERSIGNED BY: Rich Foster 2823
Mine Foreman Certificate No.

Inc. & Permit 39199

Superintendent Certificate No.

Isaac Curra 27429

EXAMINATION OF BELT CONVEYORS

DATE _____ SHIFT _____ TIME OF EXAMINATION: FROM _____ A.M. OR P.M. TO _____ A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
35sec	Got scoop that was down by rock detector trammed scoop up to #3 Sec. scoop in section #3		BB

SIGNED BY: *Bruce Brubaker* 37074
 Belt Examiner Certificate No.

COUNTERSIGNED BY: *Rick Foster* 2873 _____ _____
 Mine Foreman Certificate No. Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-21-10 SHIFT Day TIME OF EXAMINATION: FROM 12 A.M. OR PM TO 3 A.M. OR PM

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South	Belts Idle		GC
1 North		Reported	GC
2 North			LS
3 North			LS
3 Section #1	Belts Idle, NO Power, Dangered off of the Mouth of Section.	Reported	GC
LBB	Track, PC, Pumps OK At Exam	Reported	GC
Main Line	PC, D-Boxes, Pumps clear at exam	Reported	LS/GC
	97 BK Refuse clear at exam	Reported	LS

SIGNED BY: Jacy Stewart
Belt Examiner

39199
Certificate No.

George Curry 27429

COUNTERSIGNED BY: Rock Foster
Mine Foreman

28736
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-21-10

SHIFT Day

TIME OF EXAMINATION:

FROM 6

4 A.M. OR P.M. TO

A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
<u>2 North</u>	<u>Dusted from Head to tail</u>	<u>Reported</u>	<u>LS</u>

SIGNED BY:

Jac. Alenast
Belt Examiner

39199
Certificate No.

COUNTERSIGNED BY:

Bob Foster
Mine Foreman

28736
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-21-10 SHIFT 2nd TIME OF EXAMINATION: FROM 8:00 A.M. OR P.M. TO 11:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 south	needs spot cleaning needs spot dusting	Reported	BB
1 north	needs dusting 3-17BK walkway needs some cleaning wire mesh needs cut down 26° 36BK	Reported	BB
2 north	needs spot cleaning	Reported	BB
3 north	Needs spot cleaning spot dusting	Reported	BB
3 sec. #1	Needs spot cleaning spot dusting	Reported	TP
LBB	Powerbox, pumps: track ok time of exam	Reported	TP
MAIN LINE	Track, Powercenter, choppers D-Boxee clear at time of exam	Reported	TP
	Refuse Chamber 97BK's phone works ^{ok at time of exam}	Reported	TP

SIGNED BY: Bone [Signature] 37074
 Belt Examiner Certificate No.

COUNTERSIGNED BY: Rick Foster 28732
 Mine Foreman Certificate No. Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE _____ SHIFT _____ TIME OF EXAMINATION: FROM _____ A.M. OR P.M. TO _____ A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER

SIGNED BY: _____
Belt Examiner _____ Certificate No. _____

COUNTERSIGNED BY: _____
Mine Foreman _____ Certificate No. _____ Superintendent _____ Certificate No. _____

EXAMINATION OF BELT CONVEYORS

DATE 3-22-10 SHIFT OWL TIME OF EXAMINATION: FROM 300 A.M. OR P.M. TO 600 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
<u>1 south</u>	<u>need spot clean & dusted in place</u>	<u>Rep.</u>	<u>TP</u>
<u>1 north</u>	<u>walkway need spot clean in place</u>	<u>Rep.</u>	<u>TP</u>
<u>2 north</u>	<u>need spot clean</u>	<u>Rep.</u>	<u>BB</u>
<u>3 north</u>	<u>need spot clean & spot dusted</u>	<u>Rep.</u>	<u>BB</u>
<u>3 sec. #1</u>	<u>need spot clean & spot dusted</u>	<u>Rep.</u>	<u>BB</u>
<u>LBB</u>	<u>Pumps P/c's track clean at exam.</u>	<u>none</u>	<u>BB</u>
<u>Mainline</u>	<u>Pumps P/c's D. Bors charger clean at exam.</u>	<u>none</u>	<u>TP</u>

Refuse Grubber 97BK's Phone

SIGNED BY: [Signature] 29611
 Belt Examiner Certificate No.
Bruce Brault 37074

COUNTERSIGNED BY: [Signature] 28734
 Mine Foreman Certificate No.

Superintendent Certificate No.

[Signature] Jacy Stewart 39199

[Signature] George Curran 27429

EXAMINATION OF BELT CONVEYORS

DATE 3-22-10 SHIFT owl TIME OF EXAMINATION: FROM 3:00 A.M. OR P.M. TO 6:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
<u>1 North</u>	<u>Iron belt at 24 hlk. belt rubbing hangers in 2 places</u>	<u>corrected</u>	<u>TP</u>
<u>2 North</u>	<u>cleaned up All kind of trash around #2 North Head, take-up under the belt most belt pieces that were around yard & belt is put in BK where cribs are I also dusted around north tail. I put dust in the duster by the truck. We let dust run most of the shift. Got duster off on the way out.</u>	<u>Cleaning up around Head area 2 North</u>	<u>BB</u>
<u>3 sec. #1</u>	<u>Dusted belt head & take-up - hooded to duster</u>		<u>TP</u>
	<u>Best work, should not be belt line at 39, #1, #2, & #3 & cut over north of #7 set 4 seal pads at 55' x 100'</u>		
	<u>Visual on CO's clear at exam.</u>		
	<u>Pumps P/C's D. Boxes Clear at exam</u>		
	<u>Tracks & Trambways clear at exam</u>		

SIGNED BY:

[Signature]
Belt Examiner 29611
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman 28736
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Pre-Shift

DATE 3-22-10 SHIFT DAY TIME OF EXAMINATION: FROM 100 A.M. OR PM TO 400 A.M. OR PM

BELT CONVEYOR EXAMINED		VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South	0%	Needs spot dusted 22-40 Needs some spot cleaning, taking needs some cleaning & dusting	Reported	JB
#1 North	0%	Needs add dusting especially off side 3-20 Bkt Needs wire mesh cut down 26 & 36 Bkts (walkways need spot cleaning)		JB
2 North	0%	Need Spot Cleaned	Reported	LS
3 North	0%	Need Spot Cleaned and Dusted	Reported	LS
3 sec #1	0%	Need Spot Cleaned and dusted	Reported	LS
See board for Rollers				
LBB		pumps - pc's clear at rear	none	JSC
Mainline		pumps - pc's - shoes clear at rear	none	JSC
		Refuge chamber at 97 BK clear at rear. Mine phone in working order	none	JSC

SIGNED BY: George Curry 27429
Belt Examiner Certificate No.

Joy Stewart 39199
Tom Sawyer 32261

COUNTERSIGNED BY: Mark Pate 28236
Mine Foreman Certificate No.
Mark Potman 79611

Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

ON Shift

DATE 3-22-10 SHIFT DAY TIME OF EXAMINATION: FROM 6:00 A.M. OR ~~P.M.~~ TO 4:00 ~~A.M.~~ OR P.M.

BELT CONVEYOR EXAMINED			EXAMINER
#1 South	Dusted 16-22 Bk cleaned rollers at 24 & 6 Bk, cleaned V-belt at yellow thru trail		JB
#1 North	Best work & shoveled rock on belt line at 39 Bk, 41, 42, & 43		RF
2 North	set 4 road yokes at 55 Bk		RF
3 North			
3 Sec #1			

SIGNED BY: Jim Boyer 32261
Belt Examiner Certificate No.

COUNTERSIGNED BY: Rick Peter 29736
Mine Foreman Certificate No. Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-22-10 SHEET 2ND TIME OF EXAMINATION: FROM 8:00 A.M. OR P.M. TO 11:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South O70CH4	need spot checked 22-40 mt, need some spot cleaning take-up need add. rock dust	Rep.	TP
1 North O70CH4	3-20 mt. off side need add. rock dust	Rep.	TP
2 North O70CH4	need spot clean	Rep.	TP
3 North O70CH4	need spot clean & dusted	Rep.	TP
3 sec. #1 O70CH4	need spot clean & dusted	Rep.	TP
LBB O70CH4	Pumps & P's track clean at exam.	none	TP
MAIN line O70CH4	Pumps & P's D. Box's Chaugun clean at exam.	none	TP

SIGNED BY: [Signature] Certificate No. 29611
 Belt Examiner

COUNTERSIGNED BY: [Signature] Certificate No. 28736 Superintendent
 Mine Foreman

Certificate No.

EXAMINATION OF BELT CONVEYORS

3-22-10

SHIFT 2nd

TIME OF EXAMINATION:

FROM 8:30

A.M. OR P.M. TO

11:00

A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
	<p>Noct & Sect. Ob 20,002 COOB</p> <p>Visal on CO's clear at exam.</p> <p>Pumps PLC's D. ROXS charging clear at exam</p>		
	<p>Refuse chamber bet. 97 & phone</p> <p>clear at exam.</p>		

SIGNED BY:

[Signature]

Belt Examiner

29611

Certificate No.

COUNTERSIGNED BY:

[Signature]

Mine Foreman

28736

Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 3-23-10 SHIFT Over TIME OF EXAMINATION: FROM 3:00 A.M. OR P.M. TO 6:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLETIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South O'Lochy	need spot dusted 22-40 ft. need some spot cleaning & dust take-up need dusted	Rep.	TP
1 North O'Lochy	3-20 ft. off sideward odd. rock dust	Rep.	TP
2 North O'Lochy	need spot clean in place	Rep.	TP
3 North O'Lochy	need spot clean & dusted (wet & water in place)	Rep.	TP
3 sec. #1 O'Lochy	need spot clean & spot dusted in place	Rep.	TP
LBB O'Lochy	Pumps PLC's track clean at exam.	None	TP
Main line O'Lochy	Pumps PLC's D. Boxes Charge clean at exam.	None	TP
	NoCH4 det. O ₂ 20.8oz CO ₂		
	Visual on Co's clean at exam.		
	Pumps PLC's D. Boxes Charge clean at exam.		

SIGNED BY: [Signature] 29611
Belt Examiner Certificate No.

COUNTERSIGNED BY: [Signature] 28732
Mine Foreman Certificate No.

Superintendent [Signature] Certificate No. 27429

[Signature] 32711

EXAMINATION OF BELT CONVEYORS

3-23-10

SHIFT 0w1

TIME OF EXAMINATION:

FROM 12:05 Am A.M. OR P.M. TO 2:30

A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
<u>1 North</u>	<u>Loaded T. Duster & Run - green tail & st. on take up.</u>		<u>TP.</u>
<u>2 North</u>	<u>Helped Ceel unload Bag dust at T. Duster & Run Duster</u>		<u>TP</u>
	<u>Whee Chamber Picker #2 & Phone clean at exam.</u>		

SIGNED BY:

[Signature]
Belt Examiner

29611
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

28236
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Yre Shift

DATE 3-23-10 SHIFT DAY TIME OF EXAMINATION: FROM 1:00 ~~AM~~ OR P.M. TO 4:00 ~~AM~~ OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South <u>CH4</u>	0% needs spot cleaning. Needs spot dusted 22-40Buk	Reported	JB
#1 North	0% 3-20 Buk needs add dusting (mostly offside) walkways and some cleaning, wear mark 26 Buk needs cut down	Reported	JB
#2 North	0% needs spot cleaned	Reported	JSC
#3 North	0% Needs spot cleaned (w/ tin of lacquer)	Reported	B.D.
3 See #1	0% needs spot cleaned; dusted	Reported	JSC
LBB	pumps: pc's clean at sea	NONE	JSC HT
Main Line	pumps: pc's & bores clean at sea	NONE	JSC HT
	0% CH4 0% CO 20.8% O2 detected track, travelways, chutes, spawer boxes safe at spaw Visual check of CD monitor ok at spaw See hand you rollers		

SIGNED BY:

Jim Boyner
Belt Examiner

32261
Certificate No.

George Curry 27429
Belt Examiner 11764

Harley Jaylou 3700

COUNTERSIGNED BY:

Rock Foster
Mine Foreman

28732
Certificate No.

[Signature]
Superintendent

Certificate No.

Rock Foster 201.11

EXAMINATION OF BELT CONVEYORS

On Shift

3-23-10

SHIFT Day

TIME OF EXAMINATION:

FROM 6:00

A.M. OR P.M. TO

4:00

OR P.M.

Belt Conveyor Examined	Action Taken	EXAMINER
#1 South	detested from takeup - 2 Bsk, saw detested tail, cleaned Up plan	JB
#1 North	Reset tailer 13-14 Bsk	JB
#2 North		
#3 North		
#3 Sec #1	greased tail & takeup, did PM'S cleaned up power lines at mouth of section	GC JB
	97BK outby Refuge chamber OK ATTUE (PHONE) OK	HT

SIGNED BY:

Jim Boyce
Belt Examiner

32261
Certificate No.

Harley Taylor 37602

COUNTERSIGNED BY:

Rock Fata
Mine Foreman

28736
Certificate No.

Superintendent

Certificate No.

1002

EXAMINATION OF BELT CONVEYORS

Pre-shift

DATE 3-23-10 SHIFT 2nd TIME OF EXAMINATION: FROM 8:00 A.M. OR P.M. TO 11:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 south O ₂ CH4	need spot clean need spot dusted 22-40 ft.	Rep.	TP
1 north O ₂	3-20 ft. need add. rock dust - off side	Rep.	TP
2 north O ₂	need spot clean - Head & tail need add. rock dust	Rep.	TP
3 north O ₂	need spot clean & spot dusted (wet & muddy)	Rep.	TP
3 sec. # 1 O ₂	need spot clean & spot dusted	Rep.	TP
LBB O ₂	Pumps PLC's tracks clear at exam.	none	TP
MAINLINE O ₂	Pumps PLC's D. Boxes charger clear at exam.	none	TP
	NOCH4 Sect. O ₂ 20.802 CO ₂		
	Visual on CO's clear at exam.		
	Pumps PLC's D. Boxes charger clear at exam.		

SIGNED BY:

Ryan Peterson
Belt Examiner

29611
Certificate No.

COUNTERSIGNED BY:

Reck Foster
Mine Foreman.

28734
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

On-Shift

DATE 3-23-10

SHIFT 2ND

TIME OF EXAMINATION:

FROM 6:30

A.M. OR P.M. TO 2:30

A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 north head	un-stopped dust hoses for T. Duster & run duster		TP
2 north head	hooded T. Duster & Run		TP
Refuse Chamber Belts 97 & Phone clear at exam.			

SIGNED BY:

[Signature]
Belt Examiner

2966
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

2874
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Pre-Shift

DATE 3-24-10 SHIFT Owl TIME OF EXAMINATION: FROM 3:00 A.M. OR P.M. TO 8:00 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South	070CH4 need spot clean - need spot dusted 22-40 ft.	Rep.	TP
1 North	070CH4 3-20 ft. need add. rock dust - off side	Rep.	TP
2 North	070CH4 need spot clean on plow V plow need add. cleaning	Rep.	TP
3 North	070CH4 need spot clean & dusted - wet & muddy - water	Rep.	TP
3 sec. #1	070CH4 need spot dusted & spot clean	Rep.	TP
LBB	070CH4 Pumps P/C's track clean at exam	none	TP
MAIN LINE	070CH4 Pumps P/C's D. Boxes charge clean at exam.	none	TP
	NoCH4 det. 0% to 80% CO2		
	Visual on CO's clean at exam.		
	Track & Travelways clean at exam.		
	Pumps P/C's D. Boxes charge clean at exam.		

SIGNED BY: [Signature] Belt Examiner Certificate No. 29611

COUNTERSIGNED BY: [Signature] Mine Foreman Certificate No. 28736
[Signature] Superintendent Certificate No. 27429
[Signature] Ince Stenard 39199

EXAMINATION OF BELT CONVEYORS

On-Shift

DATE 3-24

SHIFT Owl

TIME OF EXAMINATION: FROM 12:10

A.M. OR P.M. TO 2:40

A.M. OR P.M.

BELT CONVEYOR EXAMINED	CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 south	Dusted from take-up to 3 Pul.		TJP
1 north	Dusted head & tail 1 south & 1 north take-up		TJP
2 north	hooded T. Dusted & Ran		TJP
2 north	guard down cross under at PLC - hung back up (corrected)		TJP
Refuse Chamber at Pul. & plone clean at exam.			

SIGNED BY:

[Signature]
Belt Examiner

29611
Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

28236
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Preshift

DATE 3-24-10 SHIFT DAY TIME OF EXAMINATION: FROM 1:00 ~~A~~ OR P.M. TO 4:00 ~~P~~ OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
# 1 South D% <u>CH4</u>	needs spot cleaned / duster: spot duster 22-40 BK	Reported	JB
# 1 North D%	3-20 BK need add. duster - off side, walkways need more cleaning, run mesh 26 bk needs cut down	Reported	JB/gsc
# 2 North D%	none observed	none	George Curry
# 3 North D%	need add spot cleaned / duster	Reported	gsc
3 sec # 1-D%	need spot cleaned / duster	Reported	LS
L BB	TRACK, POWER BOXES OK AT TOE	NONE	HT
Main line	pcis pumps - D boxes clean at exam D% CH4 D% CO 22.5% D2 detected track, travel ways, chutes, power lines safe at exam Visual check of CO monitor at exam See record for notes	none	gsc HT

SIGNED BY: George Curry Belt Examiner Certificate No. 27429
Jim Bayner 32261
Jay Stewart 39199 Harley Taylor 37002

COUNTERSIGNED BY: Tim Peterson 29611 Mine Foreman Certificate No. _____ Superintendent _____ Certificate No. _____