

STARTED 3-16-10

Finished 4-1-10

EXAMINATION OF BELT CONVEYORS

L

COMPANY Performance Coal

MINE Upper Big Branch

LOCATION Naoma WV Raleigh WV
Post Office County State

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-16-10 SHIFT: EVE AM OR PM TO AM OR PM 800 AM OR PM TO 1100 AM OR PM PRE-SHIFT EXAM.
ON-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom SKAGGS, Campbell Time 1045 AM or PM PM

Report received by: Don Miller
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELLS #4	Needs Dusted	GU	✓		
ELLS #5	Needs spot cleaned, 27-Tail + 7-3, needs Dusted	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Takeup needs Add cleaning, Needs Dusted	GU	✓		
NORTH NO. 5	None Observed	GU	✓		
NORTH NO. 6	needs Dusted, needs cleaned 87-Tail	BC	✓		
NORTH NO. 7	needs Dusted, Rib Roll 128 Brk, Dangled off	BC	✓		
ELWELL	Belt needs Dusted, Hd and Drives need cleaned	JS	✓		
GLORY HOLE	D-Box Pump OK	WC	✓		
HG 22 #1	Needs cleaned & dusted	JS	✓		
TG 22 #1	needs cleaned & dusted NEEDS CROSS OVER.	JS	—		
TG 22 #2	Needs Dusted	JS	—		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OK CH4, O2 CO2, 208202
PC's, Chargo, D-Boxes, Track, Trave ways OK

SIGNED BY: Don Miller 15397A William Campbell 13844A
Belt Examiners and Certificate Numbers
Jul [Signature] 32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357 Superintendent Certificate No.
Mine Foreman

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-17-10 SHIFT: owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom SKAGGS, Campbell Time 530 AM or PM

Report received by: Penellon
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>E11.54</u>	<u>Needs Dusted</u>	<u>GU</u>	<u>-</u>		
<u>E11.55</u>	<u>Needs Dusted, Needs cleaned 27-Tail</u>	<u>GU</u>	<u>✓</u>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Needs Dusted Hd-25Brk Takeover not Addressing</u>	<u>GU</u>	<u>-</u>		
NORTH NO. 5	<u>Needs spot Dusted</u>	<u>GU</u>	<u>✓</u>		
NORTH NO. 6	<u>Needs Dusted, 87-Tail Needs cleaned</u>	<u>WC</u>	<u>✓</u>		
NORTH NO. 7	<u>Needs Dusted/ Dangerous off #12 8Brk</u> <small>Need 8 Jacks set</small>	<u>WC</u>	<u>✓</u>		
<u>E-04/1</u>	<u>Needs Dusted Drives end Hd wet + muddy</u>	<u>JS</u>	<u>✓</u>		
GLORY HOLE	<u>D-Box Pump OK</u>	<u>WC</u>	<u>✓</u>		
LBB NO. 1					
LBB NO. 2					
<u>H622</u>	<u>Needs cleaned + dusted</u>	<u>JS</u>	<u>✓</u>		
<u>T622 #1</u>	<u>Needs cleaned + dusted</u>	<u>JS</u>	<u>✓</u>		
<u>T622 #2</u>	<u>Needs Dusted</u>	<u>JS</u>	<u>✓</u>		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OG Ch4 OG CO 208202

PC'S, CHARGES, D-Boxes, Travelings OK

SIGNED BY: Penellon 15207 John Neely 32476
Belt Examiners and Certificate Numbers
William Campbell 13548 Johnny Neely 33472
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359
Mine Foreman Certificate No.

46543-BJW Printing & Office Supplies

John A. Buckford 26176

Superintendent Certificate No.

Scott Halstead 37567

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-17-10 SHIFT 061 1100 AM OR PM TO 0300 AM OR PM AM OR PM TO AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
Elks 4		
Elks 5	Cleaned from 3-7 Brk, cleaned Tail	GV
NORTH 2		
NORTH 3		
NORTH 4	cleaned V-Roll 1 2 men Ousting change roller LC	GV
NORTH 5	cleaned V-Roll	GV
NORTH 6	change roller LC	
NORTH 7	cleaned Rib Roll Ran Duster at Head	GUJS WC
L WALL	change roller LC	
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges 6-8-89 all clear

SIGNED BY: [Signature] 15399
Belt Examiners and Certificate Numbers
[Signature] 1354-A
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 3339
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-17-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom J. Neely Time 250 AM or PM

Report received by: John A. Bedford 26174
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>Ellis 5</u>	<u>Needs dusted, Needs cleaned 27 to tail</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Take up needs add'l cleaning Needs dusted - Head to 20 Bel</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>Needs spot dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>Needs dusted, Needs cleaned 87 to tail</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>Tail Needs Add Cleaning Needs dusted, Dirty and off 128 Bel, Nels Jack</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>Lg Wall</u>	<u>DRIVE Needs Cleaned, Wet, Muddy, Belt needs Dusted</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>Pump & D'Box OK</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>LBB NO. 1</u>					
<u>LBB NO. 2</u>					
<u>HG 22</u>	<u>Needs cleaned & dusted</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>TG 22 #1</u>	<u>Needs cleaned & dusted</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>TG 22 #2</u>	<u>None Observed</u>	<u>JN</u>	<input checked="" type="checkbox"/>		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

O₂ 24, CO 4 & 20.8% O₂ detected at time of exam.

Track, Travelways, PC's, chayas, 'D' Boxes & Pumps clear at time of exam

Alan Williams 1537A

SIGNED BY: John A. Bedford 26174
Belt Examiners and Certificate Numbers

Scott Halstead 37567

John Neely 32476

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore
Mine Foreman

33359
Certificate No.

Superintendent Johnny Neely Certificate No. 33472

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-17-10 SHIFT Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____
Signed _____

BELTS	ACTION TAKEN	INT.
ELLIS 4	cleaned tail & Greased tail } Bobby	
ELLIS 5	cleaned tail & Greased tail } Bobby ^{BRE} 7-12 5 pay cleaned	
NORTH 2		
NORTH 3		
NORTH 4	Cleaned at V. Plow	JAB
NORTH 5	Cleaned at flow thru	JAB
NORTH 6	Cleaned at tail	JAB
NORTH 7	cleaned on tail, Greased tail Rollers	SH
NORTH 8	cleaned on Mud at Drive, Greased Drive Rollers	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
HG 22	Rock Dust from Drive Across both over cast Grease Drive	JAV
TG 22#1	Dust from Discharge to Drive. Dust off PCs	JAV

Checked Refuges at 6, 8 + 89 Buki OK, Plow OK

SIGNED BY: John A. Buckford 26176
Belt Examiners and Certificate Numbers

Scott Halstead 37567

Belt Examiners and Certificate Numbers

Johnny Kelly 33472

COUNTERSIGNED BY: T. Moore 75357
Mine Foreman Certificate No.

Superintendent

Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-17-10 SHIFT: Lve. AM OR PM TO 8:00 AM OR PM TO 11:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Brought out Time _____ AM or PM

Report received by: _____ Signed _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
2413 #1	NEEDS DUSTED	GU	✓		
2413 #5	NEEDS SPOT CLEAN & DUSTED	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	TAKE UP NEEDS CLEAN Head + Drive Needs Dusted	GU	✓		
NORTH NO. 5	NEEDS SPOT DUSTED	GU			
NORTH NO. 6	NEEDS DUSTED 87-Tail needs cleaned	GU	✓		
NORTH NO. 7	NEEDS CLEAN & DUSTED	JS	✓		
AWAY	DRIVE NEEDS CLEAN	JS	✓		
GLORY HOLE	D-Box ok	JS	✓		
LBB NO. 1					
LBB NO. 2					
HG 22	NEEDS CLEAN & DUSTED	JS	✓		
TG 22*1	NEED SPOT CLEAN & DUSTED	JS	✓		
TG 22*2	NONE OBSERVED	JS	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

06 Chy 0610 2082 02

01's Chayrs 0-Boves Traveling ok

SIGNED BY: [Signature] 32476
Belt Examiners and Certificate Numbers

[Signature] 15369
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M. M... 33359
Mine Foreman Certificate No.

Superintendent Certificate No.

John A. Bickel 21176

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-18-10 SHIFT: Day AM OR PM TO 600 AM OR PM TO 810 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: E. Hager Signed _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
4 FH15	needs spot dand dusted	MADON PERDUE	<input checked="" type="checkbox"/>		
5 FH15	clean called out by Russell Sumner				
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs dusted head to take up add chains ^{hand to mount on}	BICKFORD	<input checked="" type="checkbox"/>		
NORTH NO. 5	Tail needs add cleaning called out by Russell Sumner		<input checked="" type="checkbox"/>		
NORTH NO. 6	needs spot dand dusted called out by Scott Madstock		<input checked="" type="checkbox"/>		
NORTH NO. 7	7 north Belt + constructing area clean ^{called out}	MELIX PLUMER	<input checked="" type="checkbox"/>		
WALL	63 spot to 63.50 needs spot dand dusted called out by Tim Davis				
GLORY HOLE	Clean + take over				
LBB NO. 1					
LBB NO. 2					
HG 22	needs spot dand dusted	DEAN JONES			
TG 22 #1	needs spot dand dusted called out Jeremy Burdell		<input checked="" type="checkbox"/>		
TG 22 #2	Tail needs clean called out by JEREMY BURDELL		<input checked="" type="checkbox"/>		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4 0% CO 20.4% O2

CHARGERS, POWER BOXES, TRAVELWAYS OK

SIGNED BY: M. Kuhn 33017 Scott Halstead 37567
Belt Examiners and Certificate Numbers
Belt Examiners and Certificate Numbers
COUNTERSIGNED BY: T. Moore 33389 E. Hager 26041
Mine Foreman Certificate No. Superintendent Certificate No.

46543--BJW Printing & Office Supplies
W. H. Pugh 37004

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3/18/10 SHIFT: 1ST 6 AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: Eltager Signed _____

BELTS	ACTION TAKEN	INT.
VEH'S SOUTH 1	check for tail & grease tail shove to 1 3/4 BBT, Bddy	
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	ABBT refuge clear called out by John Sealeford	
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2	8 + 89 refuge clear called out by Scott Halstead	

SIGNED BY: _____ Scott Halstead 37567
Belt Examiners and Certificate Numbers
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY To M... 33359
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-18-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom John Bickford Time 2:15 AM or PM

Report received by: Russell Sumner
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted, Needs spot cleaned 27-Tail	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs add. cleaning Needs Cleaned Discharge to overcasts	RG	✓		
NORTH NO. 5	tail needs Added Cleaning	SH	✓		
NORTH NO. 6	Needs Spot Cleaned, Belt needs Dusted	SH	✓		
NORTH NO. 7	Needs cleaned & Dusted	JAB	✓		
Longwall	Wet + Muddy DRIVE AREA Needs Cleaned, Belt needs Dusted	SH	✓		
GLORY HOLE	D-Box & Pump OK	JAB	✓		
T6-22 NO. 1	Needs spot cleaned & Dusted	JAB	✓		
T6-22 NO. 2	None Observed	JAB	✓		
HG-22	Needs cleaned & Dusted	JAB	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0ppm CO Detected at EXAM times
Powercenters, D-Boxes, chargers, TRACK & TRAVELWAYS Clear at EXAM
Visual CK of C.O. Monitors Clear at EXAM

SIGNED BY: Scott Halstead 37567 John B. Bickford 26171
 Belt Examiners and Certificate Numbers
Russell Sumner 1536-A John Stoy 32476
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Alford 33359
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-18-10 SHIFT: DAY 6:00 (AM OR PM) TO 3:00 (AM OR PM)
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ___ No ___ By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	shoveled V-plow	
Ellis 5		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	cleaned V-Plow at flow thru	SH
NORTH 6	cleaned V-Plow, cleaned at tail of AB	SH
NORTH 7		
Long wall	cleaned on Mud, RAN Duster	SH
GLORY HOLE		
TG22 NO. 1	cleaned on Walkway & at tail	JAB
TG22 NO. 2		
HG22		

CK'd Refuge Chambers 6, 8, 89 BK OK at EXAM
All Phones Working

Don Miller 5301A

SIGNED BY: Russell Gunnar 1536-19 Scott Halstead 37567
Belt Examiners and Certificate Numbers
John Beckford 26171
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33389
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pen or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-18-10 SHIFT: LUC AM OR PM TO 8:00 AM OR PM TO 11:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or _____

Report received by: _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FD RU
211.3 24 SOUTH NO. 1	NEEDS DUSTED	GU	✓		
211.3 23 NORTH NO. 1	NEEDS SPOT CLEANED & DUSTED	GU	✓		
NORTH NO. 2					
NORTH NO. 3	BELTS TAKE UP CLEANED & DISCHARGE TO OUTCAST				
NORTH NO. 4	NEEDS CLEAN AT TAKE UP or DISCHARGE TO OUTCAST	GU	✓		
NORTH NO. 5	Tail NEEDS CLEAN	GU	✓		
NORTH NO. 6	NEEDS SPOT CLEAN & DUSTED	GU	✓		
NORTH NO. 7	NEEDS SPOT CLEAN & DUSTED	JS	✓		
NORTH NO. 8					
GLORY HOLE	D-Box AND Pump Oils	JS	✓		
LBB NO. 1					
LBB NO. 2					
H622	NEEDS CLEANED & DUSTED	JS	✓		
T622 ^{#1}	NEED CLEANED & DUSTED	JS	✓		
T622 ^{#2}	NONE OBSERVED	JS	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

0% CH4 0% CO 20.8% O2

TRAILWAYS, TRACK AND POWER CENTERS OK AT TIME OF EXAM

SIGNED BY: [Signature] 32476
Belt Examiners and Certificate Numbers
[Signature] 1539-A
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 33359
Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3.18 SHIFT: EVE 8:00 AM OR PM TO 6:00 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ___ No ___ By Whom _____ Time _____ AM or PM

Report received by: _____ Signed _____

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	REPLACE WATER VALVE AT TAIL	60/JS
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

CHK REFUSE BOXES AT 8, 6, 89 OK AT TIME OF EXAM
ALL PHONES WORK

SIGNED BY: [Signature] 32476
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-19-10 SHIFT: OWL AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	NEEDS DUSTED	SW	✓		
NORTH NO. 1	NEEDS SPOT CLEANED AND DUSTED	SW	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	NEEDS CLEAN & DUSTED TAKEUP NEEDS CLEAN	SW	✓		
NORTH NO. 5	TAI NEEDS CLEAN	SW	✓		
NORTH NO. 6	NEEDS SPOT CLEAN & DUSTED	JS	✓		
NORTH NO. 7	NEEDS DUSTED	JS	✓		
NORTH NO. 8					
GLORY HOLE	D-Box AND Pump OK.	JS	✓		
LBB NO. 1					
LBB NO. 2					
H620	NEEDS CLEAN AND DUSTED	JS	✓		
LW	NEED SPOT CLEANED & DUSTED	JB	✓		
T6 ^{#22} 1	NEEDS CLEAN AND DUSTED	JS	✓		
T6 ^{#22} 2	NONE OBSERVED	JS	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4 0% CO 20.8% O2.

TRAVELWAYS AND TRACKS OK AT TIME OF EXAM

SIGNED BY: J. L. [Signature] 32476 Z. R. [Signature] 38729

Belt Examiners and Certificate Numbers

[Signature] 1947-A

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M. [Signature] 33359

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-19-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom John Bickford Time 2:00 AM or PM

Report received by: Russell Gurnee
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs spot cleaned 27-29, + Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 29-Tail, Needs cleaned ^{Drive} Discharge	RG	✓		
NORTH NO. 5	tail needs cleaned	SH			
NORTH NO. 6	Needs Some Spot Cleaning, Needs Dusted	SH	✓		
NORTH NO. 7	Needs dusted	JAB	✓		
Longwall	mother Drive Area Needs Cleaned, Belt needs Dusted	SH	✓		
GLORY HOLE	D-Box + Pump OK	JAB	✓		
TG22 NO. 1	Needs cleaned + Dusted	JAB	✓		
TG22 NO. 2	Last sitop needs dusted	JAB	✓		
HG-22	Needs cleaned + Dusted	JAB	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0ppm CO at time of exam
Tramways, Power Centers, D-Boxes, chargers OK at time of exam
Visual check of CO monitors ok at time of exam

SIGNED BY: Russell Gurnee 1536-A Scott Halstead 37567
 Belt Examiners and Certificate Numbers
John Bickford 25174
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359
 Mine Foreman Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-19-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM AM OR PM TO AM OR PM AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:
Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow ^{Cleaned from 33-33BK} Shoveled tail & Greased rail / Bobby	RG
Ellis 5	Shoveled V-plow	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, Ran dusters at Tail + Drives	RG
NORTH 5	cleaned V-Plow, Cleaned on tail JAB	SH
NORTH 6	Cleaned + dusted at tail	JAB
NORTH 7		
Longwall	cleaned on Mud at Mother drive	SH
GLORY HOLE		
TG22NO. 1		
TG22NO. 2	Cleaned at tail	JAB
HG-22		

Refuge chambers at 6, 8, 8, 8 bk 2 sect OK + phones working
at time of exam

SIGNED BY: Russell Dumas 1536-A Scott Holstead 37567
Belt Examiners and Certificate Numbers
John B. Bullard 26176
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 3338-2
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-19-10 SHIFT: EVC 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 11:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs Dusted	GU	✓		
Ellis #5	needs cleaned 27-29, Needs Dusted	GU	✓		
Long wall	Herron needs cleaned; belt needs Dusted	BC	✓		
NORTH NO. 3					
NORTH NO. 4	needs spot cleaned 29 tail Drives + Discharge needs cleaned	GU	✓		
NORTH NO. 5	tail needs cleaned	GU	✓		
NORTH NO. 6	needs spot cleaned & Dusted	GU	✓		
NORTH NO. 7	needs Dusted	BC	✓		
H622 #1	needs cleaned & Dusted	BC	✓		
GLORY HOLE	D-Box & Pump - Clear	BC	✓		
H622 NO. 1	needs cleaned & Dusted	BC	✓		
H622 NO. 2	Needs Dusted	BC	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

0% CH₄, 0 ppm CO, 20.8% O₂ Detected
 TRUCK/Travelways, LHA, PCs, Pumps, D-Box's chargers, and
 visual check of CO monitors - all clear at Exam

SIGNED BY: Walter Campbell 1354-A
Belt Examiners and Certificate Numbers
Don Williams 1539-A
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Morris 33359
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-20-10 SHIFT: owl AM OR PM TO 3:06 AM OR PM TO 6:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
OKS NO. 1	Needs Dusted	GU	✓		
ELLIS NO. 5	Needs cleaned 2-Tail needs Oks fld	GU	✓		
WUPP NO. NO.	Head Needs cleaned Belt needs Dusted	BC	✓		
NORTH NO. 4	needs spot cleaned 2R-Tail HD needs cleaned	GU	✓		
NORTH NO. 5	Tail needs cleaned	GU	✓		
NORTH NO. 6	needs spot cleaned needs dusted	GU	✓		
NORTH NO. 7	needs Dusted	BC	✓		
H622 NO. 1	Needs cleaned and Dusted	BC	✓		
GLORY HOLE	D-Box & Pump clear at Exam	BC	✓		
T622 NO. 1	needs cleaned & Dusted	BC	✓		
T622 NO. 2	needs added dusting	BC	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 0 ppm CO, 20.8% O₂ Detected
TRAIL / Tramways, D-Box & KVIA's, Pumps, Pul's, and a visual
check of CO monitor clear at Exam

SIGNED BY: Alan Miller 15394 Johnny Neely 33472
Belt Examiners and Certificate Numbers
William Campbell 135410
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359
Mine Foreman Certificate No. Superintendent Certificate No.

46543—BJW Printing & Office Supplies
John B. Buckland 26176 Russell Lumroe 1536A Scott Halstead 37567

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-20-10 SHIFT: Day AM OR PM TO 1200 AM OR PM TO 300 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom John Neely Time 220 AM or PM

Report received by: John Bickford 28176
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>Ellis 5</u>	<u>Needs dusted, Needs add'l cleaning 27-29</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Needs spot cleaned 29 to tail Needs add'l cleaning down to head</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>Tail needs add'l cleaning</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>Needs spot cleaned & dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>Needs dusted</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>Lg Wall</u>	<u>Mother Drive Needs Cleaned</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	<u>Pump & D'Box OK</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>TG22 #1</u>	<u>Idle, PC & charger</u>	<u>JN</u>			<input checked="" type="checkbox"/>
<u>TG22 #2</u>	<u>Idle, PC & charger</u>	<u>JN</u>			<input checked="" type="checkbox"/>
<u>HG22 #1</u>	<u>Needs cleaned & dusted</u>	<u>JN</u>	<input checked="" type="checkbox"/>		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

O₂ ch₄ O₂ CO & 20.8% O₂ detected at time of exam

Visual check of CO's -OK

Track, trawnpops, PC's, chargers, pumps & D'Box's
clear at time of exam

Don 200mm 15394A

SIGNED BY: John Bickford 28176
Belt Examiners and Certificate Numbers

Scott Halstead 37567

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore

33359

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-20-10 SHIFT: Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____
Signed

BELTS	ACTION TAKEN	INT.
ELLIS 4	Cleaned at Tail & U' Plow	JAB
ELLIS 5	Cleaned at U' Plow	JAB
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned at U' Plow & Tail	JAB
NORTH 6	Cleaned at Tail	JAB
NORTH 7	cleaned on tail Raw Duster	SH
Log Wall	cleaned on Mud at Mother drive	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
Tailgate 22#1	CLEAN TAIL Piece	JN
HG 22#1	clean spillage of Discharge, Dust & Grease	JN

Checked Refuses 6, 8 & 89 Bkts: OK Phone OK - 8 & 89

Refuse #6 Phone not Paging

SIGNED BY: John G. Bickford 28176
Belt Examiners and Certificate Numbers

Scott Halstead 37567
Johnny Neely 33472

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore
Mine Foreman

33389
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-20-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELLIS NO.4	needs Dusted	GU	✓		
ELLIS NO.5	needs added cleaning 27-29 ton, needs Dusted	GU	✓		
NO.					
Longwell NO.	Motor Drive needs cleaned, Belt needs spot cleaned	BC	✓		
NORTH NO. 4	needs spot cleaned 29-ton drives need added cleaning to Discharge	GU	✓		
NORTH NO. 5	needs added cleaning at take up	GU	✓		
NORTH NO. 6	needs spot cleaned at airlock, 87-ton & Dusted	BC	✓		
NORTH NO. 7	needs Dusted	BC	✓		
H 622 NO.1	Needs cleaned and dusted	BC	✓		
GLORY HOLE	D-Box & Pump - clear at Exam	BC	✓		
T622 NO. 1	IDLE, P.C's & chargers - clear at Exam	BC	✓		
T622 NO. 2		BC	✓		

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

0% CHA, 0ppm CO, 20.8% O₂ Detected

Trail / Travelways, KVAs, D-Box's, Chargers, Pumps & Power centers clear at Exam, On a visual check of CO monitors clear at Exam,

SIGNED BY: Wilho Campbell 13542
Belt Examiners and Certificate Numbers
Don Mann 15392
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33352
Mine Foreman Certificate No.

Superintendent Certificate No.

Use Indefinite Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-20-10 SHIFT: EVE 6:00 AM OR PM TO 8:00 AM OR PM 8:00 AM OR PM TO 11:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
2115 4	Cleaned & plow	GU
2115 5		
Longwall		
NORTH 4		
NORTH 5	Cleaned & plow	GU
NORTH 6	Ran Duster, showered & plow	BC
NORTH 7		
1622 #1	Showered & plow at the section tail	BC
GLORY HOLE		
1622 NO. 1		
1622 NO. 2		

Checked Outby Refuges at 6,8,89 brks - all clear, phones working

SIGNED BY: William Campbell 1354
Belt Examiners and Certificate Numbers
Don Allen 1629A
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore Mine Foreman 33359 Certificate No. _____ Superintendent _____ Certificate No. _____

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-21-10 SHIFT: OWL 1100 ~~AM~~ ^{PM} TO 300 ~~AM~~ ^{PM} 300 ~~AM~~ ^{PM} TO 600 ~~AM~~ ^{PM}
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____
 Signed _____

BELTS	ACTION TAKEN	INT.
Ellis 4		
Ellis 5		
Longwell	Run Duster	BC
NORTH 4	Run Duster	
NORTH 5		
NORTH 6	Run Duster, shoveled view	BC
NORTH 7	Run Duster, shoveled view	BC
H622#1		
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		

*Checked Out by Refuges at 6.8, 8.9 blocks - all clear at Exam
 and Phones are working*

SIGNED BY: W. J. Campbell 135412
 Belt Examiners and Certificate Numbers
Don Nelson 1534
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357
 Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-21-10 SHIFT: _____ AM OR PM TO _____ AM OR PM 12:00 AM OR TO 3:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No _____ By Whom J. Neely Time 2:30 AM or PM

Report received by: John A. Beckford
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis NO. 4</u>	<u>Needs dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>Ellis NO. 5</u>	<u>Needs dusted; Needs cleaned 27-29 Belt</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>		<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 4</u>	<u>Needs cleaned 29 to tail Drive to head needs add'l cleaning</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>Needs add'l cleaning at take-up & tail</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>Needs dusted & spot cleaned</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>Needs dusted</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>Lg Wall</u>	<u>Needs spots dusted mtd needs cleaned lat cloud</u>	<u>TD</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>Pump & D'Box - OK</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>T627 NO. 1</u>	<u>Falle PCs OK</u>	<u>JN</u>			
<u>T622 NO. 2</u>	<u>Falle PCs - OK</u>	<u>JN</u>			
<u>A622 #1</u>	<u>Needs cleaned & dusted</u>	<u>JN</u>	<input checked="" type="checkbox"/>		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

O₂ ch₄, O₂ CO & 20.8% O₂ detected at time of exam
Visual check of CO₂ - OK
Track, travelways, PCs, chargers & Pump & D'Box's
clear at time of exam

SIGNED BY: John A. Beckford 26176 Jim Davis 38322
Belt Examiners and Certificate Numbers
Johnny Neely 33472 John Davis 32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Munn 33357
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-21-10 SHIFT Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ___ No ___ By Whom _____ Time _____ AM or PM

Report received by: _____
Signed

BELTS	ACTION TAKEN	INT.
<u>E415 4</u>	<u>cleaned at V Plow</u>	<u>JAB</u>
<u>E415 5</u>	<u>cleaned at V Plow</u>	<u>JAB</u>
NORTH 2		
NORTH 3		
NORTH 4	<u>cleaned at V Plow</u>	<u>JAB</u>
NORTH 5	<u>cleaned at V Plow & tail & flow thru</u>	<u>JN JAB</u>
NORTH 6	<u>cleaned at tail</u>	<u>JAB</u>
NORTH 7		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<u>H677 1</u>	<u>clean on Rib Rolls dust around PC's trim splices</u>	<u>JN</u>

Checked Refuges 6, 8 & 89 Bkrs. - OK; Phones OK

SIGNED BY: John A. Bickford 26176 Johnny Neely 33472
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357 _____
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-21-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom: Brought out Time _____ AM or PM

Report received by: _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Eff. 1</u>	<u>needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>Eff. 3</u>	<u>needs cleaned 27-29 belt, needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>needs cleaned from Drives - Discharge needs spot cleaned Tand needs added cleaning, from 32-tail</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>Take up needs added cleaning</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>need Dusted, needs spot cleaned from 87-tail + dis out</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>Glory with #</u>	<u>Mother Drive needs cleaned, needs spot cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	<u>D Box + Pump clear at Exam</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>H62 #1</u>	<u>needs cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>T622 #1</u>	<u>needs cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>#2</u>	<u>needs Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 0 ppm CO, 20.8% O2 Detected
Track / Travel ways, D-Box's, Power centers, KWAS, Pumps, chargers
in a visual check of all CO monitors all clear at Exam

SIGNED BY: William Campbell 13547
Belt Examiners and Certificate Numbers
John [Signature] 32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Name 33357
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-21-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____
Signed _____

BELTS	ACTION TAKEN	INT.
ELLIS 4		
ELLIS 5		
NORTH 2		
NORTH 3		
NORTH 4	Shoveled on tow	BC
NORTH 5	shoveled on v plow	BC
NORTH 6		
NORTH 7		
Wongwell		
GLORY HOLE		

Checked out by Refugees cat 6, 8, 89, but all clear at exam and
phones working

SIGNED BY: William Campbell 1354
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-22-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM
ON-SHIFT EXAM. **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes No X By Whom Brought out Time AM or PM

Report received by:

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	needs Dusted	BC	✓		
Ellis 5	needs cleaned from 27-29 belt needs Dusted	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs spot cleaned from 32 tail needs cleaned from Discharge - Drives, tail needs added cleaning	BC	✓		
NORTH NO. 5	tail needs added cleaning, Out by tail needs added cleaning	BC	✓		
NORTH NO. 6	needs spot cleaned at air out 87 tail needs Dusted	BC	✓		
NORTH NO. 7	needs Dusted	BC	✓		
Zonguicall	mother drive needs cleaned, belt needs spot cleaned	JS	✓		
GLORY HOLE	D-Box - Pump - clear at Exam	BC	✓		
H622 #1	needs cleaned & Dusted	JS	✓		
T622 #1	needs cleaned & Dusted	JS	✓		
#2	needs Dusted	JS	✓		

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 0 ppm CO, 20.8% O₂ detected

Track / Travelways, D-Box's, pumps, KVAs, Powercenters, chargers,

and a visual check of CO monitors all clear at Exam

SIGNED BY: William Campbell 1354-A

Belt Examiners and Certificate Numbers

Johnny Neely 33472

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore

33759

Mine Foreman

Certificate No

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-22-10 SHIFT: OWL 1100 AM OR PM TO 300 ~~AM OR PM~~ 300 ~~OR PM~~ TO 600 ~~AM OR PM~~
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	shoveled V-plow	BC
Ellis 5		
NORTH 2		
NORTH 3		
NORTH 4	worked on Gob out at tail	BC
NORTH 5	shoveled V plows at flow thru and tail and shoveled on tail, Duster at flow thru	BC
NORTH 6	Ran Duster at Head	BC
NORTH 7		JS
GLORY HOLE		
H602* 1	Shovel Tail & Replaced V-Plow, work on Hanging Life Line on Belt	JS
T6*22* 1	Shovel on Tail, work on Belt Switch Cable Rerouting	JS

Checked Out by Refuges at #6, 8, 89 hicks, none observed at Exam

20.6% O₂, 0% CH₄, Oppmco detected

SIGNED BY: [Signature] 32476
Belt Examiners and Certificate Numbers

[Signature] 1354-17
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature]
Mine Foreman

33359
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-22-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom John Neely Time 2:45 AM or PM

Report received by: Russell Gunnor
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
EN113 #1	Needs Dusted	RG	✓		
EN115 #1	Needs cleaned 27-29, Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Some Spot Cleaning, tail Needs Add Cleaning Needs cleaned Drive-Discharge	RG SH	✓		
NORTH NO. 5	takeup Needs Add Cleaning	SH	✓		
NORTH NO. 6	Needs spot cleaned at Airlock, 87-tail needs Dusted.	SH	✓		
NORTH NO. 7	Needs Dusted	JN	✓		
Longwall	Needs Some Spot Cleaning, Added Dusting needed Area Blown Discharge & Drive Needs Cleaned	SH	✓		
GLORY HOLE	D-Box + Pump OK	JN	✓		
HG-22	Needs cleaned & Dusted	JN	✓		
TG-22 #1	Needs cleaned & Dusted	JN	✓		
TG-22 #2	Needs Dusted	JN	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0 ppm CO at time of exam
Travelways, Power Centers, D-Boxes, Chargers OK at time of exam
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gunnor 1536-A Scott Halstead 37567
 Belt Examiners and Certificate Numbers
Johnny Neely 33472 John [Signature] 32476
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. [Signature] 33359 [Signature]
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-22-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____
Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled v-plow Cleared tail + Greased, ^{Cleared from tail to 3rd BK} (Bobby)	RG
Ellis 5	Shoveled v-plow cleared tail + Greased (Bobby)	RG
NORTH 2		
NORTH 3		
NORTH 4	Ran Duster at Drives, Cleared SONG on tail	RG
NORTH 5	cleaned V-Plows	SH
NORTH 6	cleaned V-Plows	SH
NORTH 7	Ran Duster at Head clean TAIL	SH
Longwall	cleaned Mud at Mother Drive, check Splices	SH
GLORY HOLE		
HG-22	clean on Rib Roll clean V Plow at TAIL	JN
TG-22 #1	CLEAN TAIL Dust from Discharge To Drive Grease Drive ^{Discharge}	JN
TG-22 #2		

Resuge chambers, 6, 8, 99 clear at EXAM
Phones working in 8, 99 BK
6 BK Phone Needs Battery

SIGNED BY: Russell Dunne 1536-19
Belt Examiners and Certificate Numbers

Scott Halstead 37567

Belt Examiners and Certificate Numbers

Johnny Neely

COUNTERSIGNED BY T. Moore
Mine Foreman

33357
Certificate No.

Superintendent

Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-22-10 SHIFT: 8:15 6:00 AM PM TO 3:00 AM OR PM 2:00 AM OR PM TO 11:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____ Signed _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis #4</u>	<u>needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>Ellis #5</u>	<u>needs Dusted, needs cleaned 27-29</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>needs cleaned from Drives - Discharge 37-tail needs spot cleaned</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>needs Dusted, ^{spot} take up needs cleaned tail needs cleaned out by</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>needs spot cleaned at Winlock, 37-tail needs cleaned & Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>needs Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>Thorpywall</u>	<u>needs spot cleaning & Dusted Mother Drive needs cleaned, Drive - Discharge needs cleaned</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>D-Box & Pump clear</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>14622 #1</u>	<u>needs cleaned & Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>T622 #1</u>	<u>Needs cleaned & Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>#2</u>	<u>needs Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

0% CH4, 0 ppm CO, 20.8% O2 Detected
Track / Travelways, D-Box's, chargers, Powercenters, Pumps, KVAs
and a visual check of CO monitors were - all clear at Exon

Wend Lilly 2009.5

SIGNED BY: Wend Lilly Campbell 1354-A
 Belt Examiners and Certificate Numbers

32476
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore
 Mine Foreman

33389
 Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-22-10 SHIFT: 6:00 AM OR PM 10:00 AM OR PM 2:00 AM OR PM 11:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
4 & 11.5	Shoveled V-plow at tail	BC
5 & 11.5	worked on Mud at tail	BC
NORTH 4	Ramp pumps at 12 & 12 bks - shoveled on tail / worked on Mud at Discharge	BC
NORTH 5	shoveled V-plow's at Flow thru, & Tail	BC
NORTH 6	shoveled V-plow at tail	BC
NORTH 7		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
Longwell	Dusted P. Lat storage unit	BC
H6 22 #1	SHOULDER ON TAIL V-Plow	JS
J6 22 #1	Work on Haggens Life Line	JS

Checked Out by Refuges at #6 bck - Replaced battery in phone WORKING now
 section # 8 bck - phone working - all cleared Exam
 # 89 bck - phone not working 20.6% 100%, 0% 104, 0.00

SIGNED BY: William Campbell 13347
 Belt Examiners and Certificate Numbers
John [Signature] 3247C
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Te [Signature] 33359
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-23-10 SHIFT: OWL 1100 AM OR 300 PM TO 300 AM OR 600 PM TO 600 AM OR PM
ON-SHIFT EXAM. **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
EMIS#1	needs Dusted	BC	✓		
EMIS#2	needs spot cleaned 27-29	BC	✓		
NORTH NO. 3					
NORTH NO. 4	DRIVES - Discharge needs cleaned needs spot cleaned 37-tail Outby tail needs cleaned	BC	✓		
NORTH NO. 5	needs spot cleaned from 60-Flourbin; Takeup needs cleaned Cleaning	BC	✓		
NORTH NO. 6	needs spot cleaned from 87-tail	BC	✓		
NORTH NO. 7	needs Dusted	JS	✓		
LOWY/WHIT	needs cleaned at Drives - Discharge needs spot cleaned + cubed Dusted	JS	✓		
GLORY HOLE	D-Box - Pump clear at Exam	JS	✓		
TB2NO.1	needs cleaned + Dusted	JS	✓		
TB2NO.2	needs Dusted	JS	✓		
H622 #1	needs cleaned + Dusted	JS	✓		
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 0ppm CO, 20.8% O₂ Detected
Track / Travelways, D-Box's, Chargers, Power Centers, LVA, Pumps,
and a Visual check of CO monitors, all clear

SIGNED BY: William Campbell 135477 JL Lopez 30476
Belt Examiners and Certificate Numbers
Johnny Neely 33472
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359
Mine Foreman Certificate No. Superintendent Certificate No.

R. M. M. 1571A

Seal Validated 37567

Use Indefible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-23-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM

Was this report phoned to outside Yes No By Whom John Neely PRE-SHIFT EXAM. Time 2:40 AM or PM

Report received by: Russell Gummoe
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs Dusted</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>Ellis 5</u>	<u>Needs spot cleaned 27-29, Needs Dusted</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Needs Spot Cleaned 57-tail</u>				
<u>NORTH NO. 5</u>	<u>Needs cleaned Drive-Discharge</u>	<u>RG SH</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>take up needs Add Cleaning, Needs Spot Cleaned 60-Flowhead</u>	<u>SH</u>			
<u>NORTH NO. 7</u>	<u>Needs Spot Cleaned 87-tail</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>Longwall</u>	<u>Needs Dusted</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>Mother Drive Area needs cleaned, Belt needs some spot clean</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
	<u>D-Box + Pump OK</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>TG-22 NO. 1</u>	<u>Needs cleaned + Dusted</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>TG-22 NO. 2</u>	<u>Needs Dusted</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>HG-22 #1</u>	<u>Needs Dusted, Needs Rib Roll cleaned up in walkway</u>	<u>JN</u>	<input checked="" type="checkbox"/>		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO at time of exam
TRAVELWAYS, POWER CENTERS, D-BOXES, CHARGERS OK at time of exam
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gummoe 1536-A Belt Examiners and Certificate Numbers
John Neely 33472 Belt Examiners and Certificate Numbers
Scott Halstead 37567 Belt Examiners and Certificate Numbers
John Neely 33472 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 53359 Mine Foreman
John Neely 33472 Superintendent
Certificate No. _____

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-23-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. AM OR PM TO AM OR PM PRE-SHIFT EXAM. AM OR PM

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____
Signed _____

BELTS	ACTION TAKEN	INT.
Ellis 4	shoveled v-plow, cleaned from tail to 310K, cleaned & greased on tail (Bobby)	RG
Ellis 5	shoveled v-plow, cleaned & greased on tail (Bobby)	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned V-Plow	
NORTH 5	cleaned V-Plows clean on tail	SH
NORTH 6	cleaned V-Plow	SH JN
NORTH 7		SH
Longwall	cleaned on mud at Mother Drive	
GLORY HOLE		SH
TG-22 NO. 1	clean on tail	
TG-22 NO. 2		JN
HG-22 #1	Clean on Rib Rolls in walkway clean v plow at tail	JN

Refuge chambers 6, 8, 89 BK Good at EXAM
 Phones Working at EXAM

SIGNED BY: Russell Sumner 1534-A Scott Halstead 37567
 Belt Examiners and Certificate Numbers
 Belt Examiners and Certificate Numbers
 COUNTERSIGNED BY T. Moore 33354
 Mine Foreman Certificate No.
 Superintendent Certificate No.

Use Indelible Pen or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-23-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 11:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
E11'S NO. 4	needs Dusted	GU	✓		
E11'S NO. 5	needs spot cleaned & Dusted	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs spot cleaned 37-tail needs cleaned from Drive - Discharge	GU	✓		
NORTH NO. 5	take up needs added cleaning - needs spot cleaned ⁶⁰⁻⁷⁰ #4	GU	✓		
NORTH NO. 6	needs spot cleaned 87-tail	BC	✓		
NORTH NO. 7	Needs Dusted	BC	✓		
Komwall	Mother Drive area needs cleaned Belt needs spot cleaned	JS	✓		
GLORY HOLE	D-Box & Pump Cleanout Screen	BC	✓		
T622 NO. 1	needs cleaned & Dusted	JS	✓		
T622 NO. 2	needs Dusted	JS	✓		
H622#1	needs Dusted, needs Rib-roll cleaned up in walking and Belt needs cleaned	JS	✓		
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

0% CH₄, 0% CO, 0.20.89% Detected
TRACK/Travelways, D-Box's, choppers, Power centers, on a visual check of CO's

SIGNED BY: William Campbell 1334-10 Alan Allen 1539A
 Belt Examiners and Certificate Numbers
John [Signature] 39476
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 73283
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-23-70 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____
Signed _____

BELTS	ACTION TAKEN	INT.
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
GLORY HOLE		
7632 NO. 1	<i>Shovel V-Flow</i>	
NO. 2		<i>JS</i>

Checked Outhy Refuges at #6 - N/O - phones working
#8 - N/O - phones working
#89 - N/O - changed battery phone working
20.6% O₂, 0% CO₂, 0 ppm CO

SIGNED BY: *William Campbell 13842*
 Belt Examiners and Certificate Numbers
Don Mc... *1539A*
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *T. M...* *35789*
 Mine Foreman Superintendent Certificate No.

Use Indelible Pen or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-24-10 SHIFT: OW 1100 AM OR PM TO 300 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____ Signed _____

BELTS	ACTION TAKEN	INT.
Ellis 4	Cleaned 6 pul	GU
Ellis 5	change rollers	
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned Flow thru, made splice	GU
NORTH 6	Shoveled plug at Flow thru	BC
NORTH 7	change rollers	
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
7N Const	Set 3 Sacks near D Box & Powercenter	BC JS
North Mains		BC JS
Intake Room	Moved pump in #4 up closer to face where water is deep	

Checked out by Relays 6-2-89 OK phones working

SIGNED BY: [Signature] 15397
Belt Examiners and Certificate Numbers
[Signature] 135424
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 33357
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-24-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom John Bickford, John Neely Time 2:20 AM or PM

Report received by: _____ Signed _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs spot cleaned + Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs cleaned Drive-Discharge, ^{Needs spot cleaned 37-Tail}	JAB RG	✓		
NORTH NO. 5	Take-up needs add. cleaning, Needs spot cleaned 60-Flw-Tran	JAB	✓		
NORTH NO. 6	Needs spot cleaned 87-Tail	JAB	✓		
NORTH NO. 7	Needs Dusted	SH	✓		
LONGWALL	Belt Needs Spot cleaned Mother Drive Needs Add Cleaning	SH	✓		
GLORY HOLE	D-Box + Pump OK	SH	✓		
TG-22 NO. 1	Needs spot cleaned + Dusted	JN	✓		
TG-22 NO. 2	Needs Spot cleaned + Dusted	JN	✓		
HG-22 #1	Needs cleaned + Dusted, Rib Roll needs cleaned up in walkway	JN	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

0% CH₄, 20.8% O₂, 0ppm CO at time of exam
TRavelways, Power Centers, D-Boxes, Chargers OK at time of exam
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Lunn 1536-A Scott Halstead 32476
Belt Examiners and Certificate Numbers
John Bickford 21/71 Johnny Dally 33472
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359 _____
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-24-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____ Signed _____

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled v-plow (shoveled tail & Greased tail) Bobby	RG
Ellis 5	Shoveled v-plow shoveled tail & Greased tail Bobby	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned at take v-plow	5AB
NORTH 5	Cleaned at flow thru	5AB
NORTH 6	Cleaned at flow thru & tail	5AB
NORTH 7		
Longwall	cleaned on Mud at Mother Drive All Shift	SH
GLORY HOLE		
TG-22 NO. 1	CLEAN TRAIL + V Plow Dust from Head To Takeup	JN
TG-22 NO. 2		
HG-22	Dust Head To Takeup fill Duster + Run ^{DUST GUARD} BACK UP	JN
	STRAIGHTEN OUT life line in by DRIVE clean on Rib Roll	JN

Resuge chamber 6, 89, 8bak 2nd OK + phones working at time of exam

SIGNED BY: Russell Gunnoe 1536-A
Belt Examiners and Certificate Numbers

John R. Buford 26176
Belt Examiners and Certificate Numbers

Scott Halstead 37567

Johnny Ruby 33472

COUNTERSIGNED BY T. Moore 33359

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-24-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELLIS NO. 4	Needs Dusted	BC	✓		
ELLIS NO. 5	needs spot cleaned & Dusted	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs cleaned from Drives - Discharge ^{Needs Spot cleaned 37-tail}	BC	✓		
NORTH NO. 5	Taken up needs added cleaning needs spot cleaned led-flower	BC	✓		
NORTH NO. 6	needs Dusted needs spot cleaned 87-tail	BC	✓		
NORTH NO. 7	Needs Dusted	BC	✓		
Longwell	But needs spot cleaner & Dusted Mother Drive needs added cleaning	JS	✓		
GLORY HOLE	D-Box & Pump Clean at Exam	BC	✓		
T601 NO. 1	needs spot cleaned & Dusted	JS	✓		
T601 NO. 2	needs spot cleaned & Dusted	JS	✓		
H622 #1	needs cleaned & Dusted Rib Roll needs cleaned up in walkway	JS	✓		

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, Oppm CO, 80.8% O2 Detected
Track/Travelways, KVA, Powercables, Chargers 17-Box's, Pumps can
advised check of CO monitors clean at Exam

SIGNED BY: Walter Campbell 13541A
 Belt Examiners and Certificate Numbers
[Signature] 32476
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M. [Signature] 33359
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-24-10 SHIFT: EVE 600 AM OR PM TO 500 AM OR PM 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ___ No ___ By Whom _____ Time _____ AM or PM

Report received by: _____ Signed _____

BELTS	ACTION TAKEN	INT.
4E11.5	shoveled v plow	BC
5E11.5		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	shoveled v plow at Flow thru	BC
NORTH 6	shoveled v plow at Flow thru	BC
NORTH 7		
Long wall		
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		
H622 #1		

Checked out by Refuser at # 6 w/o
 # 8 w/o } and phony working
 # 89 w/o } 20.0% O₂, 0% ppm CO, 0% CH₄

SIGNED BY: William Campbell
 Belt Examiners and Certificate Numbers _____
 Belt Examiners and Certificate Numbers _____

COUNTERSIGNED BY: T. Moore 33359
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-25-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis NO. 4	needs Dusted	BC	✓		
Ellis NO. 5	needs spot cleaned & Dusted	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take up needs added cleaning, tail needs added cleaning Drives to Discharge needs cleaned, needs spot cleaned 37-tail	BC	✓		
NORTH NO. 5	needs from top-flow thru, Take up needs added cleaning	BC	✓		
NORTH NO. 6	needs Dusted needs spot cleaned 37-tail	BC	✓		
NORTH NO. 7	needs Dusted Belt needs spot cleaned & Dusted	BC	✓		
Henry Hill		JS	✓		
GLORY HOLE	D-Box & Pump cleaned at Exam	BC	✓		
H622 NO. 1	needs spot cleaned & Dusted	JS	✓		
H622 NO. 2	needs spot cleaned & Dusted	JS	✓		
H622 #1	needs cleaned & Dusted, Rib Rolls need cleaned up in walk way	JS	✓		

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 0ppm CO, 20.8% O₂ Detected
Tail / Trunkways, D-Boxes, Chargers, KVAs, Powercenters, an obvious check
of cameras all clear at Exam

SIGNED BY: William Campbell 1354-A
Belt Examiners and Certificate Numbers
[Signature] 32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 33357
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-25-70 SHIFT: 0201 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
Elites 4	shoveled v plow change rolls LC.	BC
Elites 5		
NORTH 2		
NORTH 3		
NORTH 4	shoveled on tail shoveled v plow Rem Duster change rolls LC	BC
NORTH 5	shoveled v plow at Flow thru + tail, shoveled on tail	BC
NORTH 6		
NORTH 7	shoveled on Flow thru	BC
Longwall	shoveled AT Airtack, change rolls LC	JS
GLORY HOLE		
T622 NO. 1	shoveled v-plow	JS
T622 NO. 2		
H622 #1	shoveled v-plow	JS

Checked Outby Refuges at #6 - N/O

#8 - N/O

#89 - N/O

all Phones working

O'clock, Oppm 10, 20.6% O/S

SIGNED BY: [Signature] 13547

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

[Signature]

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

Use Indellible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-25-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom John Bickford Time 2:25 AM or PM

Report received by: Russell Dunne
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Spot Cleaned + Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Takeup tail Needs Add Cleaning, Needs Spot Cleaned Needs cleaned Drive-Discharge	RG SH	✓		
NORTH NO. 5	Takeup Needs Add Cleaning, Needs Cleaned 60-Flowthen	SH	✓		
NORTH NO. 6	Needs Dusted, Needs Spot Cleaned 87-tail	SH	✓		
NORTH NO. 7	Needs Spot cleaned + Dusted	JAB	✓		
Longwall	Belt needs Spot Cleaned + Dusted	SH	✓		
GLORY HOLE	D-Box + Pump OK	JAB	✓		
T622NO. 1	Needs spot cleaned + Dusted	JAB	✓		
T622NO. 2	Needs spot cleaned, Water at tail	JAB	✓		
H6-22 #1	Needs add's cleaning in Walk-way Needs add. spot cleaning + dusting, Accumulating at head	JAB	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways, Power Centers, Chargers, D-Boxes OK at time of exam
Visual Check of CO monitors OK at time of exam

Blair Mann P397

SIGNED BY: Russell Dunne 1536-A

Belt Examiners and Certificate Numbers

John Bickford
Belt Examiners and Certificate Numbers

Scott Halstead 37567

John [Signature] 32476

COUNTERSIGNED BY: T. Mann

Mine Foreman

83359
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-25-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. AM OR PM TO AM OR PM
PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow, cleaned & Greased tail (Bobby)	RG
Ellis 5	Shoveled V-plow, cleaned & Greased tail (Bobby)	RG
NORTH 2		
NORTH 3		
NORTH 4	RAN Duster at Drive, cleaned some on tail	SH RG
NORTH 5	Cleaned V-Plow at tail & flow thru, Ran Duster	SH
NORTH 6	cleaned V-Plow, Ran Duster, Cleaned & dusted tail & flow thru	SH
NORTH 7		
Longwa 11	Cleaned spillage at Discharge Greased on Drive, dusted around Drive, Spot Cleaned at Box CK	SH
GLORY HOLE		
76-22 NO. 1		
76-22 NO. 2		
HG-22 #1		

Resuge Chambers 6, 8, 89 BK OK at EXAM
Phones Working at time of EXAM

SIGNED BY: Russell Gunnel 1536-A
Belt Examiners and Certificate Numbers
John R. Buchford 26176
Belt Examiners and Certificate Numbers

Scott Halstead 37567
J. J. [Signature] 32476

COUNTERSIGNED BY T. Moore 33387
Mine Foreman Certificate No.

Superintendent Certificate No.

**PRE-SHIFT
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 3-25-10 SHIFT: EVE AM OR PM TO AM OR PM 800 AM OR PM TO 1100 AM OR PM PRE-SHIFT EXAM.
ON-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Brought out Time AM or PM

Report received by: _____

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs Dusted	GU	✓		
Ellis #5	Needs Spot Cleaned and Dusted	GU	✓		
L/WALL	Needs spot cleaned + Dusted	JS	✓		
NORTH NO. 3					
NORTH NO. 4	Takeup needs Add cleaned, Needs spot cleaned Needs cleaned Drive - Discharge	GU	✓		
NORTH NO. 5	Takeup needs Add cleaning Needs cleaned 60' Brk - Flow thru	GU	✓		
NORTH NO. 6	Needs Dusted, needs spot cleaned 87-Tail	GU	✓		
NORTH NO. 7	Needs spot cleaned + Dusted	JS	✓		
NORTH NO. 8					
GLORY HOLE	O-Box Pump OK	JS	✓		
TG NO. 1	Needs spot cleaned + Dusted	JS	✓		
TG NO. 2	Needs spot cleaned water at Tail	JS	✓		
H622 #1	Needs Add cleaning with heavy Needs spot cleaned + dusted	JS	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

OG CHY, OG CO, 20, 8202

PC's, Chargers, O-Boxes, Pumps, Travelways OK

SIGNED BY: [Signature] 1539A

Belt Examiners and Certificate Numbers

[Signature] 32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature]
Mine Foreman

33357
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-25-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ___ No X By Whom _____ Time _____ AM or PM

Report received by: _____
Signed

BELTS	ACTION TAKEN	INT.
<u>Ellis #4</u>	<u>cleaned V-Pul Run Ouster</u>	<u>GU</u>
<u>Ellis #5</u>	<u>cleaned V-Pul</u>	<u>GU</u>
NORTH 2		
NORTH 3		
NORTH 4	<u>Run Ouster</u>	<u>GU</u>
NORTH 5	<u>Run Ouster cleaned stem</u>	<u>GU</u>
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges 6-8-89 OK

SIGNED BY: [Signature]
Belt Examiners and Certificate Numbers
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33389
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-26-60 SHIFT: Owl AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: Brought out
 Signed _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ellis #4	Needs Dusted	GLC	✓		
ellis #5	Needs spot cleaned and Dusted	GLC	✓		
Longwall	Needs spot cleaned and Dusted	JS	✓		
NORTH NO. 3					
NORTH NO. 4	Take up needs add cleaning, needs spot cleaned Needs cleaned Drive - Discharge	GLC	✓		
NORTH NO. 5	Take up Needs Add cleaning Needs cleaned GOBRIN to flow then	GLC	✓		
NORTH NO. 6	Needs Dusted, Needs spot cleaned 87-Tail	GLC	✓		
NORTH NO. 7	Needs spot cleaned and Dusted	JS	✓		
NORTH NO. 8					
GLORY HOLE	D-Box pump ok	JS	✓		
TG NO. 1	Needs spot cleaned and Dusted				
TG NO. 2	Needs spot cleaned, water At Tail	JS	✓		
HG22 #1	Need Add cleaning walk ways Needs spot cleaned and Dusted	JS	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

0% CH₄, 20.8% O₂, Oppm C.O Detected
PC's, chargers, D-boxes, pumps, travelways, TRACK OK At Time of exam

Visual check of C.O. monitors OK At exam

SIGNED BY: Myer Cole 1947-A

Belt Examiners and Certificate Numbers
32476

COUNTERSIGNED BY: T. Miner

33259
 Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-26-10 SHIFT: owl AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: Brought out
Signed _____

BELTS	ACTION TAKEN	INT.
SOUTH 1 <u>Ellis</u>	<u>change roller LC</u>	
NORTH 1 <u>Ellis</u>	<u>change roller LC</u>	
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<u>cleaned Flow Thru V-Plow</u>	<u>GLC</u>
NORTH 6	<u>change roller LC</u>	
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<u>Ellis #4</u>	<u>cleaned V-Plow</u>	<u>GLC</u>

Refuge At ^{GLC} 6BRK, 8BRK OK At time of exam

SIGNED BY: Greg Cole 1947-A
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. M. [Signature]
Mine Foreman

33257
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-26-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs Dusted</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>Ellis 5</u>	<u>Needs Spot cleaned + Dusted</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Takeup needs cleaned, Belt needs Spot cleaned Needs cleaned Drive to Discharge</u>	<u>RG SH</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>Takeup needs Add cleaning, Needs Spot cleaned 66BK To flow thru</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>Needs Spot cleaned 87-tail, Needs Dusted</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>Belt needs Spot cleaned + Dusted</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>Longwall</u>	<u>Needs Dusted 55+25, 56+50, 66+00, 66+50</u>	<u>TD</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>					
<u>TG-22 NO. 1</u>	<u>Belt needs Additional Dusting, needs Spot cleaned</u>	<u>TM</u>	<input checked="" type="checkbox"/>		
<u>TG-22 NO. 2</u>	<u>Belt needs Additional Dusting needs Spot cleaned</u>	<u>TM</u>	<input checked="" type="checkbox"/>		
<u>HG-22 #1</u>	<u>Belt needs Additional Dusting, needs Spot cleaned</u>	<u>TM</u>	<input checked="" type="checkbox"/>		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways, Power Centers, D-Boxes, Chargers OK at time of exam
Visual Check of CO monitors OK at time of exam

SIGNED BY: Blair Ullman 1539-A
Russell Dunne 1536-A Belt Examiners and Certificate Numbers
Tom Moore 33389 Belt Examiners and Certificate Numbers
Scott Halstead 37567
Jim Deaver 38,322

COUNTERSIGNED BY: Tom Moore 33389 Mine Foreman Certificate No.
Willam Campbell 135404 Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-26-10 SHIFT: DAY 6:00 (AM OR PM) TO 3:00 (AM OR PM) AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____ Signed _____

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow (shoveled tail & Greased tail) Bobby	RG
Ellis 5	Shoveled V-plow (shoveled tail) & Greased tail (Bobby)	RG
NORTH 2		
NORTH 3		
NORTH 4	Rear duster at Drive, cleaned on tailpiece	SH RG
NORTH 5	cleaned V-Plows at tail & Flowthen, Rear Duster at Head	SH
NORTH 6	cleaned V-Plow, Rear Duster at Head	SH
NORTH 7	cleaned on tail & Greased tail Roller	SH
Longwall	cleaned at Head, Hand Dusted Head & Drive Area, ckd Splices	SH
GLORY HOLE		
TG-22 NO. 1		
TG-22 NO. 2		
HG-22 #1		

Refuge Chambers 6, 8, 89 Bks were clear time of EXAM
All Phones working at EXAM time

SIGNED BY: Don Wilman 1537A
Russell Sumner 1536-1A Belt Examiners and Certificate Numbers Scott Halsted 37567

Belt Examiners and Certificate Numbers
COUNTERSIGNED BY T. Moore Mine Foreman 33389 Certificate No. Superintendent Certificate No.

**PRE-SHIFT
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 3-26-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes No No X By Whom Brought out Time _____ AM or PM

Report received by: _____
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis NO.4	Needs Dusted	BC	✓		
Ellis NO.5	Needs Dusted + Spot cleaned	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take up needs cleaned, needs spot cleaned Drive to Discharge needs cleaned	BC	✓		
NORTH NO. 5	Take up needs added cleaning needs spot cleaned 60-Flour thru	BC	✓		
NORTH NO. 6	Needs Dusted, needs spot cleaned from 87-ft	GU	✓		
NORTH NO. 7	needs Dusted + spot cleaned	GU	✓		
Longwall	needs Dusted 55+25, 55+50, 66+00, 66+50	GU	✓		
GLORY HOLE	D-Box + Pump clear at exam	GU	✓		
T622 NO. 1	Needs added dusting + spot cleaning	GU	✓		
T622 NO. 2	Needs added dusting + spot cleaning	GU	✓		
H622 #1	needs added dusting + spot cleaning	GU	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 0ppm CO, 20.8% O₂ detected
Track/Hauling, D-Boxes, Chargers, Powercenters, KVA, Pumps and
visual check of CO monitors were all clear at Exam

SIGNED BY: William Campbell 13548
 Belt Examiners and Certificate Numbers
Don [Signature] 15399
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357 _____
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-26-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____
Signed _____

BELTS	ACTION TAKEN	INT.
CELLS 4	Shoveled V-plow	BC
CELLS 5		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Shoveled V-plow at flow + new + tail	BC
NORTH 6		
NORTH 7		
Longwall		
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		
H622 #1		

Check out by Refuges at #6 - N/O all phones working
#8 - N/O
#89 - N/O

20.6% O₂, 0% CH₄, OppimCO

Checked Intake Room - 5 GV

SIGNED BY: William Campbell 135411
Belt Examiners and Certificate Numbers
Don Mann 15399
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mann 33789
Mine Foreman Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-27-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____
Signed

BELTS	ACTION TAKEN	INT.
<u>E11.54</u>	<u>Shoveled V-plow</u>	<u>BC</u>
<u>E11.55</u>		
<u>NORTH 2</u>		
<u>NORTH 3</u>		
<u>NORTH 4</u>	<u>Shoveled V-plow</u>	<u>BC</u>
<u>NORTH 5</u>	<u>shoveled V-plow at Flow throat tail</u>	<u>BC</u>
<u>NORTH 6</u>	<u>cleaned V-plow</u>	<u>GU</u>
<u>NORTH 7</u>	<u>cleaned V-plow</u>	<u>GU</u>
<u>NORTH 8</u>		
<u>GLORY HOLE</u>		
<u>--- NO. 1</u>		
<u>--- NO. 2</u>		
<u>H622 #1</u>	<u>cleaned on Tail</u>	<u>GU</u>

Checked out by Refuges 6, 8, 89 OK
checked Intake Rooms OK

SIGNED BY: [Signature] 15799
Belt Examiners and Certificate Numbers
[Signature] 135402
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33389
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-27-70 SHIFT: Day AM OR PM TO 1200 AM OR PM TO 300 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<i>ELLIS 4</i>	<i>Needs dusted</i>	<i>JAB</i>	<input checked="" type="checkbox"/>		
<i>ELLIS 5</i>	<i>Needs dusted + spot cleaned</i>	<i>JAB</i>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<i>Take up needs cleaned drive to head needs cleaned</i>	<i>JAB</i>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<i>Take up needs add 3 cleaning needs spot cleaned 60 to Floor. Chw</i>	<i>JAB</i>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<i>Needs spot cleaned + dusted</i>	<i>JAB</i>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<i>Needs dusted + spot cleaned</i>	<i>SH</i>	<input checked="" type="checkbox"/>		
<i>LWall</i>	<i>Need more cleaning + dusting</i>	<i>HL</i>	<input checked="" type="checkbox"/>		
GLORY HOLE	<i>D Box + Pump OK</i>	<i>SH</i>	<input checked="" type="checkbox"/>		
LBB NO. 1					
LBB NO. 2					
<i>HG 22 #1</i>	<i>Needs add'l spot cleaning + dusting</i>	<i>SH</i>	<input checked="" type="checkbox"/>		
<i>T6 22 #1</i>	<i>Idle PCs - OK</i>	<i>SH</i>			
<i>T6 22 #2</i>	<i>Idle PCs OK</i>	<i>SH</i>			

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

0% ch4 0% CO + 20.8 to 22 detected

Track, travelways, PCs, chergens, D'Box's + Pumps clear at time of exam

SIGNED BY: *John B. Billard 21174*
 Belt Examiners and Certificate Numbers

Wm Lilly 70047
John H. ... 39058-88

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: *T. ...*
 Mine Foreman

33359
 Certificate No.

Superintendent

Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-27-10 SHIFT: EVE 800 AM OR PM TO 1100 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELLIS 4	NEEDS Dusted	J.M	✓		
ELLIS 5	Needs spot cleaned & dusted	J.M	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs cleaned, drive to head needs cleaned	BB	✓		
NORTH NO. 5	take up needs add cleaning, ^{needs spot cleaned} go to floor drive	BC	✓		
NORTH NO. 6	needs spot cleaned & dusted	BC	✓		
NORTH NO. 7	needs spot cleaned & dusted	BC	✓		
L.W. BELT	NEEDS add cleaning & dusting	J.M	✓		
GLORY HOLE					
LBB NO. 1					
LBB NO. 2					
TG 22 #1	IDLE -> P/C & chargers				
TG 22 #2	IDLE -> clear time of exam	J.M	✓		
AG #22 1	needs add spot cleaning & dusting	BC	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

O% chg - 20.802, O% CO

Track - travelways - P/C's - MVA's - D-Boxes - Pumps - all clear
 Time of exam

SIGNED BY: Jack Martin 37793
 Belt Examiners and Certificate Numbers
Wally L. Baker II 38699
 Belt Examiners and Certificate Numbers

Brian Collins 1543-A

COUNTERSIGNED BY T. Moore 33309 Certificate No. _____
 Mine Foreman Superintendent Certificate No. _____

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-28-10 SHIFT: aud AM OR PM TO 300 AM OR PM TO 600 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____ Signed _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs Dusted	JM	/		
Ellis #5	Needs spot cleaned + dusted	JM	/		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Tanker-up needs cleaned, drive to head needs cleaned	BB	✓		
NORTH NO. 5	Tanker-up needs add. cleaning, needs spot cleaned 60-to-60-then	BC	/		
NORTH NO. 6	Needs spot cleaned + dusted	BC	/		
NORTH NO. 7	Needs spot cleaned + dusted	BC	/		
LW Belt	Needs Add. cleaning + dusting	JM	/		
GLORY HOLE					
LBB NO. 1					
LBB NO. 2					
TG 22 #1	Idle > PC + chargers	JM	✓		
TG 22 #2	Idle > Clear at time of exam	JM	✓		
H622 #1	Needs Add. spot cleaning + dusting	BC	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

CH4 0% O2 20.8% CO 0
Track, Travelways, PC's, KVA's - D-Boxes, Pumps - All clear at time of exam

SIGNED BY: [Signature] 38699 Belt Examiners and Certificate Numbers
[Signature] 1543-A
[Signature] 33472

COUNTERSIGNED BY [Signature] 33359 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3.28.10 SHIFT: Day AM OR PM TO 1200 AM OR PM TO 300 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom J Neely Time 200 AM or PM

Report received by: John Biedford 26176
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELLIS NO. 4	Needs dusted	JAB	✓		
ELLIS NO. 5	Needs spot cleaned & dusted	JAB	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Tail needs cleaned Take-up & down to head needs cleaned	JAB	✓		
NORTH NO. 5	Take up needs add'l cleaning Needs spot cleaned & o to filter thru	JAB	✓		
NORTH NO. 6	Needs spot cleaned & dusted	JAB	✓		
NORTH NO. 7	Needs spot cleaned & dusted	JN	✓		
Lg Wall	Needs spot & dusted	TD	✓		
GLORY HOLE	Pump & D'Box - OK	JN	✓		
TG 22 NO. 1	Folle PC - OK	JN			
TG 22 NO. 2	Folle PC OK	JN			
HG 22 #1	Discharge ^{one} needs add'l cleaning Needs add'l cleaning & dusting	JN	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

07.04 07.00 & 20.8 to O₂ detected at time of exam

Visual check of CO's - OK

PC's, Tracks, Traversways, chryms, Pumps & D'Box

Don Miller 15394

SIGNED BY: John Biedford 26176 John Neely 32076
Belt Examiners and Certificate Numbers
John Neely 33472 Don Miller 15394
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3.28.10 SHIFT Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned at tail & flow thru	JN
NORTH 6	Cleaned at tail & flow thru	JN
NORTH 7	CLEAN ON 7 North ✓ Plow + TAIL	JN
<i>Lg. Hall</i>		
GLORY HOLE		
HG 22# 1	CLEAN ON Discharge Area. Pump Water Grease Discharge	JN
JG 22# 1		

Checked Refuser at 6.8 + 89 B she; OK, Phones OK

SIGNED BY: John R. Burkford 26176 Johnny Neely 33472
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mame 33387
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-28-10 SHIFT: EVE AM OR PM TO AM OR PM 800 AM OR PM TO 1100 AM OR PM 9
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Brought out Time _____ AM or PM

Report received by: _____

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELLIS SOUTH NO. 4	needs Dusted	GV	✓		
ELLIS SOUTH NO. 5	needs Dusted & spot cleaned	GV	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Tail needs Add cleaning take up and drive to the needs cleaned	GV	✓		
NORTH NO. 5	TAKE UP needs Add cleaning Needs Spotcleaned Co-Fluorine	GV	✓		
NORTH NO. 6	Needs Spot cleaned & dusted	GV	✓		
NORTH NO. 7	needs spot cleaned & dusted	JS	✓		
LITTLE NORTH NO. 8	needs spot Dusted	JS	✓		
GLORY HOLE	D-BOX Pump OK	JS	✓		
TC22 H622 NO. 1	needs spot cleaned & dusted	JS	✓		
TC22 H622 NO. 2	needs SPOT cleaned & dusted	JS	✓		
H622 #1	needs SPOT cleaned & dusted	JS	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OK CH4 OK CO 208802

PC'S, chargers, D-Boxes, Pumps, and Travelways OK

Phones Does NOT Page AT H622 #1 Head

SIGNED BY: Don Miller 1539A
Belt Examiners and Certificate Numbers
John [Signature] 32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. [Signature] 33359
Mine Foreman Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-28-10 SHIFT: EVE 600 AM OR ~~PM~~ TO 800 AM OR ~~PM~~ AM OR PM TO AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1 ^{SOUTH 5}	cleaned at Tail	GU
NORTH 2		
NORTH 3		
NORTH 4	cleaned at Tail Fixed Brake chain at 37Brik	GU
NORTH 5	cleaned f/w trow	GU
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges G. D, 89 all OK

SIGNED BY: Jim Ullman 1-53 9A
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33351

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-29-10 SHIFT: Owl 1100 AM OR PM TO 300 AM OR PM

ON-SHIFT EXAM.

AM OR PM TO

AM OR PM

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
⁸¹¹²⁷ SOUTH 1	cleaned V-Peen change roller LC	60
NORTH 1	change roller LC	
NORTH 2		
NORTH 3	change roller LC	
NORTH 4	cleaned on Tail, Randuster at drives	60
NORTH 5	cleaned Flow Inven, Randuster change roller LC	60
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
T622 #1	clean on walkway work on life link	55
LWA 11	change roller LC	

Checked out by Refigs 6-8-89 OK

SIGNED BY: [Signature] 15392

Belt Examiners and Certificate Numbers

[Signature] 32476

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature]

Mine Foreman

35357

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-29-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom J. Neely Time 2:47 AM or PM

Report received by: _____ Signed _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELLS # 4	Needs Dusted	SH	✓		
ELLS NO. 5	Needs Spot Cleaned & Dusted	SH	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	TAKUP, Drive - Head Needs Cleaned	SH	✓		
NORTH NO. 5	TAKUP Needs Add Cleaning Needs Spot Cleaned 60 BK - Flow thru	SH	✓		
NORTH NO. 6	Needs Spot Cleaned & Dusted	SH	✓		
NORTH NO. 7	Needs Dusted	JN	✓		
Long Wall	Needs Dusted from 8BK to Storage Unit	TD	✓		
GLORY HOLE	D-BOX & Pump Clean	JN	✓		
LBB NO. 1					
LBB NO. 2					
TG 22 # 1	Needs Dusted, TAIL Needs ADD CLEANING	JN	✓		
TG 22 # 2	Needs Spot Cleaned & Dusted	JN	✓		
HG 22 # 1	Needs Dusted	JN	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0ppm CO Detected at EXAM time
Power Centers, D-Boxes, Chargers, TRACK & TRAVELWAYS Clean at EXAM time
Visual CK of CO Monitors - Clean.

SIGNED BY: [Signature] 38322 Scott Halstead 37567
 Belt Examiners and Certificate Numbers
[Signature] 33472 [Signature] 32476
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359 _____
 Mine Foreman Certificate No. Superintendent Certificate No.

**ON-SHIFT
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 3-29-10 SHIFT: DAY AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM TO
ON-SHIFT EXAM. **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

BELTS	ACTION TAKEN	INT.
#4	cleaned tail & Greased & Dusted (Bobby)	
#5	cleaned tail & Greased & Dusted (Bobby)	
NORTH 2		
NORTH 3		
NORTH 4	cleaned on tail	SH
NORTH 5	cleaned V-Plow at tail & flow thru Ran Duster clean on TAIL	SH
NORTH 6	cleaned V-Plow Ran Duster	SH
NORTH 7	Ran Duster	SH
Long Wall	cleaned V-Plow at Head, Greased Discharge, cleaned & Dusted at Drive	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
H622#1	Hand Dust Drive Area, Grease on Drive	JN
T622#1	clean on V Plow & TAIL, Dust from Discharge to Takeup ^{PUMP} WATER Ran Trickle duster.	JN JN

CKd outby Refuge Chambers 6-8-89 BK - clean
All Phones Working

clean off PC's at H622 Drive + splitter clean off PC at 130 Brk

SIGNED BY: Scott Halstead 37567
Belt Examiners and Certificate Numbers
Johnny Nelly 33472
Belt Examiners and Certificate Numbers
 COUNTERSIGNED BY T. Moore 33359
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pen or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-29-10 SHIFT: EVG 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis NO. 4	needs Dusted	BC	✓		
Ellis NO. 5	needs spot cleaned & Dusted	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Takeup Drive-Head needs cleaned	BC	✓		
NORTH NO. 5	Takeup needs added cleaning needs spot cleaned from work - Plowman	BC	✓		
NORTH NO. 6	needs spot cleaned & Dusted	BC	✓		
NORTH NO. 7	needs Dusted	BC	✓		
Longwell	needs Dusted from Spork-Storage unit	JS	✓		
GLORY HOLE	D-Box & Pump clear at Exam	BC	✓		
T622 NO. 1	needs Dusted, Tail needs added cleaning	JS	✓		
T622 NO. 2	needs spot cleaned & Dusted	JS	✓		
H622 #1	needs Dusted	JS	✓		

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, OppimCO, 20.8% O₂ detected

Track Handways, D-Box & Chargers, Power Centers

an a visual check of CO monitors all clear at Exam

SIGNED BY: William Campbell 1354-1A
 Belt Examiners and Certificate Numbers

[Signature] 32476
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359
 Mine Foreman Certificate No.

Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-29-10 SHIFT: EVE 6:00 AM OR PM TO 8:00 AM OR PM 8:00 AM OR PM TO 11:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____
Signed _____

BELTS	ACTION TAKEN	INT.
Ellis 4	shoveled v plow	BC
Ellis 5		
NORTH 3		
NORTH 4	shoveled on v plow	BC
NORTH 5	shoveled v plow at Flow thru	BC
NORTH 6		
NORTH 7		
Lorigual		
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		
H622 #1		

Checked ~~at~~ by Refuges at #6 - N/O
 # 8 - N/O
 # 89 - N/O
 } all phones working
 20.6% O₂, 07% CH₄, OppimCO Detected

SIGNED BY: Walker Campbell 13544
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33387
Mine Foreman Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-30-70 SHIFT: 0w1 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
E11.34	Shoveled V-plow	BC
E11.35	change roll LC.	
NORTH 2		
NORTH 3		
NORTH 4	Shoveled V-plow + Worked on shoveling tail / working on Take up LC.	BC
NORTH 5	Shoveled V-plows at Flow thru tail	BC
NORTH 6	shoveled V-plows at tail + Flow thru change roll impact LC.	BC
NORTH 7		
Langwell	set 2 jacks at Power center at Storage unit	BC/JA
GLORY HOLE		
T622 NO. 1	SHOUL ON TAIL AND Airlock	J.S
T622 NO. 2		
H622 #1		

Checked Out by Refuges at #6 - n/o
 #8 - n/o
 #89 - n/o
 20.6% O₂, 0% CH₄; O₂ pm co & phones working

SIGNED BY: William Campbell 1354-A
 Belt Examiners and Certificate Numbers
[Signature] 32476
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 23269
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-30-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom John Neely Time 2:50 AM or PM

Report received by: Russell Bunn
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs spot cleaned	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Tail Needs additional cleaning Drive to Head needs cleaned	RG SH	✓		
NORTH NO. 5	Takeup needs Add Cleaning, needs Spot Cleaned 60-flutter	SH	✓		
NORTH NO. 6	Needs Some Spot Cleaning	SH	✓		
NORTH NO. 7	Need Dusted	JN			
Longwall	Needs Dusted from 80K to Storage Unit	SH	✓		
GLORY HOLE					
TG-22 NO. 1	Needs Dusted, Tail needs add cleaning	JN			
TG-22 NO. 2	Needs spot cleaned + Dusted	JN			
HG-22 *1	Needs Dusted, 2 Belt Rails out 2 1/2 Bak. out by Dave	JN			

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0 ppm CO at time of exam
Travelways, Power Centers, Chargers, D-Boxes OK at time of exam
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Bunn 1536-19 John Neely 32476
Belt Examiners and Certificate Numbers Scott Holthead 37567

Belt Examiners and Certificate Numbers
COUNTERSIGNED BY T. Moore 33959 Superintendent John Neely 33472
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-30-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow (Shoveled tail & Greased tail) Bobby	RG
Ellis 5	Shoveled V-plow (shoveled BRK 27 to 24) Bobby	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on tail	SH
NORTH 5	cleaned on V-Plows at tail & flow thru - clean on tail	JN SH
NORTH 6	cleaned on U-Plow	SH
NORTH 7	Clean on tail - Grease	JN
Longwell	CKD Splices cleaned Mud on inby & outby Side of Drive Area, Greased Drive Brakes	SH
GLORY HOLE		
TG-22 NO. 1	Clean on tail + V Plow - Grease tail	JN
TG-22 NO. 2	Clean under drive rollers	JN
HG-22 #1		

Refuge chambers 6, 8, 89 Bks clear at EXAM
Phones working at EXAM

SIGNED BY: Russell Gunnar 1536-A
Belt Examiners and Certificate Numbers

Scott Halstead 37567
Johnny Neely 33472

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY J. Munn
Mine Foreman

33559
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-30-10 SHIFT: EVE AM OR PM TO AM OR PM 8:00 AM OR PM TO 11:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom SKAGGS, Campbell Time AM or PM

Report received by: *[Signature]*
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis4	Needs Ousted	WC	-		
Ellis5	Needs Ousted	WC	-		
LWall	Needs Ousted 8Brk - Storage unit	JS	-		
NORTH NO. 3					
NORTH NO. 4	Tail needs Add cleaning Drive - Hd needs cleaned	WC	-		
NORTH NO. 5	Needs spot clean up Co. Further TAKEUP needs Add cleaning	WC	-		
NORTH NO. 6	Needs some spot cleaned	WC	-		
NORTH NO. 7	Needs Ousted	WC	-		
NORTH NO. 8					
GLORY HOLE	D-Box Pump OK	JS	-		
T6 ²² NO.1	Needs Ousted - Tail needs Add cleaning	WC/JS	-		
T6 ²² NO.2	Needs spot cleaned & dusted.	JS	-		
		JS	-		
H6 ²²	Needs Ousted 2Belt Rails out 2'2 Brk & Utility	JS	-		
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OK C44, OK CO, 208302
PC's, Changers, 2 Box, Pump, Travel ways OK

SIGNED BY: *[Signature]* 1354-w
Belt Examiners and Certificate Numbers
[Signature] 32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *[Signature]* 33359
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-30-10 SHIFT: 4:55 6:00 AM OR PM TO 8:60 AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____
Signed

BELTS	ACTION TAKEN	INT.
51154	Should v plow	BC
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Should v plow at flow thru	BC
NORTH 6	Should v plow at flow thru	BC
NORTH 7		
NORTH 8		
GLORY HOLE		
NO. 1		
NO. 2		

Checked out by Refuges 6-8-89 all OK

SIGNED BY: Willie Campbell 13544
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 35309
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-31-10 SHIFT: 0w1 AM OR PM TO 300 AM OR PM TO 600 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Brought out Time _____ AM or PM

Report received by: _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELISS SOUTH NO. 1	Needs Dusted	GV	-		
ELISS NORTH NO. 1	needs dusted, needs spot cleaned	GV	-		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Drive to Head needs cleaned	GV	-		
NORTH NO. 5	Needs spot cleaned 60-Foot throw TAKEUP needs Add cleaning	GV	✓		
NORTH NO. 6	Needs spot cleaned, TA. needs Add cleaning	BC	-		
NORTH NO. 7	needs Dusted, Flow throw needs Add cleaning	BC	-		
LIWAH NORTH NO. 8	needs Dusted 8BRK - storage unit	JS	-		
GLORY HOLE	D-Box Pump OK	BC	-		
TEB NO. 1	Needs Dusted TA. needs Add cleaning	JS	-		
TEB NO. 2	Needs Spot cleaned & dusted	JS	-		
HC22 #1	a Belt rails out 2 1/2 BRKs out by Drive	JS	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

02CH4 02 CO 20.8302
PCS, charges, D-BOXES, Pumps, Takeups OK

SIGNED BY: Don Williams 1539A John Shroy 32426
 Belt Examiners and Certificate Numbers
Walter Campbell 135472 Johnny Neely 33472
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33357
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-31-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
SOUTH ^{ELI 4}	cleaned Tail	CU
NORTH ^{ELI 5}	cleaned Tail cleaned take-up LC	CU
NORTH 2		
NORTH 3		
NORTH 4	cleaned Tail (grabbed out) cleaned take-up LC	CU BC JS
NORTH 5	cleaned bottom cleaned take-up LC	CU
NORTH 6	shoveled Tail	BC
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
TL 22 #2	SHOVEL V-Flow	JS

Checked out by Refuges 6-8-89 OK

SIGNED BY: [Signature] 15399 Belt Examiners and Certificate Numbers
[Signature] 32476 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359 Mine Foreman
Superintendent Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-31-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom John Bickford, John Neely Time 2:45 AM of PM

Report received by: Russell Sumner
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted + Spot Cleaned	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Drive-Discharge needs Add. cleaning	RG JAB	✓		
NORTH NO. 5	Needs spot cleaned 60-Flow-Thru, ^{TARE-UP needs} Add. cleaning	JAB	✓		
NORTH NO. 6	Needs spot cleaned, Tail needs add. cleaning	JAB	✓		
NORTH NO. 7	Needs Dusting, Flowthru Needs additional Cleaning	SH	✓		
Longwall	Needs Dusted RBK-Storage Unit	SH	✓		
GLORY HOLE					
TG-22 NO. 1	Tail needs add. cleaning, Needs Dusted				
TG-22 NO. 2	Needs Spot cleaned + Dusted, ^{Tail needs} add. cleaning				
HG-22 #1	Needs Dusted, 2 Bolt Rails out 2 1/2 brake out, Drive				

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:
0% CH4, 20.8% O2, Oppm CO at time of exam
Travelways, Power Centers, Chargers, D-Boxes OK at time of exam
Visual Check of CO monitors OK at time of exam

Dan Miller 1539A

SIGNED BY: Russell Sumner 1536-A John Bickford 26171 Scott Halstead 32476 Johnny Neely 33472
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33259 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pen or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-31-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM ON-SHIFT EXAM. AM OR PM TO AM OR PM PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:
Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow shoveled tail & Greased tail / Bobby	RG
Ellis 5	Shoveled V-plow (Shoveled tail & Greased tail) / Bobby	RG
NORTH 2		
NORTH 3		
NORTH 4	Shoveled V-plow, Row duster at Tail, cleaned tail & flow thru 5th	RG
NORTH 5	Cleaned at Tail & flow thru	SAB
NORTH 6	Cleaned & dusted at Tail.	SAB
NORTH 7	Greased on tail Roller, Row Duster	SH
Longwall	Cleaned around Drive Area, Greased on Drive Bearings	SH
GLORY HOLE		
TG22NO. 1	CLEAN TAIL + on Flow Thru - Grease Holdup Roller	JN
TG22NO. 2	CLEAN ON TAIL	JN
HG-22 #1	Dust Drive Area - Work on Guards	JN

ReSuge Chambers 6, 8, 9, 8 OK + phones working at time of exam

SIGNED BY: Russell Sumner 1536-19
Belt Examiners and Certificate Numbers
John H. Beckford 26176
Belt Examiners and Certificate Numbers

Scott Halstead 37567
Johnny Neely 33472

COUNTERSIGNED BY T. Moore 20209
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-31-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	set Amp at Tail	GU
NORTH 5	Cleaned Tail + Flow frame	GU
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges 6-8-89 OK

SIGNED BY: [Signature] 1539A
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33327
Mine Foreman Certificate No. Superintendent Certificate No.

