

Started 3-1-10

# EXAMINATION OF BELT CONVEYORS

Finished 3-16-10

COMPANY Performance Cont Co  
MINE Upper Big Branch  
LOCATION Naoma Raleigh WV  
Post Office County State

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-1-10 SHIFT: owl 1100 AM OR 300 TO 300 AM OR PM 300 AM OR PM TO 600 600 AM OR PM  
**ON-SHIFT EXAM.** **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>E111st#4</u>	<u>needs dusted, needs cleaned from 101 - Drift</u>	<u>BC</u>	<u>✓</u>		
<u>#E111st#5</u>	<u>mil needs added cleaning, needs spot cleaned &amp; dusted</u>	<u>BC</u>	<u>✓</u>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>needs cleaned from 10brk - Head</u>	<u>BC</u>			
<u>NORTH NO. 5</u>	<u>needs dusted</u>	<u>BC</u>	<u>✓</u>		
<u>NORTH NO. 6</u>	<u>needs spot cleaned &amp; dusted</u>	<u>BC</u>	<u>✓</u>		
<u>NORTH NO. 7</u>	<u>Needs spot clean &amp; dusted</u>	<u>JS</u>	<u>✓</u>		
<u>Longwall</u>	<u>NEED SPOT CLEAN &amp; DUSTED</u>	<u>JS</u>	<u>✓</u>		
<u>GLORY HOLE</u>	<u>PC &amp; O Box ok</u>	<u>JS</u>	<u>✓</u>		
<u>H622#1</u>	<u>NEED WALKWAY CLEAN &amp; DUSTED</u>	<u>JS</u>	<u>✓</u>		
<u>H623#</u>	<u>Idle No Pre-shift</u>	<u>JS</u>	<u>✓</u>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> detected

Track/Travelways, D-BOR's, P.L's, Pumps, Chargers & CO's all clear at Time of Exam

SIGNED BY: William Campbell 1354-12 Johnny Neely 33472  
Belt Examiners and Certificate Numbers  
32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: F. M. M... 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Russell Dummer 1536-1A

Scott Halstead 37567

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-1-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
<u>E11/5#4</u>	<u>Shoveled v plow</u>	<u>BC/JS</u>
<u>E11/5#5</u>	<u>Shoveled on tail (Gob out)</u>	
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<u>Shoveled v plow at Flow through</u>	<u>BC</u>
NORTH 6		
NORTH 7	<u>Shoveled on tail</u>	<u>BC/JS</u>
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

out by Refuges at #6, 8, 89 brk all clear at Exam, + Phones working

SIGNED BY: W. H. Campbell 12542 J. L. [Signature] 32476  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. [Signature] 33359 \_\_\_\_\_  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-1-10 SHIFT: Day AM OR PM TO AM OR PM 12:00 AM OR PM TO 3:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Neely Time 2:40 AM or PM

Report received by: Russell Gurnal  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted, Needs spot cleaned 101-Drift	RG	✓		
Ellis 5	Needs Dusted + spot cleaned	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs cleaned + Dusted 10-Head, <sup>Take-up needs</sup> Add. cleaning	RG	✓		
NORTH NO. 5	Needs Dusted	RG	✓		
NORTH NO. 6	Needs spot cleaned 90-Tail, Needs Dusted	RG	✓		
NORTH NO. 7	tail needs add cleaning	SH	✓		
Longwall	Needs Spot Cleaned + Dusted	SH	✓		
GLORY HOLE	D-Box + Pump -OK at EXAM	SH	✓		
LBB NO. 1					
LBB NO. 2					
HG-22	Needs walkway cleaned + Dusted	JN	✓		
Tail Gate 22	Needs Trash cleaned up + <sup>Needs guard behind discharge</sup> Needs Dusted Drive-Discharge	JN	✓		
HG-23	NO Power, NO preshift	RG	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0 ppm CO at time of exam  
Travelways, Power Boxes, chargers, D-Boxes OK at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gurnal 1536-A Scott Halstead 32567  
 Belt Examiners and Certificate Numbers  
John Neely  
 Belt Examiners and Certificate Numbers  
 SUPERINTENDENT  
 COUNTERSIGNED BY: J. M. ... 33357 William Campbell 1354-A  
 Mine Foreman Certificate No. Superintendent Certificate No.

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-1-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM \_\_\_\_\_

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	cleaned + Greased tail (Bobby + Stanley)	
Ellis 5	shoveled v-plow - cleaned + Greased tail (Bobby + Stanley)	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on Tail, RAN Dusters at Tail + Drives, shoveled v-plow	RG
NORTH 5	Cleaned on Tail + Flow-Thru, RAN duster at Flow-Thru	RG
NORTH 6	Dusted at Head, cleaned on tail	SH RG
NORTH 7	clean 7 North Tail	JN
Long wall	Greased on Discharge, cleaned v-plow at flowthru	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
H6221	Put clamps on GEAR'S DRIVE AREA CLEAN ON BELT	JN
	Put mats at PC-splitter at H622 DRIVE + Fire Extinguisher	JN

*Refuge chambers 6, 8, 9, 8 bek 2 sect. OK + phones work at time of exam*

SIGNED BY: Russell Gunnar 1536-A Scott Halstead 37567  
Belt Examiners and Certificate Numbers

Johnny Neely  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33357  
Mine Foreman Certificate No. Superintendent Certificate No.

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-1-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM TO 800 AM OR PM TO 1100 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom J. Skaggs Time 11:00 AM or PM

Report received by: William Campbell 1354-A  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>Ellis #4</del>	needs Dusted, needs cleaned from 101-Drift	BC	✓		
<del>Ellis #5</del>	Needs Spot cleaned & Dusted	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs cleaned from 10brk-Head, Dusted, <sup>Take up weirs</sup> added cleaning	BC	✓		
NORTH NO. 5	needs Dusted	BC	✓		
NORTH NO. 6	needs spot cleaned 90-tail & Dusted	BC	✓		
NORTH NO. 7	Tail needs added cleaning	BC	✓		
<del>Longway</del>	needs spot cleaned & Dusted	JS	✓		
GLORY HOLE	D-Box & Pump - clean at Exam				
H622	AT TAIL needs Jacks set on OFF side	JS	✓		
	Walkway & Belt needs cleaned & Dusted				
Tailgate 22	needs guard behind discharge needs Trash cleaned up around Head Dusted	JS	✓		
H623	IDLE, NO Preshift, No Power	JS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> Detected  
TRACK/Travelways, P.C.'s, D-Boxes, chargers, Pumps & visual check of CO's  
All Clear at Exam

SIGNED BY: William Campbell 1354-A  
 Belt Examiners and Certificate Numbers

[Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY To [Signature] 33357  
 Mine Foreman

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-1-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4	Shoveled v-plow	BC
Ellis #5	Shoveled v-plow	BC
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Shoveled v-plow at Flow through	BC
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LEB NO. 1		
LEB NO. 2		

Outby Refuges at breaks; 6, 8, 89 - 0% CH4, 0% CO, 20.6% O2 - all clear at Exam  
+ phones are working

SIGNED BY: William Campbell  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 3357  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-2-10 SHIFT: owl 11:30 AM OR PM TO 3:00 AM OR PM 3:00 AM OR PM TO 6:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis #4</u>	<u>needs dusted needs cleaned from IDL-Drift</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>Ellis #3</u>	<u>needs spot cleaned &amp; dusted</u>				
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Take up needs added cleaning Needs cleaned from IDL - Hens, needs dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>needs dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>Needs spot cleaned from 90-tail, needs dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>Needs dusted &amp; tail needs added cleaning</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>Longwall</u>	<u>NEEDS CLEAN &amp; DUSTED</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	<u>D-Boxes PC OK</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>H6 #2</u>	<u>NEEDS CLEAN AND DUSTED</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
FIRE RUN					
<u>Tailgate #1</u>	<u>NEEDS CLEAN &amp; DUSTED</u>	<u>JS</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> Detected  
Tram/Tranclways, PL's, D-Box's, chargers, Pumps, KVA's & visual  
check of CO's all clear at Exam

SIGNED BY: Walter Campbell 13547  
 Belt Examiners and Certificate Numbers  
[Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. [Signature] 33859  
 Mine Foreman Certificate No.



## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-2-10 SHIFT: owl 11:30 AM OR 300 300 PM TO 300 600 AM OR PM TO 600 600 PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<del>R/W</del> #4	shoveled v plow	BC
<del>R/W</del> #5	shoveled v plow	BC
NORTH 2		
NORTH 3		
NORTH 4	shoveled tail roller & v-plow	BC
NORTH 5	shoveled v plow at flowthrough	BC
NORTH 6		
NORTH 7	shoveled on tail	BC
<del>R/W</del> #11		
GLORY HOLE		
<del>CHENO</del>		
<del>CHENO 2</del>		

outby Refuges at breaks 6, 8, 89 - all clear 20.6% O<sub>2</sub>, 0% CH<sub>4</sub>, 0% CO Detected  
 + All phones work

SIGNED BY: William Campbell 1354  
 Belt Examiners and Certificate Numbers  
[Signature] 3976  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 3334  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-2-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Neely Time 2:40 AM or PM

Report received by: Russell Durnal  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted, needs cleaned 101-Drift	RG	✓		
Ellis 5 1	Needs Dusted, needs spot cleaned 12927+73	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Dusted Needs cleaned 10-Head, Take-up needs add. cleaning	RG	✓		
NORTH NO. 5	Needs Dusted, Take-up needs add. cleaning + Dust	RG	✓		
NORTH NO. 6	Needs spot cleaned 90-Tail, needs Dusted	RG	✓		
NORTH NO. 7	tail needs Add Clearing	SH	✓		
Lanowall	Needs Spot Cleaned + Dusted	SH	✓		
GLORY HOLE	D-Box + Pump - Clear	SH	✓		
HG-22	Needs cleaned + Dusted	JN	✓		
Tail Gate 22	Needs <del>was</del> cleaned + Dusted	JN	✓		
HG-23 1	} out of service, No Power - No Pre-shift	RG			
HG-23 2					
HG-23 3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO at time of exam  
Travelways, Power Centers, D-Boxes, Chargers OK at time of exam  
Visual Check of CO monitors OK at time of exam

SIGNED BY: Russell Durnal 1531-A Willie Campbell 1354-A  
 Belt Examiners and Certificate Numbers  
John Neely Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
John Shy 32476

COUNTERSIGNED BY T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-2-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM \_\_\_\_\_

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
EL15 A	Shoveled Tail & Greased Tail (Bobby)	
EL15 B	Shoveled V-plow Shoveled Tail & Greased Tail (Bobby)	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on Tail, Ran dusters at Tail + Drives	RG
NORTH 5	Cleaned on Tail + Flow-Thru, Hand Dusted at Tail	RG
NORTH 6	Ran Duster at Head	RG
NORTH 7	Cleaned some under tail - Pump some water	SHN
Long Wall	Cleaned Build up under Belt near drive & Dusted, Greased Drive <small>Ran Duster at Storage unit</small>	SH
GLORY HOLE		
LEB NG 1		
LEB NG 2		
HC22 #1	Grease Drive, Takeup, Hold down Roller Behind discharge Dust Around PC CLEAN ON Belt Line	JM JM

*Refuge chambers at 6, 8, 9, 8 back 2 sect. OK + phones working at time of exam*

SIGNED BY: Russell Ginnoc 1536-A Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
Johnny Deely 33472 John [Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359 \_\_\_\_\_  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-2-10 SHIFT: EVE AM OR PM TO 800 AM OR PM 10/100 AM OR PM 10/100 AM OR PM 10/100  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes X No      By Whom Campbell, Skaggs Time 100 AM or PM PM

Report received by: Olly Williams  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs Dusted, needs cleaned 101-Drift	GU	✓		
Ellis #5	Needs Dusted, needs spot cleaned 29-27+73	GU	✓		
NORTH NO. 2					
NORTH NO. 4	Needs Dusted Needs cleaned 10-Hd Takeup needs Add cleaning	GU	✓		
NORTH NO. 5	Needs Dusted, Takeup needs Add cleaning	GU	✓		
NORTH NO. 6	Needs spot cleaned 90-Tail, needs Dusted	WC	✓		
NORTH NO. 7	Tail Needs Add cleaning	WC	✓		
LOWAIL	Needs spot cleaned & dusted	JS			
GLORY HOLE	D-Box & Amp clear	WC	✓		
Head gate 22	Needs cleaned & dusted	JS	✓		
Tail gate 22	Needs cleaned & dusted	JS	✓		
H623	> no power no preshift				
H623					
H623					

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
02 ch4 02 CO 20.8302  
PC's, Chargers, D-Boxes Travel maps OK

SIGNED BY: Olly Williams 1539A William Campbell 1354-A  
 Belt Examiners and Certificate Numbers  
John Skaggs 3849C  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. M. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 30/10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include NORTH 2-7, GLORY HOLE, LBB NO. 1, LBB NO. 2 with handwritten notes like 'Ran duster', 'cleaned & dusted Flow Thru', 'shoveled V-plow at Flowthrough'.

checked out by Refuges 6-8-89 OK & Phones Working

SIGNED BY: [Signature] 1539A Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359 Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

DATE 3-3-10 SHIFT: owl AM OR PM TO \_\_\_\_\_ AM OR PM TO 600 ~~AM OR PM~~ 600 ~~AM OR PM~~  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_\_\_ No ✓ By Whom Brought out Time \_\_\_\_\_ AM or PM  
Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	GU	✓		
Ellis 5	Needs Dusted needs spot cleaned <sup>273</sup>	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Dusted Needs cleaned 10-Hd TAKEUP needs additional	GU	✓		
NORTH NO. 5	Needs Dusted TAKEUP needs additional	GU	✓		
NORTH NO. 6	needs cleaned from tail to 876K, needs Dusted	BC	✓		
NORTH NO. 7	Needs Dusted from Head to tail, needs spot cleaned <sup>at</sup> tail	BC	✓		
<del>NORTH NO. 8</del>	long wall Needs Dusted	JS	✓		
GLORY HOLE	IDLE, D-Box + Pump - clear at Exam	BC	✓		
LBB NO. 1					
LBB NO. 2					
H622#1	NEEDS WALKWAY & BELT NEEDS CLEAN & DUSTED	JS	✓		
H622#2	NEEDS CLEAN & DUSTED	JS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
OG ch4 OG CO 20.82 02  
PC'S CHARGERS TRACK TRAVEL WAYS OK

SIGNED BY: [Signature] 1539A Johnny Neely 33472  
Belt Examiners and Certificate Numbers  
[Signature] 32476 William Campbell 13547A  
Belt Examiners and Certificate Numbers  
COUNTERSIGNED BY [Signature] 33359  
Mine Foreman

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-3-10 SHIFT: owl 1130 AM OR PM TO 300 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<del>SOUTH</del> <u>ELLIS #4</u>	<u>Cleaned from 101Bk To outside</u>	<u>BC JS</u>
<del>NORTH</del> <u>ELLIS #5</u>	<u>cleaned V-plow Ran duster</u>	
NORTH 2		
NORTH 3		
NORTH 4	<u>Cleaned V-plow</u>	
NORTH 5	<u>cleaned V-plow Ran duster</u>	
NORTH 6	<u>cleaned vplow</u>	<u>BC</u>
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<u>Charged by</u> <u>Hole # 5211.3</u>	<u>cleaned trash upan, dusted</u>	<u>BC/JS</u>

Checked out by Refuges 6-8-89 OK

SIGNED BY: [Signature] 15347  
 Belt Examiners and Certificate Numbers  
[Signature] 1354-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-3-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM DO 3:00 AM OR PM

ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Bickford, Neely Time 2:30 AM or  PM

Report received by: Russell Gunnar  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted, needs spot cleaned 7-3	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Dusted Needs cleaned 10-Head, Take-up needs add. cleaning	RG	✓		
NORTH NO. 5	Needs Dusted, Take-up needs Add. cleaning	JAB			
NORTH NO. 6	Needs spot cleaned 87-Tail, Needs Dusted	JAB			
NORTH NO. 7	tail needs add cleaning, Needs Some Dusting	SH	✓		
Longwall	Needs Some Spot Cleaning + Dusting	SH	✓		
GLORY HOLE	D-Box + Pump OK	SH	✓		
HG-22	Needs cleaned + Dusted	JN	✓		
Tail Gate 22	needs spot cleaned + Dusted	JN	✓		
HG-23 1,2,3	NO Power, NO Pre-shift	JN			

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO at time of exam  
Travelways, Power Centers, Chargers, D-Boxes OK at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Don Wilson 1539A John Gunnar 32476  
Belt Examiners and Certificate Numbers  
John H. Bickford 26176 Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
Johnny Neely 33472

COUNTERSIGNED BY T. Munn 33359  
Mine Foreman Certificate No. Superintendent Certificate No.



## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-3-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis-4	Cleaned + Greased + Dusted tail (Bobby A)	
Ellis-5	Shoveled V-plow, RAN duster at Tail (cleaned, Greased + Dusted tail) <sup>Bobby A</sup>	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on Tail, RAN dusters at Tail + Drives	RG
NORTH 5	Dusted Take-up,	
NORTH 6	Cleaned + dusted at tail	TAB
NORTH 7	Cleaned on tail Pump water at Tail	SH
Long Wall	cleaned on Spillage <sup>RAN duster at Storage Unit,</sup> BtwN Discharge + Drive, Bailed water at Discharge	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
HG 22	Pick up Trash + dust Around Drive Grease on HEAD	JN
TAILGATE 22	" " " " " " " " + HEAD	JN

Refuge chambers at 6, 89, 86ak 22sat. OK + phones working at time of exam

SIGNED BY: Dan Williams 1539A  
Belt Examiners and Certificate Numbers  
Russell Dunne 1536-A  
Belt Examiners and Certificate Numbers  
John Bedford 2617A  
Belt Examiners and Certificate Numbers  
Scott Holstead 37567  
Johnny Neely 33472

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-3-10 SHIFT: EVE AM OR PM TO 800 AM OR PM TO 1100 AM OR PM

ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom SKAGGS Time 1100 AM or  PM

Report received by: Dan Williams

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs Dusted	GU	✓		
Ellis #5	Needs Dusted needs spot cleaned 7-3	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Cleaned Head - 10Bk Needs Dusted, Takeup needs Add cleaning	GU	✓		
NORTH NO. 5	Needs Dusted, Takeup needs Add cleaning	GU	✓		
NORTH NO. 6	Needs spot cleaned 87-Tail Needs Dusted	GU	✓		
NORTH NO. 7	Tail Needs add cleaning need som Dusting	JS	✓		
L-wall	needs spot cleaned + Dusted	JS	✓		
GLORY HOLE	D-Box + Pump	JS			
LBB NO. 1					
LBB NO. 2					
H622 H6	Needs spot cleaned + dusted	JS	✓		
H622 TG	Needs spot cleaned + dusted	JS	✓		
H623	no Power NO Reshift				

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

06 Ch4, 08 CO, 20.8202  
PG5, Chargers, D-Boxes Track Travel ways OK

SIGNED BY: Dan Williams 15397A

Belt Examiners and Certificate Numbers  
John [Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
 Mine Foreman

Certificate No. Superintendent Certificate No.

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-3-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
ELLIS #4	Ran Ouster, cleaned V-Pow	GU
ELLIS #5	cleaned V-Pow	GU
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	cleaned V-Pow	GU
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

OG CHY OG CO 20.8302  
checked out by Refuges 6-8-89 all OK

SIGNED BY: Don Wilson 15394 John [Signature] 32476  
Belt Examiners and Certificate Numbers  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33307  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-4-10 SHIFT: owl AM OR PM TO \_\_\_\_\_ AM OR PM TO 300 ~~AM OR PM TO~~ 600 ~~AM OR PM~~  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Brightout Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs dusted	GU	/		
Ellis #5	needs dusted 27-Hd need 7-3Bkt	GU	/		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs dusted Drives To Takeup Takeup need cleaned	GU	/		
NORTH NO. 5	needs dusted, Takeup needs full cleaning	GU	/		
NORTH NO. 6	needs spot cleaned 87-Tail, needs dusted	GU	/		
NORTH NO. 7	NEEDS SPOT CLEAN & DUSTED	JS	✓		
ZONWALL	NEEDS DUSTED	JS	✓		
GLORY HOLE	Pump & B-Boxes OK	JS	✓		
LBB NO. 1					
LBB NO. 2					
H622 #1	Belt Needs cleaned & dusted (6 Bottom Rollers New)	JS	✓		
	Replaced Know Pinlock to Tail	JS	✓		
<del>H622</del> #1	NEEDS CLEAN & DUSTED HEAD TO TAIL	JS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4 0% CO 20.8% O2 AT TIME OF EXAM  
TRACK & TRAVELWAYS OK AT TIME OF EXAM

SIGNED BY: Don Miller 1539A  
 Belt Examiners and Certificate Numbers  
John Bishop 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33387  
 Mine Foreman Certificate No. Superintendent Certificate No.

Russell Gunnoc 1536-A Johna. Bickford 26171 Scott Halstead 32567

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-4-10 SHIFT: owl 1100 AM OR ~~PM~~ TO 300 ~~AM~~ OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
Ellis #4	Ran Duster, cleaned v-plow change rolls h/c	JS
Ellis #5	Ran Duster, cleaned v-plow Greasol Hd, <sup>LC</sup> Take up change with	GU JS
NORTH 2		
NORTH 3		
NORTH 4	Ran Duster change brake chain h/c	GU JS
NORTH 5	Ran duster cleaned v-plow	GU JS
NORTH 6		
NORTH 7	change brake chain h/c	
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuser 6889 OK  
 Checked Intake Rooms (GU) OK  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

SIGNED BY: [Signature] 15394  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 37389  
Mine Foreman Certificate No. Superintendent Certificate No.

John H. Bickford 21176

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-4-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:30 AM or  PM

Report received by: Russell Gunnre  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted 15-25	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 10-Discharge, Needs Dusted 5-Tail	RG	✓		
NORTH NO. 5	Needs Dusted, Take-up needs Add. cleaning	RG	✓		
NORTH NO. 6	Needs Dusted, Needs spot cleaned 8-Tail	RG	✓		
NORTH NO. 7	tail needs Add. Cleaning, Walkway at 108 Needs Add. Cleaning	SH	✓		
Long wall	Belt Needs Dusted	SH	✓		
GLORY HOLE	D-Box + Pump - Clear	SH	✓		
HG-22	Needs cleaned + Dusted	JAB	✓		
Tail Gate 22	Needs spot cleaned + Dusted	JAB	✓		
HG-23 - 1	} NO Power NO Preshift				
HG-23 - 2					
HG-23 - 3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0 ppm CO at time of exam  
Travelways, Power Boxes, Chargers, D-Boxes OK at time of exam  
VISUAL check of CO monitors OK at time of exam

SIGNED BY: Russell Gunnre 1536-A Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
John Bickford 26176 [Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 32359  
Mine Foreman Certificate No. Superintendent Certificate No.

46543—BJW Printing & Office Supplies  
John Bickford 26176

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-4-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis-4	(Shoveled trail & Greased trail) (Bobby)	
Ellis-5	Shoveled v-plow (shoveled & Greased trail) (Bobby)	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, Ran Dusters at Tail & Drives,	RG
NORTH 5	Shoveled v-plow at Tail & Flow-Thru, Cleaned on Take-up 5 <sup>15</sup>	RG
NORTH 6	Ran Duster at Head, cleaned at Tail	RG
NORTH 7	cleaned some on tail, cleaned on walkway at 128 BK	SH
Long Wall	cleaned Spillage under flow thru - offside, <sup>did PM on Head &amp; Storage</sup> cleaned on Mud at Drive	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Refuge chambers at 6, 8, 9, 8 bak. 2 sect. OK & phones working at time of exam

SIGNED BY: [Signature] 15397

Belt Examiners and Certificate Numbers  
Russell Gunnar 153677

Belt Examiners and Certificate Numbers  
John A. Beckford 26176

Scott Holstead 37567

COUNTERSIGNED BY T. Mene 33359

Mine Foreman

Certificate No.

Superintendent

Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-4-70 SHIFT: 2nd AM OR PM TO 8:00 AM OR PM TO 11:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
CRUIS * 4	NEEDS DUSTED	GU	✓		
CRUIS * 5	NEEDS DUSTED	GU	✓		
NORTH NO. 2			✓		
NORTH NO. 3	NEEDS SPOT CLEAN & DUSTED	GU	✓		
NORTH NO. 4	TAKE UP NEEDS CLEAN & DUSTED	GU	✓		
NORTH NO. 5			✓		
NORTH NO. 6	NEEDS DUSTED	GU	✓		
NORTH NO. 7	NEEDS CLEANING AT TAIL & 128 BULK WALKWAY <sup>DUSTED</sup>	JS	✓		
TRAVELWAY	NEEDS CLEAN & DUSTED	JS	✓		
GLORY HOLE	PUMP & D-BOX OK.	JS	✓		
TRAVELWAY	NEEDS CLEAN & DUSTED	JS	✓		
TRAVELWAY					
Tail Gate 22	NEEDS WALKWAY & BELT CLEAN & DUSTED	JS	✓		
4623 * 1	} Idle NO POWER NO PRE-SHIFT				
* 2					
* 3					

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

% CH<sub>4</sub> 0% CO<sub>2</sub> 20.9% O<sub>2</sub> AT TIME OF EXAM

TRAVELWAYS, P.C. D-BOXES OK AT TIME OF EXAM

REFUGE BOXES 6, 8, 89 OK AT TIME OF EXAM

SIGNED BY: [Signature] 32476

Belt Examiners and Certificate Numbers

[Signature] 15397  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature]

Mine Foreman

33357  
Certificate No.

Superintendent

Certificate No.



ON-SHIFT

Use Indellible Pencil or Ink

EXAMINATION OF BELT CONVEYORS

DATE 3-4-10 SHIFT: EUS 6:00 AM OR PM TO 8:00 AM OR PM 6 AM OR PM TO            AM OR PM            AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes            No X By Whom            Time            AM or PM           

Report received by:             
Signed           

BELTS	ACTION TAKEN	INT.
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
GLORY HOLE		

Checked out by Refuges 6-8-89 OK

SIGNED BY: *[Signature]* 153011  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *T. Moore* 33357  
Mine Foreman Certificate No. Superintendent Certificate No.

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-5-10 SHIFT: owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis #4</u>	<u>Needs Dusted</u>	<u>GU</u>	<u>-</u>		
<u>Ellis #5</u>	<u>Needs Dusted 15-24</u>	<u>GU</u>	<u>-</u>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Needs Dusted Drive to Tail Takeup needs and cleaning</u>	<u>GU</u>	<u>-</u>		
NORTH NO. 5	<u>Needs Dusted, Takeup needs cleaned</u>	<u>GU</u>	<u>-</u>		
NORTH NO. 6	<u>Needs Spoked and 87-Tail, needs Dusted</u>	<u>GU</u>	<u>-</u>		
NORTH NO. 7	<u>Needs Dusted</u>	<u>JS</u>	<u>✓</u>		
<u>Longwall</u>	<u>Needs Dusted</u>	<u>JS</u>	<u>✓</u>		
GLORY HOLE	<u>Pump &amp; D-Box</u>	<u>JS</u>	<u>✓</u>		
<u>H622 #1</u>	<u>Needs Clean &amp; Dusted</u>	<u>JS</u>	<u>✓</u>		
<u>H623 #1</u>	<u>TALK NO PAVEN</u>	<u>JS</u>	<u>✓</u>		
<u>#2</u>					
<u>#3</u>					
	<u>NO PRE-SHIFT</u>	<u>JS</u>	<u>✓</u>		
<u>TAIL BATH 22</u>	<u>Needs Clean &amp; Dusted</u>	<u>JS</u>	<u>✓</u>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OG Chy CB CO 208602  
PCS, Charges, O-Boxes, Track, Travel ways clear

SIGNED BY: [Signature] 15397  
Belt Examiners and Certificate Numbers  
[Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

46543-BJW Printing & Office Supplies  
Russell Gummel 1536-A John A. Bickford 26176 Scott Halstead 37567

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-5-10 SHIFT: owl 1100 AM OR PM TO 200 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
ELISSY	Cleaned V Pan (Shoveled tail & Greased tail) Bobby	6
ELISS	Cleaned V Pan (Shoveled tail & Greased tail) Bobby	6
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned V Pan	
NORTH 6		
NORTH 7		
GLORY HOLE		

*Checked out by Refuges 6-8-89 OK*

SIGNED BY: [Signature]  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

*John A. Buckford 26176*

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-5-10 SHIFT: Day AM OR PM TO AM OR PM 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:30 AM or PM

Report received by: Russell Gurnea  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted 15-24	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Dusted, Take-up needs Add. cleaning	RG	✓		
NORTH NO. 5	Needs Dusted, Take-up need Add. cleaning	RG	✓		
NORTH NO. 6	Needs spot cleaned 87-Tail, Needs Dusted	RG	✓		
NORTH NO. 7	Needs Dusted, tail needs Add. Cleaning, <sup>WALKWAY OF 125 BK</sup> Needs Add. Cleaning	SH	✓		
L. Dringwall	Needs Dusted, DRIVE Needs Add. Cleaning	SH	✓		
GLORY HOLE	D. Box & Pump - Clear	SH	✓		
HG-22	Needs cleaned & Dusted	JAB	✓		
Tail Gate 22	Needs cleaned & Dusted	JAB	✓		
HG-23 1	} NO Power NO Preshift	JAB			
HG-23 2					
HG-23 3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO at time of exam  
Travelways, Power Boxes, chargers, D-Boxes OK at time of exam  
Visual check of CO monitors OK at time of exam

Alan Williams 1539A

SIGNED BY: Russell Gurnea 1536-A Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
John Bickford 2617 Williams 1539A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Meme 33389  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-5-10 SHIFT: DAY 6:00 AM TO 3:00 PM ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include Ellis 4, Ellis 5, NORTH 2, NORTH 3, NORTH 4, NORTH 5, NORTH 6, NORTH 7, Longwall, GLORY HOLE.

RAW DUST

Refuges at 6, 89, 86rk 2sect. OK + phones working at time of exam

SIGNED BY: Dan Wilson 1539A, Russell Dumas 1536-A, Scott Halstead 37567, John Beckel 2617A

COUNTERSIGNED BY: T. Moore Mine Foreman, Certificate No. 33357 Superintendent, Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-05-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>ENGINE</del>	<u>needs spot cleaned</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<del>ELISHA</del>	<u>needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 4	<u>needs Dusted, Takeup needs added cleaning</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>needs Dusted, Takeup needs added cleaning</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>needs spot cleaned 27-tail needs, Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>needs Dusted, tail needs added cleaning needs Appl. cleaning walkway at 188</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>Kong wall</u>	<u>needs Dusted, Drive Needs Added cleaning</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	<u>D-Box, Pump = all clear</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
H622 IO. 1	<u>needs Dusted &amp; cleaned</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>Tail Gate 22</u>	<u>needs cleaned &amp; Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
H623 #1	<u>IDLE, No Power, NO Preshift</u>				
#2					
#3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> Detected  
TRAIL / TRAVELWAY, P.L.'s, chargers, D-Box & visual check of CO's  
all clear at Exam

SIGNED BY: [Signature] 13847  
 Belt Examiners and Certificate Numbers  
[Signature] 15397  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33357  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-05-70 SHIFT: EVC 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
Ellis #4	shoveled v plow	BC
Ellis #5	shoveled v plow	BC
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
GLORY HOLE		
NO. 1		

*Checked out by Refugees 6889 OK*

SIGNED BY: William Campbell 1354-A  
Belt Examiners and Certificate Numbers  
John White 153-A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 3335-9  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3/6 SHIFT: OWL AM OR PM TO 300 AM OR PM TO 600 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes X No X By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>E118#4</u>	<u>Needs Ousted</u>	<u>GU</u>	<u>✓</u>		
<u>E118#5</u>	<u>Needs Spotcleaned</u>	<u>GU</u>	<u>✓</u>		
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Needs Ousted, Takeup needs Add cleaning</u>	<u>GU</u>	<u>✓</u>		
<u>NORTH NO. 5</u>	<u>Needs Ousted, Takeup needs Add cleaning</u>	<u>GU</u>	<u>✓</u>		
<u>NORTH NO. 6</u>	<u>Needs Spot cleaned 87-Tail, needs Ousted</u>	<u>GU</u>	<u>✓</u>		
<u>NORTH NO. 7</u>	<u>Needs Ousted, Tail needs Add cleaning</u>	<u>WC</u>	<u>—</u>		
<u>L118#1</u>	<u>Needs Spot cleaned &amp; dusted</u>	<u>WC</u>	<u>—</u>		
<u>GLORY HOLE</u>	<u>D-Box Pump OK</u>	<u>WC</u>	<u>—</u>		
<u>LBB NO. 1</u>					
<u>LBB NO. 2</u>					
<u>H622#1</u>	<u>Needs Ousted &amp; cleaned</u>	<u>WC</u>	<u>—</u>		
<u>T622#1</u>	<u>Needs Ousted &amp; cleaned</u>	<u>WC</u>	<u>—</u>		
<u>H623</u>	<u>NO Power NO Dreshift</u>	<u>GU</u>	<u>—</u>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OG Chy CB CO 20.8202 #

PC'S, Chagas, D-Boxes, Pumps Boxes OK

SIGNED BY:

William Campbell 1557A  
Belt Examiners and Certificate Numbers

Johnny Neely 33472  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

T. Moore 3507  
Mine Foreman

46543—BJW Printing & Office Supplies

Mine Foreman

Certificate No.

Superintendent

Certificate No.

John B. Bedford 26176 Russell Dunmore 1536A

Scott Holstead 37567



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-06 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM AM OR PM TO AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INF.
Ellis 4	Cleaned V-Row	GU
Ellis 5	Cleaned V-Row	GU
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned V-Row	GU
NORTH 6		
NORTH 7	Shoveled V-Row	BC
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges 6-8-89 OK  
 checked rooms  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

SIGNED BY: [Signature] 1539A  
 Belt Examiners and Certificate Numbers  
William Campbell 1354-4  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-6-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford, John Neely Time 2:25 AM or PM

Report received by: Russell Gunnore  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted 15-24	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Dusted Spot cleaned 7-HEAD, TAKE-up needs add cleaning	JAB	✓		
NORTH NO. 5	Needs Dusted, TAKE-up needs Add cleaning	JAB	✓		
NORTH NO. 6	Needs Spot cleaned 87-Tail, Needs Dusted	JAB	✓		
NORTH NO. 7	Needs Dusted, tail needs Add Cleaning, Add Cleaning <sup>WALKWAY 1200K</sup>	SH	✓		
LONGWALL	Needs Some Spot Cleaning + DUSTING	SH	✓		
GLORY HOLE	D-Box + Pump - Clear T.O.E.	SH	✓		
LBB NO. 1					
LBB NO. 2					
HG-22	Needs Cleaned + Dusted	JN	✓		
Tail Gate 22	Needs Cleaned + Dusted	JN			✓
	No HAZARDS FOUND				

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO at time of exam  
TRAVELWAYS, Power Centers, D-Boxes, chargers OK at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gunnore 1536-A  
 Belt Examiners and Certificate Numbers

John B. Bickford 26176  
 Belt Examiners and Certificate Numbers

Scott Halstead 37567

Johnny Neely 33472

COUNTERSIGNED BY T. Moore  
 Mine Foreman

32359  
 Certificate No.

Superintendent

Certificate No.

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-6-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow, Back of takeup to 7BK Both sides (Bobby + Ryan)	RG
Ellis 5	Shoveled V-plow. cleaned tail (Bobby + Ryan)	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on Tail, Ran dusters at Tail Drives	RG
NORTH 5	Dusted Headarea, Cleaned at flow thru JAB	RG
NORTH 6	Cleaned at tail + V. Plow	JAB
NORTH 7	cleaned under offside of tail Pump Water	SHJW
LONGWALL	cleaned out around DRIVE AREA, ckd Splices	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
HG22	Grease Discharge	

*Resuge chambers at 6, 89, 8 bek 2 sect. OK + phoresmarking at time of exam*

*Wiped off PC's 6 to 7 NT. Heads.*

SIGNED BY: John B. Buffel 26171  
 Belt Examiners and Certificate Numbers

Scott Halstead 37567  
Johnny Neely 33472

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357  
 Mine Foreman Certificate No.

Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-6-10 SHIFT: EVE 600 AM OR 800 AM OR 800 AM OR 1100 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom G. Ulman Time 10:30 AM or PM

Report received by: William Campbell 13542  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>E1115#4</u>	<u>needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>E1115#5</u>	<u>needs spot cleaned</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>needs Dusted + spot cleaned from <sup>one</sup> Head Take up needs added cleaning</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>needs Dusted Take up needs cleaned</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>needs Dusted, cleaned 89-Tail (spot cleaned)</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>needs Dusted Tail needs added cleaning <sup>working 1281m</sup> needs added cleaning</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>Longwall</u>	<u>needs spot cleaned + Dusted</u>	<u>GU</u>			
GLORY HOLE	<u>IDLE, D-Box + pump clear at Exam</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>H622 NO. 1</u>	<u>needs cleaned + Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>Trailgate 22 #1</u>	<u>needs cleaned + Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> detected  
Track/Travelways, D-Box's, Chargers, P.C.'s, Pumps + visual check of CO's all clear  
at Exam

SIGNED BY: William Campbell 13542  
Belt Examiners and Certificate Numbers

[Signature] 13542  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore  
Mine Foreman

33357  
Certificate No.

Superintendent

Certificate No.

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-6-10 SHIFT: EVE 600 AM OR 800 AM OR 800 AM OR TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
<u>E11, s#4</u>	<u>cleaned v-plow</u>	<u>BC</u>
<u>E11, s#5</u>	<u>cleaned v plow</u>	<u>BC</u>
NORTH 2		
NORTH 3		
NORTH 4	<u>cleaned low tail</u>	<u>BC</u>
NORTH 5	<u>cleaned v-plow at tail flowthrough</u>	<u>BC</u>
NORTH 6		
NORTH 7		
<u>Kongwall</u>		
GLORY HOLE		
<u>H622 NO. 1</u>		
<u>Tail gate 22#1</u>		

Outby Refuges checked at B 89, 6brks cleaned at Exam & Phones working  
20.6%O<sub>2</sub>, 0%CH<sub>4</sub>, 0%CO

SIGNED BY: William Campbell 13542  
 Belt Examiners and Certificate Numbers  
John Miller 15397  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-7-10 SHIFT: owl 1100 AM OR PM TO 300 OR PM 300 OR PM TO 600 OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellist#4	Needs Dusted	BC	✓		
Ellist#5	needs spot cleaned + needs Dusted 15-24	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	+ Dusted Needs spot cleaned Take-up needs cleaned	BC	✓		
NORTH NO. 5	needs Dusted, Take up needs cleaned	BC	✓		
NORTH NO. 6	Needs spot cleaned from BZ-tail + needs Dusted	BC	✓		
NORTH NO. 7	needs Dusted, Tail needs Add Cleaning <sup>WALKWAY to 128 needs Add Cleaning</sup>	GU	✓		
Howgwall	needs spot cleaned + Dusted	GU	✓		
GLORY HOLE	O-Box Pump OK	GU	✓		
H622 NO. 1	needs cleaned + Dusted	GU	✓		
Tailgate 22#1	needs Cleaned + Dusted	GU	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

06 con 4 cb cd 20.83.02  
PC'S Changes, O-Boxes, Track Travel Wires OK

SIGNED BY: William Campbell 15394 Johnny Neely 33472  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33357 \_\_\_\_\_  
 Mine Foreman Certificate No. Superintendent Certificate No.

46543-BJW Printing & Office Supplies  
John A. Buckford 26172

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-7-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4	shoveled v-plow	BC
Ellis #5	shoveled v-plow change rolls LC	
NORTH 2		
NORTH 3		
NORTH 4	Fixed Broken Chan, shoveled v-plow change rolls LC	6466
NORTH 5	shoveled v-plows at dail + Flow through	BC
NORTH 6		
NORTH 7	changed v-plow changed roller change rolls LC	6466
Kongwall	change rolls LC	
GLORY HOLE		
H622 NO. 1	cleaned v-plow	
Trigate #1	cleaned v-plow	

checked out by Refuges 6-8-89 OK + phones work  
 checked rooms

SIGNED BY:

Don Allen 15394  
 Belt Examiners and Certificate Numbers  
Walter Campbell 13547  
 Belt Examiners and Certificate Numbers

Hub Cilly 28075  
Johnny Neely

COUNTERSIGNED BY

T. McNamee 33357  
 Mine Foreman Certificate No.

Superintendent

Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-7-10 SHIFT Day AM OR PM TO 1200 AM OR PM TO 300 AM OR PM

ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom J. Neely Time 230 AM or PM

Report received by: John A. Bickford  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis NO. 4</u>	<u>Needs dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>Ellis NO. 5</u>	<u>Needs spot cleaned &amp; dusted 15 to 24</u> <small>Take up needs cleaned</small>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Tail &amp; take up needs add'l cleaning</u> <u>Needs dusted, needs spot cleaned 7 to 8 ft</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>Needs dusted, take up needs cleaned</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>Needs dusted, Needs spot cleaned 8 to 10 ft</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>Needs dusted, Tail needs add'l cleaning</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>Lg. Hall</u>	<u>Needs spot cleaned &amp; dusted</u>	<u>HL</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>D'Box &amp; Pump OK</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>HG<sup>22</sup> NO. 1</u>	<u>Needs cleaned &amp; dusted</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>LBB NO. 2</u>		<u>J</u>			
<u>Tailgate<sup>HG 22</sup></u>	<u>Folds, PC's &amp; choyers OK</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>HG 23</u>	<u>No Power</u>	<u>JN</u>	<input checked="" type="checkbox"/>		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

**(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:**

Otechy, O% CO & 20-8 to O<sub>2</sub> detected at time of exam

PC's, choyers, D'Boxes, Track & Travelways cleaned at time of exam

Visual check of CO's - OK

SIGNED BY: John A. Bickford 26176 John A. Bickford 32496  
Belt Examiners and Certificate Numbers

Johnny Neely 33472 W. D. Lully 2801  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33389  
Mine Foreman Certificate No.

46543—BJW Printing & Office Supplies William Campbell 133400  
Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3.7.10 SHIFT: Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<del>ELLIS</del> SOUTH 1 4	Cleaned at U' Plow	JAB
<del>ELLIS</del> NORTH 1 5	Cleaned at U' Plow	JAB
NORTH 2		
NORTH 3		
NORTH 4	Cleaned at U' Plow	JAB
NORTH 5	Cleaned at flow - throw & tail	JAB
NORTH 6	Cleaned at flow throw & tail, elevated from tail to flow - throw	JAB
NORTH 7 5 wall NORTH 7	Helped put up Guard at Glory Hole spur <sup>Pump in water</sup> <del>Crease on Drive</del> SN	JAB
GLORY HOLE	1-man Rock dusting belt	HL
LBB NO. 1		
LBB NO. 2		
HG 22#1	clean up spillage in front of Drive clean on Beltline Dust off PC's	JAB JN

Checked Refuges at 6, 8 & 89 Belts OK, Phone OK 6 & 89  
Phone not working at 8 Refuge

Wiped 3 PC's at Mother drive Area & one at 5 Ellis head JAB

SIGNED BY: John Bickford 26176  
Belt Examiners and Certificate Numbers

Neil Kelly 28095  
Johnny Neely 33472

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33357  
Mine Foreman Certificate No.

Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-7-10 SHIFT: 2ve 6:00 AM OR PM TO 8:00 AM OR PM 8:00 AM OR PM TO 11:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>E/11's #4</u>	<u>needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>E/11's #5</u>	<u>needs spot <sup>cleaned</sup> <del>cleaned</del> Takeup needs cleaned, <sup>needs added</sup> Dusting 15-24</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>tail + T.D. needs added cleaning</u> <u>needs Dusted, needs spot cleaned from IO-HEAD</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>needs Dusted, Take-up needs added cleaning</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>needs Dusted, needs cleaned from BT-tail</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>needs Dusted, tail needs added cleaning</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>Longwall #3</u>	<u>needs spot cleaned + dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	<u>IDLE, Pump + D-Box clear at Exam</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>H622 #1</u>	<u>needs cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>T27607 #1</u>	<u>needs cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>H623</u>	<u>No Power</u>	<u>BC</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> - Detected

Track/Travelways, P.C.'s, P-Box's, Pumps, + visual check of CO's  
all clear at Exam

SIGNED BY: William Campbell 13547  
Belt Examiners and Certificate Numbers

[Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33387  
Mine Foreman Certificate No.

Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-7-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM TO 800 AM OR PM TO 1100 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include BELT #154, NORTH 2-7, Longwall, GLORY HOLE, #622 #1, Tailgate #2.

Checked Outby Refuges #601K - N/O - phone worked
#896K N/O phone worked
old 2 section #801K N/O - phone not working

SIGNED BY: William Campbell 132411 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359 Mine Foreman Certificate No. Superintendent Certificate No.



# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-8-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM     

Report received by:       
Signed     

BELTS	ACTION TAKEN	INT.
ELLIS #4	cleaned v-plow + <del>tail</del> shovelled tail piece	BC
ELLIS #5	cleaned v-plow - Dusted on head	BC
NORTH 2		
NORTH 3		
NORTH 4	cleaned v-plow + tail roller change roller LC	BC
NORTH 5	Shovelled v-plow at tail + Flowthrough	BC
NORTH 6	Shovelled v-plow at tail	BC
NORTH 7	change roller LC	
GLORY HOLE		

Outby Refuge checked at 6:08 AM clean at Exam  
 8:00 AM - Refuge - phone not working

SIGNED BY: William Campbell 1354-A  
 Belt Examiners and Certificate Numbers  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. J. Moore 33357  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-8-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Neely Time 2:50 AM or PM

Report received by: Russell Dumas  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Spot cleaned, Needs dusted 15-27	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Dusted, <sup>Take-up</sup> Needs add. cleaning, Needs cleaned 5-Discharge	RG	✓		
NORTH NO. 5	Needs Dusted, Take-up needs Add. cleaning	RG	✓		
NORTH NO. 6	Needs Dusted, Needs spot cleaned 87-Tail	RG	✓		
NORTH NO. 7	tail Needs Add Cleaning, Belt needs Dusted, <sup>WALKWAY 128&amp;K</sup> Needs Add Cleaning	SH	✓		
Longwall	Needs Some Spot Cleaning & Dusted	SH	✓		
GLORY HOLE	Pump & D-Box OK	SH	✓		
HG-22	Needs cleaned & Dusted	JN	✓		
TG-22	Needs cleaned & Dusted	JN	✓		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, Apprx CO at time of exam  
Travelways, Power Centers, D-Boxes, Chargers OK at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Dumas 1536-A  
Belt Examiners and Certificate Numbers

Scott Holstead 37567

F. Name  
Belt Examiners and Certificate Numbers

Jh. Name 22076

COUNTERSIGNED BY F. Name 3335-9  
Mine Foreman

Certificate No.

Superintendent

Certificate No.

William Campbell 1854-A

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-8-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled v-plow	RG
Ellis 5	cleared on tail	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned At Tail, Ran dusters at Head & Drives	RG
NORTH 5	Cleaned At Tail, Ran duster at Head	JN RG
NORTH 6	Ran duster At Head	RG
NORTH 7	cleaned on Rib Roll at 1285K, cleaned some on tail. cleaned on Tail	SH
Longwall	cleaned on Mud at Drive, greased Discharge, did P.M. ON Storage Unit	SH
GLORY HOLE		
H622	Pick up Trash around PC's Grease Drive & Takeup Clean up Belt	JN
#Ailgate 22	" " " " DRIVE AREA Cut off 2 Flappers	JN

*Resuge chambers at 6, 8, 9, 8 Bak 2 sect. OK at time of exam + phones working*

SIGNED BY: Russell Sumner 1536A Scott Holstad 37567  
 Belt Examiners and Certificate Numbers  
Johnny Neely 33472  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY J. Moore 35359 \_\_\_\_\_  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-8-10 SHIFT: EVE 600 AM OR 800 \*AM OR 900 AM OR 1100 AM OR 1200

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>ELLS #4 1</u>	<u>needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>ELLS #5</u>	<u>needs spot cleaned, Needs Dusted 15-27</u> <u>Take up needs cleaned</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>needs Dusted, Take up needs cleaned</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>needs Dusted, Take up needs cleaned</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>needs Dusted needs spot cleaned from 81-tail</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>tail needs added cleaning, Needs Dusted</u> <u>workway needs 128</u>	<u>JS</u>			
<u>Longwell</u> <u>on table</u>	<u>needs spot cleaned + Dusted</u>	<u>JS</u>	<input type="checkbox"/>		
GLORY HOLE	<u>Idle, Pump + D-Box - clear</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>NG #22 #1</u>	<u>needs cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>??</u>					
<u>T622 #1</u>	<u>needs cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> - Detected  
Track / Travelways, P.L.'s, D-Box's, Chargers, all clear at Exam  
Visual check of CO's clear at Exam

SIGNED BY: William Campbell 1354-A  
Belt Examiners and Certificate Numbers  
John Shroyer 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.



## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-8-10 SHIFT: SVC ~~1000~~ AM OR ~~TO 800~~ AM OR ~~800~~ AM OR ~~TO 1100~~ AM OR ~~TO~~

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
<u>E11#4</u>	<u>shovelled v-plow</u>	<u>BC</u>
<u>E11#5</u>	<u>cleaned mud out from walkway, shovelled on tail</u>	<u>BC</u>
NORTH 2		
NORTH 3		
NORTH 4	<u>shovelled on v-plow</u>	<u>BC</u>
NORTH 5	<u>shovelled v-plow</u>	<u>BC</u>
NORTH 6		
NORTH 7		
<u>Longwall</u>		
GLORY HOLE		
<u>H6#22 #1</u>		
<u>T6#22 #1</u>		

checked Outby Refuge at brks 6, 9, 89 call clear at exam + phones working at 6, 89 brk  
8brk - not working

SIGNED BY: William Campbell 1254/14  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 35359  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-9-10 SHIFT: owl 100 AM OR 300 PM TO 300 OR PM TO 600 OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>E11s#4</u>	<u>Needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>E11s#5</u>	<u>Needs spot cleaned, needs Dusted from 15-24 brks</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Needs spot cleaned from 7-Head, Tail needs added cleaning</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>Needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>Needs Dusted, needs cleaned from 87-tail</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>tail needs cleaned, needs Dusted, DANGERED OFF RibRoll</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>Long walk 3</u>	<u>needs spot cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	<u>IDLE, D-Box + Pump clean at Exam</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>H6#22 #1</u>	<u>needs cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>TG#22 #1</u>	<u>needs cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>H623 #1</u>	<u>IDLE, NO Power, NO Preshift</u>	<u>BC</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 0% CO, 20.8% O2 detected  
TRACK/TEAR damage, D-Box's, P.L's, Chances, all clean at Exam  
Visual check of CO's clean at Exam

SIGNED BY: William Campbell 13840 Johnny Neely 33472  
Belt Examiners and Certificate Numbers  
John [Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Name 33259  
Mine Foreman Certificate No. Superintendent

46543-BJW Printing & Office Supplies  
Russell Yumroe 1536-A Scott Halatoni 87567  
Certificate No. Superintendent

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-9-10 SHIFT: owl 1100 AM OR ATO 300 PM OR PM 300 AM OR PM TO 600 PM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4	shoveled v plow	BC
Ellis #5	shoveled v plow	BC
NORTH 2		
NORTH 3		
NORTH 4	working on <sup>(havy)</sup> Take up, shoveled v plow change rolls LC take up	BC
NORTH 5	shoveled v plow at flow through + Tail	BC
NORTH 6		
NORTH 7	cleaned on Rib Roll at 128-129 bks Working on	BCPS
Konywell		
GLORY HOLE		
H622 #1	made cleaned & dusted	
TG #22 #1		
H623		

checked Out by Refuges at 6, 89 & 8 bks none observed at Exam  
 6, 89 bks Refuges Phones working  
 8 bks Refuge - Phone not working

SIGNED BY: William Campbell 135410  
 Both Examiners and Certificate Numbers  
[Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Name 33357  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-9-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Neely Time 2:25 AM or  PM

Report received by: Russell Sumner  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs spot cleaned, Needs Dusted 15-24	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 5-Head, Tail needs add cleaning	RG	✓		
NORTH NO. 5	Tail Needs Add. cleaning, Needs Dusted	RG	✓		
NORTH NO. 6	Needs spot cleaned 87 to Tail, Needs Dusted	RG	✓		
NORTH NO. 7	Tail Needs Add Cleaning, Rib Roll 123 Needs Add Cleaning	SH	✓		
LONGWALL	Needs Spot Cleaned & Dusted	SH	✓		
GLORY HOLE	D-Box + Pump OK	SH	✓		
H.G-22	Needs cleaned + Dusted Head To 3 Brks <sup>OUTLY</sup> TAIL	JN	✓		
Tail gate 22	Needs cleaned + Dusted HEAD TO TAIL	JN	✓		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, Oppm CO at time of exam  
Travelway, Power Centers, Chargers, D-Boxes OK at time of exam  
VISUAL check of CO monitors OK at time of exam

SIGNED BY: Russell Sumner 1536-A  
Belt Examiners and Certificate Numbers

John Neely 1536A

Scott Halstead 37567

John Neely 33472

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mauer 33387  
Mine Foreman Certificate No.

Superintendent

Certificate No.

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-9-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
E1175 4	shoveled V-plow	RG
E1115 5	shoveled V-plow	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on Tail	
NORTH 5	Dusted Head Area, cleaned At Tail	
NORTH 6		
NORTH 7	cleaned Sane on Rib Roll 128BR	SH
Longwall	cleaned on Mud at Drive Area, Greased Drive Rollers	SH
GLORY HOLE		
HG-22	Dust Head Area To Take up clean on Rib Rolls	SH
Tail Gate 22		

Refuge Chambers 5, 6, 8, 89 OK + phones working at time of exam  
 Phone not working at B Brk

SIGNED BY: Russell Dunne 1536-A Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
Johnny Dwyer 33472  
Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY: T. Moore 55859  
Mine Foreman Certificate No. Superintendent Certificate No.

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-9-10 SHIFT: EU2 AM OR PM TO 1030 AM OR PM TO 1000 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes X No      By Whom Camba II, Sckaggs Time 1100 AM or PM

Report received by: [Signature]  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
NORTH NO. 3	All Belts Idle PC's, Chargers D-Boxes, Pumps OK				
NORTH NO. 4					
NORTH NO. 5					
NORTH NO. 6					
NORTH NO. 7					
GLORY HOLE					
LBB NO. 1					
LBB NO. 2					
HC22#1					
TC22#1					
L122#1					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:    
OC 44 OC 40 20.8602  
Trucks OK

SIGNED BY: [Signature] 15399  
Belt Examiners and Certificate Numbers  
[Signature] 17542  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 93382  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-9-10 SHIFT: 5:45 <sup>None</sup> AM OR PM TO AM OR PM AM OR PM TO AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
ELLS 4	<u>Cleaned V Roll</u>	<u>SW</u>
ELLS 5	<u>Cleaned V Roll</u>	<u>SW</u>
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

SIGNED BY: [Signature] 1942-A  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-10-10 SHIFT: owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Elks 4	needs Ousted	SW	✓		
Elks 5	needs Ousted - spot cleaned	SW	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Takeup needs cleaned / Belt needs Ousted Needs Spot Cleaned S-Hd	GU	✓		
NORTH NO. 5	Takeup needs Add Clearing / Belt needs Ousted	GU	✓		
NORTH NO. 6	needs spot cleaned 87-Tail needs Ousted	WC	✓		
NORTH NO. 7	Tail needs Add Clearing Rib Roll 128 needs Add Clearing <small>Damaged off 128-129</small>	WC	✓		
L/Wall	needs spot cleaned & dusted	LB	✓		
GLORY HOLE	P-Box + Pump - O/K	Gill	✓		
H22#1	Needs cleaned & dusted Hd-BK	WC	✓		
T22#1	Needs cleaned & dusted Hd-Tail	JT	✓		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OG 64, OG CO, 20.8202  
PC's, Charges, P-boxes, Track, Trains OK

SIGNED BY: 1940-A W.D. Cully 28045  
 Belt Examiners and Certificate Numbers  
Walter Campbell 13540 38928  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
 Mine Foreman Scott Helms 37567 Superintendent  
John A. Beckford 26176 Russell Ammer 1536-A Certificate No. Johnny Avelly 33472



ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-10-10 SHIFT: Owl 1100 AM OR PM TO 300 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2.

Checked out by Re-fuges 6-8-89 OK
Changed around 2 mainline doors (GU, WC, JS)

SIGNED BY: Dan Miller 15394
Belt Examiners and Certificate Numbers
Willie Campbell 13544
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33559
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-10-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford, John Neely Time 2:40 AM or PM

Report received by: Russell Sumner  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs Dusted</u>	<u>RG</u>			
<u>Ellis 5</u>	<u>Needs spot cleaned, Needs Dusted 15-24</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Needs spot cleaned 5-Head, Needs Dusted</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>Needs Dusted, Take-up needs add. cleaning</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>Needs Dusted, Needs spot cleaned 8-7-Tail</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>tail Needs Add. Cleaning, 128 Needs Add. Cleaning, Needs Dusted</u> <small>R/B Roll 128-129 Damaged 11/11</small>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>Longwall</u>	<u>Belt needs Dusted &amp; Spot Cleaned</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>Pump &amp; D-Box OK</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-22</u>	<u>Needs clean &amp; Dusted from Head to</u> <u>Brks out by TAIL</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>Tail Gate 22</u>	<u>Needs cleaned &amp; Dusted Head to TAIL</u>	<u>JN</u>	<input checked="" type="checkbox"/>		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO at time of exam  
Travelways, Power Centers, D-Boxes, Chargers OK at time of exam  
Visual check of CO monitors OK at time of exam

*[Signature]*

SIGNED BY: Russell Sumner 15361A Scott Hatfield 37567  
 Belt Examiners and Certificate Numbers  
John A. Bickford 26176 Johnny Neely 33472  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 35359  
 Mine Foreman Certificate No.

Superintendent John [Signature] 28476  
 Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-10-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow (shoveled tail & Greased tail) Bobby	
Ellis 5	Shoveled V-plow (shoveled tail & Greased tail) Bobby	
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on Tail, RAN dusters at Tail & Drives Clean on tail 576	
NORTH 5	Dusted Head + Take-up Area	
NORTH 6	Cleaned at tail	576
NORTH 7	Greased tail roller, cleaned same on Rib Roll 126R Clean on Tail	SH
Longwall	cleaned on Mud at Drive Area, did P.M. on Head, cleaned V-Plow	SH
GLORY HOLE		
HG 22#1	STRAIGHTEN LIFELINE out from Drive To Tail	JN
TG 22#1	Reb Lifeline from Head To Takeup PREPARE DRIVE	JN

Resuge chambers 6,89,80K + phones working at time of exam  
 0% O<sup>2</sup> 0% CH<sup>4</sup> 20.80%

SIGNED BY: Russell Dunne 1536-19 Scott Halstead 37567  
Belt Examiners and Certificate Numbers

John B. Bickford 26176  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 3559  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 3-10-10 SHIFT: LVE AM OR PM TO 8:00 AM OR PM TO 11:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>1115-4</u>	<u>NEEDS DUSTED</u>	<u>GU</u>	<u>-</u>		
<u>1115-5</u>	<u>NEEDS CLEANED AND DUSTED 15-24</u>	<u>GU</u>	<u>-</u>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>NEEDS SPOT CLEAN &amp; DUSTED</u>	<u>GU</u>	<u>-</u>		
NORTH NO. 5	<u>NEED CLEAN AT TAKE UP AND DUSTED</u>	<u>GU</u>	<u>✓</u>		
NORTH NO. 6	<u>NEEDS CLEAN 87 BAR &amp; TAIL &amp; DUSTED</u>	<u>JS</u>	<u>✓</u>		
NORTH NO. 7	<u>NEEDS DUSTED R/B Roll AT 128 BRK DANGER OFF</u> <u>NEEDS CLEAN &amp; DUSTED</u>	<u>JS</u>	<u>✓</u>		
<u>Longwall</u>	<u>Belt Idle P.C.O.K.</u>				
<u>GLORY HOLE</u>	<u>D-Box &amp; Pumps OK AT TIME OF EXAM</u>	<u>JU</u>	<u>✓</u>		
<u>716 30</u>	<u>needs cleaned &amp; dusted from Hd-DRK</u>	<u>PH</u>	<u>✓</u>		
<u>Tail 601-23</u>	<u>NEEDS CLEAN AND DUSTED</u>	<u>JS</u>	<u>✓</u>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0% CH4 0% CO 20.5% O2

TRAVELWAYS & POWDER CENTERS D-BOXES OK AT TIME OF EXAM

SIGNED BY: [Signature] 32476

Belt Examiners and Certificate Numbers

[Signature] 15377  
Belt Examiners and Certificate Numbers

[Signature] 3046-A

COUNTERSIGNED BY: [Signature]

Mine Foreman

32359

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-10-10 SHIFT: EVE 6:00 AM OR PM TO 8:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No X By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<u>E1154</u>	<u>cleaned U-Roll</u>	<u>GU</u>
<u>E1155</u>	<u>cleaned V-Roll</u>	<u>GU</u>
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<u>cleaned U-Roll</u>	<u>GU</u>
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		

Checked out by Refuges 6-8-89 OK

---

---

---

---

---

---

---

---

---

---

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 3359  
Mine Foreman Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 3-11-10 SHIFT: 0W1 AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out / Campbell Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Elks #4</u>	<u>needs Dusted</u>	<u>CU</u>	<input checked="" type="checkbox"/>		
<u>Elks #5</u>	<u>Needs cleaned &amp; Dusted</u>	<u>CU</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>needs spot cleaned &amp; Dusted</u>	<u>CU</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>Needs cleaned Takeup needs cleaned</u>	<u>CU</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>Needs cleaned 57-Tail &amp; Dusted</u>	<u>CU JS</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>Needs Dusted Rib Roll at 128 Brk Dangerous &amp; off</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>L Wall</u>	<u>needs spot cleaned &amp; dusted</u>	<u>LB</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	<u>D-Box &amp; Pump OK</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>HG 22 #1</u>	<u>Needs cleaned &amp; dusted From Hd. 3 Brk.</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>Tail Gate 22 #1</u>	<u>needs cleaned &amp; dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

06 CH4 06 CO 208802

PC'S, Chargers, D-Boxes, Track, Travelways OK

SIGNED BY: [Signature] 1539A

Belt Examiners and Certificate Numbers

[Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359

Mine Foreman

Certificate No.

Superintendent

Certificate No.

John B. Buckford 26176 Russell Dunnoe 1536-A

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-11-10 SHIFT: OWL 1100 AM OR PM TO 300 AM OR PM AM OR PM TO AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Cleaned V-Row (cleaned 23 br to 24) Cleaned + Aif R Greased <sup>Bobby</sup> trail	GU
Ellis 5	Cleaned V-Row <sup>Bobby</sup> Tires on belt rubbing <sup>Bobby</sup> longer LC. (cleaned trail)	GU
NORTH 2		
NORTH 3		
NORTH 4	Cleaned V-Row fix chris down 370k-LC	GU
NORTH 5	Ran Ouster, cleaned V-Row	GU
NORTH 6		
NORTH 7	change rolls LC	
L-1111	change rolls LC	
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Re-fuges 6-8-89 OK

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

SIGNED BY: [Signature] 15794  
Belt Examiners and Certificate Numbers

\_\_\_\_\_

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 3339  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-11-10 SHIFT: 1st AM OR PM TO AM OR PM 12 AM OR PM 3 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 3:13 AM or PM

Report received by: Terry Moore  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis #4</u>	<u>Needs Dusted</u>	<u>MFP</u>	<input checked="" type="checkbox"/>		
<u>Ellis #5</u>	<u>Needs cleaned &amp; Dusted</u>	<u>MFP</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Needs spot Cleaned &amp; Dusted</u>	<u>MFP</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>Need Clean, Take up need Clean</u>	<u>J.B.</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>Need dusted, Need spot clean &amp; Tail</u>	<u>J.B.</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>Need dusted, Rip Roll, 128 Brk - Damaged off</u>	<u>J.B.</u>	<input checked="" type="checkbox"/>		
<u>W</u>	<u>Needs spot cleaned &amp; dusted</u>	<u>R</u>			
GLORY HOLE	<u>D-Box - Pump - o.k.</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>#16 22 #1</u>	<u>Need Clean &amp; dusted from Hd. 3 Brk.</u>	<u>J.B.</u>	<input checked="" type="checkbox"/>		
LBB NO. 2					
<u>#16 22 Tail Gate #1</u>	<u>Needs Cleaned &amp; dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

SIGNED BY: John Bickford 26176 Manfred Pedue 37004 John 32476  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33259  
 Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-11-10 SHIFT: \_\_\_\_\_ AM OR PM TO \_\_\_\_\_ AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_\_\_ No \_\_\_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<sup>5 Ells</sup> SOUTH 1	Cleaned at v Plow	SAB
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	Cleaned at tail & flow thru	SAB
NORTH 5		
NORTH 6	Cleaned & dusted at tail & flow thru	SAB
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

*Checked 8,6789 Refuges - o.k. Phones o.k.*

SIGNED BY: John A. Richards 26176  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 3359  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 3-11-10 SHIFT: EVE AM OR PM TO 800 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes X No      By Whom SKAGGS Time 1030 AM or PM

Report received by: Dem Miller  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELK #4	needs Dusted	GU	—		
ELK #5	needs cleaned & dusted	GU	—		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs spot cleaned & dusted	GU	—		
NORTH NO. 5	needs Dusted, Takeup needs Add cleaning	GU	—		
NORTH NO. 6	needs spot cleaned, 87-Tail Needs Dusted	GU	—		
NORTH NO. 7	needs Dusted, Rib Roll 128 Brk Dangerous off	JS	—		
L114/11	needs spot cleaned & Dusted	JS	—		
GLORY HOLE	D-Box, Pump OK	JS	—		
HC22 #1	needs cleaned & Dusted From Head - 3 Brk	JS	—		
T622 #1	needs cleaned & Dusted	JS	—		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

02 Ch4 06 00 2088 02  
PCS, Chargers, D-Boxes, Travelways OK

SIGNED BY: Dem Miller 15397  
Belt Examiners and Certificate Numbers  
JS 32976  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33307  
Mine Foreman Superintendent Certificate No.

Use Indellible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-11-70 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes NoX By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
ELLS #5	cleaned Tail	GU
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	cleaned off side Flow Thru	GU
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
H622 #1	Trained Belt at Drives	GU

Checked out by Refuges 6-8-89 OK(GU)  
Checked Intake Rooms OK(JS)

---



---



---



---



---



---



---



---



---



---

SIGNED BY: [Signature] 1539A  
 Belt Examiners and Certificate Numbers  
 \_\_\_\_\_  
 Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY: T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-12-10 SHIFT: Even AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time          AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	GV	✓		
Ellis 5	needs cleaned & dusted	GV	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned & Dusted	GV	✓		
NORTH NO. 5	Needs Dusted, Takeup needs Add. Cleaning	GV	✓		
NORTH NO. 6	Needs spot cleaned 87-Tail, needs Dusted	GV	✓		
NORTH NO. 7	needs Dusted, Rib Roll 128Bk Damaged off	JS	-		
L Wall	needs spot cleaned & dusted	LB	-		
GLORY HOLE	D-Box Pump OK	JS	-		
HC22#1	needs cleaned & Dusted	JS	-		
TC22#1	Needs cleaned & Dusted	JS	-		
TC22#2	none observed	JS	-		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

GC 4 OK CO 2018202  
PC'S, CHARGES, PROBES, TRAVELWAYS OK

SIGNED BY: Don M... 1539A  
 Belt Examiners and Certificate Numbers  
John ... 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
 Mine Foreman Certificate No. Superintendent 702 37928 Certificate No. Scott Halstead 37567  
John D. Bickford 26176 Russell Gummie 1536A

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-12-10 SHIFT: owl 7:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
ELLISY	Cleaned Tail Run Duster	GU
ELLISS	Cleaned Tail	GU
NORTH 3		
NORTH 4	RAN Dusted <i>change roller</i>	GU
NORTH 5	Cleaned Flow Pan <i>train on belt running off rubbing roller</i>	GU
NORTH 6		
NORTH 7	set new Duster at Tail	GU/JS
NORTH 8		
GLORY HOLE		

OGCH4 OGCO 20.8802  
Checked out by Refuges 6-8-89 OK

SIGNED BY: [Signature] 1539A  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers \_\_\_\_\_  
 COUNTERSIGNED BY [Signature] 33359  
 Mine Foreman Superintendent Certificate No.

*Leah Buckland 2/17/6*

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pen or Ink

DATE 3-12-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:15 AM or  PM

Report received by: Russell Dunnoe  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Eth's 5	Needs Spot cleaned + Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs dusted, needs cleaned Drives to Discharge	RG	✓		
NORTH NO. 5	Needs Dusted, take up needs Add Cleaning	SH	✓		
NORTH NO. 6	Needs Spot Cleaned 87-tail, Needs Dusted	SH	✓		
NORTH NO. 7	Needs Dusted, Rib Roll 128 Bak. DANGERED OFF	JAB	✓		
Longwall	Needs Spot Cleaned + Dusted	SH	✓		
GLORY HOLE	D-Box + Pump OK	JAB	✓		
HC 22	Needs cleaned + Dusted	JAB	✓		
Tail Gate 22 #1	Needs cleaned + Dusted	JAB	✓		
TG 22 #2	Needs Dusted	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO at time of exam  
Travelways, Power Centers, Chargers, D-Boxes OK at time of exam  
Visual checks of CO monitors OK at time of exam

SIGNED BY: Russell Dunnoe 1536-A John Bickford 26176  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33383  
Mine Foreman Certificate No.

William Campbell 1354A  
Superintendent Certificate No.

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-12-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
Ellis 4		
Ellis 5	shoveled V-plow Greased & Cleaned around tail (Bobby)	SAB RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail	SAB RG
NORTH 5	cleaned on tail & flow thru	SH-JAB
NORTH 6	cleaned on tail & flow thru	SH-JAB
NORTH 7		
Long Wall	cleaned V-Plow, Cleaned on Mud at Drive & Dusted	SH
GLORY HOLE		

Refuges at 6, 89, 8 brk 2 section OK at time of exam

*Debra Ullman 55344*

SIGNED BY: Russell Gurnoe 1536-AB Scott Holstead 37567  
Belt Examiners and Certificate Numbers  
John A. Beckford 26176  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 3359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-12-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis #4</u>	<u>Needs Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>Ellis #5</u>	<u>Needs spot cleaned &amp; Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
			<input type="checkbox"/>		
<u>NORTH NO. 4</u>	<u>Needs Dusted, Needs cleaned from Drives to Head</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>needs Dusted Takeup needs added cleaning</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>needs spot cleaned from ST-tail, needs Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>needs Dusted, Rib Roll at 1280RK - Dangled off</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>Long wall</u>	<u>needs spot cleaned &amp; Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>D-Box &amp; Pump clear cut Exam</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>T6 22 NO. 1</u>	<u>needs cleaned &amp; Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>T6 22 NO. 2</u>	<u>needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
			<input type="checkbox"/>		
<u>H672 #1</u>	<u>needs cleaned &amp; Dusted from Head-tail</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
			<input type="checkbox"/>		
			<input type="checkbox"/>		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> Detected

TRACK / Travelways, D-Boxes, Chargers, PC's, KVA's and a visual check of CO's all clear cut Exam

SIGNED BY: William Campbell 13547A  
 Belt Examiners and Certificate Numbers

Don Morrison 1539A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 35359  
 Mine Foreman Certificate No.

Superintendent

Certificate No.



## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-12-10 SHIFT: 2VE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
Ellis #4		
Ellis #5	Cleaned Gob out at tail	GU/BC
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
Long wall		
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		
H622 #1		

*Out by Refuges checked at 6, 8, 89 brks all clean at Exam + Phones working*

SIGNED BY: \_\_\_\_\_  
 Belt Examiners and Certificate Numbers

\_\_\_\_\_   
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 35359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-13-10 SHIFT: owl AM OR PM TO 400 AM OR PM TO 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Campbell, Brown Time 530 AM or PM

Report received by: [Signature] 1539A  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
E11.5#4	Needs Ousted	GU	—		
E11.5#5	Needs spot cleaned & Ousted	GU	—		
NORTH NO. 4	Needs Ousted	GU	—		
NORTH NO. 5	Needs Ousted & A key needs AHC cleaning	GU	—		
NORTH NO. 6	Needs spot cleaned from 87 Tail, needs Ousted	WC	—		
NORTH NO. 7	Needs Ousted, Rib Roll 128 OK, Ousted	WC	—		
Longwall	Needs spot cleaned	LB	—		
GLORY HOLE	D-BOX & Pump OK	WC	—		
H622 NO. 1	} Belts T & k PC's OK				
H622 NO. 2					
H622#1	Needs cleaned & Ousted	KA	—		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OG CH4 @ CO 201802

PC's changes D-Boxes Travelways OK

SIGNED BY: [Signature] 1539A Johnny Neely 33472  
 Belt Examiners and Certificate Numbers  
William Campbell 1354A Neil Cilly 28045  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mann 33389 [Signature]  
 Mine Foreman Certificate No. Superintendent Certificate No.

John A. Buckford 26176

[Signature] 38927

Scott Halstead 37567

Use Indelible Pencil or Ink

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-13-10 SHIFT: owl 114 AM OR PM TO 100 AM OR PM

ON-SHIFT EXAM.

AM OR PM TO \_\_\_\_\_ AM OR PM

PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4		
Ellis 5		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
GLORY HOLE		
NO. 1		
NO. 2		

*Checked out by Refuges 6-8-890K*

SIGNED BY: \_\_\_\_\_ 1539A  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33367  
Mine Foreman Certificate No. Superintendent Certificate No.

6-12

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-13-10 SHIFT Day AM OR PM TO 12:00 AM OR PM 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom S. Halstead, S. Neely Time 2:28 pm AM or PM PM

Report received by: John A. Bickford 26176  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis NO. 4</u>	<u>Needs dusted</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
<u>Ellis NO. 5</u>	<u>Needs spot cleaned &amp; dusted</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 4</u>	<u>Needs dusted</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>Needs dusted, Take-up needs add'l cleaning</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>Needs dusted Needs spot cleaned 87 Bel to tail</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>Rib Roll 128 - Payand off, Needs dusted</u>	<u>SN</u>	<input checked="" type="checkbox"/>		
<u>Lg. Wall</u>	<u>Needs spot cleaned</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>					
<u>Tray NO. 1</u>	<u>Tray PC's OK</u>	<u>SN</u>	<input checked="" type="checkbox"/>		
<u>Tray NO. 2</u>		<u>SN</u>	<input checked="" type="checkbox"/>		
<u>H/G 22 #1</u>	<u>Needs cleaned &amp; dusted</u>	<u>SN</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% ch4 0% CO + 20.8% O2 detected at time of exam

Visual check of CO's - OK

Truck, travelways, PC's, Pumps, chargers + D' Box's clear at time of exam. Men Unknown 1539A

SIGNED BY: John A. Bickford 26176 Scott Halstead 37567  
Belt Examiners and Certificate Numbers Johnny Neely 33472

COUNTERSIGNED BY T. Moore 33389  
Mine Foreman Certificate No.

46543—BJW Printing & Office Supplies Superintendent William Campbell 135472 Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-13-10 SHIFT Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
ELLIS 4	Shoveled tail & Greased tail / Bobby	
ELLIS 5	Cleaned at tail & V-Plow / Shoveled tail & Greased tail	3 AB
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on tail	5 AB
NORTH 5	cleaned V-Plow at tail & Flow thru	SH
NORTH 6	cleaned V-Plow at tail	SH
NORTH 7		
Long Wall	cleaned Discharge Area, cleaned Mud up at Drive	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked 6, 8 & 89 Refuges - OK. Phones - OK

SIGNED BY: John H. Bedford 26176 Scott Holbrook 37567  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33387  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-13-10 SHIFT: EVE AM OR PM TO 800 AM OR PM 1100 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Campbell Time 1100 AM or PM

Report received by: D. M. Allen  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs Dusted	GU	✓		
Ellis #5	Needs spot cleaned & dusted	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Dusted, Hd Area wet and muddy	GU	✓		
NORTH NO. 5	Needs Dusted, Takeup Needs Add. Cleaning	GU	✓		
NORTH NO. 6	Needs Spot cleaned & Tail, Needs Dusted	GU	✓		
NORTH NO. 7	Needs Dusted, RibRoll 128 OK (Danger off)	WC	✓		
Campbell	Needs spot cleaned & dusted	WC	✓		
GLORY HOLE	D-Box - Pump OK	WC	✓		
#622 #1	Needs cleaned & dusted	WC	✓		
TC #1	Belts Idle PC's Chargers OK	WC	✓		
TC #2					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 0% CO, 20.8% O2  
PC'S, Chargers, O-Boxes, Track, and Trave/ways OK

SIGNED BY: D. M. Allen 1539A  
 Belt Examiners and Certificate Numbers  
William Campbell 1354A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY J. Moore 33309  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-13-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<u>211.34</u>	<u>Cleaned V-Roll</u>	<u>GU</u>
<u>211.35</u>	<u>Cleaned V-Roll</u>	<u>GU</u>
NORTH 2		
NORTH 3		
NORTH 4	<u>Cleaned V-Roll</u>	<u>GU</u>
NORTH 5	<u>Cleaned V-Roll</u>	<u>GU</u>
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges 6-8-89 all ok

SIGNED BY: D. L. Allen 1579A  
Belt Examiners and Certificate Numbers  
William Campbell 1354-1A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 23369  
Mine Foreman Certificate No. Superintendent Certificate No.

46543—BJW Printing & Office Supplies  
John A. Bickford 26176

### PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-14-10 SHIFT: Coal AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>51154</del> NORTH NO. 1	needs Ousted	GU	/		
<del>51155</del> NORTH NO. 1	needs spot cleaned & dusted	GU	/		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs Ousted, Hd wet & muddy	GU	/		
NORTH NO. 5	needs Ousted, Take up needs Adjusting	GU	/		
NORTH NO. 6	needs spot cleaned 87 Tail, need aster	WC	/		
NORTH NO. 7	needs Ousted, Rib Roll 12 P/BK	WC	/		
<del>North No. 8</del>	Aster Clean around Head, Replace 3 guards <sup>around head</sup> <sub>and take up</sub>	DKS	✓		
GLORY HOLE	D-Box Pump OK	WC	/		
LBB NO. 1					
LBB NO. 2					
H622 #1	needs cleaned & dusted	WC	/		
H622 #1	Bolt's Idle PC's OK	GU	/		
T622 #2					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

02 C64 02 C0 20.8202

PC'S charged, D-Box Tractorways OK

Und Lilly 28075

SIGNED BY: William Campbell 1539A

Belt Examiners and Certificate Numbers

William Campbell 1354-10  
Belt Examiners and Certificate Numbers

Johnny Neely 33472

Daniel K Stealy 39218

COUNTERSIGNED BY: T. Moore  
Mine Foreman

33384  
Certificate No.

Superintendent

Certificate No.

John H. Beckford 26176



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3/4/90 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM OR PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
<sup>ELLIS</sup> SOUTH 1	Cleaned roller change roller LC	GC
<sup>ELLIS</sup> NORTH 1	Cleaned roller change roller LC	GC
NORTH 2		
NORTH 3		
NORTH 4	Cleaned roller	GC
NORTH 5	Cleaned roller change roller LC	GC
NORTH 6	shoveled V-plow	BC
NORTH 7	shoveled V-plow	BC
<sup>Lanswell</sup> NORTH 8	change roller LC	
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refrig 6-8-89 OK  
Checked Intake Rooms OK

\* Pulled R. bow 4 North / TRACK out 17-18 OK

SIGNED BY: Alan Williams 15300 Johnny Peely 33472  
Belt Examiners and Certificate Numbers  
Walter Capelle 13500  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mann 23259  
Mine Foreman Certificate No. Superintendent Certificate No.

46543—BJW Printing & Office Supplies  
John H. Bickford 26176

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3.14.10 SHIFT: Day AM OR PM TO 12<sup>00</sup> AM OR PM TO 3<sup>00</sup> AM OR PM

ON-SHIFT EXAM.      PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom J. Neely Time 2:20 AM or PM

Report received by: J. G. Beckford  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>Ellis 5</u>	<u>Needs dusted &amp; spot cleaned</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Needs cleaned at Overcast &amp; inlet, needs dusted, Head wet &amp; muddy</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>Needs dusted Take-up &amp; tail needs add'l cleaning</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>Needs dusted Needs spot cleaned 87 to tail</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>Rib Roll 128; Needs dusted</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>Log Wall</u>	<u>Guard need replaced at Mother drive</u>	<u>HL</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	<u>D. Box &amp; Pump OK</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>T.G. NO. 1</u>	}	<u>Belt Falls, PC's OK</u>	<input checked="" type="checkbox"/>		
<u>T.G. NO. 2</u>					
<u>H6 22 #1</u>	<u>Needs cleaned &amp; dusted</u>	<u>JN</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
O<sub>2</sub> CH<sub>4</sub>, O<sub>2</sub> CO & 20.8% O<sub>2</sub> detected at time of exam.  
Visual check of CO's - OK.

Track, travelways, PC's, Pumps, cheryon & D. Box clean at time of exam

SIGNED BY: J. G. Beckford 26176 J. Neely 33472  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359 Had Lilly 28045  
Mine Foreman      Certificate No.      Superintendent      Certificate No.

Willie Campbell 1354-A

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3.14.10 SHIFT: Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
ELLS 4	Cleaned at tail	JAB
ELLS 5	Cleaned at Tail & V'Plow	JAB
NORTH 2		
NORTH 3		
NORTH 4	Cleaned at V'Plow & tail	JAB
NORTH 5	Cleaned at flow-thru & tail	JN JAB
NORTH 6	Cleaned & dusted tail & cleaned at flow-thru	JAB
NORTH 7		
HWA 11	Replaced 2 guards.	HL
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
TC 22 #1	Cut Belt out of TAKE-up	JAB, JN
HG 22 #1	Dust HEAD AREA	JN
TAILGATE #1	Dust from Head To DRIVE	JN

*Checked Refuges at 6, 8 + 89 Belts - OK; Phones OK*

SIGNED BY: John B. Balford 26176  
Belt Examiners and Certificate Numbers  
Johnny Neely 33472  
Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-14-70 SHIFT: EVE 600 AM OR PM TO 900 AM OR PM 800 AM OR PM TO 1100 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Jon Skaggs Time 1010 AM or PM

Report received by: Willie Campbell  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>Ellis #4</del>	needs dusted	BC	✓		
Ellis #5	needs Dusted + spot cleaned front tail to Head	BC	✓		
Longwall	Needs spot cleaned + Dusted / Head area needs	JS	✓		
Longwall	added cleaning / wet + muddy needs cleaned from Discharge - Drives	JS	✓		
NORTH NO. 4	Needs Dusted, Head Area wet muddy	BC	✓		
NORTH NO. 5	Needs Dusted, Tail up needs cleaned out by tail needs cleaned	BC	✓		
NORTH NO. 6	needs Dusted, needs cleaned from 8T-tail	BC	✓		
NORTH NO. 7	Rib Roll 1286mk, Dangered off, needs Dusted	JS	✓		
H622 #1	needs cleaned + Dusted	JS	✓		
GLORY HOLE	D-Box + Pump clear at Exam	JS	✓		
T622 NO. 1	needs cleaned + Dusted	JS	✓		
T622 NO. 2	needs Dusted	JS	✓		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0ppm CO, 20.8% O<sub>2</sub> detected  
Track/Travelways, D-Box's, P.C's, KVA's, Pumps and a visual check  
of CO's clear at Exam

SIGNED BY: Willie Campbell 13547A  
Belt Examiners and Certificate Numbers  
John Skaggs 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33357  
Mine Foreman Certificate No.

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-14-70 SHIFT: EVE 1000 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
Ellis #4	shoveled & plow	BC
Ellis #5		
Konywall		
NORTH 4	Cleaned on Mud & Water at Discharge	BC
NORTH 5	shoveled & plow at Flothr	BC
NORTH 6		
NORTH 7		
H622 #1	SHOVED ON TAIL AND TRAIL BELT	BC
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		

Checked Out by Refuges at brks - 6, 8, 89, all clear at Exam + phones working

SIGNED BY: William Campbell - 1354

Belt Examiners and Certificate Numbers

J. L. [Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore

Mine Foreman

3559

Certificate No.

Superintendent

Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-15-10 SHIFT: owl 1100 AM OR TO 300 300 PM OR PM TO 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Jon Skaggs Time 530 AM or PM

Report received by: Willie Campbell 1354A  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs dusted	BC	✓		
Ellis #5	needs spot cleaned and Dusted from 7-tail	BC	✓		
Longwall	needs spot cleaned Dusted, Head needs added	JS	✓		
Longwall	cleaning/wet + Muddy	JS	✓		
NORTH NO. 4	Takeup needs added cleaning/Dusted, needs needs cleaned	BC	✓		
NORTH NO. 5	outby tail needs cleaned; Takeup needs cleaned belt needs Dusted	BC	✓		
NORTH NO. 6	needs cleaned from 87-tail + Dusted	BC	✓		
NORTH NO. 7	Rib Rollat 128, <sup>Dangered off</sup> , needs Dusted	JS	✓		
H6 #22 #1	needs cleaned + Dusted	JS	✓		
GLORY HOLE	P-Box + Pump clear at exam	JS	✓		
T622 NO. 1	needs cleaned + Dusted	JS	✓		
T622 NO. 2	needs Dusted	JS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0ppm CO, 20.8% O<sub>2</sub> detected  
TRACK / Travelway, D-Box's, chargers, P.L's, KVA's, Pumps on a visual  
check of CO's and clear at Exam

SIGNED BY: Willie Campbell 1354A  
 Belt Examiners and Certificate Numbers

[Signature] 32716  
 Belt Examiners and Certificate Numbers

Willie Campbell 1354A

COUNTERSIGNED BY [Signature]  
 Mine Foreman

33309  
 Certificate No.

Superintendent

Certificate No.

Russell Dammie 1536-A

Scott Hatfield 37567

[Signature] 33472

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-15-70 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM 200 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM     

Report received by:       
Signed

BELTS	ACTION TAKEN	INT.
Ellis #4	shoveled v-plow change rolls bc	BC
Ellis #5	cleaned on mud + water in walkway, shoveled v-plow	BC
<del>Longwall</del>		
NORTH 4	change rolls bc	
NORTH 5	WORKING ON DUSTING BELT, shoveled v-plow at tail + Flo-thru	BC
NORTH 6	shoveled v-plow at Flo-thru	BC
NORTH 7		
Longwall	-fixed guards on belt put 2 new ones on + Fixed 2 change rolls bc	BC/CS
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		
H622 #1		

checked Outby Refuges at 6, 8, 89 breaks all clear + phones working

SIGNED BY: William Campbell 13542

Belt Examiners and Certificate Numbers  
John [Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. [Signature]

Mine Foreman Certificate No. 3359

Superintendent

Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-15-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Neely Time 2:40 AM or  PM

Report received by: Russell Gunnoe  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs spot cleaned 27-Tail + 7-3, Needs dusted	RG	✓		
NORTH NO. 4	Needs Dusted, Needs spot cleaned 29-Tail, Needs cleaned Drives-Discharge	RG	✓		
NORTH NO. 5	Take up Needs Cleaning	SH	✓		
NORTH NO. 6	Needs Cleaned 87-tail, Needs Dusted	SH	✓		
NORTH NO. 7	Needs Dusted, Rib Roll at 128 (Danged off)	JN			
Longwall	Needs Cleaned at Drive, Wet + Muddy	SH	✓		
GLORY HOLE	D-Box + Pump	JN	✓		
TG-22 NO. 1	Needs cleaned + Dusted	JN	✓		
TG-22 NO. 2	Needs Dusted	JN	✓		
HG-22	Needs cleaned + Dusted	JN	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO at time of exam  
Travelways, Power center, D-Boxes, chargers OK at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gunnoe 1536-A Scott Haberland 37567  
Belt Examiners and Certificate Numbers  
John Neely 33472 John Neely 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33387  
Mine Foreman Certificate No. Superintendent Certificate No.

William Campbell 1354-A



**ON-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 3-15-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	Trained Bottom Belt (Shoveled trail & Greased tail) Bobby	RG
Ellis 5	shoveled V-plow (shoveled tail & Greased trail) Bobby	RG
NORTH 4	cleaned on Tail	RG
NORTH 5	cleaned tail Raw Duster clean on Tail JN	SH
NORTH 6	cleaned tail + Flow thru Raw Duster	SH
NORTH 7	clean TAIL + DUST & GREASE	JN
Longwall	cleaned on Mud at Drive	SH
GLORY HOLE		
TG-22 NO. 1	Cut Flappers off of Belt	JN
TG-22 NO. 2		
HG-22	Fill Trickle Duster & Run clean on spillage at Flow Thru	JN
	Grease Holdup Rollers & Discharge	JN

Refuge Chambers 6, 8, 9, 8 Bak 2 sect. OK + phones working at time of exam

SIGNED BY: Russell Sumner 1536-19 Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
Johnny Neely 33472  
Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY T. Mann 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-15-10 SHIFT: EUE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis #4</u>	<u>Needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>Ellis #5</u>	<u>needs cleaned from 27-tail &amp; 7-3 brks. Need Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>Longwell</u>	<u>needs cleaned &amp; Dusted, Wet &amp; muddy</u> <u>HEAD needs cleaned</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 4</u>	<u>Needs Dusted, needs cleaned at Takeup</u> <u>needs cleaned from Drives to Discharge</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>Needs Dusted, Takeup needs cleaned</u> <u>out by tail needs cleaned</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>needs Dusted, needs cleaned from 87-tail</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>needs Dusted, (Dangered off) RibRoll at 12861K</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>HG#22#1</u>	<u>needs cleaned &amp; Dusted from Head-tail</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>D-Box &amp; Pump clean at Exam</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>T622 NO. 1</u>	<u>needs cleaned &amp; Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>T622 NO. 2</u>	<u>needs Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0% CH<sub>4</sub>, 0ppm CO, 20.8% O<sub>2</sub> Detected  
Track/Travelways, D-Box, KVA's, PLC's, chargers, Pumps and visual  
check of CO monitors all were clear at Exam

SIGNED BY: William Campbell 13547A  
Belt Examiners and Certificate Numbers  
[Signature] 33476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-15-10 SHIFT: SUE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	cleaned v plow	BC
Ellis 5	cleaned on mid on walkway at tail	BC
Longwall		
NORTH 4	cleaned on Mud At Discharge	BC
NORTH 5	cleaned v plow at Flo thru + tail Ran Duster at Head	BC
NORTH 6	Ran Duster at Head cleaned v plow at Flo thru	BC
NORTH 7		
H622 #1	clean Tail NEED WORK.	JS
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		

CHECKED Out by Refuges at 6, 8, 89 brks all clear at Exam, + Phones working

SIGNED BY: William Campbell 13547A  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-16-10 SHIFT: OWL 1100 AM OR PM TO 300 OR PM 300 OR PM TO 600 OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Don Skaggs Time 5:15  AM or PM

Report received by: Walter Campbell  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>E115#4</u>	<u>needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>E115#5</u>	<u>needs cleaned from 27-tail 7-3 hrs, needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>Longwall</u>	<u>wet + muddy Hens needs cleaned, belt needs cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 4</u>	<u>needs Dusted Needs cleaned from Drive - Discharge needs #1 pump cleaned</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>needs Dusted tail access cleaned out by tail needs cleaned</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>needs Dusted, needs cleaned from 87-tail</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>needs Dusted, Air Ball at 128 hrk (Danger off)</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>H622 #1</u>	<u>needs cleaned + Dusted from Hens tail</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>D-Box + Pump Clear at Exam</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>T622 NO. 1</u>	<u>needs cleaned + Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>T622 NO. 2</u>	<u>needs Dusted</u>	<u>JS</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0 ppm CO, 20.8% O<sub>2</sub> detected  
Track/Travelways, D-Box, KVAs, P.C.'s, Chargers, Pumps and  
Visual check of CO monitors all clear at Exam

SIGNED BY: Walter Campbell 13540  
 Belt Examiners and Certificate Numbers  
[Signature] 32476  
 Belt Examiners and Certificate Numbers  
John Kelly 28045  
Johnny Neely 33472

COUNTERSIGNED BY T. Moore Mine Foreman Certificate No. 3339  
 Superintendent Certificate No. Scott Halstead 37567

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-16-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	shoveled v plow	BC
Ellis 5	shoveled v plow	BC
L16A11	change roll LC	
NORTH 4	Dusting on, shoveled v plow change roll LC	BC
NORTH 5	shoveled v plow at tail & Flo thru, Dusting on	BC
NORTH 6	shoveled v plow at Flo thru	BC
NORTH 7	change roll LC	
H622 #1		
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		

checked Out by Refuges at 6, 8, 89 brks all clear at Exam + Phores work

- \* ① Hung lifeline & Rerouted it from 128-123 brks
  - ② Hung waterline at 137 brk out of walkway
  - ③ Hung waterline at 128 brk to start cleaning on R6 Roll
- } BC/JS

SIGNED BY: William Campbell  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 35359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-16-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Neely Time 2:40 AM or PM

Report received by: Russell Gunnar  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs spot cleaned 27 to Tail + 7-3, Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	TAKE-UP needs add. cleaning Needs dusted, needs cleaned Drive to Discharge	RG	✓		
NORTH NO. 5	TAKEUP Needs Cleaned Spot Dusting Needed	SH	✓		
NORTH NO. 6	Needs Dusted, Needs Cleaned 87-tail	SH	✓		
NORTH NO. 7	Needs Dusted Rib Roll at 128 (dangerous off)	JN	✓		
Longwall	Belt needs Dusted Discharge & Drive Needs Cleaned, Wet & Muddy	SH	✓		
GLORY HOLE	D-Box + Pump OK	JN	✓		
TG22 NO. 1	Needs cleaned & Dusted	JN	✓		
TG22 NO. 2	Needs Dusted	JN	✓		
HG-22	Needs cleaned & Dusted	JN	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO at time of exam  
Travelways, Power Centers, D-Boxes, Chargers OK at time of exam  
Visual check of CO monitors OK At time of exam

SIGNED BY: Russell Gunnar 1536-A Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
Johnny Neely 33472 JL Shaw 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359 Willie Campbell 135420  
 Mine Foreman Certificate No. Superintendent Certificate No.

Delm McManis 1539A

Willie Campbell 135420

**ON-SHIFT  
EXAMINATION OF BELT CONVEYORS**

DATE 3-16-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM \_\_\_\_\_

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	cleaned & Greased tail (Bobby)	
Ellis 5	Shoveled v-plow, cleaned & Greased tail (Bobby)	
NORTH 2		
NORTH 3		
NORTH 4	cleaned + Dusted at Tail	
NORTH 5	cleaned V-Plow at Flow thru	SH
NORTH 6		
NORTH 7		
Long wall	cleaned on Mud at Drive, Greased on Discharge	SH
GLORY HOLE		
TG22 NO. 1	Dusted Discharge To Takeup	JN
TG22 NO. 2		
HG-22	Dusted DRIVE AREA - PAN TRICKLE DUSTER - Grease Discharge Repair Hole in STOPPING at DRIVE	JN JN

*Resuge chambers at 6, 8, 9, 8 bak 2 sect. OK + phones working at time of exam*

SIGNED BY: Russell Gunnar 1536-A Scott Halsted 37567  
Belt Examiners and Certificate Numbers  
Johny Neely 33472  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: F. Moore 33389  
Mine Foreman Certificate No. Superintendent Certificate No.