

North Belts

Started 1-13-10

# EXAMINATION OF BELT CONVEYORS

Finished 1-28-10

COMPANY Performance Coal  
MINE UBB  
LOCATION NAOMA Raleigh WVa  
Post Office County State

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-13-10 SHIFT: GW AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Tail needs cleaned	SC	—		
Ellis #5	Tail needs cleaned, Belt needs dusted	SC	—		
Lwall:	Needs spot cleaned & dusted	BC	—		
NORTH NO. 3					
NORTH NO. 4	Tail and TAKEup needs cleaned	SC	—		
NORTH NO. 5	none observed	SC	—		
NORTH NO. 6	needs dusted	GU	—		
NORTH NO. 7	Idle PC's clear	BC	—		
NORTH NO. 8					
GLORY HOLE	Idle D-Box - Pump OK	BC	—		
HG #1 NO. 1	none observed	BC	—		
HG #2 NO. 2	Hd to tail needs dusted	BC	—		
HG23 #1	needs spot cleaned	GU	—		
HG23 #2	needs dusted	GU	—		
HG23 #3	needs dusted	GU	—		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OG CHY OGCO 20.8802

PC, Chargers, Pumps, Trave always OK

SIGNED BY:

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-13-10 SHIFT: owl 600 AM OR PM TO 600 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Brought out Time AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	<i>change roll</i>	<i>CC</i>
NORTH 5		
NORTH 6	<i>change roll</i>	<i>CC</i>
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<i>1 South &amp; 1 North change rolls 2C VBB side</i>		

*Checked out by Refuges 6, 8, 89 all OK - phones work*

SIGNED BY: *Don Allen 1539A* *Steve Gish 37042*  
Belt Examiners and Certificate Numbers  
*Walter Campbell 1354-A*  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *T. Moore* *33759*  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-13 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:30 AM or PM

Report received by: M. Kellin  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis #4</u>	<u>Tail needs cleaned &amp; dusted</u>	<u>MK</u>	<input checked="" type="checkbox"/>		
<u>Ellis #5</u>	<u>Belt needs dusted</u>	<u>MK</u>	<input checked="" type="checkbox"/>		
<u>K/WAU</u>	<u>Needs Spot Cleaned &amp; Dusted</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
NORTH NO. 3					
NORTH NO. 4	<u>Tail needs Add Cleaning, TAKE-UP Needs Cleaned</u>	<u>MK</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>NONE OBSERVED</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>NONE OBSERVED</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>Idle - P.C. &amp; Changer</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 8					
GLORY HOLE	<u>Idle P.C. D-Box</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>HG 23 No. 1</u>	<u>Needs Spot dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>HG 23 No. 2</u>	<u>Needs dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>HG 23 #3</u>	<u>Needs dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>HG 22 #1</u>	<u>NONE OBSERVED</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG 22 #2</u>	<u>Belt needs Dusted</u>	<u>SH</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

O<sub>2</sub> Chy 20.9% O<sub>2</sub> O<sub>2</sub> Co detected AT Exam  
Power Centers, D-Boxes, Pumps OK  
VISUAL CK Co Monitors OK

SIGNED BY: M. Kellin 33017 Scott Holsted 37567  
 Belt Examiners and Certificate Numbers  
John Bickford 26176  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Mann 37357  
 Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-13 SHIFT: DAY 6 AM OR PM TO 3 AM OR PM ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1, NORTH 2 (cleaned Discharge, dusted Head, cleaned 29BR), NORTH 3, NORTH 4 (cleaned on mud AT Tail), NORTH 5, NORTH 6 (cleaned at tail), NORTH 7, NORTH 8, GLORY HOLE, LBB NO. 1, LBB NO. 2, H6 22 # 1 (cleaned tail roller), SH.

Outby Refuges & BK on 2 section, 89 BR, 6 BK OK at EXAM All Phones Working

SIGNED BY: M. Kiphan 33017 Scott H. H. 37547 Belt Examiners and Certificate Numbers John B. Buckner 26176 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-15-60 SHIFT: 2nd AM OR PM TO 8:30 AM OR PM TO 11:30 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1					
<u>#11's #4</u>	<u>Tail Meet. cleaned</u>	<u>S.C.</u>	<input checked="" type="checkbox"/>		
<u>#5</u>	<u>Needs Dusted</u>	<u>S.C.</u>	<input checked="" type="checkbox"/>		
NORTH NO. 3					
NORTH NO. 4	<u>Tail &amp; Take-up Needs cleaned</u>	<u>S.C.</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>None observed</u>	<u>S.C.</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>None observed</u>	<u>S.C.</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>IDLE P.C.'s chargers ok</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>KONGWAM</u>	<u>Needs spot cleaned &amp; dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	<u>IDLE P.C.'s chargers ok</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>HG 22 #1</u>	<u>Needs spot Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>#2</u>	<u>Needs Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>HG 23 #1</u>	<u>Needs spot Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>#2</u>	<u>Needs Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>#3</u>	<u>Needs Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

ON CHY, oppm co 20-25' of detected at time of exam  
Track, idlers, pulleys, D-rollers, kvs, chargers ok  
Visual check co monitors ok

SIGNED BY: [Signature] 39242  
 Belt Examiners and Certificate Numbers  
[Signature] 1539A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 26041  
 Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indefinite Pencil or Ink

DATE 1-12-10 SHIFT: 2nd AM OR PM TO AM OR PM AM OR PM TO AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2.

Refuge chamber at G 89, block # 2 section 4

SIGNED BY: Dan Williams 15397 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 26041 Mine Foreman Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-14-10 SHIFT: owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Brought out  
 Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1					
<del>Bill's #4</del>	Tail Neck cleaned	S-C	✓		
Bill's #5	Neck Dusted	S-C	✓		
NORTH NO. 3					
NORTH NO. 4	Tail's Take-up Neck cleaned	S-C	✓		
NORTH NO. 5	None observed	S-C	✓		
NORTH NO. 6	None observed	S-C	✓		
NORTH NO. 7	Tail PC'S OK	GU	✓		
NORTH NO. 8					
GLORY HOLE	D-Box OK	GU	✓		
H622 #1	needs Dusted	GU	✓		
H622 #2	needs Dusted	GU	✓		
Lwall	needs spot cleaned & dusted	GU	✓		
H623 1	needs spot dusted	GU	✓		
H623 2	needs Dusted	GU	✓		
H623 3	needs Dusted	GU	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

DB ch 0200 201802  
PC'S, CHARGES, PUMP TRAVELERS OK  
Visual check co monitors ok

SIGNED BY: [Signature] 15394 [Signature] 39042  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 26041 \_\_\_\_\_  
 Mine Foreman Certificate No. Superintendent Certificate No.



ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-14-10 SHIFT: Owl 600 AM OR PM TO 600 AM OR PM ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom brought out Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2.

Checked out by Refuges 6, 8, 89 OK

SIGNED BY: [Signatures] 15397 31042 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signatures] 26011 Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 1-14-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 2:30 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:35 AM OR PM

Report received by: Russell Gunnar  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Tail needs dusted	RG	✓		
Ellis 5	Needs dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs cleaned	RG	✓		
NORTH NO. 5	None observed	RG	✓		
NORTH NO. 6	None Observed	RG	✓		
NORTH NO. 7	Idle-power center + charger OK	JAB	✓		
Longwall	Needs Spot Cleaned & Dusted	SH	✓		
GLORY HOLE	Idle-D-Box + Pump	JAB	✓		
HG 22 #1	Needs Dusted	SH	✓		
HG 22 #2	Needs Dusted	SH	✓		
HG 23 #1	Needs spot Dusted	JAB	✓		
HG 23 #2	Needs Dusted	JAB	✓		
HG 23 #3	Needs Dusted	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO detected at time of exam  
Power Centers, TRACK, TRAVELWAYS, D-Boxes, chargers clear at time of exam  
Visual check of CO monitors OK

SIGNED BY: Russell Gunnar 1536-19 Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
John Bickford 26176 Don Miller 1539A  
Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY: [Signature] 26001  
Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-14-10 SHIFT: DAY 6:00 AM OR PM TO 6:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM

Report received by:       
 Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Cleaned Tail	RG
Ellis 5	Shoveled v-plow	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned Tail, Run duster at Tail, shoveled v-plow	RG
NORTH 5	Cleaned on Tail, Ran duster At Tail, shoveled v-plow	RG
NORTH 6	Cleaned on Tail, Cleaned off plow then	RG 5AB
NORTH 7		
Longwall	Cleaned Lots of Spillage offside Discharge, pumped water down at Discharge	SH
GLORY HOLE		
HG-22 #1	trained on Belt, cleaned on tail	SH
HG 22 #2		
HG 23 #1	Cleaned at tail	5AB
HG 23 #2	Cleaned at tail	5AB
HG 23 #3	Cleaned at tail	5AB

Resuge Chambers at 6, 89, 8 Brk 2 section clear at time of exam phones working  
 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO at time of exam

SIGNED BY: John Duggan 35476  
Russell Dunbar 1536-1A Belt Examiners and Certificate Numbers  
John Beckford 26176 Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY: [Signature] 26011 Mine Foreman Certificate No.  
Scott Halstead 37567 Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-14-10 SHIFT: EVE AM OR PM TO AM OR PM 830 AM OR PM TO 1130 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Brought out  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	NEEDS DUSTED	J.S.	✓		
Ellis #5	Needs Dusted	GU	—		
NORTH NO. 4	TAKE UP NEEDS CLEANED	J.S.	✓		
NORTH NO. 5	NONE OBSERVED	J.S.	✓		
NORTH NO. 6	NONE OBSERVED	J.S.	✓		
NORTH NO. 7	PC-Charger OK	GU	—		
Glenn	needs spot cleaned & dusted	GU	✓		
GLORY HOLE	D-Box Pumps OK	GU	—		
#623 NO. 1	needs Dusted	GU	—		
#623 NO. 2	needs Dusted	GU	—		
#623 1	needs spot Dusted	GU	—		
#623 2	needs Dusted	GU	—		
#623 3	needs Dusted	GU	—		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

Of Ch. 4, Of CO, 208602  
PC, chargers, D-Box TRAVELWAYS OK

SIGNED BY: Don Nelson 15399  
Belt Examiners and Certificate Numbers  
John T. [Signature] 12476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 26011  
Mine Foreman Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-14-10 SHIFT: EVE 6:00 AM OR PM TO 6:00 AM OR PM ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes NoX By Whom Time AM or PM

Report received by: Bought out Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2.

Checked out by Refuges 6-8-89 OK

SIGNED BY: [Signature] Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] Mine Foreman Certificate No. 26001 Superintendent Certificate No.

Use Indelible Pen or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 7-15-70 SHIFT mid. AM OR PM TO AM OR PM 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Brought on  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Ellis #4 NEEDS Ousted	JS	✓		
Ellis #5	Ellis #5 needs Ousted	GU	✓		
L...	needs spot cleaned & l. steel	GU	✓		
NORTH NO. 3					
NORTH NO. 4	TAKE UP NEEDS CLEANED	JS	✓		
NORTH NO. 5	WORK OBSERVED AT TIME OF EXAM.	JS	—		
NORTH NO. 6	WORK OBSERVED AT TIME OF EXAM.	GU	✓		
NORTH NO. 7	PC Charger OK	GU	—		
NORTH NO. 8					
GLORY HOLE	D-Box Chargers	GU	—		
H602 NO. 1	needs Ousted	GU	—		
H602 NO. 2	needs Ousted	GU	—		
H623 #1	need spot Ousted Tail needs cleaned	GU	—		
H623 #2	needs Ousted Tail needs cleaned	GU	—		
H623 #3	needs Ousted	GU	—		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

JOHN DE CO 20.8202  
PC, Chargers, D-Box, Troublers OK

SIGNED BY: [Signature] 32476.  
Belt Examiners and Certificate Numbers  
[Signature] 15347  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 26041  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-15-10 SHIFT: Owl 600 AM OR PM TO 1000 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom CSG/lt AJ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6	<u>clean on take up change rolls</u>	<u>6</u>
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

checked at by Refuges 6-8-89

SIGNED BY: [Signature] 15292  
Belt Examiners and Certificate Numbers  
[Signature] 20476  
Belt Examiners and Certificate Numbers  
COUNTERSIGNED BY: [Signature] 26041  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 1-15-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 2:30 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:35 AM or PM

Report received by: Russell Sumner  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs cleaned + Dusted	RG	✓		
NORTH NO. 5	None Observed	RG	✓		
NORTH NO. 6	None Observed	RG	✓		
NORTH NO. 7	Idle - power center + charger OK	JAB	✓		
Long Wall	Needs Spot Cleaned & Dusted	SH	✓		
GLORY HOLE	Idle - D-Box + Pump OK	JAB	✓		
HG-22 #1	Needs Dusted	SH	✓		
HG-22 #2	Needs Dusted	SH	✓		
HG-23 #1	Needs spot Dusted	JAB	✓		
HG-23 #2	Needs Dusted	JAB	✓		
HG-23 #3	Needs Dusted	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO detected at time of exam.  
TRACK, TRAVELWAYS, power Centers, chargers, D-Boxes clear at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: John Bickford 32476  
Russell Sumner 1536-19  
 Belt Examiners and Certificate Numbers  
John Bickford 26176  
 Belt Examiners and Certificate Numbers

Scott Halehead 37567  
Blen Williams 15397

COUNTERSIGNED BY T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.



**ON-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 1-15-10 SHIFT: DAY 6:00 AM OR PM TO 6:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	cleaned at overcast (Bobby + Corey)	RG
Ellis 5	cleaned & dusted Head AREA (Bobby + Corey)	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, RAN duster at Tail & Drive	RG
NORTH 5	cleaned on Tail & dusted Tail, shoveled v-plow	RG
NORTH 6	shoveled v-plow	JAB RG
NORTH 7		
Langwall	cleaned plow thru 29 BK, cleaned Behind Drive Rollers, dusted Head AREA, Spot cleaned 19-20 BK, cleaned Box CK 10BK	SH
GLORY HOLE		
HG 22 #1	cleaned Spillage at tail, trained on Belt	SH
HG 22 #2	trained on Belt, put V-Plow Back in Place, picked up trash along Belt	SH
HG-23 #1	Cleaned at tail	JAB
HG-23 #2	Cleaned at tail	JAB
HG-23 #3		

Resuge chambers at 6, 8, 9, 8 BK 2nd BK + phones working at time of exam  
 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0 ppm CO detected at time of exam

SIGNED BY: Russell Dunne 1536-A Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
John Bickford 26176 Don Miller 1537A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

DATE: 1/9/10 SHIFT: 2<sup>nd</sup> AM OR PM TO 830 AM OR PM TO 1130 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Budger Qu  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
	K11 is 4 NONE OBSERVED AT TIME OF EXPT	JS	✓		
	K11 is 5 NONE OBSERVED	JS GU	✓		
	needs spot cleaned & dusted	GU	✓		
NORTH NO. 3					
NORTH NO. 4	NONE OBSERVED	JS	✓		
NORTH NO. 5	NONE OBSERVED	JS	✓		
NORTH NO. 6	NONE OBSERVED AT TIME OF EXAM	JS GU	✓		
NORTH NO. 7	PC, Charger OK	JS GU	✓		
NORTH NO. 8					
GLORY HOLE	A-Box Pumps OK	GU	✓		
H622 NO. 1	needs dusted	GU	✓		
H622 NO. 2	needs dusted	GU	✓		
H623 #1	needs spot dusted	GU	✓		
H623 #2	needs dusted	GU	✓		
H623 #3	needs dusted	GU	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

Ob Ch4, Ob CO, 2018602  
Track, Travelways, PC, Pumps, Chargers OK

SIGNED BY: [Signature] 32476  
 Belt Examiners and Certificate Numbers  
[Signature] 15307  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 23359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 11-10 SHIFT: 8:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom straight out Time \_\_\_\_\_ AM or PM \_\_\_\_\_

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

checked 6, 8, 89 Refuges OK

SIGNED BY: [Signature] 15390A  
 Belt Examiners and Certificate Numbers  
 \_\_\_\_\_  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 39355  
 Mine Foreman Certificate No. Superintendent Certificate No.

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE: 1-16-10 SHIFT: OW1 AM OR PM TO: 300 AM OR PM TO: 600 AM OR PM TO: 600 AM OR PM TO: 600  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside: Yes  No  By Whom: \_\_\_\_\_ Time: \_\_\_\_\_ AM or PM

Report received by: Brought out  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
#1 E 115	NONE OBSERVED AT TIME OF EXAM	JS	✓		
E 115 #5	NONE OBSERVED AT TIME OF EXAM	JS	✓		
L10411	needs spot cleaned & dusted	GU	✓		
NORTH NO. 3					
NORTH NO. 4	NONE OBSERVED AT TIME OF EXAM	JS	✓		
NORTH NO. 5	none observed	GU	✓		
NORTH NO. 6	none observed	GU	✓		
NORTH NO. 7	PC's, charger OK	GU	✓		
NORTH NO. 8					
GLORY HOLE	D-Box - Pumps OK	GU	✓		
H622 NO. 1	needs dusted	GU	✓		
H622 NO. 2	needs spot dusted	GU	✓		
H623 #1	needs spot dusted, Tail needs Add cleaned	GU	✓		
H623 #2	needs dusted, Tail needs Add cleaned	GU	✓		
H623 #3	needs dusted	GU	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
OB CHY OB CO 201802  
PC, Chargers, Travelways, Obotes OK

SIGNED BY: [Signature] 1539A  
 Belt Examiners and Certificate Numbers:  
[Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-14-10 SHIFT: owl 600 AM OR PM TO 600 (AM OR PM) AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM \_\_\_\_\_

Report received by: Brought out  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	<i>change rolls cleaned on take-up</i>	<i>LC</i>
NORTH 5	<i>cleaned up low change rolls</i>	<i>GU</i>
NORTH 6	<i>cleaned up low</i>	<i>GU</i>
NORTH 7		
NORTH 8		
GLORY HOLE		
<del>HG</del> NO. 1	<i>cleaned tail</i>	<i>GU</i>
<del>HG</del> NO. 2		
HG 23#1	<i>cleaned tail</i>	<i>GU</i>
HG 23#2	<i>cleaned tail</i>	<i>GU</i>

*Checked outby Refuges 6-8-89 ok*

SIGNED BY: [Signature] 1559A  
Belt Examiners and Certificate Numbers  
[Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-16 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:35 AM or PM

Report received by: M Kilburn  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>ELLIS #4</del>	<del>Needs Dusted</del>	<del>MK</del>	<del>✓</del>		
<del>ELLIS #5</del>	<del>Tail needs Add Cleaning - Needs Dusted</del>	<del>MK</del>	<del>✓</del>		
NORTH NO. 3					
NORTH NO. 4	None observed	JAB	✓		
NORTH NO. 5	None observed	JAB	✓		
NORTH NO. 6	None observed	JAB	✓		
NORTH NO. 7	Idle - P.C., chargers, D-Box	SH	✓		
NORTH NO. 8					
GLORY HOLE	Idle D-Box, pumps	SH	✓		
HG <sup>23</sup> NO. 1	Takeup needs Some cleaning, tail needs add Clean	SH	✓		
HG <sup>23</sup> NO. 2	Needs Some Spot Cleaning, tail needs Add Clean	SH	✓		
L/WALL	Needs Spot Cleaned & dusted	JAB	✓		
HG-22 1	Need spot Clean? Dusted	DJ	-		
HG-22 2	Needs Dusted	DJ	-		
HG-23 #3	Belt needs Spot cleaned and Dusted	SH	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
O% Chx 20.9% O<sub>2</sub> 0% Co detected AT Exam  
Power Boxes D-Boxes, Pumps OK AT Exam  
Visual CK Comonitors OK Chargers OK  
GBRK Refuge OK  
89 BK and 8BK on 2 Section Refuges - Clear  
All Phones Working

SIGNED BY: M Kilburn 33017 Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
John A. Bickford 26176 [Signature] 30528  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 37359 Superintendent Certificate No.  
 Mine Foreman

Use Indelible Pencil or Ink

ON-SHIFT  
EXAMINATION OF BELT CONVEYORS

DATE 1-16 SHIFT: DAY 6 AM OR PM TO 3 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	Cleaned mud + water AT TAKE-UP + JACK	MK
NORTH 5	Cleaned at flow thru	JAB
NORTH 6	Cleaned at tail + flow thru	JAB
NORTH 7		
NORTH 8		
GLORY HOLE		
HG <sup>23</sup> NO. 1	cleaned on V-Plow + tail	SH
HG <sup>23</sup> NO. 2	cleaned on tail Roller	SH
L-WALL	cleaned flow thru, cleaned on inby Side of Drive	SH
HG 23 # 3	cleaned V-Plow	SH

SIGNED BY: M. Kilibian 33017 Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
John A. Buckford 26176  
Belt Examiners and Certificate Numbers  
COUNTERSIGNED BY T. Moore 33309  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 1-16-10 SHIFT: EVE AM OR PM TO 830 AM OR PM TO 1130 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Brought out  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN	
<u>Ellis #4</u>	Preshifted PCT, Pumps, Chargers, D-Boxes all clear at time of exam	<u>GU</u>	<u>—</u>			
<u>Ellis #5</u>		<u>GU</u>	<u>—</u>			
<u>Uwall</u>						
NORTH NO. 3						
NORTH NO. 4						
NORTH NO. 5			<u>GU</u>	<u>—</u>		
NORTH NO. 6			<u>GU</u>	<u>—</u>		
NORTH NO. 7			<u>T</u>			
NORTH NO. 8						
GLORY HOLE						
<u>HC22</u> NO. 1			<u>BC</u>	<u>—</u>		
<u>HC21</u> NO. 2			<u>BC</u>	<u>—</u>		
<u>HC23 #1</u>			<u>GU</u>	<u>—</u>		
<u>HC23 #2</u>			<u>GU</u>	<u>—</u>		
<u>HC23 #3</u>			<u>GU</u>	<u>—</u>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

02664, 0260, 208202  
Track, Travelways OK

SIGNED BY: [Signature] 1539A [Signature] 32476  
 Belt Examiners and Certificate Numbers  
[Signature]  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359 [Signature]  
 Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-16-10 SHIFT: EVE 600 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Brought out  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<u>Cleaned on Tail and Fbw then</u>	<u>60</u>
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

checked out by Refuges 6, 8, 89 all ok

SIGNED BY: [Signature] 15794  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33509  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-18-10 SHIFT: owl AM OR PM TO 400 AM OR PM TO 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time 545 AM or PM

Report received by: Kyle, Stanley, Campbell  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
L/WALL	needs spot cleaned & dusted	ICS	✓		
Ellis 4	water at 95 BK on belt belt needs Oiled	GU	✓		
Ellis 5	needs Oiled	GU	✓		
NORTH NO. 3					
NORTH NO. 4	none Observed	GU	✓		
NORTH NO. 5	none Observed	GU	✓		
NORTH NO. 6	none Observed	GU	✓		
NORTH NO. 7	PC's Pump OK	WC	✓		
NORTH NO. 8					
GLORY HOLE	O-Box Pump OK	WC	✓		
HQ NO. 1	needs spot cleaned in TAKEUP	KA	✓		
HQ NO. 2	needs spot cleaned	KA	✓		
HG23 1	} Belts Idle				
HG23 2		GU	✓		
HG23 3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OC 64, 2082 02  
PC's, Chargers, Pumps, Travelways OK

SIGNED BY: Don Williams 1537A W. J. Campbell 1354A  
 Belt Examiners and Certificate Numbers  
[Signature] 32476 Donell K. [Signature] 39218  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

46543—BJW Printing & Office Supplies  
John A. Becklund 26174 Russell Dinnel 1536-A 1.18.10 to date 038

Use Indelible Pencil or Ink

### ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-17-40 SHIFT: owl 600 AM OR PM TO 600 ~~AM~~ OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No X By Whom Brought out Time \_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1	<u>change roll</u>	<u>LC</u>
NORTH 1 <u>Fill 1.55</u>	<u>change rolls</u>	<u>LC</u>
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6	<u>cleaned on take up</u>	<u>LC</u>
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked at by Refuges 6, 8, 89 all OK

SIGNED BY: Don Miller 1539A  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33355  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-17-10 SHIFT: Day AM OR PM TO 1200 AM OR PM TO 300 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM

Report received by: Brought Out  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs additional cleaning	RG	✓		
NORTH NO. 5	None Observed	RG	✓		
NORTH NO. 6	None Observed	RG	✓		
NORTH NO. 7	PC's, D'Boxes + choppers - OK	JAB	✓		
Longwall	Needs spot cleaned + Dusted	RG	✓		
GLORY HOLE	Pump + D'Box - OK	JAB	✓		
LBB NO. 1					
LBB NO. 2					
HG-22 1	Needs spot cleaned in Take-up	BB	✓		
HG-22 2	Needs spot cleaned <sup>#2 Head Area</sup> + needs dusted	BB	✓		
HG-23 1	} Idle PC & choppers OK	JAB			
HG-23 2					
HG-23 3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

O2 ch4 O2 20.8 & 20.8 % O2 detected at time of exam  
CO's OK  
Refuges at 6, 8 & 89 Bels - OK Phones - OK  
Power Center, Pumps, D'Boxes + choppers, Trunk & travelways  
clear at time of exam

SIGNED BY: John A. Bickford 26176 Brush Boy 1122-A  
 Belt Examiners and Certificate Numbers  
Russell Dunne 1536-A JL [Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. [Signature] 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1.17.10 SHIFT: Day 6:00 AM OR PM TO 6:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include Ellis 4, Ellis 5, NORTH 2-7, Longwall, GLORY HOLE, LBB NO. 1, LBB NO. 2.

SIGNED BY: John A. Bullard 26176, Russell D. ... 1536-A

COUNTERSIGNED BY: T. Moore 33359, Superintendent, Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-17-2018 SHIFT: LVL 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Billy Campbell - Skye Time 11/11 AM or PM

Report received by: Shirley 1941A  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>L11.5-4</u>	<u>Needs dusted Tail Bearing Hauler SHUT DOWN</u>	<u>JVS</u>	<input checked="" type="checkbox"/>		
<u>L11.5-5</u>	<u>Needs dusted</u>	<u>JVS</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Takeup needs additional cleaning</u>	<u>JVS</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>none observed</u>	<u>JVS</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>none observed</u>				
NORTH NO. 7	<u>PC's DBox + charger OK</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>Longwall</u>	<u>Needs spot dusted and cleaned</u>				
GLORY HOLE	<u>pumps + DBox OK</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
LBB NO. 1					
LBB NO. 2					
<u>H6-22 1</u>	<u>Needs spot cleaned in Takeup</u>	<u>RH</u>	<input checked="" type="checkbox"/>		
<u>H6-22 2</u>	<u>Needs spot cleaned #2 Head needs cleaned</u>	<u>RH</u>	<input checked="" type="checkbox"/>		
<u>H6-23 1</u>	}	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>H6-23 2</u>		<u>BC</u>	<input checked="" type="checkbox"/>		
<u>H6-23 3</u>		<u>BC</u>	<input checked="" type="checkbox"/>		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

O2 CH4 %CO 20.8 02 detected at time of exam

Reduces at 6, 8 & 89 BCC OK phones OK

Power center, pumps D-Box + charger track and travel way OK at time of exam

SIGNED BY: Shirley 1941A

Belt Examiners and Certificate Numbers

[Signature] 2476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

Richie Hutter 37569

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-15-10 SHIFT: AWL 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Joan Strass and Billy Campbell Time 11:11 AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Refuge at #6, 8, 89 brk all clear at time of Exam  
Phones work

SIGNED BY: Walter Campbell 1354-17  
Belt Examiners and Certificate Numbers  
[Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33859  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 1-18-10 SHIFT: Day Owl 2:00 AM OR PM TO 6:00 AM OR PM 3:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought Belt Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>E1115 #4</u> NO.	<u>needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>E1115 #5</u> NO.	<u>needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>take up needs added cleaning</u>	<u>BC</u>			
NORTH NO. 5	<u>none observed</u>	<u>BC</u>			
NORTH NO. 6	<u>none observed</u>	<u>BC</u>			
NORTH NO. 7	<u>D-Box - <del>exam</del> Powercenter - clear at Exam</u>	<u>BC</u>			
<u>Longwell</u>	<u>needs Dusting &amp; spot cleaning</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
GLORY HOLE					
LBB NO. 1					
LBB NO. 2					
<u>H6 22 #1</u>	<u>NEEDS spot cleaned intake up</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>#2</u>	<u>Head needs cleaned</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>H6 23 #1</u>					
<u>H6 23 #2</u>					
<u>H6 23 #3</u>					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> detected  
Refuge's at BKT # 6, 8, 89, all clear phones work  
Powercenters, CO's, D-Box's, KVAs chargers, Tracel/Traveling  
all clear at Exam

SIGNED BY: W. D. Copple 1354-A  
 Belt Examiners and Certificate Numbers  
[Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M. [Signature] 33389  
 Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-18-10 SHIFT: owl AM OR PM TO AM OR PM 6:00 AM OR TO 6:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1 <u>1/2, 1/4</u>	<u>change rolls</u>	<u>LC</u>
NORTH 1 <u>1/2, 1/5</u>	<u>cleaned on Ellis 5 take up</u>	<u>LC</u>
NORTH 2		
NORTH 3		
NORTH 4	<u>cleaning on take up</u>	<u>LC</u>
NORTH 5		
NORTH 6		
NORTH 7		
<u>Longwell</u> NORTH 8	<u>Dusting on change rolls</u>	<u>LC</u>
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

SIGNED BY: W. Campbell 13842  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 3339  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-18 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs Dusted	MK	✓		
Ellis #5	Needs Dusted	MK	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	TAKE-UP Area Needs dusted	MK	✓		
NORTH NO. 5	None Observed	RG	✓		
NORTH NO. 6	None Observed	RG	✓		
NORTH NO. 7	Idle - P.C., Charger	SH	✓		
Longwall	Needs spot cleaned	RG	✓		
GLORY HOLE	Idle - D-Box Charger	SH	✓		
HG <sup>23</sup> NO. 1	Takeup Needs Cleaned, tail Needs Add Clean	SH	✓		
HG <sup>23</sup> NO. 2	Belt Needs Some Spot Cleaning, tail Needs Cleaned	SH	✓		
HG <sup>23</sup> NO. 3	Belt Needs Spot Cleaned	SH	✓		
HG22 #1	takeup Needs Spot Cleaned	SH	✓		
HG22 #2	Head Needs Add Clean	SH	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

O<sub>2</sub> Chy 20.9% O<sub>2</sub> D% Co detected AT Exam  
All Power Boxes, Pumps, D-Boxes, Chargers OK AT Exam  
Visual CK Co Monitors OK  
6 BRK Refuge OK Phone Working

SIGNED BY: M. Kibitz 33017 Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
Russell Burnoe 1536-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M. Mene 33389 Superintendent Certificate No.  
 Mine Foreman Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-18 SHIFT: DAY 6 <sup>AM OR PM</sup> TO 3 <sup>AM OR PM</sup>  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1	cleaned & Greased on Head & tail (Bobby & Corey)	
NORTH 1	cleaned & Greased on Head & Tail (Bobby & Corey)	
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail cleaned from take up to 5BK (Bobby & Corey)	RG
NORTH 5	shoveled v-plow	RG
NORTH 6	shoveled v-plow	RG
NORTH 7	Cleaned on mud AT TAKE-UP	mk
Longwall	cleaned Spillage at Discharge, cleaned Back of Drive, Greased Head	SH
GLORY HOLE		
HG <sup>23</sup> NO. 1	cleaned Spillage at tail	SH
HG <sup>23</sup> NO. 2	cleaned Spillage at tail Roller	SH
HG 23 # 3	cleaned V-Plow	SH
HG 22 # 1	cleaned on tail	SH

Resuge chamber 89, 8BK OK phone working at time of exam  
0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 79.2% CO<sub>2</sub> at time of exam

SIGNED BY: M. Lichty 33017  
Belt Examiners and Certificate Numbers  
Russell Dumas 1536-A  
Belt Examiners and Certificate Numbers

Scott Halstead 37567  
JL 38476

COUNTERSIGNED BY: T. Mann 33359  
Mine Foreman Certificate No.

Superintendent Certificate No.

W. Kasper 1334 A

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-18-10 SHIFT 2ND 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Jim Walker Time 11:15 AM or PM

Report received by: Kyle Anderson  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>ELLIS</del> SOUTH NO. 1	needs Dusted	BC	<input checked="" type="checkbox"/>		
<del>ELLIS</del> NORTH NO. 1	needs Dusted	BC	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	HEAD needs Dusted	BC	<input checked="" type="checkbox"/>		
NORTH NO. 5	none observed	BC	<input checked="" type="checkbox"/>		
NORTH NO. 6	none observed	BC	<input checked="" type="checkbox"/>		
NORTH NO. 7	IDLE PC clear	BC	<input checked="" type="checkbox"/>		
<del>LOWE WALL</del> NORTH NO. 8	Belts 24-27 BELT Rubbing / Belts 7-Start / R	<u>JS</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	IDLE D-Box -chargers clear	JS	<input checked="" type="checkbox"/>		
LBB NO. 1					
LBB NO. 2					
HG23 1	TAKE up needs cleaned & tail needs added cleaning	JS	<input checked="" type="checkbox"/>		
2	needs Spot cleaned	JS	<input checked="" type="checkbox"/>		
3	needs spot cleaned	JS	<input checked="" type="checkbox"/>		
HG 1	TAKE up needs spot dusted & cleaned	BC	<input checked="" type="checkbox"/>		
2	Head needs added cleaning	BC	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: 0% CH4 0% CO 20.89% O2

Detected, All Powercenters, D-Box's, KVA's, chargers all clear  
at Exam CO monitors all clear at Exam  
Refuges at 60mk, 80mk, 89mk, all clear and phones work

SIGNED BY: Walt Campbell 13542  
Belt Examiners and Certificate Numbers  
[Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

M. Kline 33017

Scott Hatfield 37567

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2/18/18 SHIFT: 2nd 600 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<u>CHS 4</u>	<u>n</u>	
<u>SOUTH 1</u>		
<u>CHS 5</u>		
<u>NORTH 1</u>		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<u>HG 23 1</u>		
<u>2</u>		
<u>3</u>		
<u>HG 22 1</u>		
<u>2</u>		
<u>Longwell</u>		

SIGNED BY:

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-19-00 SHIFT: owl AM OR PM TO 300 AM OR PM TO 6:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time 5:45 AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>S11's</u> SOUTH NO. 4	<u>tail needs added cleaning Belt needs dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>S11's</u> NORTH NO. 5	<u>Belt needs dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Head needs dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>None observed</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>floor through needs added cleaning</u> <u>tail needs added cleaning</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7					
<u>Long wall</u> NORTH NO. 8					
GLORY HOLE					
LBB NO. 1					
LBB NO. 2					
<u>H623</u> 1	<u>Head needs added cleaning</u>	<u>BC</u>			
2	<u>TAIL NEEDS CLEAN &amp; DUSTED</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
3	<u>NOISE OBSERVED</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>H622</u> 1	<u>Belt needs added cleaning &amp; Dushing</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
2	<u>Head needs added cleaning &amp; Belt needs Dusted</u>	<u>BC</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

20.84% O<sub>2</sub>, CO 0%, CH<sub>4</sub> 0% Detected

P.C., D-Bar's, chargers, KVA, Pumps, CO's all clear at Exam

Refuges #6, 8, 89, bits all clear at time of Exam

SIGNED BY: [Signature] 1354-18 [Signature] 32476  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature]  
 Mine Foreman

33389  
 Certificate No.

Superintendent

Certificate No.

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 7-19-10 SHIFT: 11:00 AM OR PM TO 6:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Blomquist Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
<del>ELLIS 4</del>		
<del>SOUTH 1</del>		
<del>ELLIS 5</del>		
<del>NORTH 1</del>	<u>change rolls</u>	<u>LC</u>
NORTH 2		
NORTH 3		
NORTH 4	<u>Shoveled head</u>	<u>BC</u>
NORTH 5	<u>Shoveled V-plow change impete flow thru</u>	<u>LC</u>
NORTH 6	<u>Shoveled Tail &amp; Floughrough</u>	<u>BC</u>
NORTH 7		
<del>Long wall</del>		
<del>NORTH 8</del>		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<u>H623 1</u>	<u>Rain cluster at head</u>	
<u>2</u>		
<u>3</u>		
<u>H622 1</u>	<u>Shoveled V-plow</u>	<u>BC</u>
<u>2</u>		

SIGNED BY: \_\_\_\_\_  
 Belt Examiners and Certificate Numbers \_\_\_\_\_  
 Belt Examiners and Certificate Numbers \_\_\_\_\_  
 COUNTERSIGNED BY T. M. ... 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-19-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Brought out  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis-5	Needs Dusted, DRIVE AREA Needs cleaned	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up + Discharge need add. cleaning + Dusted	RG	✓		
NORTH NO. 5	None observed	MK	✓		
NORTH NO. 6	Flow Thru needs Add Cleaning	mk	✓		
NORTH NO. 7					
Long wall	Needs Add Cleaning + dusting	MK	✓		
GLORY HOLE	Idle - D-Box - Charged	SH	✓		
HG-22 #1	tail needs Add Cleaning, Belt needs some Spot Cleaning	SH	✓		
HG-22 #2	Head to tail needs Dusted	SH	✓		
HG-23 #1	Head needs Add Dusting	SH	✓		
HG-23 #2	tail needs Add Cleaning, Belt needs Spot Cleaned	SH	✓		
HG-23 #3	Needs some Spot Cleaning				

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0 ppm CO detected at time of exam  
Power centers, chargers, D-Boxes, Track, Travelways clear at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: D. Len Wilton 15397A  
 Belt Examiners and Certificate Numbers  
Russell Dunne 1536-A M. Vichy 33017  
Scott Halstead 37567  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: To Name 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.



## ON-SHIFT EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-19-10 SHIFT: Day 6:00 AM OR PM TO \_\_\_\_\_ AM OR PM \_\_\_\_\_ AM OR PM TO \_\_\_\_\_ AM OR PM \_\_\_\_\_  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	shoveled v-plow	RG
Ellis 5	cleaned on Drive AREA, shoveled v-plow	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, Ran Dusters at Tail + Drive, shoveled v-plow	RG
NORTH 5	cleaned on Tail, Ran Duster at Tail	RG
NORTH 6	Ran duster at Head	RG
NORTH 7	cleaned on mud + water at head	MIC
Longwall	cleaned on offside of floathen, trained Bottom Belt 22-270R, Bent Rock offside 180R	SH
GLORY HOLE		
HG 22 #1	cleaned on tail	SH
HG 23 #1	cleaned V-Plow	SH
HG 23 #2	Men Working on it	SH

*Refuge chambers at 6, 89, clear at time of exam, phones working  
 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, Oppm CO detected at time of exam.*

*Oliver Wilson 1537A*

SIGNED BY: *M. Kilduff 33017* *Scott Halstead 37567*  
 Belt Examiners and Certificate Numbers  
*Russell Dunmore 1536-A* *John Stagg 32476*  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *T. Moore 33389* \_\_\_\_\_  
 Mine Foreman Certificate No. Superintendent Certificate No.

*1. Scott Halstead 1394-1A*

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-19-10 SHIFT EVE AM OR PM TO 830 AM OR PM TO 1130 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Cambell, SKAGGS Time            AM or PM

Report received by: Don Williams  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs Dusted	GU	✓		
Ellis #5	needs Dusted Hd & drive needs Add cleaning	GU	✓		
Llwall	Flawthrow needs Add cleaning & dusting	WC	✓		
NORTH NO. 4	shut down At 11:15 AM Takeup Needs Add cleaning	GU	✓		
NORTH NO. 5	needs Dusted Hd-STRK	GU	✓		
NORTH NO. 6	None Observed	WC	✓		
NORTH NO. 7	PC'S charger OK	JS	✓		
NORTH NO. 8					
GLORY HOLE	Power Box - amps OK	JS	✓		
<del>NO</del> NO. 1	Add Dusting Tail needs Add cleaning	WC	✓		
<del>NO</del> NO. 2	Add Tail Add cleaning needs cleaned	WC	✓		
HEAD 1	Hd needs Add cleaning	JS	✓		
HEAD 2	Tail needs Add cleaning	JS	✓		
HEAD 3	Needs some spot cleaning	JS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% chg, BCO, 20,8302  
PC, Chargers, D-Boxes, Travel ways OK

SIGNED BY: Don Williams 15374  
 Belt Examiners and Certificate Numbers  
William Cambell 135414  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-19-10 SHIFT: EVE 600 AM OR PM TO 830 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM     

Report received by:       
Signed     

BELTS	ACTION TAKEN	INT.
Ellis #4	cleaned on Tail	GU
Ellis #5	cleaned on Tail	GU
NORTH 4	Cleaned At Tail	GU
NORTH 5	cleaned Flowthrough & dusted	GU
NORTH 6	Cleaned Flowthrough	BC
NORTH 7		
NORTH 8		
GLORY HOLE		
H623 NO.1	Cleaned Head & Tail Dusted	BC
H623 NO.2	Cleaned Head & Dusted	BC
H623 NO3		<del>BC</del>
Longwall	cleaned on Flowthrough	BC

Checked out by Refuges 6, 8, 9 all OK  
Phones work

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers

[Signature] 1354A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 38359

46543—BJW Printing & Office Supplies Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 1-20-10 SHIFT: owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought Time          AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1					
NORTH NO. 1					
<u>E1154</u>	<u>needs Dusted</u>	<u>GU</u>	<u>✓</u>		
<u>E1155</u>	<u>Hand Driver needs cleaned &amp; Dusted</u>	<u>GU</u>	<u>✓</u>		
NORTH NO. 4	<u>Take up needs RT cleaning</u>	<u>GU</u>	<u>✓</u>		
NORTH NO. 5	<u>needs Dusted. Hd: SIBIK</u>	<u>GU</u>	<u>✓</u>		
NORTH NO. 6	<u>Flowthrough needs added cleaning &amp; Dusting</u>	<u>BC</u>	<u>✓</u>		
NORTH NO. 7					
NORTH NO. 8					
GLORY HOLE					
<del>H623</del> NO. 1	<u>None Observed, cleaned &amp; rock Dusted</u>	<u>JS</u>	<u>✓</u>		
<del>H623</del> NO. 2	<u>None Observed, cleaned and rock Dusted.</u>	<u>JS</u>	<u>✓</u>		
<u>H623 #3</u>	<u>Needs cleaned &amp; Dusted.</u>	<u>JS</u>	<u>✓</u>		
<u>H622 #1</u>	<u>tail needs added cleaning &amp; Dusting</u>	<u>BC</u>	<u>✓</u>		
<u>H622 #2</u>	<u>needs Dusted from Head to tail / Head needs <sup>added</sup> cleaning</u>	<u>BC</u>	<u>✓</u>		
<u>Lonywell</u>	<u>needs Flowthrough added cleaning &amp; Dusting</u>	<u>BC</u>	<u>✓</u>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

Ob 624 Ob 620 208602

SIGNED BY: Don Allen 1539A John Bishop 32476  
Belt Examiners and Certificate Numbers  
Willie Campbell 1354A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE: 1-20-10 SHIFT: Day 1130 AM OR PM TO 300 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
<del>NO. 3</del> NORTH 3	men working on Hd and Drive	CC
NORTH 4	men fixing structure change roller	CC
NORTH 5	cleared flow tail: Dusted tail	CC/BC
NORTH 6	change roller	CC
NORTH 7		
NORTH 8		
GLORY HOLE		
<del>NO. 1</del> NO. 1	cleared & Dusted on head & tail	BC/JS
<del>NO. 2</del> NO. 2	cleared on head	BC/JS

Checked 6 Belts, Refuges, O.K. BRK 89, cleared & phones work

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers

[Signature] 1384-A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 83389  
Mine Foreman Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-20-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:40 AM or PM

Report received by: Russell Gunnar  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up Needs cleaned	RG	✓		
NORTH NO. 5	Take-up + Drive need additional cleaning	RG	✓		
NORTH NO. 6	Needs spot cleaned + Dusted 85 to Tail	RG	✓		
NORTH NO. 7	Idle - Power center + charger OK	JAB	✓		
Longwall	Needs Added Spot Cleaning + Dusted	SH	✓		
GLORY HOLE	Idle - D-Box + Pump OK	JAB	✓		
HG-22 #1	tail needs Add Cleaning + Dusted	SH	✓		
HG-22 #2	Belt needs Spot Cleaned Needs Dusted	SH	✓		
HG-23 #1	needs spot Dusted	JAB	✓		
HG-23 #2	Needs Additional cleaning	JAB	✓		
HG-23 #3	Needs spot cleaned + additional spot dusting	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0 ppm CO detected at time of exam  
TRACK, Travelway, Power Centers, D-Boxes, chargers clear at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gunnar 1536-A Scott Holstad 37567  
Belt Examiners and Certificate Numbers  
John Bickford 26176 Dan Miller 15394  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Whane 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-20-10 SHIFT: Day 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
<u>EH's 4</u>	<u>cleaned at Head &amp; tail (Bobby A)</u>	
<u>Ellis 5</u>	<u>cleaned at Head &amp; tail (Bobby A)</u>	
<u>NORTH 2</u>		
<u>NORTH 3</u>		
<u>NORTH 4</u>	<u>cleaned offside from 6-12 BK, from 16-24 on track side (Bobby A)</u>	
<u>NORTH 5</u>		
<u>NORTH 6</u>		
<u>NORTH 7</u>		
<u>Longwall</u>	<u>cleaned spillage at Discharge, cleaned 9 BK, spot cleaned 19-21 BK</u>	<u>SH</u>
<u>GLORY HOLE</u>		
<u>HG-22 #1</u>	<u>cleaned V-Plow</u>	<u>SH</u>
<u>HG-22 #2</u>	<u>Picked up trash along Beltline</u>	<u>SH</u>

Refuge Chamber 6,89,8 OK at time of exam, phones working  
0% CH4, 20.8% O2, 0ppm CO detected at time of exam

SIGNED BY: Scott Halstead 37567 Russell Gunnoe 15369 John Buckford 26176 39476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-20-10 SHIFT: PM AM OR PM TO 830 AM OR PM AM OR PM TO 1130 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
E11.5#4	needs dusted	GU	✓		
E11.5#5	needs dusted	GU	✓		
L11#11	needs spot cleaned & dusted	JS	—		
NORTH NO. 3					
NORTH NO. 4	Take up, and Drives need cleaned	GU	—		
NORTH NO. 5	needs dusted Hd. side Take up needs add. cleaning	GU	—		
NORTH NO. 6	needs add cleaning and dusting 85-Tall	GU	—		
NORTH NO. 7	PC Charger OK	GU	—		
NORTH NO. 8					
GLORY HOLE	O-Box Pump OK	GU	—		
H623 NO. 1	TRAIL NEEDS DUSTED	JS	✓		
H623 NO. 2	NONE OBSERVED	JS	✓		
H623 #1	NONE OBSERVED	JS	✓		
H623 #2	NONE OBSERVED	JS	✓		
H623 #3	NEEDS CLEAN & DUSTED	JS	✓		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OK CHY, 020, 20-8-202  
PCS, chargers, O-boxes, Track, Travelways all OK AT JOE

SIGNED BY: Don Williams 15399  
 Belt Examiners and Certificate Numbers  
Paul Jones 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33357  
 Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-20-10 SHIFT: EVE 600 AM OR PM TO 830 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Brought out Time \_\_\_\_\_ AM or PM \_\_\_\_\_

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
<u>E/1,5#4</u>	<u>Cleaned U-Plow</u>	<u>GU</u>
<u>E/1,5#5</u>	<u>cleaned at Tail</u>	<u>GU</u>
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<u>cleaned on Flow throw</u>	<u>GU</u>
NORTH 6	<u>cleaned on Flow throw</u>	<u>GU</u>
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges 6, 8, 89 all ok

SIGNED BY: D. Williams 1539A  
Belt Examiners and Certificate Numbers  
J. [Signature] 32476  
Belt Examiners and Certificate Numbers  
COUNTERSIGNED BY T. [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-21-10 SHIFT: owl AM OR PM TO: 300 AM OR PM TO: 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom SKAGGS Time 510 AM or PM

Report received by: Don Williams 15799  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs dusted	GU	✓		
Ellis #5	needs dusted	GU	✓		
Lwall	Needs spot cleaned & dusted	JS	✓		
NORTH NO. 3					
NORTH NO. 4	takeup and drives need cleaned	GU	✓		
NORTH NO. 5	needs dusted #1-5 OK takeup needs cleaning	GU	✓		
NORTH NO. 6	needs add cleaning & dusted 85-Tail	GU	✓		
NORTH NO. 7	PC'S charger OK	GU	✓		
NORTH NO. 8					
GLORY HOLE	D-Box Pump OK	GU	✓		
HQ2 NO. 1	Tail needs dusted	JS	—		
HQ2 NO. 2	none observed	JS	—		
HQ3 #1	none observed	JS	—		
HQ3 #2	none observed	JS	—		
HQ3 #3	needs cleaned & dusted	JS	—		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
02CH4, 02CO, 2018302  
PC'S, chargers, DBoxes, Travelways OK

SIGNED BY: Don Williams 15799  
 Belt Examiners and Certificate Numbers  
John Skaggs 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE: 12-10 SHIFT: DWL 11:30 AM OR PM TO 3:00 AM OR PM AM OR PM TO 11:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brown et al Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
ELLIS #4	Cleaned on Tail change rolls	GU
ELLIS #5	Cleaned V-Flow change rolls	GU
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned Tail and Flow thru V-Flow	GU
NORTH 6	Cleaned V-Flow Flow thru	GU
NORTH 7		
NORTH 8		
GLORY HOLE		
NO. 1		
NO. 2		

OGCH, OGCO, 2018302  
Checked out by Refuges 6-8-89  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

SIGNED BY: Don Miller 1539A  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-21-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:45 AM OR PM

Report received by: Russell Sumner  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up + Drive Area Needs Additional cleaning	RG	✓		
NORTH NO. 5	Take-up needs Add. cleaning, needs Dusted <sup>tail to</sup>	RG	✓		
NORTH NO. 6	Needs Add. cleaning + Dusting 85-Tail	RG	✓		
NORTH NO. 7	Idle - Power center + charger OK	JAB	✓		
Longwall	Needs Spot Cleaned & Dusted	SH	✓		
GLORY HOLE	Idle - D-Box + Pump OK	JAB	✓		
HG-22 #1	tail Needs Add Cleaning & Dusted	SH	✓		
HG-22 #2	NONE OBSERVED	SH	✓		
HG-23 #1	Needs Spot Dusted	JAB	✓		
HG-23 #2	Needs Additional Cleaning at Tail	JAB	✓		
HG-23 #3	Needs Spot cleaned & Dusted	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.89% O<sub>2</sub>, 0ppm CO detected at time of exam  
Track, Travelways, Power Centers, Chargers, D-Boxes clear At time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Scott Halstead 37567 John A. Bickford 26176  
 Belt Examiners and Certificate Numbers  
Russell Sumner 1536-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-21-10 SHIFT: Day 6:00 AM OR PM TO          AM OR PM TO          AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom          Time          AM or PM

Report received by:         

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled v-plow	RG
Ellis 5	Shoveled v-plow	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on Tail, Ran dusters at Tail + Drives, <del>etc</del>	RG
NORTH 5	Cleaned on Tail + Flow-Thru, Ran Duster at Tail, cleaned on Take-up	RG
NORTH 6	Shoveled v-plow, Ran duster at Head	JAB, RG
NORTH 7		
Longwall	Cleaned Spillage offside of Discharge, cleaned Spillage at 29 BK	SH
GLORY HOLE		
HG 22 #1	cleaned under flow thru, cleaned offside of tail, Put Crossunder Guard up at Drive	SH
#2	Put Clamp Back on Guard at takeup	SH
HG 23 #1	Cleaned at tail	JAB
HG 23 #2	Cleaned at tail	JAB

Refuge Chambers at 6, 8, 9, 8, Bek 2 sect. OK at time of exam; phones work  
 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0 ppm CO detected at time of exam

SIGNED BY: Scott Halstead 37567 John A. Beckford 26176  
 Belt Examiners and Certificate Numbers  
Russell Dummer 1536-A John [Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33859  
 Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-21-10 SHIFT: EVE AM OR PM TO 8:30 AM OR PM TO 11:30 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>H113 #4</del> SOUTH NO. 1	NEEDS DUSTED	J.S.	✓		
<del>ELLIS #3</del> NORTH NO. 1	NEEDS DUSTED	J.S.	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	NONE OBSERVED	J.W.	✓		
NORTH NO. 5	NONE OBSERVED	J.W.	✓		
NORTH NO. 6	NONE OBSERVED	J.W.	✓		
<del>NORTH NO. 7</del> LONGWALL NEEDS SPOT CLEANED & DUSTED		MEXE WEBB	✓		
GLORY HOLE					
<del>H6302 #1</del> LBB NO. 1	SPOT CLEAN	J.S.			
<del>H6212 #2</del> LBB NO. 2	NONE OBSERVED	J.S.			
H623 #1	NEEDS SPOT CLEAN	J.S.	✓		
H623 #2	NEED CLEAN AND DUSTED	J.S.	✓		
H623 #3	NEEDS SPOT CLEANED & DUSTED	J.S.	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

TRACK & TRAVELWAYS CLEAN AT TIME OF EXAM  
 O% CH4 20.8% O2 0.1% CO DETECTED AT TIME OF EXAM  
 REFUGE CHAMBER 8, 89 OK AT TIME OF EXAM.

SIGNED BY: [Signature] 32476 [Signature] 24735  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-21-10 SHIFT: LU AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.


Was this report phoned to outside Yes \_\_\_ No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH-1	ALL #4 NEEDS DUSTED	JS
NORTH-1	ALL #5 NEEDS DUSTED	JS
NORTH 2		
NORTH 3		
NORTH 4	NONE OBSERVED	
NORTH 5	NONE OBSERVED	JS
NORTH 6	NONE OBSERVED	
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1	#1 SPOT CLEAN	JS
LBB NO. 2	#2 NONE OBSERVED	JS
#1	NEEDS SPOT CLEANED & DUST	JS
#2	NEEDS CLEANED & DUST	JS
#3	NEEDS CLEANED & DUST	JS

TRAVEL WAYS OK.

SIGNED BY:  38476  
Belt Examiners and Certificate Numbers

 1479-A  
Superintendent

COUNTERSIGNED BY T. Moore 33357  
Mine Foreman Certificate No.

Use Indefinible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-22-10 SHIFT: OW 3:30 AM OR PM TO 5:30 AM OR PM 3:30 AM OR PM TO 5:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Rolls <sup>#4</sup> NEED DUSTED	JS	✓		
NORTH NO. 1	Rolls <sup>#5</sup> NEED DUSTED	OS	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	NONE OBSERVED	JS	✓		
NORTH NO. 5	NONE OBSERVED	JS	✓		
NORTH NO. 6	NONE OBSERVED	JS	✓		
NORTH NO. 7					
<del>NORTH NO. 8</del>	<del>Longwall NEEDS CLEAN &amp; DUSTED</del>	<del>JS</del>	<del style="text-align: center;">✓</del>		
GLORY HOLE					
LBB NO. 1	H6 #1 SPOT CLEAN				
LBB NO. 2	#2 NONE OBSERVED				
H623 #1	NEEDS SPOT CLEANED	Kf JT	✓		
#2	NEEDS CLEAN AND DUSTED	Kf JT	✓		
#3	NEEDS CLEAN AND DUSTED	Kf JT	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

TRAVEL WAY O/C AT TIME OF EXAM.  
REFUGE CHAMBERS 2.89, 6 OK. AT TIME OF EXAM.  
0% CH4, 21.2% O2, 0ppm CO DETECTED

SIGNED BY: [Signature] 32476 [Signature] 32294  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mame 33359 Superintendent Certificate No.  
 Mine Foreman



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE \_\_\_\_\_ SHIFT: \_\_\_\_\_ AM OR PM TO \_\_\_\_\_ AM OR PM TO \_\_\_\_\_ AM OR PM TO \_\_\_\_\_ AM OR PM TO \_\_\_\_\_  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1 <i>Bill</i>	<i>change roll 2 c</i>	
NORTH 2 <i>Bill</i>	<i>change roll 1 c</i>	
NORTH 3	<i>4 north change roll inside up, cleaned take up</i>	
NORTH 4		
NORTH 5	<i>change roll 4 c</i>	
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
	<i>change roll South &amp; 1 north 1 c vBB side 26</i>	

SIGNED BY: \_\_\_\_\_  
Belt Examiners and Certificate Numbers

\_\_\_\_\_  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *T. Name* \_\_\_\_\_ *33359* \_\_\_\_\_  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-22-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 2:45 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:50 AM or  PM

Report received by: Russell Gunnar  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up + Drive AREA needs additional cleaning	RG	✓		
NORTH NO. 5	Tail + Flow-Thru needs add. cleaning, <sup>Needs Dusted</sup> 51-Head	RG	✓		
NORTH NO. 6	Needs spot cleaned 85-Tail, Take-up needs add. cleaning	RG	✓		
NORTH NO. 7	Idle- Power Center + Charger OK	JAB	✓		
Longwall	Needs Spot Cleaned + Dusted	SH	✓		
GLORY HOLE	Idle- D-Box + Pumps OK	JAB	✓		
HG-22 #1	Discharge + tail needs Add Cleaning, Belt Needs Dusted	SH	✓		
HG-22 #2	Belt Needs Spot Cleaning	SH	✓		
HG-23 #1	Needs Additional cleaning to Air lock	JAB	✓		
HG-23 #2	Needs spot cleaned + Tail cleaned	JAB	✓		
HG-23 #3	Needs spot cleaned + Last 4 Brks. need Dusted	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO detected at time of exam  
Travelways, Power Centers, D-Boxes, chargers clear at time of exam  
Visual check of CO monitors Ok at time of exam

SIGNED BY: Russell Gunnar 1536-A Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
John A. Bickford 26176 Don Williams 1539A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

with Cooper 1284-A

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-22-10 SHIFT: DAY 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis -4	Shoveled V-plow	
Ellis 5	Shoveled V-plow, Ran duster at Tail	
NORTH 2		
NORTH 3		
NORTH 4	Shoveled V-plow, Ran dusters at Tail & Drive	RG
NORTH 5	take up to 56 cleaned (Bobby + Corey), cleaned on Tail + Flow-Through <sup>Ran Dusters</sup> AT Tail & Flow-Through	RG
NORTH 6	Spot cleaned 99-100 Brk, Shoveled V-plow	RG
NORTH 7		
LONGWALL	cleaned lots of Spillage offside flowthrough, Greased Drive, cleaned 29 Brk	SH
GLORY HOLE		
HG-22 #1	Cleaned Spillage at tail, trained on Belt	SH
HG-22 #2		
HG-23 #1	Cleaned at tail & on spillage at Air Lock	SH
HG-23 #2		
HG-23 #3		

0% CH4, 20.8% O2, 0ppm CO detected at time of exam

Refuge chambers at 6, 89, 8 Brk 2 sect. OK + phones working at time of exam

SIGNED BY: Russell Gunnor 1536-A Scott Waldstead 37567  
Belt Examiners and Certificate Numbers  
John Buckford 26176 Don Wilson 15377  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

*with the new record*

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-22-10 SHIFT: EVE AM OR PM TO 830 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes NoX By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs Dusted - Tail needs add cleaning	GU	✓		
Ellis #5	needs Dusted	GU	✓		
LWAY	needs spot cleaned & dusted	WC	✓		
NORTH NO. 3					
NORTH NO. 4	Takeup drives needs add cleaning	BU	✓		
NORTH NO. 5	SI-Hd needs Dusted	GU	✓		
NORTH NO. 6	needs spot cleaned & Tail	GU	✓		
NORTH NO. 7	Tale PC charger OK	GU	✓		
NORTH NO. 8					
GLORY HOLE	Tale D-Box P Pumps OK	GU	✓		
H62 NO#1	Discharge & tail needs added cleaning	BC	✓		
H62 NO#2	Belt needs added cleaning	BC	✓		
H623#1	needs added cleaning and airlocks	BC	✓		
H623#2	tail needs cleaned	BC	✓		
H623#3	needs spot cleaned & Dusted	BC	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OG ch4 OBCO 208202  
PC'S Chargers O-Boxes, TRAVELWAYS OK

SIGNED BY: [Signature] 15397  
Belt Examiners and Certificate Numbers  
[Signature] 13844  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 35359  
Mine Foreman Certificate No. Superintendent Certificate No.

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-22-10 SHIFT: EVE 600 AM OR PM TO 830 AM OR PM AM OR PM TO AM OR PM AM OR PM

**ON-SHIFT EXAM.** **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes  No  By Whom Brought out Time        AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<u>Ellis 4</u>	<u>Cleaned V-plow</u>	<u>GU</u>
<u>Ellis 5</u>	<u>Cleaned V-plow</u>	<u>GU</u>
<b>NORTH 3</b>		
<b>NORTH 4</b>		
<b>NORTH 5</b>	<u>Cleaned Tail &amp; Flow thru</u>	<u>GU</u>
<b>NORTH 6</b>	<u>Cleaned Flow thru</u>	<u>GU</u>
<b>NORTH 7</b>		
<b>NORTH 8</b>		
<b>GLORY HOLE</b>		
<b>LBB NO. 1</b>		
<b>LBB NO. 2</b>		
<u>H622 #1</u>	<u>Cleaned on tail</u>	<u>BC</u>
<u>H622 #2</u>		
<u>H623 #1</u>	<u>Shoveled V-plow</u>	<u>BC</u>
<u>#2</u>		
<u>#3</u>		
<u>Honyway</u>	<u>cleaned on flow thru</u>	<u>BC</u>

Checked out by Refuges 6, 8, 89 all OK  
Phones work at all Refuges

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers  
[Signature] 1259A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 3339  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-23-10 SHIFT: 0W AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No X By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs Dusted Tail needs Add cleaning	GU	✓		
Ellis #5	Needs Dusted Hd area needs add cleaning	GU	✓		
L/WAII	needs spot cleaned & Dusted	BC	✓		
NORTH NO. 3					
NORTH NO. 4	#Kexp needs Add cleaning	GU	✓		
NORTH NO. 5	SI-Hd needs Dusted	GU	✓		
NORTH NO. 6	Needs Spot Cleaned 85-Tail	GU	✓		
NORTH NO. 7	PC chargers OK	GU	✓		
NORTH NO. 8					
GLORY HOLE	O-Box Pump OK	GU	✓		
H623 NO. 1	Discharged tail needs added cleaning & Dusting	BC	✓		
H623 NO. 2	Belt needs added cleaning & Needs Dusted	BC	✓		
H623 #1	needs cleaned at Air lock	BC	✓		
#2	tail needs added cleaning & Dusting	BC	✓		
#3	Hens needs added cleaning & Dusting	BC	✓		
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OB 664, OB CO, 208202  
PCIS, chargers, O-Boxes, Troubleshooting OK

SIGNED BY: Dan Allen 15397  
Belt Examiners and Certificate Numbers  
Wally Casper 13544  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33559  
Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT  
EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-23-10 SHIFT: owl 1130 AM OR ~~PM~~ TO 300 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Brought out  
Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Cleaned on Tail	GU
Ellis 5	Cleaned on Tail cleaned on take up LC	GU
L608/1	cleaned on CTW; turn on belt riding band LG	
NORTH 3		
NORTH 4		
NORTH 5	Cleaned Flow Threw	GU
NORTH 6	Cleaned Flow Threw	GU
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

checked out by Refuges 6, 8, 89 all OK  
Phones work at all Refuges

SIGNED BY: Don Williams 1539A  
Belt Examiners and Certificate Numbers  
Wally Conroy 1334A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Meier 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 1.23.10 SHIFT: Day AM OR PM TO: 1200 AM OR PM TO: 300 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>ELLIS SOUTH NO. 4</del>	<del>Needs dusted</del>	<del>5AB</del>	<del>✓</del>		
<del>ELLIS NORTH NO. 5</del>	<del>Needs dusted Head Area, needs add'l cleaning</del>	<del>5AB</del>	<del>✓</del>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs add'l cleaning	5AB	✓		
NORTH NO. 5	51 to Head needs dusted	5AB	✓		
NORTH NO. 6	Needs spot cleaned	5AB	✓		
NORTH NO. 7	PC's + Chryson OK	5A	✓		
Long Wall	Needs Spot Cleaned + Dusted	SH	✓		
GLORY HOLE	D'Boya + Pump OK	5A	✓		
HG <sup>12</sup> NO. 1	Discharge Needs Add Cleaning, off side tail needs Cleaned	SH	✓		
HG <sup>12</sup> NO. 2	Needs Some Cleaning + Needs Dusted	SH	✓		
HG 23 #1	} Toller - Power off				
HG 23 2					
HG 23 3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% ch<sub>4</sub>, 0% CO + 20.8% O<sub>2</sub> detected at time of exam

Track, Travelways, Power Centers, D'Boya + Pumpers clear at time of exam

Don Williams 15397A

SIGNED BY: John Bedford 26176  
Belt Examiners and Certificate Numbers.

Scott Habstead 37567

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Tony Moore 33359  
Mine Foreman Certificate No.

Superintendent

Certificate No.

Walter Appene 135517A



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-23-10 SHIFT: Doy AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<sup>Felin 4</sup> SOUTH 1	Cleaned at tail, Cleaned & Greased tail Roller (Bobby & Corey)	JAB
<sup>Felin 5</sup> NORTH 1	Cleaned at Head, Cleaned Head & Cleaned & Greased Tail (Bobby & Corey)	JAB
NORTH 2		
NORTH 3		
NORTH 4	Cleaned & Greased tail (Bobby & Corey)	JAB
NORTH 5	Cleaned at tail & flow thru, Cleaned offside: take-up to 55 Bch. BA	JAB
NORTH 6	Cleaned at flow thru	JAB
NORTH 7		
Long Wall	Cleaned Spillage offside of flow thru, Dusted Head AREA	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked Refuses at 6, 8, 89 Bchs. - OK, Phones OK

SIGNED BY: [Signature] 15798  
[Signature] 26176  
Belt Examiners and Certificate Numbers  
[Signature] 37567  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 3389  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-23-10 SHIFT: EVE AM OR PM TO 830 AM OR PM 10130 AM OR PM PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Brought out Time AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>E11'S NO. 4</u>	<u>Needs Dusted, Tail needs Add cleaning</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>E11'S NO. 5</u>	<u>Hd, Area needs Add cleaning, Needs Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Takeup need Add cleaning</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>SL-TAIL needs spot cleaned - SL Head needs Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>needs Dusted &amp; spot cleaned</u>	<u>BC</u>			
NORTH NO. 7	<u>PC, Charger OK</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>Longwall</u>	<u>needs spot cleaned &amp; Dusted</u>	<u>BC</u>			
GLORY HOLE	<u>O-Box Pump - OK</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>H622</u> NO. 1	<u>Discharge needs Added cleaning &amp; Dusting</u>	<u>BC</u>			
<u>H622</u> NO. 2	<u>needs some cleaning &amp; Dusting</u>	<u>BC</u>			
<u>H623 #1</u>	<u>&gt; IDK NO preshift NO Power</u>				
<u>#2</u>					
<u>#3</u>					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

CH4 0.06 , CO 0.06 , O<sub>2</sub> 20.8% Detected  
Travelways OK

SIGNED BY: [Signature] 153911  
 Belt Examiners and Certificate Numbers

[Signature] 135414  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
 Mine Foreman Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-23-10 SHIFT: EVE 600 AM OR PM TO 830 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<del>ELLIS 4</del>		
<del>ELLIS 1</del>	cleaned ✓ flow	GU
<del>ELLIS 1</del>	cleaned ✓ flow	GU
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	cleaned flow thru	GU
NORTH 6		
NORTH 7		
Longwall	shoveled flow through	BC
GLORY HOLE		
<del>NO. 1</del>	shoveled on tail	BC
<del>NO. 2</del>		

Checked out by Refuges 6-8-89

SIGNED BY: [Signature] 15397  
Belt Examiners and Certificate Numbers  
[Signature] 135477  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-24-10 SHIFT: DW1 AM OR PM TO 300 AM OR PM TO 0600 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No X By Whom Boyd Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	needs Dusted, Tail needs spot cleaning	GU	✓		
Ellis 5	Hd needs Add cleaning needs Dusted	GU	—		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	TAKE # needs Add cleaning	GU	—		
NORTH NO. 5	56-Tail needs spot cleaning 51-Hd needs Dusted	GU	—		
NORTH NO. 6	needs Dusted & spot cleaned	BC	✓		
NORTH NO. 7	Charger PC OK	GU	—		
Longview #1	needs spot cleaned & Dusted	BC	✓		
GLORY HOLE PC Dump	OK	GU	—		
H622 #1	Head needs cleaned & Dusted from <sup>Head to</sup> tail	BC	✓		
H622 #2	Head needs cleaned & Dusted from <sup>Head to</sup> tail	BC	✓		
H623 #1	} IDK no power NO Preshift				
#2					
#3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OF CH<sub>4</sub>, PECO 2080<sup>2</sup> Detected  
PC'S, Chargers Detectors, Travel ways OK

SIGNED BY: Sam Miller 15544

Belt Examiners and Certificate Numbers

Walter Capella 13844

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Tony Moore  
 Mine Foreman

33357  
 Certificate No.

Superintendent

Certificate No.

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-24-10 SHIFT: 8W1 1130 AM OR PM TO 300 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
ELLIS 4	cleaned ✓ flow	GU
ELLIS 5	cleaned ✓ flow change rolls ✓	GU
NORTH 2		
NORTH 3		
NORTH 4	change roll @ LC	
NORTH 5	clean on flow thru	GU
NORTH 6	made splice	GU
NORTH 7		
Longwall	shoveled on flow thru change rolls ✓	
GLORY HOLE		
H6 <sup>2</sup> NO. 1	shoveled on tail	BC
H6 <sup>2</sup> NO. 2		
H		

Checked out by Refuges 6, 8 & all OK

*Handwritten signature*

SIGNED BY: [Signature] 1939A  
Belt Examiners and Certificate Numbers  
[Signature] 1359-1A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

46543-BJW Printing & Office Supplies  
[Signature] 26176

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-24-10 SHIFT: Day AM OR PM TO 12<sup>00</sup> AM OR PM TO 3<sup>00</sup> AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom H. Lilly, D. Jones Time 2:35 AM or PM

Report received by: John B. Beckford  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>Falls</del> NO. 4	Needs dusted	JAB	✓		
<del>Falls</del> NO. 5	Needs dusted, Head needs add'l cleaning	JAB	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs add'l cleaning	JAB	✓		
NORTH NO. 5	51' & Head mesh dusted 56' & Tail needs spot cleaned	JAB	✓		
NORTH NO. 6	Needs spot cleaned & dusted	JAB	✓		
NORTH NO. 7	Charger & PC - OK	JAB	✓		
Long wall	Needs dusted & spot cleaned	HL	✓	✓	
GLORY HOLE	PC & Pump OK	JAB	✓		
H623 NO. 1	Needs dusted, Tail needs cleaned	DS	✓		
H623 NO. 2	Needs spot cleaned & dusted	DS	✓		
H623 1	} Follie No work, NO Power				
H623 2					
H623 3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

O<sub>2</sub> 20.8%, CO 0% + 20.8% O<sub>2</sub> detected at time of exam  
Power Centers track, travelways, Pumps, Charger & D'Boya  
clear at time of exam

SIGNED BY: John B. Beckford 26176 H. Lilly 28045  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

W. R. [Signature] 183972

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-24-10 SHIFT: Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
4 Elkin	Cleaned at tail	JAB 5G
5 Elkin	Cleaned at tail	5G JAB
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned at tail & flow thru	5G, 5A
NORTH 6	Cleaned at flow thru	5A
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
HG 23 1	Cleaned at tail & on spillage in by Air-Led	JAB 5G
HG 23 2	Cleaned at V'P flow.	JAB 5G

*Checked Refuges at 6, 8 & 89 Bks. - OK; Phones OK*

SIGNED BY: John Bickford 26176 JL 32476  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-24-10 SHIFT: EVE 6:00 AM OR PM TO 6:00 AM OR PM 8:30 AM OR PM TO 11:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>E115</del> SOUTH NO. 1	Needs dusted	BC	✓		
<del>E115</del> NORTH NO. 1	needs Dusted, Head needs added cleaning	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Takeup needs added cleaning	BC	✓		
NORTH NO. 5	5 to 11 ft needs dusted 6 to tail needs added cleaning	BC	✓		
NORTH NO. 6	needs dusted & spot cleaned	BC	✓		
NORTH NO. 7	IDLE PC CLEAR	BC	✓		
NORTH NO. 8					
GLORY HOLE	IDLE - PC CLEAR	BC	✓		
<del>HG22</del> NO. 1	NEEDS DUSTED	J/S	✓		
<del>HG22</del> NO. 2	NEEDS DUSTED	J/S	✓		
Longwall	NONE OBSERVED AT TIME OF EXAM	J/S	✓		
HG23 #1	NONE OBSERVED	J/S	✓		
#2	NONE OBSERVED	J/S	✓		
#3	NONE OBSERVED	J/S	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0% CH4, 0% CO, 20.8% O<sub>2</sub> detected  
TRACK / Trampolines, P.C. - D-Box, Pumps, Chargers  
all cleared at time of Exam

SIGNED BY: [Signature] 138478  
Belt Examiners and Certificate Numbers

[Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-24-10 SHIFT: 21/5 600 AM OR PM TO 600 8:30 AM OR PM TO 11:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
<del>CH 3-4</del> SOUTH 1	Shoveled V-plow	BC
<del>CH 3-5</del> NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	shoveled At tail	BC
NORTH 5	shoveled V-plow at Flowthrough / & tail	BC
NORTH 6	shoveled Flowthrough	BC
NORTH 7		
NORTH 8		
GLORY HOLE		
<del>HOLE</del> NO. 1		
<del>HOLE</del> NO. 2		

Reluges at # 6, 8, 89 brk all clear & phones work

SIGNED BY: [Signature] 1384-A  
Belt Examiners and Certificate Numbers  
[Signature] 22476-  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 37359  
Mine Foreman Superintendent Certificate No. Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-25-10 SHIFT: 0w1 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
<del>4113</del> SOUTH NO. 1	<del>NEEDS DUSTED</del>				
<del>4113</del> NORTH NO. 5	HEAD NEEDS Added CLEANING & DUSTED	JS	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	TAKUP NEEDS CLEANED & DUSTED	JS	✓		
NORTH NO. 5	NEEDS DUSTED	JS	✓		
NORTH NO. 6	NEEDS SPOT CLEANED & DUSTED	JS	✓		
NORTH NO. 7	NONE OBSERVED AT TIME OF EXAM	JS	✓		
<del>NORTH NO. 8</del>					
GLORY HOLE	PK & Pumps OK AT TIME OF EXAM	JS	✓		
<del>H621</del> HBB NO. 1	Head needs added cleaning & dusted from head to tail	BC	✓		
<del>H622</del> HBB NO. 2	1 brk out by tail water over boots Head needs cleaned & dusted from head to tail	BC	✓		
H623 #1	needs added cleaning at air block	BC	✓		
H623 #2	tail needs added cleaning (working on)	BC	✓		
H623 #3	NONE OBSERVED	BC	✓		
Longwall	needs spot cleaned & dusted	BC	✓		
2 North	Head needs add cleaning tail needs all cleaning	MK	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4 20.9% O2 0% CO detected AT EXAM  
Power Boxes Chargers Pumps OK AT EXAM  
D. Boxes - Visual OK Co monitors OK AT EXAM

SIGNED BY: Walter Coppen 1354A M. K. Weber 33017  
Belt Examiners and Certificate Numbers  
[Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 35357 Superintendent Certificate No.  
Mine Foreman Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-25-10 SHIFT: 0001 6:00 AM OR PM TO 6:00 AND/OR PM 3:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1	change rolls LC	
NORTH 1	change rolls LC	
NORTH 2		
NORTH 3		
NORTH 4	Shovel tail and spot clean then cleaned on take up LC	JS
NORTH 5	change rolls LC	
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
H622 EBB NO. 1	shoveled tail to 1st setup	BC
H622 EBB NO. 2		
H623 #1	Shoveled tail + v-plow	BC
H623 #2	Shoveled on tail	BC
H623 #3	shoveled from head to tail	
longwall	cleaned on flow through	BC

SIGNED BY: W. J. Capron 1254-14 John [Signature] 32476  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers  
COUNTERSIGNED BY T. [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-25-10 SHIFT: DAY AM OR PM TO AM OR PM 12:00 TO 3:00 AM OR PM PRE-SHIFT EXAM.

**ON-SHIFT EXAM.**

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Brought out

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ettis 4</u>	<u>Tail needs add. cleaning</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>Ettis 5</u>	<u>Head area needs add. cleaning</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Take-up needs add. cleaning</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>Needs dusted</u>	<u>MK</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>Needs spot cleaned &amp; dusted</u>	<u>MK</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>Idle; P.C. &amp; Charger</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>LONGWALL</u>	<u>Needs spot cleaned &amp; dusted</u>	<u>MK</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>Idle; P.C., Charger, D-Box</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-22 #1</u>	<u>Flow thru &amp; tail needs add. cleaning, belt needs dusted</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-22 #2</u>	<u>Head needs cleaned, needs dusted head to tail</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-23 #1</u>	<u>Needs add. cleaning at airlock and tail</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-23 #2</u>	<u>tail needs add. cleaning, belt needs cleaned</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-23 #3</u>	<u>tail needs add. cleaning</u>	<u>SH</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO detected at time of exam

Track, Travelways, Power centers, D-Boxes, Chargers clear at time of exam

Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Dunne 1536-1A M. Kibben 33017  
 Belt Examiners and Certificate Numbers

Scott Holstead 37567  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Tony Moore 33359 \_\_\_\_\_  
 Mine Foreman Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-28-10 SHIFT: DAY 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	shoveled v-plow, Greased tail & Cleaned (Bobby)	RG
Ellis 5	shoveled v-plow, Greased tail & Cleaned (Bobby & Cory)	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, Ran dusters at Tail & Drives	RG
NORTH 5	cleaned V Plow, Cleaned 56-68 BK ON WALK Side Bobby & Cory	MK
NORTH 6		
NORTH 7	Cleaned on mud + water at Head	MK
Longwall	cleaned Spillage at discharge, Greased Drive, Dusted Head	SH
GLORY HOLE		
HG-22 #1	cleaned on tail, Dropped Bad Roller	SH
HG-22 #2		
HG-23 #1	cleaned V-Plow	SH
HG-23 #2	cleaned V-Plow and tail	SH
HG-23 #3		

Refuge chambers at 6, 8, 89 clear at time of exam & phones working  
0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO detected at time of exam

SIGNED BY: Russell Gunnor 1536-A M Kibbin 33017  
Belt Examiners and Certificate Numbers  
Scott Halstead 37567  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Tony Mason 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 1-25-70 SHIFT: LVE AM OR PM TO AM OR PM 8:30 AM OR PM TO AM OR PM 11:00  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>ELLIS #1</del>	TAIL NEEDS Added CLEANING	JS	✓		
<del>ELLIS #5</del>	HEAD NEEDS Added CLEANING & DUSTED	J	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	TAKE UP NEEDS CLEANED	JS	✓		
NORTH NO. 5	NEEDS DUSTED	JS	✓		
NORTH NO. 6	NEEDS DUSTED TAIL CLEANED	JS	✓		
NORTH NO. 7	HEAD AND DUSTED	BC	✓		
ZONGWALIS	NEEDS CLEAN FLOWTHRU BELTS 8, 12-16 DUSTED	BC	✓		
GLORY HOLE	TDI2 DC CLEAR	BC	✓		
LBB NO. 1					
LBB NO. 2					
HG 22 #1	FLOWTHRU & TAIL NEED CLEANED & DUSTED	BC	✓		
HG 22 #2	HEAD NEEDS CLEANED & DUSTED	DC	✓		
HG 23 #1	NEEDS CLEANED & DUSTED AT AIR LOCK	BC	✓		
#2	TAIL NEEDS CLEAN & DUSTED	BC	✓		
#3	BELT TAIL NEEDS CLEAN & DUSTED	BC	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

TRACK AND TRAVELWAYS OK AT TIME OF EXAM.  
0% CH4, 20.8% O2 DETECTED AT TIME OF EXAM  
POWER CENTER, REFUGE BOXES, D-BOXES, CHARGER OK AT TIME OF  
EXAM.

SIGNED BY: [Signature] 32476  
 Belt Examiners and Certificate Numbers  
[Signature] 135476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

**ON-SHIFT  
EXAMINATION OF BELT CONVEYORS**


Use Pencil or Ink

DATE 1-25-18 SHIFT: 2<sup>nd</sup> 6:00 AM OR PM TO 6:00 AM OR PM  
**ON-SHIFT EXAM.** **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
ELTIS * 4		
ELTIS * S	SHOVEL ON HEAD	JS
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6	SHOVEL ON V-PLow	JS
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

SIGNED BY:   
 Belt Examiners and Certificate Numbers  
W. J. Connerley 1354  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pen or Ink

PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS

DATE 1-26-10 SHIFT: OW AM OR PM TO 3:30 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>ELLIS #4</del>	TAIL NEEDS ADDITIONAL CLEANING & DUSTING	JS	✓		
<del>ELLIS #5</del>	HEAD NEEDS CLEAN & DUSTED	JS	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	TAKE UP NEEDS CLEANED	JS	✓		
NORTH NO. 5	DUSTING	JS	✓		
NORTH NO. 6	DUSTING	JS	✓		
NORTH NO. 7	HEAD & TAIL NEEDS DUSTED	BC	✓		
LONG WALL	NEEDS CLEANED AT FLOWTHROUGH & BELT NEEDS DUSTED	BC	✓		
GLORY HOLE	IDLE PC CLEAR	BC	✓		
H602*1	FLOWTHRU & TAIL NEEDS CLEAN & DUSTED	BC	✓		
H602*2	HEAD NEED CLEAN & DUSTED	BC	✓		
H603*1	NEEDS CLEAN & DUSTED	BC	✓		
H603*2	TAIL NEEDS CLEAN & DUSTED	BC	✓		
H603*3	BELT TAIL NEEDS CLEAN & DUSTED	BC	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

Refuge Boxes 8, 6, 89 OK AT TIME OF EXAM  
 POWER CENTER OK AT TIME OF EXAM  
 0% CH4, 20.8% O2PPM @ DETECTOR AT TIME OF EXAM.  
 Phones at Refuges are working

SIGNED BY: [Signature] 32476  
 Belt Examiners and Certificate Numbers  
[Signature] 1339-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 3339  
 Mine Foreman Certificate No. Superintendent Certificate No.



Use Indellible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-26-10 SHIFT: swl 600 AM OR PM TO 600 AM OR PM 300 AM OR PM TO 600 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

SIGNED BY: [Signature] 1334-A  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-26-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>R1115 #4</u>	<u>Tail needs Add. cleaning + Dusting</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>R1115 #5</u>	<u>Needs spot cleaned 4 to Head</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Take-up needs cleaned</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>Tail + Flow-Thru need Add. cleaning</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>Needs spot cleaned 85 to Tail</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
* NORTH NO. 7	<u>Need add. cleaning + Dusting</u> <u>Belt needs Spot Cleaned + Dusted</u>	<u>MFP</u>	<input checked="" type="checkbox"/>		
<u>LONGWALL</u>	<u>offside-flow thru at Discharge needs Add. cleaning</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	<u>Idle + D-Box, P.C.</u>	<u>SH</u>			
<u>HG-22 #1</u>	<u>Belt needs Dusted, needs cleaned at flow thru + tail</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-22 #2</u>	<u>Belt needs Dusted Head needs cleaned</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-23 #1</u>	<u>Needs Spot Cleaned + Dusted</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-23 #2</u>	<u>Belt needs cleaned, needs Dusted</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-23 #3</u>	<u>Belt needs Dusted, tail needs cleaned</u>	<u>SH</u>	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO detected at time of exam  
Travelways, Power Centers, D-Boxes, chargers clear at time of exam  
Visual check of CO monitors OK at Time of exam

\* Adjusted Rollers at + Near tail

SIGNED BY: Russell Dunne 1536-A Scott Hatfield 37567  
Belt Examiners and Certificate Numbers  
Don Wilman 1539A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33389  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-26-10 SHIFT: Day 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	shoveled v-plow, cleaned & Greased tail (Bobby)	RG
Ellis 5	shoveled v-plow, cleaned & Greased tail (Bobby) Replaced cross under at Head	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, Run duster at Tail + Drive	RG
NORTH 5	cleaned on Tail + Flow-Thru, Run duster at Flow-Thru (55-59 offside cleaned Bobby)	RG
NORTH 6	Shoveled v-plow	RG
NORTH 7	Needs add cleaning at Head & Tail Need add Dust	MP
Lougwall	(cleaned offside flowthru at Discharge X2), cleaned 29 BK	SH
GLORY HOLE		
HG-22 #1	cleaned on tail, trained on Belt	SH
HG-22 #2		
HG-23 #1		
HG-23 #2	cleaned on V-Plow	SH
HG-23 #3		

Refuge chambers 6, 8, 9, & Bek OK + phones working at time of exam  
O<sub>2</sub> CH<sub>4</sub>, 20.8% O<sub>2</sub>, Appm CO detected at time of exam

SIGNED BY: Russell Gurnee 1536-1A  
Belt Examiners and Certificate Numbers

Scott Habstad 37567  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Certificate No.

Superintendent Certificate No.

W. A. P. ... 27000 Al ... 22476

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-26-10 SHIFT: EVE AM OR PM TO 830 AM OR PM TO 1130 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Cambell, Skapps Time 1120 AM or  PM

Report received by: [Signature] 1539A  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELLIS 4	Tail needs add cleaning dusted	GU	✓		
ELLIS 5	Needs spot cleaned & to head	GU	—		
ELWALL	Belt needs spot cleaned & dusted	PS	—		
NORTH NO. 4	Take up needs cleaned	GU	—		
NORTH NO. 5	Tail and flow throw add cleaning	GU	✓		
NORTH NO. 6	Needs spot cleaned 85 to Tail	GU	✓		
NORTH NO. 7	Needs add cleaning and dusting	GU/PS	—		
NORTH NO. 8					
GLORY HOLE	Idle PC charger Pump OK	GU	—		
H622 NO. 1	Belt needs dusted, needs spot clean	WC	—		
H622 NO. 2	Belt needs dusted, Hd. needs clean	WC	✓		
H623 1	Needs spot cleaned & dusted	WC	—		
H623 2	Belt needs cleaned & dusted	WC	—		
H623 3	Belt needs dusted Tail needs clean	WC	—		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

06 chd, PCO, 208202  
Track, Power cables, DBoxes, Chargers all OK

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers  
[Signature] 1384A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-26-10 SHIFT: 5VE 800 AM OR PM TO 850 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	cleaned V-Plow	60
NORTH 6	cleaned V-Plow	60
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
Longwall	cleaned Flowthrough and Dusted	BC/JS

Checked out by Retagos 6, 8, 59 all OK

SIGNED BY: [Signature] 1539A [Signature] 32476  
Belt Examiners and Certificate Numbers  
[Signature] 1754A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-27-10 SHIFT: 0W1 AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs Dusted, Tail needs Add Cleaning	GU	✓		
Ellis #5	48K - Head needs spot cleaned	GU	✓		
L1 wall	Belt needs spot cleaned & Dusted	BC			
NORTH NO. 3					
NORTH NO. 4	TAKE up needs Add cleaning	GU	✓		
NORTH NO. 5	none observed	GU	✓		
NORTH NO. 6	needs spot cleaned walkway side 85-Tail	GU	✓		
NORTH NO. 7	NEEDS DUSTED	JS	✓		
NORTH NO. 8					
GLORY HOLE	IDIE P.C.	JS	✓		
H62 NO. 1	needs Dusted from Head to tail	BC			
H62 NO. 2	needs Dusted from Head to tail	BC			
H623 #1	Add DUST	JS	✓		
H623 #2	TAIL NEEDS CLEAN	JS	✓		
H623 #3	Head NEEDS CLEAN	JS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OG CH4, OG CO, 20.8302  
PCS Chargers, D-Berms, Pumps, and Travel ways all OK

SIGNED BY: Don Williams 1579A W. Ethel Capron 1354A  
Belt Examiners and Certificate Numbers  
John [Signature] 38476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Superintendent Certificate No.

Robert B. Bickford 26176 Russell Gummoe 1536-A Scott Holstead 37567

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-27-10 SHIFT: owl 1130 AM OR PM TO 300 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4	Cleaned on Tail	GU
Ellis #5	Cleaned on Tail	GU
LW411	Hand Dusted From Pinch Roller to Drives <i>change roller LC</i>	GU
NORTH 3		
NORTH 4	<i>change roller LC</i>	
NORTH 5	Cleaned Tail and Flow threw <i>change roller LC</i>	GU
NORTH 6	Cleaned Tail and Flow threw, Dusted Flow threw	GU
NORTH 7		
NORTH 8		
GLORY HOLE		
HGR NO. 1		
HGR NO. 2		
HG23 #1	SPOT CLEAN	JS
HG23 #2	<del>CLEANER</del> CLEANER ON TAIL	JS/120
HG23 #3	HEAD <del>NEED</del> CLEAN ON	JS

Checked out by Refuges 6-889 all OK

SIGNED BY: *[Signature]* 18392 *[Signature]* 13342  
Belt Examiners and Certificate Numbers  
*[Signature]* 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *[Signature]* 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-27-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:40 AM or PM

Report received by: Russell Gurnee  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Tail needs Additional cleaning	RG	✓		
Ellis 5	4 BRK-Head needs spot cleaned	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs Additional cleaning	RG	✓		
NORTH NO. 5	Flow-Thru needs Additional cleaning	RG	✓		
NORTH NO. 6	Needs spot cleaned 85-Tail	RG	✓		
NORTH NO. 7	Needs Add Cleaning At head & Tail	MK	✓		
Longwall	Needs Spot Cleaned & Dusted	SH	✓		
GLORY HOLE	Idle - Power Center & Pump OK	JAB	✓		
LBB NO. 1					
LBB NO. 2					
HG-23 #1	Needs spot Dusted & cleaned at Airlock	JAB	✓		
HG-23 #2	Needs cleaned walkway side Head-Tail	JAB	✓		
HG-23 #3	HEAD NEEDS CLEAN & DUST	JAB	✓		
HG22 #1	belt needs Dusted, tail needs Add Cleaning	SH	✓		
HG22 #2	Needs Dusted	SH	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO detected at time of exam  
Travelways, Power Centers, D-Boxes, chargers, clear at time of exam  
Visual check of CO monitors OK At time of exam

SIGNED BY: Russell Gurnee 1536-A Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
M. Rider 33017 John Bickford 26176  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 35359  
Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-27-10 SHIFT: Day 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Cleaned & Greased tail (Bobby) shoveled v-plow	RG
Ellis 5	cleaned & Greased tail (Bobby) shoveled v-plow	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned Tail, Run duster at Tail	RG
NORTH 5	cleaned 59-63 offside (Bobby) cleaned on Tail + Flow-Thru	RG
NORTH 6	Shoveled v-plow	RG
NORTH 7		
Long wall	cleaned on Head, Cleaned 29 BIC	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
HG-23 #1	} Cleaned at Tails	SH
HG-23 #2		
HG-23 #3		
HG-22 #1	cleaned on tail, trained Belt, Put Guard over Holdup Bearing	SH
HG-22 #2		

Refuge Chambers 6, 8, 9, 8 brk 2 sect. OK + phones working at time of exam  
0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0 ppm CO at time of exam

SIGNED BY: Scott Halstead 37567 John Bedford 26176  
Belt Examiners and Certificate Numbers  
Russell Dunmore 1536A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

[Signature] 32476

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 1-27-10 SHIFT: EVE AM OR PM TO 830 AM OR PM TO 1130 AM OR PM PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED, EXAMINER, PRE-SHIFT, COUNT SIGN, \*FIRE RUN. Rows include entries for BELTS like NORTH NO. 3-8, GLORY HOLE, and HGR NO. 1-3.

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

Handwritten remarks: OBC4, O6LO, 20, 8602. PC'S, Chargers, D-Boxes Travelways OK

SIGNED BY: Dan Miller 1539A Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Tony Moore 33359 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT  
EXAMINATION OF BELT CONVEYORS

DATE 1-27-10 SHIFT: EVE 600 AM OR PM 10830 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

checked out by Refugio 6-8-89 all ok

SIGNED BY: Don Williams 15304  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers  
COUNTERSIGNED BY Fay Moore 35359  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indellible Pencil or Ink

DATE 1-28-10 SHIFT: 0w1 AM OR PM TO 300 AM OR PM TO 600 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom SKAGGS Time \_\_\_\_\_ AM or PM

Report received by: Don Williams 15392  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Tail needs Add Cleaning	GU	—		
Ellis #5	4Bk - Head Needs spot cleaned	GU	—		
L/Wall	needs spot cleaned + dusted	JS	—		
NORTH NO. 3			—		
NORTH NO. 4	Takeup needs Add cleaning	GU	—		
NORTH NO. 5	None Observed	GU	—		
NORTH NO. 6	Needs spot cleaned 85-Tail	GU	—		
NORTH NO. 7	needs spot cleaned Head-Tail	JS	—		
NORTH NO. 8					
GLORY HOLE	D-Box + @ Pumps OK	JS	—		
HGA NO. 1	Belt needs spot cleaned Tail needs Add cleaning	JS	—		
HGA NO. 2	needs Dusted	JS	—		
HGA #1	needs spot cleaned	JS	—		
HGA #2	needs cleaned walkway side	JS	—		
HGA #3	hd needs cleaned + dusted	JS	—		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OBCHY OB CO 2018602

PC'S, Pumps, Chargers, Travelers OK

SIGNED BY: Don Williams 15392

Belt Examiners and Certificate Numbers

33476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY Tony Moore 33389

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-28-10 SHIFT: OW | 1130 AM OR TO 300 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
E115#4	cleaned V-Plow change rolls L.C.	GU
E115#5	cleaned V-Plow change rolls L.C.	GU
	change rolls L.C.	
NORTH 3		
NORTH 4	change rolls L.C.	
NORTH 5	cleaned Flaw throw change rolls L.C.	GU
NORTH 6	cleaned Flaw throw	GU
NORTH 7		
NORTH 8		
GLORY HOLE		
NO. 1		
NO. 2		
H633#1	SHOULDER U-Plow	
H633#2	TAIL SHOULDER REPLACE TOP SADDLE & BOTTOM ROLLER	JS

checked out by Rd GCS 6-8-89 all ok

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers 32476  
[Signature] 3276  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
Mine Foreman Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-28-10 SHIFT: DAY AM OR PM TO 12 AM OR PM TO 3 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:20 AM or PM

Report received by: M Kilburn  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Tail Area Needs Add Cleaning	MK	<input checked="" type="checkbox"/>		
Ellis #5	4 BRK-head needs Spot Cleaned	MK	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	TAKE UP Needs Add Cleaning	MK	<input checked="" type="checkbox"/>		
NORTH NO. 5	None observed	MK	<input checked="" type="checkbox"/>		
NORTH NO. 6	Needs Spot Cleaned 85-TAIL	MK	<input checked="" type="checkbox"/>		
NORTH NO. 7	Needs Spot Cleaned Head to tail CO AS BR. Mark.	SH	<input checked="" type="checkbox"/>		
Long Walk	Needs Spot Cleaned & Dusted	SH	<input checked="" type="checkbox"/>		
GLORY HOLE	PC & Pumps OK	JAB	<input checked="" type="checkbox"/>		
LBB NO. 1					
LBB NO. 2					
HG 23 #1	Needs Spot Cleaned & Cleaned at Air lock	JAB	<input checked="" type="checkbox"/>		
" #2	Needs Cleaned w/wayside Tail need clean	JAB	<input checked="" type="checkbox"/>		
" #3	Needs Cleaned at Head & Tail	JAB	<input checked="" type="checkbox"/>		
HG 22 #1	Some Spot Cleaning needed, tail needs Add Cleaning	SH	<input checked="" type="checkbox"/>		
HG 22 #2	Needs Dusted	SH	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% Chy 20.9% O2 0% CO detected At Exam  
Power Boxes, D-Boxes, Chargers, Pumps OK  
Visual OK CO Monitors OK

Don Allen 15388

SIGNED BY: M Kilburn 33017 Scott Holstead 37567  
 Belt Examiners and Certificate Numbers

John Bickford 26172  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Troy Moore 33359 Superintendent Certificate No.  
 Mine Foreman

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 1-28-10 SHIFT: DAY 6 <sup>AM OR PM</sup> TO 3 <sup>AM OR PM</sup>  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
Ellis #4		
Ellis #5	cleaned & greased tail, cleaned on takeup (Bobby + Corey)	
NORTH 2		
NORTH 3		
NORTH 4	change roller LC	
NORTH 5		
NORTH 6	change roller LC	
NORTH 7	cleaned AT HEAD AREA	MK
Long Wall	Cleaned Spillage at Discharge, Dusted DRIVE, cleaned on 29BR	SH
GLORY HOLE		
HE 23 LBB NO. 1	cleaned at tail	JAB
HE 23 LBB NO. 2	cleaned at tail	JAB
HG 22 # 1	cleaned at Discharge, Dusted BRK overcast & DRIVE, cleaned on tail	SH

# 2 section 8 BRK Refuge OK Phone working  
7 BRK Refuge OK Phone working  
8 BRK Refuge OK Phone working

SIGNED BY: Mark Kibler 33017 Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
John R. Buford 26171 John De 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Tony Moore 33389 \_\_\_\_\_  
Mine Foreman Certificate No. Superintendent Certificate No.