

Started 2-13-10

Finished 2-28-10

# EXAMINATION OF BELT CONVEYORS

COMPANY PERFORMANCE COAL

MINE UBB

LOCATION NAOMA Raleigh WV  
Post Office County State

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 2-13-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:30 AM or PM

Report received by: Russell Dunmore  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs Dusted</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>Ellis 5</u>	<u>Needs Dusted</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Needs spot cleaned 4-16, Take-up needs odd cleaning</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>None Observed</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>None Observed</u>	<u>RG</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>Idle, P.C. Pump</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>Longwall</u>	<u>Needs Spot Cleaned &amp; Dusted</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>D-Box &amp; Pump OK</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>LBB NO. 1</u>					
<u>HG-22 #1</u>	<u>Needs Some Spot Cleaning, Head needs Cleaned</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-22 #2</u>	<u>Needs Spot Cleaned &amp; Dusted</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>HG-23 #1</u>	<u>Out of service</u>		<input checked="" type="checkbox"/>		
<u>HG-23 #2</u>	<u>Out of service</u>	<u>Trench PC's &amp; Chargers OK</u>	<input checked="" type="checkbox"/>		
<u>HG-23 #3</u>	<u>Out of service</u>		<u>JAB</u>	<input checked="" type="checkbox"/>	

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO at time of exam  
Travellways, powercenters, D-Boxes, chargers clear at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Dunmore 1536-A Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
John Bickford 26176 Dan White 1539A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Tony Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

William L. McNeill, V.P. SCHA

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-13-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<del>Ellis</del> 4	Greased & Cleaned on tail (Bobby + Korney)	RG
Ellis 5	shoveled v-plow, cleaned from 26-29BK, greased & cleaned (Bobby Korney)	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, Run duster at Tail + Drive	RG
NORTH 5	cleaned on Tail + Flow-Thru, RAN duster at Flow-Thru	RG
NORTH 6	shoveled v-plow, cleaned at Tail	SAK RG
NORTH 7		
Longman 11	Cleaned Mud + Water at Head, Cleaned at Box CK, cleaned at 29BK	SH
GLORY HOLE		
LBB NO. 1		
HG-22 #1	cleaned V-Plow	SH
HG-22 #2		

Refuge chambers at 6, 8, 8 bak 2 sect. OK + phones working at time of exam  
0% CH4, 20.8% O2, 0ppm CO at time of exam

SIGNED BY: Russell Gunnell 1536-A Scott Halatend 37567  
Belt Examiners and Certificate Numbers  
Joseph Budjed 26172 Dean Miller 1597A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Tony Moore 33359 Superintendent  
Mine Foreman Certificate No. Superintendent Certificate No.

William Cumbebell 1354A

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-13-10 SHIFT: EVE AM OR PM TO 830 AM OR PM TO 1130 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Cambe II Time 1100 AM or PM

Report received by: Don Williams  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
EHS #4	needs Dusted	GU	/		
EHS #5	needs Dusted	GU	/		
L/Wall	needs spot cleaned & dusted	WC	/		
NORTH NO. 3					
NORTH NO. 4	Take up needs Add cleaning / Hd. wet and muddy / 4:16 Bnk. Needs spot cleaned	GU	/		
NORTH NO. 5	none observed	GU	/		
NORTH NO. 6	none observed	WC	/		
NORTH NO. 7	Idle PC's, Chargers OK	GU	/		
NORTH NO. 8					
GLORY HOLE	D-Box & Pump OK	GU	/		
H622 NO. 1	needs spot cleaned Hd needs cleaned	WC	/		
H622 NO. 2	needs spot cleaned & Dusted	WC	/		
H623 #1	Belts Idle } Track & PC & Chargers OK	GU	/		
H623 #2		GU	/		
H623 #3		GU	/		
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

02CH4, 02CO, 208202  
PC's, Chargers, D-Boxes, Pumps and TraveLways OK

SIGNED BY: Don Williams 15794  
 Belt Examiners and Certificate Numbers  
William Campbell 1354A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-13-10 SHIFT: EVE 600 AM OR PM TO 830 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No X By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4	Cleaned V-plow	GU
Ellis #5	Cleaned V-plow	GU
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned V-plow	GU
NORTH 6	Shoveled V-plow	BC
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1	Shoveled out tail	BC
LBB NO. 2		

Checked out by Refuges 6-8-89 all ok

SIGNED BY: William Campbell 1354A  
Belt Examiners and Certificate Numbers

Don Williams 1539C  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Tracy Moore  
Mine Foreman

33359  
Certificate No.

Superintendent

Certificate No.

**PRE-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-11-10 SHIFT: owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM

**ON-SHIFT EXAM.**

**PRE-SHIFT EXAM.**

Was this report phoned to outside Yes No X By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs Ousted	GU	✓		
Ellis #5	Needs Ousted	GU	✓		
Longwell	needs spot cleaned & dusted. Flanthrow needs additional	WC	✓		
NORTH NO. 4	needs spot cleaned 4-16Bk / Hd-wat & mddy / Takeup needs add cleaning	GU	✓		
NORTH NO. 5	none observed	GU	✓		
NORTH NO. 6	none observed	WC	✓		
NORTH NO. 7	Idle PC's Chargers OK	GU	✓		
GLORY HOLE	D-Box + Pumps OK	GU	✓		
H622 NO. 1	need spot cleaned, Hd needs cleaned	WC	✓		
H622 NO. 2	needs spot cleaned - dusted / 15hrk water over Boots,	WC	✓		
H623 #1	Belts Idle } PC's, Chargers, Track OK at TOC	GU	✓		
H623 #2		GU	✓		
H623 #3		GU	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OT 4 0% CO 20.8% O<sub>2</sub>

PC's, Chargers, Track, Travelways, Pumps all clear at time of exam

SIGNED BY: [Signature] 15394

Belt Examiners and Certificate Numbers

William Campbell 13547

Belt Examiners and Certificate Numbers

[Signature] 28045

COUNTERSIGNED BY: [Signature]

33359

Mine Foreman

Certificate No.

Superintendent

Certificate No.

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-14-10 SHIFT: 0w1 1130 AM OR PM TO 300 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4	Cleaned V-Plow change rolls LC	GU
Ellis #5	Cleaned Gob off change rolls LC	GU/LC
Blwall		
NORTH 4	Cleaned V-Plow	GU
NORTH 5	Cleaned V-Plow	GU
NORTH 6	Cleaned V-Plow	GU
NORTH 7		
GLORY HOLE		
H622 NO. 1	Cleaned V-plow	BC
H622 NO. 2		
H623 #1		
H623 #2		
H623 #3		

Checked out by Refuges 6-8-89 All OK

SIGNED BY: Dan Miller 15799  
 Belt Examiners and Certificate Numbers  
William Campbell 13547  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-14-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:30 AM or PM

Report received by: Russell Sumner  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>ENIS 4</del>	<del>Needs Dusted</del>	<del>RG</del>	<del>✓</del>		
<del>ENIS 5</del>	<del>Needs Dusted</del>	<del>RG</del>	<del>✓</del>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs Add. cleaning, needs spot cleaned 4-16	RG	✓		
NORTH NO. 5	None Observed	RG	✓		
NORTH NO. 6	None Observed	RG	✓		
NORTH NO. 7	Idle - PCs, charger OK	SH	✓		
NORTH NO. 8					
Longwall	Needs Spot Cleaned & Dusted	SH	✓		
LBB NO. 1					
HG-22 #1	Belt needs Spot Cleaned & Dusted, Head needs Cleaned	SH	✓		
HG-22 #2	Needs Spot Cleaned & Dusted	SH	✓		
HG-23 #1	Belts Idle - TRACK, PCs, chargers OK				
HG-23 #2	Belts Idle - TRACK, PCs, chargers OK				
HG-23 #3	Belt Idle - TRACK, PCs, chargers OK				

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO at time of exam  
Travelways, power centers, chargers, D-Boxes clear at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Sumner 1536-A Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
John Bickford 26176  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Meane 33559  
 Mine Foreman Certificate No. Superintendent Certificate No.



**ON-SHIFT  
EXAMINATION OF BELT CONVEYORS**

DATE 2-14-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled and Greased tail (Bobby + Corey)	
Ellis 5	Shoveled V-plow, Cleaned & Greased tail (Bobby + Corey)	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail	RG
NORTH 5	cleaned on Tail + Flow-Thru	SAB RG
NORTH 6	cleaned on Flow-Thru at old 1 section, cleaned on Tail	SAB RG
NORTH 7		
Longwall	cleaned Mud & Water	SA
GLORY HOLE		
LBB NO. 1		
HG-22 #1	cleaned V-plow	SH
HG-22 #2		

ReSuges 6, 8, 9, 8 brk 2 section OK + phones working at time of exam  
0% CH4, 20.8% O2, 0ppm CO at time of exam

SIGNED BY: Russell Gump 1536-A Scott Holstead 37567  
 Belt Examiners and Certificate Numbers  
John H. Buford 26176  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 35259  
 Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-14-10 SHIFT: Even AM OR PM TO 9:00 AM OR PM TO 11:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Skaggs - Bill Campbell Time 1:00 AM or PM

Report received by: Shankha Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELLS 4	needs dusted	JS	✓		
ELLS 5	needs dusted	JS	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Takeup needs add. clean, needs spot dusted 4-16	BC	✓		
NORTH NO. 5	None observed	BC	✓		
NORTH NO. 6	None observed	BC	✓		
NORTH NO. 7	Idle PC, Charger OK	BC	✓		
NORTH NO. 8					
LW	31 BK needs cleaned outside spot dust Belt	TA	✓		
Headcat #1	Belt needs spot cleaned + dusted	RH	✓		
Headcat #2	Needs Spot Cleaned + Dusted	RH	✓		
Headcat #3	Beltside Track PC charger OK	JS	✓		
Hg 23 #2	Beltside Track PC charger OK	JS	✓		
Hg 23 #3	Beltside Track PC charger OK	JS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

**(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:**

OK CO 2018 on OTC14 Travelways and power Boxes. All clear at time of exam. visual checks at CO's good at time of exam

SIGNED BY: William Campbell 1354A  
 Belt Examiners and Certificate Numbers  
John Skaggs 32776  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
 Mine Foreman Certificate No.  
Rick Hutchins 37569  
 Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 7-14-10 SHIFT: EVE 6:00 AM OR PM TO 8:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	Shoveled V-plow	BC
NORTH 5	work on BELT would NOT STAY RUNNING, SHOVEL TAIL	JR
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
Eliss	Shoveled gabout at tail	BC/JS

Refuge, at 8, 6, 89 brks clear at Exam phones work

SIGNED BY: William Campbell 1354-A  
Belt Examiners and Certificate Numbers  
[Signature] 35476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. M. [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-15-10 SHIFT: Owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	GU	—		
Ellis 5	Needs Dusted	GU	—		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs TAKEUP needs add cleaning spot cleaned 4-1681K	GU	—		
NORTH NO. 5	None observed	BC			
NORTH NO. 6	None observed	BC			
NORTH NO. 7	Idle	JS	✓		
<del>LONG WALL NORTH NO. 8</del>	NEED SPOT CLEAN & DUSTED	JS	✓		
GLORY HOLE	IDLE D-Box + Pump clear at Exam	BC	—		
LBB NO. 1					
LBB NO. 2					
H603 * 1	NEEDS SPOT CLEAN & DUSTED	JS	✓		
* 2	NEEDS SPOT CLEAN & DUSTED	JS	✓		
H603 * 1	BELTS, TRACK, PC O/S	JS	✓		
* 2	BELTS, TRACK,	JS	✓		
* 3	BELTS, TRACK	JS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

02064 0200 2018302  
POWER BOXES D-BOXES OK  
REFUGER BOXES OK

SIGNED BY: [Signature] 15394 [Signature] 13547A  
 Belt Examiners and Certificate Numbers  
[Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33354  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-15-10 SHIFT: 0w1 1130 AM OR PM TO 300 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
<del>SOUTH 1</del> <u>SOUTH 1 E1154</u>	<u>Cleaned v-plow</u>	<u>GU</u>
<u>NORTH 1 E1155</u>	<u>Cleaned v-plow</u>	<u>GU</u>
<u>NORTH 2</u>		
<u>NORTH 3</u>		
<u>NORTH 4</u>	<u>Cleaned v-plow</u>	<u>GU</u>
<u>NORTH 5</u>	<u>Shoveled flowthrough</u>	<u>BC</u>
<u>NORTH 6</u>	<u>Shoveled v-plow change roll LC</u>	<u>BC</u>
<u>NORTH 7</u>		
<u>NORTH 8 LWN1</u>	<u>change roll LC</u>	
<u>GLORY HOLE</u>		
<u>LBB NO. 1</u>		
<u>LBB NO. 2</u>		

(check out by Refuge #6 Brk GU)  
check out by Refuge #89 Brk all clear at Exam

SIGNED BY: [Signature] 15397A [Signature] 30476  
 Belt Examiners and Certificate Numbers  
William Campbell 1354-1A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357 Superintendent Certificate No.  
 Mine Foreman Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-15-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:30 AM or  PM

Report received by: Russell Sumner  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs spot cleaned & Dusted	RG	✓		
Ellis 5	Needs dusted, needs spot cleaned 27-Tail	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs add. cleaning, Needs spot cleaned 4-16	RG	✓		
NORTH NO. 5	None Observed	RG	✓		
NORTH NO. 6	None Observed	RG	✓		
NORTH NO. 7	Idle - Power centers + chargers OK	JAB	✓		
Longwall	Needs Spot Cleaned & Dusted	SH	✓		
GLORY HOLE	Idle - D-Box + pump OK	JAB			
LBB NO. 1					
HG-22 #1	Needs Spot Cleaned & Dusted	BH	✓		
HG-22 #2	Needs Spot Cleaned & Dusted	SH	✓		
HG-23 #1	Idle - TRACK, power centers, chargers OK	JAB	✓		
HG-23 #2	Idle - TRACK, power centers, chargers OK	JAB	✓		
HG-23 #3	Idle - TRACK, power centers, chargers OK	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub> ppm at time of exam  
Travelways, power centers, D-Boxes, chargers OK at time of exam  
Visual check of CO monitors at time of exam

SIGNED BY: Russell Sumner 1536-A Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
John Bickford 26171 J.D. [Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. [Signature] 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 2-15-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM

Report received by:       
 Signed     

BELTS	ACTION TAKEN	INT.
Ellis 4	shoveled & Greased tail (Bobby & Kroy)	
Ellis 5	shoveled V-plow (shoveled & Greased tail (Bobby & Kroy)	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, Ran dusters at Tail & Drive	RG
NORTH 5	cleaned on Tail	RG
NORTH 6	cleaned on Tail	RG
NORTH 7		
Longwall	cleaned under Drive Rollers, dusted Head, Greased Discharge, cleaned 29BK flow thru JAB	SH
GLORY HOLE		
LBB NO. 1		
HE 22	cleaned V-plow, cleaned under flow thru	SH

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0 ppm CO at time of exam  
 ReSuges at 6, 8, 9, 8 bek 2 section OK & phones working at time of exam

SIGNED BY: Russell Dunbar 1536-A Scott Holstad 37567  
 Belt Examiners and Certificate Numbers  
John B. Buckford 26171  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33354  
 Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-15-10 SHIFT: 2U AM OR PM TO AM OR PM 9:00 AM OR PM TO 11:30 AM OR PM  
**ON-SHIFT EXAM.** **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM     

Report received by:     

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>E115 #4</u>	<u>Needs Dusted + spot cleaned</u>	<u>BC</u>	<u>✓</u>		
<u>E115 #5</u>	<u>Needs Dusted needs cleaned from tail - 2 bck</u>	<u>BC</u>	<u>✓</u>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Needs spot cleaned from 4-11 bck Takeup needs cleaned</u>	<u>BC</u>	<u>✓</u>		
<u>NORTH NO. 5</u>	<u>None observed</u>				
<u>NORTH NO. 6</u>	<u>None observed</u>				
<u>NORTH NO. 7</u>	<u>Idle - Powercenter, D-Box + charger cleaned T.O.E.</u>	<u>BC</u>			
<u>Longwall</u>	<u>NEEDS DUST FROM MOTION DRIVE &amp; BY</u>	<u>JS</u>	<u>✓</u>		
<u>GLORY HOLE</u>	<u>Idle - D-Box, Pump cleaned at T.O.E.</u>	<u>BC</u>	<u>✓</u>		
<u>H622 #1</u>	<u>NEEDS spot clean FROM Tail OUTBY</u>	<u>JS</u>	<u>✓</u>		
<u>H622 #2</u>	<u>1 Bkt OUTBY NEEDS PAID BELT NEEDS CLEAN</u>	<u>JS</u>	<u>✓</u>		
<u>H623 #1</u>	<u>Idle Powercenter</u> <u>AND BELTS OK AT TIME OF EXAM</u>				
<u>H623 #2</u>					
<u>H623 #3</u>		<u>JS</u>	<u>✓</u>		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:     

0% CO, 0% CH4, 20.8% O2 Detected  
Powercenters, chargers, D-Box's, Pumps, Track/Travelways, on C.O's  
all clear at time of Exam

SIGNED BY: William Campbell 1354A  
 Belt Examiners and Certificate Numbers

[Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
 Mine Foreman

Certificate No.      Superintendent      Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS


DATE 2-15-70 SHIFT: LVE 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.


Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4	shoveled V-plow both sides	BC
Ellis #5	shoveled on tail	BC
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	shoveled both sides of flowthrough	BC
NORTH 6		
NORTH 7		
LONGWALL	shovel AT #18 B/W	JS
GLORY HOLE		
H622 #2	shovel AT HEAD	JS

REFUGE BOXES OK AT TIME OF EXAM.

SIGNED BY:  32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY:  33359  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 2-16-10 SHIFT: Owl AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No X By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>4715 #4</u>	<u>Needs Ousted</u>	<u>GU</u>	<u>-</u>		
<u>4715 #5</u>	<u>Needs Ousted, needs spot cleaned 27-Tail</u>	<u>GU</u>	<u>-</u>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Needs spot cleaned 4-16/11 / Take up nose &amp; add dirt</u>	<u>GU</u>	<u>-</u>		
NORTH NO. 5	<u>none observed</u>	<u>GU</u>	<u>-</u>		
NORTH NO. 6	<u>none observed</u>	<u>BC</u>	<u>✓</u>		
NORTH NO. 7	<u>none observed</u>	<u>BC</u>	<u>✓</u>		
<u>Jongwa #1</u>	<u>NEEDS DUSTED FROM MOTION DRINK INBY</u>	<u>JS</u>	<u>✓</u>		
GLORY HOLE	<u>IDIE, O-Box, Pump all clear</u>	<u>BC</u>	<u>✓</u>		
<u>HG88 #1</u>	<u>NEEDS SPOT CLEAN &amp; DUSTED</u>	<u>JS</u>	<u>✓</u>		
<u>HG88 #2</u>	<u>NEEDS CLEAN &amp; DUSTED</u>	<u>JS</u>	<u>✓</u>		
<u>4623 #1</u>	<u>SECTION ILLD LOWER CONTAINERS, CHARGERS</u>				
<u>4623 #2</u>		<u>JS</u>	<u>✓</u>		
<u>#3</u>		<u>O-BOXES OK AT TIME OF EXAM</u>	<u>JS</u>	<u>✓</u>	

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OG CHY OGCO 208202  
PC'S, CHARGES, TRUCKS OK  
PUMPS, O-BOXES OK

SIGNED BY: Don Miller 1539A J. [Signature] 32476  
 Belt Examiners and Certificate Numbers  
Will Campbell 1354A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33354  
 Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 2-16-10 SHIFT: owl 1130 AM OR PM TO 300 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include Elliss, NORTH 2-7, LMAH, and GLORY HOLE.

checked outby Refuges 6-8-89 OK
checked Intake Rooms OK

SIGNED BY: [Signatures] 1539A 32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 33759
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-16-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM  
Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ETHIS #4	Needs Dusted	MK	✓		
ETHIS #5	Needs Dusted Needs Spot Cleaned 27-Tail	MK	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Spot Cleaned 4-16 BRK TAKE UP needs Clean	MK	✓		
NORTH NO. 5	None Observed	RG	✓		
NORTH NO. 6	None Observed	RG	✓		
NORTH NO. 7	NONE OBSERVED	SH	✓		
Long walk	Needs Spot Cleaned & Dusted	RG	✓		
GLORY HOLE	Idle P.C. <sup>s</sup> , D-Box, Pump	SH	✓		
HG <sup>22</sup> #1	Needs Spot Cleaned & Dusted	SH	✓		
HG <sup>22</sup> #2	Needs Cleaned & Dusted	SH	✓		
HG <sup>23</sup> 1,2,3	Idle, P.C. <sup>s</sup> , Chargers, D-Box - Clear	SH	✓		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% Chy 2.0% O<sub>2</sub> 0% Co detected AT EXAM  
Power Boxes D-Boxes Pumps, Chargers,  
Visual CK CO Monitors OK

SIGNED BY: M. Kibilia 33017 Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
Russell Bruner 1536-19  
 Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY: T. Moore 23359  
 Mine Foreman Certificate No. Superintendent Certificate No.

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-16-10 SHIFT: Day 6 AM OR PM TO 3 AM OR PM AM OR PM TO \_\_\_\_\_ AM OR PM \_\_\_\_\_  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM \_\_\_\_\_

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1 #4	Cleaned tail + Greased (Bobby + Korey)	MK
NORTH 1 #5	Cleaned tail + Greased (Bobby + Korey)	MK
NORTH 2		
NORTH 3		
NORTH 4	Cleaned Mud At Tail	MIC
NORTH 5	Cleaned on Tail + Flow-Thru	RG
NORTH 6	Cleaned on Tail	RG
NORTH 7		
LONGWALL	Cleaned Box CK at BRK, CKd Splices, Did PM on Head	SH
GLORY HOLE		
HG 22 #1	Cleaned V-Plow	SH
HG 22 #2		

6 BRK Refuge OK Phone Working  
 89 BRK Refuge OK + phone working at time of exam  
 88K on 2 Section Refuge OK Phone Working at exam time

SIGNED BY: M. Kibler 33017 Scott Hulet 37567  
Belt Examiners and Certificate Numbers  
Russell Dunning 1536-A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-16-10 SHIFT: EVE AM OR PM TO AM OR PM 8:30 AM OR PM TO AM OR PM 11:30  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom SKAGGS Time 10:45 AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs Dusted	GU	✓		
Ellis #5	Needs Dusted, Needs spotcleaned 27-tail	JOU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spotcleaned 4-16 BKK Take-up needs cleaned	GU	✓		
NORTH NO. 5	NEEDS Dusted	GU	✓		
NORTH NO. 6	None Observed	BC	✓		
NORTH NO. 7	None Observed	BC	✓		
Longwall	Needs spot cleaned & Dusted	JS	✓		
GLORY HOLE	IDLE - D-Box, Pump - all clear at T.O.E.	BC	✓		
H622 NO. 1	Needs Spotcleaned & Dusted	JS			
H622 NO. 2	Needs Cleaned & Dusted	JS			
H623 #1	} IDLE, P.C's, Chargers, D-Box - clear at T.O.E.				
H623 #2		JS	✓		
H623 #3					
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> Detected

Track/Travelways, P.C's, D-Box's, Pumps, Chargers & visual check of CO's

SIGNED BY: William Campbell 13544

Belt Examiners and Certificate Numbers

Dlm 1330A  
Belt Examiners and Certificate Numbers

J. L. [Signature] 32476

COUNTERSIGNED BY T. M. [Signature]

33359

Mine Foreman

Certificate No.

Superintendent

Certificate No.

**ON-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-16-10 SHIFT: EVE 600 AM OR PM TO 830 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis#4	Cleaned V-Plow	GU
Ellis#5	Cleaned V-Plow	GU
NORTH 2		
NORTH 3		
NORTH 4	Cleaned V-Plow	GU
NORTH 5	Cleaned offsid Flow throw	GU
NORTH 6	shoveled V-Plow	BC
NORTH 7	Fixed mid point sprays on Head Drive	BC
Longwall		
GLORY HOLE		
H622 NO. 1		
H622 NO. 2		

Outby Refuges at 6, 8, 89 bit all clear and Phones work

SIGNED BY: William Campbell 1354A  
 Belt Examiners and Certificate Numbers

Don [Signature] 1579A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore  
 Mine Foreman

35354  
 Certificate No.

Superintendent

Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-17-10 SHIFT: owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ENIS #4	Needs Ousted	GV	✓		
ELLIS #5	needs set cleaned 29-Tail	GV	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 4-166C Takeup needs add cleaning	GV	✓		
NORTH NO. 5	Needs Ousted	GV	✓		
NORTH NO. 6	None Observed	BC	✓		
NORTH NO. 7	None Observed	BC	✓		
KONGWILL	Needs Ousted	JS	✓		
GLORY HOLE	IDLE, D-Box, Pumps cleared Exam	BC	✓		
H622 NO. 1	Needs spot clean & Ousted	JS	✓		
H622 NO. 2	Needs spot clean	JS	✓		
H623 #1	BELTS IDLE POWER CENTERS AND CHARGERS OK	JS	✓		
H623 #2		JS	✓		
H623 #3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

O<sub>2</sub> CH<sub>4</sub>, O<sub>2</sub> CO, 20.8% O<sub>2</sub> Detected

TRACK/TRAVELWAY, Pumps, D-Boxes, chargers, P.L's & all CO's clear  
cet Exam

SIGNED BY: William Campbell 1354-A [Signature] 32476  
Belt Examiners and Certificate Numbers  
Dan Williams 1529A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33589  
Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-17-10 SHIFT: owl 1130 AM OR ~~PM~~ TO 2:00 ~~AM~~ OR ~~PM~~ AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No X By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4		
Ellis #5	Pulled 3 Ribs on Truck & cleaned up	change roller LC
NORTH 2		
NORTH 3		
NORTH 4	needed Drive <del>roll</del> to feed some LC	
NORTH 5	Cleaned Tail and Flw throw	change roller LC
NORTH 6	shoveled Tail & v-plow	BC
NORTH 7	Ran pump at tail	BC
Longwall	change roller LC	
GLORY HOLE		
H622 NO. 1		
H622 NO. 2		
7 North Const	helped put 5 Foot structure in on new longwall belt	BC/GU

outby Refuge chambers at blk #6, 8, 89 Checked all clear & phones work

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers  
William Campbell 1354A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Munn 33359  
Mine Foreman Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-17-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:30 AM or PM

Report received by: Russell Gunnor  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs spot cleaned + Dusted	RG	✓		
Ellis 5	Needs dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 4-16, Take-up needs add. cleaning	RG	✓		
NORTH NO. 5	None Observed	RG	✓		
NORTH NO. 6	None Observed	RG	✓		
NORTH NO. 7	NONE OBSERVED	SH	✓		
Longwall	Needs Some Spot Cleaning + Dusted	SH	✓		
GLORY HOLE	Idle - D-Boxes + Pump OK				
LBB NO. 1					
HG-22 #1	Needs spot cleaned + Dusted <sup>Head needs cleaned</sup>	SH	✓		
HG-22 #2	Needs Spot Cleaned + <sup>spot</sup> Dusted	JAB	✓		
HG-23 #1	Idle - power centers, chargers, OK	JAB	✓		
HG-23 #2	Idle - power centers, chargers OK	JAB	✓		
HG-23 #3	Idle - power centers, chargers OK	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION), REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, Appx CO at time of exam  
Travelways, power centers, chargers, D-Boxes clear at time of exam  
Visual checks of CO monitors OK at time of exam

SIGNED BY: Russell Gunnor 1536-A Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
John Bickford 2617h Dylan Miller 1539h  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Manner 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

[Signature] 32476

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-17-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	cleaned & Greased tail (Bobby + Kopey)	
Ellis 5	shoveled v-plow, cleaned & Greased tail, cleaned from Head to 27 BK (Bobby Kopey)	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail	RG
NORTH 5	cleaned on Tail & Flow-Thru	RG
NORTH 6	Shoveled v-plow @ cleaned at Tail JAB	RG
NORTH 7		
Long Wall	cleaned Spillage at Head, Greased Drive & Storage, Dusted Drive and Storage AREA	SH JAB
GLORY HOLE		
LBB NO. 1		

Refuge chambers 6, 8, 9, 8 back 2 section OK & phones working at time of exam  
0% CH4, 20.8% O2, 0 ppm CO at time of exam

SIGNED BY: Russell Dunne 153617 Scotty Halstead 37567  
Belt Examiners and Certificate Numbers  
John Buehler 25171 Alan Miller 15399  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 35559  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 0-17-10 SHIFT: EVE AM OR PM TO 8:30 AM OR PM TO 11:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs spot cleaned & dusted	GU	✓		
Ellis #5	Needs Dusted	GU	✓		
Llewellyn	needs spot cleaned & dusted	JS	✓		
NORTH NO. 3					
NORTH NO. 4	needs spot cleaned 4'16" BK Take up Needs Add cleaning	GU	✓		
NORTH NO. 5	Needs Dusted	GU	✓		
NORTH NO. 6	Spillage walkway side 90-97 BK	GU	✓		
NORTH NO. 7	<del>PC's</del> <del>Chargers</del> <del>OK</del> none observed	JS	✓		
NORTH NO. 8					
GLORY HOLE	D-Box, Pump OK	JS	—		
H623 NO. 1	needs spot cleaned & dusted Tail needs ground	JS	—		
H623 NO. 2	needs spot cleaned & dusted	JS	—		
H623 #1	Belts Idle PC's, chargers OK	JS	—		
H623 #2					
H623 #3					
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

02064 0700 208202

PC's, Chargers, Trac, Pumps, D-Boxes, and CO's all clear AT TOE

SIGNED BY: Don Williams 15798 [Signature] 32476  
Belt Examiners and Certificate Numbers  
William Campbell 13842  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mene 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-17-10 SHIFT: EVE 600 AM OR PM TO 830 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4	cleaned v-plow	GU
Ellis #5	cleaned v-plow	GU
NORTH 3		
NORTH 4		
NORTH 5	cleaned v-plow	GU
NORTH 6	cleaned v-plow	GU
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

*Checked out by Refuges 6, 8, 89 all OK  
checked Intake Rooms all clear*

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 38359  
Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-18-10 SHIFT: Ow 7:00 AM OR PM TO 7:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
EN 5 4	cleaned U-Plow	GU
EN 5 5	cleaned U-Plow	GU
NORTH 2		
NORTH 3		
NORTH 4	3 men shoveling on 4 Brk (Dove; cody; chandy) change rolls L	GU
NORTH 5	shoveled on Flowthrough	BC
NORTH 6	change rolls L	
NORTH 7		
NORTH 8	LWALL change rolls L	
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Rotyer 6-8-89 all ok  
Checked intake rooms all clear

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 3359  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-18-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:30 AM or PM

Report received by: Russell Gunnore  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>Ellis 4</del>	<del>Needs Spot cleaned + Dusted</del>	<del>RG</del>	<del>✓</del>		
<del>Ellis 5</del>	<del>Needs Dusted</del>	<del>RG</del>	<del>✓</del>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 4-16, Take-up needs Add. cleaning	RG	✓		
NORTH NO. 5	None Observed	RG	✓		
NORTH NO. 6	Needs cleaned 90-97 13rk	RG	✓		
* NORTH NO. 7	None OBSERVED Look at Comments	SH	✓		
<del>Lam wall</del>	<del>Needs Spot Cleaned + Dusted</del>	<del>SH</del>	<del>✓</del>		
GLORY HOLE	Idle - D-Box + pump OK	JAB	✓		
LBB NO. 1					
HG-22 #1	Belt Needs Cleaned + Dusted	SK	✓		
HG-22 #2	Needs spot cleaned + Dusted	JAB			
HG-23 #1	Idle - power centers + chargers OK	JAB	✓		
HG-23 #2	Idle - power centers + chargers OK	JAB	✓		
HG-23 #3	Idle - power centers + chargers OK	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0 ppm CO at time of exam  
Travelways, power centers, D-Boxes, chargers clear at time of exam  
Visual check of CO monitors OK at time of exam

\* Top Center Roller on 7 North Belt, First Cradles out by tailpiece Needs Replaced.

SIGNED BY: Russell Gunnore 1536-A Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
John Bickford 26176 John Mann 1539A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Mann 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

John Mann 37576



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-18-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
ELLIS 4	(Shoveld tail & Greased tail) (Bobby)	
ELLIS-5	shoveled v-plow (shoveld tail & Greased tail) (Bobby)	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on Tail, Run Dusters at Tail + Drive	RG
NORTH 5	cleaned on Tail + Flow-Thru, Run Duster at Flow-Thru	RG
NORTH 6	Shoveled v-plow	RG
NORTH 7	cut String out of Rollers	SH
Long Wall	Cleaned under Discharge, cleaned Behind drive, cleaned Some at 49 BK	SH
GLORY HOLE		
LBB NO. 1		
HC <sup>22</sup> # 1	cleaned under Discharge, cleaned tailpiece	JAB SH

Refuge chambers 6, 8, 9, 8 bet 2 sections OK + phone working at time of exam  
0% ch4, 20.8% O2, 0ppm CO at time of exam

SIGNED BY: Russell Dunne 1536-1A Scott Hatfield 37567  
Belt Examiners and Certificate Numbers  
John A. Bedford 25176  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-18-10 SHIFT: EVE AM OR PM TO AM OR PM 830 AM OR PM TO 1130 AM OR PM   
**ON-SHIFT EXAM.** **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes  No  By Whom SHALLS Time  AM or PM

Report received by: Dan Miller  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>EL1874</u>	<u>needs spot cleaned &amp; dusted</u>	<u>GU</u>	<u>/</u>		
<u>EL1875</u>	<u>needs dusted</u>	<u>GU</u>	<u>/</u>		
<u>YH11</u>	<u>needs spot cleaned &amp; dusted</u>	<u>JS</u>	<u>/</u>		
NORTH NO. 3					
NORTH NO. 4	<u>needs spot cleaned 4-16 BK <sup>take up noise is cleaned</sup></u>	<u>GU</u>	<u>/</u>		
NORTH NO. 5	<u>none observed</u>	<u>GU</u>	<u>/</u>		
NORTH NO. 6	<u>needs cleaned - 90-97 BK</u>	<u>GU</u>	<u>/</u>		
NORTH NO. 7	<u>Idle PC's chargers OK</u>	<u>JS</u>	<u>/</u>		
NORTH NO. 8					
GLORY HOLE	<u>O-Box pumps OK</u>	<u>JS</u>	<u>/</u>		
<u>H2A</u> LBB NO. 1	<u>Belt needs cleaned &amp; dusted</u>	<u>JS</u>	<u>/</u>		
<u>H2A</u> LBB NO. 2	<u>needs spot cleaned &amp; dusted</u>	<u>JS</u>	<u>/</u>		
<u>H623#1</u>	<u>Idle PC's chargers OK</u>				
<u>H623#2</u>		<u>JS</u>	<u>/</u>		
<u>H623#3</u>					

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OB CHY OBCO 20,8262  
PC's, Chargers, O-Box, Travelers OK

SIGNED BY: Dan Miller 15399 John Jones 32476  
 Belt Examiners and Certificate Numbers  
William Campbell 13597A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2/8/70 SHIFT: EVE 600 AM OR PM TO 830 AM OR PM 8 AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Should trail greased tail Body	
Ellis 5	cleaned Tail (Gobbed off) Should trail greased tail Body	60
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges 6-889 OK

SIGNED BY: [Signature] 15397  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 73759  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-19-10 SHIFT: owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs spot cleaned & Dusted	BC	✓		
Ellis #5	needs Dusted	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	NEEDS spot cleaned from 4-17 brk take up head cleaned	BC	✓		
NORTH NO. 5	none observed	BC	✓		
NORTH NO. 6	needs cleaned from 90-97 brk	BC	✓		
NORTH NO. 7	IDLE P.C.'s D-Box clear at Exam	JS	✓		
Lowgwall	NEEDS CLEAN AT Air Lock	JS	✓		
GLORY HOLE	IDLE P.C.'s D-Box clear at Exam	JS	✓		
NO. 1	IDLE P.C.'s chargers clear at Exam	JS	✓		
NO. 2		JS	✓		
HG23#1	IDLE P.C.'s, chargers clear at Exam	JS	✓		
#2		JS	✓		
#3		JS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

20.89% O<sub>2</sub>, 0% CH<sub>4</sub>, 0% CO Detected at Exam

P.C.'s, chargers, CO's, D-BOX's, Pumps, TRACK/Travelways all clear at Exam

SIGNED BY: W. Campbell 13597

Belt Examiners and Certificate Numbers

[Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Name  
 Mine Foreman

33309  
 Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-19-10 SHIFT: Over 1130 ~~AM~~ <sup>PM</sup> TO 300 ~~AM~~ <sup>PM</sup> AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM     

Report received by:       
Signed

BELTS	ACTION TAKEN	INT.
Σ115#4	shoveled V plow	BC
Σ115#5	shoveled V plow + worked on water in walkway	BC
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	shoveled Flow through change roll LC	BC
NORTH 6	shoveled V plow	
NORTH 7	change roll LC	
Longwall	Helped Robbed Mother Drive change roll LC	BC
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Refuge Boxes 68, 89 OK AT TIME OF EXAM

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

SIGNED BY: William Campbell 1384-0  
 Belt Examiners and Certificate Numbers  
32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 3359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-19-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford Time 2:30 AM or  PM

Report received by: Russell Dunnoe  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs spot cleaned + Dusted	RG	✓		
Ellis 5	Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 4-17, Take-up needs additional cleaning	RG	✓		
NORTH NO. 5	None Observed	RG	✓		
NORTH NO. 6	Needs Cleaned from 90-97BK	SH	✓		
NORTH NO. 7	Idle - Power centers, D-Boxes, chargers OK	JAB	✓		
Longwall 11	Needs Spot Cleaned + Dusted	SH	✓		
GLORY HOLE	D-Box + Pump OK	JAB	✓		
LBB NO. 1					
HG-22 #1	IDLE P.C. Chargers	OK	✓		
HG-22 #2					
HG-23 1	Out of service - P.Cs, chargers OK at time of exam	JAB	✓		
HG-23 2	Out of service - P.Cs, chargers OK at time of exam	JAB	✓		
HG-23 3	Out of service - P.Cs, chargers OK at time of exam	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO at time of exam  
Travelsways, power centers, D-Boxes, chargers clear at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Dunnoe 1536-A John Bickford 2617A Scott Halstead 37567  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 37705 John Bickford 32176  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-19-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	shoveled tail & greased tail (Bobby)	
Ellis 5	shoveled v-plow (shoveled tail & greased tail (Bobby)	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, Ran dusters at Drives & Tail	RG
NORTH 5	cleaned on Tail & Flow-Thru, Ran Duster at Flow-Thru	RG
NORTH 6	cleaned V-Plow, cleaned at Flow, Thru	JAB SH
NORTH 7		
Longwell	cleaned spillage at Discharge, cleaned spillage at 29BK, Dusted Drive Area	JAB SH
GLORY HOLE		
LBB NO. 1		

Refuge Chambers at 6, 8, 8 back 2 sect. OK & phones working at time of exam  
0% CH4, 20.8% O2, Oppm CO at time of exam

SIGNED BY: Russell Gunnor 1536-19 Scott Whithead 37567  
Belt Examiners and Certificate Numbers  
John H. Beckford 26171  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-19-10 SHIFT: EVE AM OR PM TO AM OR PM 830 AM OR PM TO AM OR PM 1130  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4.1	Needs spot cleaned + Dusted	GU	✓		
Ellis #5	Needs Dusted	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Takeup Needs Add cleaning Needs spot cleaned 4-15 Brk	GU	✓		
NORTH NO. 5	None Observed	WC	✓		
NORTH NO. 6	Needs cleaned 90-97 Brk	WC	✓		
NORTH NO. 7	Idle PC's Charger OK	JS	✓		
Liwall	Needs spot cleaned + dusted	JS			
GLORY HOLE	D-Box - Pump OK	JS	✓		
HC22 #1	Idle PC's Chargers OK	JS	✓		
HC22 #2					
HC23 #1	Idle PC's Chargers OK				
HC23 #2		JS	✓		
HC23 #3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0764 0700 208202

PC'S, Chargers, D-Boxes, Track, Travelways all OK

SIGNED BY: Dan McInerney 15399 Walt Campbell 1354-2  
Belt Examiners and Certificate Numbers  
J.P. [Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 31357  
Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-19-10 SHIFT: EVE 600 AM OR PM TO 830 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4	Cleaned V-Plow	GU
Ellis #5	Cleaned V-Plow	GU
NORTH 2		
NORTH 3		
NORTH 4	cleaned from 16-15 Brk Cleaned V-Plow	GU
NORTH 5	Shoveled flowthrough Shoveled V-plow at tail	BC
NORTH 6	Shoveled v-plow	BC
NORTH 7		
Longwall	SHOVEL AT Air Lock.	GU
GLORY HOLE		

Checked outby Refuges 6-8-89 All OK

SIGNED BY: Don Williams 1539A  
Belt Examiners and Certificate Numbers  
Walter Campbell 13845  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M. ... 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-20-10 SHIFT: ow | AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs spot cleaned from 39 - punch belt needs dusted	GV	✓		
Ellis #5	needs dusted	GV	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs cleaned from 15-4 Brk Takeup needs Add cleaning	GV	✓		
NORTH NO. 5	None observed	WG	—		
NORTH NO. 6	Needs cleaned 90-97 Brk	WG	—		
NORTH NO. 7	Idle PC's Chargers ok	RWG	—		
<del>Ellis #2</del>	needs spot cleaned & dusted	JS	—		
GLORY HOLE	O-Box Pump ok				
H622.1	Idle PC's CHARGES OK	JS	—		
H622.2		JS	—		
H623.1					
H623.2	Belts Idle PC's CHARGES OK	JS	—		
H623.3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OG CH4 OBCA 2018602  
PC'S Chargers, O-Boxes, Travel ways OK

SIGNED BY: [Signature] 15394 [Signature] 13541A  
Belt Examiners and Certificate Numbers

[Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33354  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-20-10 SHIFT: owl 1130 AM OR PM TO 300 AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4	Cleaned From Tail-GRAB (Glen, Billy, John) change walk LL	GU JS
Ellis #5	Cleaned V-Plow	
NORTH 2		
NORTH 3		
NORTH 4	cleaned 16-15 BCK	CU
NORTH 5	Shoveled V-plow both sides	BC
NORTH 6	Shoveled V-plow	BC
NORTH 7	change walk impact LL	
Longwall	SHOVEL AT Airlocks, change walk LL Top 2432-17	JS
GLORY HOLE		

Checked out by Refuges 6-8-89 all OK

---



---



---



---



---



---



---



---



---

SIGNED BY: John Miller 15394 John [Signature] 32476  
Belt Examiners and Certificate Numbers  
William Campbell 18544  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 39359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-20-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom S. Halstead, S. Neely Time 2:10 AM or PM

Report received by: John R. Beckford  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs dusted, Needs spilt cleaned 88 to draft</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>Ellis 5</u>	<u>Needs dusted</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Needs cleaned 4 to 15 feet. Tail needs add'l cleaning</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>None Observed</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>90 to 97 Needs cleaned</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>PC's &amp; Changers OK</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>WALL</u>	<u>Needs spilt cleaned &amp; dusted. Needs extra cleaning off side 29</u>	<u>SH</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>D'Box Pump OK</u>	<u>JN</u>	<input checked="" type="checkbox"/>		
<u>HG 22 #1</u>	} <u>Idle</u>				
<u>HG 22 #2</u>					
<u>HG 23 #1</u>	} <u>Idle, PC's &amp; Changers OK</u>				
<u>HG 23 #2</u>		<u>JN</u>	<input checked="" type="checkbox"/>		
<u>HG 23 #3</u>					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% ch4 0% CO + 20.8% O2 detected at time of exam

Power Centers, track, travelways, chagers, D'Boxes & Pumps clear at time of exam

Visual check of CO's - OK

SIGNED BY: John R. Beckford 26176 Belt Examiners and Certificate Numbers  
Scott Halstead 375167  
Johnny Neely 33472

COUNTERSIGNED BY: T. Moore Mine Foreman  
33357 Certificate No.  
Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 2-20-10 SHIFT: Day AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM TO  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include Ellis 4, Ellis 5, NORTH 2-7, Long Wall, GLORY HOLE.

Checked Refuges at 6, 8 + 89 Belts - OK Phones OK

SIGNED BY: John A. Beckford 26176 Scott Holstad 37567

COUNTERSIGNED BY: T. Moore 33339 Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-20-10 SHIFT: EUE AM OR PM TO AM OR PM 8:00 AM OR PM TO 11:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Campbell Time 1100 AM or PM

Report received by: Dan Ullman  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
E1118#4	Needs Ousted need spot cleaned 98-Punchout	GU	✓		
E1115#5	needs Ousted	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Cleaned 4 to 15 BK Tail needs Add Cleaning	GU	✓		
NORTH NO. 5	none observed	GU	✓		
NORTH NO. 6	90-97 BK needs cleaned & dusted	BC	✓		
NORTH NO. 7	none observed	BC	✓		
<del>100-102</del>	needs spot cleaned & dusted	BC	✓		
GLORY HOLE	D-Box Pumps OK IDLE	BC	✓		
H622#1	Idle PC's Chargers all clear	BC	✓		
H622#2			✓		
H623#1	Idle PC's Chargers OK	GU	✓		
H623#2	Idle PC's Chargers OK	GU	✓		
H623#3	Idle PC's Chargers OK	GU	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OF CH4 OF CO 20090<sup>2</sup> Detected

Power centers, Pumps, TRACK / TRAU DWAYS, chargers, D-Box's & CO's  
cell clear at Exam

SIGNED BY: Dan Ullman 1539A  
 Belt Examiners and Certificate Numbers  
William Campbell 1354A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE: 2-20-10 SHIFT: EVS 6:00 AM OR PM TO 8:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
Ellist#4		
Ellist#5	Cleaned V-Plow	BU
NORTH 2		
NORTH 3		
NORTH 4	Cleaned V-Plow	BU
NORTH 5	Cleaned V-Plow	BU
NORTH 6	Cleaned V-plow	BC
NORTH 7		
Henrywell		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Outby Refuge chambers at brk#6, 8, 89 All clean at Examt phones work all OK

SIGNED BY: Alan Miller 1539A  
Belt Examiners and Certificate Numbers  
William Campbell 1354-1A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 3339  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-2-10 SHIFT: owl 1130 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs Ousted / needs cleaned 98-Punchout	GU	/		
Ellis #5	needs Ousted	GU	/		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Talk up needs Add. cleaning <sup>needs cleaned 4-15 Brk</sup>	GU	/		
NORTH NO. 5	None Observed	GU	/		
NORTH NO. 6	90-97 Brk needs cleaned / needs ousted	WC	/		
NORTH NO. 7	Idle PC charges OK	WC	/		
<del>Horizon</del>	needs spot cleaned / ousted	WC	/		
GLORY HOLE	Idle D-Box + Pump clear at Exam	WC	✓		
H622#1	Idle PC'S Charges OK	WC	/		
H622#2					
H623#1	Idle PC, Charges OK	GU	/		
H623#2					
H623#3					

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0% CH4 , CO 0% , O<sup>2</sup> 20.8% Detected

Power center, Pumps, Track/Traveldways, chargers, D-Box & CO'S  
all - clear at Exam

SIGNED BY: Don Miller 1537A Johnny Neely 33472  
 Belt Examiners and Certificate Numbers  
Walter Campbell 1354A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33389  
 Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

### ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-21-10 SHIFT: owl 11:30 AM OR PM TO 3:00 AM OR PM  
**ON-SHIFT EXAM.** PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<u>Schiff #4</u>	<u>cleaned U-Plow</u>	
<u>Schiff #5</u>	<u>cleaned U-Plow</u>	
<b>NORTH 2</b>		
<b>NORTH 3</b>		
<b>NORTH 4</b>		
<b>NORTH 5</b>	<u>cleaned J-Plow</u>	
<b>NORTH 6</b>		
<b>NORTH 7</b>		
<u>Longwall</u> <u>North 1A</u>		
<b>GLORY HOLE</b>		

Out by Refuge chambers, at 8, 6, 89 bck are all clear at time of Exam  
and phones work

**SIGNED BY:** Pete Miller 1530A  
Belt Examiners and Certificate Numbers  
William Campbell 1350A  
Belt Examiners and Certificate Numbers

**COUNTERSIGNED BY:** T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 2-21-10 SHIFT: Day AM OR PM TO 1200 AM OR PM TO 300 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom S. Neely Time 225 AM or PM

Report received by: John A. Bickford  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs dusted, Needs cleaned 98 to Punch out</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
<u>Ellis 5</u>	<u>Needs dusted</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>4-13 needs cleaned, Needs cleaned at Overcat Tail &amp; take-up needs add'l cleaning</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>None Observed</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>Needs dusted, 90-97 Needs cleaned</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>Idle PC's &amp; chargers OK</u>	<u>SN</u>	<input checked="" type="checkbox"/>		
<u>Lg. Wall</u>	<u>Needs spot cleaned &amp; dusted</u>	<u>SN</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>	<u>Idle, Pump &amp; D'Box OK</u>	<u>SN</u>	<input checked="" type="checkbox"/>		
<u>HG 22 #1</u>	} <u>Idle PC's OK</u>	<u>SN</u>	<input checked="" type="checkbox"/>		
<u>HG 22 NO. 2</u>					
<u>HG 23 #1</u>	} <u>Idle, PC's &amp; chargers OK</u>	<u>SN</u>	<input checked="" type="checkbox"/>		
<u>HG 23 #2</u>					
<u>HG 23 #3</u>					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4 0% CO & 20.8 % O2 detected at time of exam

Power Centers, Chargers, D'Boxes, & Track & Pumps clean at time of exam

SIGNED BY: John A. Bickford 26176 John Neely 33472  
 Belt Examiners and Certificate Numbers  
John Neely 33472 William Campbell 135476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359 [Signature] 332476  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-21-10 SHIFT: Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
ELLIS SOUTH-1 4	Cleaned at V-Plow	JAB
ELLIS NORTH-1 5	Cleaned at V-Plow	JAB
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned at Tail & Flow thru	JN, JAB
NORTH 6	Cleaned at flow thru & tail	JN, JAB
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

*Checked Refuges 6, 8 & 89 Belts OK, Phones OK*

SIGNED BY: John A. Bullard 2176  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33857  
Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-21-10 SHIFT: EVS AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis#4	cleaned on tail <del>(tail)</del> cleaned on tail & GR-4504 Tail/Bobby	BC
Ellis#5	(cleaned on tail & GR-4504 Tail/Bobby)	
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
GLORY HOLE		

*Outby Refuge chambers at bks #6, 8, 89, all clear at Exam & phones  
work in Refuge chambers*

SIGNED BY: William Campbell 135412 JL [Signature] 32476  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-22-10 SHIFT: 0W2 AM OR PM TO 3:00 AM OR PM TO 6:30 AM OR PM TO 6:30 AM OR PM TO 6:30

**ON-SHIFT EXAM.** **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM \_\_\_\_\_

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>2115* 41</u>	<u>NEEDS CLEAN 98 BANK TO AIRLOCK &amp; DUST</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>2115* 5</u>	<u>NEEDS SPOT &amp; CLEAN &amp; DUSTED</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>4 BANK-17 BANK NEEDS CLEAN &amp; DUSTED</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>NONE OBSERVED</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>NEEDS DUSTED 90-97 BANK NEEDS CLEAN</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>NEEDS DUSTED AT HEAD</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>LONGWALL</u>	<u>NEEDS DUSTED MAINWALKING TO 2 BANK <sup>AIRLOCK</sup> QUAY</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>GLORY HOLE</u>					
<u>H622* 1</u>	<u>IDLE, PC, D-BOXES OK.</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u>H622* 2</u>		<u>JS</u>	<input checked="" type="checkbox"/>		
<u>H623* 1</u>	<u>SECTION IDLE.</u>	<u>JS</u>	<input checked="" type="checkbox"/>		
<u># 2</u>		<u>JS</u>	<input checked="" type="checkbox"/>		
<u># 3</u>		<u>POWER CENTER OK AT TIME OF EXAM</u>			

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub> 0% CO 20.9% O<sub>2</sub> AT TIME OF EXAM

TRAILWAYS & TRACK OK AT TIME OF EXAM

SIGNED BY: [Signature] 32476

Belt Examiners and Certificate Numbers  
William Campbell 1354A

Johnny Peely 33472

COUNTERSIGNED BY T. Moore Mine Foreman

33359 Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-22-10 SHIFT: owl 11:30 AM OR PM TO 300 AM OR PM

ON-SHIFT EXAM.

AM OR PM TO AM OR PM

PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM

Report received by:       
Signed     

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1	<u>5 Ellis change with bc.</u>	
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7	<u>work on input roll, need more change bc</u>	
NORTH 8		
GLORY HOLE	<u>LW #11 change roll bc. Top</u>	
LBB NO. 1		
LBB NO. 2		
<u>Ellis #4</u>	<u>shoveled on 98 brk</u>	<u>BC/JS</u>

Outby Refuges at 6, 8, 89, brks all clear at Exam - phones work

SIGNED BY: *Walter Campbell* 135412  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *T. Moore*  
Mine Foreman

33354  
Certificate No.

Superintendent

Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indefinite Pencil or Ink

DATE 2-22-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM PRE-SHIFT EXAM.  
ON-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Neely Time 2:40 AM or PM

Report received by: Russell Gunnor  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs cleaned 98 to Airlock, needs Dusted	RG	✓		
Ellis 5	Needs spot clean + Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 4-15, Take-up needs Add. cleaning	RG	✓		
NORTH NO. 5	None Observed	RG	✓		
NORTH NO. 6	Needs spot cleaned 90-97 brk, Needs Dusted	RG	✓		
NORTH NO. 7	Idle - power centers + Chargers OK	JN	✓		
Long wall	Needs Some Spot Cleaning, added Dusting	SH	✓		
GLORY HOLE	D-Box + pump OK	JN	✓		
LBB NO. 1					
HG-22 #1					
HG-22 #2					
HG-23 #1	Section Idle - P.C. <sup>s</sup> OK at Exam				
HG-23 #2		SH	✓		
HG-23 #3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO at time of exam  
Travelways, Power Centers, D-Boxes, chargers OK at time of exam  
Visual check of CO monitors at time of exam

SIGNED BY: Russell Gunnor 1536-1A  
Belt Examiners and Certificate Numbers

Scott Halstead 37567  
Johnny Neely 33472

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Certificate No.

Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-22-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis - 4	shoveled & Greased tail ) Bobby	
Ellis - 5	shoveled v-plow (shoveled & Greased tail) Bobby	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail	RG
NORTH 5	cleaned on Tail + Flow-Thru,	RG
NORTH 6	changed Bottom Roller at Flowthru Grease & Tail CLEAN ON TAIL	SH
NORTH 7	DUST FROM HEAD TO TAKEUP	
Long Walk	Dusted Mother drive, cleaned Box CK, cleaned at USBK	SH
GLORY HOLE		
LBB NO. 1		

Refuse chambers at 6, 8, 9, 8, 6, 2, 2, 0, 0, K at time of exam  
0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0 ppm CO at time of exam

SIGNED BY: Russell Guinn 1536-19  
Belt Examiners and Certificate Numbers

Scott Halstead 37567  
Johnny Deely 33472

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No.

Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-22-10 SHIFT: LUE AM OR PM TO 8:00 AM OR PM TO 11:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<del>EL115*51</del>	NEEDS CLEAN 98 BALK TO OUTSIDE & DUSTED	BC	✓		
<del>EL115*50</del>	NEEDS SPOT CLEAN & DUSTED	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	NEEDS SPOT CLEAN 4-15, TAKE UP NEEDS CLEAN	BC	✓		
NORTH NO. 5	WORK OBSERVED	BC	✓		
NORTH NO. 6	NEEDS SPOT CLEAN 90, 97 BALK NEEDS DUSTED	BC	✓		
NORTH NO. 7	IDIR CONSTRUCTION POWER CENTER & D-BOX CLEAR	JS/BC	✓		
<del>KONGWALK</del>	NEEDS SPOT CLEAN & DUSTED	JS	✓		
GLORY HOLE	D-Box, Pump OK.	JS	✓		
H622*1	SECTION IDIR	JS	✓		
H622*2		JS	✓		
H623*1	SECTION IDIR				
H623*2		JS	✓		
H623*3					

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4 0% CO 20.8% O2 AT TIME OF EXAM  
TRAVELWAYS & TRACK OK AT TIME OF EXAM

SIGNED BY: [Signature] 32476  
 Belt Examiners and Certificate Numbers  
[Signature] 1354A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M... 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.





Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-23-10 SHIFT: owl 11:30 AM OR ~~PM~~ TO 3:00 ~~AM~~ OR PM AM OR ~~PM~~ TO AM OR ~~PM~~

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
Ellis #4	Shoveled v-plow	BC
Ellis #5	change roll 15BL Better 17 21 26 Top LC	
NORTH 2		
NORTH 3		
NORTH 4	Cleaned 4 worth tail	BC/US
NORTH 5	Shoveled v-plow at Flowthrough	BC
NORTH 6		
NORTH 7	change roll <sup>Top</sup> scrub on belt run off LC	
Longcell	change rolls LC	
GLORY HOLE		

SIGNED BY: William Campbell 1354  
 Belt Examiners and Certificate Numbers  
J. L. Moore 32426  
 Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY T. Moore 32557  
 Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 2-23-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Neely Time 2:40 AM or  PM

Report received by: Russell Gunnor  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	FIRE RUN
Ellis 4	Needs Dusted, Needs spot clean 98 to outside	RG	✓		
Ellis 5	Needs Dusted, Needs spot cleaned 3-5 BRK	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned Discharge to 15 BRK	RG	✓		
NORTH NO. 5	None Observed	RG	✓		
NORTH NO. 6	Needs dusted	RG	✓		
NORTH NO. 7	NONE OBSERVED	SH	✓		
Longwall	Needs Some Spot Cleaning	SH	✓		
GLORY HOLE	D-Box + Pump OK				
HG 23 #1	Needs Some Spot Cleaning, and added Dusting	SH	✓		
HG-23 1	} TRACK + Power Centers OK				
HG-23 2					
HG-23 3					
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO at time of exam  
Travelways, power centers, D-Boxes, chargers clear at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gunnor 1536-A Scott H. Lynd 37562  
 Examiners and Certificate Numbers  
John Neely 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M. ... 37359 Superintendent ... Certificate No. ...  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-23-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled & Greased Tail (Bobby Kory)	
Ellis 5	Shoveled V-plow (Shoveled & Greased Tail) Bobby Kory	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on Tail, Ran Duster at Tail	RG
NORTH 5	Cleaned on Tail + Flow-Thru, Ran Dusters at Tail + Flow Thru	RG
NORTH 6	Shoveled V-plow	
NORTH 7	clean on tail Got Firehose out of Cab & hung up	JN
Longwall	cleaned V-Plow at flow thru, Greased Discharge & DRIVE	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0 ppm CO at time of exam  
Resuge chamber 6, 8, 9, 8 1/2 ok clear at time of exam & phones working

SIGNED BY: Russell Sumner 1536-A  
Belt Examiners and Certificate Numbers

Scott Habstead 37567  
Johnny Dooly

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore  
Mine Foreman

35354  
Certificate No.

Superintendent

Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-23-10 SHIFT: EVE AM OR PM TO 800 AM OR PM TO 1100 AM OR PM AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ells 4	Needs Dusted, needs spot cleaned 98' Ontt	WC	✓		
Ells 5	Needs Dusted, needs spot cleaned 3-SBK	WC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 15' Discharge	GU/WC	✓		
NORTH NO. 5	None observed	GU	-		
NORTH NO. 6	Need Dusted	GU	-		
NORTH NO. 7	need 2 Jack set at 128 BK	GU	-		
Lafayette	Needs Some Spot cleaned	JS	-		
GLORY HOLE	D-Box P Pump OK	GU	-		
H622#1	needs spot cleaned + dusted	JS	-		
H623#1	Track, Power Center OK				
H623#2		JS	-		
H623#3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OFCH4, OGCO, 208202

PLS, Chargers, Travelways OK

SIGNED BY: [Signature] 1539A Willie Campbell 1384-10  
 Belt Examiners and Certificate Numbers  
[Signature] 32476  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.



ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 2-28-10 SHIFT: ENE 600 AM OR PM TO 800 AM OR PM ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2, and entries for 11.5#4 and 11.5#5 with 'Shovelled v plow' and 'BC' markings.

Checked out by Refuges 6-8-89 a110K

SIGNED BY: [Signature] 15399 Belt Examiners and Certificate Numbers [Signature] Complex Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] Mine Foreman 33389 Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-24-70 SHIFT: Ow 1 AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes Not By Whom Brought out Time          AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs spot cleaned from 98BK - Dnt / vents Ousted	GU			
Ellis #5	needs Ousted, needs spot cleaned 3-5BK	GU	-		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs spot cleaned 12BK - Hd	GU			
NORTH NO. 5	none observed	GU	-		
NORTH NO. 6	needs dusted	BC			
NORTH NO. 7	needs 2 Jacks SE+ at 128BK-	BC	✓		
LONG WALL	NEED spot clean & DUSTED	JS	✓		
GLORY HOLE					
HG #21	NEED SPOT CLEAN & DUSTED	JS	✓		
HG #27	} IDIK SECTION	JS	✓		
*2		JS	✓		
*3		JS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OG ch 4 OG CO 20/8202

PC's Charges O-BOSS, Troublung OK

SIGNED BY: Don Miller 1539A

Belt Examiners and Certificate Numbers

William Campbell 1354A

Belt Examiners and Certificate Numbers

Johnny Peely 33472

3247E

COUNTERSIGNED BY: Terry Moore

33355

Mine Foreman

Certificate No.

Superintendent

Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indellible Pencil or Ink

DATE 2-24-10 SHIFT: Owl AM OR PM TO AM OR PM AM OR PM TO AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with 3 columns: BELTS, ACTION TAKEN, INT. Rows include BELTS 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2. Handwritten notes describe actions like 'Cleared V-Roll', 'Fixed Ch. 15 28 Brk / Replaced Bottom rollers', etc.

02 CH4, 06 CO, 2018202
Checked out by Refey 6-8-89

SIGNED BY: Dean Williams 1539A
Belt Examiners and Certificate Numbers
Willie Campbell 13547A
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY Terry Moore 33359
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-24-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Neely, John Bickford Time 2:35 AM or PM

Report received by: \_\_\_\_\_

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs spot cleaned 98-Drift, needs dusted	RG	✓		
Ellis 5	Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 10-Discharge	RG	✓		
NORTH NO. 5	None Observed	JAB	✓		
NORTH NO. 6	Needs dusted	JAB	✓		
NORTH NO. 7	tail needs Add Cleaning	SH	✓		
Longwall	Needs Spot Cleaned & Dusted	SH	✓		
GLORY HOLE	D-Box + Pump				
LBB NO. 1					
HG-22	Needs spot cleaned & Dusted	JN	✓		
HG-23 1	} TRACK + Power Centers OK				
HG-23 2		JN	✓		
HG-23 3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO at time of exam  
Travelways, power centers, D-Boxes, chargers clear at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Dunne 1536-17 Scott Holdard 37567  
Belt Examiners and Certificate Numbers  
John Bickford 28171 John Neely 33472  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Tony Moore 33359 [Signature] 33476  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-24-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. AM OR PM TO AM OR PM  
PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
Ellis 4		
Ellis 5	spot cleaned 3-5 Brk (Bobby)	
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, spot cleaned 10-12 Brk	RG
NORTH 5	cleaned at Tail & flow thru	JN
NORTH 6		JN
NORTH 7	cleaned on tail	SH
Long Wall	cleaned at Drive, Greased on Drive	SA
GLORY HOLE		
LBB NO. 1		
HG 22 #1	TRAIN Belt Dust 2 Brk near TAIL	JN
HG 23	Dust off PC's & Dust around Boxes	JN

0% CH<sub>4</sub>, 20.89% O<sub>2</sub>, 0ppm CO at time of exam

Resuge chamber at 6, 8, 9, 8 Brk 2 sect: OK & phone working at time of exam

SIGNED BY: Russell Guzman 1536-A Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
John Buchard 26171 Johnny Neely 33472  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY Tony Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-24-10 SHIFT: EVE AM OR PM TO AM OR PM 800 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom SK Time 1100 AM or  PM  
Report received by: Oliver Williams 539A  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis #4</u>	<u>needs Ousted, Needs spotcleaned 98-DK4</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>Ellis #5</u>	<u>needs Ousted</u>	<u>GU</u>	<input type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>needs spotcleaned 10' Head</u>	<u>GU</u>	<input type="checkbox"/>		
NORTH NO. 5	<u>none observed</u>	<u>GU</u>	<input type="checkbox"/>		
NORTH NO. 6	<u>needs Ousted</u>	<u>GU</u>	<input type="checkbox"/>		
NORTH NO. 7	<u>Tail needs Add cleaning</u>	<u>GU</u>	<input type="checkbox"/>		
<u>[Wall]</u>	<u>Needs spot cleaned &amp; dusted</u>	<u>JS</u>	<input type="checkbox"/>		
GLORY HOLE	<u>DBox, Pump OK</u>	<u>GU</u>	<input type="checkbox"/>		
<u>H622#1</u>	<u>needs spot cleaned &amp; dusted</u>	<u>JS</u>	<input type="checkbox"/>		
<u>H623 1</u>	<u>PC Charges OK</u>	<u>JS</u>	<input type="checkbox"/>		
<u>H623 2</u>					
<u>H623 3</u>					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OBCHY OBCO 208602  
PC'S, Charges, D-Box, Tardumps OK

SIGNED BY: Oliver Williams 539A  
Belt Examiners and Certificate Numbers

John [Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357  
Mine Foreman Certificate No. Superintendent Certificate No.

**ON-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-24-10 SHIFT: EUE 600 AM OR PM TO 860 AM OR PM AM OR PM TO AM OR PM

**ON-SHIFT EXAM.**

**PRE-SHIFT EXAM.**

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

John, DeCO, 2018202

Checked out by Refuges 6, 8, 89 all OK

Replaced 2 Top center rollers at Mother Drive

SIGNED BY: Dem Williams 15304  
Belt Examiners and Certificate Numbers  
John Williams 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.





Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-25-10 SHIFT: 02 / 1120 AM OR PM TO AM OR PM 300 AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
E/154	Cleaned V-Paw	GU
E/155	Cleaned V-Paw change roll LC	GU
NORTH 2		
NORTH 3	change roll LC	
NORTH 4	Cleaned V-Paw Pulled Rack set two Jacks. 34 BK	GU
NORTH 5	Cleaned V-Paw	GU
NORTH 6	Cleaned V-Paw change roll LC	GU
NORTH 7	Cleaned T.A.1 needs Add Clearing	GU
NORTH 8	LX All change roll LC	
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refugas 6-8-89 all OK

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-25-10 SHIFT: EVE AM OR PM TO AM OR PM 800 AM OR PM TO 1100 AM OR PM PRE-SHIFT EXAM.

Was this report phoned to outside: Yes No By Whom Brought out Time AM or PM

Report received by: \_\_\_\_\_

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs spot clean / 98-1011 needs dusted	GU	✓		
Ellis #5	Needs Dusted	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 10-11d	GU	✓		
NORTH NO. 5	none observed	GU	✓		
NORTH NO. 6	Needs Dusted	GU	✓		
NORTH NO. 7	Tail needs add cleaning	GU	✓		
L Wall	Needs spot clean & dusted	MW	✓		
GLORY HOLE	O-Box & Pump OK	GU	✓		
HG22 #1	Needs spot clean & dusted	GU	✓		
HG23 1	NO power no refresh	GU	✓		
HG23 2					
HG23 3					
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OG Ch4 OG CO 2018202  
PC's Chargers O-Boxes Track, Tramlings OK

SIGNED BY: [Signature] 15399  
Belt Examiners and Certificate Numbers  
[Signature] 39068  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

### ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-25-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No X By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges 6-8-89 OK

SIGNED BY: [Signature] 15399  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33359  
Mine Foreman Certificate No. Superintendent Certificate No.


Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-26-10 SHIFT: owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Stanley Time 515 AM or PM

Report received by: Dan Williams 15399  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>EW5 #4</u>	<u>needs spot clean 9P-dirt / need dust</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>EW5 #5</u>	<u>needs Dusted</u>	<u>GU</u>	<input checked="" type="checkbox"/>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>needs spot clean 10-Head</u>	<u>GU</u>	<input type="checkbox"/>		
<u>NORTH NO. 5</u>	<u>none observed</u>	<u>GU</u>	<input type="checkbox"/>		
<u>NORTH NO. 6</u>	<u>needs Dusted</u>	<u>GU</u>	<input type="checkbox"/>		
<u>NORTH NO. 7</u>	<u>Tr. needs Add cleaning</u>	<u>GU</u>	<input type="checkbox"/>		
<u>NORTH NO. 8</u>					
<u>GLORY HOLE</u>	<u>D-Boxes &amp; Chargers</u>	<u>GU</u>	<input type="checkbox"/>		
<u>L1000</u>	<u>needs spot clean &amp; dusted</u>	<u>KS</u>	<input type="checkbox"/>		
<u>HG22 #1</u>	<u>needs spot clean &amp; dusted</u>	<u>GU</u>	<input type="checkbox"/>		
<u>HG23 1</u>	 <u>NO Power no Pres Shift</u>				
<u>HG23 2</u>		<u>GU</u>	<input type="checkbox"/>		
<u>HG23 3</u>					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

On C4 D6 C0 20-8202  
PCS, Chargers, D-Boxes Track Travelers OK

SIGNED BY: Dan Williams 15399 Belt Examiners and Certificate Numbers  
Neil Kelly 28045  
Dave K. Stanley 39208 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Mame Mine Foreman 53309 Certificate No.  
Smith Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-26-90 SHIFT: owl 1130 AM OR PM TO 300 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<sup>51124</sup> SOUTH 1	cleaned U Pins	GU
<sup>51125</sup> NORTH 1	cleaned U Pins change roller LC	GU
NORTH 2		
NORTH 3		
NORTH 4	cleaned U Pins change roller LC cleaned on taking LC	GU
NORTH 5	cleaned U Pins	GU
NORTH 6	cleaned U Pins	GU
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1	LWA1 change roller LC	
LBB NO. 2		

Checked out by RePax 6-8-89 OK  
Checked Intake Rooms

SIGNED BY: [Signature] 15397  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33389  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-26-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes    No    By Whom    Time    AM or PM   

Report received by:    Signed   

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis-4	Needs spot cleaned 102-Drift, Needs Dusted	RG	✓		
Ellis-5	Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spots cleaned 10-Head	RG	✓		
NORTH NO. 5	Needs dusted head - 45BRK	MK	✓		
NORTH NO. 6	Needs dusted	MK	✓		
NORTH NO. 7	tail needs add Cleansing	SH	✓		
Longwall	Needs SPot + Cleaned + dusted	MK	✓		
GLORY HOLE	D-Box + Pump	SH	✓		
LBB NO. 1					
LBB NO. 2					
HG-22	Needs Spot Cleaned + Dusted	SH	✓		
HG-23 #1	<div style="font-size: 2em;">}</div> NO Power / NO Preshift				
HG-23 #2		SH	✓		
HG-23 #3					

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO at time of exam  
Travelways, power centers, chargers, D-Boxes OK at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Dunbar 1536-A William Campbell 1354-A  
 Belt Examiners and Certificate Numbers  
Scott Halstead 37567  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 3338-7  
 Mine Foreman Certificate No. Superintendent Certificate No.

**ON-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-26-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4		
Ellis-5	Shoveled v-plow	RG
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on Tail	RG
NORTH 5	Cleaned U Plow	MK
NORTH 6	Cleaned V Plow	MK
NORTH 7		
Longwall	did PM on Motherdrive, Greased on Storage Unit, cleaned Spillage at Discharge	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Refuge chambers at 6, 8, 9, 8 bak 2 sect. OK at time of exam + phones working

SIGNED BY: Russell Gunnor 1536-A M. Kihlman 33017  
Belt Examiners and Certificate Numbers  
Scott Halsted 37567  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS

DATE 2-26-10 SHIFT: EVE 800 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes X No      By Whom Campbell Time 1100 AM or PM

Report received by: Oliver Williams  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis # 4	Needs Dusted, needs spot cleaned 102-011	GU	-		
Ellis # 5	Needs Dusted	GU	-		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 10 Ark-Hd	GU	-		
NORTH NO. 5	Needs Dusted	GU	-		
NORTH NO. 6	Needs Dusted	GU	-		
NORTH NO. 7	Tail Needs Ad Cleaning + needs Dusted to tail <sup>from Head</sup> Walk way needs cleaned	WC	-		
Linnell	Needs Spot cleaned & Dusted	WC	-		
GLORY HOLE	D-Box Pump OK	WC	-		
HG22 #1	Needs spot cleaned & dusted	WC	-		
HG23 #1	No Power No Preshift	GU	-		
HG23 #2					
HG23 #3					
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OPCH OBCO 20.8202  
Power Centers, Chargers, D-Boxes, Track, and Travelways OK

SIGNED BY: Oliver Williams 1539-A  
Belt Examiners and Certificate Numbers  
William Campbell 1354-A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.



**ON-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-26-10 SHIFT: EVC 600 AM OR PM TO 800 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked art by Refuges 6-8-89 All OK

SIGNED BY: Dan Walker 1539-A  
 Belt Examiners and Certificate Numbers  
William Campbell 1354-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 3339  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-27-10 SHIFT: 0w1 AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis #4</u> SOUTH NO. 1	<u>needs dusted need spot cleaned 102-drift</u>	<u>GU</u>	<u>—</u>		
<u>Ellis #5</u> NORTH NO. 1	<u>needs dusted</u>	<u>GU</u>	<u>✓</u>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>needs spot cleaned 10. BIK-Head</u>	<u>GU</u>	<u>—</u>		
NORTH NO. 5	<u>needs dusted</u>	<u>GU</u>	<u>—</u>		
NORTH NO. 6	<u>needs dusted</u>	<u>GU</u>	<u>✓</u>		
NORTH NO. 7	<u>Tail needs gold cleaning needs dusted from Head to tail</u>	<u>WC</u>	<u>✓</u>		
GLORY HOLE	<u>D-Box Pump OK</u>	<u>WC</u>	<u>✓</u>		
LBB NO. 1					
LBB NO. 2	<u>B</u>				
HG22 #1	<u>Needs <sup>walkway needs cleaned</sup> spot cleaned &amp; dusted</u>	<u>WC</u>	<u>✓</u>		
HG23	<u>NO Power / No pre shift</u>	<u>GU</u>	<u>—</u>		
L1 wall	<u>needs spot cleaned &amp; dusted</u>	<u>WC</u>	<u>✓</u>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

O2 cut off CO 20.86 O2  
PC'S chargers D-Boxes Transducers OK

SIGNED BY: William Campbell 1354-10  
Belt Examiners and Certificate Numbers  
William Campbell 1354-10  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359  
Mine Foreman Certificate No.

46543—BJW Printing & Office Supplies  
Johnnie Arnold 2201-1  
Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-27-10 SHIFT: owl 1130 AM OR PM TO 300 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
<u>511504</u> SOUTH 1	<u>cleaned v-flaw change roll last impact LC</u>	<u>GU</u>
<u>511505</u> NORTH 1	<u>cleaned v-flaw</u>	<u>GU</u>
NORTH 2		
NORTH 3		
NORTH 4	<u>change roll impact test @ Top 39B LC</u>	
NORTH 5	<u>cleaned v-flaw change roll @ Top 77B @ Bottom v-flaw LC</u>	<u>GU</u>
NORTH 6	<u>impact change roll LC</u>	
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<u>220111</u>	<u>change roll LC &amp; TW @ Top to head LC</u>	

Checked out by Refeyos 6-8-79 OK

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers  
[Signature] 1354-12  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33354  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indellible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-27-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Neely, Scott Halstead Time 2:30 AM or PM

Report received by: Russell Gunnor  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted, Needs spot cleaned 102-Deck	RG	✓		
Ellis 5	Needs Dusted, Needs spot cleaned 7-3 Bnk	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 10-Head	RG	✓		
NORTH NO. 5	Needs Dusted 46-Head	RG	✓		
NORTH NO. 6	Needs Dusted	RG	✓		
NORTH NO. 7	Tail needs add. cleaning, needs Dusted	SH	✓		
1 original	Needs Spot cleaned + Dusted	SH	✓		
GLORY HOLE	D-Box + Pump OK	SH	✓		
LBB NO. 1					
LBB NO. 2					
HG-22	Needs spot cleaned + Dusted	JN	✓		
HG-23 1	NO Power No Pre-Shift				
HG-23 2		SH	✓		
HG-23 3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, Apprx CO at time of exam  
Travelways, power Boxes, chargers, D-Boxes OK at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gunnor 1536-A Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
John Neely 33472  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359 Superintendent  
Mine Foreman Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-27-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
E11.5 4	shoveled v-plow	RG
E11.5 5	shoveled v-plow	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail	RG
NORTH 5	cleaned on Tail, shoveled v-plow at Tail + Flow-Thru	RG
NORTH 6	cleaned under offside tailpiece	SH
NORTH 7	cleaned under tailpiece walkway side. CLEAN TAIL + DUST	SH JW
LONGWALL	cleaned offside of discharge, cleaned up mud at DRIVE + dusted	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
HG22	Clean off pc's + Dust at HG22 Drive + splitter Behind Stopping also Picked up TRASH.	JW

Resuge chambers 6, 8, 9, 8 OK + phones working at time of exam

SIGNED BY: Russell Lannon 1536-19 Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
Johnny Peely 33472  
Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY: T. Moore 35587  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 2-27-10 SHIFT: EVE 600 AM OR PM TO 900 AM OR PM 600 AM OR PM TO 1100 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Cambell Time 1100 AM or PM

Report received by: John Williams  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis #4</u>	<u>Needs Dusted, Needs spotcleaned 102 Duff</u>	<u>GU</u>	<u>/</u>		
<u>Ellis #5</u>	<u>Tail needs Add cleaning, Needs Dusted, Needs spotcleaned 7-3 Bk</u>	<u>GU</u>	<u>/</u>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Needs spotcleaned 10-Bk-Hd</u>	<u>GU</u>	<u>/</u>		
NORTH NO. 5	<u>Needs Dusted</u>	<u>GU</u>	<u>/</u>		
NORTH NO. 6	<u>Needs Dusted</u>	<u>GU</u>	<u>/</u>		
NORTH NO. 7	<u>Tail need Add cleaning</u>	<u>WC</u>	<u>/</u>		
<u>Abrogwall</u>	<u>Needs spot cleaned</u>	<u>WC</u>	<u>/</u>		
GLORY HOLE	<u>D-Box Pump OK</u>	<u>WC</u>	<u>/</u>		
<u>H622 #1</u>	<u>Needs spotcleaned &amp; dusted</u>	<u>GU</u>	<u>/</u>		
<u>H623</u>	<u>IDLE. NO Power. NO Preshift</u>				

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> Detected  
TRACK / Travelways, P/L's, D-Box, chargers, all - clean w/ Exam  
Visual check of all CO's at Time of Exam

SIGNED BY: John Williams 15377  
 Belt Examiners and Certificate Numbers  
William Campbell 18547A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Mann 33557  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-27-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 900 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis #4	cleaned cob off	GU/PC
Ellis #5	cleaned on tail	GU
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned v-plow	GU
NORTH 6	shoveled v-plow	BC
NORTH 7	Shoveled v-plow	BC
Longwall		
Glory Hole		
H6 #20 #1		
H6 #23 #1		
#2		
#3		

Outby Refuges at #6, B, 89 brk - all O/K & phones working

SIGNED BY: [Signature] 1534  
Belt Examiners and Certificate Numbers  
Willow Campbell 1354A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 3359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-28-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM

ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time          AM or PM

Report received by:         

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis #4</u>	<u>needs cleaned and dusted</u>	<u>SW</u>	<u>/</u>		
<u>Ellis #5</u>	<u>tail and takeup need additional dust and heads</u> <small>Beltline needs dust</small>	<u>SW</u>	<u>/</u>		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>needs additional spot dust 10BK Area</u>	<u>SW</u>	<u>/</u>		
<u>NORTH NO. 5</u>	<u>Head needs dusted Beltline needs add dust</u>	<u>SW</u>	<u>/</u>		
<u>NORTH NO. 6</u>	<u>needs SPOT cleaned + Dusted</u>	<u>BC</u>	<u>✓</u>		
<u>NORTH NO. 7</u>	<u>needs Dusted</u>	<u>BC</u>	<u>✓</u>		
<u>Lory #11</u>	<u>needs spot cleaned + Dusted</u>	<u>BC</u>	<u>✓</u>		
<u>GLORY HOLE</u>	<u>IDLE, D-Box + Pump clear Exam</u>	<u>BC</u>	<u>✓</u>		
<u>H622 #1</u>	<u>Walkway needs cleaned + Dusted</u> <small>+ Belt</small>	<u>BC</u>	<u>✓</u>		
<u>H623 #</u>	<u>NO POWER, NO Pre-shift IDLE</u>				

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% %CH4, 0%CO, 20.8 %O2 detected

Track / Travelways, P.C.'s, D-Boxes, Chargers + visual check of

CO's all clear w/ Exam

And Lilly 28045

SIGNED BY: [Signature] 19417 Johnny Aelby 33472

Belt Examiners and Certificate Numbers  
William Campbell 13847

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 73359

Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

### ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-28-10 SHIFT: 0wl 1100 AM OR PM TO 300 AM OR PM 500 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7	<u>cleaned on tail</u>	<u>BC</u>
GLORY HOLE		

OUT by Refuges at #6, 8, 89 btrks - all clear + phones working

SIGNED BY: W. J. Campbell 1384-A  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. J. ... 33357  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 2-28-10 SHIFT: Day AM OR PM TO 1200 AM OR PM TO 300 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom S. Neely Time 210 AM or PM

Report received by: John A. Bickford  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs spot cleaned &amp; dusted</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
<u>Ellis 5</u>	<u>Belt needs spot cleaned, needs dusts Tank &amp; hose up needs add'l cleaning</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Needs spot cleaned 10' belt to head</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>Head needs dusted, belt needs add'l dust</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>Needs spot cleaned &amp; dusted</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>Needs dusted</u>	<u>SN</u>	<input checked="" type="checkbox"/>		
<u>Lg. Wall</u>	<u>Fidle, PC's OK</u>	<u>SAB</u>	<input checked="" type="checkbox"/>		
GLORY HOLE	<u>D'Box &amp; Pump OK</u>	<u>SN</u>	<input checked="" type="checkbox"/>		
<u>H622 NO. 1</u>	<u>Needs spot cleaned &amp; dusted</u>	<u>SN</u>	<input checked="" type="checkbox"/>		
<u>H623</u>	<u>No Power, No Preshift Fidle</u>				

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% ch4, 0% CO & 20.8 % O2 detected at time of exam.

Visual check of CO's OK

Track, travelways, PC's, chargers, pumps & D'Boxes  
clear at time of exam

SIGNED BY: John A. Bickford 26176 J. Neely 32176  
 Belt Examiners and Certificate Numbers

Johnny Neely 33472  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mene 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-28-10 SHIFT: Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	Cleaned V-Plow	SAB
Ellis 5	Cleaned on spillage at tail	SAB
NORTH 2		
NORTH 3		
NORTH 4	Cleaned at V-Plow	SAB
NORTH 5	Cleaned at tail & flow thru	5N SAB
NORTH 6		
NORTH 7	CLEAN TAIL	
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
H022	Pickup TRASH Around PC's Grease DRIVE Dust Area	5N

*Checked Refuges at 6, 8 + 89 Bnh.; Phones OK*

SIGNED BY: John Bickford 26176 Johnny Neely 33472  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mann 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-28-10 SHIFT: EVS 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
<del>AGS #4</del>	needs cleaned from 101 - Drift, needs Dusted	BC	✓		
<del>AGS #5</del>	Tail needs added cleaning, needs spotcleaned + Dusted.	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs cleaned from 10brk - Head + Dusted	BC			
NORTH NO. 5	NEEDS DUSTED				
NORTH NO. 6	needs spotcleaned + Dusted				
NORTH NO. 7	NEEDS DUSTED	JIS	✓		
Kongwa A.	IDLE	JIS	✓		
GLORY HOLE					
H622#1	NEEDS WALKWAY & BKT. CLEANED & DUSTED	JIS	✓		
H623	IDLE, NO Preshift, NO Power	JIS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> detected  
TRACK/TRAVELWAY, D-Box's, P.L's, C.D's, Pumps chargers -

SIGNED BY: William Campbell 135474 J. [Signature] 32476  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. [Signature] 33359 \_\_\_\_\_  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 2-28-10 SHIFT: EV2 6:00 AM OR PM TO 8:00 AM OR PM 8:00 AM OR PM TO 11:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<u>E11.5#4</u>	<u>shoveled v-plow</u>	<u>BC</u>
<u>E11.5#5</u>	<u>shoveled on tail</u>	<u>BC</u>
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<u>cleaned v-plow at flow through</u>	
NORTH 6		
NORTH 7		
<u>Longwall</u>		
GLORY HOLE		
<u>H6.22#1</u>		

outby Refuges at #6, 8, 89 brks - all clear at Exam & phones working

SIGNED BY: William Campbell 135474  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 35309  
Mine Foreman Certificate No. Superintendent Certificate No.