

Started 1-14-10

# PRESHIFT - ONSHIFT and DAILY REPORT

North Pumps

Full-1-30-10

Company Performance Coal

Mine U.S.S.

SECTION ~~North~~ ~~Sells~~ North Pumps

LOCATION Naoma Raleigh W.V.  
Post Office County State

Form 6-1489  
(March 1970)

Budget Bureau No. 42-R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-13-10 20. Section or Area Examined North Delts
Time of Examination: from 3:22 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time 5:05 (M) P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include Ellis #4, #5, #4 North, #5 North, #6 North, #7 North, Glory Hole, Longwall, HG 22 #1, #2.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Rows include HG 23 #1, #2, #3.

Remarks: OX CH4 approx 20.8% detected at time of exam
Track traveling, powercenter, D-boxes, kva's, chargers ok
Visual check co monitors ok

Refuge at G, 89, 8brk #2 section ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Pre-shift Mine Examiner Certificate No. 37542
Assistant Foreman [Signature] Certificate No. 13541
Countersigned [Signature] Mine Manager-Mine Foreman

John A. Buckford 26176 Super 37567
Assistant Superintendent [Signature] 1539A M. Kiker 33017

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT**  
**MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-14 2010 Section or Area Examined Pumps
Time of Examination: from 12:00 p.m. to 2:30 p.m.
Was this report phoned to outside: Yes no
By whom John Bickford Time 2:35 P.M.
Report received by Russell Sumner (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows 1-10. Data: 1. North Mains, 0%, None Observed, None; 2. Glory Hole, 0%, None Observed, None; 3. Ellis, 0%, None Observed, None.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Data: Good Air Movement.

Remarks: 0% CH4, 20.8% O2, 0ppm CO detected at time of exam
TRAVEL ways clear at time of exam

Signature: Dan Sullivan 1531A JH 32476

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Sumner 1536-R Certificate No. 26041
Countersigned John A. Bickford Assistant Foreman Certificate No. 37561 26176
Assistant Foreman Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-14-2010 2010 Section or Area Examined Pumps  
 Time of Examination: from 7:45 a.m. or p.m. to 10: a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_  
 (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>NORTH MAINS 0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>GLORY HOLE 0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>ELLIS 0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4, 20.8% O2, 0ppm CO DETECTED AT TIME OF EXAM

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 32476  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 262211  
 \_\_\_\_\_ Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant  
John Bickford 26176

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-15-10 20. Section or Area Examined Pumps  
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.  
Was this report phoned to outside: Yes no  
By whom brought out Time      A.M.      P.M.  
Report received by \_\_\_\_\_  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>N. MAINS OBCHY</u>	<u>none</u>	<u>none</u>
2. <u>CLAY HOLE OBCHY</u>	<u>none</u>	<u>none</u>
3. <u>ELLIS OBCHY</u>	<u>none</u>	<u>none</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 15397  
Preshift Mine Examiner Assistant Foreman Certificate No. \_\_\_\_\_  
Countersigned [Signature] Certificate No. 32476  
Mine Manager - Mine Foreman Assistant Foreman

Russell Dunnoe 1536-A Superintendent or Assistant  
Tim Moore 33359 Scott Holston 37527



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-15 20 10 Section or Area Examined Pumps  
Time of Examination: from 12:00 a.m. or p.m. to 2:30 a.m. or p.m.  
Was this report phoned to outside: Yes  no   
By whom John Bickford Time 2:35 A.M. P.M.  
Report received by Russell Dunnoe  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>North MAINS</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO detected at time of exam  
TRAVELWAYS clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dunnoe 1536-A Certificate No. \_\_\_\_\_ Assistant Foreman  
Countersigned John Bickford 32476 Certificate No. 37567  
Mine Manager - Mine Foreman Scott Halstead Assistant Foreman  
Assistant Foreman John A. Bickford Superintendent or Assistant  
Superintendent or Assistant

Do Not 1500A Turn Phone 33359

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-15-10 Section or Area Examined 20.10 Drift  
 Time of Examination: from 8:00 a.m. or 1:00 p.m. to 1:00 a.m. or 8:00 p.m.  
 Was this report phoned to outside: Yes no  
 By whom Boyer et Time --- A.M. --- P.M.  
 Report received by ---  
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North Main 02 Ch4</u>	<u>none</u>	<u>none</u>
2. <u>Glory Hole 02 Ch4</u>	<u>none</u>	<u>none</u>
3. <u>Ellie's 02 Ch4</u>	<u>none</u>	<u>none</u>
4. <u>---</u>	<u>---</u>	<u>---</u>
5. <u>---</u>	<u>---</u>	<u>---</u>
6. <u>---</u>	<u>---</u>	<u>---</u>
7. <u>---</u>	<u>---</u>	<u>---</u>
8. <u>---</u>	<u>---</u>	<u>---</u>
9. <u>---</u>	<u>---</u>	<u>---</u>
10. <u>---</u>	<u>---</u>	<u>---</u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>

Remarks: 02 Ch4, 02 CO, 208802

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 15811 Assistant Foreman [Signature] Certificate No. 32476  
 Countersigned T. Moore Mine Manager—Mine Foreman  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-16-10 2010 Section or Area Examined Pumps  
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no  
 By whom Draught out Time          A.M.          P.M.  
 Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>NMANS OZ ch4</u>	<u>none</u>	<u>none</u>
2. <u>Colony Hole OZ ch4</u>	<u>none</u>	<u>none</u>
3. <u>Ellis OZ ch4</u>	<u>none</u>	<u>none</u>
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good diamond</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: O2 ch4 O2 CO 208602  
Traceways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1528 Assistant Foreman Certificate No.           
 Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 32476  
         Assistant Foreman

Robert Buckford 26176 T. Moore 33359 Superintendent or Assistant  
Scott Halstead 37567

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-16-10 20. Section or Area Examined North Pumps  
Time of Examination: from 12:00 a.m. or 3:00 p.m. to 3:00 a.m. or 3:00 p.m.  
Was this report phoned to outside: Yes  no   
By whom J. Bickford Time 2:35 A.M. P.M.  
Report received by M. Kiblinger (Signed)

Violations and other Hazardous Conditions Observed and Reported			
Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>N. MAINS</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>Ellis</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements			
Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO Detected at EXAM  
Power Centers, D. Boxes, track & travelways clean at EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead 37567  
Preshift-Mine Examiner Certificate No.

Countersigned T. Manna 35359  
Mine Manager—Mine Foreman

John A. Bickford Assistant Foreman Certificate No. 26116

D. Manna Assistant Foreman

Superintendent or Assistant



Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-16-10 20 Section or Area Examined Pumps  
Time of Examination: from 8:30 a.m. or 11:30 a.m. or no p.m.  
Was this report phoned to outside: Yes no  
By whom Brought out Time      A.M.      P.M.  
Report received by      (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>N main</u> <u>OK</u>	<u>none</u>	<u>none</u>
2. <u>Glory hole</u> <u>OK</u>	<u>none</u>	<u>none</u>
3. <u>Elk's</u> <u>OK</u>	<u>none</u>	<u>none</u>
4. <u>    </u>	<u>    </u>	<u>    </u>
5. <u>    </u>	<u>    </u>	<u>    </u>
6. <u>    </u>	<u>    </u>	<u>    </u>
7. <u>    </u>	<u>    </u>	<u>    </u>
8. <u>    </u>	<u>    </u>	<u>    </u>
9. <u>    </u>	<u>    </u>	<u>    </u>
10. <u>    </u>	<u>    </u>	<u>    </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Airway</u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>

Remarks: OKAY OKCO 208202  
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1579A [Signature] 13508A  
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.  
Countersigned T. Moore 33259 [Signature]  
Mine Manager—Mine Foreman Assistant Foreman  
Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-17-10 20 Section or Area Examined Pumps
Time of Examination: from 9:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes X no
By whom Cancell, Skiff Time 5:50 P.M.
Report received by Dan Williams (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for items 1-3.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Meant'.

Remarks: JB Cuy JB CO 20862
TRUCKS 05

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dan Williams 15397 Certificate No. Assistant Foreman
Countersigned Mine Manager-Mine Foreman 32976
Assistant Foreman 33359 Superintendent or Assistant
Johna. Bickford 26175 Russell Dumme 1536-A

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT**  
**MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1:17 10 Section or Area Examined Pumps  
Time of Examination: from 1200 a.m. or 0 p.m. to 300 a.m. or 0 p.m.  
Was this report phoned to outside: Yes no  
By whom Brought out Time          A.M.          P.M.  
Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>Wt. Main</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
4. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: 0% ch<sub>4</sub> 0% CO<sub>2</sub> 20.8% O<sub>2</sub> detected at time of span  
Power Center, D. Byrd, Track & Travelways clear at time of  
span

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Beckford 26176 John A. Beckford 32476  
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.  
Countersigned T. M. Moore 33307 Russell D. Moore 1536A  
Mine Manager—Mine Foreman Assistant Foreman

Will (space) 1354-01

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-17 20 10 Section or Area Examined Pumps
Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom B. Campbell / S. Scoggins Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include North Mains, Glory hole, Ellis, and empty rows 4-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1 contains 'Good Air Measurement'.

Remarks: 0% CH4, 0% CO, 20.890 O2 detected
Power centers, D-Boxes, KVAs, TRAIL/Travelways clean
at time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift Mine Examiner Certificate No. 13542 Assistant Foreman Certificate No.
Countersigned [Signature] Mine Manager / Mine Foreman Certificate No. 32476
T. Moore Assistant Foreman Certificate No. 33357 Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

North  
Pumps

Date of Examination 1-16 2010 Section or Area Examined \_\_\_\_\_

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes \_\_\_\_\_ no

By whom Brought out Time 543 AM P.M.

Report received by \_\_\_\_\_  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
2. <u>Geleg hole</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
3. <u>Ell's</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> Detected  
TRAIL/Travelways D-Boys, HVAs clear at time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell 1384-A [Signature] 32476  
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.

Countersigned T. Moore 3339  
 Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Russell Dunnoe 1536-A Scott Halstead 37867

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-18 20 10 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no X
By whom Brought out Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include North MAINS, Glory Hole, Ellis, and empty rows 4-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement.

Remarks: 0% CH4, 20.8% O2, 0 ppm CO detected at time of exam
Travelways, D-Boxes, Power Centers clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Russell Dunbar Preshift-Mine Examiner Certificate No. 1536-A
Countersigned T. Moore Mine Manager-Mine Foreman Certificate No. 35359
Assistant Foreman Scott Halstead Assistant Foreman Certificate No. 32476
Superintendent or Assistant Certificate No. 37567

With Copy 1354-A

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-18 2010 Section or Area Examined North Pumps  
 Time of Examination: from 8:30 a.m. or am to 11:30 a.m. or pm  
 Was this report phoned to outside: Yes no no no  
 By whom Brought out Time 10:45 A.M. (P.M.)  
 Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u>	<u>0%</u>	<u>none observed</u>	<u>none</u>
2. <u>Gilery Hole</u>	<u>0%</u>	<u>none observed</u>	<u>none</u>
3. <u>Ellis</u>	<u>0%</u>	<u>none observed</u>	<u>none</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>GOOD Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 0% CO, 20890<sup>2</sup> Detected  
TRAIL/TRAVELWAYS, D-BOX'S, KVIA'S POWERCENTERS  
all clear at Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By W. S. Campbell 1354-11 [Signature] 32476  
 Preshift Mine Examiner Certificate No. Assistant Foreman Certificate No.  
 Countersigned T. Moore 33307  
 Mine Manager—Mine Foreman  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date 1-19-10 Shift mid Area or Section NORTH Runps

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-19-2010 2010 Section or Area Examined NORTH Pumps  
Time of Examination: from 6:00 a.m. or p.m. to 6:30 a.m. or p.m.  
Was this report phoned to outside: Yes no  
By whom Brought out Time 5:40 A.M. P.M.  
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CHCI	Violation or Hazardous Condition	Action Taken
1. NORTH MAINS	0%	none observed	none
2. GLORY HALL	0%	none observed	none
3. ELLIS	0%	none observed	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 20.8% O<sub>2</sub>, CH<sub>4</sub> 0%, CO 200 Detected  
KVH's, Powercenters, D Box's TRACK / Travelways all clear  
At Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1354  
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 3339  
Assistant Foreman Certificate No. 32476  
Superintendent or Assistant



Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-19 <sup>20</sup>10 Section or Area Examined North Pumps  
 Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by Brought Out  
 (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>North mains</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>Ellis</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO detected at time of exam  
TRACK, TRAVELWAYS, Power Centers, D-Boxes clear at time of exam

Don Williams 1539A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gurnea <sup>1536-A</sup> Certificate No. 33359  
 Preshift-Mine Examiner  
 Countersigned T. Williams Mine Manager--Mine Foreman  
Scott H. Haddock Assistant Foreman Certificate No. 37567  
John [Signature] Assistant Foreman Certificate No. 32476  
 Superintendent or Assistant

With [Signature] 1384-A

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported		
Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places					
Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses					
Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-19-10 20 Section or Area Examined North Pump  
Time of Examination: from 8:30 a.m. or 8:30 p.m. to 11:30 a.m. or 11:30 p.m.  
Was this report phoned to outside: Yes  no  
By whom SKAGS, Campbell Time 11:00 A.M. P.M.  
Report received by Don Miller 15397A  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North Mains 02 ch4</u>	<u>none</u>	<u>none</u>
2. <u>6607 Hale 02 ch4</u>	<u>none</u>	<u>none</u>
3. <u>Ellis (GU) 02 ch4</u>	<u>none</u>	<u>none</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air vent</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 02 ch4 02 CO 20.8202  
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Don Miller 15397A  
Preshift-Mine Examiner Certificate No. 33357  
Countersigned T. Moore  
Mine Manager—Mine Foreman  
Assistant Foreman  
Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 120-10 Section or Area Examined Pumps
Time of Examination: from 3:00 a.m. or p.m. to 9:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for 'Pumps', 'Clay Hole', and 'Elis' with 'NONE' violations and 'none' actions.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Vent'.

Remarks: OBCU OK CO 20.8202
Treadways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By: [Signature] 1536 Assistant Foreman Certificate No. 135412
Countersigned: [Signature] Mine Manager-Mine Foreman Certificate No. 33359

John B. Buckford 26176 Russell Gunnoe 1536-A Scott H. H. 37567

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift *1st* Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-20 2010 Section or Area Examined Pumps  
Time of Examination: from 12:00 a.m. or p.m. to 2:30 a.m. or p.m.  
Was this report phoned to outside: Yes  no   
By whom John Bickford Time 2:40 A.M. P.M.  
Report received by Russell D. Moore  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u>	<u>CH4 0%</u> <u>None Observed</u>	<u>None</u>
2. <u>Glory Hole</u>	<u>0%</u> <u>None Observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>0%</u> <u>None Observed</u>	<u>None</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4, 20.8% O2, 0ppm CO detected at time of exam  
Travelways clear at Time of exam

Dm 1539

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell D. Moore 1536-A Certificate No. 33359  
 Preshift-Mine Examiner  
 Countersigned T. Moore Assistant Foreman  
 Mine Manager—Mine Foreman  
Scott Halstead Assistant Foreman  
 Certificate No. 32476  
John G. Bickford Superintendent or Assistant  
 Certificate No. 26176



Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-20-10 2010 Section or Area Examined Pumps  
 Time of Examination: from 8:30 a.m. or 9:00 p.m. to 1:30 a.m. or 5:00 p.m.  
 Was this report phoned to outside: Yes no X  
 By whom Brought out Time AM PM  
 Report received by \_\_\_\_\_  
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North mains <sup>CH</sup> OB</u>	<u>none</u>	<u>none</u>
2. <u>Gery hole OB</u>	<u>none</u>	<u>none</u>
3. <u>Elke OB</u>	<u>none</u>	<u>none</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air mount</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: OB CH<sub>4</sub>, OB CO, 2082 OB  
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all-violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 15397 Assistant Foreman Certificate No. 32476  
 Countersigned T. Moore Mine Manager—Mine Foreman Certificate No. 33257  
 Assistant Foreman

Shm. B. Bifford 26176 Superintendent or Assistant Russell Gunnoe 1536-A  
Scott Halstead 37567

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift 9 Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-21-10 Section or Area Examined Dumps
Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.
Was this report phoned to outside: Yes X no
By whom SLAGGS Time A.M. 510 AM
Report received by Dan Miller 15397 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for North Mans, Gary Hole, and Ellis.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry for Coal Airway.

Remarks: OK CH4, O2CO, 20188 O2
TRAVELWAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dan Miller 15397 Certificate No. 33577 Assistant Foreman
Countersigned T. Moore Mine Manager-Mine Foreman
Assistant Foreman
Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-21 2010 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or p.m. to 2:40 a.m. or p.m.
Was this report phoned to outside: Yes [checked] no
By whom John Beckford Time A.M. 2:45 P.M.
Report received by Russell Gurnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include North mains, Glory Hole, and Ellis, all with 0% CH4 and 'None Observed' violations.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4, 20.8% O2, 0ppm CO detected at time of exam
Travelways, Power centers, D-Boxes clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gurnoe Preshift-Mine Examiner
Countersigned T. Moore Mine Manager-Mine Foreman
Assistant Foreman

1536-A Certificate No.
3335-9

John Beckford Assistant Foreman
Scott Halstead
John R. Beckford Superintendent or Assistant

32476 Certificate No.
37567
26176

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT**  
**MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-21 2010 Section or Area Examined Pump  
 Time of Examination: from 8:30 a.m. or 8:30 p.m. to 11:30 a.m. or 11:30 p.m.  
 Was this report phoned to outside: Yes no  
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_ (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>NORTH MAINS</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>Gloxy Hole</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>Kallis</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: TRAVELWAYS, POWER CABLES, D-BOXES CLEAN AT TIME OF EXAM.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 24735 [Signature] 32476  
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.  
 Countersigned [Signature] 33359  
 Mine Manager—Mine Foreman  
 \_\_\_\_\_ Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

<i>Violations and other Hazardous Conditions Observed and Reported</i>		
<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-22-2010 20 Section or Area Examined Pump  
 Time of Examination: from 7:00 a.m. or p.m. to 5:30 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported			Action Taken
Location	Violation or Hazardous Condition		
1. <u>NORTH MAINS</u> <u>CH<sub>4</sub> 0%</u>	<u>NONE OBSERVED</u>		<u>NONE</u>
2. <u>GLOVE HOLD</u> <u>0%</u>	<u>NONE OBSERVED</u>		<u>NONE</u>
3. <u>ELLIS</u> <u>0%</u>	<u>NONE OBSERVED</u>		<u>NONE</u>
4. _____	_____		_____
5. _____	_____		_____
6. _____	_____		_____
7. _____	_____		_____
8. _____	_____		_____
9. _____	_____		_____
10. _____	_____		_____

Air Measurements			
Location	CFM	Location	CFM
<u>Good Air Movement</u>			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: TRAVELWAYS OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 32475  
 Assistant Foreman Certificate No. \_\_\_\_\_  
 Countersigned T. Moore Mine Manager - Mine Foreman Certificate No. 33559  
 Assistant Foreman \_\_\_\_\_  
 Superintendent or Assistant \_\_\_\_\_

El A. Rickard 26176 Russell Dummoe 1536-A Scott Halstead 37567

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-22 20 10 Section or Area Examined North Pumps  
 Time of Examination: from 12:00 a.m. or p.m. to 2:45 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom John Bickford Time 2:50 A.M. P.M.  
 Report received by Russell Gunnol  
(Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>North MAINS</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
4. _____			
5. _____			
6. _____			
7. _____			
8. _____			
9. _____			
10. _____			

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			
_____			
_____			
_____			
_____			
_____			
_____			
_____			
_____			

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO detected at time of exam  
TRAVELWAYS, Power centers, D-Boxes clear at time of exam

Don Williams 15394

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnol Preshift-Mine Examiner Certificate No. 1536-A  
 Countersigned T. Moore Mine Manager—Mine Foreman Certificate No. 3337  
Scott Halstead Assistant Foreman Certificate No. 37567  
John A. Bickford Superintendent or Assistant Certificate No. 26176

Walter Cooper 13542

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-22-10 20. Section or Area Examined DRUMS  
 Time of Examination: from 8:30 a.m. or 6:00 to 11:00 a.m. of 6 p.m.  
 Was this report phoned to outside: Yes no  
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. North Main's OBCAY	none	none
2. Gary Hole OBCAY	none	none
3. Ellis OBCAY	none	none
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

### Air Measurements

Location	CFM	Location	CFM
<u>Gas Account</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: OBCAY OBCO 208802  
TRAVEL WAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 15389 Assistant Foreman  
 Countersigned [Signature] Certificate No. 1354A  
 Mine Manager—Mine Foreman  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-23-10 Section or Area Examined Pumps
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10. Locations include North Mains OB, Glory Hole OB, Ellis OB. All violations listed as NONE.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. One entry: Good Air, CFM blank.

Remarks: OB CH4, OB CO, 20.8602 TRAVEL WAYS

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1530
Countersigned T. Moore Mine Manager-Mine Foreman Certificate No. 35359
Assistant Foreman [Signature] Certificate No. 1354-A
Superintendent or Assistant [Signature]

John Riedel 26176

Scott Halstead 37567



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT**  
**MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-23-10 Section or Area Examined Pumps  
 Time of Examination: from 1200 a.m. or 00 h. to 300 a.m. or 00 h.  
 Was this report phoned to outside: Yes no  
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_ (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	ch	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% ch 0% CO2 20.8% O2 detected at time of exam

Traneways clear.

Don Ullman 1539A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John B. Bedford Certificate No. 26176  
 Preshift Mine Examiner  
 Countersigned Jay Moore Certificate No. 37567  
 Mine Manager—Mine Foreman  
 Assistant Foreman

Superintendent or Assistant

Walter Cooper 13541A

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-23 2010 Section or Area Examined North Pumps  
 Time of Examination: from 8:30 a.m. or (p.m.) to 11:30 a.m. or (p.m.)  
 Was this report phoned to outside: Yes (no) no (X)  
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

Location	Violations and other Hazardous Conditions Observed and Reported	Violation or Hazardous Condition	Action Taken
1. <u>North Main CB</u>	<u>CH4</u>	<u>None</u>	<u>None</u>
2. <u>Gilroy hole CB</u>		<u>None</u>	<u>None</u>
3. <u>Ellis CB</u>		<u>None</u>	<u>None</u>
4. <u>        </u>			
5. <u>        </u>			
6. <u>        </u>			
7. <u>        </u>			
8. <u>        </u>			
9. <u>        </u>			
10. <u>        </u>			

Location	CFM	Air Measurements	Location	CFM
<u>Good Airman</u>				
<u>        </u>				
<u>        </u>				
<u>        </u>				
<u>        </u>				
<u>        </u>				
<u>        </u>				
<u>        </u>				
<u>        </u>				

Remarks: CH4 06, CO 06, O<sub>2</sub> 20.82 Detected  
TRAIL WAS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 15397 [Signature]  
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No. 1354-1A

Countersigned [Signature] 33327  
 Mine Manager—Mine Foreman Assistant Foreman

Assistant Foreman Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-24 20 19 69 Section or Area Examined North Pump  
Time of Examination: from 3:00 a.m. to 6:00 p.m. or p.m.  
Was this report phoned to outside: Yes no  
By whom Bought out Time A.M. P.M.  
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10. Locations include North Main, Ellis, Glory hole. All violations listed as 'none' and actions as 'none'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Point, blank, blank, blank.

Remarks: CH4 0.2, CO2, O2 20.8% Detected  
Traveling ok

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dan Allen 15377 Assistant Foreman Certificate No. 13544  
Countersigned Fred Moore Mine Manager - Mine Foreman Certificate No. 33751  
Assistant Foreman Superintendent or Assistant

Ed A. Rickard 26176

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1:24 10 Section or Area Examined Pumps  
 Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no Time AM P.M.  
 By whom \_\_\_\_\_  
 Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North Main c64</u>	<u>None observed</u>	<u>None</u>
2. <u>Flour Hole</u>	<u>None observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>None observed</u>	<u>None</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
----------	-----	----------	-----

Good Air Movement

Remarks: 07.64, 07. CO & 20.8% O2 detected at time of year  
PC's, D'Bot's, Trach & Trambways clear at time of year

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John Balfour Certificate No. 26176 Assistant Foreman  
 Countersigned F. Moore Certificate No. 37959 Mine Manager— Mine Foreman  
 Assistant Foreman \_\_\_\_\_  
 Superintendent or Assistant \_\_\_\_\_

32476  
Certificate No.

W. D. Casper 1354A



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-24 2010 Section or Area Examined Pumps  
 Time of Examination: from 8:30 a.m. or am to 11:30 a.m. or am  
 Was this report phoned to outside: Yes  no   
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u>	<u>none observed</u>	<u>none</u>
2. <u>Glory hole</u>	<u>none observed</u>	<u>none</u>
3. <u>Ellis</u>	<u>none observed</u>	<u>none</u>
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected  
Travel wings & Track will clean out Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 13844  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 33752  
[Signature] Assistant Foreman Certificate No. 32476  
         Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-25 2020 Section or Area Examined North Pump  
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no  
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>Ellis</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Glenhale</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
4. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: 0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> Detected  
D-Box's, Power centers all clear at time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By W. Bladen Preshift-Mine Examiner Certificate No. 12544  
 Countersigned T. Moore Mine Manager—Mine Foreman Certificate No. 32476  
         Assistant Foreman  
         Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-25 20 10 Section or Area Examined North Pumps  
 Time of Examination: from 12:00 a.m. or (p.m) to 3:00 a.m. or (p.m)  
 Was this report phoned to outside: Yes \_\_\_\_\_ no X  
 By whom Brought Out Time \_\_\_\_\_ A.M \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u>	<u>CH4 0% None Observed</u>	<u>None</u>
2. <u>Glory Hole</u>	<u>0% None Observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>0% None Observed</u>	<u>None</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4, 20.8% O2, 0ppm CO detected at time of exam  
Travelways, Power centers, D-Boxes clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Sumner Preshift-Mine Examiner Certificate No. 1536-A  
 Countersigned Tony Moore Mine Manager - Mine Foreman Certificate No. 37567  
Scott Holston Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-25-10 20\_\_\_\_ Section or Area Examined Pumps  
 Time of Examination: from 9:30 a.m. or 11:00 a.m. or 1:00 p.m.  
 Was this report phoned to outside: Yes  no\_\_\_\_  
 By whom Billy Campbell Time 11:12 A.M. P.M.  
 Report received by John [Signature] (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>NORTH MAINS CH<sub>4</sub> 0%</u>	<u>NONE OBSERVED</u>	<u>none</u>
2. <u>GLORY HOLE CH<sub>4</sub> 0%</u>	<u>NONE OBSERVED</u>	<u>none</u>
3. <u>ELLIS CH<sub>4</sub> 0%</u>	<u>NONE OBSERVED</u>	<u>none</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO DETECTED AT TIME OF EXAM  
TRAVELWAYS & POWER CENTRAL O.K. AT TIME OF EXAM D-BOXES

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1354-11  
 Countersigned T. Moore Mine Manager—Mine Foreman Certificate No. 33209  
 Assistant Foreman Certificate No. 32476  
 Superintendent or Assistant



Use Indefinite Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content, Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content, Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-28-10 20 Section or Area Examined Pumps  
 Time of Examination: from 3:30 a.m. or p.m. to 6:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no Time          A.M.          P.M.  
 By whom           
 Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. NORTH MAIN	0%	NONE OBSERVED	none
2. GLORY HOLE	0%	none observed	none
3. Ellis	0%	none observed	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
GOOD AIR MOVEMENT			

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO DETECTOR AT TIME OF EXAM  
TRAVELWAYS, POWER CENTER, P-BOXES 0% AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1354-A  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 33359  
 Assistant Foreman Certificate No. 32476  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-26 2010 Section or Area Examined North Pumps  
 Time of Examination: from 12:00 a.m. or (p.m) to 3:00 a.m. or (p.m)  
 Was this report phoned to outside: Yes \_\_\_\_\_ no X  
 By whom Brought out Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_ (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Ellis</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO detected at time of exam  
TRAVELWAYS, Power Centers, D-Boxes clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dunnoe Preshift-Mine Examiner Certificate No. 1536-A  
 Countersigned T. Moore Mine Manager—Mine Foreman Assistant Foreman Certificate No. 37562  
Scotty Holstead Assistant Foreman Certificate No. 15377  
Don Williams  
 Superintendent or Assistant W. B. ...

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-26-10 20 10 Section or Area Examined Ramp  
Time of Examination: from 8:30 a.m. or (p.m.) to 1:00 a.m. or (p.m.)  
Was this report phoned to outside: Yes X no  
By whom Campbell, Steve  
Report received by Dan Moran 1539A (Signed) Time A.M. P.M.

Table with 3 columns: Location, Violations and other Hazardous Conditions Observed and Reported, Action Taken. Rows 1-10.

Table with 4 columns: Location, Air Measurements, Location, CFM. Row 1: Good Point.

Remarks: 02 CHY OF CO 20.8 202  
Travel ways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.  
Signed By Dan Moran 15397 with Caprice Assistant Foreman Certificate No. 13500A  
Countersigned T. Moore Mine Manager - Mine Foreman Certificate No. 35359  
Assistant Foreman  
Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-27-10 20. Section or Area Examined Pumps  
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.  
 Was this report phoned to outside: Yes  No   
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>N. Mains CH</u>	<u>none</u>	<u>none</u>
2. <u>Glory Hole OZ</u>	<u>none</u>	<u>none</u>
3. <u>Ellis OZ</u>	<u>none</u>	<u>none</u>
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Airman</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: OZ CH4, OZ CO, 20188 OZ  
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1539A [Signature] Assistant Foreman  
 Certificate No. 33359 13342  
 Countersigned T. Moore Mine Manager—Mine Foreman  
 Certificate No. 32475  
 Assistant Foreman [Signature]

Schub. Buckrod 26176 Russell Gunnoe 1536-A Scott Halstead 37567  
 Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-27 20 10 Section or Area Examined North Pumps  
 Time of Examination: from 12:00 or (p.m.) to 3:00 or (p.m.)  
 Was this report phoned to outside: Yes  no   
 By whom John Bickford Time 2:40 A.M. P.M.  
 Report received by Russell Durnace (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North Mains</u> <u>CH<sub>4</sub> 0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>Glory Hole</u> <u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Ellis</u> <u>0%</u>	<u>None Observed</u>	<u>None</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

### Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, Apprx CO detected at Time of exam  
TRavelways, Power Centers, D-Boxes clear at time of exam

Dues \$1539

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Durnace Preshift-Mine Examiner Certificate No. 1536-A  
 Countersigned T. Mann Mine Manager—Mine Foreman Assistant Foreman Certificate No. 37567  
Scott Halstead Assistant Foreman  
John B. Bickford Superintendent or Assistant Certificate No. 26176

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-27-10 20\_\_ Section or Area Examined N Ramp 5  
 Time of Examination: from 8:30 a.m. or pm to 11:30 a.m. or pm  
 Was this report phoned to outside: Yes \_\_\_ no X  
 By whom Greg Whit Time \_\_\_ A.M. \_\_\_ P.M.  
 Report received by \_\_\_\_\_ (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>North MAINS 02</u>	<u>none</u>	<u>none</u>
2. <u>Glory Hole 02</u>	<u>none</u>	<u>none</u>
3. <u>Ellis 02</u>	<u>none</u>	<u>none</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Airman A</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 02 CHY 02 CO 20186 02  
TRAILWAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 15397A Assistant Foreman Certificate No. \_\_\_\_\_  
 Countersigned [Signature] 35359 Mine Manager—Mine Foreman Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_  
Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_  
Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-28-10 Section or Area Examined N. Pumps  
 Time of Examination: from 2:00 a.m. or p.m. to 6:00 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	<u>N. MAINS OZ</u>	<u>none</u>	<u>none</u>
2.	<u>Geo Hole OZ</u>	<u>none</u>	<u>none</u>
3.	<u>Ellis OZ</u>	<u>none</u>	<u>none</u>
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
<u>Geo &amp; A. main</u>			

Remarks: 06 CH4 02 CO 208802  
TRAVEL MAPS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 15304  
 Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33359  
[Signature] Assistant Foreman Certificate No. 32476

Shub. Bickford 26176 Superintendent or Assistant  
Scott Halstead 37567

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-28-10 Section or Area Examined North Pumps  
 Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)  
 Was this report phoned to outside: Yes no Time 2:25 A.M. P.M.  
 By whom J. Bickford  
 Report received by Mike Kiblinger (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>N. Mains</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>Ellis</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO Detected at EXAM TRACK & TRAVELWAYS, Power centers, D-Boxes Clear at EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead Preshift-Mine Examiner Certificate No. 37547  
 Countersigned Jerry Moore Mine Manager—Mine Foreman Assistant Foreman Certificate No. 26776  
[Signature] Superintendent or Assistant Certificate No. 33776



Use Indelible  
Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-28-10 20. Section or Area Examined Pumps

Time of Examination: from 8:30 a.m. or 8:30 p.m. to 11:30 a.m. or 6 p.m.

Was this report phoned to outside: Yes X no

By whom JAGGS Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.

Report received by \_\_\_\_\_  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>N. MAINS OB</u>	<u>none</u>	<u>none</u>
2. <u>Boothle OB</u>	<u>none</u>	<u>none</u>
3. <u>Ellis OB</u>	<u>none</u>	<u>none</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air vent</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: OB CHY, OB CO, 208602  
TRAVEL WAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dean Williams 15394 Certificate No. 32476  
 Freshift-Mine Examiner Assistant Foreman  
 Countersigned Tony Moore 33889  
 Mine Manager—Mine Foreman  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-29-16 2010 Section or Area Examined Pumps  
 Time of Examination: from 2:00 a.m. or p.m. to 6:00 a.m. or p.m.  
 Was this report phoned to outside: Yes  No   
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>N. MAINS CH4 OF</u>	<u>NONE</u>	<u>NONE</u>
2. <u>Glory Hole OF</u>	<u>NONE</u>	<u>NONE</u>
3. <u>Ellis OF</u>	<u>NONE</u>	<u>NONE</u>
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

### Air Measurements

Location	CFM	Location	CFM
<u>Good Airway</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: OF CH4 OF CO 208302  
Travel ways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Glen Ullman Preshift-Mine Examiner Certificate No. 1539A  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 32475  
[Signature] Assistant Foreman Certificate No. 35559  
[Signature] Superintendent or Assistant Certificate No. Scott Halstead 32567

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-29-10 20\_\_\_\_ Section or Area Examined North Rumps  
 Time of Examination: from 10:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)  
 Was this report phoned to outside: Yes\_\_\_\_ no   
 By whom J. Buckford Time 2:25 A.M. P.M.  
 Report received by Mike Kibling (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>N. Mairs</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>Glory Hole</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>Ellis</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Power Centers, D. Boxes, track & travelways  
0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, Dppm CO Detected at EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Holstead Preshift-Mine Examiner Certificate No. 37547  
 Countersigned T. Moore Mine Manager - Mine Foreman Assistant Foreman Certificate No. 26176  
John A. Buckford Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-29-10 Section or Area Examined Pumps  
 Time of Examination: from 8:30 a.m. or (p.m.) to 11:30 a.m. or (p.m.)  
 Was this report phoned to outside: Yes X no \_\_\_\_\_  
 By whom Carroll Time 1:10 P.M.  
 Report received by [Signature] 1579A (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Nimans Chy O<sub>2</sub></u>	<u>None Observed</u>	<u>None</u>
2. <u>Glory Hole O<sub>2</sub></u>	<u>None Observed</u>	<u>None</u>
3. <u>Ellis O<sub>2</sub></u>	<u>None Observed</u>	<u>None</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

### Air Measurements

Location	CFM	Location	CFM
<u>Good Armoat</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Pl's changes, O<sub>2</sub> boxes Travelways OK  
O<sub>2</sub> Chy O<sub>2</sub> CO 208202

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1539A [Signature] Assistant Foreman Certificate No. 13541A  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 33889  
 Assistant Foreman  
 Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-30-10 2010 Section or Area Examined Pumps  
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.  
Was this report phoned to outside: Yes  no   
By whom Brought out Time          A.M.          P.M.  
Report received by           
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>N. MAINS <sup>CH4</sup> OB</u>	<u>None</u>	<u>None</u>
2. <u>Gray Hole OB</u>	<u>None</u>	<u>None</u>
3. <u>Ellis OB</u>	<u>None</u>	<u>None</u>
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air mount</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: OB CH4 O2 CO 2086 O2  
TRAIL WAYS O1

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Don Allman 15397 Walter Campbell 1354-A  
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.  
Countersigned Fred Moore 38359  
Mine Manager-Mine Foreman Assistant Foreman  
Superintendent or Assistant

John H. Beckford 26176

Use Indelible  
Penell or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-30 Section or Area Examined Pumps  
 Time of Examination: from 12 a.m. or 3 p.m. to 3 a.m. or 3 p.m.  
 Was this report phoned to outside: Yes  no  Time          A.M.          P.M.  
 By whom           
 Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>R Mains</u>	<u>cb4</u> <u>0%</u> <u>None</u>	<u>None</u>
2. <u>Glory Hole</u>	<u>0%</u> <u>None</u>	<u>None</u>
3. <u>Ellis</u>	<u>0%</u> <u>None</u>	<u>None</u>
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

Air Measurements

Location	CFM	Location	CFM
<u>good Air movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: 0% CH<sub>4</sub> 20.9% O<sub>2</sub> 0% CO detected AT Exam  
Travel ways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By M. Kilduff Preshift-Mine Examiner Certificate No. 33017  
 Countersigned Fred Munn Mine Manager—Mine Foreman Assistant Foreman Certificate No. 33389  
Scott Halstead Assistant Foreman Certificate No. 37567  
John H. Bickford Superintendent or Assistant Certificate No. 2617A

W. H. Campbell 1354-A