

Longwall Construction

PRESHIFT - ONSHIFT and DAILY REPORT

Started 1-16-10

Company Performance Coal

Mine UBB

SECTION Long Wall Construction

LOCATION Naoma Raleigh W.Va.
Post Office County State

Form 6-1489
(March 1970)

Budget Bureau No. 42-R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-16-10 20 Section or Area Examined Hwall Construction
Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include Power Centers, D. Boxes, Chargers, and WORK AREA, all with 0% CH4 and None Observed.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4, 20.8% O2, 0 ppm CO Detected at EXAM time
TRACK & TRAVELWAYS - Clean at EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead 37567 Assistant Foreman Certificate No.
Countersigned T. Moore Mine Manager - Mine Foreman 73359
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-16-10 2010 Section or Area Examined Luau 11 Const
 Time of Examination: from 8:30 a.m. or 6:00 p.m. to 1:30 a.m. or 6:00 p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time AM P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	<u>Power centers C4</u> <u>10</u>	<u>none</u>	<u>none</u>
2.	<u>Ducts O2</u>	<u>none</u>	<u>none</u>
3.	<u>Chargers O2</u>	<u>none</u>	<u>none</u>
4.	<u>work area O2</u>	<u>none</u>	<u>none</u>
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
<u>Good Amount</u>			

Remarks: O2 C4 0.20 208802
TRAVELWAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 32476
 Preshift-Mine Examiner
 Countersigned T. Moore Certificate No. 33357
 Mine Manager—Mine Foreman
 Assistant Foreman [Signature] Certificate No. 13364
 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-10-10 20 Section or Area Examined L1 wall const
Time of Examination: from 3:00 a.m. or p.m. to 9:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Camille Time 5:45 A.M. P.M.
Report received by Don Williams 159A
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Power Centers ⁰² <u>ch4</u>	<u>none</u>	<u>none</u>
2. <u>Docks</u> ⁰² <u>ch4</u>	<u>none</u>	<u>none</u>
3. <u>Chargers</u> ⁰² <u>ch4</u>	<u>none</u>	<u>none</u>
4. <u>work area</u> ⁰² <u>ch4</u>	<u>none</u>	<u>none</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Location	Air Measurements CFM	Location	CFM
<u>Good Air</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 06 ch4, 06 CO, 208202
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 32476
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
Countersigned T. Williams 33359
Mine Manager—Mine Foreman
Assistant Foreman
Superintendent or Assistant

John A. Buckland 25176

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-17-10 Section or Area Examined Longwall Coast
Time of Examination: from 1200 a.m. or 0000 to 300 a.m. or 0000
Was this report phoned to outside: Yes no
By whom Brought Out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include Power Centers, D. Boy's, Chargers, Work Area, and empty rows 5-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1 contains 'Good Air Movement'.

Remarks: 07% ch4 07% CO + 20.8% O2 detected at time of exam

Track + trackage clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Joseph B. Beecher 2617 Certificate No. Assistant Foreman
Countersigned T. M. Moore 33357 Certificate No. Mine Manager - Mine Foreman
Assistant Foreman

with license 17547

Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-17 20 10 Section or Area Examined Lonywall Const.
 Time of Examination: from 9:30a.m. or 07:00 to 11:30a.m. or 07:00
 Was this report phoned to outside: Yes no
 By whom B. Campbell Time 10:45 A.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>Power Center</u>	<u>0%</u>	<u>None Observed</u>	<u>none</u>
2. <u>D-Box</u>	<u>0%</u>	<u>None Observed</u>	<u>none</u>
3. <u>Work Area</u>	<u>0%</u>	<u>None Observed</u>	<u>none</u>
4. <u>Chargers</u>	<u>0%</u>	<u>none observed</u>	<u>none</u>
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0% CO 20.8% O₂ detected
TRAIL/Travel ways clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By W. Campbell Preshift-Mine Examiner Certificate No. 1354
 Countersigned T. Moore Mine Manager—Mine Foreman Certificate No. 35559
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-18 20-20 Section or Area Examined Longwall Coast
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for Power Center, D-Box, Work Area, and Chargers, all marked as 'None Observed'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: Track & Travel ways clean at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift-Mine Examiner Certificate No. 32476
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33359
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-18 2010 Section or Area Examined Longwall Const.
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>Power Centers</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>D-Boxes</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>Work Area</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
4. <u>CHARGERS</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: TRACK + TRAVELWAYS CLEAR AT TIME OF EXAM
0% CH₄, 20.8% O₂, APPX CO AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report
Signed By Scott Halstead 37567 Certificate No. JL [Signature] 32476 Assistant Foreman Certificate No.
Countersigned T. Moore Mine Manager—Mine Foreman
Assistant Foreman

Superintendent or Assistant
Wilho [Signature] 13344

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date 7-19-2016 Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-19-2010 20 Section or Area Examined Longwall Construction
 Time of Examination: from 6:00 a.m. or 6:00 p.m. to 6:00 a.m. or 6:00 p.m.
 Was this report phoned to outside: Yes _____ no _____
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>POWER CENTER</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>D-BOXES</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>" "</u>
3. <u>WORK AREA</u>	<u>0%</u>	<u>NONE OBSERVED</u>	
4. <u>CHANGES</u>	<u>0%</u>	<u>NONE OBSERVED</u>	
5. _____			
6. _____			
7. _____			
8. _____			
9. _____			
10. _____			

Air Measurements

Location	CFM	Location	CFM
<u>GOOD AIR MOVEMENT</u>			

Remarks: Tracks & TRAVEL WAYS CLEAR AT TIME OF EXAM.
0% CH₄, 20.8% O₂, OPEN CO AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 32476 Assistant Foreman Certificate No. _____
 Countersigned T. Moore Mine Manager—Mine Foreman Certificate No. 3338
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-19 2010 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no X
By whom Brought out Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include Power Centers, D-Boxes, Chargers, WORK AREA, all with 'None Observed' and 'None' action.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: TRAVELWAYS, + TRACK clear at time of exam
0% CH4, 20.8% O2, 0ppm CO detected at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead Preshift-Mine Examiner Certificate No. 37567
Countersigned T. Moore Mine Manager-Mine Foreman Certificate No. 33359
Assistant Foreman Certificate No. 32076
Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested _____ Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-19-10 20____ Section or Area Examined L11011 const.
Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.
Was this report phoned to outside: Yes no____
By whom SKAGGS Time 11:00 P.M.
Report received by [Signature] 1829A
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Power Centers <u>CH4</u>	<u>none</u>	<u>none</u>
2. D-Boxes <u>06CH4</u>	<u>none</u>	<u>none</u>
3. Chargers <u>06CH4</u>	<u>none</u>	<u>none</u>
4. <u>WALKWAYS</u> <u>06CH4</u>	<u>none</u>	<u>none</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Airman</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 06CH4 06CO 20.8602
TRAVELWAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 32476
Preshift-Mine Examiner Certificate No. _____ Assistant Foreman Certificate No. _____
Countersigned T. M. [Signature] 33357
Mine Manager—Mine Foreman
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-20 2010 Section or Area Examined Longwall Construction
Time of Examination: from 3:00 a.m. or p.m. to 5:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom
Report received by (Signed)

Table with 4 columns: Location, Violations and other Hazardous Conditions Observed and Reported, Violation or Hazardous Condition, Action Taken. Rows include Power Controls, D-Boxes, Changers, Walkways.

Table for Air Measurements with columns: Location, CFM, Location, CFM. Includes handwritten entry 'Good Air Movement'.

Remarks: 06 CH4, 06 CO 208602 TRAVEL WAYS CLEAN

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 32476
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33357
Assistant Foreman
Superintendent or Assistant

John A. Bickford 26176

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-20 2010 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 or p.m. to 2:30 or p.m.
Was this report phoned to outside: Yes [checked] no
By whom John Bickford Time A.M. 2:40 P.M.
Report received by Russell Gurnee (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include Power Centers, D-Boxes, Chargers, Work Areas, all with 0% CH4 and None Observed/None action.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4, 20.8% O2, 0ppm CO detected at time of exam
Track + Travelways clear at time of exam

Signature: John Allen 157A

This is to certify that: (a) This section of the mine was properly examined by me. (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford Preshift-Mine Examiner Certificate No. 26176
Countersigned T. Moore Mine Manager-Mine Foreman Certificate No. 30359
Assistant Foreman Certificate No. 30476

Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-20-10 Section or Area Examined Long wall east
Time of Examination: from 8:30 a.m. or pm to 1:30 a.m. or pm
Was this report phoned to outside: Yes no
By whom Broughton Time AM P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Power Centers ^{CH4} O2</u>	<u>none</u>	<u>none</u>
2. <u>Charges O2</u>	<u>none</u>	<u>none</u>
3. <u>O2 boxes O2</u>	<u>none</u>	<u>none</u>
4. <u>work Area O2</u>	<u>none</u>	<u>none</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: O2 CH4 O2 CO 20.83 O2
Trails always OK
* Need A1 TRACK stop At end of TRACK *

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 15372
Preshift-Mine Examiner Certificate No. _____ Assistant Foreman Certificate No. _____
Countersigned T. Moore
Mine Manager—Mine Foreman Certificate No. _____
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-21-10 20. Section or Area Examined L. Wall east
Time of Examination: from 8:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes No
By whom [Signature] Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Power Center CH4	none	none
2. Chaugus OF	none	none
3. Dr. Boxes OF	none	none
4. [unclear] OF	none	none
5.		
6.		
7.		
8.		
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
Good Air 300 ft			

Remarks: 06 CH4 0800 208802
Travelways OK
Need Truck stop at end of Track

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] 15397 Assistant Foreman Certificate No. 38476
Countersigned T. Moore Mine Manager—Mine Foreman Certificate No. 33357
Assistant Foreman
Superintendent or Assistant

John A. Beckford 26171

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date: Shift: Area or Section:

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-21 2010 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 or p.m. to 2:40 or p.m.
Was this report phoned to outside: Yes no
By whom John Bickford Time 2:45 P.M.
Report received by Russell Dunne (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include Power Centers, CH4 0%, Chargers, D-Boxes, Work Area, all with 'None Observed' and 'None' action.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4, 20.8% O2, 0ppm CO detected at time of exam
Travelways OK at time of exam
Need TRACK stop AT end of TRACK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford 26176 Preshift-Mine Examiner Certificate No. Assistant Foreman 32476 Certificate No.
Countersigned T. Moore 33359 Mine Manager-Mine Foreman
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-21-10 20 Section or Area Examined LONGWALL CONSTRUCTION
Time of Examination: from 8:30 a.m. or p.m. to 9:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Entries include POWER CENTERS, CHARGERS, D-BOX, WORK AREA, all marked as NONE OBSERVED.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good AIR MOVEMENT.

Remarks: TRAVEL WAYS OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] 24735 Certificate No. 33359 Assistant Foreman [Signature] 3247C Certificate No.
Countersigned [Signature] Mine Manager - Mine Foreman
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-22-10 20 Section or Area Examined Longwall Construction

Time of Examination: from 8:30 a.m. or p.m. to 5:30 a.m. or p.m.

Was this report phoned to outside: Yes no

By whom Time A.M. P.M.

Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include POWER CABLES, CHARGERS, D-BOX, WORKS AREA, all with 'NONE OBSERVED' and 'NONE'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement.

Remarks: TRAVEL WAYS OK AT TIME OF EXAM. 0% CH4, 20.8% O2, 0 PPM CO DETECTED AT TIME OF EXAM.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 38476 Assistant Foreman Certificate No. 53259

John A. Bickford 26176

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-22 2010 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 a.m. or p.m. to 2:45 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom John Bickford Time AM 2:50 P.M.
Report received by Russell Dumas (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include Power Centers, CHARGERS, D-Boxes, WORK AREA, all with 0% CH4 and None Observed/None action.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4, 20.8% O2, 0ppm CO detected at time of exam
TRAVELWAYS OK at time of exam

Signature of Examiner: John A. Bickford

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By John A. Bickford Preshift-Mine Examiner Certificate No. 26176
Countersigned T. Moore Mine Manager-Mine Foreman Certificate No. 35357
Assistant Foreman

Superintendent or Assistant: William Campbell 1354-A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-22-10 Section or Area Examined Unstall carst
Time of Examination: from 8:30 a.m. or 6 p.m. to 11:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Dought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include: 1. Power centers OK, 2. Charger OK, 3. O-Box OK, 4. Walk Area OK. All violations listed as 'none' and actions as 'none'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. One entry: Good Air in A.

Remarks: OK CHY, OK LO, 20, 830
Time / ways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dan Williams Preshift-Mine Examiner Certificate No. 15399
Countersigned T. Moore Mine Manager-Mine Foreman Certificate No. 73259
Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-3-10 20____ Section or Area Examined Wall Coast
 Time of Examination: from 3:30 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Power centers of ch4</u>	<u>None</u>	<u>None</u>
2. <u>Chargers of</u>	<u>None</u>	<u>None</u>
3. <u>D-Boxes of</u>	<u>None</u>	<u>None</u>
4. <u>Wall Area of</u>	<u>None</u>	<u>None</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Airman</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 06 ch4, JECCO, 208202
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 153H
 Assistant Foreman Certificate No. _____
 Countersigned T. Moore Mine Manager—Mine Foreman Certificate No. 33507
 Assistant Foreman

John B. Beckford 26176
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Assistant Mine

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-23-10 Section or Area Examined Long-wall Conit.

Time of Examination: from 1200 a.m. or 300 p.m. to 0 a.m. or 0 p.m.

Was this report phoned to outside: Yes no

By whom Time A.M. P.M.

Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, % (CH), Violation or Hazardous Condition, Action Taken. Rows include Power Centers, Chargers, D'Boys, Work Area.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH 0% CO & 20.8% O2 detected

Travelways & Track clear at time of exam.

Blair Ullman 1539-A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead Preshift-Mine Examiner Certificate No. 37567 Assistant Foreman Certificate No. 33277

Superintendent or Assistant Walter Cochran 3847

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

	Location	Violations and other Hazardous Conditions Observed and Reported Violation or Hazardous Condition	Action taken
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1.	_____	_____	11.	_____	_____
2.	_____	_____	12.	_____	_____
3.	_____	_____	13.	_____	_____
4.	_____	_____	14.	_____	_____
5.	_____	_____	15.	_____	_____
6.	_____	_____	16.	_____	_____
7.	_____	_____	17.	_____	_____
8.	_____	_____	18.	_____	_____
9.	_____	_____	19.	_____	_____
10.	_____	_____	20.	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1.	_____	_____	6.	_____	_____
2.	_____	_____	7.	_____	_____
3.	_____	_____	8.	_____	_____
4.	_____	_____	9.	_____	_____
5.	_____	_____	10.	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 123 2010 Section or Area Examined Longwell Const
Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.
Was this report phoned to outside: Yes ~~no~~
By whom ~~Brought out~~ Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Power Center 06	CH4 none	none
2. Work Area 06	none	none
3. Chargers 06	none	none
4. D-Box's 06	none	none
5.		
6.		
7.		
8.		
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
Good Air Mount			

Remarks: CH4 06, O2 20.86 Detected
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By ~~W. L. ...~~ Preshift-Mine Examiner Certificate No. 1384
Countersigned ~~Tony ...~~ Mine Manager—Mine Foreman Certificate No. 3338
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-24 2010 Section or Area Examined Lowywall Const.
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Amber Time A.M. P.M.
 Report received by Alan Allen (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Power center OK</u>	<u>none</u>	<u>none</u>
2. <u>Work Area OK</u>	<u>none</u>	<u>none</u>
3. <u>Chargers OK</u>	<u>none</u>	<u>none</u>
4. <u>D-Box's OK</u>	<u>none</u>	<u>none</u>
5. <u> </u>	<u> </u>	<u> </u>
6. <u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>GoodAMENT</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: CH4 OK CO2 OK 0.208% Detected
Trucking OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Walter Carper Preshift-Mine Examiner Certificate No. 1354A
 Countersigned Tracy Moore Mine Manager - Mine Foreman Assistant Foreman Certificate No. 33359

Superintendent or Assistant

John A. Bickel 26176

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-24-10 Section or Area Examined Longwall-Const.
Time of Examination: from 12⁰⁰ a.m. or P to 3⁰⁰ a.m. or P
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Power Center</u>	<u>CH₄ 0%</u> <u>None Observed</u>	<u>None</u>
2. <u>Work Area</u>	<u>0%</u> <u>None Observed</u>	<u>None</u>
3. <u>Chargers</u>	<u>0%</u> <u>None Observed</u>	<u>None</u>
4. <u>D-Boss</u>	<u>0%</u> <u>None Observed</u>	<u>None</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0% CO & 20.8% O₂ detected at time of exam

Track & travelways Clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report
Signed By John H. Buckford Certificate No. 25176
Countersigned T. Moore Certificate No. 33357
Assistant Foreman

Superintendent or Assistant
W. D. ... 7354A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-24 2010 Section or Area Examined Lowy wood Const
Time of Examination: from 8:30 a.m. or 9:00 a.m. to 11:30 a.m. or 6:00 p.m.
Was this report phoned to outside: Yes no
By whom Blount Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include Work Area, Chargers, Powercenter, D-Box's, all with 'None Observed' and 'none' action.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: 7000 Air Movement.

Remarks: D2044, D2010, 208602 detected
Track/Travel ways - Chargers, Powercenter D-Box's
all clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift Mine Examiner Certificate No. 1354A
Assistant Foreman Certificate No. 32476
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33359
Assistant Foreman

Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-25- 2010 Section or Area Examined Langwell Const.
Time of Examination: from 3:00 or p.m. to 4:00 or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>Powercenter</u>	<u>0%</u>	<u>none observed</u>	<u>none</u>
2. <u>D-Box</u>	<u>0%</u>	<u>none observed</u>	<u>none</u>
3. <u>Chargers</u>	<u>0%</u>	<u>none observed</u>	<u>none</u>
4. <u>Work Area</u>	<u>0%</u>	<u>none observed</u>	<u>none</u>
5. <u> </u>	<u> </u>	<u> </u>	<u> </u>
6. <u> </u>	<u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: 0% CH₄, 0% CO, 20.8% O₂ detected
Track Headways, Powercenters, D-Box's, Chargers, and
Clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report

Signed By [Signature] Certificate No. 138498
Preshift-Mine Examiner

Countersigned [Signature] Certificate No. 32976
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-25 2010 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)
Was this report phoned to outside: Yes _____ no X
By whom Brought Out Time _____ A.M. _____ P.M.
Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	City	Violation or Hazardous Condition	Action Taken
1. <u>Power Centers</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
2. <u>CHARGERS</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
3. <u>D-Boxes</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
4. <u>WORK AREA</u>	<u>0%</u>	<u>None Observed</u>	<u>None</u>
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 20.8% O₂, 0ppm CO detected at time of exam
TRAVELWAYS, Power centers, D-Boxes OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Habstead 37567
Preshift-Mine Examiner Certificate No.
Countersigned Fey M... 33359
Mine Manager—Mine Foreman
Assistant Foreman
Superintendent or Assistant

Intelligible
Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-25-10 20. Section or Area Examined LONGWALL CONSTRUCTION
 Time of Examination: from 9:30 a.m. or (p.m.) to 11:00 a.m. or (p.m.)
 Was this report phoned to outside: Yes no
 By whom Billy Campbell Time 11:12 (P.M.)
 Report received by [Signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>POWER CENTERS</u>	<u>0%</u>	<u>NONE OBSERVED</u>	
2. <u>CHANGES</u>	<u>0%</u>	<u>NONE OBSERVED</u>	
3. <u>D-BOXES</u>	<u>0%</u>	<u>NONE OBSERVED</u>	
4. <u>WORK AREA</u>	<u>0%</u>	<u>NONE OBSERVED</u>	
5. _____			
6. _____			
7. _____			
8. _____			
9. _____			
10. _____			

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			

Remarks: 0% CH₄, 20.8% O₂, OPPN CO DETECTED AT TIME OF EXAM
TRAILWAYS D-BOXES, POWER CENTER O/S.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1334-A
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 32476
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date ----- Shift ----- Area or Section -----

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. -----	-----	-----
2. -----	-----	-----
3. -----	-----	-----
4. -----	-----	-----
5. -----	-----	-----
6. -----	-----	-----
7. -----	-----	-----
8. -----	-----	-----

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. -----	-----	-----	11. -----	-----	-----
2. -----	-----	-----	12. -----	-----	-----
3. -----	-----	-----	13. -----	-----	-----
4. -----	-----	-----	14. -----	-----	-----
5. -----	-----	-----	15. -----	-----	-----
6. -----	-----	-----	16. -----	-----	-----
7. -----	-----	-----	17. -----	-----	-----
8. -----	-----	-----	18. -----	-----	-----
9. -----	-----	-----	19. -----	-----	-----
10. -----	-----	-----	20. -----	-----	-----

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. -----	-----	-----	6. -----	-----	-----
2. -----	-----	-----	7. -----	-----	-----
3. -----	-----	-----	8. -----	-----	-----
4. -----	-----	-----	9. -----	-----	-----
5. -----	-----	-----	10. -----	-----	-----

Number of Bolts Tested -----
Number of Bolts Torqued Above Range ----- Below Range -----

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken -----

Remarks (Statement as to General Conditions of Mine or Area of Mine) -----

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date ----- Shift ----- Area or Section -----

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. -----	-----	-----
2. -----	-----	-----
3. -----	-----	-----
4. -----	-----	-----
5. -----	-----	-----
6. -----	-----	-----
7. -----	-----	-----
8. -----	-----	-----

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. -----	-----	-----	11. -----	-----	-----
2. -----	-----	-----	12. -----	-----	-----
3. -----	-----	-----	13. -----	-----	-----
4. -----	-----	-----	14. -----	-----	-----
5. -----	-----	-----	15. -----	-----	-----
6. -----	-----	-----	16. -----	-----	-----
7. -----	-----	-----	17. -----	-----	-----
8. -----	-----	-----	18. -----	-----	-----
9. -----	-----	-----	19. -----	-----	-----
10. -----	-----	-----	20. -----	-----	-----

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. -----	-----	-----	6. -----	-----	-----
2. -----	-----	-----	7. -----	-----	-----
3. -----	-----	-----	8. -----	-----	-----
4. -----	-----	-----	9. -----	-----	-----
5. -----	-----	-----	10. -----	-----	-----

Number of Bolts Tested -----
Number of Bolts Torqued Above Range ----- Below Range -----

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken -----

Remarks (Statement as to General Conditions of Mine or Area of Mine) -----

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination _____ 20. _____ Section or Area Examined _____
 Time of Examination: from _____ a.m. or p.m. to _____ a.m. or p.m.
 Was this report phoned to outside: Yes _____ no _____
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____
 Preshift-Mine Examiner _____ Certificate No. _____ Assistant Foreman _____ Certificate No. _____
 Countersigned _____
 Mine Manager—Mine Foreman _____
 Assistant Foreman _____
 Superintendent or Assistant _____

Use Indelible
Pen or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-26 20 10 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)
Was this report phoned to outside: Yes no X
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include Power Centers, Chargers, D-Boxes, and Work Area, all with 0% CH4 and 'None Observed'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air movement.

Remarks: 0% CH4, 20.8% O2, 0ppm CO detected at time of exam
Travelways, Power Centers, D-Boxes OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Scott Halstead 37567
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
Countersigned Mine Manager-Mine Foreman Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

	Location	Violations and other Hazardous Conditions Observed and Reported Violation or Hazardous Condition	Action taken
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1.	_____	_____	11.	_____	_____
2.	_____	_____	12.	_____	_____
3.	_____	_____	13.	_____	_____
4.	_____	_____	14.	_____	_____
5.	_____	_____	15.	_____	_____
6.	_____	_____	16.	_____	_____
7.	_____	_____	17.	_____	_____
8.	_____	_____	18.	_____	_____
9.	_____	_____	19.	_____	_____
10.	_____	_____	20.	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1.	_____	_____	6.	_____	_____
2.	_____	_____	7.	_____	_____
3.	_____	_____	8.	_____	_____
4.	_____	_____	9.	_____	_____
5.	_____	_____	10.	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Use Indelible
Pencil or Ink

Date of Examination _____ 20____ Section or Area Examined _____
 Time of Examination: from _____ a.m. or p.m. to _____ a.m. or p.m.
 Was this report phoned to outside: Yes _____ no _____ Time _____ A.M. _____ P.M.
 By whom _____
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner Certificate No. _____ Assistant Foreman Certificate No. _____
 Countersigned _____ Mine Manager--Mine Foreman _____
 _____ Assistant Foreman _____
 _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

	<i>Location</i>	<i>Violations and other Hazardous Conditions Observed and Reported</i>	<i>Action taken</i>
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	11.	_____	_____
2.	_____	_____	12.	_____	_____
3.	_____	_____	13.	_____	_____
4.	_____	_____	14.	_____	_____
5.	_____	_____	15.	_____	_____
6.	_____	_____	16.	_____	_____
7.	_____	_____	17.	_____	_____
8.	_____	_____	18.	_____	_____
9.	_____	_____	19.	_____	_____
10.	_____	_____	20.	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	6.	_____	_____
2.	_____	_____	7.	_____	_____
3.	_____	_____	8.	_____	_____
4.	_____	_____	9.	_____	_____
5.	_____	_____	10.	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____