

Ellis Out By South Pumps
started 11-27-9

PRESHIFT - ONSHIFT and DAILY REPORT

South Pumps

Company

Performance Coal

Mine

UBB

SECTION

Pumps

LOCATION

NAOMA

Post Office

Raleigh WU

County

State

Finished 12-13-09

Form 6-1489
(March 1970)

Bureau of Mines - Bureau of Safety

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-26 20-9 Section or Area Examined Pumps South
 Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom [Signature] Time A.M. P.M.
 Report received by [Signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Em's 110's</u>	<u>0% CH₄</u> none observed	<u>none</u>
2. <u>60-62-77-HG17 126</u>	<u>0%</u> none observed	<u>none</u>
3. <u>BB 3-415</u>	<u>0%</u> none observed	<u>none</u>
4. <u>37-32 Seal</u>	<u>0%</u> none observed	<u>none</u>
5. <u>35-8-14</u>	<u>0%</u> no power none observed	<u>none</u>
6. <u>4 sec 110's</u>	<u>0%</u> none observed	<u>none</u>
7. <u>19</u>	<u>0%</u> none observed	<u>none</u>
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: No CH₄ detect 0% 20' 40' CO₂
Tracks + tramways clean at exam.
Pumps P/C's P. Box charger clean

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 29611
 Assistant Foreman Certificate No. 350602
 Countersigned [Signature] Mine Manager—Mine Foreman

Assistant Foreman Superintendent or Assistant

[Signature] 1539A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-29 20 9 Section or Area Examined Camps - South
Time of Examination: from 3:50 a.m. or p.m. to 4:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought outside Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 7 rows of handwritten entries such as 'Em's 110's 0% CH4 none observed none'.

Air Measurements

Location CFM Location CFM

good air movement

Remarks: No CH4 det. O2 20.802 CO2
Tracks & haulways clean at exam
Pumps Ple's D.Box clean

This is to certify that (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 2901
Countersigned [Signature] Mine Manager - Mine Foreman
Assistant Foreman Certificate No.
Assistant Foreman
Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-5.

Number of Bolts Tested _____ Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-27 2009 Section or Area Examined Pumps
Time of Examination: from 7:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no. 1
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for East Mains 110's, #32 Seal, #13, #37, 60, 62, 77, 126, HG 17 Sump, and LBB Pumps 3, 4, 15.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry: Good Air Movement.

Remarks: 0% CH4 0% Co 20.8% O2
TRACK & TRAVELWAYS, POWER BOXES, P. BOXES OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Harley Taylor 37002 Certificate No.
Countersigned Russell Dummel 1536-1A Assistant Foreman
Assistant Foreman
Superintendent or Assistant

Yeg Col 1947-A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-27 2009 Section or Area Examined South Pumps
Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom
Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for 1-4: 1. east main 110's 0% ch4, 2. 325eq, 13,37 0%ch4, 3. 60, 62, 77, 126, HG 175UMP 0%ch4, 4. LBB Pumps 3, 4, 15 0%ch4.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry: Good Air Movement.

Remarks: 0% Ch4, 20.8% O2, 0PPM CO.
Tracks, Travelways, Power Boxes, D-Boxes, OK At Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1947-A
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 39000
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1.	-----	-----	-----
2.	-----	-----	-----
3.	-----	-----	-----
4.	-----	-----	-----
5.	-----	-----	-----
6.	-----	-----	-----
7.	-----	-----	-----
8.	-----	-----	-----

Examinations for Methane in Working Places

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	-----	-----	-----	11.	-----	-----	-----
2.	-----	-----	-----	12.	-----	-----	-----
3.	-----	-----	-----	13.	-----	-----	-----
4.	-----	-----	-----	14.	-----	-----	-----
5.	-----	-----	-----	15.	-----	-----	-----
6.	-----	-----	-----	16.	-----	-----	-----
7.	-----	-----	-----	17.	-----	-----	-----
8.	-----	-----	-----	18.	-----	-----	-----
9.	-----	-----	-----	19.	-----	-----	-----
10.	-----	-----	-----	20.	-----	-----	-----

Examinations for Methane in Return Aircourses

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	-----	-----	-----	6.	-----	-----	-----
2.	-----	-----	-----	7.	-----	-----	-----
3.	-----	-----	-----	8.	-----	-----	-----
4.	-----	-----	-----	9.	-----	-----	-----
5.	-----	-----	-----	10.	-----	-----	-----

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-28 2009 Section or Area Examined South Pumps

Time of Examination: from 3:00 A.M. or P.M. to 6:00 A.M. or P.M.

Was this report phoned to outside: Yes no

By whom Time A.M. P.M.

Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for CH4 levels at various locations like East Mains, 32 Seal, etc.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air movement'.

Remarks: 0%ch4, 20.8% O2, 0PPM C.O. Detected At Time of Exam

Track, Travelways, Power Boxes, D-Boxes, OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Freshshift-Mine Examiner Certificate No. 1947-A Assistant Foreman [Signature] Certificate No. [Signature] Countersigned [Signature] Mine Manager - Mine Foreman Assistant Foreman Superintendent or Assistant

Jay Stewart 39199

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-28 2009 Section or Area Examined Pumps ' South
Time of Examination: from 12 a.m. or 6 p.m. to 3 a.m. or 6 p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'East Mains 110's' and '32 Seal, 13, 37' with 'NONE observed' and 'NONE' as actions.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected at etam
Track, Travelway, Powercenters, D-Boxes Clear at etam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By: Jay Stuart, Preshift-Mine Examiner, Certificate No. 39199
Countersigned: John A. Beckford, Assistant Foreman, Certificate No. 26776
Assistant Foreman
Superintendent or Assistant

DMS/Ch 1947-A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-24 Section or Area Examined Pumps South
 Time of Examination: from 8:30 or 11:30 a.m. or 6 p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought Out (Signed)

Violations and other Hazardous Conditions Observed and Reported
 Violation or Hazardous Condition

Action Taken

Location	Violation or Hazardous Condition	Action Taken
1. east mains 110'S	0% CH ₄	
2. 32 seal, 13, 37	0% CH ₄	
3. 60, 62, 77, HG 1750' R	0% CH ₄	
4. LBB 3, 4, 15	0% CH ₄	
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

CFM

Location

CFM

Location	CFM	Location	CFM
Good Air Movement			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 20.8% O₂, 0 PPM C.O. Detected At Time of exam
Track, Travelways, Powercenters, D-Boxes ok At Time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1947-A
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 29160224
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-29-09 2009 Section or Area Examined PUMPS SOUTH
Time of Examination: from 1:00 p.m. or p.m. to 6:00 p.m. or p.m.
Was this report phoned to outside: Yes no
By whom
Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 4 rows of data: 1. east mains 110's 0% ch4 none observed None; 2. 32 seq, 13, 37 0% ch4 none observed None; 3. 60, 62, 77, HG 17 sump 0% ch4 none observed None; 4. LBB, 3, 4, 15 0% ch4 none observed None.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains one row: Good Air movement.

Remarks: 0% ch4, 20.4% O2, 0 PPM C.O., Detected At Time of exam

Tracks, Travelways, Powercenters, D-Boxes, At Time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1947-A
Countersigned [Signature] Mine Manager-Mine Foreman Assistant Foreman Certificate No. 2500001

George Curry 27429 Superintendent or Assistant 34199

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-29 2009 Section or Area Examined South Pumps
 Time of Examination: from 1200 a.m. or (p.m) to 300 a.m. or (p.m)
 Was this report phoned to outside: Yes no No to
 By whom _____ Time _____ A.M _____ P.M.
 Report received by Brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. East Mains, 110's $\frac{1}{2}$ ch ₄	none observed	none
2. 32 Seal, 13, 37 $\frac{1}{2}$ ch ₄	none observed	none
3. 60, 62, 77, 116, 17 sump $\frac{1}{2}$ ch ₄	none observed	none
4. LBB 3, 4, 15 $\frac{1}{2}$ ch ₄	none observed	none
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Scarf Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: $\frac{1}{2}$ ch₄, 0% CO, 20.8% O₂, track, travelways, p's, D. Boles clean at elec

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Seorn Curry 27429 Certificate No. 28736
 Preshift-Mine Examiner
 Countersigned Rick Foster Assistant Foreman
 Mine Manager-Mine Foreman
Am Johnson Assistant Foreman
Jacq Stewart Assistant Foreman
 Certificate No. 39199
 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-29 20 9 Section or Area Examined Pumps - South
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Report received by (Signed) Time A.M. P.M.

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'Em's 110's', '32 seal 37-13', etc., with violations noted as 'none observed' or 'no power'.

Air Measurements

Location CFM Location CFM

good air movement

Remarks: No CH4 det. 0% CO2 or CO 0%
Grass & haulways clean at exam.
Pumps P/C's D.Box clean

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29611 Assistant Foreman
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 28736
Assistant Foreman [Signature] Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 11-30 20-9 Section or Area Examined Pumps - South

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes no

By whom Report received by Time A.M. P.M.

brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Entries include locations like '110's', '32 sid 37 Rk.-13', etc., with violations like 'none observed' and actions like 'none'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: 'good air movement'.

Remarks: 110's sect. 0% 20.80% CO2% track & travelways clear at exam. Pumps 110's D. Box charger clear

This is to certify that (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 79011 Certificate No. Assistant Foreman Countersigned [Signature] 28736 Certificate No. 1947-A

Assistant Foreman Superintendent or Assistant: J. Hopper 32261, Joe Stewart 39199, George Curry 27429

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11.30 Section or Area Examined South Pumps
Time of Examination: from 1200 a.m. or 300 p.m. to 300 a.m. or 600 p.m.
Was this report phoned to outside: Yes no no 6
By whom _____ Time _____ A.M. _____ P.M.
Report received by Broughton outside
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location CH4 Violation or Hazardous Condition Action Taken

Location	CH4	Violation or Hazardous Condition	Action Taken
<u>LS 1. EM 110</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
<u>SC 2. 32 seal, 37 BK</u>	<u>0%</u>	<u>None Found</u>	<u>None</u>
<u>SC 3. 66, 62, 77, HG 17</u>	<u>0%</u>	<u>None Found</u>	<u>None</u>
<u>SC 4. LBB - 3-15</u>	<u>0%</u>	<u>None Found</u>	<u>None</u>
<u>LS 5. sec 3 - 8-14</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
<u>LS 6. sec 4 - 110</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
<u>SC 7. 1216</u>	<u>0%</u>	<u>None Found</u>	<u>None</u>
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location CFM Location CFM

Door Air Movement

Remarks: 0% CH4, 0% CO, 20.8% O2, track travelways, pct's D-Boes
clear at even

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Deane Curry Preshift-Mine Examiner Certificate No. 27429
Countersigned Bob Hill Mine Manager-Mine Foreman Certificate No. 23736
Jim Sawyer Assistant Foreman Certificate No. 32261
Joe Stewart

Am Peterson Assistant Foreman Certificate No. 29611
Superintendent or Assistant

1247-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 11-30 209 Section or Area Examined South Pump 3
 Time of Examination: from 8:30 a.m. or 1:30 p.m. to 1:30 a.m. or 8:30 p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Mem's 110's 0%	None observed	None
2. 325sq1, 37BRK 0%	None observed	None
3. 60, 62, 77, HG17 0%	None observed	None
4. LBB 3, 15 0%	None observed	None
5. 3sec, 8, 14 0%	None observed	None
6. 4sec. 110 0%	None observed	None
7. 126 0%	None observed	None
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4, 20.8% O2, 0ppm C.O. Detected At time of exam

Track, Travelways, Powercenters, D-Boxes, ok At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 291011
 Certificate No. 19474
 Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature]
 Mine Manager—Mine Foreman _____
 Assistant Foreman _____
 Superintendent or Assistant _____

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-21-61 20. 9 Section or Area Examined South - Pumps
Time of Examination: from 7:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 7 entries for locations like 'Em 15 110's' and '32 Seal 37 Pul', all with 'none observed' and 'none' action.

Air Measurements

Location CFM Location CFM

Good air movement

Remarks: NOCH4 Defs 0% 20.502 000%
Track & Trawlways clean at exam.
Pumps Hc D. Box charger clean

This is to certify that (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29611 Assistant Foreman
Countersigned [Signature] Certificate No. 29732 Mine Manager - Mine Foreman

Assistant Foreman

Superintendent or Assistant

George Curry 27429

[Signature] 32261

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-1-09 Section or Area Examined Pumps
Time of Examination: from 6:00 a.m. or p.m. to 4:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include HT 13, 37, #32 Seal, HT 77, 126, JB East Mains 110's, GC 60, 62, HG 17 Sump, GC LBB Pumps 3, 15, JB GC 3 Sec 8, 14, JB 4 Sec 110's, JB 19 BK.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4 0% CO 20.8% O2
Track, Travelways, Power Boxes, Di Boxes OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Charley Taylor Preshift-Mine Examiner Certificate No. 37002
Countersigned Rick Asta Mine Manager-Mine Foreman Certificate No. 28236
Assistant Foreman Certificate No. 32261
Superintendent or Assistant Certificate No. 2429

1947-A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-1 20-9 Section or Area Examined South Pump 3
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for various locations like 'Ems' 110's', '13-37-32 seal', etc., with '0%' violations and 'none observed' actions.

Air Measurements

Location CFM Location CFM

good air movement

Remarks: NoCH4 det. 0% 20.8oz COOZ
Traneways + track clear of exam
Pumps P/C's D. Box Charger clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Certificate No. 29611 Assistant Foreman
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 28236
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-2 20 9 Section or Area Examined South - Pumps
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include locations like 'Em's 110's', '13-37-32 seal', '77-126 SC', '60-62-HG17', 'LBB 3-15', '3 sec. 8-14', '4 sec. 110's', '19 BNC' with corresponding '0% CH4' and 'none observed' entries.

Air Measurements

Location CFM Location CFM

Good air movement

Remarks: No CH4 det. 0% 20.50 CO2
Track & travelways clear at exam
Pumps, 110's D.Box. Charges clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 28754 Assistant Foreman [Signature] Certificate No. 1947A
Countersigned [Signature] Mine Manager - Mine Foreman Assistant Foreman [Signature] Superintendent or Assistant

Jim Boyer 3224

George Curry 27429

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 12-2 2009 Section or Area Examined Pumps
Time of Examination: from 6:00 a.m. or p.m. to 1:30 a.m. or 6:00 p.m.
Was this report phoned to outside: Yes _____ no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH4	Violation or Hazardous Condition	Action Taken
HT. 13, 32 Seal, 37, HC17 Sump	0%	NONE OBSERVED	NONE
HT. 60, 77, 126	0%	NONE OBSERVED	NONE
HT. LBB Pumps 3, 15	0%	NONE OBSERVED	NONE
JB 3 sec 8, 14	0%	None observed	None
SB 4 sec 110's	0%	None observed	None
JB 19 B-K, EM 110's	0%	None observed	None
HT. 13			
8. _____			
9. _____			
10. _____			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	

Remarks: 0% CH4 0% CO 20.8% O2
TRACK, TRAVELWAYS, POWER BOXES, D. BOXES OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Harley Taylor 37002 Certificate No.
Preshift Mine Examiner
Countersigned Bob Foster 28736 Mine Manager—Mine Foreman
Jim Berger 32261 Assistant Foreman Certificate No.
Jim Peterson 29611 Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-2-9 Section or Area Examined South Pumps
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom brought outside Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include locations like TR EM'S 110's, TR 32 Seal 37, TR HG-17, etc., with handwritten entries 'none observed' and 'none'.

Air Measurements

Location CFM Location CFM

good air movement

Remarks: No CH4 Sect. 0% 20.50% CO2

Trach & Travelways clean at exam
Pumps e/c's D. Boxes Charges clean

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29011 Assistant Foreman
Countersigned [Signature] Certificate No. 28234 Mine Foreman
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No. _____

Mine Foreman-Mine Manager

Certificate No. _____

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-3 20 Section or Area Examined South-Kumps
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom
Report received by Brought Astute (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Entries include TP 50's 110's, TP 32 seal 37 etc, 0%, etc.

Air Measurements

Location CFM Location CFM

Good air movement

Remarks: No CH4 det 0% 20.5oz CO2
Tracks + Tramways clean at exam
Pumps flc D. Box Charge clean

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29019 Assistant Foreman
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 2373

Jim Boyer 35261 Superintendent or Assistant
Joey Stewart 39199

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-3-09 20 Section or Area Examined South Pumps
Time of Examination: from 7:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by Brought Out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CHY, Violation or Hazardous Condition, Action Taken. Contains 8 rows of inspection data with handwritten entries like 'EM 110's', '#32 real #37', 'AG 17 amp', etc.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good air movement'.

Remarks: O% CH4, O% CO, 20.8% O2 detected track, travelways, power lines, signal lines

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Certificate No. 32261
Countersigned [Signature] Certificate No. 28732
Assistant Foreman [Signature] Certificate No. 37002
Superintendent or Assistant [Signature] Certificate No. 29611

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 12-3 20-9 Section or Area Examined South Pumps
 Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom brought outside Time A.M. P.M.
 Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. TP Ems 110's 0%CH4	none observed	none
2. TP 32 sec 37 Ark, 0%	none observed	none
3. TP HG 17 0%	none observed	none
4. ^{5C} TP TP 5C 77 60 62 126 0%	none observed	none
5. TP 3 sec 18-8-14 0%	none observed	none
6. TP 4 sec 110's 0%	none observed	none
7. TP 19 Ark, 13-30 0%	none observed	none
8. TPLBB 0%	none observed	none
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location CFM Location CFM

good air movement

Remarks: NOCH4 det, 0% 20.8oz COO%
Track & Troneways clean at exam.
Pumps P/C 2 Box Chassis clean

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29611 Assistant Foreman [Signature] Certificate No. 39242
 Countersigned [Signature] Mine Manager - Mine Foreman 28236
 Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Date of Examination 12-4 209 Section or Area Examined South Pumps
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
TP Ems. 110's	0% CH ₄ none observed	none
TP 32 seal 37 mt.	0% CH ₄ none observed	none
TP HG 17 TP TO 36	0% CH ₄ none observed	none
4-77-60-62 126	0% CH ₄ none observed	none
TP 3 sec. 18-8-14	0% CH ₄ none observed	none
TP 4 sec. 110's	0% CH ₄ none observed	none
TP 19 mt.	0% CH ₄ none observed	none
TP LBB	0% CH ₄ none observed	none
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄ det. 0% CO₂ 20.50% CO₂
Traneways & track clear at exam
Pumps 110's D. Box charger clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 29611 Freshift-Mine Examiner Certificate No.
 Countersigned [Signature] 28734 Mine Manager—Mine Foreman Assistant Foreman Certificate No.

[Signature] 32261 Superintendent or Assistant [Signature] 39199

Use Indefinible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested

Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-4-09 Section or Area Examined Pumps
Time of Examination: from 1 a.m. or 9 p.m. to 4 a.m. or 10 p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include HT 1, HT 2, HT 3, LS 4, JB 5, SH 6, JB 7.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4 0% CO 20.8% O2
TRACK, TRAVELWAYS, POWER BOXES, D. BOXES OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Joey Stewart Preshift Mine Examiner Certificate No. 39199
Countersigned Rick Kosta Mine Manager - Mine Foreman Certificate No. 28734
Assistant Foreman Jim Sawyer Certificate No. 32261
Superintendent or Assistant [Signature]

DMS/Ed 1947-A

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made SOUTH

Date of Examination 12-4 2009 Section or Area Examined Pumps
Time of Examination: from 8:30 a.m. or 6 a. to 11:30 a.m. or 6 a.
Was this report phoned to outside: Yes no
By whom Report received by Brought out (Signed)
Time 10:55 a.m.

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 8 rows of data, all with 'None observed' and 'None' as action taken.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains one entry: 'Good Air movement'.

Remarks: 0% CH4, 2.0% O2, 0 PPM CO. Detected At time of exam
Track, travelways, Power Boxes, D-Boxes, OK At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Certificate No. 1947A
Countersigned [Signature] Certificate No. 28754
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-5-09 2009 Section or Area Examined Pumps South
Time of Examination: from 2:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom
Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10 listing locations like 'east main 110's' and '32 sec 1, 32 BRK' with 'None observed' and 'None' as results.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: 'Good Air movement'.

Remarks: 0% ch4, 20.8% O2, 0ppm C.o. Detected At Time of exam Tracks, Travelways, Power Boxes, D-Boxes OK At Time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By M. J. Cole Preshift Mine Examiner Certificate No. 1947A
Countersigned Rick Foster Mine Manager - Mine Foreman Certificate No. 28732
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____ 2-81

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Use Indelible Pencil or Ink

Report shall be signed when made

Date of Examination 12-5 2009 Section or Area Examined Pumps
 Time of Examination: from 7:00 a.m. or p.m. to 4:00 a.m. or p.m.
 Was this report phoned to outside: Yes _____ no ✓
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
HT 13, #32 Seal, 37,	0%	NONE OBSERVED	NONE
HT 60, 62, HG 17 Sump, 77	0%	NONE OBSERVED	NONE
HT LBB Pumps 3, 15	0%	NONE OBSERVED	NONE
4. EAST MAINS 110's	0%	NONE OBSERVED	NONE
5. 3 Sec #8	0%	NONE OBSERVED	NONE
6. _____			
7. _____			
8. _____			
9. _____			
10. 126 BK pump		RESET (PUMP DOWN) BREAKER ON OUTLET KNOCKING	Reported

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH₄ 0% CO 20.8% O₂
TRACK, TRAVELWAYS, POWER BOXES, D. BOXES OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Charley Taylor 37002 Certificate No. 28222 Assistant Foreman George Curry Certificate No. 27429
 Countersigned Rick Foster Mine Manager - Mine Foreman
 Assistant Foreman _____
 Superintendent or Assistant _____

Mgr/col 447-A

Use Indelible
Penell or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date 11/02 Shift 2nd Area or Section 2528

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-5-59 Section or Area Examined PUMPS south
Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Report received by Brought Time A.M. P.M.
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 13, #32 sec 1, 37 0% CH ₄	None observed	None
2. 60, 62, HG 17 SUMP, 77 0%	None observed	None
3. LBB Pumps, 3, 15 0%	None observed	None
4. East mains 110's 0%	None observed	None
5. 3 sec 9-14-18 0%	None observed	None
6.		
7.		
8.		
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: 0% CH₄, 20.8% O₂, 0PPM C.O., Detected At Time of Exam
TRACK, Travelways, Power Boxes, D-Boxes OK At Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1947-A
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 28236
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-6 2009 Section or Area Examined Pumps south

Time of Examination: from 3:00 P. or p.m. to 6:00 P. or p.m.

Was this report phoned to outside: Yes no

By whom Report received by Brought out Time A.M P.M.

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 5 entries for locations like '13, #32 seal 37 0%' and '60, 62, HG 17 sump, 77 0%'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten text 'Good AIR movement'.

Remarks: 0% CH4, 20.8% O2, 0ppm C.O., Detected At Time of exam

Tracks, Travel ways, Power Boxes, D-Boxes, OK At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1947-A Certificate No. Assistant Foreman Countersigned [Signature] 28734 Certificate No. Mine Manager - Mine Foreman

Assistant Foreman Superintendent or Assistant

George Curry 27429

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 12-16 2069 Section or Area Examined South Pumps
 Time of Examination: from 1200 a.m. or 300 p.m. to 300 a.m. or 000 p.m.
 Was this report phoned to outside: Yes no
 By whom Brought outside Time A.M. P.M.
 Report received by Brought outside
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. B32 seal 37BK $\frac{9}{10}$ CH ₄	none observed	none
2. 66, 67, HBT pump $\frac{9}{10}$ CH ₄	none observed	none
3. LBB pumps 3; 15BK $\frac{9}{10}$ CH ₄	none observed	none
4. E Mains 110D $\frac{9}{10}$ CH ₄	none observed	none
5. 3 sec 8-14-18 $\frac{9}{10}$ CH ₄	none observed	none
6. <u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
Good Air Movement	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: $\frac{9}{10}$ CH₄, $\frac{9}{10}$ CO, 20.8% O₂, tracks, travelways, pc's
 O-boles seen at seal

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By George Carr 27429 Certificate No.
 Preshift-Mine Examiner Assistant Foreman Certificate No.
 Countersigned Rich Edin 28734
 Mine Manager—Mine Foreman
Amf Peterson 29611
 Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-6-20 Section or Area Examined South - Pumps
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom brought outside Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for various locations like TP Em's 110 1/2, TP 32 sec, 37 Pul, etc., all with 'none observed' and 'none' action taken.

Air Measurements

Location CFM Location CFM

god air movement

Remarks:

Accident. 0% 20.8oz CO2
Track & travelways clear at exam
Pumps 1/2's D. Box Chasou clear

This is to certify that (a) this section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29011
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 28734
Assistant Foreman [Signature] Certificate No. 0947A
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	_____	_____	_____	11.	_____	_____	_____
2.	_____	_____	_____	12.	_____	_____	_____
3.	_____	_____	_____	13.	_____	_____	_____
4.	_____	_____	_____	14.	_____	_____	_____
5.	_____	_____	_____	15.	_____	_____	_____
6.	_____	_____	_____	16.	_____	_____	_____
7.	_____	_____	_____	17.	_____	_____	_____
8.	_____	_____	_____	18.	_____	_____	_____
9.	_____	_____	_____	19.	_____	_____	_____
10.	_____	_____	_____	20.	_____	_____	_____

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	_____	_____	_____	6.	_____	_____	_____
2.	_____	_____	_____	7.	_____	_____	_____
3.	_____	_____	_____	8.	_____	_____	_____
4.	_____	_____	_____	9.	_____	_____	_____
5.	_____	_____	_____	10.	_____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use: Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-7-09 Section or Area Examined South Pumps
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by Freight outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 rows of inspection data, mostly showing 0% CH4 and 'None observed'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains one entry for 'Good air movement'.

Remarks: 0% CH4 0% CO 20.8% O2 detected track, travelways, power lines safe at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Certificate No. 29611
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 28734

Assistant Foreman: [Signature] 32261
Superintendent or Assistant: [Signature] 39199
[Signature] 27429

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 12-7 2009 Section or Area Examined South Pumps
Time of Examination: from 1 a.m. or 6 p.m. to 4 a.m. or 6 p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. ^{JB} East Mains ^{LS} 110's ^{JB} 19, 30 CH ₄	NONE observed	NONE
2. 32 Seal, 37 BK ^{0%}	NONE observed	NONE
3. HG 17 Sump ^{0%}	NONE observed	NONE
4. 60, 62, 77, 126 ^{0%}	NONE observed	NONE
5. LBB ^{0%}	NONE observed	NONE
^{LS} 6. 3 Section 8, 18, 14 ^{0%}	NONE observed	NONE
^{LS} 7. 4 Section 110's ^{0%}	NONE observed	NONE
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0% CO₂, 20.8% O₂
Track, Travelway, Powercenters, D-Boxes, Pumps OK at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Jay Stewart 39199 Paul Sawyer 32261
Preshift Mine Examiner Certificate No. Assistant Foreman Certificate No.
Countersigned Richard [unclear] 23736 George Curry 29429
Mine Manager - Mine Foreman
[unclear] 29611
Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 12-7 20 9 Section or Area Examined South Pumps
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom brought outside Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
TP Em's 110's 19-30 O ₂ CH ₄	none observed	none
TP 32 sec 32 Meters 0%	none observed	none
TP HG 17 0%	none observed	none
TP TP GLE GLE 60-62 22-26 0%	none observed	none
TP LBB 0%	none observed	none
TP 3 sec 8-18-14 0%	none observed	none
TP 4 sec 110's 0%	none observed	none
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>			
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: No CH₄ det. 0% 20.8 or CO 0%
Tracks & Travelways clear at exam
Pumps floor D. Box charges clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 29611 Certificate No. 29235 Assistant Foreman [Signature] Certificate No. 1947A
Countersigned [Signature] Mine Manager—Mine Foreman [Signature] Assistant Foreman [Signature] Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 12-8 20 9 Section or Area Examined South Pump 3
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought outside Time A.M. P.M.
Report received by Brought outside
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
TP Em's 110's O2CH4	none observed	none
TP 32 and 37 hkt. O2CH4	none observed	none
TP Hg 17 SC 65 O2CH4	none observed	none
TP 60-27-12 6 O2CH4	none observed	none
TP LBB O2CH4	none observed	none
TP 3 sec. 8+4-18 O2CH4	none observed	none
TP 9 sec. 110's O2CH4	none observed	none
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location CFM Location CFM

good air movement

Remarks: NCH4 lect. 0% 20.80% CO2
Track-travelways clear at seam.
Pumps H/C's D. Box charger clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift-Mine Examiner Certificate No. 29611
Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 28234
[Signature] Assistant Foreman
[Signature] Superintendent or Assistant Certificate No. 1047-A
[Signature] 32261
[Signature] 27429

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-8 2027 Section or Area Examined South Pumps
Time of Examination: from 1200 a.m. or p.m. to 300 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by Brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like '1. EMs 110s' and 'HT 32 seal 37BK' with corresponding observations and actions.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: %O2, %CO, 20.8% tracks, travelways, pcs, boxes clear at all times

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By: [Signature] Certificate No. 27429
Countersigned: [Signature] Mine Manager - Mine Foreman Certificate No. 28236
Assistant Foreman: [Signature] Certificate No. 29011
Assistant Foreman: [Signature] Certificate No. 37002
Superintendent or Assistant: [Signature] Certificate No. 32261

July 5th 1947-A

Use Indefible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-8-20 Section or Area Examined South Pumps
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'TR Em's 110's' and 'TR 32 seal 37 Rk.' with 'none observed' and 'none' as actions.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'good air movement'.

Remarks: Rocky sect. 0% 20.80 or 20.00
Track & Transway clear at exam
Pumps 110's D. Box Chagan clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29611
Countersigned [Signature] Certificate No. 28734
Assistant Foreman [Signature] Certificate No. 1947A
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-9 20 9 Section or Area Examined South Pumps
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom
Report received by brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'TP Em's 110's', 'GLC HG 17', etc., with 'none observed' and 'none' as common entries.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'good air movement'.

Remarks: Noisy deck. Ok 20 or 2000 Pumps & Box Change P/c's clean travelways & track clear at exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29611
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 2373
Assistant Foreman [Signature] Certificate No. 1947-A

Superintendent or Assistant [Signature] George Curry 27429
[Signature] 32261

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-9-69 Section or Area Examined Pumps
Time of Examination: from 7:00 a.m. or p.m. to 4:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include HT 13, #32 Seal, TW2 H&I Sump, TW3 LBB Pumps, JB GC East Mains 110's, JB 3 Sec 8-14-18, GC #19, 30, SH 4 Sec 110's.

Table for Air Measurements with columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4 0% Co 20.8% O2
Tracks, Travelways, Power Boxes, D. Boxes OK AT TOE

Signed By Harley Taylor 37002 Certificate No.
Countersigned Mine Manager - Mine Foreman 29736 Assistant Foreman 29611
Superintendent or Assistant George Curry 39058-06 Certificate No. 1659-A 27429

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-9-20 Section or Area Examined South Pumps
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Entries include 'R. Eams 110's', '32-seal 37 tank', 'HG 17 60-62', '77-126', 'LBB 3-15', 'Sec. 3 8-14-18', '4 sec. 110's'. All violations listed as 'none observed' and actions as 'none'.

Air Measurements

Location CFM Location CFM

Good air movement

Remarks: No CH4 detected 20.50 CO2
Tracks travelways clean at exam
Pumps etc's D. Boxes Charges clean

This is to certify that (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 28256
Countersigned [Signature] Mine Manager - Mine Foreman Assistant Foreman Certificate No.

Assistant Foreman Superintendent or Assistant

Indelible
Pen or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 12-10 20-9 Section or Area Examined South Pumps
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought out safe
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
TP ₁ Em's 110's <u>Doc H4</u>	<u>none observed</u>	<u>none</u>
TP ₂ 32 seal 32 h/c <u>0%</u>	<u>none observed</u>	<u>none</u>
TP ₃ HC 17 60-62 <u>0%</u>	<u>none observed</u>	<u>none</u>
SC ₄ 77-124 <u>0%</u>	<u>none observed</u>	<u>none</u>
TP ₅ LBB 3-15 <u>0%</u>	<u>none observed</u>	<u>none</u>
TP ₆ Sc. 3 8-14-18 <u>0%</u>	<u>none observed</u>	<u>none</u>
TP ₇ 4 sec. 110's <u>0%</u>	<u>none observed</u>	<u>none</u>
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Doc H4 sect. 0% 20.5 or 000%
Track & Transways clean
Pumps HC D. Box charges clean

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29011
 Preshift-Mine Examiner Assistant Foreman Certificate No.
 Countersigned [Signature] Certificate No. 28736
 Mine Manager—Mine Foreman

Assistant Foreman: Jay Stewart 39199
 Superintendent or Assistant: Tom Canyon 32261

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 12-10 2009 Section or Area Examined Pumps
Time of Examination: from 6:00 a.m. or p.m. to 4:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH ₄	Violation or Hazardous Condition	Action Taken
HT 1.	13, #32 Seal, 37BK	0% ²	NONE OBSERVED	NONE
HT 2.	HG17 Sump, 60, 62, 77	0%	NONE OBSERVED	NONE
LS 3.	LBB Pumps 3+15	0%	None observed	None
LS 4.	EAST MAINS 110's	0%	None observed	None
5.	3 Sec 8-14-18, 16	0%	None observed	None
6.	#19, 30	0%	None observed	None
7.	4 Sec 110's	0%	None observed	None
LS 8.	126	0%	None observed	None
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH₄ 0% CO 20.8% O₂

TRACK, TRAVEL WAYS, POWER BOXES, D. BOXES OK AT TOE

#16 Brk pump on 3 section needs a starter box JB
(Not in service now)

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Harley Taylor 37002 Certificate No. 28732
 Countersigned Rich Taylor Mine Manager—Mine Foreman
Ray Stewart Assistant Foreman 32261 Certificate No. 39199
Ray Stewart Assistant Foreman 29611
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-10 20 9 Section or Area Examined South Pumps
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom
Report received by brought outside (Signed) Time A.M. P.M.

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for various locations like 'TR Em's 110's' and 'TR HG17 60-62-77' with 'none observed' and 'none' as actions.

Air Measurements

Location CFM Location CFM

good air movement

Remarks: NOCH4 detected @ 20.80% CO2
Tracks & travelways clear
Pumps etc's D. Boxes charger clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29611
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 28786
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-11 20. 9 Section or Area Examined South Pumps
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought outside Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'Em's 110's', 'HG 17 60-62-77', 'LABB 3-15', etc., with violations listed as 'none observed' and actions as 'none'.

Air Measurements

Location CFM Location CFM

good air movement

Remarks:

Rocky Sect. 0% 20.5oz CO2 0%
Track & Travelways clear at exam
Pumps, PLC D. Box Charger clear

This is to certify that (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29011 Assistant Foreman
Countersigned [Signature] Mine Manager--Mine Foreman Certificate No. 3873

Jay Stewart 39199

Tom Boyer 32261

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-11 20 09 Section or Area Examined Pumps
Time of Examination: from 7:00 a.m. or p.m. to 4:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Contains 7 rows of handwritten data.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten text 'Good Air Movement'.

Remarks: 0% CH4 0% CO 20.8%

TRACK, TRAVELWAYS, POWERBOXES, P. BOXES OK AT TOE

#16 Brk on 3 section needs started box JB

5 May 37222

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Harley Taylor 37002 Certificate No. Assistant Foreman
Countersigned Rick Kala 28235 Certificate No. 39199

May 1947-A

Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made
Pumps South

Date of Examination 12-11 2009 Section or Area Examined _____
 Time of Examination: from 2:30 a.m. or 0 p.m. to 11:30 a.m. or 6 p.m.
 Was this report phoned to outside: Yes _____ no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought out
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 13, 32 Seal, 37 BAK ^{CH4} 0%	None observed	None
2. MG17, SUPP, 60, 62, 77, 126 0%	None observed	None
3. east mains 110's 0%	None observed	None
4. 3 sec 8-14-16 0%	None observed	None
5. 19, 30 0%	None observed	None
6. 4 sec 110's 0%	None observed	None
7. LBB Pumps 3-15 0%	None observed	None
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good Air movement			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% ch4, 20.9% O2, 0 PPM CO, Detected At time of exam
Track Travelways OK At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Yusef Cole 1947-A
 Preshift Mine Examiner Certificate No.
 Countersigned Rick Bell 2872
 Mine Manager—Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-12-09 20 Section or Area Examined Pumps
Time of Examination: from 3:00 a.m. or 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by BROUGHT OUT (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Contains 8 rows of data regarding gas levels and observations at various locations like #13, 32, 37, HG17, #60, 62, 77, 126, EM 110's, 3 res #8, 14, 16, 18, #19, 30, 4 res 110's, and LBB pumps.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains one entry: Good Air movement.

Remarks: 0% ch4, 20.8% O2, 0PPM CO, Detected AT Time of exam Track, Travelways, OK AT Time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Freshift-Mine Examiner Certificate No. 1947A
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 2973C
Assistant Foreman Certificate No.

Jim [Signature] 32261 Jay Stewart 39199 George Curry 27429 Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____
 Mine Foreman-Mine Manager _____ Certificate No. _____
 Superintendent or Assistant _____

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 12-12 2009 Section or Area Examined Pumps
 Time of Examination: from 7:00 a.m. or p.m. to 4:00 m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
HT 1. 13, #32SEAL, 37BK	0%	NONE OBSERVED	NONE
HT 2. HG17Sump, 60, 62	0%	NONE OBSERVED	NONE
HT 3. 77, 126	0%	NONE OBSERVED	NONE
HT 4. LBB Pumps 3+15	0%	NONE OBSERVED	NONE
LS 5. EAST MAINS 110'S		NONE OBSERVED	NONE
LS 6. 3 Sec 8, 14, 16, 18		NONE OBSERVED	NONE
LS 7. 19BK, 30		NONE OBSERVED	NONE
8. 4 Sec 110'S			
9. _____			
10. _____			

Air Measurements

Location	CFM	Location	CFM
Good AIR MOVEMENT			

Remarks: 0% CH₄ 0% CO 20.8% O₂
TRACK, TRAVELWAYS, POWER BOXES, D. BOXES OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Charley Taylor Preshift-Mine Examiner Certificate No. 37002
 Countersigned Jay Stewart Assistant Foreman Certificate No. 39199
 _____ Mine Manager—Mine Foreman
 _____ Assistant Foreman
 _____ Superintendent or Assistant

MS/Col 1947-A

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-12-09 2009 Section or Area Examined Pumps South

Time of Examination: from 8:30 a.m. or P.M. to 11:30 a.m. or P.M.

Was this report phoned to outside: Yes no

By whom Report received by Brought out (Signed) Time A.M. P.M.

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Contains 8 rows of data, all showing 0% CH4 and 'None Observed'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good AIR movement'.

Remarks: 0% CH4, 20.8% O2, 0PPM CO, Detected AT TOE TRACK, Travelways, OK AT time OF exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1947A Assistant Foreman Countersigned [Signature] Mine Manager-Mine Foreman Assistant Foreman Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-13-09 20⁰⁹ Section or Area Examined Pumps South

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes no

By whom Report received by Brought out (Signed) Time A.M. P.M.

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Contains 8 rows of data, all with 'None observed' and 'None'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains one entry: 'Good Air movement'.

Remarks: 0% CH4, 20.8% O2, 0PPM CO detected AT TIME OF exam TRACK, Travelways OK AT TIME OF exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1947A Assistant Foreman Certificate No.

Countersigned [Signature] Mine Manager—Mine Foreman Assistant Foreman

[Signature] Superintendent or Assistant 27429 [Signature] 39199