

Started 3-31-2010

(#4) Barrier
Section

EXAMINATION OF ELECTRICAL EQUIPMENT

Company Performance Coal Company
Mine UBB - Barrier Section (#4)
Location _____
 Post Office County State

Re-order from
BJW Printing and
Office Supplies
P. O. Box 1309
Beckley, W. Va. 25801
Phone (304) 253-7361

Form 6—1492
(March 1970)

Budget Bureau No. 42-R1589
Approval expires 9-30-71

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. This book is approved by the Director of The West Virginia Department of Mines and The U. S. Bureau of Mines.

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3/31/2010	#4 Section	Forklift	No @ time of exam		Forklift Exam 3-90
3/31/2010	#4 Section	Forklift Charger	No @ time of exam		Forklift Exam 3-90
3/31/2010	#4 Section	Power Center	Weekly exam signs, fire ext, lid bolts, lights etc. - ok - No dangerous conditions found @ time of exam		Forklift Exam 3-90
3/31/2010	#4 Section	Splitter	weekly exam all ok - No dangerous conditions found @ time of exam		Forklift Exam 3-40
3/31/2010	#4 Section	FEEDER #4103	No DANGEROUS conditions found @ time of exam		Kenneth Dunn 4-836
3/31/2010	#4 Section	Maint Scoop Charger	No DANGEROUS conditions found @ time of exam		Kenneth Dunn 4-836
3/31/2010	#3 North	Belt head	Completed weekly exam no dangerous conditions found @ time of exam		Weekly tests of grounding devices (diodes)
3/31/2010	#4 Section	FEEDER	Fire suppression ok. At time of exam		Kenneth Dunn 4-836
3/31/10	4 Sec	LSC	Retaped cable / checked fire suppression		CMW 3-279
3/31/10	4 Sec	Maintain Scoop	washed / checked fire suppression		CMW 3-279
3-31-10	4 section	301 Right R/B	needs Dust hose replaced needs off side start switch reisolated 2 spec found		Dunn 4-845
3-31-10	4 section	301 Right R/B	visual exam of Fire suppression (OK)		James Bell 4-745
3-31-10	4 section	1 Scoop charger	were observed at time of Exam (Fire Ext OK)		James Bell 4-745
3-31-10	4 section	Right SIC 17640	were observed Lock is Brake were other observed at time of Exam		James Bell 4-745
3-31-10	4 section	Right SIC 17640	off side Red Button is Broken etc were other observed on Fire suppression		James Bell 4-745
4-1-10	4 sec	RCM	Replaced light Bulb / checked fire suppression (clean spray)		CMW 3-279
4-1-10	4 sec	U/M Jim 5849	Clean spray checked fire suppression No PU		HWG 4-836
4-1-10	4 section	Pressure Pump	- ok at time of exam		G Halpern
Monthly examinations of methane monitors					
4-1-10	4 section	048 Bolter	- retaped old splices		G Halpern
4-1-10	4 section	048 Bolter	Fire supp - ok at time of exam		G Halpern
4-1-10	4 section	641 5/c	- retaped old splices		G Halpern 4-94
4-1-10	4 section	641 5/c	Fire supp - ok at time of exam		G Halpern
4-1-10	4 section	230 Scoop	- needs breaker reset cable Reported		G Halpern
4-1-10	4 Section	230 Scoop	Fire supp - ok at time of exam		G Halpern

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4-1-10	4 Section	181 SC00P	replaced UVR Trac none other observed at time of Exam	Sum/Bad 4-740	
4-1-10	4 section	181 SC009	visl exam of fire suppressor Ok	Sum/Bad 4-745	
4-1-10	4 section	Power center	two Brake ground trip switch circuit 2 and 3 1 Bad Female rest	Sum/Bad 4-745	

Examinations of low- medium-voltage power circuit breakers (monthly)

