

L/WA 11

Weekly Examinations For Methane And Hazardous Conditions

Company Performance Coal
Mine UBB
Location _____
Post Office _____ County Raleigh State WV

EP-LW 1
EP-LW 2
Primary Excavation

	Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
Entries	1-6-10	LW1	0	20.8	0	30,160	To outside	<i>W.D. Cully</i>	28045
3	1-6-10	LW2	0	20.8	0	48,360	TD outside	<i>W.D. Cully</i>	28045
4	1-6-10	"	0	20.8	0	53,100	TD Outside	<i>W.D. Cully</i>	28045
5	1-6-10	"	0	20.8	0	54,010	TD Outside	<i>W.D. Cully</i>	28045
6	1-6-10	"	0	20.8	0	11,175	TD Outside	<i>W.D. Cully</i>	28045
							FD outside		

W.D. Cully 28045

Air Way Travels

Traveled 4/wall Primary escapeway from LOB to 12-Bk. HL

Signature _____

Mine Foreman

Certificate No. _____

Superintendent of Company _____

Entrance

	Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
	1-13-10	LW1	0	20.8	0	30,000	To outside	W.D. Lilly	28045
4	1-13-10	LW2	0	20.8	0	48,010	To outside	W.D. Lilly	28045
5		"	0	20.8	0	52,000	To outside	W.D. Lilly	28045
6		"	0	20.8	0	54,080	To outside	W.D. Lilly	28045
7		"	0	20.8	0	11,115	To outside	W.D. Lilly	28045

W.D. Lilly 28045

Air Readings

[Lined area for recording air readings]

Signature _____
 Mine Foreman

_____ Certificate No.

_____ Superintendent of Company

Air Way Travels

Travelled Primary Escapeway L/wall from LOB to #12 Blk. #2

Neil Lilly 2804r

Signature _____
Mine Foreman

_____ Certificate No.

_____ Superintendent of Company

	Date	EP	CH ₄	O ₂	CO	Cfm	Direction of Air	Signature	Certification #
	1-20-10	LW1	0	20.7	0	39,400	TO Outside	W.D. Cully	28048
4	1-20-10	LW2	0	20.8	0	48,100	TO Outside	W.D. Cully	28048
5	1-20-10	"	0	20.6	0	52,160	TO Outside	W.D. Cully	28048
6	1-20-10	"	0	20.6	0	54,890	TO Outside	W.D. Cully	28048
7	1-20-10	"	0	20.7	0	11,090	TO Outside	W.D. Cully	28048

W.D. Cully 28048

Air Way Travels

Traveled Primary escapeway from LOB + wall to #12 Blk.

W.D. Lilly 28045

Signature _____
Mine Foreman

_____ Certificate No.

_____ Superintendent of Company