

8 5-18-10-18

Started 11-22-09

# PRESHIFT - ONSHIFT and DAILY REPORT

L/W Const

Company Performance Coal

Mine UBB

SECTION L/W Const

LOCATION Naoma Raleigh WV  
Post Office County State

# Finished 12-8-09

Form 6-1489  
(March 1970)

Bureau of Mines

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-22 2009 Section or Area Examined L/W Const  
 Time of Examination: from 12 a.m. or 0 p.m. to 3 a.m. or 0 p.m.  
 Was this report phoned to outside: Yes  no   
 By whom John N Time A.M. 245  P.M.  
 Report received by Jay Stenat 39199  
 (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>D-Boxes</u>	<u>none observed</u>	<u>NONE</u>
2. <u>Chargers</u>	<u>NONE observed</u>	<u>NONE</u>
3. <u>Work Area</u>	<u>NONE observed</u>	<u>NONE</u>
4. <u>Power Centers</u>	<u>NONE observed</u>	<u>NONE</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> Detected at etam  
Track, Travelways OK at etam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely 33472  
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.  
 Countersigned [Signature] [Signature]  
 Mine Manager—Mine Foreman  
Mike Bailey 27085  
 Assistant Foreman Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-22-07 20 Section or Area Examined Longwall Construction
Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Mike Deilen Time A.M. 11:10 P.M.
Report received by [Signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CHY, Violation or Hazardous Condition, Action Taken. Rows 1-4 contain handwritten entries: 1. Work Area, CHY, None observed, None; 2. Power Center, CHY, None observed, None; 3. D-Boxes, CHY, None observed, None; 4. Chargers, CHY, None observed, None.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1 contains handwritten entry: Good Air Movement.

Remarks: OUCHY openings 20-25 ft
Track & Travelways ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 35400
Assistant Foreman Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-23 2009 Section or Area Examined Longwall Construction

Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.

Was this report phoned to outside: Yes \_\_\_\_\_ no \_\_\_\_\_

By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.

Report received by \_\_\_\_\_  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	WORK AREA	0% CH <sub>4</sub> None observed	None
2.	Power center	0% CH <sub>4</sub> None observed	None
3.	D-Boxes	0% CH <sub>4</sub> None observed	None
4.	Charger's	0% CH <sub>4</sub> None observed	None
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
GOOD AIR MOVEMENT			

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0.1ppm C.O., Detected At Time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085

Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 33472

[Signature] Assistant Foreman

[Signature] Superintendent or Assistant

Use Indelible  
Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-23 Section or Area Examined 2009 Longwall Construction  
 Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom John Neely Time 2:46 A.M. P.M.  
 Report received by John Neely 59199 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. WORK AREA	0%	NONE OBSERVED	NONE
2. POWER CENTER	0%	NONE OBSERVED	NONE
3. D. BOXES	0%	NONE OBSERVED	NONE
4. CHARGERS	0%	NONE OBSERVED	NONE
5. _____			
6. _____			
7. _____			
8. _____			
9. _____			
10. _____			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			
_____			
_____			
_____			
_____			
_____			
_____			
_____			
_____			

Remarks: 0% CH<sub>4</sub> 0% CO 20.8% O<sub>2</sub>

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely 33472  
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.  
 Countersigned Carl Cook 35660  
 Mine Manager—Mine Foreman  
Mike Bailey 27085  
 Assistant Foreman Superintendent or Assistant



Use Indefinible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-23-09 20 Section or Area Examined Longwalk Constr.
Time of Examination: from 8:30 a.m. or P.M. to 11:30 a.m. or P.M.
Was this report phoned to outside: Yes no
By whom Mike Bailey Time A.M. 11:05 P.M.
Report received by Steve Goh 3124 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows 1-4 contain handwritten entries: 1. Power Center, CH4 OK, None observed, None; 2. Work Area, CH4 OK, None observed, None; 3. D. Boxes, CH4 OK, None observed, None; 4. Chargers, CH4 OK, None observed, None.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1 contains handwritten entry: Good Air Movement.

Remarks: OK CH4, 0ppm CO2, 20.8% O2 detected at time of exam
Track & Travelling OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
Countersigned Assistant Foreman Certificate No. 3124
Assistant Foreman Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-24-09 Section or Area Examined 4W Conat.
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CHA, Violation or Hazardous Condition, Action Taken. Includes handwritten entries for 'Dance Center', 'Work Area', 'D-Bases', and 'Chargus'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Includes handwritten entry 'Good Air Measurement'.

Remarks: 0% CHA 20.8% O2 DCD
Track Troubleshooting OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Mike Bailey Freshift-Mine Examiner Certificate No. 27085
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33472
Assistant Foreman [Signature] Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-24 2009 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 a.m. or 12:00 p.m. to 3:00 a.m. or 3:00 p.m.
Was this report phoned to outside: Yes [checked] no
By whom John Neely Time A.M. 2:45 P.M.
Report received by Charley Taylor 37002 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include Power Center, Work Area, D. BOXES, CHARGERS, all with 0% CH4 and NONE observed.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4 0% CO 20.8% O2 TRACK & TRAVELWAYS OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely Preshift-Mine Examiner Certificate No. 33472
Countersigned [Signature] Mine Manager - Mine Foreman Assistant Foreman Certificate No.
Assistant Foreman Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-24-01 20 Section or Area Examined Longwall Constr.  
 Time of Examination: from 8:32 a.m. or P.M. to 11:30 a.m. or P.M.  
 Was this report phoned to outside: Yes  no   
 By whom Mike Bailey Time A.M. 11:10 P.M.  
 Report received by Steve Gyles 3104  
 (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	CH4	Violation or Hazardous Condition	Action Taken
1. <u>Power Center</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
2. <u>Chargers</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
3. <u>Work Area</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
4. <u>D-Boxes</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: OX CH4 open co, 20.35 oz detected at time of exam  
Track & Travelways ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27185  
 Countersigned [Signature] Mine Manager—Mine Foreman Assistant Foreman Certificate No. \_\_\_\_\_  
 Assistant Foreman Superintendent or Assistant \_\_\_\_\_



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-25 2009 Section or Area Examined Langwell Condit.  
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.  
Was this report phoned to outside: Yes  no   
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Power Center CH#</u>	<u>None Observed</u>	<u>Reported</u>
2. <u>D-Base</u>	<u>" "</u>	<u>"</u>
3. <u>Work Area</u>	<u>" "</u>	<u>"</u>
4. <u>Chargers</u>	<u>" "</u>	<u>"</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH# 20.8% O<sub>2</sub> 0 CO  
Track Travelway O.K.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Nick Bailey Preshift-Mine Examiner Certificate No. 27085  
Countersigned Charles Cook Mine Manager—Mine Foreman Assistant Foreman Certificate No. 33472  
Johnny Neely Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date                      Shift                      Area or Section                     

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. -----	-----	-----
2. -----	-----	-----
3. -----	-----	-----
4. -----	-----	-----
5. -----	-----	-----
6. -----	-----	-----
7. -----	-----	-----
8. -----	-----	-----

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. -----	-----	-----	11. -----	-----	-----
2. -----	-----	-----	12. -----	-----	-----
3. -----	-----	-----	13. -----	-----	-----
4. -----	-----	-----	14. -----	-----	-----
5. -----	-----	-----	15. -----	-----	-----
6. -----	-----	-----	16. -----	-----	-----
7. -----	-----	-----	17. -----	-----	-----
8. -----	-----	-----	18. -----	-----	-----
9. -----	-----	-----	19. -----	-----	-----
10. -----	-----	-----	20. -----	-----	-----

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. -----	-----	-----	6. -----	-----	-----
2. -----	-----	-----	7. -----	-----	-----
3. -----	-----	-----	8. -----	-----	-----
4. -----	-----	-----	9. -----	-----	-----
5. -----	-----	-----	10. -----	-----	-----

Number of Bolts Tested                       
Number of Bolts Torqued Above Range                      Below Range                     

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken                     

Remarks (Statement as to General Conditions of Mine or Area of Mine)                     

Assistant Mine

Certificate No.

Mine Foreman, Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-25 2009 Section or Area Examined Longwall Construction  
Time of Examination: from 12:00 a.m. or 3:00 p.m. to 3:00 a.m. or 3:00 p.m.  
Was this report phoned to outside: Yes  no   
By whom John Neely Time 2:27 A.M. P.M.  
Report received by Stanley Taylor 37002 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. POWER CENTER	0%	NONE OBSERVED	NONE
2. D. BOXES	0%	NONE OBSERVED	NONE
3. WORK AREA	0%	NONE OBSERVED	NONE
4. CHARGERS	0%	NONE OBSERVED	NONE
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub> 0% CO 20.8% O<sub>2</sub>  
TRACK & TRAVELWAYS OK

Glen Ullman IS 39-A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.  
Signed By John Neely 33472 Certificate No.  
Countersigned Stanley Taylor 37002 Mine Manager - Mine Foreman Assistant Foreman Certificate No.  
Assistant Foreman Superintendent or Assistant

27 Nov 1947-A

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-25 2009 Section or Area Examined Longwall Construction

Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes no

By whom Time A.M. P.M.

Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include Powercenter, D-Boxes, work Area, Chargers, all with 0% ch4 and None observed.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% ch4, 20.8% O2, 0ppm C.O., Detected At Time of exam

Track, Travelways, OK At Time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dennis Ullman 1539-A Certificate No. Assistant Foreman Certificate No.

Countersigned [Signature] Mine Manager - Mine Foreman 3542 Certificate No.

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_ Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-26 2009 Section or Area Examined Longwall Construction
Time of Examination: from 3:00 p.m. to 6:00 p.m.
Was this report phoned to outside: Yes no
By whom
Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for Power center, D-Boxes, Work Area, and Chargers, all with 'None observed' and 'None' action.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: 0% ch4, 20.8% O2, 0ppm CO2, Detected At Time of Exam

Track, Travelways, OK At Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dan Ullman Preshift-Mine Examiner Certificate No. 15397A
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 370000
Assistant Foreman Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-26-09 20 Section or Area Examined Long wall Construction
Time of Examination: from 12:00 m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4 %, Violation or Hazardous Condition, Action Taken. Rows include Power Center, D-Boxes, WORK AREA, CHARGERS, all with 0% CH4 and None Observed/None action.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movements.

Remarks: 0% CH4, 20.8% O2, 0.4ppm CO Detected at time of exam
TRACK, TRAVELWAYS OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Russell Gunnice 1536-A Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
Countersigned [Signature] 3244 Mine Manager-Mine Foreman Assistant Foreman
Superintendent or Assistant [Signature] 1536A

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-22-20 Section or Area Examined New Const  
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.  
Was this report phoned to outside: Yes no  
By whom Time A.M. P.M.  
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for Power Center, D. Box, Work Area, and Change.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good air movement'.

Remarks: No 4 Let O2 20.50 CO2  
Track & travelway's clear of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 15399 Assistant Foreman  
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 39065  
Assistant Foreman  
Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-27-09 20 Section or Area Examined LWall construction
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M P.M.
Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-4 contain handwritten entries: 1. Powercenters, none observed, none; 2. D.Box, none observed, none; 3. Work Area, none observed, none; 4. Chargers, none observed, none.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. One handwritten entry: Good Air mount.

Remarks: 02064 0200 20.88 02
Track Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dan Williams Preshift-Mine Examiner Certificate No. 15394
Countersigned Cash... Mine Manager-Mine Foreman Assistant Foreman
Johnny Neely Superintendent or Assistant Certificate No. 33472

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-27 2009 Section or Area Examined Longwall Constructions  
Time of Examination: from 12:00 a.m. or (p.m) to 3:00 a.m. or (p.m)  
Was this report phoned to outside: Yes  no   
By whom John Neely Time A.M 12:55 (P.M)  
Report received by Harley Taylor 37002  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>POWER CENTERS</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>D. BOXES</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>WORK AREA</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. <u>CHARGERS</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub> 0% CO 20.8% O<sub>2</sub>  
TRACK + TRAVELWAYS OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John Neely 33472 Certificate No. Assistant Foreman Certificate No.  
Countersigned Harley Taylor 37002 Mine Manager—Mine Foreman  
White Bailey Assistant Foreman 27085 Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
 Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_  
 If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-27-09 20 Section or Area Examined Longwall Construction  
Time of Examination: from 8:30 a.m. or (p.m.) to 11:30 a.m. or (p.m.)  
Was this report phoned to outside: Yes  no   
By whom Barly Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by Dan Williams 15397A  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Powercenters CH4 O2	None Observed	None
2. D-Box O2	None Observed	None
3. Work Area O2	None Observed	None
4. Chargers O2	None Observed	None
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good Airment	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: O2 CH4, O2 CO, 20.82 O2  
Track, Travelways OK at TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.  
Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085  
Countersigned [Signature] Mine Manager - Mine Foreman Assistant Foreman Certificate No. \_\_\_\_\_  
Assistant Foreman  
Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-28 2009 Section or Area Examined LW Canal  
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.  
Was this report phoned to outside: Yes \_\_\_\_\_ no \_\_\_\_\_  
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Power Center	CH <sub>4</sub> None Observed	Reported
2. Changer	" "	"
3. Work Area	" "	"
4. D-Basis	None Observed	Reported
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good air movement			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Track Travelways OK  
0% CH<sub>4</sub> 20.8% O<sub>2</sub> 0 CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085  
Countersigned John Neely Mine Manager—Mine Foreman Assistant Foreman Certificate No. 33472  
John Neely Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

	<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

*Examinations for Methane in Working Places*

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	11.	_____	_____	_____
2.	_____	_____	_____	12.	_____	_____	_____
3.	_____	_____	_____	13.	_____	_____	_____
4.	_____	_____	_____	14.	_____	_____	_____
5.	_____	_____	_____	15.	_____	_____	_____
6.	_____	_____	_____	16.	_____	_____	_____
7.	_____	_____	_____	17.	_____	_____	_____
8.	_____	_____	_____	18.	_____	_____	_____
9.	_____	_____	_____	19.	_____	_____	_____
10.	_____	_____	_____	20.	_____	_____	_____

*Examinations for Methane in Return Aircourses*

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	6.	_____	_____	_____
2.	_____	_____	_____	7.	_____	_____	_____
3.	_____	_____	_____	8.	_____	_____	_____
4.	_____	_____	_____	9.	_____	_____	_____
5.	_____	_____	_____	10.	_____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-28-09 Section or Area Examined Long-Wall Const.
Time of Examination: from 1200 a.m. or p.m. to 2 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom John Neely Time A.M. P.M.
Report received by John G. Beckford (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10. All violations listed as 'None Observed' and actions as 'None'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% ch4 0% CO & 20.8% O2 detected at time of exam

Track & Travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John Neely, Preshift-Mine Examiner (Certificate No. 33472)
Countersigned John G. Beckford, Mine Manager-Mine Foreman (Certificate No. 37060-01)
Mike Bailey, Assistant Foreman (Certificate No. 27005)
Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-28-09 20 Section or Area Examined L/wall construction
Time of Examination: from 8:30 a.m. or p.m. to 10:0 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Bally Time A.M. P.M.
Report received by Dan Williams 1539A (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for Power center, Chargers, Work Area, and O-Boxes, all with 'None observed' and 'None' action taken.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Return A'.

Remarks: O2 CH4, O2 CO, 20.82 O2

TRACK TRACELWAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Barby 27085 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
Countersigned Charles Cook 390600-04 Mine Manager-Mine Foreman
Assistant Foreman Superintendent or Assistant



Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported		
Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-27-09 20\_\_ Section or Area Examined Wall Construction  
Time of Examination: from 7 a.m. on PM to 6 a.m. PM  
Was this report phoned to outside: Yes \_\_\_ no X  
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_  
(Signed) \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Power Center OTO</u>	<u>None Observed</u>	<u>Reported</u>
2. <u>Charge</u>	<u>" "</u>	<u>"</u>
3. <u>D-Bakes</u>	<u>" "</u>	<u>"</u>
4. <u>Work Area</u>	<u>None Observed</u>	<u>Reported</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Grand Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Trench Traversing OK  
O To CH4 20.8 To DC 0 CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Benby Preshift Mine Examiner Certificate No. 27185  
Countersigned Arthur Cochran Mine Manager—Mine Foreman Certificate No. 3966001  
Assistant Foreman Johnny Deely Certificate No. 33472  
Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-29 2009 Section or Area Examined L/W Const  
 Time of Examination: from 12 a.m. or 0 p.m. to 3 a.m. or 0 p.m.  
 Was this report phoned to outside: Yes no  
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_ (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Power Center</u>	<u>NONE observed</u>	<u>NONE</u>
2. <u>Changens</u>	<u>NONE observed</u>	<u>NONE</u>
3. <u>D-Boxes</u>	<u>NONE observed</u>	<u>NONE</u>
4. <u>Work Area</u>	<u>NONE observed</u>	<u>NONE</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Track + Travelway  
0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub>

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Deely Preshift-Mine Examiner Certificate No. 33472  
 Assistant Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_  
 Countersigned Mike Bailey Mine Manager—Mine Foreman Certificate No. 33000014  
Mike Bailey Assistant Foreman Certificate No. 29085  
 Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT**  
**MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11-29-07 20. Section or Area Examined L/W Const.  
 Time of Examination: from 8:30 a.m. or P.M. to 11:30 a.m. or P.M.  
 Was this report phoned to outside: Yes  no   
 By whom Mike Bailey Time 10:55 A.M. P.M.  
 Report received by John Smith  
 (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Power Center</u>	<u>CH<sub>4</sub></u>	
2. <u>D-Boxes</u>		
3. <u>Charges</u>		
4. <u>Work Area</u>		
5. _____		
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			
_____			
_____			
_____			
_____			
_____			
_____			
_____			
_____			

Remarks: OK CH<sub>4</sub> 0 ppm CO<sub>2</sub> 20.8% wd detected at time of exam  
Track's travelings ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey 27085  
 Preshift-Mine Examiner Certificate No.  
 Countersigned John Smith 370000  
 Mine Manager—Mine Foreman Assistant Foreman Certificate No.  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-30-69 Section or Area Examined L.W. Conner  
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.  
Was this report phoned to outside: Yes no  
By whom Time A.M. P.M.  
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for 'Panes Center', 'D-Box', 'Charger', and 'Wack Area'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Measurement'.

Remarks: Track Trackage OK  
0% CH4 20.8% O2 0 CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085  
Countersigned [Signature] Mine Manager-Mine Foreman  
Assistant Foreman Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-30 2009 Section or Area Examined L W Construction
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no X
By whom Brought Out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported.

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include Power Center, D-Boxes, CHARGERS, Work Areas, all with 0% CH4 and None Observed/None.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air movement.

Remarks: TRACK, Travelways OK
0% CH4, 20.8% O2, 0ppm CO detected at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Sumner Preshift-Mine Examiner Certificate No. 1536-A Assistant Foreman Certificate No.
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 38060-28 Assistant Foreman
Superintendent or Assistant

Mines Act 1947-A

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-30-09 20 Section or Area Examined h/v Constr.

Time of Examination: from 8:29 a.m. or 8:29 p.m. to 11:30 a.m. or 11:30 p.m.

Was this report phoned to outside: Yes no. [checked]

By whom brought out Time A.M. 10:10 P.M.

Table with 4 columns: Location, CFM, Violation or Hazardous Condition, Action Taken. Rows 1-10.

Table for Air Measurements with columns: Location, CFM, Location, CFM.

Remarks: O2 CH4, oppm co, 20.8% O2 detected at time of exam. Track & Travelways ok at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report. Signed By [Signature] Preshift-Mine Examiner Certificate No. 3704 Assistant Foreman Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 38000-08 Assistant Foreman Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 12-1-09 20... Section or Area Examined L/WALK Consta.  
 Time of Examination: from 3:22 a.m. or p.m. to 6:02 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom Brought out Time 5:02 AM P.M.  
 Report received by \_\_\_\_\_ (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. Power Center's	0%	None observed	None
2. D-Boxes	0%	None observed	None
3. Chargers	0%	None observed	None
4. Work Area	0%	None observed	None
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
Good Air movement	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, oppm co, 20.8% O<sub>2</sub> detected at time of exam  
Track & Travelways ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 39246  
 Countersigned [Signature] Mine Manager—Mine Foreman Assistant Foreman Certificate No. 290600  
 \_\_\_\_\_ Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant

Russell Dunnoe 1536-A

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 12-1 2009 Section or Area Examined Longwall Construction  
 Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.  
 Was this report phoned to outside: Yes \_\_\_\_\_ no X  
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Power Center</u>	<u>CH<sub>4</sub> 0%</u> <u>None Observed</u>	<u>None</u>
2. <u>D-Boxes</u>	<u>0%</u> <u>None Observed</u>	<u>None</u>
3. <u>Chargers</u>	<u>0%</u> <u>None Observed</u>	<u>None</u>
4. <u>WORK AREA</u>	<u>0%</u> <u>None Observed</u>	<u>None</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, Open Co detected at time of exam  
Track + Travelways OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dunning 1536-A  
 Preshift-Mine Examiner Certificate No.  
 Countersigned John Cook 39042  
 Mine Manager—Mine Foreman Assistant Foreman Certificate No.  
 \_\_\_\_\_  
 Assistant Foreman  
 \_\_\_\_\_  
 Superintendent or Assistant



Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-1-07 20 Section or Area Examined L/WALL Conste.
Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. 10:50 P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include Power Center, Work Area, Chargers, O-Boxes, and empty rows 5-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1 contains 'Good Air movement'.

Remarks: 0% CH4, open co, 20-25% O2 detected at time of exam
Track, travel ways ok at time of exam

Signature of Examiner

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift-Mine Examiner Certificate No. [Number] Assistant Foreman [Signature] Certificate No. [Number]
Countersigned [Signature] Mine Manager-Mine Foreman Assistant Foreman Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-2-09 20 Section or Area Examined H/WALK Costr  
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.  
Was this report phoned to outside: Yes no  
By whom Brought out Time 5:05 A.M. P.M.  
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows 1-10. Handwritten entries: 1. Power Center's CH4 OK, None observed, None. 2. O-Boxes CH4 OK, None observed, None. 3. Work Area CH4 OK, None observed, None. 4. Chargers CH4 OK, None observed, None.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Handwritten entry: Good Air Movement.

Remarks: OK CH4, oppm co, 20-30% detected at time of exam  
Track & Traveling; OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.  
Signed By Dan Williams Preshift-Mine Examiner Certificate No. 15897  
Countersigned Charles Cook Mine Manager-Mine Foreman Certificate No. 3700122  
Assistant Foreman Superintendent or Assistant

John A. Bickford 26176

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 12.2 2009 Section or Area Examined Long Wall Const.  
 Time of Examination: from 12:00 a.m. or PM to 1:30 a.m. or PM  
 Was this report phoned to outside: Yes no  
 By whom R. Wright Time          A.M.          P.M.  
 Report received by          (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>Power Center</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
2. <u>D'Bois</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
3. <u>Work Area</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
4. <u>Cheyers</u>	<u>0%</u>	<u>None observed</u>	<u>None</u>
5. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: 07.0 by 07.00 + 20.9% O<sub>2</sub> detected  
Trench + trambways clear at time of exam  
Fan off 1:30 PM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John B. Beckford Preshift-Mine Examiner Certificate No. 22171  
 Countersigned          Mine Manager—Mine Foreman Assistant Foreman Certificate No. 38209  
 Assistant Foreman Superintendent or Assistant

Use Indefinible  
Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 12-2-09 20. Section or Area Examined LW const.

Time of Examination: from 3:00 a.m. or p.m. to 5:00 a.m. or p.m.

Was this report phoned to outside: Yes  no

By whom Russell Gurnoe Time 5:12 A.M.  P.M.

Report received by Brian Collins 1543-A  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Powercenters CH4 0%	none observed	none
2. D-boxes 0%	none observed	none
3. Work Area's 0%	none observed	none
4. Chargers 0%	none observed	none
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>ground air movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 20.8% O2 0% CH4 0.11% CO at time of exam

Track + tunneling done at TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gurnoe  
Preshift-Mine Examiner

1536-A  
Certificate No.

Brian Collins  
Assistant Foreman

1543-A  
Certificate No.

Countersigned \_\_\_\_\_  
Mine Manager—Mine Foreman

392000

Joseph Beckford

Assistant Foreman

Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT**  
**MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 12-2-09 20. Section or Area Examined LW CONSTRUCTION  
 Time of Examination: from 830 a.m. or 1130 p.m. to 1130 a.m. or 1130 p.m.  
 Was this report phoned to outside: Yes no  
 By whom Bryant Time AM P.M.  
 Report received by \_\_\_\_\_  
 (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Power Centers <u>CH4 O2</u>	<u>none observed</u>	<u>none</u>
2. O Boxes <u>O2</u>	<u>none observed</u>	<u>none</u>
3. Work Areas <u>O2</u>	<u>none observed</u>	<u>none</u>
4. Chargers <u>O2</u>	<u>none observed</u>	<u>none</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

### Air Measurements

Location	CFM	Location	CFM
<u>Coal Plant</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 02 CH4 02 CO 208202

Track, Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 15394  
 Preshift-Mine Examiner Certificate No. \_\_\_\_\_ Assistant Foreman Certificate No. \_\_\_\_\_  
 Countersigned [Signature] 37044  
 Mine Manager—Mine Foreman  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 12-3-09 20 Section or Area Examined L/WALK Constr.  
 Time of Examination: from 5:00 a.m. or p.m. to 6:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no / no ✓  
 By whom Brought out Time 5:10 PM  
 Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH4	Violation or Hazardous Condition	Action Taken
1. <u>Power Center's</u>	<u>OK</u>	<u>None observed</u>	<u>None</u>
2. <u>D-Doke's</u>	<u>OK</u>	<u>None observed</u>	<u>None</u>
3. <u>Charger's</u>	<u>OK</u>	<u>None observed</u>	<u>None</u>
4. <u>Work Area</u>	<u>OK</u>	<u>None observed</u>	<u>None</u>
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: OK CH4 approx 0.03% detected at time of exam  
Track & Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Dem Williams 1539A Certificate No. Assistant Foreman Certificate No.  
 Countersigned Charles Lee Mine Manager—Mine Foreman Assistant Foreman  
 Superintendent or Assistant

John A. Bickel 26176

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 12-3 2009 Section or Area Examined H/wall Const.  
Time of Examination: from 2:00 a.m. or p.m. to 2:30 a.m. or p.m.  
Was this report phoned to outside: Yes  no   
By whom John Beckford Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by Rick Hutchins  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Powercables 0%CH4</u>	<u>N/O</u>	<u>Reported</u>
2. <u>D-Box's 0%CH4</u>	<u>N/O</u>	<u>Reported</u>
3. <u>Chargers 0%CH4</u>	<u>N/O</u>	<u>Reported</u>
4. <u>Work Area 0%CH4</u>	<u>N/O</u>	<u>Reported</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0%CH4, 20.8oz Detected at Time of Exam  
Track Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Beckford 26176  
FRESHIFT-MINE EXAMINER Certificate No.  
Countersigned Rick Hutchins 37569  
Mine Manager—Mine Foreman Assistant Foreman Certificate No.  
Rick Hutchins 37569  
Assistant Foreman Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_

Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-4-04 20 Section or Area Examined L/Walk Constr.
Time of Examination: from 3:00 p.m. to 5:25 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time 5:25 A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CFM, Violation or Hazardous Condition, Action Taken. Rows 1-4 contain handwritten entries: 1. Power Center, 2. Work Area, 3. D-Socks, 4. Charger's. All violations are listed as 'None observed' and actions as 'None'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Handwritten entry: 'Good Air Movement' in the first Location column.

Remarks: 0.1 CFM approx 20-30 ft detected at time of exam
Track & Travelway's OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 15397
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 3906025
Assistant Foreman Superintendent or Assistant

John A. Bickford 26176



Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 12-4 2009 Section or Area Examined Longwall Construction  
 Time of Examination: from 12:00 a.m. or 9:00 p.m. to 3:00 a.m. or 6:00 p.m.  
 Was this report phoned to outside: Yes  no   
 By whom John Bickford Time A.M. 2:58 P.M.  
 Report received by T. Moore (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. <u>POWER CENTER</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>WORK AREA</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>D. BOXES</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. <u>CHARGERS</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub> 0% CO 20.8% O<sub>2</sub>  
TRACK & TRAVELWAYS OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford Certificate No. 26176 Assistant Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_  
 Countersigned \_\_\_\_\_ Mine Manager—Mine Foreman \_\_\_\_\_  
Mike Bailey Assistant Foreman \_\_\_\_\_ Certificate No. 27085 Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-4-09 Section or Area Examined Longwall construction  
Time of Examination: from 8:30 a.m. or 9 a.m. to 11:30 a.m. or 6 p.m.  
Was this report phoned to outside: Yes  no   
By whom Mike Bailey Time A.M. 11:00 P.M.   
Report received by [Signature] 1947-A (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Power center CH <sub>4</sub> 0%	None observed	None
2. work Area 0%	None observed	None
3. D-Boxes 0%	None observed	None
4. chargers 0%	None observed	None
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good Air Movement	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm C.O. Detected AT TIME OF EXAM  
TRACK, TRAVELWAYS OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Freshift-Mine Examiner Certificate No. 27085  
Countersigned [Signature] Mine Manager—Mine Foreman Assistant Foreman Certificate No. 5466  
Assistant Foreman  
Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine. \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 12-5 2009 Section or Area Examined LW Conet.  
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.  
Was this report phoned to outside: Yes  no   
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Power Center 0% CH<sub>4</sub></u>	<u>None Observed</u>	<u>Reported</u>
2. <u>Work Area</u>	<u>" "</u>	<u>" "</u>
3. <u>D-Ropes</u>	<u>" "</u>	<u>" "</u>
4. <u>Charges</u>	<u>None Observed</u>	<u>Reported</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Ground Air Measurement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Track Travelmap OK  
0% CH<sub>4</sub> 20.8% O<sub>2</sub> 0 CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Pre-shift-Mine Examiner Certificate No. 27085  
Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. \_\_\_\_\_  
Assistant Foreman \_\_\_\_\_  
Superintendent or Assistant \_\_\_\_\_

A. B. Bickel 26176

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-5 2009 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 a.m. on p.m. to 3:00 a.m. on p.m.
Was this report phoned to outside: Yes no
By whom Scott Halstead Time A.M. 2:50 P.M.
Report received by Harley Taylor 37002 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include POWER CENTER, Work AREA, D. Box, CHARGERS, all with 0% CH4 and NONE OBSERVED/Action Taken.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4 0% CO 20.8% O2 TRACK & TRAVELWAYS OK AT TOE

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Scott Halstead Preshift-Mine Examiner Certificate No. 37567
Countersigned [Signature] Mine Manager - Mine Foreman
Assistant Foreman Certificate No.
M. J. Bailey Assistant Foreman Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-5-09 20 Section or Area Examined Lull 11 conduct from

Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.

Was this report phoned to outside Yes no

By whom 2014 Time A.M. 11:00 P.M.

Report received by (Signed) 15377

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: Power centers, none observed, none. Row 2: work Area. Row 3: D-Box. Row 4: Charger.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air.

Remarks: Oachy 0200 208202 Track Truways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey 27085 Certificate No. Assistant Foreman

Countersigned [Signature] Mine Manager - Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-6 20 69 Section or Area Examined LA Corral
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Includes handwritten entries like 'Power Lines', 'Work Area', 'D-Box', 'Charges'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Includes handwritten entry 'Good Air Movement'.

Remarks: Track Tranchmaps OK
0% CH4 20.870 O2 0 ED

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 390677A
Assistant Foreman Superintendent or Assistant

John Bickford 26176

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date April 11, 1941 Shift 1st Area or Section 2nd

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 12-6-09 20. Section or Area Examined LW Constr.  
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.  
Was this report phoned to outside: Yes  no   
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. Power Center	0%	NONE OBSERVED	NONE
2. WORK AREA	0%	NONE OBSERVED	NONE
3. D. BOX	0%	NONE OBSERVED	NONE
4. Charger	0%	NONE OBSERVED	NONE
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good Air Movement	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: TRACK, TRAVELWAYS - OK  
0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO. Detected at EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead 37567 Assistant Foreman Certificate No.  
Countersigned [Signature] Mine Manager—Mine Foreman  
Mike Bailey Assistant Foreman 27085 Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-6-09 20 Section or Area Examined L/WAN Constr.
Time of Examination: from 8:30 a.m. or P.M. to 11:30 a.m. or P.M.
Was this report phoned to outside: Yes no
By whom Mike Bailey Time A.M. 11:10 P.M.
Report received by Steve Cohen 39042 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include Power Center, Chargers, Work Area, D-Boxes, and empty rows 5-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement.

Remarks: OX CH4 approx 20.8% detected at time of exam
Track & Trackage OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085
Countersigned Mine Manager-Mine Foreman Assistant Foreman Superintendent or Assistant



Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested

Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 12-7-01 20. Section or Area Examined L/Wall Const.  
 Time of Examination: from 5:30 or p.m. to 6:00 or p.m.  
 Was this report phoned to outside: Yes no  
 By whom D. J. [unclear] [unclear] Time          A.M.          P.M.  
 Report received by          (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	CHY	Violation or Hazardous Condition	Action Taken
1. <u>Power Center</u>	<u>OK</u>	<u>None observed</u>	<u>None</u>
2. <u>D-Socks</u>	<u>OK</u>	<u>None observed</u>	<u>None</u>
3. <u>Chargers</u>	<u>OK</u>	<u>None observed</u>	<u>None</u>
4. <u>Work Area</u>	<u>OK</u>	<u>None observed</u>	<u>None</u>
5. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: OK CHY upper co, 20-25 ft below at time of exam  
Track: Traveling OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Barley Certificate No. 27085  
 Preshift-Mine Examiner Assistant Foreman Certificate No.  
 Countersigned          Mine Manager—Mine Foreman  
         Assistant Foreman  
         Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 12-7-09 20. Section or Area Examined L W CONSTRUCTION  
Time of Examination: from 12:00 a.m. or 3:00 a.m. of p.m.  
Was this report phoned to outside: Yes no  
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. Power Center	0%	NONE OBSERVED	NONE
2. D-Box's	0%	NONE OBSERVED	NONE
3. Chargers	0%	NONE OBSERVED	NONE
4. WORK AREA	0%	NONE OBSERVED	NONE
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good Air Movement	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO Detected at EXAM  
TRACK TRAVELWAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead Preshift-Mine Examiner Certificate No. 37567  
 Assistant Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_  
 Countersigned \_\_\_\_\_ Mine Manager—Mine Foreman  
Mike Bailey Assistant Foreman Certificate No. 27085  
 Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 12-7-09 2009 Section or Area Examined Longwall construction

Time of Examination: from 8:30 a.m. or 0 p.m. to 11:30 a.m. or 0 p.m.

Was this report phoned to outside: Yes no

By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.

Report received by \_\_\_\_\_  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1.	Power centers	0%	None observed	None
2.	D-Boxes	0%	None observed	None
3.	Chargers	0%	None observed	None
4.	Work Areas	0%	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0PPM Detected At Time of exam  
Track, Travelways, OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mide Bailey Preshift-Mine Examiner Certificate No. 27085 Assistant Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_

Countersigned \_\_\_\_\_ Mine Manager—Mine Foreman

Assistant Foreman \_\_\_\_\_

Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-8-01 20 Section or Area Examined L/WALL Constr.
Time of Examination: from 3:00 P.M. or p.m. to 6:00 P.M. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time 5:20 P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows 1-10 with handwritten entries like 'Power Center', 'Work Area', 'D-Jones', 'Charger's'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Handwritten entry: 'Good Air Movement'.

Remarks: OK CH4 approx 2.2% detected at time of exam
Track & Travelways OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27065
Countersigned Mine Manager-Mine Foreman Assistant Foreman Superintendent or Assistant



Use Indelible  
Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-8-89 20 Section or Area Examined L W Construction  
Time of Examination: from 12:00 a.m. or (p.m) to 3:00 a.m. or (p.m.)  
Was this report phoned to outside: Yes no  
By whom Brought Old Time A.M P.M.  
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows 1-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement.

Remarks: 0% CH4, 20.87 O2, 0ppm CO Detected at EXAM time  
TRACK & TRAVELWAYS Clear at EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead Preshift-Mine Examiner Certificate No. 37567 Assistant Foreman  
Countersigned Mine Manager-Mine Foreman  
Mike Bailey Assistant Foreman Certificate No. 27085 Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

	<i>Location</i>	<i>Violations and other Hazardous Conditions Observed and Reported</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1.	_____	_____	_____	_____
2.	_____	_____	_____	_____
3.	_____	_____	_____	_____
4.	_____	_____	_____	_____
5.	_____	_____	_____	_____
6.	_____	_____	_____	_____
7.	_____	_____	_____	_____
8.	_____	_____	_____	_____

*Examinations for Methane in Working Places*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	11.	_____	_____
2.	_____	_____	12.	_____	_____
3.	_____	_____	13.	_____	_____
4.	_____	_____	14.	_____	_____
5.	_____	_____	15.	_____	_____
6.	_____	_____	16.	_____	_____
7.	_____	_____	17.	_____	_____
8.	_____	_____	18.	_____	_____
9.	_____	_____	19.	_____	_____
10.	_____	_____	20.	_____	_____

*Examinations for Methane in Return Aircourses*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	6.	_____	_____
2.	_____	_____	7.	_____	_____
3.	_____	_____	8.	_____	_____
4.	_____	_____	9.	_____	_____
5.	_____	_____	10.	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-8-09 20 Section or Area Examined Longwalk Construction
Time of Examination: from 9:30 a.m. or 9 p.m. to 11:30 a.m. or 11 p.m.
Was this report phoned to outside: Yes [checked] no
By whom Mike Bailey Time A.M. 11:10 P.M.
Report received by [Signature] (Signed) 1947-A

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include Power center, Work Area, D-Box's, and chargers, all with 0% CH4 and 'None observed'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air movement.

Remarks: 0% CH4, 20.8% O2, oppm C.O.
Track, travelways OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 27085 Assistant Foreman Certificate No.
Countersigned Mine Manager—Mine Foreman Assistant Foreman Superintendent or Assistant