

5-25-10-4

Full 10-7-09

# FULL EXAMINATION OF BELT CONVEYORS

FINISHED  
10-7-09

COMPANY Performance Coal

MINE U.S.B.

LOCATION Naam Raleigh W.V.  
Post Office County State

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-22-07 SHIFT: 3rd AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Jeremy Bergdoff Keith Staley Time 5:48 AM or PM

Report received by: Jim Bergman 39261  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	<del>15-19</del> 28 to 40 need spot clean & dusted	TP JLB	—		
NORTH NO. 1	idle checked p/c + pump - clean	TP	—		
<del>NORTH NO. 2</del>	<del>need work dusted</del>	TP	—		
<del>NORTH NO. 3</del>	<del>need clean 28 truck to 23 + dusted</del>	TP	—		
NORTH NO. 4	Needs Spot cleaned 32-38, Needs All. Dusting	S.C.	✓		
NORTH NO. 5	Needs add. Dusting 45-60	S.C.	✓		
NORTH NO. 6	Head Area needs Add. cleaning & Dusting	S.C.	✓		
NORTH NO. 7	P.C. Pumps, Chargers OK	S.C.	✓		
<del>NORTH NO. 8</del>	<del>Needs add. dusting, replaced two controllers</del> <del>trip needs changed flow of Section</del>	KS	✓		
GLORY HOLE	P.C. Pumps OK IDLE	S.C.	✓		
#1 Sec #1	None observed	JLB	✓		
#2 Sec #2	None observed	JLB	✓		
#3 Sec #1	Needs dusted 4-tail	JLB	✓		
#3 Sec #2	Needs spot cleaned & dusted	JLB	✓		
#4 Sec	IDLE (moving)				
L.O.B.	Pumps & P/C's	TP	—		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

O<sub>2</sub> CH<sub>4</sub>, O<sub>2</sub> CO<sub>2</sub>, CO, H<sub>2</sub>S detected at time of exam  
Track, Travelways, power centers, D-boxes, KW's, chargers ok at time of exam  
Visual check CO monitors ok at time of exam

SIGNED BY: Alan Galt 39012 Jeremy Bergdoff 1759A Donald K. Staley 39261  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: John Cook 3906018  
Mine Foreman Certificate No. Superintendent Certificate No.

Jim Curry 27429 Russell Dumme 1536-1A Jim Bergman 39261 John H. Erickson 26174

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-22-07 SHIFT: 3rd AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM TO  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	cleaned v. plow	sc.
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
2/115 H	tail cleaned v plow & dusted	sc.

Outby Refuge Chambers ok at time of exam <sup>sc. sc.</sup> 97, 98, 6 bck

SIGNED BY: [Signature] 39012 [Signature] 29011  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 39012 [Signature]  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 9-22 SHIFT: Day AM OR PM / 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom J. Roles, G. Curry, John B. R. Sumner Time 2:35 AM or PM

Report received by: Scott Halstead 37567  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs spot clean all spot dusting 28-40 needs dusted	J.B	✓		
NORTH NO. 1	IDLE power head pump at exam	J.B	✓		
Ellis #4	Needs Dusted	G.C.	✓		
Ellis #5	Needs Cleaned 23 to 28 BK	G.C.	✓		
NORTH NO. 4	Needs Spot Dusted 32-38, needs Dusted	G.C.	✓		
NORTH NO. 5	Needs additional Dusting 45-60 BK	R.G.	✓		
NORTH NO. 6	Needs additional Cleaning + Dusting	R.G.	✓		
NORTH NO. 7	Powercenters, Chargers, Pumps - OK	J. Backford	✓		
NORTH NO. 8	Needs Additional Cleaning Tripper & Flow	J. Roles	✓		
GLORY HOLE	Powercenters, Chargers, Pumps - OK	J. Backford	✓		
2 Sec. NO. 1	NONE OBSERVED	J. Backford	✓		
2 Sec. NO. 2	NONE OBSERVED	J. Backford	✓		
#3 Sec. #1	Needs dusted 4-tail, some spot cleaning	J.B	✓		
#3 Sec. #2	Needs dusted 26-28, some spot cleaning	J.B	✓		
#4 Sec.	Out of service, power boxes, chargers at exam	J.B SH	✓		
LBB	Powercenters, Pumps	SH	✓		
#1 Section	NONE OBSERVED	J. Backford	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

Splitter box on 1 section OK 0-20.8-0 DB  
Power Center at 2 head on old 1 section OK PB

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0 ppm CO detected at EXAM time  
Track, travelways, powercenters, D-Box's, chargers, OK at EXAM time  
Visual CK of CO Monitors OK at EXAM time.

Track over 4 sections ends at 18 Brk Stop sign equipment being moved around. JB, SH George Curry 27429  
R. Sumner 29611  
5905505

SIGNED BY: Tom Baynes 32261 J. Roles 35881 Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
John B. Backford 26171 Russell Sumner 1536-A D. Whatley 32746  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] Mine Foreman [Signature] Certificate No. [Signature] Superintendent [Signature] Certificate No.

35042 [Signature] 1597 [Signature] 1947-A

Use Indefinite Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-22-09 SHIFT: DAY 6:00 AM OR PM TO 4:00 AM OR PM AM OR PM TO AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1	filled down dusties at 1 South flow thru Tail, hand dusted 16-17	JB
NORTH 1	cut down wire mesh at 14, 17-8 B.K., shoveled coal on	
NORTH 2	top of conveyor & shoveled fine on ground	JB
NORTH 3	cleaned on 1 North takeup at stationary roller	JB
NORTH 4	cleaned beltline 2 B.Ks in by 4 head, cleaned Tail	93C
NORTH 5	Hand Dusted Head, Cleaned on Tail	RG
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
3 sec #1	put top rail in at 8 B.K. cleaned, dusted, ground tail, started head & takeup	JB
3 sec #2	dusted around head area	JB
2 sec #2	Cleaned at V-Plow	5AB
Ell. 5	cleaned V-Plow & hoist piece	93C

outby Refuge Chambers # 6, 8, 89 JB 0-20.8-0  
# 97 GC 0-20.8-0 Phones: OK

SIGNED BY: Jim Bannan 32261 George Curry 27429  
Belt Examiners and Certificate Numbers  
John B. Bishop 26171 Russell Dunmore 15367A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 3900000  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-22-9 SHIFT: 2<sup>nd</sup> AM OR PM TO 8:00 AM OR PM TO 11:30 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom G. Miller S. Chandler Time 11:00 AM or PM

Report received by: T. Peterson Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	need spot clean & dusted 28-40. need dusted	TP	—		
NORTH NO. 1	check power box & pumps OK	TP	—		
<del>Ellis 4-2</del>	Needs Dusted	S.C.	✓		
<del>Ellis 5</del>	Needs cleaned 23-28 brk	S.C.	✓		
NORTH NO. 4	Needs Spot Cleaned 32-38, Needs Dusted	S.C.	✓		
NORTH NO. 5	Needs All Dusting 45-60 brk	S.C.	✓		
NORTH NO. 6	Needs All cleaning & Dusting see Remarks	G.V.	✓		
NORTH NO. 7	Idle P.C. & Chargers OK	G. Cole	✓		
<del>Long Wall</del> <del>NORTH NO. 8</del>	Needs All Dusting & All cleaning at Tripper & Flotation	G.V.	✓		
GLORY HOLE	Idle P.C. & Pumps OK	G. Cole	✓		
2 <sup>sec</sup> 1	None observed	G. Cole	✓		
2 <sup>sec</sup> 2	None observed	G. Cole	✓		
3 <sup>sec</sup> 1	need dusted & spot clean	TP	—		
3 <sup>sec</sup> 2	need spot clean & dusted	TP	—		
4 <sup>sec</sup>	Out of service - power boxes & charger clean	TP	—		
L&B	Electric pumps clean	TP	—		
#1 <sup>sec</sup>	None observed	S. Cole	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

NOCH4 det. O<sub>2</sub> 20.802 con  
Visual on CO's \*needs Impacts changed in GN Tail cu  
P/C's & D. Bores Pumps clean  
Tramways & track clean at time of exam  
Track for 4<sup>sec</sup> is stopped at Bk. 18 TP stop sign hung  
Equip. being moved.

SIGNED BY: T. Peterson 29011 Ste. 3122  
 Belt Examiners and Certificate Numbers  
G. Cole 1947-A Don Allman 15372A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] Superintendent Certificate No.  
 Mine Foreman Certificate No.



Use Indefinite Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-23-9 SHIFT: owl AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	need spot clean & dusted 28-40+ need dusted TP	TP	✓		
NORTH NO. 1	edge lower & box - Pump clean	TP	—		
E/115.4	needs Dusted	GV	✓		
E/115.5	Needs cleaned 23-235rk	S.C.	✓		
NORTH NO. 4	Need Spot Cleaned 32-335rk, Needs Dusted	S.C.	✓		
NORTH NO. 5	Need. Add. Dusting 45-605rk	S.C.	✓		
NORTH NO. 6	Needs Add. Cleaning needs Dusted <sup>See Remarks</sup>	GV	✓		
NORTH NO. 7	Idle P.C. Chargers ok	GLC	✓		
KANG WALL	need Add. Dusting Flawthrow needs Add. cleaning	GV	✓		
GLORY HOLE	Idle P.C. and PUMPS ok	GLC	✓		
LBB	Pumps - Power Boxes clean	TP	—		
2 Sec. 1	None observed	GLC	✓		
2 Sec. 2	None observed	GLC	✓		
3 Sec. 1	need spot clean & dusted	TP	—		
3 Sec. 2	need spot clean & dusted	TP	—		
4 Sec.	Out of service - P.C.s charger clean	TP	—		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

No CH<sub>4</sub> def. 0% 20.802 CO<sub>2</sub>

Travelways & track clean at time of exam

Pumps - Power Boxes D Boxes charger clean

Visual on CO no.

Track stopped at 18 Pk. on 4 Sec. Signaling equip moving.

Pump at OLD LBB 3 Head - no fire ext. - out of service

SIGNED BY: [Signature] 29011 [Signature] 39042  
 Belt Examiners and Certificate Numbers  
[Signature] 15397A [Signature] 1947-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 290607  
 Mine Foreman Certificate No.  
 Superintendent Certificate No.

48543 - BJW Printing & Office Supplies  
[Signature] 32261 [Signature] 26176 [Signature] 1536-A

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-23-04 SHIFT: Own 12:00 AM OR PM TO 6:00 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM     

Report received by:       
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
<del>NORTH 2</del>		
<del>NORTH 3</del> 5	Cleaned V-Plow on both sides & Dusted around Tail: <del>Discharge</del> Roller	S-C.
NORTH 4		
NORTH 5	cleaned V-Plow	S-C.
NORTH 6	Cleaned Flow Thru	GU
NORTH 7		
<del>NORTH 8</del> Longwall	cleaned on Flow Thru	GU
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
3sec. #1 Head	loaded Lickle Luster & run	TP
2sec. #1 Tail	Dusted tail area	GLC

*Refuge chambers at 97, 6, 89 ed at exam*

SIGNED BY: *Ray Peterson 29611* *Stef 39042*  
Belt Examiners and Certificate Numbers  
*Greg Cole 1947-A* *Don Williams 15392*  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *Charles Cook* *3500000*  
Mine Foreman Certificate No. Superintendent Certificate No.

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-28-09 SHIFT: Day AM OR PM TO 1200 AM OR PM TO 300 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom J Bickford R Gunn or Time 249 AM or PM

Report received by: George Curry  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Chain broke across side 33-34 Tracks spot cleaned, Tracks spot dusted, Tracks dusted 25-40	JB	✓		
NORTH NO. 1	IDLE, Power Box & pump at repair	JB	✓		
Ellis 4	needs dusted	RC	✓		
Ellis 5	needs cleaned 23 to 28	RC	✓		
NORTH NO. 4	spot cleaned 32 to 38 entire belt need dusted	RG	✓		
NORTH NO. 5	add dust 45 to 60	RG	✓		
NORTH NO. 6	head need add cleaning; dusting	RG	✓		
NORTH NO. 7	Idle - ✓ PCs; chargers	JAB	✓		
WALK	Need more Rock dusting	HL			
GLORY HOLE	Idle - ✓ PCs; pumps	JAB	✓		
1 sec 1	none observed	JAB	✓		
2 sec 1	none observed	JAB	✓		
2 sec 2	none observed	JAB	✓		
3 sec 1	Needs dusted, some spot cleaning	JB	✓		
3 sec 2	Head in walking 23 belt, Tracks spot cleaning dusting	JB	✓		
4 sec	left out of service, power box & pump at repair	JB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
 0% CH<sub>4</sub> - 0% CO - 20.8% O<sub>2</sub>  
 Tracks, travelways, PCs, rollers, chargers all clear at time of exam  
 Visual check of C-monitors at exam

6N Tail needs Impacts changed  
 Signed by: George Curry 27429 Scott Hildner 37567  
 Belt Examiners and Certificate Numbers  
Jim Banger 32261 Russell Gunnore 1536A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 3906000 Mine Foreman Certificate No.  
 Superintendent [Signature] 15370 Certificate No.

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-23-09 SHIFT: DAY 6:00 AM OR PM TO 4:00 AM OR PM 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1	<i>filled &amp; re-adjusted at flow thru tail, cleaned head &amp; tail                      then did PM's journal on takeup, dusted tail - 2 Bk                      hand dusted 23-25 Bk</i>	
<del>NORTH 1</del>		
<del>NORTH 2</del>		
<del>NORTH 3</del>		
NORTH 4	Rock dusted 4 w 2 Bk south by 4 Ineel, cleaned TAIL	JB RG
NORTH 5	Clean Tail, dusted HEAD & TAIL, Run Duster at 42	RG
NORTH 6	Hand Dusted Head, cleaned on Head	RG
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
Ellis 5	cleaned tailpiece: v plow - Rock dusted tailpiece	RG
3 sec #1	cleaned & dusted around head, cleaned & dusted ground tail	JB
3 sec #2	cleaned & dusted head area	

Reggie Chambers at 97, 6, 89, 18 Bk all Ineel at time of exam

took rock dust to outly creep charger JB

SIGNED BY: George Curry 27429 Russell Gunnoe 1536-19  
 Belt Examiners and Certificate Numbers  
Jim Boyer 30261 John H. Buford 26176  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 3306000  
 Mine Foreman Certificate No. Superintendent Certificate No.

GC.

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 9-23 SHIFT: ~~DAY~~ EVE AM OR PM TO 8:00 AM OR PM TO 11:30 AM OR PM  
ON-SHIFT EXAM. 8:00 PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Gilman S. Cable Time 11:00 AM or PM

Report received by: T. Peterson

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	33-34 chain broke need spot clean & dusted - spot dusted - 28-40	TP	-		
NORTH NO. 1	IDLE - P/C & Pump OK	TP	-		
E/H 2.4	need dusted wet & mxd by	GC	-		
E/H 1.5	need spot clean - head to tail	GC SC	-		
NORTH NO. 4	3.4 to 3.8 need dusted	SC	-		
NORTH NO. 5	need add dust 45-60	SC	-		
NORTH NO. 6	head need add. cleaning	GU	-		
NORTH NO. 7	<del>check</del> after P/C's chargen clean	GC	-		
h/wall	need add. dust - flow thru add. clean	GU	-		
GLORY HOLE	IDLE Pumps & P.C. OK	TP	-		
#1 sec. 1	Pumps - P/C Boos	GC	-		
2 sec. 1	air lock need clean	TP	-		
2 sec. 2	need clean air lock	TP	-		
3 sec. 1	need spot clean & dusted	TP	-		
3 sec. 2	need spot clean & dusted	TP	-		
4 sec.	No power on sec. at time of exam	TP	-		
h/bb	P/C's & Pumps clean	TP	-		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: OVER CASE ON h/wall clean

No CH4 det. 0% 20.8oz CO 0%

Track & Tramelways clean at time of exam.

Visual on CO no. Stoppings on longwall belt are clear

Pumps - P/C's - D. Boos - chargen clean

Need 3 sacks set at 10 Bkt. on h/wall

\* Roller SW tail impacts need changed

Stuck impact SW. Flow thru - 5 Ellis tail stuck roller

9 stop roller 6 W. Belt - Refuse chamber <sup>at V Plow</sup> 97-6-89 - 8 Bkt clear

SIGNED BY: T. Peterson 2966

Belt Examiners and Certificate Numbers  
Gilman 1539A

Stacy Stone  
Stacy Cob 1949A

COUNTERSIGNED BY: Gilman

Mine Foreman

Certificate No. 3906000

Superintendent

Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-23-09 SHIFT: Five AM OR PM TO AM OR PM AM OR PM TO AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
<del>NORTH 2</del>		
<del>NORTH 3</del>	Cleaned v. Plow & washed out Impacts	S.C.
NORTH 4	Trained on belt	
NORTH 5	Cleaned v. Plow at Tail & Flaw thru Trained on belt	S.C.
NORTH 6		
<del>NORTH 7</del>	Cleaned on Flaw Thru	GU
NORTH 8		
GLORY HOLE		
LBB NO. 1	Dust Tail Piece Area	GC
LBB NO. 2		

SIGNED BY: [Signature] 39046  
Belt Examiners and Certificate Numbers  
[Signature] 15397  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 3906000  
Mine Foreman Certificate No. Superintendent Certificate No.





## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-24 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom J.B. Bidford R. Gurnoe Time 2:30 AM or PM

Report received by: J. Sawyer 32261 Signed George Curry 27429 Harold Lilly 9:22 PM

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs some spot cleaning & dusting, needs add dusting	JB	✓		
NORTH NO. 1	IDLE Power box & pump safe at exam	JB	✓		
Ellis H	needs dusted	JSC	✓		
Ellis B	needs spot cleaned	JSC	✓		
NORTH NO. 4	spot cleaned 32 to 37	RG	✓		
NORTH NO. 5	add dusting 45 to 60	RG	✓		
NORTH NO. 6	add cleaning & dusting Ab Head	RG	✓		
NORTH NO. 7	Tdk - chargers, PC	JAB	✓		
Langwell	Tadump area & 36-tail needs dusted	HL	✓		
GLORY HOLE	Tdk - pumps, PC	JAB	✓		
2 sec #1	add cleaning in by airlock	JAB	✓		
2 sec #2	spot cleaned	JAB	✓		
3 sec #1	Needs some spot cleaning, needs dusted 2-18 Bk	JB	✓		
3 sec #2	Needs spot cleaned 23-25 Bk, needs dusted 21-22 Bk	JB	✓		
4 sec	IDLE, Power Boxes chargers safe at exam	JB	✓		
LBB	Pumps & Boxes ok at exam	GC	✓		
#1/Sec #1	IDLE Boxes & pumps safe at exam	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub> - 0% CO - 20.8% O<sub>2</sub>  
 Tracks, travelways, PCs, O Boes, chargers clear at time of exam  
 Visual check of CD monitors ok at exam  
 Dusted h/w belt from #15 Bk to #34 Bk (hand dusted)

SIGNED BY: George Curry 27429 Russell Gurnoe 1536-A  
 Belt Examiners and Certificate Numbers  
J.B. Bidford 26176  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: John Cole 3206007  
 Mine Foreman Certificate No. Superintendent Certificate No.

#6543 - B.J.W. Printing & Office Supplies  
John Cole 1947-A John Gurnoe 39199  
Mike Binkley 27085

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-24 SHIFT: DAY AM OR PM TO 1200 AM OR PM TO 300 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1	<i>filled iron ducting of lower thru tail blacked belt 33-34, shouldered splices 33-34, cleaned ductal around plow thru</i>	<i>JB</i>
NORTH 1		
Ellis 5	<i>cleaned Ellis 5 tailpiece &amp; v plow</i>	<i>JSC</i>
NORTH 3		
NORTH 4	<i>cleaned 4 Bks of 40 belt from drive towards head SPG cleaned 37-38 Bk</i>	<i>JSC</i>
NORTH 5	<i>Run Dust on at 42, shoveled v-plow</i>	
NORTH 6		
NORTH 7		
<del>NORTH 8</del>	<i>2 men during Belt</i>	<i>HL</i>
GLORY HOLE		
<del>LBB NO. 1</del>	<i>Cleaned on 1 Belt in by Air Lock</i>	<i>JAB</i>
LBB NO. 2		
3 sec # 1	<i>cleaned &amp; dusted around head - 2 Bk, cleaned, dusted, greased tail</i>	<i>JB</i>
3 sec # 2	<i>cleaned up rib roll 23 Bk, shouldered 21-23 Bk</i>	<i>JB</i>

*Refriger chambers at 97, 6, 89, 18 Bk clear at time of exam*

SIGNED BY: George Curry 27429 Russell Dunnoe 15367A  
Belt Examiners and Certificate Numbers  
Tom Bayner 32861 John Beckford 26176  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY John Cook 390000  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 9-24-09 SHIFT: Even ~~Day~~ AM OR PM TO 800 AM OR PM TO 1100 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Mike Bailey Time 11:30 AM or  PM

Report received by: John 39042  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Need Spot cleaned and Dusted, Need add Dusting 28-40	LS/GC	✓		
NORTH NO. 1	IDLE Power box, pump safe at exam	LS/GC	✓		
NORTH NO. 2	Needs Dusted (Belt is wet & muddy)	S.C.	✓		
NORTH NO. 3	Needs Spot cleaned	S.C.	✓		
NORTH NO. 4	Needs Spot cleaned 32-37	S.C.	✓		
NORTH NO. 5	Needs Add. dusting 45-60	G.U.	✓		
NORTH NO. 6	IDLE P.C. & Pumps ok	G.U.	✓		
NORTH NO. 7	IDLE Chargers & P.C. ok	M.B.	✓		
NORTH NO. 8	IDLE P.C. & Pumps ok	G.U. & M.A.	✓		
GLORY HOLE	IDLE P.C. & Pumps ok	M.B.	✓		
#1 Sec #1	Add. cleaning in by Airlock	M.S.	✓		
#2 Sec #2	Spot cleaned	M.S.	✓		
#3 Sec #1	Need Spot cleaned and Dusted 2-18 B/L	LS/GC	✓		
#3 Sec #2	Need Spot Dusted and Cleaned/Dusted from 2L28 BK	LS/GC	✓		
#4 Sec	IDLE, Power Boxes, chargers, safe at exam	LS/GC	✓		
L.S.S	Pump, Power boxes OK at exam	LS/GC	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

O<sub>2</sub> CH<sub>4</sub>, O<sub>2</sub> CO, 20.8% O<sub>2</sub> detected at time of exam  
Track, Travelways, power boxes, chargers, Kvas ok at time of exam  
Visual check co monitors ok  
Stoppings on Longwall are clear  
Track and travel ways Needs Dusted From mouth of 3 sec. TO end of Track.

SIGNED BY: Mike Bailey 27025  
 Belt Examiners and Certificate Numbers  
John 39042 Jay Stewart 39199  
Don 15577 Gary 1947-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] Mine Foreman [Signature] Certificate No. [Signature] Superintendent- [Signature] Certificate No.

Use Indellible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-27-07 SHIFT: Even 6:00 AM OR PM TO 11:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
<sup>Ellis #4</sup> NORTH 2	Cleaned U-Plow	S-C
<sup>Ellis #5</sup> NORTH 3	Cleaned U-Plow	S-C
NORTH 4	Cleaned U-Plow	S-C
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
3 Sec #1	Cleaned U-Plow	LS

Outby Refuge chambers ok at time of exam 97, 6, 87, 18 b/c

SIGNED BY: Steve Sel 39244 Jay Stewart 39199  
Belt Examiners and Certificate Numbers  
Mike Bailey 27085  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 390000  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-25-07 SHIFT: OWN AM OR PM TO 3:00 AM OR PM TO 6:00  OR PM TO 6:00  OR PM  
**ON-SHIFT EXAM.** **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes  No  By Whom Milk B Time 5:30 AM or PM

Report received by: Jay Stewart 39199  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs Spot Cleaned and Dusted, Needs add Dusting 28-40 BRK	LS	✓		
NORTH NO. 1	IDLE, Power Boxes, Pumps safe at exam	LS	✓		
<del>NORTH NO. 2</del>	Needs Dusted (wet & muddy)	GO	✓		
<del>NORTH NO. 3</del>	Needs Spot cleaned HEAD to Tail	S-C	✓		
NORTH NO. 4	Needs Spot cleaned 30-35 BRK	S-C	✓		
NORTH NO. 5	needs Add Dusting 45-60 BRK	GU	✓		
NORTH NO. 6	Belt Idle PC Pumps clear	GU	✓		
NORTH NO. 7	IDLE, Chargers, DC's OK	MB	✓		
<del>NORTH NO. 8</del>	Belt Idle PC Pumps Clear	MB	✓		
GLORY HOLE	Idles, PC, Pumps OK	MB	✓		
<del>EDE NO. 1</del>	Add Cleaning mby Airlock	MB	✓		
<del>EDE NO. 2</del>	Need Spot Cleaned	KF	✓		
<del>3 Section</del>	Needs Spot Cleaned and Dusted 3-16 BRK	GC	✓		
<del>3 Section</del>	Needs spot cleaned 23-28 Needs Dusted 23-28 BRK	GC	✓		
<del>4 Section</del>	IDLE, Power Boxes, Chargers safe at exam	LS	✓		
<del>L.S. 2</del>	" " " & pumps safe at exam	GC	✓		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

ON CH<sub>4</sub>, ON CO<sub>2</sub>, 208 N<sub>2</sub> detected at time of exam  
Track, Travelways, powerboxes, D-boxes, kvs, chargers ok at time of exam  
Visual check to monitors ok  
Track and travel ways Needs Dusted FROM mouth of 3.sec - end of Track

SIGNED BY: Milk Bailey 27085 Jay Stewart 39199  
Belt Examiners and Certificate Numbers  
John Miller 15397A John G. 1947A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY John G. 1947A George Curry 27429  
Mine Foreman Certificate No. Superintendent Certificate No.  
Jim Boyer 3226 Russell Dunmore 1536-A John A. Beckford 26176

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-25-09 SHIFT: Owt 12:00 AM OR PM TO 6:00 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1	filled bran duster on 1 South at Flow thru	GC, LS
NORTH 1		
<del>NORTH 2</del>		
<del>NORTH 3</del>		
NORTH 4	cleaned V-Plow	S-C
NORTH 5	cleaned from 37-35hrk both sides	S-C & GU
NORTH 6	cleaned Tail and V Plow, cleaned V-plow Flow thru	GU
NORTH 7		
<del>NORTH 8</del>	Elon and aman was Rock casting	GU
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
3 Section #1	Cleaned V-Plow, dusted from 2-3, 16-19 Brk	LS GC
3 Section #2	Dusted head area	GC & LS

Outby Refuge chambers ok at time of ex 97, 6, 89, 18brk

SIGNED BY: Wile Bailey 27085  
Don 39042 Jay Stewart 39199  
 Belt Examiners and Certificate Numbers  
Don Ullman 1539-12 Wiley Cole 1447-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: \_\_\_\_\_ 3586  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-25-09 SHIFT: DAY AM OR PM TO 0 AM OR PM TO 1200 AM OR PM TO 300 AM OR PM TO 0

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom J. Bedford R Gunnor Time 2:40  or PM

Report received by: George Curry 27429  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Head some spot cleaning & dusting. Needs add dusting 28-39 Bk JB	JB	✓		
NORTH NO. 1	IDLE, power down & pumps safe at exam	JB	✓		
Ellis #4	needs dusted	JSC	✓		
Ellis #5	needs spot cleaned	JSC	✓		
NORTH NO. 4	spot cleaned 32 to 35 Bk	RG	✓		
NORTH NO. 5	need add dusting 45 to 60 Bk	RG	✓		
NORTH NO. 6	head needs add cleaning & dusting	RG	✓		
NORTH NO. 7	Idle - ✓ charger / PC	JAB	✓		
<u>Longwell</u>	IDLE				
GLORY HOLE	Idle ✓ PC / pumps	JAB	✓		
2 sec #1	Add cleaning in by airlock	JAB	✓		
2 sec #2	spot cleaned	JAB	✓		
3 sec #1	Needs dusted 3-16 Bk, some spot cleaning	JB	✓		
3 sec #2	Needs spot cleaning & dusting 23-28 Bk	JB	✓		
4 sec	IDLE, power down & pumps safe at exam	JB	✓		
LBB	IDLE, power down & pumps safe at exam	GC	✓		
1 sec	No power				

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub> - 0% CO - 20.8% O<sub>2</sub> - Travelways, track, pc's, D Bel  
chargers clear at time of exam  
Visual check of CO monitor ok at exam  
See board for rollers

SIGNED BY: George Curry 27429 Jay Stewart 39199  
Belt Examiners and Certificate Numbers  
Jim Wagner 32261 John A. Bedford 26174  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Mike Bailey 27085 34111  
Mine Foreman Certificate No. Superintendent Certificate No.



PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 9-25-09 SHIFT: CVL AM OR PM TO 800 AM OR PM TO 1100 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom L Ford, Steve Cole, Mike B Time 700 AM or  PM

Report received by: Joy Stewart 39199  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Need Spot Cleaned and Dusted, Need add Dusting 28-39 BK	LS	✓		
NORTH NO. 1	IDLE, PC, Chargers, Pumps Clear at exam	LS	✓		
<del>Ellis</del>	needs Dusted	GU	✓		
<del>Ellis</del>	needs spot cleaned	GU	✓		
NORTH NO. 4	needs spot cleaned 32-35BR K	GU	✓		
NORTH NO. 5	needs Add Dusting 45-60 BK K	GU	✓		
NORTH NO. 6	HD needs Add Cleaning & dusting	GU	✓		
NORTH NO. 7	Chargers, PC OK at exam	MB	✓		
<sup>Longwall</sup> NORTH NO. 8	<sup>6:15-7:05</sup> need spot dusted 16:00-22:00 Add Cleaning 51:00 need dusted 16-7a.1	GU / LF	✓		
GLORY HOLE	IDLE PC/Pumps OK	MB	✓		
<sup>2 Section</sup> NO. 1	Add cleaning at Air Lock	MB	✓		
<sup>2 Section</sup> NO. 2	Need Spot Cleaned	MB	✓		
<sup>3 Section</sup> # 1	Needs Dusted 3-16 BK, Some Spot Cleaning	SC	✓		
<sup>3 Section</sup> # 2	Need Spot Cleaned and Dusted 23-28 BK	SC	✓		
<sup>4 Section</sup>	IDLE, PC, Chargers Clear at exam	LS	✓		
LBB	IDLE, Pumps, PC, Clear at exam	LS	✓		
<sup>1 Section</sup>	Idle				

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

CH<sub>4</sub>-0%, O<sub>2</sub>-20.5%, CO-0%

Track, Travelway clear at exam

Stoppings on Longwall Belt & Track are Clear

SIGNED BY: Joy Stewart 39199 Mike Bailey 27085  
 Belt Examiners and Certificate Numbers  
Dan Althman 1539A 24 May 37022  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] [Signature]  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-25-09 SHIFT: One 6 AM OR PM TO 1130 AM OR PM AM OR PM TO AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1	Dusted around take-up	HS
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned on Flow throw	GU
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Refuge Out-by Chambers at 97, 6, 89, 8 OK at etam

SIGNED BY: Jay Strout 39199 Don Williams 1539-1A  
Belt Examiners and Certificate Numbers  
Mike Bailey 27085  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] [Signature]  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-26-09 SHIFT: OWL AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Jeremy Burgdoff Time 5:46 AM or PM  
Report received by: Jim Baugher 32261  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs Spot Cleaned and Dusted. Need add Dusting 28-39 BK	LS	✓		
NORTH NO. 1	IDle PC, Chargers, Pumps Clear at exam	LS	✓		
ELLIS 4	needs Dusted	GU	✓		
ELLIS 5	needs Spot cleaned	GU	✓		
NORTH NO. 4	Needs Spot Cleaned 33-35 BK	GU	✓		
NORTH NO. 5	Spot Dusted 45-60 BK	GU	✓		
NORTH NO. 6	Hd Needs A Little dusting	GU	✓		
NORTH NO. 7	Idle PC Chargers	MB	✓		
<del>Longwall</del>	needs Dusted from Tripper to 56 BK	GU	✓		
GLORY HOLE	Idle - PC & Boxes	MB	✓		
2 Section NO. 1	Air Lock Needs Lubrication	MB	✓		
2 Section NO. 2	Needs Spot Cleaned	KF	✓		
3 Section #1	Needs dusted 3-16 BK, some spot cleaning	JLB	✓		
3 Section #2	Needs spot cleaning dusting 23-28 BK	JLB	✓		
4 Section	IDle PC, Chargers Clear at exam	LS	✓		
LBB	IDle PC, Pumps Clear at exam	LS	✓		
1 Section	IDLE				

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0% CO, 20.89% O<sub>2</sub> Detected at exam

Track, Travelway, PC, D-Boxes, Chargers clear at exam  
Stoppings on Long wall are clear  
Visual check of CO<sub>2</sub> ok at exam

SIGNED BY: Lacy Stewart 39199 Jim Baugher 32261  
Belt Examiners and Certificate Numbers  
Dean Ulman 1539A Mike Bailey 27085  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 35222  
Mine Foreman Certificate No. Superintendent Certificate No.

48543-BJW Printing & Office Supplies  
Jim Baugher 32261 Mike Bailey 27085

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-26-09 SHIFT: Owk 1200 AM OR PM TO 600 AM OR PM 1200 AM OR PM TO 1200 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	Cleaned 32 Brk	GU
NORTH 5		
NORTH 6 <del>Longwall</del>	Cleaned At 51-00 - Helped Dust on Longwall Belt	GU
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
3 Section #1	Dusted around 1 Head	LS

Refuge Out by Chambers at 97, 6, 89, 8 OK at exam

SIGNED BY: Lee Stamat 39199 Mike Benley 27085  
Belt Examiners and Certificate Numbers  
Don Almon 1535-A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: \_\_\_\_\_  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-26-09 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Tony Peterson, Greg Cole, Harold Lilly Time 2:40 AM or  PM

Report received by: Charley Taylor 37002  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs some spot cleaning & dusting Needs add dust 35-39 BK JB	JB	✓		
NORTH NO. 1	IDLE Power box & pump safe at exam	JB	✓		
Ellis #4	Needs Dusted	TP	✓		
Ellis #5	Needs spot cleaned	TP	✓		
NORTH NO. 4	Needs spot cleaned 33 to 35 BK	TP	✓		
NORTH NO. 5	Needs spot Dusted 45 to 60 BK	GC	✓		
NORTH NO. 6	Head Drive Needs some Dusting	GC	✓		
NORTH NO. 7	POWER CENTERS & CHARGERS OK	GC	✓		
Longwall	Needs spot Dusted 36 BK to 50	HL	✓		
GLORY HOLE	Power Center & D. Box OK	GC	✓		
2 Sec #1	Air lock on Belt needs cleaned offside	GC	✓		
2 Sec #2	Needs spot cleaned	GC	✓		
3 Sec #1	Needs dusted 3-16, some spot cleaning	JB	✓		
3 Sec #2	Needs spot cleaning & dusting 23-28 BK	JB	✓		
4 Sec	IDLE power head & charger safe at exam	JB	✓		
LBB	POWER CENTERS & Pumps OK AT TOE	HT	✓		
1 Sec	No power IDLE				

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
\_\_\_\_\_  
\_\_\_\_\_

0% CH4 0% CO 20.8% O2

TRAVELWAYS, POWER CENTERS, CHARGERS, D. BOXES OK AT TOE

VISUAL CHECK OF CO OK AT TOE

See record of rollers

SIGNED BY: Jim Boyer 32261 Ray Brown 29611 Dan Ullman 15397  
Belt Examiners and Certificate Numbers  
Doug 1947-A Jay Stewart 39199 Charley Taylor 37002  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] [Signature]  
Mine Foreman Certificate No. Superintendent Certificate No.

Mike Bailey 27085

**ON-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 9-26-89 SHIFT: Day 6:00 AM OR PM TO 6:00 AM OR PM  
AM OR PM TO AM OR PM  
**ON-SHIFT EXAM.** **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1	<i>put roller in at tail, shoveled dust 46-47 Bel</i>	JB
<del>NORTH 1</del>		
NORTH 2	<i>filled 8 in dust at flow thru</i>	
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
<i>L1 Wall</i>	<i>2 new Rockdusting &amp; 2 tri-nagle dusters set.</i>	HL
GLORY HOLE		
<del>3 sec #1</del> LBB NO. 1 #1	<i>Cleaned Walk Way Side of air Lock</i>	GC
LBB NO. 2		
<i>3 sec #1</i>	<i>cleaned dusted around head, pickup, &amp; tail, greased tail</i>	JB
<i>3 sec #2</i>	<i>put in bottom roller at 26 Bel (3rd shift)</i>	JB
<i>Ellis 5</i>	<i>cleaned at 28 Bel.</i>	TR

<sup>(HT)(TP)(GC)(CC)</sup>  
 Refuge Outby Chambers AT 97, 6, 89, 8 OK AT TOE

SIGNED BY:

*Jay Dewat 3999*  
*Harley Taylor 37002* *Ron Hanson 2900*  
 Belt Examiners and Certificate Numbers  
*Tom Sawyer 30061* *2/10 Cab 1947-A*  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY \_\_\_\_\_

Mine Foreman

Certificate No.

Superintendent

Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 9-26-09 SHIFT: eve AM OR PM TO 900 AM OR PM TO 1100 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Lacy Stewart Time 1100 AM or PM

Report received by: [Signature] Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Don Fire Run	LS	<input type="checkbox"/>		
NORTH NO. 1	Belt Idle PC Clear	LS	<input checked="" type="checkbox"/>		
<del>ELLIS</del> NORTH NO. 2	needs Dusted	GU	<input checked="" type="checkbox"/>		
<del>ELLIS</del> NORTH NO. 3	needs spot cleaned	GU	<input type="checkbox"/>		
NORTH NO. 4	none Observed	GU	<input type="checkbox"/>		
NORTH NO. 5	needs Dusted 45-60 Brk	GU	<input type="checkbox"/>		
NORTH NO. 6	none Observed	GU	<input checked="" type="checkbox"/>		
NORTH NO. 7	Power center chargers Tunde	MB	<input type="checkbox"/>		
<del>Langwell</del> NORTH NO. 8	needs Dusted 26-50 Brk	GU	<input type="checkbox"/>		
GLORY HOLE	power centers, chargers, NVA	MB	<input type="checkbox"/>		
LBB NO. 1	needs add cleaning & Brk	MB	<input type="checkbox"/>		
LBB NO. 2	need spot cleaned	MB	<input checked="" type="checkbox"/>		
3 section Hd	Done Fire Run	SC	<input type="checkbox"/>		
4 section	Idle Power centers chargers Clear	LS	<input type="checkbox"/>		
LBB	Pumps & Boxes Clear	LS	<input checked="" type="checkbox"/>		
1 sec no Power	NO Power				

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

CO-O<sub>2</sub> 0.2-0.8% CH<sub>4</sub> 0.1%  
8 Brk Repair ok mb.  
Track Travel way 5 clear

SIGNED BY: [Signature] 29611  
[Signature] 15397 [Signature] 39199  
Belt Examiners and Certificate Numbers  
[Signature] 27085 [Signature] 28070  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] Mine Foreman  
[Signature] Certificate No.  
Superintendent  
Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-26-09 SHIFT: EVE 600 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	Run wickline and crew cleaned 33-35 BK	R.W
NORTH 5	Clean V-Plow	GC
NORTH 6	Dusted around Head cleaned tail	GC
NORTH 7 <del>Longwall</del>	cleaned At 29 BK cleaned & dusted flow thru	GC
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
1 Head 3 Sec	Dusted around Head, run trickle Duster	W

Checked out By Refugees <sup>PP GC GC GC</sup> 97 6 89 8 Bik 2 Section

Took rock dust & extinguisher charges at #7 Bk  
d.c.d 1 Section #1 belt MB

SIGNED BY: Tom Allman 15597 Joe Dhusat 39199  
Belt Examiners and Certificate Numbers Roni Wickline 32670  
Mike Barly 27085  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY \_\_\_\_\_  
Mine Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent \_\_\_\_\_ Certificate No. \_\_\_\_\_









## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-27 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom G. Cole Time          AM or PM

Report received by: T. Peterson  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	IDLE	SH	✓		
NORTH NO. 1	IDLE	SH	✓		
ELLIS 4	need dusted	TP	—		
ELLIS 5	need clean 28 to 23. spot clean & dusted	TP	—		
NORTH NO. 4	N/O	GC	—		
NORTH NO. 5	need dusted 45-60 Pk	GC	✓		
NORTH NO. 6	none observed	GC	✓		
NORTH NO. 7	Power Center Chargin OK	GC	✓		
XON & WALK	need add. dusting	HL	—		
GLORY HOLE	P/C's chargin KVA	GC	—		
<del>ELLIS NO. 1</del>	IDLE NO Power	GC	—		
<del>ELLIS NO. 2</del>	IDLE NO Power	GC	—		
3 sec. 1	IDLE	SH	✓		
3 sec. 2	IDLE	SH	✓		
4 sec.	IDLE P/C's chargin clear	TP	—		
LBB	P/C's pumps clear	TP	—		
1 sec.	No Power				

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

No CH4 det. 0% 20.00 0%00  
Track & travelways clear at time of exam.  
Pumps - P/C - D. Pumps - chargin clear  
Visual on C/O's

SIGNED BY: T. Peterson 29611 Jay Stewart 39199  
 Belt Examiners and Certificate Numbers  
Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
Greg Chilton 28045

COUNTERSIGNED BY: Mike Bailey 27085           
 Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 9-27-9 SHIFT: Day AM OR PM TO AM OR PM 12:00 AM OR PM TO 3:00 AM OR PM ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2. Handwritten entry: NORTH 5, Clean V-plow, GC.

Refuse Chamber Bk. 97 T. Return 29611 clear
'' '' 4 Sec. T. Return 29611 clear
'' '' 6 Bk.
'' '' 89 Bk.
'' '' 8 Bk.

SIGNED BY: [Signature] 29611
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 29611
Mine Foreman Certificate No. Superintendent Certificate No.

J May Cole 1947-A

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-27-09 SHIFT: Even AM OR PM TO 800 AM OR PM TO 1100 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Steve C, Mike B Time 1040 AM or PM

Report received by: Jay Stewart 39199  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Idle	LS	✓		
NORTH NO. 1	Idle	LS	✓		
<sup>Ellis 4</sup> NORTH NO. 2	Need Spot Dusted "Belt wet and Muddy"	SC	✓		
<sup>Ellis 5</sup> NORTH NO. 3	Need Spot Cleared Head to tail and Dusted	SC	✓		
NORTH NO. 4	None Observed	SC	✓		
NORTH NO. 5	Add Dusting 45-60 BK	SC	✓		
NORTH NO. 6	None Observed	SC	✓		
NORTH NO. 7	Powercenter, Changer OK	MB	✓		
<sup>HP</sup> NORTH NO. 8	Belt need Dusted 29-60 BK	SC	✓		
GLORY HOLE	PC, Changer OK at exam Kuz	MB	✓		
<sup>2 Section</sup> <del>NO.</del> NO. 1	IDLE NO Power	MB	✓		
<sup>2 Section</sup> <del>NO.</del> NO. 2	IDLE NO Power	MB	✓		
3 Section * 1	IDLE PC Pumps OK at exam	LS	✓		
3 Section * 2	IDLE PC Pumps OK at exam	LS	✓		
4 Section	IDLE PC Pumps Changers OK at exam	LS	✓		
LBB	IDLE, PC Pumps OK at exam	LS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0% CO, 20.8% O<sub>2</sub> Detected at exam

Track, Travelway, Powercenter, D-Boxes, Changers OK at exam

Visual check Co monitors OK at time of exam

SIGNED BY: Jay Stewart 39199 Sten glen 3904  
 Belt Examiners and Certificate Numbers  
Mike Bailey 27085  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 3904  
 Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 9-27-09 SHIFT: Eve 6 AM OR PM TO 11 AM OR PM TO PRE-SHIFT EXAM. ON-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2, 3Sec 1 Head (Dusted around 1 Head), etc.

Outby Refuge Chambers OK at time of exam 97, 6, 89, 8 bck section

SIGNED BY: Jay Skurat 39199 Mike Bailey 27085

COUNTERSIGNED BY: Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-23-09 SHIFT: 3rd 12:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
<del>NORTH 2</del> #4		
<del>NORTH 3</del> #5	Cleaned V-Plow	S-C
NORTH 4		
NORTH 5	Cleaned V-Plow at Flo-thru	S-C
NORTH 6	Cleaned V-Plow	MKB
NORTH 7		
<del>NORTH 8</del>	Cleaned around head - dusted	MKB
GLORY HOLE		
#2 Section #1 LBB NO. 1		
#3 Section #2 LBB NO. 2		
#3 Section #1	Filled Trunk Duster, Dusted around Head	NS
#3 Section #2		
#4 Section		
L.B.D.		

Outby Refuge Chambers ok at time of exam 9/23/09, 8 brk 2 section

cleaned off P.C. at 2 brk on #4 North / Also cleaned off P.C. at  
5 brk #4 North store Glesh 3904A

SIGNED BY: John Glesh 3904A Jag Brewat 39199  
Belt Examiners and Certificate Numbers  
Mike Bailey 27085  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: \_\_\_\_\_  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-28-9 SHIFT: Day AM OR PM TO 1200 AM OR PM TO 300 AM OR PM

ON-SHIFT EXAM. Russel Gunnar PRE-SHIFT EXAM. Greg Cole  
Was this report phoned to outside Yes  No  By Whom Pete Peterson Time 240 AM or PM

Report received by: Charles Smith 3122  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs spot cleaning & dusting, needs dusted 28-40BK	JB	✓		
NORTH NO. 1	Needs spot cleaning, needs dusted, needs spot cleaned, top up made with cleaning	JB	✓		
Ellis #4	Needs spot dusted (just 2 minutes)	TP	✓		
Ellis #5	Needs spot cleaned head-tail, needs dusted	TP	✓		
NORTH NO. 4	None observed	RG	—		
NORTH NO. 5	Needs, added dusting 45 to 65	RG	—		
NORTH NO. 6	None observed	RG	—		
NORTH NO. 7	Idle	GC	—		
NORTH NO. 8	needs dusted #1/belt head to end <sup>12:50-2:30</sup>	Jack Roles	✓		
GLORY HOLE	IDLE Pumps here & pump safe at gun	GC	✓		
Doc NO. 1	Needs add cleaning at air lock	GC	✓		
Doc NO. 2	Needs spot cleaned	GC	✓		
Ellis	None observed	TP	✓		
5 Ellis	needs spot clean south end to tail	TP	✓		
3 sec #1	Needs spot cleaning, needs dusted 3-16 Bk	JB	✓		
3 sec #2	Needs spot cleaning & dusting 23-30	JB	✓		
4 sec #1	Work area needs trash, parts etc. picked up & taken to tail	JB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

2BB IDLE, pumps, lower safe at rear CS ✓  
(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% ch 070 CO 20, 870<sup>02</sup>  
Track travel ways, power centers, choppers, clean at time of exam  
Visual check of CD monitor at gun

#1 North chands make #2 & #5 Bk need blood up walking block at tail by steps off old crossover, #7-8, 9, 10 Bks <sup>House</sup> walking need same cleaning & sand sicks set. Needs steps at Overcat 14 Bk JB  
#4 section scoop chaper at head needs dis. extinguisher & mat, potter pallet.

SIGNED BY: Tom Gunnar 32261 Russel Gunnar 29611 Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
Russel Gunnar 1536-17 Greg Cole 1447-A Jack Roles 35881  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: John Cook 3901  
Mine Foreman Certificate No. Superintendent Certificate No.

George Curry 27429 John Bickford 26176 Steve Glen 39042



# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-28-09 SHIFT: EVE AM OR PM TO 830 AM OR PM TO 1130 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Scarbelle & Bedford Time 1105 AM or  PM

Report received by: George Curry 27429  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	needs spot cleaning / dust / needs dusted 28 to 468	SC	/		
NORTH NO. 1	needs dusted / spot cleaned	SC	/		
Ellis 4	none observed	SC	/		
Ellis 5	spot dusted 27 to head	SC	/		
NORTH NO. 4	none observed	SC	/		
NORTH NO. 5	need spot dusted 45 to LD	SC	/		
NORTH NO. 6	none observed	SC	/		
NORTH NO. 7	idle ✓ pc & charger	JAB	/		
H/WALL	need dusted 29 to LD	SC	/		
GLORY HOLE	idle ✓ pc / pumps	JAB	/		
2sec NO. 1	needs add cleaning in by airlock	JAB	/		
2sec NO. 2	need spot cleaned	JAB	/		
1sec 1	none observed	JAB	/		
4sec 1	head area need track picked up	SC	/		
3sec 1	needs spot cleaned / dusted	SC	/		
3sec 2	needs spot cleaned / dusted 23-30	SC	/		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% CH<sub>4</sub> - 0% CO - 20.8% O<sub>2</sub> track, roadways, pcs, chargers  
clean at time of exam  
Visual check to monitor ok at time of exam

SIGNED BY: George Curry 27429 Steve Geh 3704  
 Belt Examiners and Certificate Numbers  
Scarbelle Bedford 2117  
 Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY: [Signature] 3501000  
 Mine Foreman Certificate No. Superintendent Certificate No.



## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-29-09 SHIFT: 3<sup>rd</sup> AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM  
**ON-SHIFT EXAM.** PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom K. Stanley Time 5:44 AM  PM

Report received by: Jim Baynes 3226  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	needs spot cleaned / dusted needs dusted 28 to 40	JSC	<input checked="" type="checkbox"/>		
NORTH NO. 1	needs dusted + spot cleaned	JSC	<input checked="" type="checkbox"/>		
<del>NORTH NO. 2</del> ELLIS #4	None observed	S.C.	<input checked="" type="checkbox"/>		
<del>NORTH NO. 3</del> ELLIS #5	Needs spot cleaned 27 brk to HEAD	S.C.	<input checked="" type="checkbox"/>		
NORTH NO. 4	None observed	S.C.	<input checked="" type="checkbox"/>		
NORTH NO. 5	Needs spot Dusted 45 - 60 brk	S.C.	<input checked="" type="checkbox"/>		
NORTH NO. 6	None observed	S.C.	<input checked="" type="checkbox"/>		
NORTH NO. 7	PC's + chayan ok	SAB	<input checked="" type="checkbox"/>		
<del>NORTH NO. 8</del>	Needs dusted 29-60	KS	<input checked="" type="checkbox"/>		
GLORY HOLE	PC's + Pumps OK	SAB	<input checked="" type="checkbox"/>		
<del>LBB NO. 1</del> 2 Section #1	Needs add'l cleaning in by Air Lock	SAB	<input checked="" type="checkbox"/>		
<del>LBB NO. 2</del> 2 Section #2	Needs spot cleaned	SAB	<input checked="" type="checkbox"/>		
3 Section #1	Need spot cleaned / dusted	JSC	<input checked="" type="checkbox"/>		
3 Section #2	needs spot cleaned / dusted 23:30	JSC	<input checked="" type="checkbox"/>		
4 Section #1	Head AREA needs TRASH picked up	JSC	<input checked="" type="checkbox"/>		
5 Section #1	None obs, Tail need some cleaning	JT	<input checked="" type="checkbox"/>		
LBB	Pump Bore & pumps ok at exam	BC	<input checked="" type="checkbox"/>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
OX CHY, OXCO, 20-8% of detected at time of exam  
Track, Traveling, powercords, boxes, chargers, kvas, oil at time of exam  
Visual check to monitor ok at time of exam

Jim Baynes 1479-A  
Ray Peterson 29611  
George Cherry 23429  
April K. Stutz 39218

SIGNED BY: Alan Cahill 39042  
 Belt Examiners and Certificate Numbers  
Frank Bickford 26176  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Jim Baynes 3226  
 Mine Foreman  
39042  
 Certificate No.  
 Superintendent  
 Certificate No.

46543—BJW Printing & Office Supplies  
Jim Baynes 3226 Russell Dummie 1536-A Jim Cahill 1047-A

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-29-89 SHIFT: 3rd 4:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1	<i>fixed broken chain/silencing at 5812 Bks</i>	<i>JB</i>
<del>ELLIS #4</del> NORTH 2	<i>cleaned V-Plow walkway side</i>	<i>S.C.</i>
<del>ELLIS #5</del> NORTH 3	<i>cleaned V-Plow walkway side</i>	<i>S.C.</i>
NORTH 4		
NORTH 5	<i>cleaned V-Plow at flo-thru</i>	<i>S.C.</i>
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<i>Longwall</i>	<i>cleaned at discharge dusting in progress per K.S.</i>	<i>SAB</i>

*Outby Refuge chambers ok at time of exam 97, 6, 89, 85ck #2 section*

SIGNED BY: *Steve Selch 39242* *John B. Bulford 26176*  
Belt Examiners and Certificate Numbers  
*George Curran 27429* *David W. Dunbar 39218*  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY \_\_\_\_\_  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 9-29-09 SHIFT: DAY AM OR PM TO AM OR PM 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom T. Peterson, G. Cole Time 2:55 AM or PM

Report received by: Russell Dinnel 1536-A  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs spot cleaning, Needs dusted 25-40 Brk	JB	✓		
NORTH NO. 1	See Remarks	JB	✓		
ELL'S #4 NORTH NO. 2	Needs dusted, Needs spot cleaned, Needs dusted at 14 Brk and out	TP	✓		
ELL'S #5 NORTH NO. 3	None Observed	TP	✓		
NORTH NO. 4	Needs Spot Cleaned + Dusted Tail to Head	TP	✓		
NORTH NO. 4	Need Add. Dusting 3 Brk - 8 Brk	RG	✓		
NORTH NO. 5	Needs Add. Dusting 45 to 60 Brk	RG	✓		
NORTH NO. 6	None Observed	RG	✓		
NORTH NO. 7	Idle Power Center + Charger OK	GG	✓		
Low wall NORTH NO. 8	Needs dusted from 32 Brk - Trip Dusted from 45-20 Hand Dusted from 36+50 - JB+CO	JR	✓		
GLORY HOLE	Idle Power Center + Pumps OK	G Cole	✓		
2 section EBB NO. 1	Needs add. cleaning around Air Lock	G Cole	✓		
2 section EBB NO. 2	None observed	G Cole	✓		
3 section #1	Needs dusting 3-16, little spot cleaning	JB	✓		
3 section #2	Needs little cleaning, Needs dusted 25-30 Brk	JB	✓		
4 section #1	water at head (not possible now) See Remarks	JB	✓		
1 Section	Needs tail need add. cleaning	TC	✓		
2 BB	P/C + Pumps clear	TP	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

Visual check of CO monitors OK at time of exam  
 TRACK, TRAVELWAYS, power centers, D-Boxes, CHARGERS clear at time of exam  
 0% ch4, 20.8% O2, 0ppm CO detected at time of exam  
 #1 North needs walking cleared at tail, needs walkway cleared  
 as off side at 7-8, 9-10 and sand jacks set. JB  
 #4 section #1 belt needs fire extinguisher at pickup JB

SIGNED BY: Russell Dinnel 1536-A Den Ullman 1539-A  
 Belt Examiners and Certificate Numbers  
Tom Danner 32261 J Roles 35881  
 Belt Examiners and Certificate Numbers  
L. M. Cole 1947-A

COUNTERSIGNED BY George Curry 27429 Superintendent Steve Gledy 39044  
 Mine Foreman Certificate No. Certificate No.  
John H. Buckford 26176

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-29-09 SHIFT: DAY 6:00 AM OR PM TO 4:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1	3rd shift dusted <sup>machine</sup> from head-18 Bel, cleaned Vplow at tail	JB
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	Cleaned on Tail	RG
NORTH 5	Hand Dusted at Flow-Thru + Tail, cleaned at Flow-Thru + Tail	RG
NORTH 6	Hand Dusted Head, Ruv Duster at 79, cleaned at Tail	RG
NORTH 7		
Long wall	Cleaped and <del>to</del> Dusted Flow thru	GC
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
Ellis 4	cleaned Vplow + washed tail out	TP
3 sec # 1	cleaned, dusted, & greased tail	JB
3 sec # 2	cleaned, dusted, & greased head, & pul bottom Redline <sup>228</sup>	JB
1 section Belt	Cleaned tail piece	GC

T. Peterson 29611

Resuge Chambers at 97, 6, 89, 8 Bel 2 sect. clean at time of exam

+ phones working

20.8% O<sub>2</sub>, 0% CH<sub>4</sub>, 0 ppm CO at time of exam

cleaned off issues box at 18 Bel on 3 sec JB

4 section at Fork Lift chargin I set a sand load at Beam JB

4 section chargin at head now has mats up on pallet

& give retouched.

SIGNED BY: Russell Purnoe 1536-A T. Peterson 29611  
Belt Examiners and Certificate Numbers  
Jim Boyer 32261 Mary Cole 1947-A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: \_\_\_\_\_ Mine Foreman Certificate No. \_\_\_\_\_ Superintendent Certificate No. \_\_\_\_\_

Stan Del 39042

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE, 9-29-09 SHIFT: EVE AM OR PM TO 8:30 AM OR PM TO 11:30 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Steve Campbell J.S. Division Time 11:15 AM or  PM

Report received by George Curry 27429  
 Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	needs spot cleaned; needs dusted 28-40 BK	JSC	/		
NORTH NO. 1	needs spot cleaned; dusted	JSC	/		
Ellis 4	none observed	SC	/		
Ellis 5	needs spot cleaned; dusted tail to head	SC	/		
NORTH NO. 4	need add dusting 3 BK to	SC	/		
NORTH NO. 5	needs Add dusting 45-60 BK Flaw thru needs	SC	/		
NORTH NO. 6	flaw thru needs Add cleaning	GU	/		
NORTH NO. 7	Idle - power center; charges	JAB	/		
4/WALK	needs dusted 32 BK to Tip - needs hand duster 5/150 - 58100 Flaw thru needs	GU	/		
GLORY HOLE	Idle - power center - pumps	JAB	/		
2sec NO. 1	none observed	JAB	/		
2sec NO. 2	none observed	JAB	/		
3sec # 1	need dusted 3:16	JSC	/		
3sec # 2	need spot clean - needs dusted 22-30 BK	JSC	/		
4sec # 1	WATER AHEAD	JSC	/		
1sec # 1	none observed	JAB	/		
LBB	P/Cs / Pumps clear	JSC	/		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% CH<sub>4</sub> - 0% CO - 0% O<sub>2</sub> - track travelways, pc, D-Boles  
chargers clear at time of exam  
visual check co monitors ok  
Stoppings on long belt clear (GU)

SIGNED BY: George Curry 27429 Jay Stewart 39199  
 Belt Examiners and Certificate Numbers  
John B. Buford 21176 Jim 39042  
 Belt Examiners and Certificate Numbers  
Alan Williams 15307

COUNTERSIGNED BY \_\_\_\_\_ Mine Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_  
\_\_\_\_\_ Superintendent \_\_\_\_\_ Certificate No. \_\_\_\_\_

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-27-07 SHIFT: Even 6:00 AM OR PM TO 11:00 AM OR PM TO PM AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM     

Report received by:       
Signed     

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3	Cleaned in Tail / V-Plow / 20 ft. only by Tail	S-C
NORTH 4	Cleaned in Tail Roller	S-C
NORTH 5	Cleaned V-Plow	S-C
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
2 sect #1	Cleaned + dusted in by Air Lock	SAB
1 sect #1	Cleaned at Tail	SAB

Refuge chambers, <sup>S-C</sup> 97, <sup>S-C</sup> 89, 8B OK at time of exam

SIGNED BY: George Cerron 27429 John 37042  
Belt Examiners and Certificate Numbers  
John 28172  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY      37042  
Mine Foreman Certificate No. Superintendent Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indellible Pencil or Ink

DATE 9-30-07 SHIFT: 3rd AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No / By Whom Brought out Time 5:20 AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	needs spot cleaned / dusted 28-40 BK	JSC	✓		
NORTH NO. 1	need spot cleaned / dusted	JSC	✓		
<del>NORTH NO. 2</del>	none observed	GU	✓		
<del>NORTH NO. 3</del>	Need, Spot clean 26BK - Head	S.C.	✓		
NORTH NO. 4	Need, Spot dusted 3-8BK	S.C.	✓		
NORTH NO. 5	Need, All. Dusty 45-60BK / Tail Needs clean	S.C.	✓		
NORTH NO. 6	Flaw throw Add cleaning	GU	✓		
NORTH NO. 7	Power Center + charger OK	JAB	✓		
Longwall	needs dusted 30-Trip or needs Hard Dusted 26-28	GU	✓		
GLORY HOLE	PC's + Pumps - OK	JAB	✓		
2Sec NO. 1	None Observed	JAB	✓		
2Sec NO. 2	None Observed	JAB	✓		
3Sec #1	needs dusted 31b	JSC	✓		
3Sec #2	need spot cleaned / dusted 22-30 BK	JSC	✓		
4Sec #1	water at head	JSC	✓		
1Sec #1	none observed	GU	✓		
LBB	P/C + Pumps clean	JSC	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OSCHY, OS CO, 208X ok detected at time of run  
 Track, Travelways, rollers, D-boxes, KW's, chargers ok at time of run  
 Visual check co monitors ok  
 Longwall stoppings Clear (GU)

SIGNED BY: Jay Hual 39199 George Curry 27429  
 Belt Examiners and Certificate Numbers  
John Allen 15377 John A. Bedford 26176  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 39000x Mine Foreman Certificate No. Superintendent Certificate No.

Jim Lappin 32261 Russell Dummo 153617 Mike Bailey 27088

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE: 9-30-09 SHIFT: 3rd 12:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1	cleaned tail U-plow	JSC
NORTH 1		
NORTH 2		
<del>NORTH 3</del> NORTH 3 J	cleaned tail / U-plow	J.C. GU
NORTH 4	cleaned U-plow	J.C.
NORTH 5	cleaned Flw-thru / Qu-10 Around Flw-thru	J.C. GU
NORTH 6	cleaned Flw-thru	GU
NORTH 7		
<del>NORTH 8</del> NORTH 8	cleaned Tripper flw-thru	GU
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Outby Refuge chambers ok at time of exam 97, 6, 81, 85th 23chm

SIGNED BY: [Signature] 2704 George Curry 27429  
Belt Examiners and Certificate Numbers  
[Signature] 15397A John Bullard 26176  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 33401  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-30-09 SHIFT: Day AM OR PM TO 10:00 AM OR PM TO 3:00 OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Mike Bailey, Propy Time 2:45 AM or PM  
Russell

Report received by: Chark Smith 3/282  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	<i>Needs spot cleaning, needs dusted 35-40 Bk</i>	JB	✓		
NORTH NO. 1	<i>See Remarks Needs dusted, Needs spot clean, tarp needs cleaned</i>	JB	✓		
LBB	<i>Power boxes &amp; sensors ok at exam</i>	LS	✓		
NORTH NO. 4	<i>Needs dusted 3 to 8 Bk</i>	RG	✓		
NORTH NO. 5	<i>needs Added dusting 75 to 60</i>	RG	✓		
NORTH NO. 6	<i>NONE</i>	RG	✓		
NORTH NO. 7	<i>none &amp; d/c Power boxes</i>	MB	✓		
ELWALL	<i>Belt needs more rock dusting</i>	HL	✓		
GLORY HOLE	<i>Idle Power Boxes Chargers</i>	MB	✓		
#1 sec #1	<i>None observed</i>	MB	✓		
#4 sec #1	<i>water at head &amp; tail and cleaned</i>	JB	✓		
2 sec 1 & 2	<i>NONE observed</i>	MB	✓		
4 Ellis	<i>Wet &amp; muddy</i>	<del>MB</del> LS	✓		
5 Ellis	<i>Needs spot dust 26 to head</i>	<del>MB</del> LS	✓		
3 sec #1	<i>Needs dusted 3-16</i>	JB	✓		
3 sec #2	<i>Water behind head some spot cleaning</i>	JB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

20.87% O<sub>2</sub> O<sub>2</sub> Chy O<sub>2</sub> CO detected  
TRACK, TRAVELWAYS, CHARGERS, POWER CENTER ok at time of Exam  
Visual check of CD mounted on at exam  
8-9-6 Shelters ok at exam  
#1 North needs steps built at overcastal 14 Bk, opposite of 7-8, 9, 10 needs walk way cleared & hand jobs set JB

SIGNED BY: Tom Bayne 32261 Russell Dymore 1536-A  
 Belt Examiners and Certificate Numbers  
Mike Bailey 27085 Jack Stuart 39199  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: John Curry 27429 Superintendent  
 Mine Foreman Certificate No.

48543—BJW Printing & Office Supplies  
John G. Burkhead 26176 Glenn Walker 5398 Emil Walker 32670

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9-30-09 SHIFT: Day 6:00 AM OR PM TO 4:00 AM OR PM PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM     

Report received by:      Signed     

BELTS	ACTION TAKEN	INT.
SOUTH 1	<i>shouldered 41-43 Bek, filled down dustier at head Tail</i>	<i>JB</i>
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<i>Cleaned Tail</i>	<i>RG</i>
NORTH 6	<i>Cleaned on Tail &amp; Plow-Then &amp; Dusted</i>	<i>MB</i>
NORTH 7		
LWALL	<i>2 men rockdusting &amp; 2 trickle dustier running.</i>	<i>HL</i>
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<i>3ea #1</i>	<i>set sander jacks at 13 &amp; 14 Bek</i>	<i>JB</i>
	<i>Cleaned &amp; dusted &amp; greased tail</i>	<i>JB</i>
<i>3ea #2</i>	<i>Cleaned &amp; dusted head area, <sup>JB</sup> 3rd shift dusted</i>	<i>JB</i>
	<i><del>but time</del> beltline</i>	<i>LS</i>
<i>Ellis 4</i>	<i>Cleaned U-Plow</i>	<i>LS</i>
<i>Ellis 5</i>	<i>Cleaned U-Plow</i>	

*Took piece extinguisher to 4 section to keep PFD JB  
set 1 sand jack at 13 Bek on track 5 section JB*

*Refuge Chambers 97, 6, 89, 8 Bek 2 sect OK at time of exam (phones working)*

*Steve Gyleh 39042*

*Jackman 39199*

SIGNED BY: *Tim G... 32261* *Russell G... 1536-1A*  
Belt Examiners and Certificate Numbers  
*Mike Bailey 27085*  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY:  Mine Foreman  Certificate No.  Superintendent  Certificate No.

*John Beckel 26171* *Don Williams 1539H* *Dee... 27469* *Kennie Wickham 32620*

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 9.30.09 SHIFT: EVE AM OR PM TO AM OR PM 830 AM OR PM 1130 AM OR PM

ON-SHIFT EXAM. Bulman PRE-SHIFT EXAM. SCAMPELLI

Was this report phoned to outside Yes  No  By Whom Bickford Wickline Time \_\_\_\_\_ AM or PM

Report received by: George Curry  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs spot cleaned / dusted 25-40 BK	JSC	/		
NORTH NO. 1	Need spot cleaned / dusted Takeup needs cleaned	JSC	/		
Ellis 4	wet / muddy	RW	/		
Ellis 5	need add dusting 26 to head	RW	/		
NORTH NO. 4	need dusted 3 to 8 BK	SC	/		
NORTH NO. 5	need add dusting 45 to 60 BK	SC	/		
NORTH NO. 6	none observed Flow thru needs cleaned	GU	/		
NORTH NO. 7	Take / charger / pcs	JAB	/		
Longwall	Needs Add Dusting	GU	/		
GLORY HOLE	Take / pumps / pcs	JAB	/		
1 Sec #1	None observed	JAB	/		
4 Sec #1	water at head / tail needs cleaned	JSC	/		
2 Sec 1	none observed	JAB	/		
2 Sec 2	none observed	JAB	/		
1 section	none observed	GU	/		
3 Sec #1	needs dusted 3-16 BKs	JSC	/		
3 Sec #2	water behind head	JSC	/		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0% CH<sub>4</sub> - 0% CO - 20.8% O<sub>2</sub>  
Track, Travelways, pc's, D Boles, chargers clear at time of exam  
Stoppings on Long wall are clear (GU)

SIGNED BY: George Curry 27429 John Bulford 21176  
 Belt Examiners and Certificate Numbers  
John Bulford 15397 Ronnie Wickline 32670  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: \_\_\_\_\_  
 Mine Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_  
 Superintendent \_\_\_\_\_ Certificate No. \_\_\_\_\_



PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 10-1-09 SHIFT: OW AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes X No    By Whom J. Bidford, Glen Time 5:30 AM or PM

Report received by: George Curry 27429  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	needs spot cleaned / dusted 25 to 40 BK	JSC	✓		
NORTH NO. 1	need spot cleaned / dusted Takeup needs cleaned	JSC	✓		
Ellis 4	wet + muddy	R.W	✓		
Ellis 5	needs add cleanin 26 to head	R.W	✓		
NORTH NO. 4	need DUSTED 3 to 8 BK	JSC	✓		
NORTH NO. 5	needs add dusting 55 to 60 BK	JSC	✓		
NORTH NO. 6	none observed	JSC	✓		
NORTH NO. 7	Take / chargers + pcs	JAB	✓		
4/WALL	need spot dusted - Mother Drive to Tail	JT/GU	✓		
GLORY HOLE	Take / pumps / pc	JAB	✓		
1 sec #1	water ahead - tail needs cleaned	JSC	✓		
2 sec #1	none observed	JAB	✓		
2 sec #2	none observed	JAB	✓		
1 sec	" "	JAB	✓		
LBB	pcs / pumps	RW	✓		
3 sec #1	NEED DUSTED 3-16 BK	JSC	✓		
3 sec #2	WATER BEHIND HEAD	JSC	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% CH<sub>4</sub> - 0% CO - 20.8% O<sub>2</sub> - Tracks, travelways, pcs, 0 Boles  
chargers clear at time of exam  
Rooms Clear on Longwall

SIGNED BY: George Curry 27429 Jerry Stewart 39199  
 Belt Examiners and Certificate Numbers  
John Buford 26176 James Buff 1759A  
 Belt Examiners and Certificate Numbers  
Don Williams 15397

COUNTERSIGNED BY: [Signature] Mine Foreman [Signature] Certificate No.  
 Superintendent [Signature] Certificate No.

48543 - EJV Printing & Office Supplies  
Don Sawyer 3224 Mike Bailey 27085

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-1-09 SHIFT: owl AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom [Signature] Time [Signature] AM or PM

Report received by: [Signature]

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1	cleaned ✓ plow	GC
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	cleaned Flow threw	GU
NORTH 6	cleaned Flow threw	GU
NORTH 7		
<del>NORTH 8</del> <sup>Longwell</sup>	cleaned Flowthrew	GU/AT
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
ellis 4	spot clean	R.W.

Refuge chamber at 97, 10, 89, 8 BK OK at time of exam

SIGNED BY: J. George Curry 27429 Rennie Williams 32670  
Belt Examiners and Certificate Numbers  
John B. Beckford 29176  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] [Signature]  
Mine Foreman Superintendent Certificate No. Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 10-1-09 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Mike Bailey, Lacy Stewart, Harold Lilly Time 2:55 AM or  PM  
Report received by: Bruce Collins 1543-A  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs spot cleaned, Needs dusted 25-40 Bsk	JB	✓		
NORTH NO. 1	Needs add cleaning, Needs dusted, see Remarks	JB	✓		
Ellis #4	Wet & Muddy	LS	✓		
Ellis #5	26BK to Head Needs Add cleaning	LS	✓		
NORTH NO. 4	3 to 8 Needs Dusted	LS	✓		
NORTH NO. 5	45 to 60 Add Dusting	LS	✓		
NORTH NO. 6	NONE OBSERVED	LS	✓		
NORTH NO. 7	CHARGER & POWER CENTERS OK	MB	✓		
Long Wall	Needs spot Dusted	HL	✓		
GLORY HOLE	Pumps & POWER CENTERS OK	MB	✓		
4 Sec #1	Wet & Muddy, needs some Spot cleaning, tail Needs Add cleaning	SH	✓		
2 Sec #1	NONE OBSERVED	MB	✓		
2 Sec #2	" "	MB	✓		
1 Sec	NONE OBSERVED	MB	✓		
LBB	Power down & pumps safe at exam	SH	✓		
3 Sec #1	Needs dusted 3-19 Bsk	JB	✓		
3 Sec #2	some water behind head but passable	JB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
 #1 North needs steps on conveyor at 14 Bsk, Needs sand jackets  
 off-side at 7-8, 9, 10 Bsk, Flaring needs cleaned JB

0% CH4 0% CO 20.8% O2  
 TRAVELWAYS, POWER CENTERS, CHARGERS, D. BOXES OK AT TOE  
 VISUAL CHECK OF CO'S OK AT TOE

SIGNED BY: Mike Bailey 27005  
Jim Sawyer 30261 Lacy Stewart 39199 Scott Holstead 37567  
 Belt Examiners and Certificate Numbers  
Don Williams 153976  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 39199 Superintendent Certificate No.  
 Mine Foreman

48543-BJW Printing & Office Supplies  
Isaac Curry 27429 John Beckford 26174 Ranni Whitelam 32670



Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-19-90 SHIFT: EVE AM OR PM TO 830 AM OR PM TO 1130 AM OR PM   
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Burkford Time 11:00 AM or PM

Report received by: Lanni Wickham 32670  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Need spot cleaned / dusted 2540 BK	JSLC	✓		
NORTH NO. 1	Needs ADD cleaning Needs Dusted	GC	✓		
3500 #1	Needs Dusted 3BK to 19BK	RW	✓		
3500 #2	Some water leaking in hand line	RW	✓		
NORTH NO. 4	3BK to 8BK Needs Dusted	GC	✓		
NORTH NO. 5	NONE OBS	GU	✓		
NORTH NO. 6	NONE observed	GU	✓		
NORTH NO. 7	charger + P.	JAB	✓		
LONGWALL NORTH NO. 8	Needs ADD Dusting	GU	✓		
GLORY HOLE	pumps + power center OK	JAB	✓		
4500 #1	wet + muddy, needs spot dusting.	G.C.	✓		
2500 #1	NONE OBS.	JAB	✓		
ELLIS 4	wet + muddy	RW	✓		
ELLIS 5	26BK to Hand Needs Add cleaning	RW	✓		
2500 #2	NONE OBS	JAB	✓		
1500	NONE OBS	JAB GU	✓		
LBB	P.C. + pumps clear time of exam	RW	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

Cc 0% ch4 % 20.802  
travelway, power center, chargers D-Boxes clean  
Time of Exam.  
Stopping ~~at~~ clear longwall clear

SIGNED BY: Lanni Wickham 32670 John Burkford 26171  
Belt Examiners and Certificate Numbers  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 32670  
Mine Foreman Certificate No. Superintendent Certificate No.



PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE: 10-2-09 SHIFT: OWL AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	need spot cleaned / dusted 25 to 40 BK	JSC	✓		
NORTH NO. 1	need add cleaning / add dust	JSC	✓		
3sec 1	need dusting 3BK 15 19 BK	JSC	✓		
3sec 2	some water behind head	JSC	✓		
NORTH NO. 4	3BK to 8BK need dusted	JSC	✓		
NORTH NO. 5	none observed	JLU	✓		
NORTH NO. 6	none observed	JLU	✓		
NORTH NO. 7	PC's + charger	JAB	✓		
4/WALL	need add dusting Flow thru and <sup>to deck</sup> top	JLU	✓		
GLORY HOLE	PC's + Pumps - OK	JAB	✓		
4sec 1	wet / muddy need spot dusting	JSC	✓		
4sec 1	none observed	JLU	✓		
LBB	Power Controls + pumps CLEAR TOE	RW	✓		
3sec #1	needs dusted 13-19BK	RW	✓		
3sec #2	some water Behind HEAD	RW	✓		
ELLIS 4	wet + muddy	RW	✓		
ELLIS 5	26 BK To Head needs Add Cleaning	RW	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

2500142 None Observed JAB ✓  
 (ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub> - 0% CO - 20.8% O<sub>2</sub> tracks from conveyor per obs  
 charger clear at of clear

SIGNED BY: Jay Stewart 39199  
George Torre 27429 Rennis Winkler 32670  
 Belt Examiners and Certificate Numbers  
John A. Beckford 25176 Alan Williams 15397  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] Mine Foreman Certificate No. [Number] Superintendent Certificate No. [Number]

48543—BJW Printing & Office Supplies  
John [Signature] 32561 Russell Dunmore 1536-A Mike Bailey 27085

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-2-09 SHIFT: OWL AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	cleaned & plow - rock dusted tailpiece	98
NORTH 5		
NORTH 6		
NORTH 7		
<del>NORTH 8</del>	cleaned on Tripper and Flow throw, and made 2 splices	60
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
ELLIS 4	spot cleaned	
ELLIS 5	clean U-plow	

Refuge Chambers at 97, 6, 89, 8 all ok at time of exam

SIGNED BY: George Curry 27429 Rami Wickham 32670  
Belt Examiners and Certificate Numbers  
John A. Beckel 28176 John Wilson 15397A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: \_\_\_\_\_  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-2-09 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Russell Gunnoe, Gary Stencourt Time 2:55 AM or PM

Report received by: Devinne Callin 1543-A  
Signed Harold Lilly

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs spot cleaning, head dusted 35-40 BRK	JB	✓		
NORTH NO. 1	Needs dusted, Needs add cleaning (See Remarks)	JB	✓		
#1 Sec	None observed	MB	✓		
#4 Sec	water behind head, needs spot cleaned	JB	✓		
NORTH NO. 4	needs dusted 3 to 8 BRK	ES RG	✓		
NORTH NO. 5	head needs add dusting	ES RG	✓		
NORTH NO. 6	none observed	ES RG	✓		
NORTH NO. 7	Power hose & charger safe at exam	MB	✓		
L Wall	Needs add dusting	HL	✓		
GLORY HOLE	Power line 7 pumps	MB	✓		
2sec NO. 1	None observed	MB	✓		
2sec NO. 2	None observed	MB	✓		
Ellis #4	none observed	LS	✓		
Ellis #5	26 BK to head needs add cleaning	LS	✓		
3sec #1	Needs dusted 3-19 BRK, needs spot cleaned 6-7 BRK	JB	✓		
3sec #2	some water behind head (but passable)	JB	✓		
LBB	None observed	LS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
 20.89% O<sub>2</sub> 0.60CH<sub>4</sub> 0ppm CO at line of exam  
 track, travelways, pulverizers, & D-bases clean  
 at line of exam  
 Visual check of CD monitors at at exam  
 #1 North needs stop at overcast at 14 BRK, Needs sand Grich  
 at 7-8, 9, 10 BRK, take up needs cleaned JB

SIGNED BY: Devinne Callin 30561 Mike Bailey 27085 Russell Gunnoe 29611  
 Belt Examiners and Certificate Numbers  
Harold Lilly 28015 Russell Gunnoe 1536-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY Mike Callin 39199  
 Mine Foreman Certificate No.  
Devinne Callin 1543-A Jay Street 39199 Superintendent Certificate No.  
Devinne Callin 1543-A

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-2-09 SHIFT: Day 6:00 AM OR ~~PM~~ TO 6:00 ~~AM~~ OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1	<i>cleaned V-plow spillage, dusted tail area, filled sand</i>	<i>JB</i>
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	<i>Dusted 1 to 4 BRK, Shoveled V-plow</i>	<i>RG</i>
NORTH 5	<i>cleaned Tail, cleaned at Flo-Thru</i>	<i>RG</i>
NORTH 6	<i>cleaned flow thru</i>	<i>MB</i>
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
3 sec #1	<i>cleaned, dusted, ground tail, shoveled 2-4 Bk</i>	<i>JB</i>
3 sec #2	<i>cleaned &amp; dusted head area, shoveled 26-27 Bk</i>	<i>JB</i>
Ellis #4	<i>cleaned U-Plow</i>	<i>LS</i>
Ellis #3	<i>cleaned U-Plow</i>	<i>LS</i>

*Refuge Chambers 97, 6, 89, 8 ok at time of exam*

*set sand jack at 30 Bk on 1 South JB*

*set sand jacks both sides 12 Bk on 1 North*

SIGNED BY: *Tom Sawyer 32261*  
Belt Examiners and Certificate Numbers  
*Mike Bailey 27085*  
Belt Examiners and Certificate Numbers

*Russell Gannoe 1536-A*  
*Jan Stewart 39199*

COUNTERSIGNED BY: *Conrad Cook*  
Mine Foreman

Certificate No. \_\_\_\_\_

Superintendent

Certificate No. \_\_\_\_\_

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-2-9 SHIFT: 2ND AM OR PM TO 8:00 AM OR PM TO 11:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom G. Cole Time 10:53 AM or PM  
Report received by: G. Peterson 29611  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	need spot clean, need dusted 25-40 Pk.	TP	-		
NORTH NO. 1	need dusted, need spot clean (See remarks)	TP	-		
E11154	none observed	GU	-		
E11155	26 Pk. to head need spot clean	GU	-		
NORTH NO. 4	need dusted 3-8 Pk.	GU	-		
NORTH NO. 5	Head need add. dust	GU	-		
NORTH NO. 6	<del>none</del> none observed	GU	-		
NORTH NO. 7	IDLE	GC	-		
L/Wall	need clean & add. dusted	GU	-		
GLORY HOLE	Pumps / P/C's	GC	-		
2 <sup>nd</sup> NO. 1	none observed	GC	-		
2 <sup>nd</sup> NO. 2	" "	GC	-		
3 <sup>rd</sup> 1	need 3-19 dusted need spot clean	TP	-		
3 <sup>rd</sup> 2	water behind head - passable	TP	-		
4 <sup>th</sup> 1	water at drive - need spot clean	TP	-		
1 <sup>st</sup> 1	none observed	GU	-		
LBB	Pump / P/C's clear	TP	-		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
NoCH4 detect. 0% 20.802 CO 0%  
Tramways & track clear at time of exam.  
Pumps - P/C's D. Boxes - charger - clear  
Visual on Co's  
1 north take-up need clean TP  
Stoppers on Longwall are clear

SIGNED BY: G. Peterson 29611  
Belt Examiners and Certificate Numbers  
G. Peterson 29611  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Joy Stewart 39199 Mine Foreman  
Certificate No. 39199  
Superintendent  
Certificate No.



PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 10-3-9 SHIFT: Owl AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Gr. Cole, J. Broughton Time 6:50 AM or PM

Report received by: G. Peterson 29611 Tom Dwyer 32261  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	need spot clean, need dusted 25-40 Btk.	TP	-		
NORTH NO. 1	need dusted, need spot clean (see remarks)	TP	-		
Ellis 4	none (see remarks)	TP	-		
Ellis 5	26 Btk, to head need spot clean & dusted	TP	-		
NORTH NO. 4	needs Dusted 3-2 Btk	GU	-		
NORTH NO. 5	Hd needs Add Dust	GU	✓		
NORTH NO. 6	none observed see remarks	GU	✓		
NORTH NO. 7	PC's and Pumps OK	GC	✓		
L/wall	Need cleaned Additional Dusting	GC	✓		
GLORY HOLE	Pumps and PC's OK	GC	✓		
2 <sup>nd</sup> NO. 1	None observed idle	GC	✓		
2 <sup>nd</sup> NO. 2	" " idle	GC	✓		
3 <sup>rd</sup> 1	Needs dusted 3-19 Btk	JLB	✓		
3 <sup>rd</sup> 2	head needs dusted / water behind head	JLB	✓		
4 <sup>th</sup> 1	need water lamped at head & need dusted	TP	-		
1 <sup>st</sup> Sec. 1	None observed	GC	✓		
LBB	Pump. + PC's clean	TP	-		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

Moisture det. O<sub>2</sub> 20.802 CO-O<sub>2</sub>  
 Travel ways & track clean at time of exam.  
 Pumps, PC's - D. Bors. - charger - clean  
 Visual on CO's  
 #1 north need steps at ourcase at 14 Btk. - need Sand Sticks TP  
 Stoppings on long wall clear  
 6 stuck impacts in Tail  
 Ellis 5 still need add. dusting TP

SIGNED BY: G. Peterson 29611 Tom Dwyer 32261  
 Belt Examiners and Certificate Numbers  
Don Williams 1539-A Jim 189-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY John Lab 310000 Mine Foreman Certificate No. Superintendent Certificate No.

40543-B.W. Printing & Office Supplies  
Mike Bailey 27085 Jay Stewart 39199 Tom Dwyer 32261

**ON-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indefinite Pencil or Ink

DATE 10-3-9 SHIFT: 0600 AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
NOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	made splice	GU
NORTH 5	shoveled V Plow Flow Threw	GU
NORTH 6	shoveled V plow Flow threw	GU
NORTH 7		
	Cleaned Flow Threw Cleaned V-plow at tripper	GC
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
Ellis 4	cleaned Vplow & dusted tail	TP

SIGNED BY: [Signature] 29611  
 Belt Examiners and Certificate Numbers  
[Signature] 153972 [Signature] 1947-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 3706000  
 Mine Foreman Superintendent Certificate No.

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 10-3-09 SHIFT: Day AM OR PM TO 12 AM OR PM TO 500 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM. Time 245 AM or PM

Was this report phoned to outside Yes  No  By Whom Brandon B, Mike Bailey

Report received by: Jay Stewart 39199

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	<i>Needs spot cleaning, Needs dusted 25-40 BK</i>	JB	✓		
NORTH NO. 1	<i>Needs add cleaning, Needs dusted (See Remarks)</i>	JB	✓		
<del>Ellis 4</del>	<i>None observed</i>	LS	✓		
<del>Ellis 5</del>	<i>26 BK to head need spot cleaned and Dusted</i>	LS	✓		
NORTH NO. 4	<i>Need Dusted from 3-8 BK</i>	LS	✓		
NORTH NO. 5	<i>None observed</i>	LS	✓		
NORTH NO. 6	<i>None observed</i>	LS	✓		
NORTH NO. 7	<i>PC, Pumps OK at exam</i>	MB	✓		
<del>Longwall</del>	<i>Need more dusting</i>	HL	✓		
GLORY HOLE	<i>Pumps, PC</i>	MB	✓		
<del>2 Sec</del>	<i>None observed</i>	MB	✓		
<del>2 Sec</del>	<i>None observed</i>	MB	✓		
<del>2 Sec</del>	<i>Needs dusted 3-19 BK</i>	JB	✓		
3 Sec 1	<i>Water behind head (not passable)</i>	JB	✓		
3 Sec 2	<i>Tail needs cleaned, needs dusted</i>	JB	✓		
4 Sec 1	<i>Flow thru needs add cleaning</i>	BB	✓		
5 Sec 1	<i>Pumps, Boxes OK at exam</i>	MB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0% CO 20.8% O<sub>2</sub> Detected at exam  
Visual check of CD Stations at exam  
Track, Travelway, PC, Chargers, D-Boxes CO's OK at exam  
#1 North needs steps at 14 Bel Anceast, need some sand jacks set  
off side at 7-8, 9, 10 Bels  
Kim Elson 29611 Brub Doug 1122-A

SIGNED BY: Jay Stewart 39199 Wendy Gully 29045  
 Belt Examiners and Certificate Numbers  
Jim Boyer 39061 Mike Bailey 27085 Harley Taylor 37002  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 39199 Mine Foreman Certificate No. Superintendent Certificate No.

M. C. O. 1947-A [Signature] 1539-A

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-3-09 SHIFT: 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_ Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1	<i>Shouldered 45-47 belt walk side, dusted tail area, filled from dusts at flow thru</i>	<i>JB</i>
NORTH 1	<i>Shouldered &amp; dusted head &amp; tail area</i>	<i>JB</i>
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<i>Dusted around Belthead</i>	<i>LS</i>
NORTH 6		
NORTH 7	<i>Raised cables at charger</i>	<i>MB</i>
<del>1086 62 A 4 8</del>	<i>Closed head &amp; dusted</i>	<i>MB</i>
GLORY HOLE	<i>Took 2 bags dust to longwall construction</i>	<i>MB</i>
LBB NO. 1		
LBB NO. 2		
3 sec #1	<i>Shouldered 5-7 belt, cleaned &amp; dusted &amp; general tail, dusted head area</i>	<i>JB</i>
3 sec #2	<i>cleaned &amp; dusted head area</i>	<i>JB</i>

*Out by Refuges OK at exam*

*0% CH<sub>4</sub>, 0% CO 20.8% O<sub>2</sub> Detected at exam  
Cleaned off power lines at mouth of 3 sections JB*

SIGNED BY: *Jay Stewart 39199* *Meli Bailey 21085*  
Belt Examiners and Certificate Numbers

*Jim Wagner 32361*  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: *[Signature]* *[Signature]*  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-3-9 SHIFT: 2nd AM OR PM TO 8:00 AM OR PM TO 11:00 AM OR PM  
**ON-SHIFT EXAM.** PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom G. Cole Time 11:00 AM or PM

Report received by: T. Peterson 29611

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Em's Pumps P/C clear	TP	/		
NORTH NO. 1	P/C clear	TP	/		
E1154	none observed (See stamp)	GU	/		
E1155	26 Pul. to head need spot clean & dusted	GU	/		
NORTH NO. 4	none observed	GU	/		
NORTH NO. 5	need H/P clean Tail needs clean	GC	/		
NORTH NO. 6	none observed	GU	/		
NORTH NO. 7	IDLE Pumps PC	GC	/		
h/wall	need dusted	GC	/		
GLORY HOLE	PC Pumps	GC	/		
2 Sec. 1	Idle	GC	/		
2 Sec. 2		GC	/		
3 Sec. 1	Chargue P/C's - Pumps clear	TP	/		
3 Sec. 2		TP	/		
4 Sec. 1	P/C's - chargue - clear	TP	/		
h.B.B	Pumps P/C clear	TP	/		
1 sec #1	Flow thru need addl. cleaning	GU	/		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
No CH4 det. @ 20.50 CO 0%  
Travelways + track clear at time of exam  
Visual on CO's  
P/C - Pumps - chargue - D. boxes clear  
E1155 Stair need clean GU.

SIGNED BY: T. Peterson 29611  
 Belt Examiners and Certificate Numbers  
John Wilson 1529A G. Cole 1947-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: G. Cole 330600  
 Mine Foreman Certificate No. Superintendent Certificate No.



## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-4-09 SHIFT: owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Larry Brown Time 546 AM or PM  
Report received by: John A. Buckford  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	> Made Fire Run no Hazards found	TP	—		✓
NORTH NO. 1					
Ellis 4	none observed	GU	—		
Ellis 5	needs spot cleaned 26-Hd	GU	—		
NORTH NO. 4	None Observed	GU	✓		
NORTH NO. 5	None observed	GU	✓		
NORTH NO. 6	None observed	GC	✓		
NORTH NO. 7	Idle PUMP PC	GC	✓		
Longwell	Needs add'l dusting	LB	✓		
GLORY HOLE	Idle Pumps PC	GC	✓		
2 <sup>nd</sup> NO. 1	Idle NO Power	GC	✓		
2 <sup>nd</sup> NO. 2	Idle NO Power	GC	✓		
4 Sec. 1	Made Fire Run - No Hazards found	TP	—		✓
3 Sec. 1	Made Fire Run - No Hazards found	SP	—		—
3 Sec. 2	Made Fire Run No Hazards found	TP	—		✓
hBB	Pumps P/C's clear	TP	—		
15cc #1	Flow thru need add' cleaning	GU	—		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

02Ch4, 02CO, 208202  
PC, Chargers, Pumps clear ATOC  
out by Re-fuges clear ATOC  
CO's clear ATOC  
Longwell Stoppings clear

SIGNED BY: Don Williams 1539-A Greg Cob 1947-A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] [Signature]  
Mine Foreman Superintendent Certificate No.



Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-7-04 SHIFT BNL AM OR PM TO 1200 AM OR PM TO 300 AM OR PM  
**ON-SHIFT EXAM.** PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom J. Burkhead Time 225 AM or PM

Report received by: George Curry 27429  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Belts Idle Powercenters, chargers - OK	SH	✓		
NORTH NO. 1	Belts Idle Powercenters chargers	SH	✓		
3 Section #1	PC's, chargers - OK section Idle	SH	✓		
3 Section 2	PC's chargers OK	SH	✓		
NORTH NO. 4	None observed	JSC/RW	✓		
NORTH NO. 5	None observed	JSC	✓		
NORTH NO. 6	None observed	JSC	✓		
NORTH NO. 7	Idle - pc + chargers	JAB	✓		
L/COAL	Belt needs Rockover	NL	✓		
GLORY HOLE	Idle - pump! pcs	JAB	✓		
1 sec LBB NO. 1	Idle - stepping / track clear	JAB	✓		
2 sec LBB NO. 2	Idle - stepping / track clear	JAB	✓		
1 sec P	None observed	JAB	✓		
ELLIS #4	None observed	RW	✓		
ELLIS #5	26 BK TO HEAD needs spot @ lens	RW	✓		
4 Section #1	Idle - PC's, chargers, track - Clear	SH	✓		
LBB	Pumps / PC's clear at time of exam	JSC/RW	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% CH<sub>4</sub>, 0% CO, 0% O<sub>2</sub> track, trackways, pcs, rollers  
chargers clear at time of exam

SIGNED BY: George Curry 27429 Ronnie Wicklin 32670  
Belt Examiners and Certificate Numbers  
John Burkhead 26176 Scott Holstead 37567  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 39000  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indefinite Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-4-09 SHIFT: DAY AM OR PM TO 1200 AM OR PM TO 300 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	cleaned V-plow - rock dusted tailpiece	JSC
NORTH 5	cleaned V-plow / tailpiece	JSC
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
<sup>1-2-7</sup> LBB NO. 1	cleaned at discharge	JAB
LBB NO. 2		
ELLIS #4	cleaned V-plow + spot dusted	RW
ELLIS #5	CLEAN V-plow	RW

Reggie Chambers 97, 6, 89, 18 BK ok at time of exam

EXAMINED BY: George Curran 27429 Ronnie Wickline 32670  
Belt Examiners and Certificate Numbers  
John B. Bell 26176  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 3501000  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-4-09 SHIFT: 2nd AM OR PM TO 8:00 AM OR PM TO 11:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom T. Peterson S. Camble Time 10:50 AM or PM

Report received by: K. Farmer Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	<u>ROLL</u>	<u>TP</u>	<u>beta</u>		
NORTH NO. 1	<u>ROLL</u>	<u>TP</u>	<u>beta</u>		
<del>NORTH NO. 2</del>	<u>Idle</u>	<u>TP</u>			
<del>NORTH NO. 3</del>	<u>Idle</u>	<u>TP</u>			
NORTH NO. 4	<u>N/O</u>		<u>SC</u>		
NORTH NO. 5	<u>N/O</u>		<u>SC</u>		
NORTH NO. 6	<u>N/O</u>		<u>SC</u>		
<del>NORTH NO. 7</del>	<u>Idle P. pumps</u>	<u>GC</u>	<u>GC</u>		
<u>1 Sec</u>	<u>NONE observed</u>	<u>GC</u>	<u>GC</u>		
<u>GLORY HOLE</u>	<u>ROLL Pumps, PCs, Chargers OK</u>	<u>GC</u>	<u>GC</u>		
<u>2 Sec #1</u>	<u>IDLE Power Centers OK</u>	<u>GC</u>	<u>GC</u>		
<u>2 Sec #2</u>	<u>IDLE Pumps PC's and chargers OK</u>	<u>GC</u>	<u>GC</u>		
<u>Elk #5</u>	<u>26 Drk to Hll. roads cleaned</u>	<u>SC</u>	<u>SC</u>		
<u>Elk #4</u>	<u>N/O</u>	<u>SC</u>	<u>SC</u>		
<u>3 Sec #1</u>	<u>ROLL</u>	<u>TP</u>	<u>beta</u>		
<u>3 Sec #2</u>	<u>ROLL</u>	<u>TP</u>	<u>beta</u>		
<u>3 Sec #4</u>	<u>ROLL</u>	<u>TP</u>	<u>beta</u>		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

LBB Pump/plc's clear TP ✓  
(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
Rebuy chubon 97 Btk - OK  
" " 6 Btk 89 Drk OK  
All Pumps relays switched to Planting and  
LBS - N/O  
East Pumps - N/O  
Visual on CO's Track, Traveling, powerlines, D-boxes, Kins OK  
0.1ctm, 0.1CO, 20.8102 detected at time of ex

SIGNED BY: T. Peterson 2904 John 3404  
Belt Examiners and Certificate Numbers  
May 6th 1947-A

COUNTERSIGNED BY [Signature] Superintendent  
Mine Foreman Certificate No.



Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-5-07 SHIFT: 3rd AM OR PM TO 3:00 AM OR PM TO 6:00 PRE-SHIFT EXAM.  AM OR PM TO 6:00 AM OR PM TO 3:00 ON-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	need spot clean - need dusted 25-40 lsk.	TP	—		
NORTH NO. 1	need add cleaning need dusted (See L.)	TP	—		
NORTH NO. 2	None observed	S-C	✓		
NORTH NO. 3	26 lsk - Head needs cleaned & dusted	S-C	✓		
NORTH NO. 4	None observed	S-C	✓		
NORTH NO. 5	None observed	S-C	✓		
NORTH NO. 6	None observed	S-C	✓		
NORTH NO. 7	Idle P/C, chargers	GC	✓		
NORTH NO. 8	Needs dusted	KS.	✓		
GLORY HOLE	Tally pumps, chargers	GC	✓		
LBB NO. 1	Idle P/C, chargers	GC	✓		
LBB NO. 2	Idle P/C, chargers	GC	✓		
#3 Sec #1	need spot clean & spot dusted	TP	—		
#3 Sec #2	need spot clean & dusted in place	TP	—		
#4 Sec #1	need dusted - water at head (possible)	TP	—		
LBB	Checked Pumps & P/C's	TP	—		
1 Sec	Kibbellen Lateral	GC	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
 OX CH<sub>4</sub>, Oppan CO, 20.8% O<sub>2</sub> detected at time of exam  
 Tracks, travel pumps, power centers, D-boxes, chargers, KWAS on at time of exam  
 Visual check of CO monitors ok  
 need cross over at over cast 14 lsk.

SIGNED BY: Steve John 39244 Ray Clemens 21611  
 Belt Examiners and Certificate Numbers  
David Kelly 39218 D/ef col 1047-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: John A. B... 39218  
 Mine Foreman Certificate No. 1536-A Superintendent

46543—BJW Printing & Office Supplies  
John A. B... 26174 Tom Berger 32261  
 Certificate No.



Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-5-09 SHIFT: DAY AM OR PM TO 1200 AM OR PM TO 300 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes X No    By Whom J Bickford R Gunnor Time 226 AM or PM  
Report received by: George Curry 27429  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs dusted 25-40, head spot cleaning	JB	✓		
NORTH NO. 1	Needs dusted, head add cleaning (See Remarks)	JB	✓		
Ellis #4	none observed	JSC	✓		
Ellis #5	26 to head needs cleaned/dusted	JSC	✓		
NORTH NO. 4	none observed	JSC	✓		
NORTH NO. 5	none observed	RG	✓		
NORTH NO. 6	head filter need dusted	RG	✓		
NORTH NO. 7	Take PCs & chargers	JAB	✓		
1/2 Wall	needs add dusting	RG	✓		
GLORY HOLE	Take PCs & pumps	JAB	✓		
2 <sup>nd</sup> NO. 1	Take PCs + charger OK	JAB	✓		
2 <sup>nd</sup> NO. 2	Take PCs + charger OK	JAB	✓		
LBB	Checked pumps & boxes	JSC	✓		
3 sec #1	Needs dusted 2-19, (some spot cleaning) <sup>Bookstand 10-11 B.K.</sup>	JB	✓		
3 sec #2	Needs spot dusted (some spot cleaning) head but possible	JB	✓		
4 sec #1	Needs dusted, some water at head (using pump)	JB	✓		
#1 Sec	Rib Roll on Life Life	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0.7% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO Detected at Exam time  
Powercenters, D-Boxes, chargers, track, travelways OK at EXAM  
Visual CK of CO monitors - OK at EXAM  
#1 North needs steps at succast at 14' bel, Needs some sand jacks  
set at 6, 7-8, 9, 10 Boks. JB

SIGNED BY: George Curry 27429 Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
John Gunnor 30361 John Bickford 26176 Russell Gunnor 1536-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Nancy Peterson 29611 8500000 Stu Gu 39012  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-5-09 SHIFT: DAY 6:00 AM OR 6:00 PM TO AM OR PM AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM

Report received by:     

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1	Greased South tail, <i>cleaned &amp; dusted 46 tail area</i>	SH JB
NORTH 1	<i>dusted head area</i>	JB
Ellis 5	<i>cleaned v. plow / tail piece</i>	
NORTH 4	<i>cleaned v. plow - spot cleaned for drive to head</i>	DC
NORTH 5	<i>cleaned v. plow at Tail + Flow-Through, Run Duster at 42 Brk</i>	RG
NORTH 6	<i>cleaned v. plow</i>	
NORTH 7		
NORTH 8		
GLORY HOLE		
15' cut LBB NO. 1	<i>cleaned at tail + head</i>	JAB
LBB NO. 2		
3 sec # 1	<i>dusted head &amp; tail area, cleaned, dusted, greased tail</i>	JB
3 sec # 2	<i>cleaned &amp; dusted head area</i>	JB
4 W Belt	<i>cleaned &amp; dusted tripper - hand dusting tripper towards # 1 Section</i>	

Outby Refuge Chambers - <sup>8C 8C</sup> 7, 97, <sup>JAB</sup> 89, <sup>JAB</sup> 88K or a Section

SIGNED BY: George Curry 27429 John A. Bueford 26171 Scott Halstead 37567  
Belt Examiners and Certificate Numbers  
Jim Boyer 32261  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY      Mine Foreman      Certificate No.      Superintendent      Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE Oct 5, 09 SHIFT: Even AM OR PM TO 8:30 AM OR PM TO 11:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom T. Peterson - G. Cole Time            AM or PM

Report received by: *[Signature]* 1259-A  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs spot cleaned Dusted 25-40% <sup>2</sup>	TP	✓		
NORTH NO. 1	Needs dusted, needs add cleaners	TP	✓		
<sup>EMIS 4</sup> NORTH NO. 2	None observed	TP	✓		
<sup>EMIS 5</sup> NORTH NO. 3	26 to Head needs Add cleaners	TP	✓		
NORTH NO. 4	None observed	S-C.	✓		
NORTH NO. 5	" "	S-C.	✓		
NORTH NO. 6	Head and tail needs Dusted	S-C.	✓		
NORTH NO. 7	Idle PIC, chargers OK	GLC	✓		
<sup>4 call</sup> NORTH NO. 8	Needs Add Dusting	GLC	✓		
GLORY HOLE	Idle PIC Pumps clear	GLC	✓		
<sup>2 Sec #1</sup> LBB NO. 1	Idle PIC and Pumps, chargers OK	GLC	✓		
<sup>2 Sec #2</sup> LBB NO. 2	" " " "	GLC	✓		
3-Sec #1	3 to 19 needs dusted over spot cleaned	TP	✓		
3-Sec #2	Water behind Head needs spot cleaned	TP	✓		
LBB	Pumps and Boxes OK	TP	✓		
4 Sec.	Head needs dusted	TP	✓		
#1 Sec	NONE OBSERVED	GLC	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
CH<sub>4</sub> 0.0% CO 0% O<sub>2</sub> 20.8% at time of exam.  
Powercenter, chargers, travelways, track clear at time of exam.  
CO OK at time of exam.  
#1 North needs steps at overcast at 14:00

SIGNED BY: *[Signature]* 24611 *[Signature]* 39042  
 Belt Examiners and Certificate Numbers

*[Signature]* 1947-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: *[Signature]* 3306000                        
 Mine Foreman Certificate No. Superintendent Certificate No.



**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indefinite Pencil or Ink

DATE 10-6-09 SHIFT: Dwl AM OR PM TO 3:00 AM OR PM TO 6:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Pete Time 6:10 AM or PM

Report received by: Jim Bayne 32261  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs spot cleaned, Needs dusted 25-40	TP	✓		
NORTH NO. 1	Needs dusted needs add cleaning	TP	✓		
Ellis # 4	None Observed	TP	✓		
Ellis # 5	None Observed	TP	✓		
NORTH NO. 4	None Observed	GLC	✓		
NORTH NO. 5	None Observed	GLC	✓		
NORTH NO. 6	Head + Tail need Dusted	GLC	✓		
NORTH NO. 7	Idle - Power Center, charger OK	GLC	✓		
Swall	Needs Add. Dusting, needs spot cleaned 9-11	GLC	✓		
GLORY HOLE	Idle - Power Center + Pumps OK	GLC	✓		
#2 Sec NO. 1	Idle - Power center, pumps, chargers OK	GLC	✓		
#2 Sec NO. 2	Idle - Power centers, pumps, chargers OK	GLC	✓		
3 Sec # 1	3-19 needs dusted and spot cleaned	TP	✓		
3 Sec # 2	unterside head, needs spot cleaned	TP	✓		
4 Sec # 1	Head needs dusted	TP	✓		
#1 Sec	None observed	GLC	✓		
LBB	Pumps + Power boxes OK	TP	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% CO<sub>2</sub> 0% CO 20.8% O<sub>2</sub> detected  
track, travel ways, chargers power down safe at exam  
Visual check of CO monitors safe at exam

SIGNED BY: Ray [Signature] 29411 Ly [Signature] 1947-A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 230000 Mine Foreman Certificate No.  
 Superintendent George [Signature] 27429 Certificate No.

46543-B3W Printing & Office Supplies  
32261 John A. Bickford 2617A Russell Dumore 1536-A

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-10 SHIFT: 0600 AM OR PM TO 1500 AM OR PM TO 0630 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
Ellis 5	rock dusted at Drive to Ellis 4 tail	TP

<sup>TP</sup>  
 Refuge Chambers (97, 6, 89, 8) Ark 2 sect. clear at time of  
 exam 20.8% O<sub>2</sub>, 0% CH<sub>4</sub>, 0 CO  
 Updates fire ext. at Ellis 5 head for oct.

SIGNED BY: [Signature] 29011  
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] Mine Foreman [Signature] Certificate No. 370000 Superintendent \_\_\_\_\_ Certificate No. \_\_\_\_\_

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-6-09 SHIFT: DAY AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom J. Bickford, Russell, Time 7:45 AM or ~~PM~~  
Report received by: Bruce Collins 1543-A  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Needs spot cleaning, Needs dusted 25-40 Bed	JB	✓		
NORTH NO. 1	Needs dusted, Needs spot cleaned, See Remarks	JB	✓		
Ellis 4	None observed	JSC	✓		
Ellis 5	None observed	JSC	✓		
NORTH NO. 4	None observed	JSC	✓		
NORTH NO. 5	None observed	RG	✓		
NORTH NO. 6	Head tail need dusted	RG	✓		
NORTH NO. 7	Idle, power switches & chargers clean at TOE	JAB	✓		
L/Wall	Need add dusting needs spot cleaned 9 to 11	RG	✓		
GLORY HOLE	Idle, power switches & pumps clean at TOE	JAB	✓		
#2 sect. 1	Idle, power switches, pumps & chargers OK AT TOE	JAB	✓		
#2 sect. 2	Idle, power switches, pumps, & chargers OK AT TOE	JAB	✓		
#4 Section #1	Head Needs Dusted, Belt needs Added Dusting	SH	✓		
3sec #1	3 to 19 needs dusted & spot cleaned	RF	✓		
3sec #2	Water Behind Head, needs spot cleaned	RF	✓		
#1/sect. #1	tail needs cleaned	JAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

20.8% O<sub>2</sub> 0% CH<sub>4</sub> 0ppm CO at time of exam

Track, tunnelways, power switches, chargers all clean at time of exam

#1 North needs steps at succast at 14 bed. Needs some sand jacked at 6, 7-8, 9-10 beds JB

Back faster 28234

SIGNED BY: Scott Halstead 37567 John Bickford 21174  
Belt Examiners and Certificate Numbers  
George Perry 27429 Russell Sumner 1536-A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY John Carl 3306007 Superintendent Certificate No.  
Mine Foreman  
Jack Stewart 39199 Oliver Johnson 1537A Dr. Jim 39042  
39042

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-6-09 SHIFT: DAY 6:00 AM OR PM TO 4:00 AM OR PM          AM OR PM TO          AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom          Time          AM or PM

Report received by:           
Signed         

BELTS	ACTION TAKEN	INT.
SOUTH 1	<i>Dusted Portal - 2 Belts, shoveled 44-46 Belts (head side) spilled beam dust at glider</i>	<i>JB</i>
NORTH 1	<i>cleaned on tail</i>	<i>SH</i>
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<i>Shoveled V-Plow</i>	<i>RG</i>
NORTH 6	<i>Hand Dusted Tail to 101 Belts</i>	<i>RG</i>
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
4 Section	<i>cleaned spillage at tail, Dusted Belt Line</i>	<i>SH</i>
El 135	<i>cleaned V plow; tail piece</i>	<i>SH, RG</i>
El 134	<i>cleaned V plow</i>	<i>RG</i>
3 sec #1	<i>dusted head &amp; tail area, cleaned &amp; dusted tail</i>	<i>JB</i>
	<i>dusted 18-19 Belts</i>	
3 sec #2	<i>dusted head area</i>	<i>JB</i>

*Refuge Chamber at 97, 98, 89; 8 BK all ok at time of exam*

*cleaned off Lamin Box at 1 North head. JB*

EXAMINED BY: Scott Halstead 37567 John A. Bickford 21171  
Belt Examiners and Certificate Numbers  
George Curry 27429 Paul Bayler 32261  
Belt Examiners and Certificate Numbers  
 SUPERVISOR BY:          3746000  
Mine Foreman Certificate No.  
Superintendent Certificate No.

*John G. 29041*

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 10-6

SHIFT: Even

AM OR PM TO

AM OR PM

8:30 AM OR PM TO 11:30 AM OR PM

PRE-SHIFT EXAM.

ON-SHIFT EXAM.

Time 11 AM or PM

Was this report phoned to outside Yes  No  By Whom Mike Bailey

Report received by: Joy Stewart 39199

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Need Spot Cleaning, Need Dusted 25 to 40 BK	LS	✓		
NORTH NO. 1	Needs Dusted and Need Spot Cleaned "See Remarks"	LS	✓		
<del>NORTH NO. 2</del>	<del>none observed</del>	<del>GU</del>	<del>✓</del>		
<del>NORTH NO. 3</del>	<del>Needs cleaned 26-Head / offside Tail Needs cleaned</del>	<del>S.C.</del>	<del>✓</del>		
NORTH NO. 4	None observed	S.C.	✓		
NORTH NO. 5	None observed	S.C.	✓		
NORTH NO. 6	needs Spot Dusted	GU	✓		
NORTH NO. 7	Idle PC, Charger OK at exam	MB	✓		
<del>NORTH NO. 8</del>	<del>needs Add Dusting Top Tail needs cleaned</del>	<del>GU</del>	<del>✓</del>		
GLORY HOLE	Idle, PC, Pumps OK	MB	✓		
<del>2.5 Sec</del> NO. 1	<del>Idle PC Pumps Clean at exam</del>	<del>MB</del>	<del>✓</del>		
<del>2.5 Sec</del> NO. 2	<del>Idle PC Pumps Clean at exam</del>	<del>MB</del>	<del>✓</del>		
3 Sec #1	3-19 BK Needs Dusted	LS	✓		
3 Sec #2	Water behind head, Need Spot Cleaned	LS	✓		
4 Sec #1	Head Needs Dusted, Belt need add Dusting	LS	✓		
1 Sec #1	Tail needs cleaned	GU	✓		
LBB	Pumps, Boxes OK at exam	LS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sup>4</sup>, 0% CO, 20.8% O<sub>2</sub> Detected at exam

Track, Travelway, PC, D-Boxes, Pumps OK at exam

Longwall stoppings are clear  
CO's OK at exam

1 North needs Steps at overcast at 14 BK, Need sandjacks  
set at 6, 7-8, 9-10 BK

SIGNED BY: Joy Stewart 39199

Belt Examiners and Certificate Numbers

D. Gen Williams 15397A Mike Bailey 27085  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY Cash

Mine Foreman

39199

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-6 SHIFT: Eve 8 AM OR PM TO 11 AM OR PM TO AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Mike Bailey Time            AM or PM

Report received by: Joy Stewart 39199  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
<del>ELLIS #5</del>		
NORTH 4	cleaned walkway side of Tail & Tailcoller (offside still need clean)	S-C
NORTH 5	cleaned on Tail	S-C
NORTH 6	cleaned U-Plow both sides & Dusted	S-C
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
3 Sec *1	Cleaned U-Plow	✓
1 sec	cleaned on tail	60

Out by Refuse OK at etam 97, 6, 89, 85ck #2 Section

SIGNED BY: Joy Stewart 39199 Mike Bailey 27085  
Belt Examiners and Certificate Numbers  
Don Williams 1539A Stewart 39042  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY                                            
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-7-01 SHIFT: 3rd AM OR PM TO 6:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time          AM or PM

Report received by:         

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	Need Spot Cleaned, Need Dusted 25-40 BK	LS	✓		
NORTH NO. 1	Need Spot Dusted and Spot Cleaned "See Remarks"	LS	✓		
<del>NORTH NO. 2</del>	none observed	GU	✓		
<del>NORTH NO. 3</del>	Need Spot cleaned HA - 25 BK / OFFSIDE Tail Needs cleaned	S.C.	✓		
NORTH NO. 4	None observed	S.C.	✓		
NORTH NO. 5	None observed	S.C.	✓		
NORTH NO. 6	Needs Spot Dusted see Remarks	GU	✓		
NORTH NO. 7	Idle AC Charge Truck	MB	✓		
<del>NORTH NO. 8</del>	needs Add Dusting	GU	✓		
GLORY HOLE	Idle PC Pumps	MB	✓		
EBB NO. 1	None Observed	MB	✓		
EBB NO. 2	None Observed	MB	✓		
#3 sec #1	3-19 BK Need Dusted	LS	✓		
#3 sec #2	Water behind head need Spot Cleaned	LS	✓		
#4 sec #1	Head needs Dusted, Belt need add Dusting	LS	✓		
#1 sec #1	Tail needs add cleaning	GU	✓		
L.B.S	Pumps, Boxes OK at exam	LS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OXCHY, Ogen CO, 20.8% of detected at time of exam  
 Tank, Traveling, power cables, D-boxes, KWAs, chargers ok at the exam  
 Visual check CO monitors ok

Stoppings on longwall are clear

6 North Tail needs impacts Changed

1 North needs Steps a overcart at 14 BK, Need Sandjacks set at 6, 7-8, 9-10 BK

SIGNED BY:

39000 Mike Bailey 22085  
 Belt Examiners and Certificate Numbers

15397 Jay Stewart 39199  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY         

Mine Foreman

Certificate No. 39000

Superintendent

Certificate No. 3226

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 10-7-09 SHIFT: 3rd 12:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1	Cleaned U-Plow	L5
NORTH 1		
<del>NORTH 2</del> NORTH 2	cleaned U-Plow	GU
<del>NORTH 3</del> NORTH 3	cleaned walking side V-Plow	S-C
NORTH 4		
NORTH 5	clean U-Plow at Flo-thru	S-C
NORTH 6		
NORTH 7		
<del>NORTH 8</del> LONGWELL NORTH 8	Cleaned Tripper Tail made 2 splices	GU SC
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
3Sec #1	Greased Head, Cleaned U-Plow	L5
Section	cleaned on Tail	GU

Outby Refuge chambers ok at time of exam 97, 98, 99, 88rb # d Sec. S.C. S.C. GU

SIGNED BY: [Signature] 39042 [Signature] 59199  
Belt Examiners and Certificate Numbers  
[Signature] 15347 [Signature] 27085  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 3506007  
Mine Foreman Certificate No. Superintendent Certificate No.

46543—BJW Printing & Office Supplies  
[Signature] 26176 [Signature] 32670