

AW  
5-25-10-11

NORTH Side Belts  
STARTED 12-23-09

ELLIS Switch Inby Belts

**EXAMINATION OF  
BELT CONVEYORS**

**NORTH BELTS**

COMPANY PERFORMANCE COAL  
MINE UBB  
LOCATION NAOMA RALIEGH WV  
Post Office County State

Started Prematurely  
Do NOT use this one  
Till other one is full

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 12-23-09 SHIFT: Day AM OR PM TO 1800 AM OR PM TO 300 AM OR PM TO 6  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM     

Report received by:      Signed     

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1					
NORTH NO. 1					
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	None observed	RG/BC	✓		
NORTH NO. 5	none observed	BC	✓		
NORTH NO. 6	needs spot dusted	BC	✓		
NORTH NO. 7	Idle-charger, pc OK	RG			
<del>NORTH NO. 8</del>	Needs Add Dusting	HL/OKS			
GLORY HOLE	Idle-D-Box, pumps OK	RG			
LBB NO. 1					
LBB NO. 2					
Ellis 4	needs dusted	RG			
5	head needs cleaned	RG			
HG 22#1	Needs dusted from Head to tail	BC	✓		
HG 23#1,2,3	IDLE NO POWER				
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:     

Pumps clean electly 2.0802, opp CO detected at time of exam  
TRACK, TRAVELWAYS, POWERCENTERS, D-BOXES, CHARGERS CLEAR AT TIME OF EXAM  
VISUAL CHECK OF CO MONITORS OK AT TIME OF EXAM

see Board for Rollers  
 SIGNED BY: Russell Dunroe 1536-A Glen Williams 1530A  
 Belt Examiners and Certificate Numbers Daniel K. Schuster 39218  
W. J. ... 1354-1A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Chager 26041  
 Mine Foreman Certificate No. Superintendent Certificate No.

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 12-23-09 SHIFT: DAY AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	<i>pumped water 12+17 BRKs</i>	<i>RG</i>
NORTH 5	<i>pumped water 46 BRK , Pumped water at 40 brk</i>	<i>RG/BC</i>
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<i>E4</i>		
<i>E5</i>		

*Resuge chambers 6,89, clear at time of exam phones working*

SIGNED BY: *Russell Dunnoe 1536-A*  
Belt Examiners and Certificate Numbers

*WSD Chappel 1354-17*  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *[Signature]* *26041*  
Mine Foreman Certificate No.

Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 12-25-09 SHIFT: eve AM OR PM TO 8:30 AM OR PM TO 11:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Brought out  
Signed \_\_\_\_\_

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Belts Idle PC, Charges Pumps, and D-Boxes OK	GU	/		
Ellis 5		GU	/		
NORTH NO. 4		GU	/		
NORTH NO. 5		GU	/		
NORTH NO. 6		GU	/		
NORTH NO. 7		GU	/		
L/Wall		GU	/		
GLORY HOLE		GU	/		
H623 #1		GU	/		
H623 #2		GU	/		
H623 #3	GU	/			
H622 #1	GU	/			

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0604, 0600, 20R202

PC, Charges, Travelways OK At time of exam

SIGNED BY: [Signature] 15397  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 26041  
Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 12-25-09 SHIFT: EUC 600 AM OR PM TO 600 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Bought out

Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2.

Out by Refuges clear At time of Exam

SIGNED BY: Dan Miller 1539A

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] Mine Foreman

26024 Certificate No.

Superintendent

Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 12-26-09 SHIFT: OWL AM OR PM TO 300 AM OR PM TO 600 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Brought out  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Uwall</u>	<u>needs Add Ousting</u>	<u>KS</u>	<u>✓</u>		
<u>Ellis4</u>	<u>Needs Dusted</u>	<u>GLC</u>	<u>✓</u>		
<u>Ellis5</u>	<u>water at 29 Brk</u>	<u>GLC</u>	<u>✓</u>		
<u>NORTH NO. 4</u>	<u>none observed</u>	<u>GLC</u>	<u>✓</u>		
<u>NORTH NO. 5</u>	<u>none observed</u>	<u>GU</u>	<u>✓</u>		
<u>NORTH NO. 6</u>	<u>needs spot Dusted</u>	<u>GU</u>	<u>✓</u>		
<u>NORTH NO. 7</u>	<u>PC charger OK</u>	<u>GU</u>	<u>✓</u>		
<u>NORTH NO. 8</u>					
<u>GLORY HOLE</u>	<u>D-Box Pump OK</u>	<u>GU</u>	<u>✓</u>		
<u>HG22 1</u>	<u>Needs Dusted Hd-Tail</u>	<u>GU</u>	<u>✓</u>		
<u>HG23 1</u>	<u>&gt; NO Power NO Preshift</u>				
<u>HG23 2</u>					
<u>HG23 3</u>					

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OBCH4, OZCO, 20.8302  
PC'S, Chargers, Pumps, Travelways OK AT TOE

SIGNED BY: [Signature] 1537A [Signature] 28045  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 2604W [Signature]  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 12-26-09 SHIFT: owl 600 AM OR PM TO 600 (AM OR PM) AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed Brought out

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Outby Refuge OK

SIGNED BY: [Signature] 15394  
Belt Examiners and Certificate Numbers  
[Signature] 1947-A  
Belt Examiners and Certificate Numbers  
COUNTERSIGNED BY: [Signature] 26044  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 12-26-09 SHIFT: DAY AM OR PM TO 1200 AM OR PM TO 12:45 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Bill Campbell / John Bickford Time 2:50 AM or PM

Report received by: John Wilton  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	CHY	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1						
<u>19/20</u> Ellis #4 2	<u>Needs add'l cleaning</u>	<u>0%</u>	<u>HL</u>	<input checked="" type="checkbox"/>		
	<u>NEEDS dusted</u>	<u>0%</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
Ellis #5	<u>WATER AT 29 BRT</u>	<u>0%</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 4	<u>NONE observed</u>	<u>0%</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 5	<u>NONE observed</u>	<u>0%</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 6	<u>NEEDS spot dusted</u>	<u>0%</u>	<u>JAB</u>	<input checked="" type="checkbox"/>		
NORTH NO. 7	<u>PKs &amp; charger ON</u>	<u>0%</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
NORTH NO. 8						
GLORY HOLE	<u>D. Box + Pump</u>	<u>0%</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
HG 22 #1	<u>needs dusted from head to tail</u>	<u>0%</u>	<u>BC</u>	<input checked="" type="checkbox"/>		
HG 23 #1	<u>NO POWER, NO PRESHIFT</u>					
HG 23 #2						
HG 23 #3						

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% Chy, 20, 8% O2, 0% CO  
PKs, Pumps, chargers, travelways ON at TOE.

Refuge chamber at 6 BRT & 89 BRT, & 8 belt on 2 section ON at TOE.

SIGNED BY: John R. Bickford 26176 Wilton [Signature] 13544  
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers  
COUNTERSIGNED BY: [Signature] 26001  
Mine Foreman Certificate No. Superintendent Certificate No.

46543-BJW Printing & Office Supplies  
[Signature] 1947-A [Signature] 5597



**ON-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 12-26-09 SHIFT: Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
LWall	1-man cleaning Belt	HL
NORTH 2		
NORTH 3		
NORTH 4	Ran Duster at Head	BC
NORTH 5	cleaned at flow thru	
NORTH 6	cleaned at flow thru + dustered tail to flow thru	BC SAB
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
longWall	Dusted Mother Drive + Belt Box	BC
SEllin	cleaned at tail + <del>flow</del> head	SAB
HG 22 #1	Shoveled tail	BC

*Checked*

SIGNED BY: John B. Bulford 26176  
Belt Examiners and Certificate Numbers  
W. H. ... 1354-A  
Belt Examiners and Certificate Numbers  
COUNTERSIGNED BY: [Signature] 26041  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 12-26-09 SHIFT: eve AM OR PM TO 8:30 AM OR PM TO 11:30 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: Brought out

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs Dusted	GLC	✓		
Ellis #5	water At 29BRK Drives need cleaned	GLC	✓		
Longwall	Needs Spot cleaned	GU	✓		
NORTH NO. 3					
NORTH NO. 4	None observed	GLC	✓		
NORTH NO. 5	None observed	GLC	✓		
NORTH NO. 6	Needs spot Dusted	GU			
NORTH NO. 7	P.C., Chargers OK	GU	✓		
NORTH NO. 8	<del>P.C., Chargers OK</del>	<del>GLC</del>	✓		
GLORY HOLE					
HG 22#1	Needs Dust Head to Tail	GU	✓		
HG 23#1	No Preshift No Power				
#2		GLC	✓		
#3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% CH4, 20.8% O2, 0PPM C.O., Detected  
Track, Travelways, P.C.'s, Chargers, Pumps, OK At Time  
of exam

SIGNED BY: [Signature] 1947-A  
Belt Examiners and Certificate Numbers  
[Signature] 1539A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 2604A  
Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 12-26-09 SHIFT: eve AM OR PM TO 8:30 AM OR PM TO 11:30 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No [checked] By Whom Time AM or PM

Report received by: Brought out Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2, Ellis #5 (Clean V-Plow), Ellis #4, and GLC.

Refuges At 6, 89, OK

SIGNED BY: [Signature] 1947-A
Belt Examiners and Certificate Numbers
COUNTERSIGNED BY: [Signature] 26001
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 12-27-09 SHIFT: owl AM OR PM TO 500 AM OR PM TO 600 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes      No      By Whom      Time      AM or PM

Report received by:     

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
24.5 #5	Head Needs cleaned, water A+ 29 BRK	GLC	✓		
24.5 #4	Tail Needs Add Cleaning	GLC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	None observed	GLC	✓		
NORTH NO. 5	None observed	GLC	✓		
NORTH NO. 6	needs spot Dusted	GU	✓		
NORTH NO. 7					
HWALL	needs more spot cleaning	FS	✓		
GLORY HOLE					
LBB NO. 1					
LBB NO. 2					
HG 22 #1	needs Dusted Hd-Tail	GU	✓		
HG 23 #1	FDIE No Power	GLC	✓		
#2					
#3					

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OB CIV CP CO 208802  
PC Chargers Travelways OK

SIGNED BY: Dan Allen 1554  
Belt Examiners and Certificate Numbers  
Sydney Cole 1947-A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 2602D  
Mine Foreman Certificate No.

Wad Lilly 28040  
Superintendent Certificate No.  
W.D. Campbell 1354-A

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 12-27-09 SHIFT: owl 6:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Brought out Time          AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<u>ellis #4</u>	<u>Cleaned on tail</u>	<u>GLC</u>

outby Refuges OK <sup>GLC</sup> 89,6BRK

SIGNED BY [Signature]  
Belt Examiners and Certificate Numbers  
[Signature]  
Belt Examiners and Certificate Numbers  
COUNTERSIGNED BY [Signature] 260411  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 12-27 SHIFT: Day AM OR PM TO 12 AM OR PM TO 3 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom B. McC, John B Time 2:35 AM or  PM

Report received by: Jay Stewart 39199  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ENIS 4	Tail need add cleaning	JAB	✓		
ENIS 5	Head needs cleaned, water at 29 BK	JAB	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	None Observed	JAB	✓		
NORTH NO. 5	None Observed	JAB	✓		
NORTH NO. 6	Needs Spot Dusted	JAB	✓		
NORTH NO. 7	PC's + Chargers	BC	✓		
L/WALL	needs spot cleaned + dusted	MW	✓		
GLORY HOLE	Power box + Pump	BC	✓		
LBB NO. 1					
LBB NO. 2					
HG 22 #1	Needs Dusted Head to tail, "Sprays aren't working"	BC	✓		
HG 23 1	} Idle No Power	BC	✓		
2		BC	✓		
3		BC	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 0% CO, 20.8% O2  
PC, Chargers, Travelways OK at exam  
outby Refuge's at #8 BK on #2 section, 89 BK OK at Exam  
Set Pump at LBB PC

SIGNED BY: Will Campbell 1354-A  
 Belt Examiners and Certificate Numbers  
John B. Burkhead 26176  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY E. Stager Mine Foreman 26041 Certificate No.  
 Superintendent \_\_\_\_\_ Certificate No. \_\_\_\_\_

Use Indelible Pencil or Ink

### ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 12-27 SHIFT: Day 6 AM OR PM TO 6 AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Bill C, John B Time 230 AM or  PM

Report received by: Jay Stewart 39199  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
<u>2/Wall</u>	<u>1-MAN Rockdusting</u>	<u>HL</u>
GLORY HOLE		
LBB NO. 1	<u>- Set Pump on track</u>	<u>BC/JS</u>
LBB NO. 2		

Outby Refuser 6, 89 OK at etam

SIGNED BY: W. D. ... 1354-A  
Belt Examiners and Certificate Numbers  
John B. Buckford 26176  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 260415  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 12-27-09 SHIFT: eve AM OR PM TO 8:30 AM OR PM TO 11:30 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Steve Campbell Time 11:10 AM or PM

Report received by: Jay Cole 1947-A  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
E1115 #4	<del>tail</del> Tail Needs cleaned	S.C.	✓		
E1115 #5	Tail Needs cleaned, water at 29BRK	S.C.	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs cleaned from Discharge to First overcast	S.C.	✓		
NORTH NO. 5	None observed				
NORTH NO. 6	None observed				
NORTH NO. 7	P.C.S chargers	S.C.	✓		
hangvill	Needs spot dust	HL	✓		
GLORY HOLE	Power Box, Pumps	S.C.	✓		
LBB NO. 1					
LBB NO. 2					
HG 23 #1	} No Power Belts Idle	S.C.	✓		
#2					
#3					
HG-22 #1	Needs Dusted Sprays NOT working	Rit	✓		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:  
0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0 PPM C.O. Detected  
Track, Travelways, Powercenters, Chargers, Pumps, D-Boxes, OK  
At time of exam

SIGNED BY: [Signature] [Signature]  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 26041  
 Mine Foreman Certificate No. Superintendent Certificate No.



ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 12-27-09 SHIFT: eve AM OR PM TO 6:30 AM OR PM TO 11:30 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Steve Campbell Time 11:10 AM or PM

Report received by: [Signature] 1247-A Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2.

Refuges At 6BRK, 89BRK, OK AT TIME OF EXAM

SIGNED BY: [Signature] 1247-A Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] Mine Foreman [Signature] 260011 Superintendent [Signature] Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 12-28-09 SHIFT: 3rd AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom S. Walker Time 5:30 AM or PM

Report received by: St Jk 3902  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1					
Fills #4	98-95 Neels, Dusted	S-W	✓		
Fills #5	Neels, All. dust = HEAD neels, cleaned	S-W	✓		
NORTH NO. 3					
NORTH NO. 4	None observed	S-W	✓		
NORTH NO. 5	None observed	S-C	✓		
NORTH NO. 6	None observed	S-C	✓		
NORTH NO. 7	FOLR P-c.'s, chargers ok	S-C	✓		
LONKWAH	Neels Spot cleaned, Dusted	L.B.	✓		
GLORY HOLE	FOLR P-c.'s, chargers ok	S-C	✓		
LBB NO. 1					
LBB NO. 2					
HG 22 #1					
HG 23 #1	} JOLE	S-C	✓		
HG 23 #2		S-C	✓		
HG 23 #3		S-C	✓		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OSCHY oppm co 2028 ok detected at time of exam  
Track, Travelway's, powerlines, P-Jones, leaves, chargers,  
visual check co monitors ok

SIGNED BY: St Jk 3902  
 Belt Examiners and Certificate Numbers  
David WMA 38928  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: Chager 26041  
 Mine Foreman Certificate No. Superintendent Certificate No.

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 12-26-07 SHIFT: 3rd AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

Table with columns: BELTS, ACTION TAKEN, INT. Rows include SOUTH 1, NORTH 1-8, GLORY HOLE, LBB NO. 1, LBB NO. 2.

Refuge chamber at 6th str #2 section ok

SIGNED BY: [Signature] 39046 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature] 26041 Mine Foreman Certificate No. Superintendent Certificate No.

Troy Malone 35359



Use Indelible Pencil or Ink

## ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE \_\_\_\_\_ SHIFT: \_\_\_\_\_ AM OR PM TO \_\_\_\_\_ AM OR PM \_\_\_\_\_ AM OR PM TO \_\_\_\_\_ AM OR PM

**ON-SHIFT EXAM.                      PRE-SHIFT EXAM.**

Was this report phoned to outside Yes \_\_\_ No \_\_\_ By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**SIGNED BY:** \_\_\_\_\_  
Belt Examiners and Certificate Numbers

\_\_\_\_\_

**COUNTERSIGNED BY** \_\_\_\_\_  
Mine Foreman                      Certificate No.                      Superintendent                      Certificate No.