

Started 8-20-09

Full 9-5-09

# PRESHIFT - ONSHIFT

## and

# DAILY REPORT

# Pumps

6-6 WM  
5-25-2010

Company Performance Coal

Mine U6B

SECTION Pumps

LOCATION Norma Releigh WV  
Post Office County State

Form 6-1489  
(March 1970)

Budget Bureau No. 42-R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014



Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 8-20 Section or Area Examined Pumps  
 Time of Examination: from 8:30 a.m. or (p.m.) to 11:00 a.m. or (p.m.)  
 Was this report phoned to outside: Yes no  
 By whom B. W. Bailey Time 11:05 P.M.  
 Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>EM 10<sup>13</sup> 14 30 19 04</u>	<u>none observed</u>	<u>None</u>
2. <u>32 seal 37</u>	<u>none observed</u>	<u>None</u>
3. <u>H. 6. 117 Sump</u>	<u>none observed</u>	<u>None</u>
4. <u>60 62 77 126</u>	<u>none observed</u>	<u>none</u>
5. <u>1 29</u>	<u>Down</u>	<u>Reported</u>
6. <u>LBB</u>	<u>none observed</u>	<u>none</u>
7. <u>N. Mains</u>	<u>none observed</u>	<u>none</u>
8. <u>1 Sec .9%</u>	<u>none observed</u>	<u>none</u>
9. <u>2 Sec</u>	<u>none observed</u>	<u>none</u>
10. <u>3 Sec</u>	<u>none observed</u>	<u>none</u>

Air Measurements

Location	CFM	Location	CFM
<u>Good air movement</u>			

Remarks: Walkways, Travelways, Trays, power center all clear at last exam

M. L. Bailey 27085

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By B. W. Bailey Preshift-Mine Examiner Certificate No. 37074  
 Countersigned Kenney Thompson Mine Manager—Mine Foreman Assistant-Foreman Certificate No. 1689A  
 \_\_\_\_\_ Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 4-21-09 20 Section or Area Examined Pumps  
 Time of Examination: from 900 a.m. or p.m. to 1200 a.m. or p.m.  
 Was this report phoned to outside: Yes no Time          A.M.          P.M.  
 By whom           
 Report received by          (Signed)

Location	Violations and other Hazardous Conditions Observed and Reported	Action Taken
1. <sup>HT</sup> EM 110's (3, 14, 30, 19)	none observed	None
2. 32 seal 37	none observed	"
3. HG 117 sump	none observed	"
4. 60, 62, 77, 124	none observed	"
5. 129	Down	⊙
6. LBB	none observed	"
7. N. Mains	none observed	"
8. 1 sect 5 to 7	none observed	"
9. 2 sect	none observed	"
10. 3 sect (A8)	none observed	"

Air Measurements

Location	CFM	Location	CFM
Good Air mount			

Remarks: walk ways, trackways, track power centers all clear at time of exam  
 LBB, Pumps + Boxes clear outside to Ellis + M.K.

J.N., J.B., R.G., D.J., S.H. Harley Jayou 37002

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By J. B. Brown 32261 Certificate No. 32000  
 Preshift Mine Examiner  
 Countersigned          Certificate No. 33017  
 Mine Manager - Mine Foreman  
         Assistant Foreman  
         Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-21 2009 Section or Area Examined Pumps
Time of Examination: from 11:30 a.m. or p.m. to 2:30 a.m. or p.m.
Was this report returned to outside: Yes [checked] no
By whom Russell GUNAWDE Time A.M. 3:05 P.M.
Report received by Mike Ferrell (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: HT, Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include JB 1 EAST MAINS 110's, HT 2 #32 Seal, HT 3 126, 77, HG 17 Sump, 6M 4 LBB 3, 15, RG 5 North MAINS Pumps, 6 1 Sec Pumps, 7 2 Sec Pumps, 8 3 Sec Pumps (8)%, 9 129 BK Pump.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: GOOD AIR MOVEMENT

Remarks: 0% CH4 0% CO 20.8% O2
TRAVELWAYS, POWER BOXES, D. BOXES FOR PUMPS OK AT TOE

Handwritten signature/initials

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By: Charley Taylor (Preshift-Mine Examiner), Certificate No. 37002
Countersigned: Mike Bailey (Assistant Foreman), Certificate No. 27085
Assistant Foreman: Russell Gunawde (Certificate No. 32261), Johny Neely (Certificate No. 1536-A, 33472)
Supintendent or Assistant: [Signature]



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Date of Examination 8-24 Section or Area Examined Pump  
 Time of Examination: from 5:30 a.m. or p.m. to 11:00 a.m. or p.m.  
 Was this report phoned to outside? Yes  No   
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_  
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. East Main 110 <sup>5</sup> 13, 14, 19, 30 CH <sub>4</sub> 0%	none observed	none
2. 32 Seal 37, 60, 62	↑ ↑	↑
3. 126, 77, 4617		
4. LBB 3, 15	↓ ↓	↓
5. North Main pump		
6. 1 Sec pump 45%	none observed	none
7. 2 Sec pump		
8. 3 Sec pump		
9. 128 BK	Down	Reported
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Coal in movement	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub> 0% CO 0<sup>2</sup> 20.8%  
 Translump Power by P Boyer pump at time of exam

File Bailey 27085

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Gene Smith 37074 Kenny Thompson 1689A  
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.  
 Countersigned [Signature] 37074  
 Mine Manager—Mine Foreman Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-22-44 Section or Area Examined Pump  
 Time of Examination: from 3:00 a.m. or 6:00 p.m. to 5:30 a.m. or 9:30 p.m.  
 Was this report phoned to outside: Yes no  
 By whom Bruce Burt Time 5:40 (A.M.) 5:40 P.M.  
 Report received by Bruce Burt (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. East Main - 110° 13, 14, 19, 30	none observed	none
2. 32 Seal 37 60, 62	none observed	none
3. 126 77 60, 62	none observed	none
4. LBB 3, 15	none observed	none
5. North Main	NONE observed	NONE
6. 1 Sec <u>45%</u>	none observed	none
7. 2 Sec	none observed	none
8. 3 Sec	NONE observed	NONE
9. 125 RK	DOWN	Reported
10.		

Air Measurements

Location	CFM	Location	CFM
<u>Good air movement</u>			

Remarks: O<sub>2</sub> CH<sub>4</sub> O<sub>2</sub> CO O<sub>2</sub> 20.8%  
Tramway, Power House, P. Boxes OK at transfer  
Bruce Burt 37074 Mike Bailey 27085

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kenneth Thompson 1689A  
 Preshift-Mine Examiner Certificate No.  
 Countersigned John Cook 37074  
 Mine Manager—Mine Foreman Assistant Foreman Certificate No.

John Deery 3224 Russell Linn 1636A Superintendent or Assistant Johnny Deery 33472

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-22 2009 Section or Area Examined Pumps
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Mike Bailey Time A.M. 11:00 P.M.
Report received by Bruce Bennett (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CFM, Violation or Hazardous Condition, Action Taken. Contains 10 rows of inspection data.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good air movement'.

Remarks: O2 20.4% O2 20.0% O2 20.8% O2

Truckings, Powerboxes, DP, etc. changed all clear at time of exam

Mike Bailey 27085

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Bruce Bennett Preshift-Mine Examiner Certificate No. 37074
Countersigned Mike Bailey Mine Manager - Mine Foreman Certificate No. 1089A
Assistant Foreman
Superintendent or Assistant



Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported  
Violation or Hazardous Condition

Location

Action taken

- 1. \_\_\_\_\_
- 2. \_\_\_\_\_
- 3. \_\_\_\_\_
- 4. \_\_\_\_\_
- 5. \_\_\_\_\_
- 6. \_\_\_\_\_
- 7. \_\_\_\_\_
- 8. \_\_\_\_\_

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 8-23 Section or Area Examined Pumps  
 Time of Examination: from 3:00 a.m. or p.m. to 5:00 a.m. or 5:00 p.m.  
 Was this report phoned to outside: Yes  no  Time          A.M.          P.M.  
 By whom           
 Report received by          (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>E-M 110 13, 14, 19, 30</u>	<u>none observed</u>	<u>None</u>
2. <u>325 ad 37, 175 ad</u>	<u>none observed</u>	<u>None</u>
3. <u>60, 67, 77, 126</u>	<u>none observed</u>	<u>NONE</u>
4. <u>129</u>	<u>DOWN</u>	<u>Reports</u>
5. <u>LRB 3, 15</u>	<u>none observed</u>	<u>None</u>
6. <u>N Mains</u>	<u>none observed</u>	<u>None</u>
7. <u>1 Section 885</u>	<u>none observed</u>	<u>None</u>
8. <u>2 Section</u>	<u>none observed</u>	<u>None</u>
9. <u>3 Section</u>	<u>none observed</u>	<u>None</u>
10. <u>N Mains</u>	<u>none observed</u>	<u>NONE</u>

#### Air Measurements

Location	CFM	Location	CFM
<u>Good air movement</u>			

Remarks: 0% CH<sub>4</sub> 0% CO 0.2208%

Traffic, Power, Pumps, P. B. B. C. C. C.

White Bailey 27085

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 37074  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 350000  
 Assistant Foreman Certificate No. 1689A

Superintendent or Assistant John A. Neely Certificate No. 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 8-23-09 20. Section or Area Examined Pumps  
 Time of Examination: from \_\_\_\_\_ a.m. or \_\_\_\_\_ p.m. to 2:30 a.m. or p.m.  
 Was this report phoned to outside: Yes \_\_\_\_\_ no \_\_\_\_\_  
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_ (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. Em's 110's, #13, 14, 19, 30	0%	NONE OBSERVED	NONE
2. #32 Seal, #37, 60, 62	0%	" "	"
3. #77, 126	0%	" "	"
4. #129		DOWN	
5. LBB	0%	NONE OBSERVED	NONE
6. N. Main	0%	NONE OBSERVED	NONE
7. 1 Section			
8. 2 Section	0%	NONE OBSERVED	NONE
9. 3 Section	0%	NONE OBSERVED	NONE
10.			

#### Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO Detected at time of EXAM  
Power Centers, D-Boxes, TRACK & TRAVELWAYS Clear time of EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Habstead 37567 Certificate No. 3672  
 Freshift-Mine Examiner Assistant Foreman  
 Countersigned [Signature] Mine Manager--Mine Foreman Certificate No. 1689A  
 Assistant Foreman

George Curry 27429 Superintendent or Assistant Johnny Neely 33472

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-23-9 Section or Area Examined Pumps
Time of Examination: from 830 a.m. or 6 p.m. to 1100 a.m. or 6 p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Table with 3 columns: Location, Violations and other Hazardous Conditions Observed and Reported, Action Taken. Includes handwritten entries for EMs, seals, LBB, N. Mains, and sections.

Table for Air Measurements with columns for Location, CFM, Location, CFM. Includes handwritten entry 'Good Air Movement'.

Remarks: 0% ch4, 20.8% O2, 0ppm CO, Detected at time of ex same power centers, D Boxes, TRACK & TRavelways clear time of ex same

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Kenny Thompson 1689A
Countersigned George Curry 27479
Assistant Foreman
Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 8-24- 2069 Section or Area Examined Pumps  
Time of Examination: from 3:30 a.m. or p.m. to 6:00 a.m. or p.m.  
Was this report phoned to outside: Yes \_\_\_\_\_ no \_\_\_\_\_  
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>EMs 110's #13, 14, 19, 30</u>	<u>NONE observed</u>	<u>NONE</u>
2. <u>#32 seal, #37, 60, 62</u>	<u>NONE observed</u>	<u>NONE</u>
3. <u>#77, 126</u>	<u>NONE observed</u>	<u>NONE</u>
4. <u>#129</u>	<u>DOWN</u>	<u>Reported</u>
5. <u>LBB</u>	<u>NONE observed</u>	<u>NONE</u>
6. <u>N. Mains</u>	<u>NONE observed</u>	<u>NONE</u>
7. <u>1 section</u>	<u>NONE observed</u>	<u>NONE</u>
8. <u>2 section</u>	<u>NONE observed</u>	<u>NONE</u>
9. <u>3 section</u>	<u>NONE observed</u>	<u>NONE</u>
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH<sub>4</sub>, 0 ppm CO, 20.8% O<sub>2</sub>. Detected time of exsme  
power Boxes, D-Boxes, TRACK & TRAVELWAYS CLEAR at  
time of exsme

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.  
Signed By Kenneth Thompson 1689A Certificate No. \_\_\_\_\_ Assistant Foreman  
Countersigned [Signature] Mine Manager—Mine Foreman  
[Signature] Assistant Foreman Certificate No. 27479

[Signature] 3226 / Russell Dummer 1536-A Johnny Neely 33472



Use Indelible  
Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-24 2009 Section or Area Examined Pumps
Time of Examination: from 11:30 a.m. to 2:30 p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include locations like Em 110s, #32 seal, #37, #17 sump, #60, #62, #77, #126, LBB, N. MAINS, 1 Section, 2 Section, 3 Section.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air movement.

Remarks: 0% CH4, 20.8% O2, 0ppm CO Detected at time of exam
Track, travelways, Power Boxes, D-Boxes clear at time of exam

Signed By Russell Burnoe 1536-A Certificate No.
Countersigned Kenny Thompson 1689A Assistant Foreman
Scott Halstead 32261 Assistant Foreman
John Kelly 33472

George Curry 27129 John Q. Burkhead 21174 Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT**  
**MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

	<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

*Examinations for Methane in Working Places*

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	11.	_____	_____	_____
2.	_____	_____	_____	12.	_____	_____	_____
3.	_____	_____	_____	13.	_____	_____	_____
4.	_____	_____	_____	14.	_____	_____	_____
5.	_____	_____	_____	15.	_____	_____	_____
6.	_____	_____	_____	16.	_____	_____	_____
7.	_____	_____	_____	17.	_____	_____	_____
8.	_____	_____	_____	18.	_____	_____	_____
9.	_____	_____	_____	19.	_____	_____	_____
10.	_____	_____	_____	20.	_____	_____	_____

*Examinations for Methane in Return Aircourses*

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	6.	_____	_____	_____
2.	_____	_____	_____	7.	_____	_____	_____
3.	_____	_____	_____	8.	_____	_____	_____
4.	_____	_____	_____	9.	_____	_____	_____
5.	_____	_____	_____	10.	_____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pen or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 8-24-09 Section or Area Examined Pumps  
 Time of Examination: from 8:30 a.m. or 6:00 to 1:30 a.m. or 6:00  
 Was this report phoned to outside: Yes  no   
 By whom G. Curry Time A.M. 11:00 P.M.  
 Report received by John A. Beckford  
 (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Exc 110's, 13, 14, 19, 30</u>	<u>0% ch4 None Observed</u>	<u>None</u>
2. <u>325 cal, 37,</u>	<u>0% " "</u>	<u>" "</u>
3. <u>HG 17, 60, 62, 126</u>	<u>0% None Observed</u>	<u>None</u>
4. <u>129</u>	<u>Down</u>	
5. <u>LBB</u>	<u>0% None Observed</u>	<u>None</u>
6. <u>WT. Mains</u>	<u>0% " "</u>	<u>" "</u>
7. <u>1 Sect</u>	<u>0% " "</u>	<u>" "</u>
8. <u>2 Sect</u>	<u>0% " "</u>	<u>" "</u>
9. <u>3 Sect</u>	<u>0% None Observed</u>	<u>None</u>
10.		

### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			

Remarks: 0% ch4, 0% CO + 20.8% O2 detected at time of exam

Tracks, travelways, Power Centers, chgns, D's - B's clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Beckford 26176 Curtis 15947  
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.  
 Countersigned John A. Beckford 3904001 Tommy Thompson 1689A  
 Mine Manager - Mine Foreman Assistant Foreman  
George Curry 27429  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Date of Examination: 8/25/09 Section or Area Examined: Pumps  
 Time of Examination: from 3:00 or p.m. to 6:00 or p.m.  
 Was this report phoned to outside? Yes  no   
 By whom: K. Thompson Time: 5:47 A.M. P.M.  
 Report received by: Jim Keyser 32261 (Signed)

Violations and other Hazardous Conditions Observed and Reported

KT	Location	Violation or Hazardous Condition	Action Taken
1.	EM's 110's #13, 30, 19, 14	0% None observed	None
2.	32 + 37 seals	0% none obs.	none
3.	HG 17 Sump SAB	0% none obs.	none
4.	60, 62, 55, 126	0% none obs.	none
5.	129	Down	Reported
6.	LBB SAB	0% none obs.	none
7.	N. Mains SAB	0% none obs.	none
8.	1 sec. 6C	0% None observed	"
9.	2 sec. 6C	0% " "	"
10.	3 sec. #8	0% " "	"

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: CH<sub>4</sub> 0%, 20.8% O<sub>2</sub>, CO - 0ppm  
Track, Travelways, Power centers, chargers, D-Boxes clear at  
Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By: Robert A. Bickford 21176 Coal Mine Examiner  
 Countersigned: Mike Bailey 27085 Mine Manager - Mine Foreman Assistant Foreman  
George Curry 15441 Assistant Foreman Certificate No. 27429  
Kennedy Thompson 1689A  
Jim Keyser 32261 Superintendent or Assistant  
Russell Dummoe 1536-A 37074

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_





Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-25-09 Section or Area Examined Pumps
Time of Examination: from 8:30 a.m. or 11:30 a.m. or 4:00 p.m.
Was this report phoned to outside: Yes no
By whom G. Curry Time A.M. 11:01 P.M.
Report received by John A. Bickford (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, Chy, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'Em's 110's', 'LBB 3.15', and 'NT. Mains'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: 0% ch4, 0% CO + 20.8% O2 detected at time of exam
Tracks, travelways, Power Centers, chargers + P' Boxes clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By John A. Bickford 26176 Harry Thompson 16894
Countersigned [Signature] Mine Manager - Mine Foreman Assistant Foreman George Curry 2 27429
Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination: 8-26-01 20 Section or Area Examined: Pump's
Time of Examination: from 3:00 p.m. to 6:00 p.m.
Was this report phoned to outside: Yes no
By whom: Time: A.M. P.M.
Report received by: (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CHM, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'Em's 10s 13, 14, 19, 30' and '32 seal 37 HG 17 60'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry: 'Good Air Movement'.

Remarks: 0% CH4, 0% CO2, 20.6% O2 detected at time of exam. Track, Travelways, powerlines, D-boxes, choppers clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By: [Signature] Preshift Mine Examiner
Countersigned: [Signature] Mine Manager-Mine Foreman
Assistant Foreman: [Signature]
Certificate No.: 39042, 26176, 27429
Assistant Foreman: [Signature]
Superintendent or Assistant: [Signature]

Handwritten notes at bottom: [Signature] 3226/Russell Dunbar 1535-A, [Signature] 27085

Use Indelible  
Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-26 Section or Area Examined Pump
Time of Examination: from 11:30 a.m. to 12:24 a.m. or p.m.
Was this report phoned to outside: Yes no X
By whom Brochu, Duester, Mike Bailey, L.V.
Report received by Dunstun (Signed) Time A.M. 235 P.M.

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 entries for various locations like EM's 110's, 3252, 62, 126, 129, LBB 3, 15, North Main, #1 Section, #2 Sec, #3 Section.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good air Movement'.

Remarks: O2 CH4, O2 CO, O2 20.8% all seen at Haulage area. Track, haulage, pavement, D. Boxer charges seen at haulage area.

Mike Bailey 27085

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Bruce Duester Preshift Mine Examiner
Countersigned Scott Halstead Mine Manager-Mine Foreman
Certificate No. 3704, 3222
Assistant Foreman Russell Gammie, Kerrey, Jim Gray
Certificate No. 1536-A, 37567, 32261

George Curry 27419 John A. Buckford 26176 Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

	<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

*Examinations for Methane in Working Places*

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	11.	_____	_____	_____
2.	_____	_____	_____	12.	_____	_____	_____
3.	_____	_____	_____	13.	_____	_____	_____
4.	_____	_____	_____	14.	_____	_____	_____
5.	_____	_____	_____	15.	_____	_____	_____
6.	_____	_____	_____	16.	_____	_____	_____
7.	_____	_____	_____	17.	_____	_____	_____
8.	_____	_____	_____	18.	_____	_____	_____
9.	_____	_____	_____	19.	_____	_____	_____
10.	_____	_____	_____	20.	_____	_____	_____

*Examinations for Methane in Return Aircourses*

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	6.	_____	_____	_____
2.	_____	_____	_____	7.	_____	_____	_____
3.	_____	_____	_____	8.	_____	_____	_____
4.	_____	_____	_____	9.	_____	_____	_____
5.	_____	_____	_____	10.	_____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Use Indelible  
Pen or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 8-26-09 Section or Area Examined Pumps  
 Time of Examination: from 1:30 a.m. or 1:30 p.m. or 0  
 Was this report phoned to outside? Yes no  
 By whom John A. Bickford Time 10:55 P.M.  
 Report received by John A. Bickford (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Em's 110's, 13, 14, 19, 30</u>	<u>CHY NONE observed</u>	<u>NONE</u>
2. <u>32 Seal, 37, 116, 17, 60</u>	<u>0% None Observed</u>	<u>None</u>
3. <u>62, 126</u>	<u>0% None Observed</u>	<u>None</u>
4. <u>129</u>	<u>Down</u>	
5. <u>LBB</u>	<u>0% None Observed</u>	<u>None</u>
6. <u>North Mains</u>	<u>0% None Observed</u>	<u>None</u>
7. <u>#1 Section</u>	<u>0% None</u>	<u>None</u>
8. <u>2 Section</u>	<u>0% None Observed</u>	<u>None</u>
9. <u>3 Section</u>	<u>0% NONE observed</u>	<u>NONE</u>
10. _____		

Air Measurements

Location	CFM	Location	CFM
<u>Load Air Movement</u>			
_____			
_____			
_____			
_____			
_____			
_____			
_____			
_____			
_____			

Remarks: 0% ch, 0% CO + 20.8% O<sub>2</sub> detected at time of exam  
Tracks, travelways, Power Centers & D. Box's clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford 26176 John J. Kelly  
 Preshift-Mine Examiner Certificate No. Assistant Foreman  
 Countersigned George Curry Mine Manager—Mine Foreman George Curry 27429  
 Assistant Foreman Superintendent or Assistant



Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 8-27-09 20... Section or Area Examined Pumps  
Time of Examination: from 3:30 a.m. or p.m. to 6:00 a.m. or p.m.  
Was this report phoned to outside: Yes..... no.....  
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Emis Nos 13, 14, 17, 30</u>	<u>CH<sub>4</sub> NONE observed</u>	<u>NONE</u>
2. <u>32 seal, 37, Hg17, 60</u>	<u>0% None observed</u>	<u>None</u>
3. <u>62, 126</u>	<u>0% None observed</u>	<u>None</u>
4. <u>129</u>	<u>Down</u>	
5. <u>LSD</u>	<u>0% None observed</u>	<u>None</u>
6. <u>North Mains</u>	<u>0% None observed</u>	<u>None</u>
7. <u>#1 Section</u>	<u>"NONE observed"</u>	<u>None</u>
8. <u>#2 Section</u>	<u>"NONE observed"</u>	<u>"NONE"</u>
9. <u>#3 Section</u>	<u>NONE observed</u>	<u>NONE</u>
10. _____	<u>N</u>	

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Mains</u>			
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	

Remarks: 02 30% 0% CH<sub>4</sub> 0% CO detected at time of exam  
Track, Traveling, power centers, D-DOKES, KVAs

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John H. Buchford 26171 St. J. J.  
Freshift-Mine Examiner Certificate No. Assistant Foreman  
Countersigned Bob Cook 33000 James Curry  
Mine Manager—Mine Foreman Superintendent or Assistant  
Mike Bailey 22085  
Jim Boyer 32261 Russell Gunnoe 1536A

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-22 2009 Section or Area Examined Pumps  
Time of Examination: from 6:00 a.m. or p.m. to 3:00 a.m. or p.m.  
Was this report phoned to outside: Yes no  
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
JB 1. EM's 110's 13, 14, 17, 30 CH <sub>4</sub> D%	None observed	None
HT 32 Seal, 37 H617, 60, 77 D%	NONE OBSERVED	NONE
3. 62, 126 BB	none observed	none
4. 129	DOWN	Reported
5. LBB BB	none observed	none
6. AG Noodle Mains	none observed	none
7. #1 Section .95	" "	Reported
8. #2 Section	" "	"
9. JB #3 Section D% CH <sub>4</sub>	None observed	None
10.		

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH<sub>4</sub> 0% CO 20.8% O<sub>2</sub>  
Trucks, Truvelway, power entry, D-Boxes, KVA'S

Signed By: Jim Bowyer (Preshift-Mine Examiner, Certificate No. 32261), Harley Taylor (Assistant Foreman, Certificate No. 37002)  
Countersigned: \_\_\_\_\_ (Mine Manager—Mine Foreman, Certificate No. 15364)  
Assistant Foreman  
Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

	Location	Violations and other Hazardous Conditions Observed and Reported	Action taken
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

**Examinations for Methane in Working Places**

Location	Time	Methane Content	Location	Time	Methane Content
1.	_____	_____	11.	_____	_____
2.	_____	_____	12.	_____	_____
3.	_____	_____	13.	_____	_____
4.	_____	_____	14.	_____	_____
5.	_____	_____	15.	_____	_____
6.	_____	_____	16.	_____	_____
7.	_____	_____	17.	_____	_____
8.	_____	_____	18.	_____	_____
9.	_____	_____	19.	_____	_____
10.	_____	_____	20.	_____	_____

**Examinations for Methane in Return Aircourses**

Location	Time	Methane Content	Location	Time	Methane Content
1.	_____	_____	6.	_____	_____
2.	_____	_____	7.	_____	_____
3.	_____	_____	8.	_____	_____
4.	_____	_____	9.	_____	_____
5.	_____	_____	10.	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_



Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-28-09 20 Section or Area Examined Pumps
Time of Examination: from 3:37 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'Em 110s', '3d Seal', 'L.S.G.', and 'North main's' with corresponding observations and actions.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: OK CH4, OK CO, 20.8% O2 detected at the of ERM
Track, Travelways, passageway, D. zones, chargers OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift-Mine Examiner
Countersigned [Signature] Mine Manager-Mine Foreman
Assistant Foreman [Signature]
Certificate No. 32261
Assistant Foreman [Signature]
Certificate No. 17517A
Superintendent or Assistant [Signature]
Certificate No. 33472

32261 Russell Gummoe 1536-A Bureau Form 3704



Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_



Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 8-28 2009 Section or Area Examined Pumps  
 Time of Examination: from 8:30 a.m. or 6:00 to 11:30 a.m. or 6:00  
 Was this report phoned to outside: Yes \_\_\_\_\_ no ✓  
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_  
 (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>EMIS 110's, 13, 14, 17, 30</u> <u>CH4</u> <u>0%</u>	<u>None observed</u>	<u>None</u>
2. <u>32 Seal, 37 HG 17, 60, 77</u> <u>0%</u>	<u>" "</u>	<u>"</u>
3. <u>JN 62, 126</u> <u>0%</u>	<u>" "</u>	<u>"</u>
4. <u>129</u> <u>0%</u>	<u>Down</u>	<u>Reported</u>
5. <u>JN LBB</u> <u>0%</u>	<u>None observed</u>	<u>None</u>
6. <u>North Main</u> <u>0%</u>	<u>" "</u>	<u>"</u>
7. <u>#1 Section</u> <u>.10</u>	<u>None observed</u>	<u>None</u>
8. <u>#2 Section</u> <u>0%</u>	<u>None observed</u>	<u>"</u>
9. <u>#3 Section</u> <u>0%</u>	<u>None observed</u>	<u>None</u>
10. _____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH4 0% CO 20.8 O2 clear at time of Exam.  
Track, travelways, powercenter D.Boxes clear at time of Exam.  
Pump down & S BOK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely 33472 Richard Rann 1357-A  
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.  
 Countersigned [Signature] 3300000 [Signature] 15390  
 Mine Manager—Mine Foreman Assistant Foreman  
 \_\_\_\_\_  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-29-09 20 Section or Area Examined Pumps
Time of Examination: from 3:00 a.m. or 9 to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom J Neely, J Byrdell, Glen Time 5:20 P.M.
Report received by Jim Boyer 32261 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Contains 10 rows of inspection data including locations like EM 10's, 32 Seal, NB 17 ramp, etc.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten note 'Good air movement'.

Remarks: 0% CH4 0% CO 20.8% O2 detected track, travel ways, rooms. Areas safe at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 33472 Certificate No.
Countersigned [Signature] 35000 Certificate No.
Assistant Foreman [Signature] 1539A

Jim Boyer 32261 John Byrdell 25176 Superintendent or Assistant George Curry 27429

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-29-09 Section or Area Examined Pumps
Time of Examination from 4:00 a.m. or p.m. to 4:00 a.m. or p.m.
Was this report phoned to outside? Yes [X] no
By whom John Bickford Time A.M. 2:25 P.M.
Report received by Harley Taylor 37002 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include HT1 37, #32 Seal, HG 17 Sump 0% CH4, HT2 60, 77, HT3 LBB Pumps 3, 4, 15, JB East Mains 110's 0%, JB 13, 14, 19, 30, 126, 62, North Mains Pumps, #1 Section Pumps, 129 BK Pump, JB #3 section (8, 18) 0%.

Location CFM Location CFM
GOOD AIR MOVEMENT

Remarks: 0% CH4 0% CO 20.8% O2
TRAVELWAYS, D-BOXES & POWER BOXES FOR PUMPS OK AT T&E

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By Harley Taylor 37002 Certificate No.
Countersigned John Bickford Mine Manager - Mine Foreman Assistant Foreman
Superintendent or Assistant Johnnie Neely 33472



Use Indelible  
Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action taken
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

Examinations for Methane in Working Places

	Location	Time	Methane Content		Location	Time	Methane Content
1.	_____	_____	_____	11.	_____	_____	_____
2.	_____	_____	_____	12.	_____	_____	_____
3.	_____	_____	_____	13.	_____	_____	_____
4.	_____	_____	_____	14.	_____	_____	_____
5.	_____	_____	_____	15.	_____	_____	_____
6.	_____	_____	_____	16.	_____	_____	_____
7.	_____	_____	_____	17.	_____	_____	_____
8.	_____	_____	_____	18.	_____	_____	_____
9.	_____	_____	_____	19.	_____	_____	_____
10.	_____	_____	_____	20.	_____	_____	_____

Examinations for Methane in Return Aircourses

	Location	Time	Methane Content		Location	Time	Methane Content
1.	_____	_____	_____	6.	_____	_____	_____
2.	_____	_____	_____	7.	_____	_____	_____
3.	_____	_____	_____	8.	_____	_____	_____
4.	_____	_____	_____	9.	_____	_____	_____
5.	_____	_____	_____	10.	_____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 8-29-09 20. Section or Area Examined Pumps  
 Time of Examination: from 8:00 a.m. or 5:00 p.m. to 5:00 a.m. or 8:00 p.m.  
 Was this report phoned to outside: Yes  no   
 By whom Wally Time 12:05 A.M. P.M.  
 Report received by Gene Ullman  
 (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Em 31109 37 <u>0%</u>	<u>non-observed</u>	<u>none</u>
2. <u>32 seal HG 175ump</u>	/	/
3. <u>60, 77</u>		
4. <u>UBB Pump</u> <u>0%</u>		
5. <u>EMTS 13, 14, 19, 30</u>		
6. <u>126, 62</u>		
7. <u>NM</u>		
8. <u>1 section pump</u>		
9.		
10.		

#### Air Measurements

Location	CFM	Location	CFM
<u>660 Airmanent</u>			

Remarks: 0204 0200 20.8202  
Pumps Boxes travelways clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Gene Ullman Certificate No. 15397  
 Preshift-Mine Examiner Assistant Foreman  
 Countersigned Wally Certificate No. 32000  
 Mine Manager—Mine Foreman

Assistant Foreman

John J. Neely 33472

Superintendent or Assistant

Use Indelible  
Pen or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman/Mine Manager

Date

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-30-09 20 Section or Area Examined Pump  
Time of Examination: from a.m. or p.m. to a.m. or p.m.  
Was this report phoned to outside: Yes no  
By whom Time A.M. P.M.  
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. EM 1103	CH4 none	none
2. 13, 14, 19, 20, 32 sec	No Power on Pumps	none
3. HG 17, 57, 60, 62		
4. 77, 126, 129, 4B13		
5. Pump		
6. 1 section		
7.		
8.		
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
Good			

Remarks: 23 chf 0310 2018802  
pumps & Boss Tank was clean

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely - 33472 Preshift-Mine Examiner Certificate No.  
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 1479-A  
Assistant Foreman [Signature] 15298

John D. Beckford 2617A Superintendent or Assistant George Curry 27429

Use Indelible  
Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 8-30-09 20 Section or Area Examined Pumps  
Time of Examination: from 7:00 a.m. or 4:00 p.m.  
Was this report phoned to outside: Yes  no   
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. Em's 110 <sup>s</sup> , 13, 14, 19, 30	0%	NONE OBSERVED	NONE
2. #32 seal, #37, HG17	0%	" "	"
3. #60, #62, #77, #126	0%	" "	"
4. #129		DOWN	
5. LBB	0%	NONE OBSERVED	NONE
6. 1 Section		Power off	
7. 2 Section		Power off	
8. N. Mains			
9. _____			
10. _____			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	
_____		_____	

Remarks: 0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0 ppm CO detected at EXAM time  
Power centers, D-Boxes, TRACK & TRAVELWAYS Clear at time of EXAM

St. John 39042

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead Certificate No. 37567 Assistant Foreman George Perry Certificate No. 1122-A  
 Countersigned Charles Cook Mine Manager - Mine Foreman Assistant Foreman John A. Buehler Certificate No. 27429  
 Superintendent or Assistant John A. Buehler Certificate No. 25171  
 Superintendent or Assistant John A. Buehler Certificate No. 33472

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman/Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-30 20. 09 Section or Area Examined Pumps
Time of Examination: from 7:50 a.m. or 10:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 rows of handwritten entries such as 'EM's 110's 13, 14, 19, 30' and 'None observed'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: 0% CH4 0% CO 20.8 O2 Detected at Time of Exam. Power Centers, D. Boxes, Tracks, Travelways, Clear at Time of Exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely 33472 Certificate No. Assistant Foreman 39042 Certificate No.
Countersigned [Signature] Mine Manager-Mine Foreman

Assistant Foreman Rick Hutchins 37569 Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 8-31-07 20\_\_\_\_ Section or Area Examined Pumps  
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.  
Was this report phoned to outside: Yes \_\_\_\_\_ no \_\_\_\_\_  
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Em 1105 13, 14, 19, 30	NO Power At time of Exam	
2. 32 Seal, 37, HG-17	[Large vertical bracket spanning rows 2-11]	
3. 60, 62, 72, 126		
4. 129		
5. L.O.B.		
6. #1 Section		
7. #2 Section		
8. N mains		
9. 3- section		
10.		

Air Measurements

Location	CFM	Location	CFM

Remarks: Ch<sup>4</sup> 0.09% CO 0.9% O<sub>2</sub> 20.8% at time of exam.

Russell Dunbar 1536-A  
 This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Steve John 39042 Assistant Foreman  
 Countersigned John Loh 33066 Certificate No.  
 Assistant Foreman

George Curry 27429 John A. Bickford 26176 Superintendent or Assistant  
Tom Dwyer 32261

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-31-49 Section or Area Examined Pump
Time of Examination: from 100 a.m. or (p.m.) to 400 a.m. or (p.m.)
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'EMs, 1103, 13, 14, 19, 30' and '32 seal, 37, HG17'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Local Air Movement'.

Remarks: 0% CH4 - 0% CO - 20.8% O2
travelways, track, pass, chargers clear at time of exam

Signed By George Curry 27429 Shift-Mine Examiner
Countersigned Mike Bailey 27085 Assistant Foreman
Russell Sumner 1536A Assistant Foreman
John Bullard 26126 Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-31-09 Section or Area Examined Pumps
Time of Examination: from 8:30 a.m. or 11:30 a.m. or 6 p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'Em 110', '22 Seal', '60, 62, 77, 126', '129', 'h B B', '21 Section', '22 Section', 'N. Mains'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: ON CH4, ON CO, 20-80 O2 detected at time of em track, travelling, powder's, D. boxes OK at time of em

Signed By Steve Gales Fresh M. Mine Examiner Certificate No. 31042
Countersigned Mike Cook Mine Manager - Mine Foreman
Assistant Foreman
Superintendent or Assistant

Use Indelible  
Pen or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift 19 Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 9-1-09 20 Section or Area Examined Pumps
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Dwyer M Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Includes entries for Em 110's, 32 Seal, 60, 62, 77, 126, 129, L.B.D., #1 Section, #2 Section, N. Main's, #3 Section.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air movement.

Remarks: OK CH4, OK CO2, 20.8% O2 detected at time of exam. Track, Travelways, Powercables, D-Boxes, Changers OK at time of exam.

Mike Bailey 27085

[Signature]

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 35012
Countersigned [Signature] Mine Manager-Mine Foreman
Assistant Foreman [Signature] Certificate No. 15397A

Superintendent or Assistant: [Signature] 32261, [Signature] 27429, [Signature] 1536-A



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 9-1-09 20 Section or Area Examined Pumps
Time of Examination: from 6:00 a.m. or 2:00 p.m.
Was this report phoned to outside: Yes no
By whom Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, Violation or Hazardous Condition, Action Taken. Includes entries for Em 110's, #14, 19, #32 seal, #37, #HG 17 pump, #60, 62, 77, 126, #129, LBB, N Main, #1 Section, #2 Section, #3 Section #18, 8.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Cool air movement.

Remarks: O% CH4 D% CO 20.8% O2 detected track, tunnelways remain down safe at eye

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift Mine Examiner Certificate No. 32241
Scott Halstead Assistant Foreman Certificate No. 37567
Countersigned [Signature] Mine Manager-Mine Foreman
Assistant Foreman
Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 9-1-09 20 Section or Area Examined Pumps
Time of Examination: from 8:30 a.m. or 0 to 11:30 a.m. or 0
Was this report phoned to outside: Yes/ no
By whom M. Bailey 3-3 Time A.M 11:30 P.M
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include locations like 'Em Nos #14, 19, 30', '32 Seal 37, HG-17', '60, 62, 77, 126', '129', 'L.B. 8', '#1 Section', '#2 Section', 'N. Mains'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: 'Good Air Movement'.

Remarks: 0% CH4, 0% CO, 20-25% O2 detected at time of exam. Track, travelways, passageways, D. boxes, choppers ok at time of exam.

Mike Bailey 27085 Bruce Brant 37074

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey Preshift-Mine Examiner Certificate No. 39342
Countersigned Dan Miller Mine Manager-Mine Foreman Certificate No. 1330A
Assistant Foreman Superintendent or Assistant

Use Indelible  
Pen or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 9-2-09 20 Section or Area Examined Pumps  
Time of Examination: from 3:00 (m) or p.m. to 6:00 (a.m) or p.m.  
Was this report phoned to outside: Yes no  
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. En 110, #14, 19, 30	OK	Non-Observed	None
2. 32 Seal 37, HG-17	OK	       DOWN	     
3. 60, 62, 77, 126	OK		
4. 129	OK		
5. L. B. G.	OK		
6. #1 Section		   	   
7. #2 Section			
8. N. Main's			
9. #3 Section		None observed	None
10.			

Air Measurements

Location	CFM	Location	CFM
<u>Good Airway</u>			

Remarks: 02097 0200 2018202  
pumps Boxes Tra-relay clear

Signed By Mike Bailey 27085 37074  
Preshift-Mine Examiner Certificate No. 37074  
Countersigned Steve Cofeln 39042  
Mine Manager—Mine Foreman Assistant Foreman Certificate No. 39042  
Assistant Foreman

Tom Boyer 3226 Russell Dumoc 1536A Johnny Neely 33472  
Superintendent or Assistant

Use Indelible  
Pen or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_





Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 9-2-69 20. Section or Area Examined Pump  
 Time of Examination: from 7:00 a.m. or 3:00 a.m. to 3:00 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_ (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

SB #	Location	Violation or Hazardous Condition	Action Taken
1.	<u>EM 112's, #13,</u>	<u>CHH</u> <u>OP</u> <u>None observed</u>	<u>None</u>
2.	<u>#37, #32 Seal</u>		
3.	<u>AL 17 ramp</u>		
4.	<u>#62, bit, 77, 126</u>		
5.	<u>129</u>	<u>Down</u>	
6.	<u>ABB</u>		
7.	<u>#1 Section</u>	<u>OP</u> <u>None Obs</u>	
8.	<u>#2 Section (69 BK)</u>	<u>None Obs</u>	
9.	<u>#3 Section (8, 18, 14)</u>	<u>OP</u> <u>None observed</u>	<u>None</u>
10.	<u>North Main</u>		

#### Air Measurements

Location	CFM	Location	CFM
<u>Coal and movement</u>			

Remarks: OPCH, OPED 20.8% O<sub>2</sub> detected  
Lead, handways, yellow lines safe at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Tom [Signature] Preshift-Mine Examiner Certificate No. 32261  
 Countersigned Paul [Signature] Mine Manager—Mine Foreman Assistant Foreman  
Scott Halstead Assistant Foreman Certificate No. 37567  
Russell [Signature] Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 9-2-09 20 Section or Area Examined Pumps  
Time of Examination: from 8:30 a.m. or 8:30 p.m. to 11:30 a.m. or 11:30 p.m.  
Was this report phoned to outside: Yes no  
By whom Don Bailey D. Bailey Time 11:05 A.M. PM  
Report received by Don Bailey 39042  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH <sub>4</sub>	Violation or Hazardous Condition	Action Taken
1. Em 110's 14, 19, 20	OK	None observed	None
2. 32 Seal 37, HG 17	OK	" "	" "
3. 60, 62, 77, 126	OK	" "	" "
4. 129		Down	Reported
5. L.G. 0	OK	None observed	None
6. #1 Section	OK	" "	" "
7. #2 Section	OK	" "	" "
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
<u>Room Air Movement</u>			

Remarks: OK CH<sub>4</sub>, OK CO, 2000' OK detected at time of exam  
Track, Travelways, powerlines, chargers OK at time of exam

Don Bailey 39042

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.  
Signed By Don Bailey 39042 22085 Don Williams 19397  
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.  
Countersigned Don Bailey 39042  
Mine Manager—Mine Foreman Assistant Foreman  
Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 9-3-09 20. Section or Area Examined Pumps  
 Time of Examination: from 1:00 or p.m. to 6:00 or p.m.  
 Was this report phoned to outside: Yes no  
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_  
 (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Em Nos 14, 19, 30	CH <sub>4</sub>	
2. 32 seal 37, Hg-17 01	None observed	None
3. 60, 62, 77, 126 01	" "	" "
4. 129	Down	Reported
5. L.B.B. 01		
6. #1 Section		
7. #2 Section		
8. N. Mains		
9. #3 Section	None observed	None
10.		

#### Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: OX CH<sub>4</sub>, OX CO, 20.8% O<sub>2</sub> detected at time of exam  
Track, Travelways, powerlines, chargers, O-Daxes ok at time of exam

Mike Bailey 27085 Bruce Baletts 37074 John J. Taylor 1759A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1539A  
 Freshift-Mine Examiner Certificate No. \_\_\_\_\_  
 Countersigned [Signature] 32261 [Signature] 1759A  
 Mine Manager—Mine Foreman Assistant Foreman Certificate No. 39042  
 Assistant Foreman

Tom Sawyer 32261 Russell Duvall 1536-A John J. Taylor 33472  
 Superintendent or Assistant

Use Indelible  
Pen or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 9-3-09 20 Section or Area Examined Pumping

Time of Examination: from 7:00 a.m. or 3:00 p.m.

Was this report phoned to outside: Yes no

By whom Time A.M. P.M.

Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, Violation or Hazardous Condition, Action Taken. Includes entries for E.M. 110's, #19, 13, #32 seal, #37, #60, 62, 77, 126, #129, #1 Section, #2 Section, #3 Section.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Includes handwritten entry 'Good movement'.

Remarks: D% CH4 D% CO2 20.8% O2 detected track, tunnelways, power lines safe at repair

Mike Bailey 27085

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 33211 Assistant Foreman [Signature] 1122-A Certificate No. 1536-A

Countersigned [Signature] Mine Manager - Mine Foreman Assistant Foreman

Superintendent or Assistant [Signature] 33472



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 9-3-09 20 Section or Area Examined Pumps
Time of Examination: from 8:00 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom M. Dailer D. Brackett Time A.M. 11:10 P.M.
Report received by Steve Cohen 39042 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'Em 1105' and 'L. B. B.' with corresponding observations and actions.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: OX CH4, OX CO, 20.8% O2 detected at time of exam. Track, Travelways, powerlines, choppers, D. wires etc at time of exam.

Signed By Mike Dailer 27085 Preshift-Mine Examiner Certificate No. 39042
Countersigned Steve Cohen 39042 Mine Manager-Mine Foreman
Assistant Foreman Dan Ullman 15377A

Russell Dunnoe 1536-A Superintendent or Assistant 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 9-4-09 20. Section or Area Examined Pumps  
 Time of Examination: from 5:00 a.m. or p.m. to 6:20 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
 Report received by \_\_\_\_\_ (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. Em 110's 14, 19, 13 <u>CH4</u>		
2. 32 Seal # 27 <u>OX</u>	None observed	None
3. 60, 62, 77, 120 <u>OX</u>	None observed	None
4. 129	<u>DOWN</u>	<u>Reported</u>
5. L. B. B. <u>OX</u>	None observed	None
6. #1 Section		
7. #2 Section		
8. #3 Section		
9. N. Mains		
10. _____		

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Manual</u>			
_____			
_____			
_____			
_____			
_____			
_____			
_____			
_____			
_____			

Remarks: ON CH4, OX CO, 22-25 O2 detected at time of exam  
Truck, Traveling, power cables, D. boxes, chargers on at time of exam

Mike Bailey 27085 Bruce Brant 37074

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Steve Glen Preshift Mine Examiner Certificate No. 31074  
 Countersigned John [Signature] Mine Manager—Mine Foreman Certificate No. 15874  
 \_\_\_\_\_ Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 9-4-09 20. Section or Area Examined Pump
Time of Examination: from 7:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, Violation or Hazardous Condition, Action Taken. Includes entries for SW CH, EMIID'S #13, 19, HT #32, #37, #60, 62, 77, 126, 129, LBB, #1 Sec, #2 Sec, #3 Sec #18, 8, 14, 0%, and #7 Main.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Board air movement.

Remarks: Weekly 2% CO 30.8% O2 detested track, haulways, power lines safe at depth

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] 32261 Certificate No.
Countersigned [Signature] 35000 Certificate No.
Assistant Foreman [Signature] 1536-1A
Superintendent or Assistant [Signature] 33472

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 9-4-09 20 Section or Area Examined Pumps  
 Time of Examination: from 8:00 a.m. or 8:00 p.m. to 11:30 a.m. or 11:30 p.m.  
 Was this report phoned to outside: Yes no  
 By whom Bickford Time A.M. 11:30 P.M.  
 Report received by Glen Ullman (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
CU Em 5 110'S 13,14 O2 CH4	none observed	none
G <sub>2</sub> U 19 #32 seal 37 O2 CH4	" "	/
G <sub>4</sub> 60, 62, 77, 126, O2 CH4	" "	
4. LBB O2 CH4	" "	
5. #1 sec O2 CH4	" "	
6. #2 sec O2 CH4	" "	
CU #3 sec 18, 8, 14 O2 CH4	" "	
8. A. mains O2 CH4	" "	
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: O2 CH4 O2 CO 2018202  
Track, Travel ways Clear At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Glen Ullman 1537A Certificate No. 3900000  
 Preshift-Mine Examiner Assistant Foreman  
 Countersigned John Bickford 26174 Certificate No.  
 Mine Manager—Mine Foreman Superintendent or Assistant

John Bickford 1662-A



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 9-5-69 20 Section or Area Examined Pumps  
Time of Examination: from 3:00 a.m. or p.m. to 5:00 a.m. or p.m.  
Was this report phoned to outside: Yes no  
By whom Brought out Time A.M. P.M.  
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 'Em 3 1105 13M, 19' and 'None Observed'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air amount'.

Remarks: 02CH4, 02CO, 208202  
Toweways Haulage ways clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.  
Signed By [Signature] 1539A  
Countersigned [Signature] Mine Manager - Mine Foreman  
Assistant Foreman [Signature] John A. Butford  
Superintendent or Assistant [Signature] John A. Neely 33472

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 9-5 2009 Section or Area Examined Pumps
Time of Examination: from 1200 a.m. or 0000 to 300 a.m. or 0000
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 rows of data including locations like 'EM 110's' and 'N. MAINS'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains one entry: 'Good Air Movement'.

Remarks: 0% CH4 0% CO 20.8 O2

Track, Travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] 33472 Certificate No.
Counter-signed [Signature] 37002 Certificate No.
Assistant Foreman

John A. Bickford 2d Lt. J. 1479A Superintendent or Assistant