


Appendix B

\fTimes New Roman\b1|i0|c0|p18;Cardinal Belt and Supply Slope 16° Decline



(FALL OF RIB)

\fTimes New Roman\b1|i0|c0|p18;Cardinal Slope

MSHA ID No. 15-17216

Gunther-Nash, Inc.

Contractor ID No. B08