



Section I--Violation Data

1. Date Mo Da Yr 07/24/2008	2. Time (24 Hr. Clock) 1200	3. Citation/ Order Number 7697005
4. Served To Gary Peacock, Superintendent		5. Operator GENWAL RESOURCES INC and UEI
6. Mine CRANDALL CANYON MINE		7. Mine ID 42-01715 (Contractor)
8. Condition or Practice		8a. Written Notice (103g) <input type="checkbox"/>

The operator did not propose adequate revisions to the roof control plan when conditions at the mine indicated that the plan was not adequate or suitable for controlling the roof, face, ribs or coal bursts. These conditions included bounces that occurred in the Main West North Barrier section and resulted in roof and rib damage and equipment damage, and a coal outburst, which occurred on March 10, 2007 and caused substantial damage to the section.

The revisions to the roof control plan proposed following the March 10, 2007 coal outburst did not make the plan adequate or suitable for controlling the roof, face, ribs or coal or rock bursts. The operator's failure to make appropriate changes to its roof control plan contributed to

See Continuation Form (MSHA Form 7000-3a)

9. Violation	A. Health <input type="checkbox"/> Safety <input checked="" type="checkbox"/> Other <input type="checkbox"/>	B. Section of Act	C. Part/Section of Title 30 CFR 75.223(a)
--------------	--	----------------------	---

Section II--Inspector's Evaluation

10. Gravity:						
A. Injury or Illness (has) (is):		No Likelihood <input type="checkbox"/>	Unlikely <input type="checkbox"/>	Reasonably Likely <input type="checkbox"/>	Highly Likely <input type="checkbox"/>	Occurred <input checked="" type="checkbox"/>
B. Injury or illness could reasonably be expected to be:		No Lost Workdays <input type="checkbox"/>	Lost Workdays Or Restricted Duty <input type="checkbox"/>	Permanently Disabling <input type="checkbox"/>	Fatal <input checked="" type="checkbox"/>	
C. Significant and Substantial:				D. Number of Persons Affected:		
Yes <input checked="" type="checkbox"/>		No <input type="checkbox"/>		006		
11. Negligence (check one)						
A. None <input type="checkbox"/>		B. Low <input type="checkbox"/>		C. Moderate <input type="checkbox"/>		D. High <input checked="" type="checkbox"/>
E. Reckless Disregard <input type="checkbox"/>						
12. Type of Action			13. Type of Issuance (check one)			
104(d)(2)			Citation <input type="checkbox"/>		Order <input checked="" type="checkbox"/>	
Safeguard <input type="checkbox"/>						
14. Initial Action			E. Citation/ Order Number		F. Dated	
A. Citation <input type="checkbox"/> B. Order <input checked="" type="checkbox"/> C. Safeguard <input type="checkbox"/> D. Written Notice <input type="checkbox"/>			7286500		Mo Da Yr 12/29/2006	
15. Area or Equipment N/A						

16. Termination Due	A. Date Mo Da Yr	B. Time (24 Hr. Clock)

Section III--Termination Action

17. Action to Terminate The mine has been abandoned.

18. Terminated	A. Date Mo Da Yr	B. Time (24 Hr. Clock)
	07/24/2008	1205

Section IV--Automated System Data

19. Type of Inspection (activity code)	20. Event Number	21. Primary or Mill
E06	4476435	
22. Signature	23. AR Number	
Signature	23305/23109	



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input type="checkbox"/> <input checked="" type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 07/24/2008	3. Citation/ Order Number 7697005
4. Served To Gary Peacock, Superintendent	5. Operator GENWAL RESOURCES INC and UEI	
6. Mine CRANDALL CANYON MINE	7. Mine ID 42-01715	(Contractor)

Section II--Justification for Action

Continuation of 8. Condition or Practice

the August 6, 2007 fatal accident. This was an unwarrantable failure to comply with a mandatory standard.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	--	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection E06	10. Event Number 4476435		
11. Signature	AR Number 23305	12. Date Mo Da Yr 07/24/2008	13. Time (24 Hr. Clock) 1200