

1

Nov 29/06

— Jan 4



MAIN WEST

**PRE-SHIFT
SECTIONS**

2MSHA02648

M

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 11-29-06

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 7:22 AM/PM (AM)

END 8:33 AM/PM (AM)

EXAM. CALLED OUT — YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	32,964		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 8783

COUNTER SIGNATURE

CERT. # 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 11-30-06

SECTION/AREA Main West

TIME OF EXAMINATION START 3:07 AM PM

END 4:48 AM PM

EXAM. CALLED OUT — YES NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX / INTAKE	21.0	0	0	32,766		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	21.0	0	0			None Observed	
#1 ENTRY	21.0	0	0			None Observed	
#2 ENTRY	21.0	0	0			None Observed	
#3 ENRTY	21.0	0	0			None Observed	
#4 ENTRY	21.0	0	0			None Observed	
#5 ENTRY							
#6 ENTRY							
Transformer	21.0	0	0			None Observed	
Charger	21.0	0	0			None Observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Section appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 8783
 COUNTER SIGNATURE _____ CERT. # 03892
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 11 30 06

SECTION/AREA Main West

TIME OF EXAMINATION START 1105 AM PM

END 1229 AM PM

EXAM. CALLED OUT YES NO

CALL OUT TIME 103 AM PM

CALLED OUT BY Brandon Kimber

REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	36864		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY	20.9	0	0	α		None observed	
#2 ENTRY	20.9	0	0	α		None observed	
#3 ENRTY	20.9	0	0	α		None observed	
#4 ENTRY	20.9	0	0	α		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.9	0	0	α		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work areas & travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINEE **Signature**

CERT. # 9658

COUNTER SIGNATURE **Signature**

CERT. # 7485

SECTION SUPERVISOR

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 11-30-06 SECTION/AREA MAIN WEST
 TIME OF EXAMINATION START 7:12 AM/PM AM END 8:56 AM/PM PM
 EXAM. CALLED OUT YES/NO CALL OUT TIME 9:45 AM/PM PM
 CALLED OUT BY CASEY ALLRED REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	36499		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
POWER CENTER	20.9	0	0			NONE OBSERVED	
CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME
OF EXAMINATION

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 8783
 COUNTER SIGNATURE **Signature** CERT. # 7485
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-1-06

SECTION/AREA Main West

TIME OF EXAMINATION START 3:08 AM PM

END 4:37 AM PM

EXAM. CALLED OUT — YES NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	21.0	0	0	35,941		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	21.0	0	0			None Observed	
#1 ENTRY	21.0	0	0			None Observed	
#2 ENTRY	21.0	0	0			None Observed	
#3 ENRTY	21.0	0	0			None Observed	
#4 ENTRY	21.0	0	0			None Observed	
#5 ENTRY							
#6 ENTRY							
Transformer	21.0	0	0			None Observed	
Charger	21.0	0	0			None Observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS

Section appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER

CERT. # 8783

COUNTER SIGNATURE

CERT. # 4735

SECTION SUPERVISOR

2MSHA02653

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-1-06

SECTION/AREA Mt. West

TIME OF EXAMINATION START 11-35 AM/PM

END 1257 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 140 AM/PM

CALLED OUT BY Achy Batus

REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	31464		none	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.9	0	0			none	
#2 ENTRY	20.9	0	0			none	
#3 ENRTY	20.9	0	0			none	
#4 ENTRY	20.9	0	0			none	
#5 ENTRY							
#6 ENTRY							

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS ARCAS Approval Sigs at the of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 592
 COUNTER SIGNATURE **Signature** CERT. # 4735
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-1-06

SECTION/AREA Main West

TIME OF EXAMINATION START 700 AM/PM

END 732 AM/PM

EXAM. CALLED OUT — YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				326 10			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			7	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
TRANSFORMER	20.9	0	0			None Observed	
CHARGER	20.9	0	0			7	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT.# 4842
 COUNTER SIGNATURE Signature CERT.# 4735
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-2-06

SECTION/AREA Main West

TIME OF EXAMINATION START 305 ~~AM~~/PM

END 347 ~~AM~~/PM

EXAM. CALLED OUT — YES/~~NO~~

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE				32,740			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			<i>None Observed</i>	
#1 ENTRY	20.9	0	0			7	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam.

PRE-SHIFT/MINE EXAMINEE **Signature** CERT. # 4892

COUNTER SIGNATURE _____ CERT. # 8462

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-2-06

SECTION/AREA Main West

TIME OF EXAMINATION START 1130 ~~AM~~/~~PM~~

END 118 ~~AM~~/~~PM~~

EXAM. CALLED OUT YES/ NO

CALL OUT TIME 1:25 ~~AM~~/~~PM~~

CALLED OUT BY Art Boletis

REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	30400		None obs.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None obs.	
#1 ENTRY	20.9	0	0			None obs.	
#2 ENTRY	20.9	0	0			None obs.	
#3 ENRTY	20.9	0	0			None obs.	
#4 ENTRY	20.9	0	0			None obs.	
#5 ENTRY							
#6 ENTRY							

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature

CERT.# 8916

COUNTER SIGNATURE Signature

CERT.# 8462

SECTION SUPERVISOR _____

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-2-06 SECTION/AREA MAIDWEST
 TIME OF EXAMINATION START 7:50 AM/PM AM END 8:34 AM/PM AM
 EXAM. CALLED OUT YES/NO CALL OUT TIME 9:32 AM/PM AM
 CALLED OUT BY J HANNA REPORT RECEIVED BY Signature
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	26,748		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		none observed	
#1 ENTRY	20.9	0	0	OK		none observed	
#2 ENTRY	20.9	0	0	OK		none observed	
#3 ENRTY	20.9	0	0	OK		none observed	
#4 ENTRY	20.9	0	0	OK		none observed	
#5 ENTRY							
#6 ENTRY							

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT
TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINER Signature CERT. # 1842
 COUNTER SIGNATURE _____ CERT. # 8462
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12306

SECTION/AREA Main West

TIME OF EXAMINATION START 315 AM/PM

END 418 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	27118			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			<i>None Observed</i>	
#1 ENTRY	20.9	0	0			?	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4892
 COUNTER SIGNATURE Signature CERT. # 8925
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-3-06

SECTION/AREA Main West

TIME OF EXAMINATION START 1140 AM PM

END 109 AM PM

EXAM. CALLED OUT — YES NO

CALL OUT TIME 1:37 AM PM

CALLED OUT BY Art Bolotas

REPORT RECEIVED BY **Signature**
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	30275			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None	
#1 ENTRY	20.9	0	0			None	
#2 ENTRY	20.9	0	0			None	
#3 ENRTY	20.9	0	0			None	
#4 ENTRY	20.9	0	0			None	
#5 ENTRY							
#6 ENTRY							

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam.

PRE-SHIFT/MINE EXAMINER **Signature**
COUNTER SIGNATURE _____
SECTION SUPERVISOR _____

CERT. # 8916
CERT. # 7488

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-3-06 SECTION/AREA Main West
 TIME OF EXAMINATION START 700 AM/PM AM END 732 AM/PM PM
 EXAM. CALLED OUT — YES/NO NO CALL OUT TIME _____ AM/PM
 CALLED OUT BY _____ REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				27940			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			7	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
TRANSFORMER	20.9	0	0			None Observed	
CHARGER	20.9	0	0			7	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4842
 COUNTER SIGNATURE _____ CERT. # 8462
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-4-06

SECTION/AREA Main West

TIME OF EXAMINATION START 315 AM/PM

END 354 AM/PM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				30,744			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			7	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None Observed	
Charger	20.9	0	0			7	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of spot

PRE-SHIFT/MINE EXAMINER _____ **Signature** _____ CERT.# 4844
 COUNTER SIGNATURE _____ **Signature** _____ CERT.# 7485
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-4-06

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 1:06 AM/PM

END 1:40 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 1:46 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				29,484			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.4	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANSFORMER	20.9	0	0			NONE OBSERVED	
CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 7483

COUNTER SIGNATURE

CERT.# 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 11 4 06

SECTION/AREA Main West

TIME OF EXAMINATION START 715 AM/PM AM PM

END 820 AM/PM AM PM

EXAM. CALLED OUT YES NO

CALL OUT TIME 932 AM/PM AM PM

CALLED OUT BY Don Erickson

REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX / INTAKE	20.8	0	0	36560		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0	05		None observed	
#1 ENTRY	20.8	0	0	05		None observed	
#2 ENTRY	20.8	0	0	05		None observed	
#3 ENRTY	20.8	0	0	05		None observed	
#4 ENTRY	20.8	0	0	05		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.8	0	0	05		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas + travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature

CERT. # 9659

COUNTER SIGNATURE Signature

CERT. # _____

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 11-5-06

SECTION/AREA MAIN West

TIME OF EXAMINATION START 3:05 AM PM

END 4:10 AM PM

EXAM. CALLED OUT — YES/ NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY Don Erickson

REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	38840		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0	OK		"	
#1 ENTRY	20.8	0	0	OK		"	
#2 ENTRY	20.8	0	0	OK		"	
#3 ENRTY	20.8	0	0	OK		"	
#4 ENTRY	20.8	0	0	OK		"	
#5 ENTRY							
#6 ENTRY							
Traps / changer	20.8	0	0	OK		"	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas + travel ways appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 9659

COUNTER SIGNATURE

Signature

CERT.# 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-5-06 SECTION/AREA Main West
 TIME OF EXAMINATION START 1:00 AM/PM END 1:57 AM/PM
 EXAM. CALLED OUT — YES/NO CALL OUT TIME 1:55 AM/PM
 CALLED OUT BY Dale Black REPORT RECEIVED BY Foster McArthur
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	32.346		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	CE		None observed	
#1 ENTRY	20.9	0	0	CE		None observed	
#2 ENTRY	20.9	0	0	CE		None observed	
#3 ENRTY	20.9	0	0	CE		None observed	
#4 ENTRY	20.9	0	0	CE		None observed	
#5 ENTRY							
#6 ENTRY							
Truss/Charger	20.9	0	0	CE		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas Reported safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT.# 7483
 COUNTER SIGNATURE Signature CERT.# 7480
 SECTION SUPERVISOR _____

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 11 5 06

SECTION/AREA Main West

TIME OF EXAMINATION START 706 AM/PM

END 840 AM/PM

EXAM. CALLED OUT — YES / NO

CALL OUT TIME 843 AM/PM

CALLED OUT BY Benny Allred

REPORT RECEIVED BY Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	31900		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY	20.9	0	0	α		None observed	
#2 ENTRY	20.9	0	0	α		None observed	
#3 ENRTY	20.9	0	0	α		None observed	
#4 ENTRY	20.9	0	0	α		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.9	0	0	α		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work areas & travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature

CERT. # 9279

COUNTER SIGNATURE Signature

CERT. # 03892

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-6-06

SECTION/AREA WEST MAINS

TIME OF EXAMINATION START 304 (AM)/PM

END 447 (AM)/PM

EXAM. CALLED OUT — YES/(NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX / INTAKE	20.9	0	0	34,955		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS/CHARBON	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS ALL AREAS APPEARED SAFE AT
TIME OF EXAM

PRE-SHIFT/MINE EXAMINER _____ **Signature** _____ CERT. # 9658
 COUNTER SIGNATURE _____ **Signature** _____ CERT. # 7488
 SECTION SUPERVISOR _____

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-6-06

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 103 AM/PM

END 211 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 220 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	34120		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANSFORMER	20.9	0	0			NONE OBSERVED	
CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
TAILPIECE	ACCUMULATIONS	SHOULDER WASHED

PRE-SHIFT REMARKS AREAS REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 7483

COUNTER SIGNATURE

Signature

CERT.# 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 6 06

SECTION/AREA Main West

TIME OF EXAMINATION START 730 AM/PM ~~AM~~

END 850 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 854 AM/PM

CALLED OUT BY Benny Allred

REPORT RECEIVED BY Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	34/290		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		None observed	
#1 ENTRY	20.9	0	0	OK		None observed	
#2 ENTRY	20.9	0	0	OK		None observed	
#3 ENRTY	20.9	0	0	OK		None observed	
#4 ENTRY	20.9	0	0	OK		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.9	0	0	OK		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work areas & travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature
 COUNTER SIGNATURE Signature
 SECTION SUPERVISOR _____

CERT. # 9279
 CERT. # 03892

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-7-06

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 3:07 AM/PM

END 4:25 AM/PM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	35480		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.8	0	0	OK		//	
#2 ENTRY	20.8	0	0	OK		//	
#3 ENRTY	20.8	0	0	OK		//	
#4 ENTRY	20.8	0	0	OK		//	
#5 ENTRY							
#6 ENTRY							
Travs / Chweger	20.8	0	0	OK		//	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas & Travelways Appeared
SAFE AT TIME OF EXAM

PRE-SHIFT/MINE EXAMINER Signature CERT.# 9659

COUNTER SIGNATURE Signature CERT.# 8725

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-7-06 SECTION/AREA MAIN West
 TIME OF EXAMINATION START 1:03 AM/PM AM END 1:41 AM/PM AM
 EXAM. CALLED OUT — YES/NO CALL OUT TIME 1:46 AM/PM AM
 CALLED OUT BY Dale Black REPORT RECEIVED BY Foster McArthur
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	35.005		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		none observed	
#1 ENTRY	20.9	0	0	OK		none observed	
#2 ENTRY	20.9	0	0	OK		none observed	
#3 ENRTY	20.9	0	0	OK		none observed	
#4 ENTRY	20.9	0	0	OK		none observed	
#5 ENTRY							
#6 ENTRY							
TRADS/charger	20.9	0	0	OK		none observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas Reported Reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 7483
 COUNTER SIGNATURE **Signature** CERT.# 03892
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 7 06

SECTION/AREA Main West

TIME OF EXAMINATION START 712 AM/PM

END 835 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 848 AM/PM

CALLED OUT BY B Kimber

REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	35840		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY	20.9	0	0	α		None observed	
#2 ENTRY	20.9	0	0	α		None observed	
#3 ENRTY	20.9	0	0	α		None observed	
#4 ENTRY	20.9	0	0	α		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.9	0	0	α		None observed	

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work areas & travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER **Signature**
 COUNTER SIGNATURE _____
 SECTION SUPERVISOR _____

CERT. # 9658
 CERT. # 03792

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-8-06

SECTION/AREA WEST MAINS

TIME OF EXAMINATION START 304 AM/PM

END 440 AM/PM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	35,665		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY						NONE OBSERVED	
TRANS/CHARGER	20.9	0	0				

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS ALL AREAS APPEARED SAFE AT
TIME OF EXAM

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 9658
 COUNTER SIGNATURE Signature CERT. # 4735
 SECTION SUPERVISOR _____

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-8-06

SECTION/AREA Main West

TIME OF EXAMINATION START 11:35 AM/PM

END 12:52 AM/PM

EXAM. CALLED OUT YES NO

CALL OUT TIME 1.48 AM/PM

CALLED OUT BY arty Bolotas

REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				32650			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None obs	
#1 ENTRY	20.9	0	0			None obs	
#2 ENTRY	20.9	0	0			None obs	
#3 ENRTY	20.9	0	0			None obs	
#4 ENTRY	20.9	0	0			None obs.	
#5 ENTRY							
#6 ENTRY							
<i>Trans.</i>	20.9	0	0			None obs.	
<i>Charger</i>	20.9	0	0			None obs.	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS _____

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 8916

COUNTER SIGNATURE

CERT. # 8462

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-8-06 SECTION/AREA Main West
 TIME OF EXAMINATION START 737 AM/PM AM END 815 AM/PM AM
 EXAM. CALLED OUT — YES/NO NO CALL OUT TIME _____ AM/PM _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				37679			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			<i>None</i>	
#1 ENTRY	20.9	0	0			7	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
<i>Transformer</i>	20.9	0	0			<i>None</i>	
<i>Charger</i>	20.9	0	0			<i>None</i>	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4842
 COUNTER SIGNATURE Signature CERT. # 8462
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-9-06
 TIME OF EXAMINATION START 315 AM/PM
 EXAM. CALLED OUT — YES/NO (NO)
 CALLED OUT BY _____

SECTION/AREA Main West
 END 420 AM/PM
 CALL OUT TIME _____ AM/PM
 REPORT RECEIVED BY _____
 SIGNATURE _____

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				31426			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			}	
#1 ENTRY	20.9	0	0				
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None Observed	
Charger	20.9	0	0			" "	

V = VIOLATION
 H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4842
 COUNTER SIGNATURE Signature CERT. # 8462
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-9-06

SECTION/AREA Main West

TIME OF EXAMINATION START 2:00 AM/PM (M)

END 2:28 AM/PM (M)

EXAM. CALLED OUT — YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				31424			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			none observed	
#1 ENTRY	20.9	0	0				
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
transformer	20.9	0	0				
charger	20.8	0	0			none observed	
	20.8	0	0				

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER _____ **Signature** _____ CERT.# 6845-7958

COUNTER SIGNATURE _____ **Signature** _____ CERT.# 81162

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-9-06

SECTION/AREA Main West

TIME OF EXAMINATION START 710 AM/PM

END 758 AM/PM

EXAM. CALLED OUT — YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				30026			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			7	
#1 ENTRY	20.9	0	0				
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			7	
Charger	20.9	0	0				

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 2882
 COUNTER SIGNATURE Signature CERT. # 8462
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-10-06

SECTION/AREA Main West

TIME OF EXAMINATION START 315 AM/PM

END 452 AM/PM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE				32710			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			7	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
TRANSFORMER	20.9	0	0			None Observed	
CHARGER	20.9	0	0			7	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT.# 4872
 COUNTER SIGNATURE Signature CERT.# 4735
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-10-06

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 11:18 ~~AM/PM~~

END 1:00 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 2:00 AM/PM

CALLED OUT BY Aety Boltes

REPORT RECEIVED BY **Signature**
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	21.0			316 70		nae obs.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	21.0	0	0			nae obs.	
#1 ENTRY	21.0	0	0			nae obs.	
#2 ENTRY	21.0	0	0			nae obs.	
#3 ENRTY	21.0	0	0			nae obs.	
#4 ENTRY	21.0	0	0			nae obs.	
#5 ENTRY							
#6 ENTRY							
TRAWS	21.0	0	0			nae obs.	
Chargee	21.0	0	0			nae obs.	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS Apper! Sup. at top of Exam

PRE-SHIFT/MINE EXAMINER **Signature**

CERT.# 8916

COUNTER SIGNATURE **Signature**

CERT.# 8962

SECTION SUPERVISOR

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-10-06

SECTION/AREA West Mines

TIME OF EXAMINATION START 7:30 AM/PM AM

END 8:18 AM/PM AM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 9:58 AM/PM AM

CALLED OUT BY Jim Hanna

REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	24048		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			None Observed	
#2 ENTRY	20.9	0	0			None Observed	
#3 ENRTY	20.9	0	0			None Observed	
#4 ENTRY	20.9	0	0			None Observed	
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None Observed	
Charger	20.9	0	0			None Observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at
Time of Exam

PRE-SHIFT/MINE EXAMINER **Signature**
COUNTER SIGNATURE **Signature**
SECTION SUPERVISOR **Signature**

CERT. # 2842
CERT. # 4735

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-11-06

SECTION/AREA Main West

TIME OF EXAMINATION START 315 AM/PM

END 418 AM/PM

EXAM. CALLED OUT — YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE				28800			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			<i>None Observed</i>	
#1 ENTRY	20.9	0	0				
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
<i>Transformer</i>	20.9	0	0			<i>None Observed</i>	
<i>Charger</i>	20.9	0	0				

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER

Signature
Signature

CERT. # 4842

COUNTER SIGNATURE

CERT. # 4735

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-11-06

SECTION/AREA Main West

TIME OF EXAMINATION START 1125 AM/PM

END 1245 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 130 AM/PM

CALLED OUT BY Arty Bobbas

REPORT RECEIVED BY **Signature**

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	31779		none obs.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			none obs	
#1 ENTRY	20.9	0	0			none obs	
#2 ENTRY	20.9	0	0			none obs	
#3 ENRTY	20.9	0	0			none obs	
#4 ENTRY	20.9	0	0			none obs	
#5 ENTRY							
#6 ENTRY							
TRANS	20.9	0	0			none obs.	
Charger	20.9	0	0			none obs.	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS

Secs Apprd Safe at end Exam.

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 8916

COUNTER SIGNATURE

Signature

CERT. # 8962

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-11-06

SECTION/AREA Main West

TIME OF EXAMINATION START 9:05 AM/PM

END 9:48 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 9:30 AM/PM

CALLED OUT BY Jim Hanna

REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	27622		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			None Observed	
#2 ENTRY	20.9	0	0			None Observed	
#3 ENRTY	20.9	0	0			None Observed	
#4 ENTRY	20.9	0	0			None observed	
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None Observed	
Charger	20.9	0	0			None Observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at
Time of Exam

PRE-SHIFT/MINE EXAMINER **Signature**
COUNTER SIGNATURE **Signature**
SECTION SUPERVISOR **Signature**

CERT. # 4872
CERT. # 7485

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-12-06

SECTION/AREA Main West

TIME OF EXAMINATION START 3:15 AM PM

END 5:06 AM PM

EXAM. CALLED OUT — YES NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE				<u>29788</u>			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	<u>20.9</u>	<u>0</u>	<u>0</u>			<u>None Observed</u>	
#1 ENTRY	<u>20.9</u>	<u>0</u>	<u>0</u>			7	
#2 ENTRY	<u>20.9</u>	<u>0</u>	<u>0</u>				
#3 ENRTY	<u>20.9</u>	<u>0</u>	<u>0</u>				
#4 ENTRY	<u>20.9</u>	<u>0</u>	<u>0</u>				
#5 ENTRY							
#6 ENTRY							
<u>Transformer</u>	<u>20.9</u>	<u>0</u>	<u>0</u>			<u>None Observed</u>	
<u>Charger</u>	<u>20.9</u>	<u>0</u>	<u>0</u>			7	

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER

Signature
Signature

CERT. # 4882

COUNTER SIGNATURE

CERT. # 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-12-06

SECTION/AREA Main West

TIME OF EXAMINATION START ~~1:00~~ 1:00 AM/PM

END 1:55 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 1:57 AM/PM

CALLED OUT BY Dale Black

REPORT RECEIVED BY Foster McArthur
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				30825			
HEADGATE #10							
TAILGATE #126							
BELTLINE	209	0	0				
RETURN	209	0	0			none observed	
#1 ENTRY	209	0	0			none observed	
#2 ENTRY	209	0	0			none observed	
#3 ENRTY	209	0	0			none observed	
#4 ENTRY	209	0	0			none observed	
#5 ENTRY							
#6 ENTRY							
Transformer	209	0	0			none observed	
Charger	209	0	0			none observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas Reported Reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT.# 7483

COUNTER SIGNATURE Signature CERT.# 7485

SECTION SUPERVISOR _____

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12/12/06

SECTION/AREA Main West

TIME OF EXAMINATION START 709 AM/PM

END 820 AM/PM

EXAM. CALLED OUT — YES / NO

CALL OUT TIME 845 AM/PM

CALLED OUT BY B. Allred

REPORT RECEIVED BY Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	332/10		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY	20.9	0	0	α		None observed	
#2 ENTRY	20.9	0	0	α		None observed	
#3 ENRTY	20.9	0	0	α		None observed	
#4 ENTRY	20.9	0	0	α		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.9	0	0	α		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work areas & travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature

CERT. # 9279

COUNTER SIGNATURE

CERT. # 03892

SECTION SUPERVISOR

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-13-06

SECTION/AREA WEST MAINS

TIME OF EXAMINATION START 302 AM/PM

END 415 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	35,220		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS/CHASSIS	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS ALL AREAS APPEARED SAFE AT TIME
OF EXAM

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 9658

COUNTER SIGNATURE

Signature

CERT. # 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12.13-06

SECTION/AREA Main West

TIME OF EXAMINATION START 1:07 AM/PM

END 1:59 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 2:00 AM/PM

CALLED OUT BY Dale Black

REPORT RECEIVED BY Foster McArthur
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE	20.9	0	0	35.500		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None observed	
#1 ENTRY	20.9	0	0			None observed	
#2 ENTRY	20.9	0	0			None observed	
#3 ENRTY	20.9	0	0			None observed	
#4 ENTRY	20.9	0	0			None observed	
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None observed	
Charger	20.9	0	0			None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas Reported Reasonably safe
At time of exam

PRE-SHIFT/MINE EXAMINER
COUNTER SIGNATURE
SECTION SUPERVISOR

Signature
Signature

CERT. # 7483
CERT. # 7485

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 17 06

SECTION/AREA Main West

TIME OF EXAMINATION START 7 09 AM/PM

END 8 25 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 8 31 AM/PM

CALLED OUT BY B. Kimber

REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	36665		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY	20.9	0	0	α		None observed	
#2 ENTRY	20.9	0	0	α		None observed	
#3 ENRTY	20.9	0	0	α		None observed	
#4 ENTRY	20.9	0	0	α		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/charger	20.9	0	0	α		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS

All areas appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 9658

COUNTER SIGNATURE

Signature

CERT.# 03892

SECTION SUPERVISOR

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-14-06

SECTION/AREA WEST MAINS

TIME OF EXAMINATION START 307 AM/PM

END 423 AM/PM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	38,250		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.7	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS/CHARGES	20.9	0	0			NONE OBSERVED	

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS ALL AREAS APPEARED SAFE AT
TEMP OF EXAM

PRE-SHIFT/MINE EXAMINER _____ **Signature** _____ CERT. # 9658
 COUNTER SIGNATURE _____ **Signature** _____ CERT. # 7485
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-14-06

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 1:00 AM/PM

END 1:48 AM/PM

EXAM. CALLED OUT YES NO

CALL OUT TIME 1:55 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	35,260		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
CHARGER- TRANSFORMER	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 7483

COUNTER SIGNATURE

Signature

CERT.# 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 14 06

SECTION/AREA Main West

TIME OF EXAMINATION START 706 AM/PM

END 845 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 920 AM/PM

CALLED OUT BY B Kimber

REPORT RECEIVED BY

Signature

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	37570		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY	20.9	0	0	α		None observed	
#2 ENTRY	20.9	0	0	α		None observed	
#3 ENRTY	20.9	0	0	α		None observed	
#4 ENTRY	20.9	0	0	α		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.9	0	0	α		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS

All areas appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER

Signature
Signature

CERT. # 9653

COUNTER SIGNATURE

CERT. # 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-15-06

SECTION/AREA main west

TIME OF EXAMINATION START 3:05 AM/PM

END 4:15 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	38016		None	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None	
#1 ENTRY	20.9	0	0			None	
#2 ENTRY	20.9	0	0			None	
#3 ENRTY	20.9	0	0			None	
#4 ENTRY	20.9	0	0			None	
#5 ENTRY							
#6 ENTRY							
Tran	20.9	0	0			None	
Charger	20.9	0	0			None	

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all area appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER _____ **Signature** _____ CERT.# 9279

COUNTER SIGNATURE _____ **Signature** _____ CERT.# 7485

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-15-06

SECTION/AREA Main West

TIME OF EXAMINATION START 12:32 AM/PM AM

END 1:49 AM/PM AM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 1:50 AM/PM AM

CALLED OUT BY Dale Black

REPORT RECEIVED BY Foster McArthur
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	209	0	0	36805		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	209	0	0	α		None observed	
#1 ENTRY	209	0	0	α		None observed	
#2 ENTRY	209	0	0	α		None observed	
#3 ENRTY	209	0	0	α		None observed	
#4 ENTRY	209	0	0	α		None observed	
#5 ENTRY							
#6 ENTRY							
TRANS/Charger	209	0	0	α		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas Reported Reasonably Safe At time of exam

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 7483

COUNTER SIGNATURE

Signature

CERT. # 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 15 06

SECTION/AREA Main West

TIME OF EXAMINATION START 700 AM/PM

END 816 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 856 AM/PM

CALLED OUT BY B. Alford

REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	37950		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY	20.9	0	0	α		None observed	
#2 ENTRY	20.9	0	0	α		None observed	
#3 ENRTY	20.9	0	0	α		None observed	
#4 ENTRY	20.9	0	0	α		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.9	0	0	α		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work areas & travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER **Signature**
 COUNTER SIGNATURE _____
 SECTION SUPERVISOR _____

CERT. # 9279
 CERT. # 03892

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-16-06

SECTION/AREA WEST MAIN

TIME OF EXAMINATION START 302 AM/PM

END 410 AM/PM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	38,366		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.9	0	0			None Observed	
#2 ENTRY	20.9	0	0			None Observed	
#3 ENRTY	20.9	0	0			None Observed	
#4 ENTRY	20.9	0	0			None Observed	
#5 ENTRY							
#6 ENTRY							
TRANS/CHAFFIN	20.9	0	0			None Observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS ALL AREAS APPEARED SAFE
AT TIME OF EXAM

PRE-SHIFT/MINE EXAMINER

COUNTER SIGNATURE

SECTION SUPERVISOR

Signature
Signature

CERT. # 9658

CERT. # 7485

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-16-04 SECTION/AREA MAIN WEST
 TIME OF EXAMINATION START 1203 AM/PM AM END 141 AM/PM PM
 EXAM. CALLED OUT YES/NO CALL OUT TIME 150 AM/PM PM
 CALLED OUT BY DALE BLACK REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	36,722		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS/CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME
OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 7483

COUNTER SIGNATURE

CERT.# 7485

SECTION SUPERVISOR

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 16 06

SECTION/AREA Main West

TIME OF EXAMINATION START 7 AM/PM

END 820 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 831 AM/PM

CALLED OUT BY Benny Allred

REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX / INTAKE	20.9	0	0	38682		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		None observed	
#1 ENTRY	20.9	0	0	OK		None observed	
#2 ENTRY	20.9	0	0	OK		None observed	
#3 ENRTY	20.9	0	0	OK		None observed	
#4 ENTRY	20.9	0	0	OK		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.9	0	0	OK		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work areas & travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER **Signature**

CERT. # 9279
CERT. # 03892

COUNTER SIGNATURE _____
SECTION SUPERVISOR _____

2MSHA02700

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-17-06

SECTION/AREA WEST MAINS

TIME OF EXAMINATION START 304 AM/PM

END 410 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE	90.9	0	0	38,764		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	90.9	0	0			NONE OBSERVED	
#2 ENTRY	90.9	0	0			NONE OBSERVED	
#3 ENRTY	90.9	0	0			NONE OBSERVED	
#4 ENTRY	90.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS / CHARGE	90.9	0	0			NONE OBSERVED	

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS ALL AREAS APPROVED SAFE
AT TIME OF EXAM

PRE-SHIFT/MINE EXAMINER _____ **Signature** _____ CERT.# 9658
 COUNTER SIGNATURE _____ **Signature** _____ CERT.# 7485
 SECTION SUPERVISOR _____

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-17-06 SECTION/AREA MAIN WEST
 TIME OF EXAMINATION START 11:45 ~~AM~~ PM END 1:16 AM/PM
 EXAM. CALLED OUT ~~YES~~ NO CALL OUT TIME 1:45 AM/PM
 CALLED OUT BY DALE BLACK REPORT RECEIVED BY Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	37485		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS/CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7483
 COUNTER SIGNATURE Signature CERT. # 7485
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-19-06

SECTION/AREA West mains

TIME OF EXAMINATION START 3:00 AM/PM

END 4:30 AM/PM

EXAM. CALLED OUT — ^{BA} ~~YES/NO~~

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	39,060		None	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None	
#1 ENTRY	20.9	0	0			None	
#2 ENTRY	20.9	0	0			None	
#3 ENRTY	20.9	0	0			None	
#4 ENTRY	20.9	0	0			None	
#5 ENTRY							
#6 ENTRY							
Tran charger	20.9	0	0			None	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All area appeared safe at
Time of exam

PRE-SHIFT/MINE EXAMINER: _____ Signature _____ CERT.# 9279
 COUNTER SIGNATURE _____ Signature _____ CERT.# 8462
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-18-06 SECTION/AREA Main West
 TIME OF EXAMINATION START 1200 AM PM END 1215 AM PM
 EXAM. CALLED OUT — YES NO CALL OUT TIME _____ AM/PM
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				42776			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0				None Observed
#1 ENTRY	20.9	0	0			?	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
TRANSFORMER ²	20.9	0	0			None	
CHARGER ²	20.9	0	0			None	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4842
 COUNTER SIGNATURE Signature CERT. # 8462
 SECTION SUPERVISOR _____

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-18-06

SECTION/AREA Main West

TIME OF EXAMINATION START 7:00 AM/PM

END 8:25 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				42.080			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None observed	
#1 ENTRY	20.9	0	0			None observed	
#2 ENTRY	20.9	0	0			None observed	
#3 ENRTY	20.9	0	0			None observed	
#4 ENTRY	20.9	0	0			None observed	
#5 ENTRY							
#6 ENTRY							
Trans.	20.9	0	0			None obs	
Charger	20.9	0	0			None obs	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Section approved safe for work and turned off time program

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 8916
 COUNTER SIGNATURE **Signature** CERT.# 8402
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12/14/06
 TIME OF EXAMINATION START 300 AM/PM
 EXAM. CALLED OUT — YES/NO NO
 CALLED OUT BY _____

SECTION/AREA main west
 END 421 AM/PM
 CALL OUT TIME _____ AM/PM
 REPORT RECEIVED BY _____
 SIGNATURE _____

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	39890		none of	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			none of	
#1 ENTRY	20.9	0	0			none of	
#2 ENTRY	20.9	0	0			none of	
#3 ENRTY	20.9	0	0			none of	
#4 ENTRY	20.9	0	0			none of	
#5 ENTRY							
#6 ENTRY							
<i>Tram</i>	20.9	0	0			none of	
<i>Charger</i>	20.9	0	0			none of	

V = VIOLATION
 H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS

*Section appeared safe for work
 and turned out from of them*

PRE-SHIFT/MINE EXAMINER

COUNTER SIGNATURE

SECTION SUPERVISOR

Signature

CERT. # 8962

CERT. # 8462

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-19-06 SECTION/AREA Main West
 TIME OF EXAMINATION START 1100 AM/PM END 1148 AM/PM
 EXAM. CALLED OUT — YES/NO (NO) CALL OUT TIME _____ AM/PM
 CALLED OUT BY _____ REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				40964			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			?	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None	
Charger	20.9	0	0			None	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam

Signature

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 8892
 COUNTER SIGNATURE _____ CERT. # 8462
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12/19/06 SECTION/AREA Main West
 TIME OF EXAMINATION START 718 AM/PM AM END 822 AM/PM PM
 EXAM. CALLED OUT — YES/NO NO CALL OUT TIME _____ AM/PM _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	39765		none ob	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			no work.	
#1 ENTRY	20.9	0	0			no work	
#2 ENTRY	20.9	0	0			no work	
#3 ENTRY	20.9	0	0			no work	
#4 ENTRY	20.9	0	0			no work	
#5 ENTRY							
#6 ENTRY							
<i>Iron -</i>	20.9	0	0			no work	
<i>Charger</i>	20.9	0	0			no work	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe for work and haul at time of exam

PRE-SHIFT/MINE EXAMINER _____ **Signature** _____ CERT.# 8916
 COUNTER SIGNATURE _____ **Signature** _____ CERT.# 4135
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12/20/06

SECTION/AREA Main west

TIME OF EXAMINATION START 316 AM/PM

END 421 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	40015		None ob	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None ob	
#1 ENTRY	20.9	0	0			None ob	
#2 ENTRY	20.9	0	0			None ob	
#3 ENRTY	20.9	0	0			None ob	
#4 ENTRY	20.9	0	0			None ob	
#5 ENTRY							
#6 ENTRY							
Tran am	20.9	0	0			None ob	
Charger	20.9	0	0			None ob	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe for work and travel at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT.# 8916
 COUNTER SIGNATURE Signature CERT.# 8462
 SECTION SUPERVISOR _____

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-20-06

SECTION/AREA Main West

TIME OF EXAMINATION START 1:00 AM/PM

END 1:43 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY Jim Hanna

REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE	20.9	0	0	40228		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			None Observed	
#2 ENTRY	20.9	0	0			None Observed	
#3 ENRTY	20.9	0	0			None Observed	
#4 ENTRY	20.9	0	0			None Observed	
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None Observed	
Charger	20.9	0	0			None Observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at Time of exam

PRE-SHIFT/MINE EXAMINER **Signature**

CERT. # 4892

COUNTER SIGNATURE **Signature**

CERT. # 4735

SECTION SUPERVISOR _____

2MSHA02710

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-20-06

SECTION/AREA Main West

TIME OF EXAMINATION START 7:00 AM/PM

END 8:05 AM/PM

EXAM. CALLED OUT — YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	40, 396		None obs	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None obs	
#1 ENTRY	20.9	0	0			None obs.	
#2 ENTRY	20.9	0	0			None obs	
#3 ENRTY	20.9	0	0			None obs	
#4 ENTRY	20.9	0	0			None obs	
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None obs	
Charger	20.9	0	0			None obs	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
XC 131 2 to 3 rc	Bolt Spacing To Fray	Set Timber AB

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

PRE-SHIFT/MINE EXAMINEE **Signature** CERT.# 2916

COUNTER SIGNATURE **Signature** CERT.# 8462

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12/21/06

SECTION/AREA Main West

TIME OF EXAMINATION START 301 AM/PM

END 420 AM/PM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____

REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	40137 41132		none ob	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			none ob	
#1 ENTRY	20.9	0	0			none ob	
#2 ENTRY	20.9	0	0			none ob	
#3 ENRTY	20.9	0	0			none ob	
#4 ENTRY	20.9	0	0			none ob	
#5 ENTRY							
#6 ENTRY							
Tran-	20.9	0	0			none ob	
Chy-	20.9	0	0			none ob	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
Beltline to 131 & 132	Rib slush & dirt to Ear from Rib	Spot Bolted Done ARS
LOX 132	Rib slush & dirt to Ear from Rib	Spot Bolted Done ARS

PRE-SHIFT REMARKS

*all areas appeared safe for
work and found at time of exam.*

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 8912

COUNTER SIGNATURE

Signature

CERT.# 8462

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

64

2MSHA02712

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-21-06

SECTION/AREA Main West

TIME OF EXAMINATION START 12:20 AM/PM AM

END 1:32 AM/PM PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 2:00 AM/PM PM

CALLED OUT BY Jim Hanna

REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	41162		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			None Observed	
#2 ENTRY	20.9	0	0			None Observed	
#3 ENRTY	20.9	0	0			None Observed	
#4 ENTRY	20.9	0	0			None Observed	
#5 ENTRY							
#6 ENTRY							

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 1892

COUNTER SIGNATURE **Signature** CERT.# 4735

SECTION SUPERVISOR

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-21-06 SECTION/AREA Main West
 TIME OF EXAMINATION START 7:00 AM/PM END 9:30 AM/PM
 EXAM. CALLED OUT — YES/NO NO CALL OUT TIME _____ AM/PM
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	38965		None obs.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None obs.	
#1 ENTRY	20.9	0	0			None obs.	
#2 ENTRY	20.9	0	0			None obs.	
#3 ENRTY	20.9	0	0			None obs.	
#4 ENTRY	20.9	0	0			None obs.	
#5 ENTRY							
#6 ENTRY							
Turns,	20.9	0	0			None obs.	
Charger	20.9	0	0			None obs.	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas approved Safe at time of Exam.

PRE-SHIFT/MINE EXAMINER _____ **Signature** _____ CERT.# 8914
 COUNTER SIGNATURE _____ **Signature** _____ CERT.# 4135
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12/22/06

SECTION/AREA Main W.

TIME OF EXAMINATION START 338 AM PM

END 440 AM PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	38965		None ob	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None ob	
#1 ENTRY	20.9	0	0			None ob	
#2 ENTRY	20.9	0	0			None ob	
#3 ENRTY	20.9	0	0			None ob	
#4 ENTRY	20.9	0	0			Preparation	reported
#5 ENTRY							
#6 ENTRY							
Tram	20.9	0	0			None ob	
Charger	20.9	0	0			None ob	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Section approved safe for work and level at time of exam

PRE-SHIFT/MINE EXAMINER _____ **Signature** _____ CERT.# 8916

COUNTER SIGNATURE _____ **Signature** _____ CERT.# 05892

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 22 06

SECTION/AREA Main West

TIME OF EXAMINATION START 1105 AM PM

END 1225 AM PM

EXAM. CALLED OUT YES NO

CALL OUT TIME 1:00 AM PM

CALLED OUT BY D. Erickson

REPORT RECEIVED BY

Signature

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	38650		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0	05		None observed	
#1 ENTRY	20.8	0	0	05		None observed	
#2 ENTRY	20.8	0	0	05		None observed	
#3 ENRTY	20.8	0	0	05		None observed	
#4 ENTRY	20.8	0	0	05		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.8	0	0	05		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work areas & travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature

CERT. # 9659

COUNTER SIGNATURE Signature

CERT. # 7480

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-22-06 SECTION/AREA MAIN WEST
 TIME OF EXAMINATION START 7:00 AM/PM AM END 8:07 AM/PM AM
 EXAM. CALLED OUT (YES)/NO CALL OUT TIME 9:35 AM/PM AM
 CALLED OUT BY DALE BLACK REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	37,940		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS-CHARGE	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE
AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 7483
 COUNTER SIGNATURE **Signature** CERT. # 7485
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-23-06 SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 340 AM/PM END 451 AM/PM

EXAM. CALLED OUT — YES/ NO CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	OK	38060		None	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	OK			None	
#1 ENTRY	20.9	0	OK				
#2 ENTRY	20.9	0	OK				
#3 ENTRY	20.9	0	OK				
#4 ENTRY	20.9	0	OK				
#5 ENTRY							
#6 ENTRY							
TRANS/CHARGER							

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe for work and travel

PRE-SHIFT/MINE EXAMINER _____ **Signature** _____ CERT. # 7483
 COUNTER SIGNATURE _____ **Signature** _____ CERT. # 03892
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 1223 06

SECTION/AREA Main West

TIME OF EXAMINATION START 1116 AM PM

END 1227 AM PM

EXAM. CALLED OUT YES NO

CALL OUT TIME 1256 AM PM

CALLED OUT BY B. Allred

REPORT RECEIVED BY Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	37152		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY	20.9	0	0	α		None observed	
#2 ENTRY	20.9	0	0	α		None observed	
#3 ENRTY	20.9	0	0	α		None observed	
#4 ENTRY	20.9	0	0	α		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.9	0	0	α		None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work areas and travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINEE

Signature

CERT. # 9279

COUNTER SIGNATURE

CERT. # 03892

SECTION SUPERVISOR

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 23 06

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 7:03 AM/PM

END 821 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 9:00 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	35,712		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS / CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 7483

COUNTER SIGNATURE

Signature

CERT. # 7488

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-26-06

SECTION/AREA MAIN West

TIME OF EXAMINATION START 4:20 AM/PM

END 4:54 AM/PM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	37,230		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			none observed	
#1 ENTRY	20.9	0	0			none observed	
#2 ENTRY	20.9	0	0			Exposed Bolt 2 cuts In by TRANSFORMER	Damaged off Rebolted 12-26 12:26
#3 ENRTY	20.9	0	0			none observed	
#4 ENTRY	20.9	0	0			none observed	
#5 ENTRY							
#6 ENTRY							

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME
OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINER Signature CERT.# 7375
COUNTER SIGNATURE Signature CERT.# 7462
SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-26-06

SECTION/AREA Main West

TIME OF EXAMINATION START 1202 AM/PM AM

END 1259 AM/PM AM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME _____ AM/PM _____

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE				37116			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None observed	
#1 ENTRY	20.9	0	0			}	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None	
Charger	20.9	0	0			None	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 4802
 COUNTER SIGNATURE **Signature** CERT. # 4735
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-26-06

SECTION/AREA Main West

TIME OF EXAMINATION START 7:00 AM/PM (P)

END 8:09 AM/PM (P)

EXAM. CALLED OUT — (YES)/NO

CALL OUT TIME 9:40 AM/PM (P)

CALLED OUT BY Arty Bolotas

REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	30/20		no obs	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.9	0	0			no obs	
#2 ENTRY	20.9	0	0			no obs	
#3 ENRTY	20.9	0	0			no obs	
#4 ENTRY	20.9	0	0			no obs	
#5 ENTRY							
#6 ENTRY							
TRANS.	20.9	0	0			no obs	
Charger	20.9	0	0			no obs	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS Appered Safe at time of Exam

PRE-SHIFT/MINE EXAMINER **Signature**

CERT.# 8916

COUNTER SIGNATURE **Signature**

CERT.# 4735

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-27-06

SECTION/AREA Main West

TIME OF EXAMINATION START 3:00 AM/PM

END 3:45 AM/PM

EXAM. CALLED OUT — YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0%	OPPN	34450		NONE observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0%	OPPN			NONE observed	
#1 ENTRY	20.9	0%	OPPN			NONE observed	
#2 ENTRY	20.9	0%	OPPN			NONE observed	
#3 ENRTY	20.9	0%	OPPN			NONE observed	
#4 ENTRY	20.9	0%	OPPN			NONE observed	
#5 ENTRY							
#6 ENTRY							
Section doors	20.9	0%	OPPN			NONE observed	
Scoop charger	20.9	0%	OPPN			NONE observed	

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Agents appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER _____ **Signature** _____ CERT.# 7940

COUNTER SIGNATURE _____ **Signature** _____ CERT.# 8462

SECTION SUPERVISOR _____

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-27-06

SECTION/AREA Main West

TIME OF EXAMINATION START 1220 AM/PM

END 158 AM/PM

EXAM. CALLED OUT — YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				36429			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			?	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None	
Charger	20.9	0	0			None	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of spec

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4842

COUNTER SIGNATURE Signature CERT. # 8462

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-27-06 SECTION/AREA West Midlands
 TIME OF EXAMINATION START 700 AM/PM AM END 803 AM/PM AM
 EXAM. CALLED OUT — YES/NO CALL OUT TIME 855 AM/PM AM
 CALLED OUT BY Arturo Bolotas REPORT RECEIVED BY Signature
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	308??		none obs.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.9	0	0			none obs	
#2 ENTRY	20.9	0	0			none obs	
#3 ENRTY	20.9	0	0			none obs	
#4 ENTRY	20.9	0	0			none obs	
#5 ENTRY							
#6 ENTRY							
TRANS	20.9	0	0			none obs	
Charge C	20.9	0	0			none obs	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7916
 COUNTER SIGNATURE Signature CERT. # 8462
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12/28/06

SECTION/AREA Main W

TIME OF EXAMINATION START 321 AM PM

END 444 AM PM

EXAM. CALLED OUT — YES NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____

REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	31070		None ob	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None ob	
#1 ENTRY	20.9	0	0			None ob	
#2 ENTRY	20.9	0	0			None ob	
#3 ENRTY	20.9	0	0			None ob	
#4 ENTRY	20.9	0	0			None ob	
#5 ENTRY							
#6 ENTRY							
Tram-	20.9	0	0			None ob	
Charger	20.9	0	0			None ob	

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS

Sections reasonably safe at
time of exam.

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 896

COUNTER SIGNATURE

Signature

CERT. # 8462

SECTION SUPERVISOR

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-28-06

SECTION/AREA Main West

TIME OF EXAMINATION START 12:25 AM/PM

END 1:06 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 2:00 AM/PM

CALLED OUT BY Jim Hanna

REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	31642		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			None Observed	
#2 ENTRY	20.9	0	0			None Observed	
#3 ENRTY	20.9	0	0			None Observed	
#4 ENTRY	20.9	0	0			None Observed	
#5 ENTRY							
#6 ENTRY							

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature**

CERT.# 45812

COUNTER SIGNATURE **Signature**

CERT.# 4735

SECTION SUPERVISOR

2MSHA02728

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-28-06

SECTION/AREA Main West

TIME OF EXAMINATION START 7:18 AM/PM

END 8:30 AM/PM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	29,925		None	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None	
#1 ENTRY	20.9	0	0			None	
#2 ENTRY	20.9	0	0			None	
#3 ENRTY	20.9	0	0			None	
#4 ENTRY	20.9	0	0			None	
#5 ENTRY							
#6 ENTRY							
Traps.	20.9	0	0			None	
Charger	20.9	0	0			None	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT.# 8912
 COUNTER SIGNATURE Signature CERT.# 4135
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION ~~30~~ 12/29/04

SECTION/AREA Main W.

TIME OF EXAMINATION START 302 AM/PM

END 415 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	38320		Nonech	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			Nonech	
#1 ENTRY	20.9	0	0			Nonech	
#2 ENTRY	20.9	0	0			Nonech	
#3 ENRTY	20.9	0	0			Nonech	
#4 ENTRY	20.9	0	0			Nonech	
#5 ENTRY							
#6 ENTRY							
Tram.	20.9	0	0			Nonech	
Charger	20.9	0	0			Nonech	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at
Time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8916
 COUNTER SIGNATURE Signature CERT. # 9279
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-29-06

SECTION/AREA MAIN West

TIME OF EXAMINATION START 11.10 AM/PM

END 12:15 AM/PM

EXAM. CALLED OUT — YES/ NO

CALL OUT TIME 1:34 AM/PM

CALLED OUT BY DON ERICKSON

REPORT RECEIVED BY Foster McArthur
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	38680		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.8	0	0			None observed	
#2 ENTRY	20.8	0	0			None observed	
#3 ENRTY	20.8	0	0			None observed	
#4 ENTRY	20.8	0	0			None observed	
#5 ENTRY							
#6 ENTRY							
Trans.	20.8	0	0			None observed	
Charger	20.8	0	0			None observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas reported reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 9659

COUNTER SIGNATURE

CERT.# 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 29 06 SECTION/AREA Main West
 TIME OF EXAMINATION START 705 AM/PM (AM) END 742 AM/PM (AM)
 EXAM. CALLED OUT (YES)/NO CALL OUT TIME 9:30 AM/PM (AM)
 CALLED OUT BY DALE BLACK REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	35,376		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS/CHARGER	20.9	0	0			NONE OBSERVED	

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 7483
 COUNTER SIGNATURE **Signature** CERT.# 7485
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 30 06

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 307 AM PM

END 400 AM PM

EXAM. CALLED OUT YES NO

CALL OUT TIME 4:36 AM PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	36500		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS/CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 7483

COUNTER SIGNATURE

CERT.# 7485

SECTION SUPERVISOR

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-30-06

SECTION/AREA Main West

TIME OF EXAMINATION START 11:05 AM PM

END 12:15 AM PM

EXAM. CALLED OUT YES NO

CALL OUT TIME 1:54 AM PM

CALLED OUT BY Don Erickson

REPORT RECEIVED BY Signature
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	38,240		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0			None Observed	
#1 ENTRY	20.8	0	0			None Observed	
#2 ENTRY	20.8	0	0			None Observed	
#3 ENRTY	20.8	0	0			None Observed	
#4 ENTRY	20.8	0	0			None Observed	
#5 ENTRY							
#6 ENTRY							
Trans,	20.8	0	0			None Observed	
Charger	20.8	0	0			None Observed	

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Reported safe at time of exam

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 9659

COUNTER SIGNATURE

CERT.# 9279

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 30 06 SECTION/AREA MAIN WEST
 TIME OF EXAMINATION START 712 AM/PM AM END 800 AM/PM AM
 EXAM. CALLED OUT YES/NO CALL OUT TIME 1020 AM/PM AM
 CALLED OUT BY DALE BLACK REPORT RECEIVED BY **Signature**

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	38,164		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS/CHARGERS	20.9	0	0			NONE OBSERVED	

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 7483
 COUNTER SIGNATURE **Signature** CERT.# 7485
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-31-06

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 400 AM PM

END 504 AM PM

EXAM. CALLED OUT YES NO

CALL OUT TIME 510 AM PM

CALLED OUT BY DAVE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	35,425		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS/CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT
TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 7483

COUNTER SIGNATURE

Signature

CERT.# 9279

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12-31-06

SECTION/AREA West mains

TIME OF EXAMINATION START 11:05 AM/PM

END 12:20 AM/PM

EXAM. CALLED OUT — ~~YES~~ ^{SA} NO

CALL OUT TIME 12:40 AM/PM

CALLED OUT BY Don Erickson REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE	20.8	0	0	37860		None	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0			None	
#1 ENTRY	20.8	0	0			None	
#2 ENTRY	20.8	0	0			None	
#3 ENRTY	20.8	0	0			None	
#4 ENTRY	20.8	0	0			None	
#5 ENTRY							
#6 ENTRY							
charger	20.8	0	0			None	
Tram	20.8	0	0			None	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all area appear safe at time exam

PRE-SHIFT/MINE EXAMINEE Signature

COUNTER SIGNATURE

SECTION SUPERVISOR

CERT. # 9659

CERT. # 9279

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 12 31 06

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 7:05 AM/PM (M)

END 8:36 AM/PM (M)

EXAM. CALLED OUT YES/NO

CALL OUT TIME 8:45 AM/PM (M)

CALLED OUT BY DALE BLACK REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	33,800		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 7483

COUNTER SIGNATURE

Signature

CERT.# 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 1-1-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 305 AM/PM

END 447 AM/PM

EXAM. CALLED OUT — YES/~~NO~~

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	ok	36144		None	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	ok			None	
#1 ENTRY	20.9	0	ok			S	
#2 ENTRY	20.9	0	ok				
#3 ENRTY	20.9	0	ok				
#4 ENTRY	20.9	0	ok				
#5 ENTRY							
#6 ENTRY							
Trans	20.9	0	ok			None	

V= VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Section appeared safe
at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT.# 7483
 COUNTER SIGNATURE Signature CERT.# 4735
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 1-1-07

SECTION/AREA Main West

TIME OF EXAMINATION START 11:35 AM/PM

END 103 AM/PM

EXAM. CALLED OUT — YES / NO

CALL OUT TIME 122 AM/PM

CALLED OUT BY Arty Bolotas

REPORT RECEIVED BY Signature

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	23765		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY	20.9					none observed	
#2 ENTRY	20.9					none observed	
#3 ENTRY	20.9					none observed	
#4 ENTRY	20.9					none observed	
#5 ENTRY							
#6 ENTRY							
TRANS.	20.9					none observed	
Chargers	20.9					none observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS

Areas beyond Scope of Exam

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 8914

COUNTER SIGNATURE

Signature

CERT.# 8462

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 1-1-07

SECTION/AREA MAIN west

TIME OF EXAMINATION START 7:07 AM/PM AM

END 7:55 AM/PM AM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME 9:05 AM/PM AM

CALLED OUT BY Jim HANNA

REPORT RECEIVED BY **Signature**

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	38,782		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			none observed	
#1 ENTRY	20.9	0	0			none observed	
#2 ENTRY	20.9	0	0			none observed	
#3 ENRTY	20.9	0	0			none observed	
#4 ENTRY	20.9	0	0			none observed	
#5 ENTRY							
#6 ENTRY							
TRANSFORMER	20.9	0	0			none observed	
CHARGER	20.9	0	0			none observed	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS

Section appeared reasonably safe
at time of pre-shift

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 4842

COUNTER SIGNATURE

CERT. # 8462

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 1-2-07

SECTION/AREA Main West

TIME OF EXAMINATION START 300 AM/PM

END 457 AM/PM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				37914			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			?	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None	
Charger	20.9	0	0			None	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER

COUNTER SIGNATURE

SECTION SUPERVISOR

Signature
Signature

CERT. # 4842

CERT. # 4735

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 1-2-07

SECTION/AREA Main West

TIME OF EXAMINATION START 1130 AM/PM

END 114 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 1:58 AM/PM

CALLED OUT BY Art Bolot's

REPORT RECEIVED BY **Signature**
SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				<u>35658</u>			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	<u>20.9</u>	<u>0</u>	<u>0</u>			<u>None</u>	
#1 ENTRY	<u>20.9</u>	<u>0</u>	<u>0</u>			<u>None</u>	
#2 ENTRY	<u>20.9</u>	<u>0</u>	<u>0</u>			<u>None</u>	
#3 ENRTY	<u>20.9</u>	<u>0</u>	<u>0</u>			<u>None</u>	
#4 ENTRY	<u>20.9</u>	<u>0</u>	<u>0</u>			<u>None</u>	
#5 ENTRY							
#6 ENTRY							
<u>TRANS.</u>	<u>20.9</u>					<u>None</u>	
<u>Charger</u>	<u>20.9</u>					<u>None</u>	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 8916
 COUNTER SIGNATURE **Signature** CERT.# 8462
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 1-2-07
 TIME OF EXAMINATION START 203 AM/PM
 EXAM. CALLED OUT — YES/NO NO
 CALLED OUT BY _____

SECTION/AREA Main West
 END 806 AM/PM
 CALL OUT TIME _____ AM/PM
 REPORT RECEIVED BY _____
 SIGNATURE _____

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				33422			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			<i>None Observed</i>	
#1 ENTRY	20.9	0	0			7	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
<i>Transformer</i>	20.9	0	0			<i>None</i>	
<i>Charger</i>	20.9	0	0			<i>None</i>	

V = VIOLATION
 H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8462
 COUNTER SIGNATURE Signature CERT. # 8462
 SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 1-3-07

SECTION/AREA Main West

TIME OF EXAMINATION START 300 (AM/PM)

END 420 (AM/PM)

EXAM. CALLED OUT — YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				32618			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			?	
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
TRANSFORMER	20.9	0	0			None	
CHARGER	20.9	0	0			None	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** _____ CERT.# 4842

COUNTER SIGNATURE **Signature** _____ CERT.# 4435

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 1-3-07

SECTION/AREA Main West

TIME OF EXAMINATION START 11:35 AM/PM

END 1:10 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 1:42 AM/PM

CALLED OUT BY Andy Bobotas

REPORT RECEIVED BY

Signature

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				3070			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None obs	
#1 ENTRY	20.9	0	0			None obs	
#2 ENTRY	20.9	0	0			None obs	
#3 ENRTY	20.1	0	0			None obs	
#4 ENTRY	20.9	0	0			None obs	
#5 ENTRY							
#6 ENTRY							
Truss	20.9	0	0			None obs	
chargers	20.9	0	0				

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at this time

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 8916

COUNTER SIGNATURE

SECTION SUPERVISOR

CERT. # 8462

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 1-3-07

SECTION/AREA Mine West

TIME OF EXAMINATION START 800 AM/PM

END 853 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				31422			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None Observed	
#1 ENTRY	20.9	0	0			?	
#2 ENTRY	20.9	0	0				
#3 ENTRY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
TRANSFORMER	20.9	0	0			None	
CHARGER	20.9	0	0			None	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 21872

COUNTER SIGNATURE Signature CERT. # 8462

SECTION SUPERVISOR _____

PRE-SHIFT SECTIONS

DATE OF EXAMINATION 1-4-07

SECTION/AREA Main West

TIME OF EXAMINATION START 305 AM/PM

END 510 AM/PM

EXAM. CALLED OUT — YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE

LOCATIONS	O ₂	CH ₄ %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE				30768			
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			7	
#1 ENTRY	20.9	0	0				
#2 ENTRY	20.9	0	0				
#3 ENRTY	20.9	0	0				
#4 ENTRY	20.9	0	0				
#5 ENTRY							
#6 ENTRY							
Transformer	20.9	0	0			None	
Charger	20.9	0	0			None	

V = VIOLATION
H = HAZARD

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4842
 COUNTER SIGNATURE Signature CERT. # 4185
 SECTION SUPERVISOR _____

INITIALS (NOT REQUIRED)

2MSHA02749