

✓

# PRESHIFT/ON-SHIFT REPORT FOR GENERAL MINE

---

**GENWAL**

---

**Mine Name**

---

**ID Number**

---

*GRANDALL MINE*

---

**SECTION / AREA**

2MSHA03178

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-1-07 SECTION/AREA Em Mine 1

TIME OF EXAMINATION START 11:40 AM/PM (AM) END 1:15 AM/PM (AM) Examiners Initials KK  
 TIME OF EXAMINATION START 1:00 AM/PM (AM) END 1:30 AM/PM (AM) Examiners Initials RL/RR  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT \_\_\_\_\_ YES/NO CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. North seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. West haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/RR</u>	<u>OK</u>	<u>none observed</u>	
<u>storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none observed</u>	
<u>washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>3rd north</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>1st right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL/RR</u>	<u>OK</u>	<u>none</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/RR</u>	<u>OK</u>	<u>none</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

Signature

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 4954  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 6401  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 4375  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-1-02

SECTION/AREA Gen. mine

TIME OF EXAMINATION START 2:00  
 TIME OF EXAMINATION START 700  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM AM END 2:25 AM/PM PM  
 AM/PM AM END 710 AM/PM PM  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials PL  
 Examiners Initials DD  
 Examiners Initials MC

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	ok	None Observed	
main North haulage seals	20.9	0	0	PC	ok	None observed	
Main West haulage seals	20.9	0	0	DD/mc	ok	none observed	
3rd North	20.9	0	0	DD/mc	ok	none observed	
1st Right	20.9	0	0	DD/mc	ok	none observed	
Transformers	20.9	0	0	DD/mc	ok	none observed	
chargers	20.9	0	0	DD/mc	ok	none observed	
wash down	20.9	0	0	mc	ok	none observed	
Storage area	20.9	0	0	DD	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

PRE-SHIFT/MINE EXAMINE Signature

CERT. # 8058  
 CERT. # 2325  
 CERT. # 8462  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature

CERT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-2-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 3:00 AM/PM END 3:28 AM/PM Examiners Initials PC  
 TIME OF EXAMINATION START 3:00 AM/PM END 5:25 AM/PM Examiners Initials DD/mc  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>OK</u>	<u>None Observed</u>	
<u>main north seals Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>OK</u>	<u>None Observed</u>	
<u>main West seals haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/mc</u>	<u>OK</u>	<u>none obs.</u>	
<u>3rd North</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/mc</u>	<u>OK</u>	<u>none obs.</u>	
<u>1st right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/mc</u>	<u>OK</u>	<u>none obs.</u>	
<u>transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/mc</u>	<u>OK</u>	<u>none obs.</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/mc</u>	<u>OK</u>	<u>none obs.</u>	
<u>Wash down</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>OK</u>	<u>none obs.</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>OK</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe At time of exam.

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 8462  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4935

2MSHA03181

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-2-07

SECTION/AREA Gen Area 1

TIME OF EXAMINATION START 11:00 (AM)/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1:20 AM/(PM)  
 END \_\_\_\_\_ AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KK/RL  
 Examiners Initials \_\_\_\_\_  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parting area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>M. North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>M. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none obs</u>	
<u>Over</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>none</u>	
<u>charges</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>		<u>none</u>	
<u>3' <sup>up</sup> north</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none observed</u>	
<u>8' 5" <sup>up</sup> right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none observed</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

All areas appeared safe  
at time of exam

Signature

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 7954  
 CERT. # 6401  
 CERT. # 4323  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR

CERT. # 8962

2MSHA03182

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-2-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7:00 AM/PM  
 TIME OF EXAMINATION START 7:25 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 2:36 AM/PM  
 END 8:59 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials PC  
 Examiners Initials MC/DD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Seals Haulage	20.9	0	0	PC	OK	None Observed	
Main North	20.9	0	0	MC/DD	OK	None observed	
Seals Haulage	20.9	0	0	MC/DD	OK	None observed	
Main West	20.9	0	0	MC/DD	OK	None observed	
3 <sup>rd</sup> North	20.9	0	0	MC/DD	OK	None observed	
1 <sup>st</sup> Right	20.9	0	0	MC	OK	None observed	
transformers	20.9	0	0	MC/DD	OK	None observed	
chargers	20.9	0	0	MC	OK	None observed	
Storage area	20.9	0	0	MC	OK	None observed	
Wash down	20.9	0	0	MC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe  
AT Time of pre-shift

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 8462  
 CERT. # 7375  
 CERT. # 8058  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR

CERT. # 8462

2MSHA03183

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-3-07

SECTION/AREA Ben. Mine

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 3:20 AM/PM  
START 300 AM/PM  
START \_\_\_\_\_ AM/PM

END 3:50 AM/PM  
END 530 AM/PM  
END \_\_\_\_\_ AM/PM

Examiners Initials pc  
Examiners Initials DD me  
Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	pc	ok	None Observed	
Main North <sup>Haulage</sup> seals	20.9	0	0	pc	ok	None Observed	
Main West <sup>Haulage</sup> seals	20.9	0	0	DD/me	ok	none obs.	
3 <sup>rd</sup> North	20.9	0	0	DD/me	ok	none obs.	
1 <sup>st</sup> Right	20.9	0	0	DD	ok	none obs.	
Storage area	20.9	0	0	DD	ok	none obs.	
Transformers	20.9	0	0	DD/me	ok	none obs.	
Chargers	20.9	0	0	DD	ok	none obs.	
Wash down	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe  
At time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMIN  
PRE-SHIFT/MINE EXAMIN  
PRE-SHIFT/MINE EXAMIN  
PRE-SHIFT/MINE EXAMIN

CERT. # 8462  
CERT. # 8058  
CERT. # 7375  
CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATUR

CERT. # 7485

2MSHA03184

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-3-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 11:10 AM/PM  
 TIME OF EXAMINATION START 11:33 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 12:47 AM/PM  
 END 12:38 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials SW  
 Examiners Initials FM  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
Main North haulage <sup>SLAB</sup>	20.9	0	0	FM	OK	none observed	
Main West haulage <sup>SLAB</sup>	21.0	0	0	<del>FM</del> SW	OK	Life line a part cut 1/4	repaired 4-3-07 SW
3rd North	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	<del>FM</del> SW	OK	none observed	
Chargers	21.0	0	0	SW	OK	none observed	
Wash down	21.0	0	0	SW	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
Main South	no cap on battery	replaced cap.

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 9548  
 CERT. # 8897  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 7485

2MSHA03185

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-3-07

SECTION/AREA Gen mine 1 1

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 8:41 AM/PM  
START 8:15 AM/PM  
START \_\_\_\_\_ AM/PM

END 9:01 AM/PM  
END 9:02 AM/PM  
END \_\_\_\_\_ AM/PM

Examiners Initials BH  
Examiners Initials R  
Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage Seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH	OK	None Observed	
3 <sup>rd</sup> North Haulage Seals	20.9	0	0	BH	OK	None Observed	
1 <sup>st</sup> Right Haulage	20.9	0	0	BH	OK	None observed	
Storage Area	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None observed	
Chargers	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 8395  
CERT. # 9362  
CERT. # \_\_\_\_\_  
CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature

CERT. # 03892

2MSHA03186

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-4-07

SECTION/AREA Gen M. 1

TIME OF EXAMINATION START 4:15 AM/PM  
 TIME OF EXAMINATION START 4:20 AM/PM  
 TIME OF EXAMINATION START 3:40 AM/PM

END 5:00 AM/PM  
 END 3:10 AM/PM  
 END 5:15 AM/PM

Examiners Initials TC  
 Examiners Initials BP  
 Examiners Initials BH

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>none obs.</u>	
<u>Main North Amalgam &amp; seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>none obs.</u>	
<u>Main West Amalgam Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u> <u>BP</u>	<u>OK</u>	<u>none obs.</u>	
<u>3rd North Amalgam Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>none obs.</u>	
<u>1st Right Amalgam</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>none obs.</u>	
<u>Storage Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>none obs.</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u> <u>BP</u>	<u>OK</u>	<u>none obs.</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u> <u>BP</u>	<u>OK</u>	<u>none obs.</u>	
<u>Wash Down</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>none obs.</u>	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe  
At time of EIA

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_

CERT. # 9362  
 CERT. # 9399  
 CERT. # 8385  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 7485

2MSHA03187

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-4-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 11:45 AM/PM  
 TIME OF EXAMINATION START 11:45 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 12:50 AM/PM  
 END 1:20 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials SW  
 Examiners Initials dy  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage <sup>SLATS</sup>	21.0	0	0	SW	OK	none observed	
Main West haulage <sup>SLATS</sup>	21.0	0	0	<del>SW</del> dy	OK	none observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	<del>SW</del> dy	OK	none observed	
Chargers	21.0	0	0	<del>SW</del> dy	OK	none observed	
Washdown	21.0	0	0	dy	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
3rd North	tripping hazard	removed

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINE CERT. # 9548  
 PRE-SHIFT/MINE EXAMINE CERT. # 6622  
 PRE-SHIFT/MINE EXAMINE CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_  
 Signature \_\_\_\_\_  
 CERT. # 7483

2MSHA03188

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-4-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 9:15 AM/PM AM END 9:55 AM/PM PM Examiners Initials TC  
 TIME OF EXAMINATION START 8:03 AM/PM PM END 8:30 AM/PM PM Examiners Initials BP  
 TIME OF EXAMINATION START 7:47 AM/PM PM END 7:06 AM/PM PM Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None observed	
Main north Haulage seals	20.9	0	0	BH	OK	None observed	
Main West Haulage seals	20.9	0	0	TC/BP BH	OK	None observed	
3rd North Haulage seals	20.9	0	0	BH	OK	None observed	
1st Right Haulage	20.9	0	0	BH	OK	None observed	
Storage Area	20.9	0	0	BH	OK	None observed	
Washdown	20.9	0	0	BH	OK	None observed	
Chargers	20.9	0	0	BP/BH	OK	None obs.	
Transformers	20.9	0	0	BP/BH	OK	None obs.	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
XCBH Main West	Machine Door <del>open</del>	
	Blocked open	Moved block closed door

PRE-SHIFT REMARKS All acca's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 9362  
 CERT. # 2599  
 CERT. # 8345  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 03892

2MSHA03189

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION ~~4-5-07~~ 4-5-07 SECTION/AREA Gen 1 main 1

TIME OF EXAMINATION START 4:02 AM/PM END 4:40 AM/PM Examiners Initials TC  
 TIME OF EXAMINATION START 3:43 AM/PM END 5:18 AM/PM Examiners Initials BH  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO \_\_\_\_\_ CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None obs.	
Seals main North Haalage	20.9	0	0	BH	OK	None obs.	
Seals Malawcaat Haalage	20.9	0	0	TC/BH	OK	None obs.	
3rd North Haalage	20.9	0	0	BH	OK	None obs.	
1st Right	20.9	0	0	BH	OK	None obs.	
Storage Area	20.9	0	0	BH	OK	None obs.	
Transformer	20.9	0	0	TC/BH	OK	None obs.	
Changest	20.9	0	0	TC/BH	OK	None obs.	
washdown	20.9	0	0	BH	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
3 North	Getting gray	Bulk dusted it

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 9362  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8395  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ RT. # 7480  
 Signature \_\_\_\_\_

2MSHA03190

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/9/07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 12:45 AM/PM AM END 1:05 AM/PM PM Examiners Initials FM  
 TIME OF EXAMINATION START 11:47 AM/PM AM END 1:13 AM/PM PM Examiners Initials FM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	FM	OK	none observed	
<sup>NORTH</sup> Mainseals	20.9	0	0	FM	OK	none observed	
Seals Pumps Mainwest Haulage	21.	0	.1	<del>FM</del>	OK	none observed	
3rd No Haulage	20.9	0	0	FM	OK	none observed	
1st Right	20.9	0	0	FM	OK	none observed	
Storage areas	20.9	0	0	FM	OK	none observed	
Transformers	21.	0	0	<del>FM</del>	OK	none observed	
chargers	21.	0	0	<del>FM</del>	OK	none observed	
washdown	20.9	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINI \_\_\_\_\_ CERT. # 6622  
 PRE-SHIFT/MINE EXAMINI \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINI \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINI \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR \_\_\_\_\_ CERT. # 7485

2MSHA03191

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-5-07

SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 8:15  
 TIME OF EXAMINATION START 7:45  
 TIME OF EXAMINATION START 8:01

AM/PM AM END 8:45 AM/PM  
 AM/PM AM END 7:12 AM/PM  
 AM/PM AM END 8:28 AM/PM

Examiners Initials TC  
 Examiners Initials BH  
 Examiners Initials BP

EXAM. CALLED OUT ---- YES  NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	none observed	
Main North Haulage seals	20.9	0	0	BH	OK	none obs.	
Main West Haulage seals	20.9	0	0	TC/BP BH	OK	none obs.	
3rd North Haulage	20.9	0	0	BH	OK	none obs	
15th Right Haulage	20.9	0	0	BH	OK	none obs.	
Storage Area	20.9	0	0	BH	OK	none observed	
Transformers	20.9	0	0	TC/AS BH	OK	none obs.	
Chargers	20.9	0	0	TC/BP BH	OK	none obs	
Wash Down	20.9	0	0	BH	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
cut 108	Trash accumulations	Cleared
Main West		

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINEE Signature

CERT. # 9362  
 CERT. # 8395  
 CERT. # 6399  
 CERT. # \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
Signature

COUNTER SIGNATURE

CERT. # 03892

2MSHA03192

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-6-07 SECTION/AREA General Mine 1

TIME OF EXAMINATION START 4:15 AM/PM END 4:40 AM/PM Examiners Initials TZ  
 TIME OF EXAMINATION START 3:50 AM/PM END 5:17 AM/PM Examiners Initials BH  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO \_\_\_\_\_ CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage & seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage & seals	20.9	0	0	<sup>BH</sup> TZ/BH	OK	None obs.	
3rd North Haulage & seals	20.9	0	0	BH	OK	None Observed	
1st Right Haulage	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	
Transducers	20.9	0	0	<sup>BH</sup> TZ/BH	OK	None obs.	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
M. West 110 to 103	Feeling gray	Bulk dusted

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINE CERT. # 9362  
 PRE-SHIFT/MINE EXAMINE CERT. # 8395  
 PRE-SHIFT/MINE EXAMINE CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINE CERT. # \_\_\_\_\_

COUNTER SIGNATURE **Signature** CERT. # 7485

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-6-07

SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 11:00 AM/PM  
 TIME OF EXAMINATION START 11:00 AM/PM  
 TIME OF EXAMINATION START 12:50 AM/PM

END 12:10 AM/PM  
 END 1:10 AM/PM  
 END 1:10 AM/PM

Examiners Initials JG  
 Examiners Initials SW  
 Examiners Initials dy

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	21.0	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	21.0	0	0	SW	OK	none observed	
MAIN WEST HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
UNDERGROUND STORAGE	20.9	0	0	JG	OK	NONE OBSERVED	
WASH DOWN	20.9	0	0	JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	21.0	0	0	JG	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS TRAVELED REASONABLY SAFE AT TIME OF EXAMINATION

**Signature**

PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE

CERT. # 7485  
 CERT. # 9548  
 CERT. # 6622  
 CERT. # \_\_\_\_\_

**Signature**

COUNTER SIGNATURE

CERT. # 7485

2MSHA03194

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/6/07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 8:10 AM/PM AM END 8:42 AM/PM PM Examiners Initials GA  
 TIME OF EXAMINATION START 7:00 AM/PM AM END 9:30 AM/PM PM Examiners Initials BH  
 TIME OF EXAMINATION START 7:30 AM/PM AM END 8:30 AM/PM PM Examiners Initials BP

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking area</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>GA</u>	<u>OK</u>	<u>None observed</u>	
<u>3rd No. 4 Haulage</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>GA</u>	<u>OK</u>	<u>None observed</u>	
<u>1st R/H Haulage</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>GA</u>	<u>OK</u>	<u>None observed</u>	
<u>Main North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>None Observed</u>	
<u>Storage Area's</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/BP</u>	<u>OK</u>	<u>None observed</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/BP</u>	<u>OK</u>	<u>None observed</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/BP</u>	<u>OK</u>	<u>None Observed</u>	
<u>washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>None Observed</u>	
<u>Main West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/BP</u>	<u>OK</u>	<u>None Observed</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE CERT. # 03892  
 PRE-SHIFT/MINE EXAMINEE CERT. # 8395  
 PRE-SHIFT/MINE EXAMINEE CERT. # 9599  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE CERT. # 03892

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4707 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 3:50 AM/PM END 4:40 AM/PM Examiners Initials CA  
 TIME OF EXAMINATION START 3:26 AM/PM END 5:20 AM/PM Examiners Initials BY  
 TIME OF EXAMINATION START 3:00 AM/PM END 3:30 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CA	OK	None observed	
3rd No Haulage seals	20.9	0	0	CA	OK	None observed	
1st Rt Haulage	20.9	0	0	CA	OK	None observed	
Main North Haulage seals	20.9	0	0	BP	OK	None Observed	
Main West Haulage seals	20.9	0	0	BH/BP	OK	None Observed	
Transformers	20.9	0	0	BH/BP	OK	None Observed	
Chargers	20.9	0	0	BH/BP	OK	None Observed	
Washdown	20.9	0	0	BP	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 93892  
 PRE-SHIFT/MINE EXAMINER CERT. # 6385  
 PRE-SHIFT/MINE EXAMINER CERT. # 9399  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 7488

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-7-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 11:50 AM/PM  
 TIME OF EXAMINATION START 11:50 AM/PM  
 TIME OF EXAMINATION START 11:50 AM/PM

END 12:52 AM/PM  
 END 1:00 AM/PM  
 END 1:00 AM/PM

Examiners Initials SW  
 Examiners Initials dy  
 Examiners Initials dy

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area.	21.0	0	0	SW	OK	none observed	
3rd North <sup>haulage</sup> SEALS	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Main North <sup>haulage</sup> SEALS	21.0	0	0	SW	OK	none observed	
Main West <sup>haulage</sup> SEALS	21.0	0	0	<del>SW</del> dy	OK	None observed	
Transformers	21.0	0	0	<del>SW</del> dy	OK	None observed	
chargers	21.0	0	0	<del>SW</del> dy	OK	None observed	
wash down	21.0	0	0	dy	OK	None observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 9548  
 PRE-SHIFT/MINE EXAMINEE CERT. # 6622  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7488

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/7/07 SECTION/AREA Gen Mine | |

TIME OF EXAMINATION START 8:00 AM/PM AM/PM END 8:52 AM/PM AM/PM Examiners Initials GA  
 TIME OF EXAMINATION START 7:00 AM/PM AM/PM END 8:15 AM/PM AM/PM Examiners Initials BH  
 TIME OF EXAMINATION START 7:43 AM/PM AM/PM END 8:20 AM/PM AM/PM Examiners Initials BP

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE  
 CALLED OUT BY \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	GA	OK	None observed	
3rd No. Haulage <i>Seals</i>	20.9	0	0	GA	OK	None observed	
1st Rt Haulage	20.9	0	0	GA	OK	None observed	
Main North Haulage <i>Seals</i>	20.9	0	0	BH	OK	None Observed	
Main West Haulage <i>Seals</i>	20.9	0	0	BH/BP	OK	None observed	
Transformers	20.9	0	0	BH/BP	OK	None observed	
Chargers	20.9	0	0	BH/BP	OK	None observed	
Washdown	20.9	0	0	BH	OK	None observed	
Storage Areas	20.9	0	0	BP	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 03892  
 PRE-SHIFT/MINE EXAMINER CERT. # 8385  
 PRE-SHIFT/MINE EXAMINER CERT. # 9589  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ ERT. # 03892 2MSHA03198

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-9-07 SECTION/AREA Gen 1 Mine 1 1

TIME OF EXAMINATION START 3:05 AM/PM END 4:15 AM/PM Examiners Initials RM  
 TIME OF EXAMINATION START 4:30 AM/PM END 5:45 AM/PM Examiners Initials RC  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
U.G. Parking	20.9	0	0	RM	OK	none observed	
MAIN North haulage seals	20.9	0	0	<del>RM</del> RL	OK	none observed	
MAN West haulage seals	20.9	0	0	<del>RM</del>	OK	none observed	
Washdown	20.9	0	0	RM	OK	none observed	
3rd North haulage seals	20.9	0	0	RL	OK	none observed	
1st Right haulage seals	20.9	0	0	RL	OK	none observed	
Transformers	20.9	0	0	RM	OK	none observed	
Chargers	20.9	0	0	<del>RM</del> RL	OK	none observed	
Storage Areas	20.9	0	0	RM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exams.

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ **Signature** CERT. # 6845  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9379  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6401  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE **Signature** CERT. # 9385

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-9-07

SECTION/AREA Gen Mining

TIME OF EXAMINATION START 11:00 AM/PM  
 TIME OF EXAMINATION START 11:48 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1:00 AM/PM  
 END 12:58 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KM LR  
 Examiners Initials FM  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	FM	OK	none observed	
3 <sup>rd</sup> North haulage	20.9	0	0	FM	OK	none observed	
1 <sup>st</sup> Right haulage	20.9	0	0	FM	OK	none observed	
Main North <sup>haulage</sup> seals	20.9	0	0	FM	OK	none observed	
Main West <sup>haulage</sup> seals	20.9	0	0	LR FM	OK	None obs.	
Treas.	20.9	0	0	LR FM	OK	None obs.	
Chargers	20.9	0	0	FM	OK	none observed	
Wash down	20.9	0	0	FM	OK	none observed	
Storage Area	20.9	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of exam

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE CERT. # 9329  
 PRE-SHIFT/MINE EXAMINEE CERT. # 4325  
 PRE-SHIFT/MINE EXAMINEE CERT. # 6297  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_

Signature \_\_\_\_\_  
 COUNTER SIGNATURE CERT. # 9388

2MSHA03200

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-9-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7:00 AM/PM AM END 9:13 AM/PM PM Examiners Initials KK/MC  
 TIME OF EXAMINATION START 7:00 AM/PM AM END 8:00 AM/PM PM Examiners Initials KK  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO \_\_\_\_\_ CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	DD	OK	none obs.	
M. North Haulage	20.9	0	0	DD	OK	none obs.	
M West Haulage	20.9	0	0	KK/MC	OK	None obs.	
3 <sup>rd</sup> North Haulage	20.9	0	0	KK	OK	none obs.	
1 <sup>st</sup> North Haulage	20.9	0	0	KK	OK	none obs.	
Trucks	20.9	0	0	KK/MC	OK	none obs.	
chargers	20.9	0	0	KK/MC	OK	none obs.	
Storage area	20.9	0	0	KK	OK	none obs.	
Washdown	20.9	0	0	KK	OK	none obs.	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7954  
 PRE-SHIFT/MINE EXAMINER CERT. # 7375  
 PRE-SHIFT/MINE EXAMINER CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-10-07

SECTION/AREA Gem Mine 1

TIME OF EXAMINATION START 3:00 AM/PM  
 TIME OF EXAMINATION START 3:02 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 5:00 AM/PM  
 END 525 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials MS  
 Examiners Initials TA  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	KK	OK	none obs	
MAIN NORTH Haulage Seal	20.9	0	0	KK	OK	none obs	
MAIN WEST Haulage Seal	20.9	0	0	mc	OK	none observed	
3RD NORTH Haulage	20.9	0	0	mc	OK	none observed	
1st Right Haulage	20.9	0	0	mc	OK	none observed	
TRANSFORMERS	20.9	0	0	mc	OK	none observed	
CHARGERS	20.9	0	0	mc	OK	none observed	
WASH DOWN	20.9	0	0	mc	OK	none observed	
STORAGE AREA	20.9	0	0	mc	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7954  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8925

2MSHA03202

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-10-07 SECTION/AREA Con Mine 1

TIME OF EXAMINATION START 11:10 AM/PM END 12:40 AM/PM Examiners Initials RL  
 TIME OF EXAMINATION START 11:46 AM/PM END 12:40 AM/PM Examiners Initials FM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
Main North Haulage Road	20.9	0	0	FM	OK	None observed	
Main West Haulage Road	20.9	0	0	RL/FM	OK	None observed	
3rd North Haulage	20.9	0	0	RL	OK	none	
Int Right Haulage	20.9	0	0	RL	OK	none	
Transformers	20.9	0	0	RL/FM	OK	None observed	
Charger	20.9	0	0	RL	OK	none	
Workdown	20.9	0	0	RL	OK	none	
Storage	20.9	0	0	RL	OK	None observed	
Kitchen	20.9	0	0	FM	OK	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 6401  
 PRE-SHIFT/MINE EXAMINEE CERT. # 8297  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 9385

2MSHA03203

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-10-07

SECTION/AREA Gen Mining

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 7:00 AM/PM  
START 7:55 AM/PM  
START \_\_\_\_\_ AM/PM

END 8:33 AM/PM  
END 8:38 AM/PM  
END \_\_\_\_\_ AM/PM

Examiners Initials MC  
Examiners Initials KK  
Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	KK	OK	none obs	
MAIN NORTH Haulage Seals	21.0	0	0	KK	OK	none obs.	
MAIN WEST Haulage Seals	20.9	0	0	MC	OK	none observed	
3RD NORTH Haulage	20.9	0	0	MC	OK	none observed	
1ST RIGHT Haulage	20.9	0	0	MC	OK	none observed	
TRANSFORMERS	20.9	0	0	MC	OK	none observed	
CHARGERS	20.9	0	0	MC	OK	none observed	
UPCHDOWN	20.9	0	0	MC	OK	none observed	
STORAGE AREA	20.9	0	0	MC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

AREAS APPEARED REASONABLY  
SAFE AT TIME OF PRE-SHIFT

Signature

PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER

— CERT. # 7375  
— CERT. # 7954  
— CERT. # \_\_\_\_\_  
— CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 9385

2MSHA03204

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-11-07

SECTION/AREA Gen Mtn 1

TIME OF EXAMINATION START 3:00 AM/PM  
 TIME OF EXAMINATION START 3:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 5:40 AM/PM  
 END 5:47 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KK/AD  
 Examiners Initials mc  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>mc</u>	<u>ok</u>	<u>none observed</u>	
<u>N. North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>mc</u>	<u>ok</u>	<u>none observed</u>	
<u>N. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/AD</u>	<u>ok</u>	<u>none obs.</u>	
<u>3' north</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/AD</u>	<u>ok</u>	<u>none obs</u>	
<u>1' right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>AD</u>	<u>ok</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/AD</u>	<u>ok</u>	<u>none obs</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>AD</u>	<u>ok</u>	<u>none obs</u>	
<u>Trams</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/AD/mc</u>	<u>ok</u>	<u>none obs</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/AD</u>	<u>ok</u>	<u>none obs.</u>	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM  
 \_\_\_\_\_  
 Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7954  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7325  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03205

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-11-07

SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:00 ~~AM~~/PM  
 TIME OF EXAMINATION START 11:00 ~~AM~~/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 12:18 AM/~~PM~~  
 END 1:20 AM/~~PM~~  
 END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials LR/AM  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	209	0	0	FM	OK	none observed	
Main North haulage seals	209	0	0	FM	OK	none observed	
Main West haulage seals	209	0	0	<del>FM</del> LR	OK	None observed	
3 <sup>rd</sup> North haulage	209	0	0	FM	OK	none observed	
1st Right	209	0	0	FM	OK	none observed	
Transformers	209	0	0	<del>FM</del> LR/AM	OK	None observed	
Chargers	209	0	0	<del>FM</del> LR	OK	None observed	
Washdown	209	0	0	FM	OK	none observed	
Storage Area	209	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE

CERT. # 8297  
 CERT. # 4375  
 CERT. # 9379  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 9385

2MSHA03206

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-11-07

SECTION/AREA Gen Mnd 1

TIME OF EXAMINATION START 7:02 AM/PM AM  
 TIME OF EXAMINATION START 7:00 AM/PM AM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_

END 7:30 AM/PM AM  
 END 9:20 AM/PM AM  
 END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials KK  
 Examiners Initials DD mc  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_

CALLED OUT BY \_\_\_\_\_

CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>ok</u>	<u>none observed</u>	
<u>m. North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>ok</u>	<u>none observed</u>	
<u>M. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/mc</u>	<u>ok</u>	<u>none obs.</u>	
<u>3rd North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	
<u>1st Right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	
<u>Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/mc</u>	<u>ok</u>	<u>none obs.</u>	
<u>chairs</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/mc</u>	<u>ok</u>	<u>none obs.</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>mc</u>	<u>ok</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 7954  
 CERT. # 8054  
 CERT. # 7375  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATUR \_\_\_\_\_

CERT. # 8462

2MSHA03207

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-18-07 SECTION/AREA Gen Mgmt

TIME OF EXAMINATION START 3:00 AM/PM END 5:30 AM/PM Examiners Initials KK/ML  
 TIME OF EXAMINATION START 3:00 AM/PM END 4:00 AM/PM Examiners Initials DD  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.8</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs</u>	
<u>Midwest Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	
<u>Midwest Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/ML</u>	<u>ok</u>	<u>none obs</u>	
<u>3rd north</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/ML</u>	<u>ok</u>	<u>none obs.</u>	
<u>1st right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>ok</u>	<u>none obs.</u>	
<u>Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/ML</u>	<u>ok</u>	<u>none obs.</u>	
<u>charger</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/ML</u>	<u>ok</u>	<u>none obs.</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>ok</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/ML</u>	<u>ok</u>	<u>none obs</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7954  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 2375  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # 9385

2MSHA03208

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-12-07 SECTION/AREA Gen Air 1 1

TIME OF EXAMINATION START 11:00 ~~AM~~/PM END 1:15 AM/~~PM~~  
 TIME OF EXAMINATION START 11:00 ~~AM~~/PM END 1:25 AM/~~PM~~  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

Examiners Initials LR/KM  
 Examiners Initials RC  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	RL	OK	none observed	
1st North Haulage seals	20.9	0	0	R/LR/KM	OK	None obs.	
3rd North	20.9	0	0	RL	OK	none observed	
1st Right	20.9	0	0	RL	OK	none	
TUNNS.	20.9	0	0	R/LR/KM	OK	None obs.	
Charger	20.9	0	0	R/LR/KM	OK	none obs	
Washdown	20.9	0	0	RL	OK	none	
Storage Area	20.9	0	0	RL	OK	none	
Main West Haulage seals	20.9	0	0	R/LR/KM	OK	None obs	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINE Signature CERT. # 4375  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # 4379  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # 6401  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 9385

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-12-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 7:00  
 TIME OF EXAMINATION START 7:30  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM AM END 2:35 AM/PM PM  
 AM/PM AM END 9:10 AM/PM PM  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials PC  
 Examiners Initials PCMC  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North <sup>Haulage seals</sup>	20.9	0	0	PC	OK	None Observed	
Main West <sup>Haulage seals</sup>	20.9	0	0	MC/DD	OK	None Observed	
3rd North Haulage	20.9	0	0	MC/DD	OK	None Observed	
1st Right	20.9	0	0	MC	OK	None Observed	
Transformers	20.9	0	0	MC/DD	OK	None Observed	
Chargers	20.9	0	0	MC/DD	OK	None Observed	
Wash down	20.9	0	0	MC	OK	None Observed	
Storage area	20.9	0	0	DD	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe  
at time of pre shift

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 8462  
 CERT. # 7375  
 CERT. # 8058  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 8462

2MSHA03210

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-13-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 3:05 ~~AM~~/PM  
 TIME OF EXAMINATION START 300 ~~AM~~/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 3:45 ~~AM~~/PM  
 END 550 ~~AM~~/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials PC  
 Examiners Initials DD mc  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	ok	None Observed	
Main North Haulage seals	20.9	0	0	PC	ok	None Observed	
M. West Haulage seals	20.9	0	0	mc/DD	ok	none observed	
3rd North Haulage	20.9	0	0	mc/DD	ok	none observed	
1st Right	20.9	0	0	mc/DD	ok	none observed	
Transformers	20.9	0	0	mc/DD	ok	none observed	
Chargers	20.9	0	0	mc/DD	ok	none observed	
Wash down	20.9	0	0	DD	ok	none observed	
Storage area	20.9	0	0	DD	ok	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 8462  
 CERT. # 7375  
 CERT. # 8058  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_

ERT. # 03892

2MSHA03211

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-13-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:00 ~~AM~~/PM END 12:43 AM/~~PM~~  
 TIME OF EXAMINATION START 11:52 ~~AM~~/PM END 12:45 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials BH  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
MAIN North haulage seals	20.9	0	0	BH	OK	None Observed	
MAIN West haulage seals	20.9	0	0	<del>BH</del> FM	OK	none observed	
3rd North haulage	20.9	0	0	FM	OK	none observed	
1st Right	20.9	0	0	FM	OK	none observed	
transformers	20.9	0	0	<del>FM</del> BH	OK	None Observed	
Chargers	20.9	0	0	FM	OK	none observed	
Wash down	20.9	0	0	FM	OK	none observed	
Storage Area	20.9	0	0	FM	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
M West So.	Trash Accumulations	Cleaned At 4/13/07

PRE-SHIFT REMARKS All areas appeared ~~to be~~ reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 8297  
 PRE-SHIFT/MINE EXAMINEE CERT. # 8285  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03212

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-13-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 7:50 AM/PM  
START 7:50 AM/PM  
START \_\_\_\_\_ AM/PM

END 8:50 AM/PM  
END 9 AM/PM  
END \_\_\_\_\_ AM/PM

Examiners Initials SW  
Examiners Initials dg  
Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North <sup>SLAB</sup> haulage	21.0	0	0	SW	OK	none observed	
Main West <sup>SLAB</sup> haulage	21.0	0	0	SW <sup>dg</sup>	OK	none observed	
3 <sup>rd</sup> North haulage	21.0	0	0	SW	OK	none observed	
1 <sup>st</sup> Right	21.0	0	0	SW	OK	none observed	
transformers	21.0	0	0	SW <sup>dg</sup>	OK	none observed	
chargers	21.0	0	0	SW <sup>dg</sup>	OK	none observed	
Washdown	21.0	0	0	dg	OK	none observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 9548  
CERT. # 6622  
CERT. # \_\_\_\_\_  
CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 7483

2MSHA03213

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/4/07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 3:45 AM/PM  
 TIME OF EXAMINATION START 3:50 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 5 AM/PM  
 END 5:40 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials dy  
 Examiners Initials SW  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21.0	0	0	SW	OK	None observed	
Mainly North Roadway	21.0	0	0	SW	OK	None observed	
Mainly seats Main West Haulage	20.9	0	0	dy SW	OK	None observed	
Redwood Haulage	21.0	0	0	SW	OK	None observed	
1st Right Haulage	21.0	0	0	SW	OK	None observed	
Transformers	20.9	0	0	dy SW	OK	None observed	
Chargers	20.9	0	0	dy SW	OK	None observed	
Wash down	20.9	0	0	dy	OK	None observed	
Storage areas	21.0	0	0	SW	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe to travel and work at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6622  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9548  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ RT. # 03992

2MSHA03214

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/4-07 SECTION/AREA Gen Mine | |

TIME OF EXAMINATION START 12:30 AM/PM AM END 1:14 AM/PM PM Examiners Initials TC  
 TIME OF EXAMINATION START 12:45 AM/PM AM END 1:16 AM/PM PM Examiners Initials BP  
 TIME OF EXAMINATION START 11:42 AM/PM AM END 12:12 AM/PM PM Examiners Initials BH

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AMPM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	BH	OK	None obs.	
Main north Haulage + seals	20.9	0	0	BH	OK	None obs.	
Main west + seals + Haulage	20.9	0	0	TC/BP BH	OK	None obs.	
3RD north seals Haulage	20.9	0	0	BH	OK	None obs.	
1st Right Haulage	20.9	0	0	BH	OK	None obs.	
Transformers	20.9	0	0	TC/BP BH	OK	None obs.	
chargers	20.9	0	0	BH	OK	None obs.	
Washdown	20.9	0	0	BH	OK	None obs.	
STORAGE AREA	20.9	0	0	BH	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
M West 30	Trash accu.	Cleaned

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 9362  
 PRE-SHIFT/MINE EXAMINER CERT. # 9399  
 PRE-SHIFT/MINE EXAMINER CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE **Signature** CERT. # 05892

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-14-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 7:45 AM/PM AM  
 TIME OF EXAMINATION START 7:45 AM/PM AM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_

END 8:50 AM/PM PM  
 END 8:50 AM/PM PM  
 END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials SW  
 Examiners Initials dy  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage <sup>SEALS</sup>	21.0	0	0	SW	OK	none observed	
Main West haulage <sup>SEALS</sup>	21.0	0	0	<del>SW</del> dy	OK	none observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	<del>SW</del> dy	OK	none observed	
chargers	21.0	0	0	<del>SW</del> dy	OK	none observed	
washdown	21.0	0	0	dy	ok	None observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 9548  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 6622  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR \_\_\_\_\_ CERT. # 74885

2MSHA03216

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/5/07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 3:50 AM/PM END 5:10 AM/PM  
 TIME OF EXAMINATION START 3:55 AM/PM END 5:40 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM  
 Examiners Initials Dg  
 Examiners Initials SW  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES  NO  CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
WC parking area	21.0	0	0	SW	OK	none observed	
main seals worth haulage	21.0	0	0	SW	OK	none observed	
main seals pumps west haulage	21.1	0	0	Dg	OK	None observed	
3rd west haulage	21.0	0	0	SW	OK	none observed	
1st right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	Dg	OK	none observed	
chargers	21.0	0	0	Dg	OK	none observed	
Washdown	21.0	0	0	Dg	OK	None observed	
Storage areas	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe to travel and work at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6622  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9548  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 03992

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-15-07 SECTION/AREA General Mine / /

TIME OF EXAMINATION START 11:52 AM/PM END 12:35 AM/PM Examiners Initials K  
 TIME OF EXAMINATION START 11:47 AM/PM END 1:20 AM/PM Examiners Initials BH  
 TIME OF EXAMINATION START 126 AM/PM END 1:10 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
U.G. Parking Area	20.9	0	0	BH	OK	None Observed	
MAIN North Haulage & seals	20.9	0	0	BH	OK	None Observed	
MAIN West Haulage & seals	20.9	0	0	TC/BP BH	OK	none obs.	
3 <sup>rd</sup> North Haulage <sup>Seals</sup>	20.9	0	0	BH	OK	None observed	
1 <sup>st</sup> Right Haulage	20.9	0	0	BH	OK	None observed	
Transformer	20.9	0	0	TC/BH	OK	none obs.	
Chargers	20.9	0	0	TC/BH	OK	none obs.	
Washdown	20.9	0	0	BP	OK	none obs.	
Storage Area	20.9	0	0	BH/BP	OK	none obs.	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
M West So	Trash accu.	Cleaned &

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362  
 PRE-SHIFT/MINE EXAMINER CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER CERT. # 9399  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

Signature  
 CERT. # 03892

COUNTER SIGNATURE

2MSHA03218

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-15-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 7:45  
 TIME OF EXAMINATION START 7  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM AM END 8:53 AM/PM AM  
 AM/PM PM END 8:30 AM/PM PM  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials SW  
 Examiners Initials dy  
 Examiners Initials 7

EXAM. CALLED OUT ----- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage <sup>SLATS</sup>	21.0	0	0	SW	OK	none observed	
Main West haulage <sup>SLATS</sup>	21.0	0	0	SW <sup>dy</sup>	OK	None observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	SW <sup>dy</sup>	OK	None observed	
chargers	21.0	0	0	SW <sup>dy</sup>	OK	None observed	
Washdown	20.9	0	0	dy	OK	none observed	
Storage Area.	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 9548  
 CERT. # 6622  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 7485

2MSHA03219

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/6/07 SECTION/AREA Cen 1/line 1

TIME OF EXAMINATION START 3  AM/PM  PM END 4:30  AM/PM  PM  
 TIME OF EXAMINATION START 3:00  AM/PM  PM END 4:05  AM/PM  PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM

Examiners Initials dy  
 Examiners Initials SW  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
etc Parking	21.0	0	0	SW	OK	none observed	
MAIN NORTH Haulage seals	21.0	0	0	SW	OK	none observed	
Main Pump seals west Haulage	21.	0	1	dy SW	OK	none observed	
3rd no haulage	21.0	0	0	SW	OK	none observed	
1st Right Haulage	21.0	0	0	SW	OK	none observed	
TRANSFORMERS	21.	0	0	dy SW	OK	none observed	
chargers	20.9	0	0	dy SW	OK	none observed	
washdown	21.	0	0	dy	OK	none observed	
STORAGE AREAS	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe to travel and work at time of exam.

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # 6622  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # 9548  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATUR \_\_\_\_\_ CERT. # 8462 2MSHA03220

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-16-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 11:00 ~~AM/PM~~ END 12:00 ~~AM/PM~~ Examiners Initials DD  
 TIME OF EXAMINATION START 11:30 ~~AM/PM~~ END 1:25 ~~AM/PM~~ Examiners Initials AL/RM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21	0	0	DD	ok	none obs.	
main north Haulage seals	21	0	0	DD	ok	none obs.	
main west Haulage seals	20.9	0	0	mc/km	OK	none observed	
3rd North Haulage	20.9	0	0	mc/km	OK	none observed	
1st Right Haulage	20.9	0	0	mc/km	OK	none observed	
TRANS.	20.9	0	0	mc/km	OK	none observed	
chargers	20.9	0	0	mc	OK	none observed	
washdown	20.9	0	0	mc	OK	none observed	
Storage area	20.9	0	0	mc	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe  
at time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE

CERT. # 8058  
 CERT. # 7375  
 CERT. # 9379  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNA

CERT. # 8462

2MSHA03221

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-16-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 9:05 AM/PM  
 TIME OF EXAMINATION START 8:40 AM/PM  
 TIME OF EXAMINATION START 8 AM/PM

END 9:35 AM/PM  
 END 9:30 AM/PM  
 END 9:20 AM/PM

Examiners Initials SW  
 Examiners Initials LR/KK  
 Examiners Initials dy

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North <sup>SEALS</sup> haulage	21.0	0	0	SW	OK	none observed	
Main West <sup>SEALS</sup> haulage	21.1	0	0	LR/KK dy	OK	None observed	
3rd North <sup>SEALS</sup> haulage	20.9	0	0	KK/LR	OK	None obs	
1st Right haulage	20.9	0	0	KK	OK	None obs.	
Transformers	21.0	0	0	SW/KK	OK	none obs	
chargers	20.9	0	0	LR/KK dy	OK	none obs	
Washdown	20.9	0	0	dy	OK	None observed	
Storage Area	20.9	0	0	LR	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

*all areas examined appear safe at time of pre-shift*

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 9548  
 CERT. # 4375  
 CERT. # 7954  
 CERT. # 6622

Signature

COUNTER SIGNATURE

CERT. # 1135

2MSHA03222

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-17-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 3:00 AM/PM (A) END 5:35 AM/PM  
 TIME OF EXAMINATION START 4:00 AM/PM (A) END 5:30 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM  
 Examiners Initials KK/RL  
 Examiners Initials LR  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO \_\_\_\_\_ CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>none obs.</u>	
<u>M. North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>none obs.</u>	
<u>M. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>none obs.</u>	
<u>3rd North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>none obs.</u>	
<u>1st right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>none obs.</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>none obs.</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>none obs.</u>	
<u>Trams</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u> <u>LR</u>	<u>OK</u>	<u>none obs.</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7954  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6401  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4375  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNAT \_\_\_\_\_ CERT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-17-07

SECTION/AREA General 1

TIME OF EXAMINATION START 11:00 AM/PM  
 TIME OF EXAMINATION START 11:56 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 12:30 AM/PM  
 END 12:33 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KM/FM  
 Examiners Initials FM  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none obs.	
Main North seals <sup>haulage</sup>	20.9	0	0	FM	OK	none obs.	
Main West seals <sup>haulage</sup>	20.9	0	0	FM/KM	OK	Deep water x 50, 51, 73, 75	Pumped 4-17-07 MC
3rd North seals <sup>haulage</sup>	20.9	0	0	KM	OK	none obs.	
1st Right	20.9	0	0	KM	OK	none obs.	
Trucks	20.9	0	0	FM/KM	OK	none obs.	
chargers	20.9	0	0	KM	OK	none obs.	
washdown	20.9	0	0	KM	OK	none obs.	
Storage Area	20.9	0	0	KM	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 9379  
 CERT. # 8397  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 4935

2MSHA03224

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-17-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7.45 AM/PM AM END 9.37 AM/PM PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

Examiners Initials KK/LR  
 Examiners Initials \_\_\_\_\_  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO \_\_\_\_\_ CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>OK</u>	<u>none obs</u>	
<u>M. Dault Haulage</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>LR/KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>OK</u>	<u>none obs</u>	
<u>3rd Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>OK</u>	<u>none obs.</u>	
<u>1st Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Trams</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR/KK</u>	<u>OK</u>	<u>none obs.</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>OK</u>	<u>none obs.</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs.</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Belt Kitchen</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>none obs</u>	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7954  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4325  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4135

2MSHA03225

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/18/07

SECTION/AREA Gen/Pre!

TIME OF EXAMINATION START 500 AM/PM  
 TIME OF EXAMINATION START 400 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 400 AM/PM  
 END 515 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KK  
 Examiners Initials LR  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO X

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. North Haulage</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs.</u>	
<u>M. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>OK</u>	<u>none obs</u>	
<u>3 North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>13<sup>5</sup> Night Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs.</u>	
<u>T. Stairs.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>OK</u>	<u>none obs.</u>	
<u>Storage area</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>None obs.</u>	
<u>chargers</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>None obs.</u>	
<u>Washdown</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>None obs.</u>	
<u>Belt Kitcher</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 7954  
 CERT. # 4375  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ RT. # 8462

2MSHA03226

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-18-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 11:00 AM/PM END 12:45 AM/PM Examiners Initials MC/FM  
 TIME OF EXAMINATION START 11:53 AM/PM END 12:42 AM/PM Examiners Initials FM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	Fm	OK	none observed	
MAIN NORTH <sup>Haulage</sup> <del>peaks</del>	20.9	0	0	Fm	OK	none observed	
MAIN WEST <sup>Haulage</sup> <del>peaks</del>	20.9	0	0	MC	OK	none observed	
3 <sup>RD</sup> NORTH <sup>Haulage</sup> <del>peaks</del>	20.9	0	0	MC <sup>Fm</sup>	OK	none observed	
1 <sup>ST</sup> Right Haulage	20.9	0	0	MC	OK	none observed	
Transformers	20.9	0	0	MC/FM	OK	none observed	
chargers	20.9	0	0	MC	OK	none observed	
washdown	20.9	0	0	MC	OK	none observed	
Storage Area	20.9	0	0	MC	OK	none observed	
Kitchen	20.9	0	0	Fm	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY  
SAFE AT TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 7325  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4945 2MSHA03227

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-19-07

SECTION/AREA Gem Mine 1

TIME OF EXAMINATION START 7:05 AM/PM (P)  
 TIME OF EXAMINATION START 7:05 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 8:25 AM/PM (P)  
 END 8:25 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials JK  
 Examiners Initials JK  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

CALL OUT TIME ----- AM/PM

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	21.0	0	0	LR	OK	None obs.	
M. West Haulage <sup>seal</sup>	21.0	0	0	LR	OK	None obs.	
M. West Haulage <sup>seal</sup>	20.9	0	0	KK	OK	none obs	
3 West Haulage <sup>seal</sup>	21.0	0	0	LR	OK	None obs.	
1st right Haulage	21.0	0	0	LR	OK	None obs.	
Storage area	20.9	0	0	KK	OK	none obs.	
chargers	20.9	0	0	KK/LR	OK	none obs	
Washdown	20.9	0	0	KK	OK	none obs	
Belt Kitcher	21.0	0	0	LR	OK	None obs.	
Trams.	20.9	0	0	KK/LR	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM R.

PRE-SHIFT/MINE EXAMINER Signature  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXA \_\_\_\_\_

CERT. # 7954  
 CERT. # 4375  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR:

CERT. # 4725

2MSHA03228

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-19-67

SECTION/AREA General

TIME OF EXAMINATION  
 TIME OF EXAMINATION  
 TIME OF EXAMINATION

START 300 AM/PM  
 START 400 AM/PM  
 START \_\_\_\_\_ AM/PM

END 5:35 AM/PM  
 END 5:40 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KK/RC  
 Examiners Initials RC  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- AM/PM

ALLOTTED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.8</u>	<u>0</u>	<u>0</u>	<u>RC</u>	<u>0</u>	<u>none</u>	
<u>W. North haulage</u>	<u>20.8</u>	<u>0</u>	<u>0</u>	<u>RC</u>	<u>0</u>	<u>none</u>	
<u>W. West haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>0</u>	<u>none obs</u>	
<u>3rd North haulage</u>	<u>20.8</u>	<u>0</u>	<u>0</u>	<u>RC</u>	<u>0</u>	<u>none</u>	
<u>1st North haulage</u>	<u>20.8</u>	<u>0</u>	<u>0</u>	<u>RC</u>	<u>0</u>	<u>none</u>	
<u>Flume area</u>	<u>20.8</u>	<u>0</u>	<u>0</u>	<u>RC</u>	<u>0</u>	<u>none</u>	
<u>winchdown</u>	<u>20.8</u>	<u>0</u>	<u>0</u>	<u>RC</u>	<u>0</u>	<u>none</u>	
<u>Towers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>0</u>	<u>none obs</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>0</u>	<u>none obs</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All was appeared safe at time of exam

Signature \_\_\_\_\_

- PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7954
- PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4375
- PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6401
- PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNAT

CERT. # 4735

2MSHA03229

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-19-07

SECTION/AREA Genuine 1

TIME OF EXAMINATION START 11:00 AM/PM  
 TIME OF EXAMINATION START 11:50 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 12:45 AM/PM  
 END 12:45 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials MC  
 Examiners Initials FW  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	Fm	OK	none observed	
Main North Haulage Seals	20.9	0	0	Fm	OK	none observed	
Main West Haulage Seals	20.9	0	0	MC	OK	none observed	
3 <sup>rd</sup> North Haulage Seals	20.9	0	0	MC	OK	none observed	
1 <sup>st</sup> Right Haulage	20.9	0	0	MC	OK	none observed	
Transformers	20.9	0	0	MC/FM	OK	none observed	
Chargers	20.9	0	0	MC	OK	none observed	
Washdown	20.9	0	0	MC	OK	none observed	
Storage Area	20.9	0	0	MC	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
Main West	Deep Water 49 to 51	Pumped 4-19-07 MC

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8097  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_  
 Signature \_\_\_\_\_  
 CERT. # 8462

2MSHA03230

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-19-07

SECTION/AREA 6-11-1

TIME OF EXAMINATION START 7:00 AM/PM (P)  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 9:00 AM/PM (P)  
 END \_\_\_\_\_ AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KK/RL  
 Examiners Initials \_\_\_\_\_  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DC</u>	<u>OK</u>	<u>none obs</u>	
<u>N. North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DC</u>	<u>OK</u>	<u>none obs</u>	
<u>Midwest Haulage</u>	<u>20.9</u>	<u>A</u>	<u>B</u>	<u>KK/RL</u>	<u>OK</u>	<u>none obs</u>	
<u>South Haulage</u>	<u>20.9</u>	<u>A</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Flight Haulage</u>	<u>20.9</u>	<u>A</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>B</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs.</u>	
<u>Washdown</u>	<u>20.9</u>	<u>B</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs.</u>	
<u>Tunnels</u>	<u>20.9</u>	<u>A</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>none</u>	
<u>chargers</u>	<u>20.9</u>	<u>B</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>none obs</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe  
at time of EXAM.

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 7954  
 CERT. # 6201  
 CERT. # 4235  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR

CERT. # 4735

2MSHA03231

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-26-07 SECTION/AREA Remain 1

TIME OF EXAMINATION START 3:00 AM/PM END 5:00 AM/PM Examiners Initials OG  
 TIME OF EXAMINATION START 3:00 AM/PM END 5:25 AM/PM Examiners Initials KK/RL  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	OG	OK	none obs	
N. Drift Haulage	20.9	0	0	OG	OK	none obs	
N. West Haulage	20.9	0	0	KK/RL	OK	none obs	
South Haulage	20.9	0	0	KK/RL	OK	none obs	
1st Flight Haulage	20.9	0	0	KK	OK	none obs	
Storage area	20.9	0	0	RL	OK	none obs	
warehouse	20.9	0	0	KK	OK	none obs	
chargers	20.9	0	0	KK/RL	OK	none obs	
Trans.	20.9	0	0	KK/RL	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 4735  
 CERT. # 7954  
 CERT. # 0401  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE

CERT. # 03892

2MSHA03232

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-20-07 SECTION/AREA Gen Mine | |

TIME OF EXAMINATION START 12:00 AM/PM AM END 12:30 AM/PM PM Examiners Initials JC  
 TIME OF EXAMINATION START 11:50 AM/PM AM END 12:00 AM/PM PM Examiners Initials BH  
 TIME OF EXAMINATION START 11:43 AM/PM AM END 1:26 AM/PM PM Examiners Initials Fm

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none obs.	
Main North <sup>Hanloge</sup> seals	20.9	0	0	FM	OK	none obs.	
Main West <sup>Hanloge</sup> seals	20.9	0	0	BH/FM	OK	none obs.	
3 <sup>rd</sup> North <sup>Hanloge</sup> seals	20.9	0	0	FM	OK	none obs.	
1 <sup>st</sup> Right Hanloge	20.9	0	0	FM	OK	none obs.	
Transformers	20.9	0	0	BH/FM	OK	none obs.	
Chargers	20.9	0	0	BH/FM	OK	none obs.	
Washdown	20.9	0	0	FM	OK	none obs.	
Storage Areas	20.9	0	0	FM	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main/Intake	Trash	Cleaned CA

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER CERT. # 9362  
 PRE-SHIFT/MINE EXAMINER CERT. # 8397  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 05892 2MSHA03233

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-20-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 7:55  
 TIME OF EXAMINATION START 7:00  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM (M) END 8:55 AM/PM (M)  
 AM/PM (M) END 9:00 AM/PM (M)  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials SW  
 Examiners Initials LD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage <sup>SLATS</sup>	21.0	0	0	SW	OK	lifeline broken next 25' x 4'	sent memo to repair, repaired 4-20-07 SW
Main West haulage <sup>SLATS</sup>	21.0	0	0	SW	OK	none observed	
3rd North haulage <sup>SLATS</sup>	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
washdown	21.9	0	0	LD	OK	none observed	
chargers	21.0	0	0	LD	OK	none observed	
Transformers	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas appeared Safe at the time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9660  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03234

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-21-07

SECTION/AREA General 1 Mine. 1

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 3:50 AM/PM  
START 3:45 AM/PM  
START \_\_\_\_\_ AM/PM

END 5:15 AM/PM  
END 5:00 AM/PM  
END \_\_\_\_\_ AM/PM

Examiners Initials SW  
Examiners Initials dy  
Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North <sup>seals</sup> haulage	21.0	0	0	SW	OK	none observed	
Main West <sup>seals</sup> haulage	21.0	0	0	<del>SW</del> dy	OK	Roadway Timber <sup>28x</sup> <sup>(5)</sup> Knocked out	Sent men to set timber Done 4-21-07 TC
3rd North <sup>seals</sup> haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
washdown	21.0	0	0	dy	OK	none observed	
chargers	21.0	0	0	<del>SW</del> dy	OK	none observed	
Transformers	21.0	0	0	<del>SW</del> dy	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift except what is noted above

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

Signature

CERT. # 9548  
CERT. # 6622  
CERT. # \_\_\_\_\_  
CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 8925

2MSHA03235

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-21-07 SECTION/AREA benzene / /

TIME OF EXAMINATION START 12:15 ~~AM/PM~~ END 12:50 AM/PM  
 TIME OF EXAMINATION START 11:47 ~~AM/PM~~ END 1:20 AM/PM  
 TIME OF EXAMINATION START 11:57 ~~AM/PM~~ END 12:50 AM/PM

Examiners Initials JK  
 Examiners Initials BH  
 Examiners Initials BP

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North <sup>seals</sup> haulage	20.9	0	0	BH	OK	None Observed	
Main West Haulage <sup>seals</sup>	20.9	0	0	<del>JK/BH</del> BH	OK	None obs.	
3rd North <sup>seals</sup> haulage	20.9	0	0	BH	OK	None Observed	
1st Right haulage	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	<del>JK/BH</del> BH	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 9362  
 PRE-SHIFT/MINE EXAMINEE CERT. # 8395  
 PRE-SHIFT/MINE EXAMINEE CERT. # 9597  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 03892

2MSHA03236

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-21-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 8:05  
 TIME OF EXAMINATION START 7:20  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM AM/PM END 9:14 AM/PM AM/PM  
 AM/PM AM/PM END 9:20 AM/PM AM/PM  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials SW  
 Examiners Initials SD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage <sup>seals</sup>	21.0	0	0	SW	OK	none observed	
Main West haulage <sup>seals</sup>	21.0	0	0	<del>SD</del> SW	OK	none observed	
3rd North haulage <sup>seals</sup>	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	20.9	0	0	SD	OK	none observed	
chargers	21.0	0	0	<del>SD</del> SW	OK	none observed	
Transformers	21.0	0	0	<del>SD</del> SW	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas App end Safe at the time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEI  
 PRE-SHIFT/MINE EXAMINEI  
 PRE-SHIFT/MINE EXAMINEI  
 PRE-SHIFT/MINE EXA

CERT. # 9548  
 CERT. # 9660  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATUR

CERT. # 7485

2MSHA03237

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-22-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 3:55 AM/PM  
 TIME OF EXAMINATION START 3:45 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 5:17 AM/PM  
 END 5:20 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials SW  
 Examiners Initials dg  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage <sup>SCATS</sup>	21.0	0	0	SW	OK	none observed	
Main East haulage <sup>SCATS</sup>	21.0	0	0	<del>SW</del> dg	OK	none observed	
3rd North haulage <sup>SCATS</sup>	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	20.9	0	0	dg	OK	none observed	
Chargers	21.0	0	0	<del>SW</del> dg	OK	main #3X float dust west charger acc	applied back dg
Transformers	21.0	0	0	<del>SW</del> dg	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
1st transformer	trash acc.	removed

**PRE-SHIFT REMARKS**

all areas examined appear safe at times of preshift

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 9548  
 CERT. # 6622  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_

ERT. # 03892

2MSHA03238

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4 22 07 SECTION/AREA Gen Mine | |

TIME OF EXAMINATION START 11:50 AM/PM AM/PM END 12:20 AM/PM  
 TIME OF EXAMINATION START 11:40 AM/PM AM/PM END 1:44 AM/PM  
 TIME OF EXAMINATION START 11:55 AM/PM AM/PM END 1:45 AM/PM

Examiners Initials GA  
 Examiners Initials BH  
 Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	GA	OK	None observed	
Main North <sup>Haulage</sup> seals	20.9	0	0	BH/TC	OK	None Observed	
Main West <sup>Haulage</sup> seals	20.9	0	0	BH/TC	OK	None Observed	
3rd No Haulage <sup>seals</sup>	20.9	0	0	GA	OK	None observed	
1st At Haulage	20.9	0	0	GA	OK	None observed	
Storage Area 2	20.9	0	0	BH/TC	OK	None observed	
Transformers	20.9	0	0	BH/TC	OK	None observed	
Chargers	20.9	0	0	TC	OK	None observed	
Washdown	20.9	0	0	BH	OK	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at the time of exam

Signature

PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE

CERT. # 03892  
 CERT. # 8395  
 CERT. # 9362  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 03892

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-22-07

SECTION/AREA General 1 Mill

TIME OF EXAMINATION START 7:50 AM/PM  
 TIME OF EXAMINATION START 7:05 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 9:00 AM/PM  
 END 7:35 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials SW  
 Examiners Initials dy  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North <sup>SEALS</sup> haulage	21.0	0	0	SW	OK	none observed	
Main West <sup>SEALS</sup> haulage	21.0	0	0	<del>SW</del> <sup>dy</sup>	OK	None observed	
3rd North <sup>SEALS</sup> haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
washdown	20.9	0	0	dy	OK	None observed	
chargers	21.0	0	0	<del>SW</del> <sup>dy</sup>	OK	None observed	
Transformers	21.0	0	0	<del>SW</del> <sup>dy</sup>	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 9548  
 CERT. # 6622  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature

CERT. # 7485

2MSHA03240

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-23-07 SECTION/AREA General Mine 1

TIME OF EXAMINATION START 3:44 ~~AM~~PM END 5:19 ~~AM~~PM Examiners Initials SW  
 TIME OF EXAMINATION START 3:45 ~~AM~~PM END 5:15 ~~AM~~PM Examiners Initials dg  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (N) CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North <sup>SLATS</sup> haulage	21.0	0	0	SW	OK	none observed	
Main West <sup>SLATS</sup> haulage	21.0	0	0	<del>SW</del> dg	OK	none observed	
3rd North <sup>SLATS</sup> haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
wash down	21.2	0	0	dg	OK	none observed	
Chargers	21.0	0	0	<del>SW</del> dg	OK	None observed	
Transformers	21.0	0	0	<del>SW</del> dg	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # 9548  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # 6622  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 03892 2MSHA03241

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-23-07 SECTION/AREA Genuine 1

TIME OF EXAMINATION START 11:30 AM/PM AM END 1:05 AM/PM PM Examiners Initials mc  
 TIME OF EXAMINATION START 1:00 AM/PM PM END 1:00 AM/PM PM Examiners Initials DD  
 TIME OF EXAMINATION START 11:55 AM/PM PM END 1:13 AM/PM PM Examiners Initials Fm

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	Fm	OK	none observed	
MAIN NORTH Haulage seals	20.9	0	0	Fm	OK	none observed	
MAIN WEST Haulage seals	20.9	0	0	mc/DD Fm	OK	Deep water vent 25	Pumped 4-23-07 mc
3 <sup>RD</sup> NORTH Haulage seals	20.9	0	0	Fm	OK	none observed	
1 <sup>ST</sup> Right Haulage	20.9	0	0	Fm	OK	none observed	
TREWS FORMERS	20.9	0	0	Fm/mc	OK	none observed	
CHARGERS	20.9	0	0	Fm/mc DD	OK	none observed	
WASHDOWN	20.9	0	0	mc	OK	none observed	
STORAGE AREA	20.9	0	0	mc	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe AT Time of Pre-shift

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # \_\_\_\_\_  
 Signature \_\_\_\_\_

COUNTER SIGNAT \_\_\_\_\_ CERT. # 4735 2MSHA03242

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-23-07 SECTION/AREA Gen Mine | |

TIME OF EXAMINATION START 800 AM/PM AM END 900 AM/PM PM Examiners Initials DG  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES  NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Pargear Area	20.9	0	0	DG	OK	none observed	
Main North Haulage Seals	20.9	0	0	DG	OK	none observed	
Main West Haulage Seals	20.9	0	0	RL/KK	OK	none observed	
3rd North Haulage Seals	20.9	0	0	RL/KK	OK	none observed	
1st Right Haulage	20.9	0	0	KK	OK	none observed	
Transformers	20.9	0	0	RL/KK	OK	none observed	
chargers	20.9	0	0	RL/KK	OK	none observed	
washdown	20.9	0	0	KK	OK	none "	
Storage Area	20.9	0	0	RL	OK	none "	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4735  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6901  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7956  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATUR \_\_\_\_\_ CERT. # 4735

2MSHA03243

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-24-07

SECTION/AREA General

TIME OF EXAMINATION START 4:00 AM/PM  
 TIME OF EXAMINATION START 3:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 5:00 AM/PM  
 END 6:35 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials DL  
 Examiners Initials KK/RC  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Haulage Main Booth seals	20.9	0	0	DL	OK	none observed	
Parking Area	20.9	0	0	DL	OK	none "	
Main Haulage seals	20.9	0	0	RL/KK	OK	none "	
3rd No Haulage seals	20.9	0	0	RL/KK	OK	none "	
1st Right Haulage	20.9	0	0	KK	OK	none "	
Transformers	20.9	0	0	RL/KK	OK	none "	
Chargers	20.9	0	0	RL/KK	OK	none "	
washdown	20.9	0	0	KK	OK	none "	
Storage Area	20.9	0	0	RL	OK	none "	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4735  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6806  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7959  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_  
 COUNTY SIGNATURE CERT. # 8462

2MSHA03244

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/24/07 SECTION/AREA Gen Mine 1 / /

TIME OF EXAMINATION START 11:52 AM/PM END 1:10 AM/PM Examiners Initials FM  
 TIME OF EXAMINATION START 1:00 AM/PM END 1:19 AM/PM Examiners Initials DD mc  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	209	0	0	FM	OK	none observed	
Main North haulage seals	209	0	0	FM	OK	none observed	
Main West haulage seals	209	0	0	FM DD mc	OK	none observed	
3rd North haulage seals	209	0	0	FM	OK	none observed	
1st Right	209	0	0	FM	OK	none observed	
Transformers	209	0	0	FM DD mc	OK	none observed	
Changers	209	0	0	FM DD mc	OK	none observed	
Storage Area	209	0	0	MC	OK	none observed	
Washdown	209	0	0	DD	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7325  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8762

2MSHA03245

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-24-07 SECTION/AREA Gen Mins

TIME OF EXAMINATION START 8 AM/PM AM END 9 AM/PM PM Examiners Initials AG  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Main North Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DG</u>	<u>OK</u>	<u>none obs</u>	
<u>Parking Area</u>	<u>20.3</u>	<u>0</u>	<u>0</u>	<u>Ph</u>	<u>OK</u>	<u>none obs</u>	
<u>Main West Haulage Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>none observed</u>	
<u>3rd North Haulage Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>none observed</u>	
<u>1st Right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none observed</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>none observed</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>none "</u>	
<u>workdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none "</u>	
<u>Storage Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none "</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4735  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6406  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7054  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 Signature \_\_\_\_\_  
 COUNTER SIGNAT \_\_\_\_\_ RT. # 8925

2MSHA03246

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-25-07

SECTION/AREA Gen Mtn I

TIME OF EXAMINATION START 4:00 AM/PM  
 TIME OF EXAMINATION START 3:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 4:52 AM/PM  
 END 5:40 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials DL  
 Examiners Initials RL/KK  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	DL	OK	no obs.	
<sup>seats</sup> N. North Haulage	20.9	0	0	DL	OK	no obs.	
<sup>seats</sup> M. West Haulage	20.9	0	0	RL/KK	OK	none observed	
<sup>seats</sup> S. North Haulage	20.9	0	0	RL/KK	OK	none observed	
<sup>seats</sup> 1 <sup>st</sup> Right Haulage	20.9	0	0	KK	OK	none observed	
Storage area	20.9	0	0	RL	OK	none observed	
Washdown	20.9	0	0	KK	OK	none observed	
chargers	20.9	0	0	RL/KK	OK	none observed	
Trucks	20.9	0	0	RL/KK	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of pre shift

Signature

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 4735  
 CERT. # 6401  
 CERT. # 7954  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE CERT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-25-07 SECTION/AREA Genuine 1

TIME OF EXAMINATION START 11:30  AM  PM END 1:05  AM  PM Examiners Initials MC/DD  
 TIME OF EXAMINATION START 11:48  AM  PM END 1:02  AM  PM Examiners Initials FM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO  CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	Fm	OK	none observed	
MAIN NORTH HAULAGE SEALS	20.9	0	0	Fm	OK	none observed	
MAIN WEST HAULAGE SEALS	20.9	0	0	MC DD	OK	none observed	
3 <sup>RD</sup> NORTH HAULAGE SEALS	20.9	0	0	Fm	OK	none observed	
1 <sup>ST</sup> RIGHT HAULAGE	20.9	0	0	Fm	OK	none observed	
Transformers	20.9	0	0	MC Fm DD	OK	none observed	
Chargers	20.9	0	0	MC Fm DD	OK	none observed	
Washdown	20.9	0	0	MC	OK	none observed	
TOP OFF AREA	20.9	0	0	DD	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7375  
 PRE-SHIFT/MINE EXAMINER CERT. # 8397  
 PRE-SHIFT/MINE EXAMINER CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8462

2MSHA03248

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-25-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 7:00  
START 8:19  
START \_\_\_\_\_

AM/PM (AM)  
AM/PM (AM)  
AM/PM \_\_\_\_\_

END 9:00  
END 9:35  
END \_\_\_\_\_

Examiners Initials RL  
Examiners Initials KK  
Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>0</u>	<u>none obs</u>	
<u>Main West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>0</u>	<u>none obs</u>	
<u>Main West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>0</u>	<u>none obs</u>	
<u>3rd North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>0</u>	<u>none obs</u>	
<u>1st Right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>0</u>	<u>none obs</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/RL</u>	<u>0</u>	<u>none obs</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/RL</u>	<u>0</u>	<u>none obs</u>	
<u>Workdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

all areas appeared safe at time of pre-shift

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER

CERT. # 6401  
CERT. # 7954  
CERT. # \_\_\_\_\_  
CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE

CERT. # 4735

2MSHA03249

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-26-07

SECTION/AREA Coal Mine 1

TIME OF EXAMINATION START 3:46 AM/PM  
 TIME OF EXAMINATION START 3:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 4:28 AM/PM  
 END 4:20 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials DL  
 Examiners Initials RJ/KK  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Darkness area	20.9	0.0	0.0	DL	OK	none obs	
M. North haulage	20.9	0.0	0.0	DL	OK	none obs	
M. West Haulage	20.9	0.0	0.0	RJ/KK	OK	none obs	
South Haulage	20.9	0.0	0.0	RJ/KK	OK	none obs	
Eight haulage	20.9	0.0	0.0	RJ/KK	OK	none obs	
Storage area	20.9	0.0	0.0	AL	OK	none obs	
Underground	20.9	0.0	0.0	RJ/KK	OK	none obs	
Truss	20.9	0.0	0.0	RJ/KK	OK	none obs	
Charger	20.9	0.0	0.0	RJ/KK	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift

PRE-SHIFT/MINE EXAMINE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_

CERT. # 4735  
 CERT. # 4957  
 CERT. # 6401  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03250

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-26-07

SECTION/AREA Gen Mine 1 / /

TIME OF EXAMINATION START 11:48 AM/PM  
 TIME OF EXAMINATION START 11:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1:02 AM/PM  
 END 1:20 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials DD MC  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	FM	OK	none observed	
MAIN North haulage seals	20.9	0	0	FM	OK	none observed	
MAIN West haulage seals	20.9	0	0	FM DD MC	OK	none obs.	
3rd North haulage seals	20.9	0	0	FM	OK	none observed	
1st Right	20.9	0	0	FM	OK	none observed	
Transformers	20.9	0	0	FM DD MC	OK	none obs.	
Changers	20.9	0	0	FM DD MC	OK	none obs.	
Storage Area	20.9	0	0	MC	OK	none obs.	
Washdown	20.9	0	0	DD	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # 8097  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # 7376  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_  
 COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8462

2MSHA03251

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-26-07 SECTION/AREA Gen Mins / /

TIME OF EXAMINATION START 800 AM/PM END 835 AM/PM Examiners Initials DK  
 TIME OF EXAMINATION START 705 AM/PM END 915 AM/PM Examiners Initials KK/RL  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DK	OK	none obs	
Main North <sup>Haulage</sup> <sub>SCALS</sub>	20.9	0	0	DK	OK	none obs	
M. West Haulage <sup>scals</sup>	20.9	0	0	KK/RL	OK	none obs.	
3 <sup>rd</sup> North Haulage <sup>scals</sup>	20.9	0	0	KK/RL	OK	none obs.	
1 <sup>st</sup> North Haulage	20.9	0	0	KK	OK	none obs	
Storage area	20.9	0	0	KK/RL	OK	none obs	
Washdown	20.9	0	0	KK	OK	none obs	
Trucks	20.9	0	0	KK/RL	OK	none obs	
chargers	20.9	0	0	KK/RL	OK	none obs	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of pre-shift.

Signature

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 4235  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 4954  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 6441  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4735

2MSHA03252

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-27-07

SECTION/AREA Gen Mtn 21 / /

TIME OF EXAMINATION START 4:00 AM/PM END 4:50 AM/PM Examiners Initials DS  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DG</u>	<u>OK</u>	<u>none obs</u>	
<u>N. North haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DG</u>	<u>OK</u>	<u>none obs</u>	
<u>N. West haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>Deep water 6' depth</u>	<u>men working on it Done 1-27-07 SW</u>
<u>5' depth haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Light haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none</u>	
<u>Trucks</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>none</u>	
<u>Charger</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>none</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All other areas appeared safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER CERT. # 4735  
 PRE-SHIFT/MINE EXAMINER CERT. # 6400  
 PRE-SHIFT/MINE EXAMINER CERT. # 7954  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 7485

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-27-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START ~~11:00~~ 11:50 AM/PM AM END ~~12:00~~ 12:30 AM/PM AM  
 TIME OF EXAMINATION START 11:50 AM/PM AM END 12:30 AM/PM AM  
 TIME OF EXAMINATION START 11:00 AM/PM AM END 12:55 AM/PM AM

Examiners Initials [Signature]  
 Examiners Initials [Signature]  
 Examiners Initials FM

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- AM/PM

REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage <sup>SLAIS</sup>	21.0	0	0	SW	OK	none observed	
Main West haulage <sup>SLAIS</sup>	20.9	0	0	FM	OK	none observed	
3rd North haulage <sup>SLAIS</sup>	20.9	0	0	FM	OK	none observed	
1st Right haulage	20.9	0	0	FM	OK	none observed	
Storage Area	20.9	0	0	FM	OK	none observed	
Washdown	20.9	0	0	FM	OK	none observed	
Transformers	21.0	0	0	SW <del>FM</del>	OK	none observed	
Chargers	20.9	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
vent 34	timber knocked out	reset timber

PRE-SHIFT REMARKS all areas appeared reasonable safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINE CERT. # 9548  
 PRE-SHIFT/MINE EXAMINE CERT. # 8397  
 PRE-SHIFT/MINE EXAMINE CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03254

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4 27 07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 8:05 AM/PM AM END 8:30 AM/PM PM Examiners Initials CA  
 TIME OF EXAMINATION START 8:40 AM/PM AM END 9:40 AM/PM PM Examiners Initials TC  
 TIME OF EXAMINATION START 7:30 AM/PM AM END 3:37 AM/PM PM Examiners Initials BD

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	CA	OK	None observed	
Main North Haulage Seals	20.9	0	0	TC/BD	OK	none obs.	
Main West Haulage & seals	20.9	0	0	TC/BD	OK	none obs.	
3rd North Seals Haulage	20.9	0	0	CA	OK	None observed	
1st Right Haulage	20.9	0	0	CA	OK	None observed	
Storage AREA	20.9	0	0	TC	OK	none obs.	
Wash Down	20.9	0	0	TC	OK	none obs.	
Transformers	20.9	0	0	TC/BD	OK	none obs.	
Chargers	20.9	0	0	TC/BD	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe  
at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 03892  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8362  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9599  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 03892

2MSHA03255

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/28/07 SECTION/AREA Gen Mine 1 \_\_\_\_\_

TIME OF EXAMINATION START 4 AM/PM END 4:50 AM/PM Examiners Initials CT  
 TIME OF EXAMINATION START 3:33 AM/PM END 5:36 AM/PM Examiners Initials R  
 TIME OF EXAMINATION START 3:38 AM/PM END 5:26 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	CT	OS	None observed	
Main North Haulage seals	20.9	0	0	TC/BP	OK	None obs.	
Main West Haulage seals	20.9	0	0	TC/BP	OK	None obs.	
3rd No Haulage	20.9	0	0	CT	OS	None observed	
1st Rt. Haulage	20.9	0	0	CT	OS	None observed	
Storage Area	20.9	0	0	TC	OK	None obs.	
Waste dump	20.9	0	0	TC	OK	None obs.	
Trans Rovers	20.9	0	0	TC/BP	OK	None obs.	
Chargers	20.9	0	0	TC/BP	OK	None obs.	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 03892  
 PRE-SHIFT/MINE EXAMINER CERT. # 9362  
 PRE-SHIFT/MINE EXAMINER CERT. # 2599  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03256

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-28-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 11:55  
START 12:50  
START \_\_\_\_\_

~~AM/PM~~  
~~AM/PM~~ PM  
AM/PM

END 1:10 AM/PM  
END 1:50 AM/PM  
END \_\_\_\_\_ AM/PM

Examiners Initials SW  
Examiners Initials dy  
Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage <sup>seats</sup>	21.0	0	0	SW	OK	none observed	
Main West haulage <sup>seats</sup>	21.0	0	0	<del>SW</del> <u>dy</u>	OK	None observed	
3rd North haulage <sup>seats</sup>	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Wash down	21.0	0	0	dy	OK	None observed	
Tractor formers	21.0	0	0	SW	OK	none observed	
chargers	21.0	0	0	<del>SW</del> <u>dy</u>	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

X 112 charging station

LOCATIONS	HAZARDS	ACTIONS
Main West	Plast accumulated dust	Removed trash & dust

PRE-SHIFT REMARKS

all areas examined appear safe at time of preshift

PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 9548  
CERT. # 6622  
CERT. # \_\_\_\_\_  
CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature

CERT. # 7485

2MSHA03257

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/28/07 SECTION/AREA Gen Mine | |

TIME OF EXAMINATION START 8:15 AM/PM AM END 9 AM/PM PM Examiners Initials LP  
 TIME OF EXAMINATION START 7:00 AM/PM AM END 8:50 AM/PM PM Examiners Initials LP  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LP	OK	None observed	
Main North	20.9	0	0	LP	OK	None observed	
Main West Haulage <sup>seals</sup>	20.9	0	0	LP	OK	None observed	
3 <sup>rd</sup> No Haulage <sup>seals</sup>	20.9	0	0	GT	OK	None observed	
1 <sup>st</sup> RT Haulage	20.9	0	0	GT	OK	None observed	
Storage Area	20.9	0	0	LP	OK	None observed	
Wash down	20.9	0	0	LP	OK	None observed	
Transformers	20.9	0	0	LP	OK	None observed	
Chargers	20.9	0	0	LP	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas & travel ways appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 03892  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6908  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 03892

2MSHA03258

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4/29/07 SECTION/AREA Gen Mine 1 1

TIME OF EXAMINATION START 3:02  AM  PM END 4:30  AM  PM Examiners Initials LP  
 TIME OF EXAMINATION START 350  AM  PM END 415  AM  PM Examiners Initials CT  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LP	OK	None observed	
Main North	20.9	0	0	LP	OK	None observed	
Main west Haulage <sup>Seals</sup>	20.9	0	0	LP	OK	None observed	
3rd No Haulage <sup>Seals</sup>	20.9	0	0	CT	OK	None observed	
1st Haulage	20.9	0	0	CT	OK	None observed	
Storage Area	20.9	0	0	LP	OK	None observed	
wash down	20.9	0	0	LP	OK	None observed	
Transformers	20.9	0	0	LP	OK	None observed	
charger	20.9	0	0	LP	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas + Travel ways appeared safe at Time of exam.

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6908  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 03792  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03259

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-29-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 11:55  
 TIME OF EXAMINATION START 11:46  
 TIME OF EXAMINATION START 12:30

AM/PM  
 AM/PM  
 AM/PM

END 1:10 AM/PM  
 END 1:55 AM/PM  
 END 1:15 AM/PM

Examiners Initials JJ  
 Examiners Initials dy  
 Examiners Initials dy

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North <sup>SEALS</sup> haulage	21.0	0	0	SW	OK	none observed	
Main West <sup>SEALS</sup> haulage	21.0	0	0	<del>SW</del>	OK	none observed	
3rd North <sup>SEALS</sup> haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	21.0	0	0	dy	OK	None observed	
Transformers	21.0	0	0	<del>dy</del>	OK	None observed	
Chargers	21.0	0	0	<del>dy</del>	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

Signature

CERT. # 9548  
 CERT. # 6622  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 74885

2MSHA03260

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4 29 07 SECTION/AREA Gen Mine | |

TIME OF EXAMINATION START 8:20 AM/PM AM END 9:10 AM/PM PM Examiners Initials GA  
 TIME OF EXAMINATION START 7:40 AM/PM AM END 9:50 AM/PM PM Examiners Initials TR  
 TIME OF EXAMINATION START 7:36 AM/PM AM END 9:56 AM/PM PM Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	GA	OK	None observed	
MAN North Haulage seals	20.9	0	0	TR/BP	OK	None obs.	
MAN West Haulage seals	20.9	0	0	TR/BP	OK	None obs.	
3rd No Haulage seals	20.9	0	0	GA	OK	None observed	
1st Rt Haulage	20.9	0	0	GA	OK	None observed	
Storage Area	20.9	0	0	BP	OK	None obs.	
Washdown	20.9	0	0	TR	OK	None obs.	
Transformers	20.9	0	0	TR/BP	OK	None obs.	
CHARGERS	20.9	0	0	TR/BP	OK	None obs.	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
MAN West South	Getting gray	Bulk dusted.

PRE-SHIFT REMARKS All Areas appeared safe  
AT Time of Exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 03892  
 CERT. # 9362  
 CERT. # 9399  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_

CERT. # 03892

2MSHA03261

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 43007 SECTION/AREA Gen Mine - 1

TIME OF EXAMINATION START 3:55 AM/PM END 4:38 AM/PM Examiners Initials CA  
 TIME OF EXAMINATION START 3:33 AM/PM END 5:25 AM/PM Examiners Initials BP  
 TIME OF EXAMINATION START 3:50 AM/PM END 5:30 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	CA	OK	None observed	
Mainwest Haulage seals	20.9	0	0	TC/BP	OK	none obs.	
Main North Haulage seals	20.9	0	0	TC/BP	OK	none obs	
3rd No Haulage seals	20.9	0	0	CA	OK	None observed	
1st Rt Haulage	20.9	0	0	CA	OK	None observed	
Storage Area	20.9	0	0	TC	OK	None obs.	
Washdown	20.9	0	0	BP	OK	None obs.	
Transformers	20.9	0	0	TC/BP	OK	None obs	
Chargers	20.9	0	0	TC/BP	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe at  
Time of Exam

Signature

PRE-SHIFT/MINE EXAMINEE CERT. # 03792  
 PRE-SHIFT/MINE EXAMINEE CERT. # 9562  
 PRE-SHIFT/MINE EXAMINEE CERT. # 9579  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4115 2MSHA03262

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-30-07 SECTION/AREA Gen/Min 1 / /

TIME OF EXAMINATION START 11:50 AM/PM END 1:13 AM/PM Examiners Initials FM  
 TIME OF EXAMINATION START 11:00 AM/PM END 1:30 AM/PM Examiners Initials RL/KK  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	
<u>M. North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	
<u>M. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>none observed</u>	
<u>3 North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	
<u>1st Right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none observed</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none observed</u>	
<u>Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u> <u>RL/KK</u>	<u>OK</u>	<u>none observed</u>	
<u>Changover</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u> <u>RL/KK</u>	<u>OK</u>	<u>none observed</u>	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6401  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7951  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature  
 CCOUNTER SIGNATUR CERT. # 4135

2MSHA03263

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 43007 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 7:37 AM/PM AM END 8:24 AM/PM AM Examiners Initials MC  
 TIME OF EXAMINATION START 7:30 AM/PM AM END 9:25 AM/PM AM Examiners Initials MC  
 TIME OF EXAMINATION START 7:00 AM/PM AM END 9:20 AM/PM AM Examiners Initials AD

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	MC	OK	NONE OBSERVED	
MAIN NORTH Haulage	20.9	0	0	MC	OK	NONE OBSERVED	
MAIN WEST Haulage	20.9	0	0	MC/AD	OK	NONE OBSERVED	
3rd No. Haulage	20.9	0	0	MC	OK	NONE OBSERVED	
1st Rt Haulage	20.9	0	0	MC	OK	NONE OBSERVED	
JRANS FARMERS	20.9	0	0	MC	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	MC	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	MC	OK	NONE OBSERVED	
STORAGE AREA	20.9	0	0	MC	OK	NONE OBSERVED	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of pre-shift

PRE-SHIFT/MINE EXAMINEE Signature CERT. # Number Pending  
 PRE-SHIFT/MINE EXAMINEE CERT. # 2375  
 PRE-SHIFT/MINE EXAMINEE CERT. # 8058  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature RT. # 8462

2MSHA03264

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-1-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 3:02 AM/PM  
 TIME OF EXAMINATION START 330 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 3:59 AM/PM  
 END 525 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials PC  
 Examiners Initials DD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking Under ground</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>ok</u>	<u>None Observed</u>	
<u>Main North Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>ok</u>	<u>None Observed</u>	
<u>3rd North Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>ok</u>	<u>None Observed</u>	
<u>Main West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/mc</u>	<u>ok</u>	<u>Deep water # 73 &amp; 75</u>	<u>Sand was to pump pumped 5/1/07</u>
<u>1st Right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>ok</u>	<u>None Observed</u>	
<u>Trans Formers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	
<u>wash down</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

**Signature**

CERT. # 8462  
 CERT. # 8058  
 CERT. # 7375  
 CERT. # \_\_\_\_\_

**Signature**

COUNTER SIGNATURE

CERT. # 4735

2MSHA03265

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-1-07

SECTION/AREA Sanfilippo 1

TIME OF EXAMINATION START 1100 AM/PM  
 TIME OF EXAMINATION START 11:50 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 130 AM/PM  
 END 1:30 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials PL/KK  
 Examiners Initials EM  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>WO Parking</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>α</u>	<u>none observed</u>	
<u>Main North Haulage Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>α</u>	<u>none observed</u>	
<u>Main West Haulage Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM/PL/KK</u>	<u>α</u>	<u>none observed</u>	
<u>3rd N Seals Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>α</u>	<u>none observed</u>	
<u>1st Right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>α</u>	<u>none observed</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PL/KK</u>	<u>α</u>	<u>none observed</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PL/KK</u>	<u>α</u>	<u>none - 1</u>	
<u>Workdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PL</u>	<u>α</u>	<u>none - 1</u>	
<u>Storage Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PL</u>	<u>α</u>	<u>none - 1</u>	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

Signature

CERT. # 6401  
 CERT. # 8297  
 CERT. # 7954  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8762

2MSHA03266

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-1-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 7:30 AM/PM  END 9:28 AM/PM  Examiners Initials MC/DD  
 TIME OF EXAMINATION START 7:00 AM/PM  END 7:38 AM/PM  Examiners Initials Pc  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM  END \_\_\_\_\_ AM/PM  Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>UG Parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>Pc</u>	<u>OK</u>	<u>none observed</u>	
<u>Main North Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>Pc</u>	<u>OK</u>	<u>none observed</u>	
<u>Main West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>MC/DD</u>	<u>OK</u>	<u>none observed</u>	
<u>3rd North Haulage and seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>MC/DD</u>	<u>OK</u>	<u>none observed</u>	
<u>1st Right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>MC</u>	<u>OK</u>	<u>none observed</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>MC/DD</u>	<u>OK</u>	<u>none observed</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>MC/DD</u>	<u>OK</u>	<u>none observed</u>	
<u>Wash down</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>MC</u>	<u>OK</u>	<u>none observed</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>MC</u>	<u>OK</u>	<u>none observed</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8462  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8462

2MSHA03267

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-2-07

SECTION/AREA Gen Mining

TIME OF EXAMINATION START 3:30 AM/PM  
 TIME OF EXAMINATION START 5:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 5:35 AM/PM  
 END 5:32 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials MC/DD  
 Examiners Initials PL  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	PL	OK	None Observed	
MAIN NORTH Haulage SEALS	20.9	0	0	PL	OK	None Observed	
MAIN WEST Haulage SEALS	20.9	0	0	mc/DD	OK	None observed	
3 <sup>RD</sup> NORTH Haulage SEALS	20.9	0	0	mc/DD	OK	None observed	
1 <sup>ST</sup> Right Haulage	20.9	0	0	DD	OK	None observed	
TRANSFORMERS	20.9	0	0	mc/DD	OK	None observed	
CHARGERS	20.9	0	0	mc/DD	OK	None observed	
Washdown	20.9	0	0	DD	OK	None observed	
STORAGE AREA	20.9	0	0	DD	OK	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Signature

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 7521  
 CERT. # 8058  
 CERT. # 8462  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 4135

2MSHA03268

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5.2.07 SECTION/AREA Gen. Mined / /

TIME OF EXAMINATION START 11:27 AM/PM END 1:10 AM/PM Examiners Initials FM/KK  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	RL	OK	none	
Main North haulage Seals	20.9	0	0	RL	K	none	
MAIN West haulage Seals	20.9	0	0	FM KK RL	OK	none observed	
3 <sup>rd</sup> North haulage Seals	20.9	0	0	RL	OK	none	
1 <sup>st</sup> Right	20.9	0	0	RL	OK	none	
Transformers	20.9	0	0	FM KK RL	OK	none observed	
Chargers	20.9	0	0	KK RL	OK	none observed	
Storage Area	20.9	0	0	FM	OK	none observed	
Wash down	20.9	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6406  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7754  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR \_\_\_\_\_ CERT. # 8462

2MSHA03269

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-2-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7:20 AM/PM  
 TIME OF EXAMINATION START 7:30 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 2:50 AM/PM  
 END 9:40 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials PC  
 Examiners Initials MC/DD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	PC	OK	None Observed	
Main North Haulage - seals	20.9	0	0	PC	OK	None Observed	
Main West Haulage - seals	20.9	0	0	MC/DD	OK	None observed	
3rd North Haulage - seals	20.9	0	0	MC/DD	OK	None observed	
1st Right Haulage	20.9	0	0	MC	OK	None observed	
Transformers	20.9	0	0	MC/DD	OK	None observed	
Chargers	20.9	0	0	MC/DD	OK	None observed	
Wash down	20.9	0	0	MC	OK	None observed	
Storage area	20.9	0	0	MC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 8462  
 CERT. # 7371  
 CERT. # 8058  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR

ERT. # 8462

2MSHA03270

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-3-07 SECTION/AREA Gen. M. Sec 1

TIME OF EXAMINATION START 3:50 AM/PM END 5:33 AM/PM Examiners Initials PC  
 TIME OF EXAMINATION START 3:35 AM/PM END 5:40 AM/PM Examiners Initials MC/DD  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	ok	None Observed	
Main North seals	20.9	0	0	PC	ok	None Observed	
Main West Haulage seals	20.9	0	0	MC/DD	ok	None observed	
3rd North Haulage seals	20.9	0	0	MC/DD	ok	None observed	
1st Right Haulage	20.9	0	0	DD	ok	None observed	
TRANSFORMERS	20.9	0	0	MC/DD	ok	None observed	
CHARGERS	20.9	0	0	MC/DD	ok	None observed	
WASHDOWN	20.9	0	0	MC/DD	ok	None observed	
STORAGE AREAS	20.9	0	0	DD	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe AT time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7462  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4735

2MSHA03271

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-3-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 12:05 AM/PM AM END 1:30 AM/PM PM Examiners Initials FM  
 TIME OF EXAMINATION START 11:00 AM/PM AM END 1:00 AM/PM PM Examiners Initials RB/KK  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO \_\_\_\_\_ CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	209	0	0	FM	OK	none observed	
MAIN North haulage seals	209	0	0	FM	OK	none observed	
MAIN West haulage seals	209	0	0	FM RB	OK	none observed	
3rd North haulage seals	209	0	0	FM	OK	none observed	
1st Right	209	0	0	FM	OK	none observed	
Transformers	209	0	0	FM RB	OK	none observed	
Chargers	209	0	0	FM RB	OK	none observed	
wash down	209	0	0	FM	OK	none observed	
Storage Area	209	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 8097  
 PRE-SHIFT/MINE EXAMINEE CERT. # 606  
 PRE-SHIFT/MINE EXAMINEE CERT. # 7959  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 8462

2MSHA03272

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-3-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 7:43 AM/PM AM END 8:15 AM/PM AM Examiners Initials R  
 TIME OF EXAMINATION START 7:30 AM/PM AM END 9:25 AM/PM AM Examiners Initials mc/DD  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	R	OK	None Observed	
Main North <sup>Haulage</sup> <sub>Seals</sub>	20.9	0	0	R	OK	None Observed	
Main West <sup>Haulage</sup> <sub>Seals</sub>	20.9	0	0	mc/DD	OK	None Observed	
3 <sup>rd</sup> North <sup>Haulage</sup> <sub>Seals</sub>	20.9	0	0	mc/DD	OK	None Observed	
1 <sup>st</sup> Right	20.9	0	0	mc	OK	None Observed	
Transformers	20.9	0	0	mc/DD	OK	None Observed	
Chargers	20.9	0	0	mc/DD	OK	None Observed	
Wash Down	20.9	0	0	mc	OK	None Observed	
Storage Area	20.9	0	0	mc	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINE CERT. # 9293  
 PRE-SHIFT/MINE EXAMINE CERT. # 7325  
 PRE-SHIFT/MINE EXAMINE CERT. # 8058  
 PRE-SHIFT/MINE EXAMINE CERT. # \_\_\_\_\_

Signature \_\_\_\_\_ RT. # 8462

COUNTER SIGNATURE \_\_\_\_\_

2MSHA03273

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-4-07

SECTION/AREA Gen. M. Seal

TIME OF EXAMINATION START 3:30  AM  PM  
 TIME OF EXAMINATION START 3:00  AM  PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 4:55  AM  PM  
 END 4:15  AM  PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials FM/MC  
 Examiners Initials DD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	α	none observed	
MAIN North haulage seals	20.9	0	0	DD	α	none observed	
MAIN West haulage seals	20.9	0	0	DD MC FM	α	none observed	
3 <sup>rd</sup> North haulage seals	20.9	0	0	DD	α	none observed	
1 <sup>st</sup> Right	20.9	0	0	DD	α	None observed	
Transformers	20.9	0	0	MC DD	α	None observed	
Chargers	20.9	0	0	MC DD	α	none observed	
Wash down	20.9	0	0	MC	α	None observed	
Storage Area	20.9	0	0	FM	α	None Observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 7485

2MSHA03274

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-4-07 SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 11:55 AM/PM END 1:15 AM/PM Examiners Initials SW  
 TIME OF EXAMINATION START 11:45 AM/PM END 115 AM/PM Examiners Initials dy  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES (NO) CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage <sup>SEALS</sup>	20.9	0	0	SW	OK	none observed	
Main West haulage <sup>SEALS</sup>	20.9	0	0	SW <sup>dy</sup>	OK	none observed	
3 <sup>rd</sup> North haulage <sup>SEALS</sup>	20.9	0	0	SW	OK	none observed	
1 <sup>st</sup> Right haulage	20.9	0	0	SW <sup>dy</sup>	OK	none observed	
Transformers	20.9	0	0	<del>SW</del> <sup>dy</sup>	OK	none observed	
Chargers	20.9	0	0	<del>SW</del> <sup>dy</sup>	OK	None observed	
Washdown	20.9	0	0	dy	OK	none observed	
Storage Area	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 9548  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 6622  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 7485 2MSHA03275

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-4-07 SECTION/AREA Gen Mining | |

TIME OF EXAMINATION START 7:48 AM/PM AM END 9:20 AM/PM PM Examiners Initials BH  
 TIME OF EXAMINATION START 7:47 AM/PM AM END 9:01 AM/PM PM Examiners Initials JK  
 TIME OF EXAMINATION START 7:40 AM/PM AM END 9:10 AM/PM PM Examiners Initials RP

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North <small>Haulage Seals</small>	20.9	0	0	BH	OK	None Observed	
Main West <small>Haulage Seals</small>	20.9	0	0	BH/JP	OK	none obs.	
3 <sup>rd</sup> North <small>Haulage Seals</small>	20.9	0	0	BH	OK	None Observed	
1 <sup>st</sup> Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/JP	OK	None obs.	
Chargers	20.9	0	0	BH/JP	OK	none obs.	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe  
AT Time of Exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER CERT. # 9367  
 PRE-SHIFT/MINE EXAMINER CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER CERT. # 9379  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE CERT. # 03892

2MSHA03276

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-5-07 SECTION/AREA Genitive 1

TIME OF EXAMINATION START 3:40 AM/PM END 4:50 AM/PM Examiners Initials TC  
 TIME OF EXAMINATION START 3:41 AM/PM END 5:51 AM/PM Examiners Initials BD  
 TIME OF EXAMINATION START 3:47 AM/PM END 5:25 AM/PM Examiners Initials OK

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	BH	OK	None obs.	
MAIN north haulage & seals	20.9	0	0	BH	OK	None obs.	
MAIN west haulage & seals	20.9	0	0	TC/BP BH	OK	None obs.	
3rd north haulage seals	20.9	0	0	BH	OK	None obs.	
1st Right haulage	20.9	0	0	BH	OK	None obs.	
TRANS formers	20.9	0	0	TC/BP BH	OK	None obs.	
CHARGERS	20.9	0	0	TC/BP BH	OK	None obs.	
Washdown	20.9	0	0	BH	OK	None obs.	
Storage Area	20.9	0	0	BH	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362  
 PRE-SHIFT/MINE EXAMINER CERT. # 8399  
 PRE-SHIFT/MINE EXAMINER CERT. # 6395  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 7485

2MSHA03277

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-5-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 11:45 AM/PM  
 TIME OF EXAMINATION START 12:30 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1:10 AM/PM  
 END 1:20 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials SW  
 Examiners Initials LD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North <sup>haulage</sup> Seals	20.9	0	0	SW	OK	none observed	
Main West <sup>haulage</sup> Seals	20.9	0	0	<del>SW</del>	OK	none observed	
3rd North <sup>Seals</sup> haulage	20.9	0	0	SW	OK	none observed	
1st Right haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>SW</del>	OK	none observed	
Chargers	20.9	0	0	<del>SW</del>	OK	none observed	
Washdown	20.9	0	0	LD	OK	none observed	
Storage Area.	20.9	0	0	SW	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
Main North	loose rib	bar down

PRE-SHIFT REMARKS all areas appeared safe at the time of exam

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 9548  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 9660  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03278

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5507 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 8:10 AM/PM AM END 8:50 AM/PM PM Examiners Initials CA  
 TIME OF EXAMINATION START 7:55 AM/PM PM END 9:45 AM/PM PM Examiners Initials TC  
 TIME OF EXAMINATION START 7:44 AM/PM PM END 9:45 AM/PM PM Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	CA	OK	None observed	
Main North <sup>Haulage</sup> seals	20.9	0	0	BH/TC	OK	None Observed	
Main West <sup>Haulage</sup> seals	20.9	0	0	BH/TC	OK	None Observed	
3rd No. <sup>Seals</sup> Haulage	20.9	0	0	CA	OK	None observed	
1st Rt Haulage	20.9	0	0	CA	OK	None observed	
Transformers	20.9	0	0	BH/TC	OK	None Observed	
Chargers	20.9	0	0	BH/TC	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH/TC	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Hrt seal 3No	Loose top	Scaled down & 5507

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 03892  
 PRE-SHIFT/MINE EXAMINER CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER CERT. # 9302  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 03892

2MSHA03279

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-6-07 SECTION/AREA Gen mt

TIME OF EXAMINATION START 3:00  AM  PM END 4:20  AM  PM Examiners Initials TC  
 TIME OF EXAMINATION START 3:00  AM  PM END 4:15  AM  PM Examiners Initials BP  
 TIME OF EXAMINATION START 3:44  AM  PM END 5:35  AM  PM Examiners Initials DT

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE  
 CALLED OUT BY \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	BH	OK	None Obs.	
MAIN NORTH Haulage & Seals	20.9	0	0	BH	OK	None Obs.	
MAIN WEST Haulage & Seals	20.9	0	0	TC/BP BH	OK	None Obs.	
3rd North Haulage Seals	20.9	0	0	BH	OK	None Obs.	
1st Right Haulage	20.9	0	0	BH	OK	None Obs.	
TRANSFORMERS	20.9	0	0	TC/BP BH	OK	None Obs.	
Chargers	20.9	0	0	TC/BH	OK	None Obs.	
Washdown	20.9	0	0	BH	OK	None Obs.	
Storage Area	20.9	0	0	BH	OK	None Obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 9362  
 PRE-SHIFT/MINE EXAMINEE CERT. # 2520  
 PRE-SHIFT/MINE EXAMINEE CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7485 2MSHA03280

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-6-07 SECTION/AREA ~~General Mine~~ General Mine 1

TIME OF EXAMINATION START 11:50 AM/PM END 1:10 AM/PM Examiners Initials SW  
 TIME OF EXAMINATION START 1245 AM/PM END 115 AM/PM Examiners Initials dy  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage <sup>SLATS</sup>	20.9	0	0	SW	OK	none observed	
Main West haulage <sup>SLATS</sup>	20.9	0	0	<del>SW</del> dy	OK	none observed	
3 <sup>rd</sup> North haulage <sup>SLATS</sup>	20.9	0	0	SW	OK	none observed	
1 <sup>st</sup> Right haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>SW</del> dy	OK	none observed	
chargers	20.9	0	0	<del>SW</del> dy	OK	none observed	
Washdown	20.9	0	0	dy	OK	none observed	
Storage Area.	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9548  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6622  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 7485

2MSHA03281

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-6-07 SECTION/AREA General Mine

TIME OF EXAMINATION START 7:45 AM/PM AM END 9:30 AM/PM PM  
 TIME OF EXAMINATION START 8:09 AM/PM AM END 9:40 AM/PM PM  
 TIME OF EXAMINATION START 9:30 AM/PM AM END 9:58 AM/PM PM

Examiners Initials TR  
 Examiners Initials BH  
 Examiners Initials BP

EXAM. CALLED OUT ----- YES  CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Lib. Packing	20.9	0	0	BH	OK	None obs.	
Main North Haulage & seals	20.9	0	0	BH	OK	None obs.	
Main West Haulage & seals	20.9	0	0	BP/PC BP	OK	Water Acc at Xcut 7.3 main west	PLW m/d/m/s SET up pump 5 done 5-7-07
3rd North Haulage & seals	20.9	0	0	BH	OK	None obs.	
1st Right Haulage	20.9	0	0	BH	OK	None obs.	
TRANSFORMERS	20.9	0	0	TR/BP BH	OK	None obs	
Chargers	20.9	0	0	BH/BP	OK	None obs	
Washdown	20.9	0	0	BH	OK	None obs.	
Storage Areas	20.9	0	0	BH	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe  
at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362  
 PRE-SHIFT/MINE EXAMINER CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER CERT. # 9599  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03282

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-7-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 3:05 AM/PM END 4:40 AM/PM Examiners Initials BH  
 TIME OF EXAMINATION START 4:08 AM/PM END 5:16 AM/PM Examiners Initials TC  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Main North Harlage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC</u>	<u>OK</u>	<u>none obs.</u>	
<u>Packing Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC</u>	<u>OK</u>	<u>none obs.</u>	
<u>Main West Harlage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>OK</u>	<u>Deep water x-cut 73</u>	<u>pumped down 5-7-07</u>
<u>M3<sup>rd</sup> North Harlage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC/BH</u>	<u>OK</u>	<u>none obs.</u>	
<u>1<sup>st</sup> Right Harlage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC</u>	<u>OK</u>	<u>none obs.</u>	
<u>All Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>OK</u>	<u>none obs.</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>OK</u>	<u>none obs.</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>none obs.</u>	
<u>Storage Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>OK</u>	<u>none obs.</u>	
<u>Kitchen</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC</u>	<u>OK</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS other than noted above  
All Areas safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8395  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 9362  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8462

2MSHA03283

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-7-07

SECTION/AREA Emblem 1

TIME OF EXAMINATION START 11:05  AM/PM  
 TIME OF EXAMINATION START 11:47  AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_  AM/PM

END 12:20 AM/PM   
 END 12:15 AM/PM   
 END \_\_\_\_\_ AM/PM

Examiners Initials KK/RR  
 Examiners Initials FM  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	
<u>M. North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	
<u>M. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RR</u>	<u>OK</u>	<u>none obs</u>	
<u>3. north</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>None obs</u>	
<u>1st Right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Trucks</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RR</u>	<u>OK</u>	<u>none obs</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RR</u>	<u>OK</u>	<u>None obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of EXAM

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_

CERT. # 7954  
 CERT. # 8297  
 CERT. # 4375  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE

CERT. # 8462

2MSHA03284

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-7-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 7:45  
START 7:00  
START \_\_\_\_\_

AM/PM  
AM/PM  
AM/PM

END 9:20 AM/PM  
END 8:30 AM/PM  
END \_\_\_\_\_ AM/PM

Examiners Initials BH/TC  
Examiners Initials DD  
Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	OK	None Observed	
Main North Haulage Seals	20.9	0	0	DD	OK	None Observed	
Main West Haulage Seals	20.9	0	0	BH/TC DD	OK	None Observed	
3 <sup>rd</sup> North Haulage Seals	20.9	0	0	DD	OK	None Observed	
1 <sup>st</sup> Right Haulages	20.9	0	0	DD	OK	None Observed	
Transformer	20.9	0	0	BH/TC DD	OK	None Observed	
Chargers	20.9	0	0	BH/TC DD	OK	None Observed	
Washdown	20.9	0	0	DD	OK	None Observed	
Storage Area	20.9	0	0	BH/TC DD	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonable safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER

CERT. # 8395  
CERT. # 9362  
CERT. # 8058  
CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATUR

CERT. # 8462

2MSHA03285

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-8-07

SECTION/AREA Ben Mine 1

TIME OF EXAMINATION START 3:30  
 TIME OF EXAMINATION START 3:20  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM AM END 4:08 AM/PM  
 AM/PM AM END 5:18 AM/PM  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM

Examiners Initials JR  
 Examiners Initials DD/PL  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	JR	OK	None Observed	
Main North Haulage <sup>seals</sup>	20.9	0	0	JR	OK	None Observed	
West Mains Haulage <sup>seals</sup>	20.7	0	0	DD/PL	OK	none obs.	
3 <sup>rd</sup> North Haulage <sup>seals</sup>	20.9	0	0	DD/PL	OK	none obs.	
1 <sup>st</sup> Right	20.7	0	0	DD/PL	OK	none obs.	
Storage area	20.7	0	0	DD	OK	none obs.	
Wash down	20.9	0	0	PL	OK	none obs.	
Transformers	20.7	0	0	DD/PL	OK	none obs.	
Chargers	20.7	0	0	DD/PL	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE  
 PRE-SHIFT/MINE EXAMINE

CERT. # 9293  
 CERT. # 8462  
 CERT. # 8058  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR

CERT. # 4735

2MSHA03286

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-8-07 SECTION/AREA Central

TIME OF EXAMINATION START 11:48  AM  PM END 1:17  AM  PM Examiners Initials FM  
 TIME OF EXAMINATION START 11:00  AM  PM END 1:29  AM  PM Examiners Initials KR/RR  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>209</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	
<u>N. North Haulage</u>	<u>209</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	
<u>W. West Haulage</u>	<u>209</u>	<u>0</u>	<u>0</u>	<u>FM</u> <u>KR/RR</u>	<u>OK</u>	<u>none obs</u>	
<u>3rd North Haulage</u>	<u>209</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	
<u>1st North Haulage</u>	<u>209</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	
<u>Trams</u>	<u>209</u>	<u>0</u>	<u>0</u>	<u>FM</u> <u>KR/RR</u>	<u>OK</u>	<u>none obs</u>	
<u>chargers</u>	<u>209</u>	<u>0</u>	<u>0</u>	<u>FM</u> <u>KR/RR</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>209</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	
<u>Workshop</u>	<u>209</u>	<u>0</u>	<u>0</u>	<u>FM</u>	<u>OK</u>	<u>none observed</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam  
 \_\_\_\_\_  
 Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 4375  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 7954  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_  
 Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4135

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-8-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7:00  
 TIME OF EXAMINATION START 7:40  
 TIME OF EXAMINATION START 7:20

AM/PM AM END 7:59 AM/PM AM  
 AM/PM AM END 9:45 AM/PM AM  
 AM/PM AM END 9:45 AM/PM AM

Examiners Initials PC  
 Examiners Initials TC  
 Examiners Initials DD

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>OK</u>	<u>None Observed</u>	
<u>Main North seals</u> <small>Haulage</small>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>OK</u>	<u>None Observed</u>	
<u>Main West seals</u> <small>Haulage</small>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC/DD</u>	<u>OK</u>	<u>None observed</u>	
<u>3<sup>rd</sup> North seals</u> <small>Haulage</small>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC/DD</u>	<u>OK</u>	<u>None observed</u>	
<u>1<sup>st</sup> Right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC/DD</u>	<u>OK</u>	<u>none observed</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC/DD</u>	<u>OK</u>	<u>none observed</u>	
<u>Wash down</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC</u>	<u>OK</u>	<u>none observed</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC/DD</u>	<u>OK</u>	<u>none observed</u>	
<u>Changers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC/DD</u>	<u>OK</u>	<u>none observed</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 8462  
 CERT. # 9362  
 CERT. # 8058  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03288

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-9-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 4:30 AM/PM  
 TIME OF EXAMINATION START 3:35 AM/PM  
 TIME OF EXAMINATION START 3:29 AM/PM

END 5:00 AM/PM  
 END 5:50 AM/PM  
 END 5:50 AM/PM

Examiners Initials PC  
 Examiners Initials TC  
 Examiners Initials DD

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None observed	
Main North <sup>Haulage</sup> seals	20.9	0	0	PC	OK	None observed	
Main West <sup>Haulage</sup> seals	20.9	0	0	TC/DD	OK	none observed	
3rd North <sup>Haulage</sup> seals	20.9	0	0	TC/DD	OK	none observed	
1st Right	20.9	0	0	DD	OK	none observed	
Storage area	20.9	0	0	DD	OK	None observed	
Wash down	20.9	0	0	DD	OK	none observed	
Transformers	20.9	0	0	TC/DD	OK	none observed	
Chargers	20.9	0	0	TC/DD	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of Exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 9362  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4735

2MSHA03289

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-9-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 11:00 ~~AM/PM~~ END 1:20 ~~AM/PM~~ Examiners Initials AR/KK  
 TIME OF EXAMINATION START 11:59 ~~AM/PM~~ END 1:23 ~~AM/PM~~ Examiners Initials FM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES (NO) CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
Mine North Seals <sup>haulage</sup>	20.9	0	0	FM	OK	none observed	
Mine West Seals <sup>haulage</sup>	20.9	0	0	FM/KK/LR	FM/KK/LR OK	none observed	
3rd North Seals <sup>haulage</sup>	20.9	0	0	FM	OK	none observed	
1st Right	20.9	0	0	FM	OK	none observed	
Storage Area	20.9	0	0	FM	OK	none observed	
Wash down	20.9	0	0	FM	OK	none observed	
Transformers	20.9	0	0	FM/KK/LR	FM/KK/LR OK	none observed	
Chargers	20.9	0	0	FM/KK/LR	FM/KK/LR OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

Signature

PRE-SHIFT/MINE EXAMINI  
 PRE-SHIFT/MINE EXAMINI  
 PRE-SHIFT/MINE EXAMINI  
 PRE-SHIFT/MINE EXAMINI

CERT. # 4325  
 CERT. # 8297  
 CERT. # 7954  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

:# 8462

2MSHA03290

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-9-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 4:10 AM/PM  AM  PM END 9:00 AM/PM  AM  PM Examiners Initials TC  
 TIME OF EXAMINATION START 7:15 AM/PM  AM  PM END 9:15 AM/PM  AM  PM Examiners Initials DD  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Ub Parking Area	20.5	0	0	TC	OK	none obs.	
Main north Haulage scale	20.5	0	0	TC	OK	none obs.	
Main west Haulage scale	20.9	0	0	DD	OK	none obs.	
3rd North <sup>Haulage</sup> scale	20.5	0	0	TC/DD	OK	none obs.	
1st Rig LA	20.9	0	0	TC	OK	none obs.	
Storage Area	20.9	0	0	DD	OK	none obs.	
Wash Down	20.9	0	0	DD	OK	none obs.	
Transformers	20.5	0	0	TC/DD	OK	none obs.	
Chargers	20.9	0	0	DD	OK	none obs.	
Kitchen	20.9	0	0	DD	OK	none obs.	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 9362  
 CERT. # 8058  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE

ERT. # 8167

2MSHA03291

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-10-07 SECTION/AREA Gen. Mine 1

TIME OF EXAMINATION START 3:30 AM/PM END 5:37 AM/PM Examiners Initials TE  
 TIME OF EXAMINATION START 3:28 AM/PM END 5:40 AM/PM Examiners Initials DD  
 TIME OF EXAMINATION START 3:20 AM/PM END 5:38 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES  CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	TC/DD	OK	none obs.	
Main north Haulage & seals	20.9	0	0	TC/PC/DD	OK	none obs.	
Main west Haulage & seals	20.9	0	0	TC/DD	OK	none obs.	
3rd North Haulage Seals	20.9	0	0	TC/DD	OK	none obs.	
1st Right Haulage	20.9	0	0	DD	OK	none obs.	
Storage Area	20.9	0	0	TC	OK	none obs.	
Wash Down	20.9	0	0	DD	OK	none obs.	
Transformers	20.9	0	0	TC/PC/DD	OK	none obs.	
Chargers	20.9	0	0	TC/DD	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Area appeared safe  
At time of Exa

Signature

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXA-----

CERT. # 9362  
 CERT. # 8058  
 CERT. # 7462  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR

CERT. # 478

2MSHA03292

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-10-07

SECTION/AREA General

TIME OF EXAMINATION START 11:00 AM/PM  
 TIME OF EXAMINATION START 11:50 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END \_\_\_\_\_ AM/PM  
 END 1:17 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KR/WR  
 Examiners Initials FM  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parting area	20.9	0	0	FM	α	none observed	
Mid West Haulage	20.9	0	0	KR/WR	α	none obs	
Mid North Haulage	20.9	0	0	FM	α	none observed	
3rd North Haulage	20.9	0	0	FM	α	none observed	
1st right Haulage	20.9	0	0	FM	α	none observed	
Storage area	20.9	0	0	FM	α	none observed	
Washdown	20.9	0	0	FM	α	none observed	
trans	20.9	0	0	KR/WR	α	none observed	
chargers	20.9	0	0	KR/WR	α	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved Safe at time of Exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 7954  
 CERT. # 4375  
 CERT. # 8297  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_

CERT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-10-07 SECTION/AREA Gen Mae 1

TIME OF EXAMINATION START 7:44 AM/PM AM END 8:18 AM/PM AM Examiners Initials JR  
 TIME OF EXAMINATION START 7:20 AM/PM AM END 7:45 AM/PM AM Examiners Initials DD/PC  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>V6 Parking</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JR</u>	<u>OK</u>	<u>None Observed</u>	
<u>Main North Haulage &amp; seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JR</u>	<u>OK</u>	<u>None Observed</u>	
<u>Main West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/PC</u>	<u>ok</u>	<u>none obs.</u>	
<u>3rd North Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	
<u>1st Right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	
<u>Storage Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>ok</u>	<u>none obs.</u>	
<u>Wash down</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>ok</u>	<u>none obs.</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/PC</u>	<u>ok</u>	<u>none obs.</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

\_\_\_\_\_  
 Signature  
 PRE-SHIFT/MINE EXAMINER CERT. # 9293  
 PRE-SHIFT/MINE EXAMINER CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER CERT. # 8462  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

\_\_\_\_\_  
 Signature  
 COUNTER SIGNATURE CERT. # 8462

2MSHA03294

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-16-07

SECTION/AREA Level 1

TIME OF EXAMINATION START 5:10 AM/PM  
 TIME OF EXAMINATION START 3:00 AM/PM  
 TIME OF EXAMINATION START 5:37 AM/PM

END 5:15 AM/PM  
 END 5:35 AM/PM  
 END 5:57 AM/PM

Examiners Initials RK  
 Examiners Initials DD PC  
 Examiners Initials BH/FE

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/FE</u>	<u>OK</u>	<u>none observed</u>	
<u>M. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/FE</u>	<u>OK</u>	<u>None Observed</u>	
<u>M. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/PC</u>	<u>ok</u>	<u>none obs.</u>	
<u>3 West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/PC</u>	<u>ok</u>	<u>none obs</u>	
<u>1st Right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>ok</u>	<u>none obs.</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD</u>	<u>ok</u>	<u>none obs.</u>	
<u>Workdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>PC</u>	<u>ok</u>	<u>none obs.</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/PC</u>	<u>ok</u>	<u>none obs.</u>	
<u>Trams</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DD/PC</u>	<u>ok</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
<u>X-73 west</u>	<u>Deep Water</u>	<u>Pumped</u>

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 8058  
 CERT. # 8395  
 CERT. # 9362  
 CERT. # 8462

COUNTER SIGNATURE Signature CERT. # 03992

2MSHA03295

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-11-07 SECTION/AREA Gen Mineral

TIME OF EXAMINATION START 11:52 ~~AM~~/PM END 1:20 AM/~~PM~~  
 TIME OF EXAMINATION START 12:00 AM/~~PM~~ END 1:40 AM/~~PM~~  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials YB/C  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
MAIN North haulage seals	20.9	0	0	FM	OK	none observed	
MAIN West haulage seals	20.9	0	0	FM/BH/TC	OK	None Observed	
3rd North haulage seals	20.9	0	0	FM	OK	none observed	
1st Right	20.9	0	0	FM	OK	none observed	
Transformers	20.9	0	0	FM/BH/TC	OK	None Observed	
chargers	20.9	0	0	FM/BH/TC	OK	None Observed	
washdown	20.9	0	0	FM	OK	none observed	
storage Area	20.9	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9362  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03296

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-11-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 7:55  
 TIME OF EXAMINATION START 8:40  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM AM END 9:15 AM/PM PM  
 AM/PM PM END 9:15 AM/PM PM  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials SW  
 Examiners Initials dy  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North <sup>SEAB</sup> haulage	20.9	0	0	SW	OK	none observed	
Main West <sup>SEAB</sup> haulage	20.9	0	0	<del>SW</del> dy	OK	None observed	
3 <sup>rd</sup> North <sup>SEAB</sup> haulage	20.9	0	0	SW	OK	none observed	
1 <sup>st</sup> Right haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>SW</del> dy	OK	None observed	
chargers	20.9	0	0	<del>SW</del> dy	OK	None observed	
Washdown	20.9	0	0	dy	OK	None observed	
Storage Area.	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 9548  
 CERT. # 6622  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7485

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-12-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 3:47 AM/PM  
 TIME OF EXAMINATION START 4:30 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 5:30 AM/PM  
 END 5:10 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials SW  
 Examiners Initials LD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage	20.9	0	0	SW	OK	none observed	
Main West haulage	20.9	0	0	<del>LD</del> SW	OK	none observed	
3rd North haulage	20.9	0	0	SW	OK	none observed	
1st Right haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>LD</del> SW	OK	none observed	
Chargers	20.9	0	0	<del>LD</del> SW	OK	Section Scoop Charging Station ACCTrash dust	sent people to clean dust. Done OK
Washdown	20.9	0	0	LD	OK	none observed	
Storage Area	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main North	timber knocked out	reset timber

PRE-SHIFT REMARKS all areas appeared safe at time of exam except those noted above,

Signature

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINER

CERT. # 9548  
 CERT. # 9660  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 03892

2MSHA03298

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-12-07 SECTION/AREA General Mine 1

TIME OF EXAMINATION START 11:47 ~~AM/PM~~ END 12:45 AM/PM Examiners Initials TC  
 TIME OF EXAMINATION START 11:52 ~~AM/PM~~ END 1:28 AM/PM Examiners Initials BH  
 TIME OF EXAMINATION START 12:00 ~~AM/PM~~ END 12:20 AM/PM Examiners Initials BP

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None obs.	
Main North Haulage Seals	20.9	0	0	BH	OK	None obs.	
Main West Haulage & seals	20.9	0	0	TC/BP BH	OK	None obs.	
3rd North Haulage Seals	20.9	0	0	BH	OK	None obs.	
1st Right Haulage				BH	OK	None Observed	
Transformers	20.9	0	0	TC/BP BH	OK	None obs.	
Chargers	20.9	0	0	BP/BH	OK	None obs.	
Washdown	20.9	0	0	BH	OK	None obs.	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINE Signature CERT. # 9362  
 PRE-SHIFT/MINE EXAMINE CERT. # 8395  
 PRE-SHIFT/MINE EXAMINE CERT. # 9594  
 PRE-SHIFT/MINE EXAMINE CERT. # \_\_\_\_\_

Signature  
 CERT. # 03892

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_ 2MSHA03299

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-12-07

SECTION/AREA General Mine / /

TIME OF EXAMINATION START 7:00  
 TIME OF EXAMINATION START 8:35  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM (M) END 8:20 AM/PM (M)  
 AM/PM (M) END 9:10 AM/PM (M)  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials SW  
 Examiners Initials JD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage <sup>SEALS</sup>	20.9	0	0	SW	OK	none observed	
Main West haulage <sup>SEALS</sup>	20.9	0	0	<del>JD</del> SW	OK	none observed	
3rd North haulage <sup>SEALS</sup>	20.9	0	0	SW	OK	none observed	
1st Right haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>JD</del> SW	OK	none observed	
chargers	20.9	0	0	<del>JD</del> SW	OK	none observed	
Washdown	20.9	0	0	JD	OK	none observed	
Storage Area.	20.9	0	0	SW	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

**PRE-SHIFT REMARKS**

all areas appeared safe at the time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 9548  
 CERT. # 9660  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature

**COUNTER SIGNATURE**

CERT. # 7485

2MSHA03300

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5/30/07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 3:35  AM  PM END 5:30  AM  PM  
 TIME OF EXAMINATION START 3:55  AM  PM END 5:40  AM  PM  
 TIME OF EXAMINATION START \_\_\_\_\_  AM  PM END \_\_\_\_\_  AM  PM

Examiners Initials [Signature]  
 Examiners Initials [Signature]  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking area	20.9	0	0	SW	OK	none observed	
Main Seals	20.9	0	0	SW	OK	none observed	
NORTH Haulage	20.9	0	0	SW	OK	none observed	
Main Pumps Seals	20.9	0	.1	SW	OK	none observed	
WEST Haulage	20.9	0	0	SW	OK	none observed	
3RD NO Haulage Seals	20.9	0	0	SW	OK	none observed	
1ST Right Haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW	OK	none observed	
chargers	20.9	0	0	SW	OK	none observed	
Wash down	20.9	0	0	dy	OK	none observed	
Storage area	20.9	0	0	SW	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6622  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9548  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 03992

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-13-07

SECTION/AREA Gen mine 1 1

TIME OF EXAMINATION START 11:46 AM/PM  
 TIME OF EXAMINATION START 12:35 AM/PM  
 TIME OF EXAMINATION START 12:20 AM/PM

END 1:30 AM/PM Examiners Initials BH  
 END 12:40 AM/PM Examiners Initials BP  
 END 12:52 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME -----          AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North <sup>Haulage</sup> Seals	20.9	0	0	BH	OK	None Observed	
Main West <sup>Haulage</sup> Seals	20.9	0	0	BH/BP	OK	None Observed	
3 <sup>rd</sup> North <sup>Haulage</sup> Seals	20.9	0	0	BH	OK	None Observed	
1 <sup>st</sup> Right <sup>Haulage</sup> Seals	20.9	0	0	BH	OK	None Observed	
Parking Area	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/TC	OK	None Observed	
Chargers	20.9	0	0	BH/TC	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 8395  
 PRE-SHIFT/MINE EXAMINEE CERT. # 9367  
 PRE-SHIFT/MINE EXAMINEE CERT. # 9399  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 03892

2MSHA03302

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-13-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 7:50  
START 8:20  
START \_\_\_\_\_

AM/PM (M)  
AM/PM (M)  
AM/PM \_\_\_\_\_

END 9:05 AM/PM  
END 9:20 AM/PM  
END \_\_\_\_\_

Examiners Initials SW  
Examiners Initials dy  
Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage <sup>SCALS</sup>	20.9	0	0	SW	OK	none observed	
Main West haulage <sup>SCALS</sup>	20.9	0	.2	<del>SW</del> <sup>dy</sup>	OK	None observed	
3rd North haulage <sup>SCALS</sup>	20.9	0	0	SW	OK	none observed	
1st Right haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>SW</del> <sup>dy</sup>	OK	None observed	
chargers	20.9	0	0	<del>SW</del> <sup>dy</sup>	OK	None observed	
Washdown	20.9	0	0	dy	OK	None observed	
Storage Area.	20.9	0	0	SW	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main North haulage	tripping hazard #7 SCAL	removed

PRE-SHIFT REMARKS all areas examined appear safe at Time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINE  
PRE-SHIFT/MINE EXAMINE  
PRE-SHIFT/MINE EXAMINE  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 9548  
CERT. # 6622  
CERT. # \_\_\_\_\_  
CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03303

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5/4/07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 3:05 AM/PM  
 TIME OF EXAMINATION START 3:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 5 AM/PM  
 END 4:12 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials dy  
 Examiners Initials SW  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES  NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking Lot	20.9	0	0	SW	OK	none observed	
Main North Haulage Seals	20.9	0	0	SW	OK	none observed	
Main Pump Seals West Haulage	20.9	0	.2	SW/dy	OK	Roadway DRY Roads	Watered Roads
3rd No Haulage Seals	20.9	0	0	SW	OK	none observed	
1st Right Haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW/dy	OK	None observed	
Chargers	20.9	0	0	SW/dy	OK	None observed	
wash down	20.9	0	0	dy	OK	None observed	
Storage areas	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear reasonably safe at times of pre-shift except what is noted above

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6623  
 PRE-SHIFT/MINE EXAMINER CERT. # 9548  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_  
 ERT. # 8462

2MSHA03304

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-14-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 1130 AM/PM END 115 AM/PM Examiners Initials DD mc  
 TIME OF EXAMINATION START 1146 AM/PM END 110 AM/PM Examiners Initials FM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
U.G. Parking	20.9	0	0	FM	α	none observed	
main north Haulage Seals	20.9	0	0	FM	α	none observed	
west mine Haulage Seals	20.9	0	0	DD/mc	ok	none obs.	
3 <sup>rd</sup> North Haulage <sup>seals</sup>	20.9	0	0	FM	α	none observed	
1 <sup>st</sup> Right Haulage	20.9	0	0	FM	α	none observed	
Transformers	20.9	0	0	DD/mc FM	ok	none obs.	
chargers	20.9	0	0	DD/mc FM	ok	none obs	
Wash down	20.9	0	0	mc	ok	none obs.	
Storage Area	20.9	0	0	mc	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of exam

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 2373  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_  
 COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4735

2MSHA03305

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-14-07

SECTION/AREA Coal Mine 1

TIME OF EXAMINATION START 7:00 AM/PM  
 TIME OF EXAMINATION START 7:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 9:30 AM/PM  
 END 9:00 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials RL  
 Examiners Initials LR/KR  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking Lot	20.9	0	0	RL	0	none	
Main North Haulage Seals	20.9	0	0	RL	0	none	
Main West Haulage Seals	20.9	0	0	RL/LR/KR	0	Deep water 73xc	working on pumps 5-14-07
2nd North Haulage Seals	20.9	0	0	RL	0	none	
1st North Haulage	20.9	0	0	RL	0	none	
Transformers	20.9	0	0	RL/LR/KR	0	none	
Chargers	20.9	0	0	RL/LR/KR	0	none	
Washdown	20.9	0	0	RL	0	none	
Storage area	20.9	0	0	RL	0	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at time of Exam except as noted above

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 6401  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 4375  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 7954  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

RT. # 4735

2MSHA03306

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5.15.07 SECTION/AREA Gen 1

TIME OF EXAMINATION START 306 (AM) PM END \_\_\_\_\_ AM/PM Examiners Initials LR/RR  
 TIME OF EXAMINATION START 300 (AM) PM END 530 (AM) PM Examiners Initials RL  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>N. North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>N. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RR/RL</u>	<u>OK</u>	<u>none obs</u>	
<u>3rd West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>1st Right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>trans</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RR/RL</u>	<u>OK</u>	<u>none obs</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RR/RL</u>	<u>OK</u>	<u>none obs</u>	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at time of Exam.  
 \_\_\_\_\_  
**Signature** \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ RT. # 7954  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ RT. # 6401  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ RT. # 4325  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ RT. # \_\_\_\_\_

**Signature** \_\_\_\_\_  
 COUNTER SIGNATURE \_\_\_\_\_ RT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-15-07

SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:57 ~~AM~~/PM  
 TIME OF EXAMINATION START 11:30 ~~AM~~/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1:10 AM/~~PM~~  
 END 1:05 AM/~~PM~~  
 END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials mc/DD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
MAIN North haulage seals	20.9	0	0	FM	OK	none observed	
MAIN West haulage seals	20.9	0	0	mc/DD	OK	none observed	
3 <sup>rd</sup> North haulage	20.9	0	0	FM	OK	none observed	
1 <sup>st</sup> Right	20.9	0	0	FM	OK	none observed	
transformers	20.9	0	0	FM mc/DD	OK	none observed	
chargers	20.9	0	0	FM mc/DD	OK	none observed	
wash down	20.9	0	0	DD	OK	none observed	
storage area	20.9	0	0	DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 8297  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATUR \_\_\_\_\_ CERT. # 8462

2MSHA03308

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-18-07 SECTION/AREA Gen Mine: 1 | |

TIME OF EXAMINATION START 700 AM/PM (M) END 910 AM/PM (M) Examiners Initials RL/KK  
 TIME OF EXAMINATION START 715 AM/PM (M) END 833 AM/PM (M) Examiners Initials BR  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (N) CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	LR	OK	None obs.	
Main North Haulage Seals	21.0	0	0	LR	OK	None obs.	
Main West Haulage Seals	20.9	0	0	RL/KK	OK	None obs.	
3rd North Haulage	20.9	0	0	LR	OK	None obs.	
1st Right	20.9	0	0	LR	OK	None obs.	
Transformers	20.9	0	0	RL/KK	OK	None obs.	
Chargers	20.9	0	0	LR	OK	None obs.	
Washdown	20.9	0	0	LR	OK	None obs.	
Storage Area	20.9	0	0	LR	OK	None obs.	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appraised Safe at time of Exam

Signature \_\_\_\_\_

- PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 7954
- PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8401
- PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 4325
- PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4135

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-16-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 300 AM/PM END 545 AM/PM Examiners Initials RL  
 TIME OF EXAMINATION START 300 AM/PM END 535 AM/PM Examiners Initials RL  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>0</u>	<u>none observed</u>	
<u>Main North haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>0</u>	<u>none obs</u>	
<u>Main Int Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL LR/KK</u>	<u>0</u>	<u>10 one obs</u>	
<u>3rd North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none observed</u>	
<u>1st Right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none "</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL LR/KK</u>	<u>0</u>	<u>none observed</u>	
<u>Charger</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>0</u>	<u>none obs</u>	
<u>Workdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none observed</u>	
<u>Storage Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none "</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at time of Exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER CERT. # 6401  
 PRE-SHIFT/MINE EXAMINER CERT. # 7954  
 PRE-SHIFT/MINE EXAMINER CERT. # 4375  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATUR CERT. # 8462 2MSHA03310

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5.16.07

SECTION/AREA Gen Min 21

TIME OF EXAMINATION START 11:51 ~~AM~~/PM  
 TIME OF EXAMINATION START 11:30 ~~AM~~/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1:05 AM/~~PM~~  
 END 1:28 AM/~~PM~~  
 END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials DD MC  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/~~NO~~

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
MAIN North haulage seals	20.9	0	0	FM	OK	None observed	
MAIN West haulage seals	20.9	0	0	DD/mc	ok	none obs.	
3rd North haulage seals	20.9	0	0	FM	OK	None observed	
1st Right	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	FM DD/mc	ok	none obs.	
Chargers	20.9	0	0	FM DD/mc	ok	none obs.	
Storage Area	20.9	0	0	MC	ok	none obs.	
Washdown	20.9	0	0	MC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

\_\_\_\_\_  
 Signature

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03311

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-16-07

SECTION/AREA (See Min 21) \_\_\_\_\_

TIME OF EXAMINATION START 7:57 AM/PM  
 TIME OF EXAMINATION START 7:15 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 9:10 AM/PM  
 END 9:20 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KK  
 Examiners Initials KK/RL  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	none obs	
M. North storage	20.9	0	0	KK	OK	none obs	
Storage area	20.9	0	0	KK	OK	none obs	
Washdown	20.9	0	0	KK	OK	none obs	
Trens.	20.9	0	0	KK/RL	OK	None obs.	
chargers	20.9	0	0	KK/RL	OK	None obs.	
3rd of cells							
3 Heritage seals	20.9	0	0	KK	OK	none obs	
1st right	20.9	0	0	KK	OK	none obs	
M. West haulers	20.9	0	0	KK/RL	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 7954  
 CERT. # 4375  
 CERT. # 6401  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_

CERT. # 475

2MSHA03312

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-17-07 SECTION/AREA Gen Mine 91 | |

TIME OF EXAMINATION START 3:50 AM/PM END 5:20 AM/PM Examiners Initials KK  
 TIME OF EXAMINATION START 3:5 AM/PM END 5:35 AM/PM Examiners Initials LA/RL  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21.0	0	0	KK	0	none obs	
N. North Haulage seals	21.0	0	0	KK	0	none obs	
Storage area	20.9	0	0	KK	0	none obs	
Washdown	20.9	0	0	KK	0	none obs.	
3 Haulage seals	20.9	0	0	KK	0	none obs.	
1 <sup>st</sup> Night Haulage	20.9	0	0	KK	0	none obs	
N. West Haulage seals	20.9	0	0	LA/RL	0	none observed	
chargers	20.9	0	0	LA/RL	0	none observed	
Trans	20.9	0	0	LA/RL	0	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS It was appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # 7954  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6401  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4373  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-17-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 11:52 AM/PM  
 TIME OF EXAMINATION START 11:30 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1:08 AM/PM  
 END 1:15 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials MC/DD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
MAIN North haulage Seals	20.9	0	0	FM	OK	None observed	
MAIN West haulage Seals	20.9	0	0	MC/DD	OK	None observed	
3rd North haulage Seals	20.9	0	0	FM	OK	None observed	
1st Right	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	FM MC/DD	OK	None observed	
Chargers	20.9	0	0	FM MC/DD	OK	None observed	
Storage Area	20.9	0	0	DD	OK	None observed	
Wash down	20.9	0	0	DD	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Signature

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 8297  
 CERT. # 7875  
 CERT. # 8058  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03314

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5/7/07

SECTION/AREA Exam Room 1

TIME OF EXAMINATION START 7:46 AM/PM  AM  PM  
 TIME OF EXAMINATION START 7:10 AM/PM  AM  PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM  AM  PM

END 9:05 AM/PM  AM  PM  
 END 9:25 AM/PM  AM  PM  
 END \_\_\_\_\_ AM/PM  AM  PM

Examiners Initials KK  
 Examiners Initials HR/RL  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO  YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	none obs	
Main North <sup>at Hall</sup> area	21.0	0	0	KK	OK	none obs	
Storage area	20.9	0	0	KK	OK	none obs	
Washdown	20.9	0	0	KK	OK	none obs	
3rd <sup>at Haulage</sup> <del>at</del> seals	20.9	0	0	KK	OK	none obs	
1 <sup>st</sup> right <sup>at Haulage</sup> seals	20.9	0	0	KK	OK	none obs	
M. West <sup>at Haulage</sup> seals	20.9	0	0	KK/RL	OK	none obs	
Trams	20.9	0	0	KK/RL	OK	none obs	
chargers	20.9	0	0	HR/RL	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at time of Exam.

Signature

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 7954  
 CERT. # 4275  
 CERT. # 6401  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 9385

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-18-07

SECTION/AREA Gen Run 1

TIME OF EXAMINATION START 3:47 AM/PM  
 TIME OF EXAMINATION START 3:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 5:00 AM/PM  
 END 5:25 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KK  
 Examiners Initials KR/L  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	KK	OK	None observed	
In North haulage seals	20.9	0	0	KK	OK	None observed	
Storage area	20.9	0	0	KK	OK	None observed	
Washdown	20.9	0	0	KK	OK	None observed	
In North haulage seals	20.9	0	0	KK	OK	None observed	
1st Right Haulage	20.9	0	0	KK	OK	None observed	
In West haulage seals	20.9	0	0	<del>KK</del> KR/L	OK	None observed	
Trans.	20.9	0	0	<del>KK</del> KR/L	OK	None observed	
chargers	20.9	0	0	KR/L	OK	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
MU Section intake	Getting gray	Bulk dusted OK

**PRE-SHIFT REMARKS**

Area around Seife at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 7954  
 CERT. # 4325  
 CERT. # 6401  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 03892

2MSHA03316

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-18-07

SECTION/AREA Gen Mine 1 / /

TIME OF EXAMINATION START 11:58 AM/PM  
 TIME OF EXAMINATION START 11:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 12:47 AM/PM  
 END 1:10 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials BH  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
MAIN North haulage seals	20.9	0	0	FM	OK	None observed	
MAIN West haulage seals	20.9	0	0	BH	OK	None observed	
3rd North haulage seals	20.9	0	0	BH	OK	None observed	
1st Right	20.9	0	0	BH	OK	None observed	
Transformers	20.9	0	0	FM/BH	OK	None observed	
chargers	20.9	0	0	BH	OK	None observed	
wash down	20.9	0	0	BH	OK	None observed	
storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 03892

2MSHA03317

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-18-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 7:40  
 TIME OF EXAMINATION START 8:30  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM AM END 9:05 AM/PM AM  
 AM/PM AM END 9:10 AM/PM AM  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials SW  
 Examiners Initials dy  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES (NO)

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage	20.9	0	0	SW	OK	none observed	
Main West haulage	20.9	0	.2	SW	OK	Deepwater 73X	BEING PUMPED DONE
3rd North haulage	20.9	0	0	SW	OK	none observed	
1st Right	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW	OK	none observed	
chargers	20.9	0	0	SW	OK	none observed	
Storage Area	20.9	0	0	SW	OK	none observed	
washdown	20.9	0	0	dy	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

all areas examined appears safe at time of pre-shift except what is noted above

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 9548  
 CERT. # 6622  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATUR

CERT. # 7485

2MSHA03318

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-19-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 3:50  
 TIME OF EXAMINATION START 4:35  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM    END 5:20  AM/PM  
 AM/PM    END 5:15  AM/PM  
 AM/PM    END \_\_\_\_\_  AM/PM

Examiners Initials SW  
 Examiners Initials LD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/ NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage <sup>SLAB</sup>	20.9	0	0	SW	OK	none observed	
Main West haulage <sup>SLAB</sup>	20.9	0	0	<del>SW</del> <sup>LD</sup>	OK	Ribs Blowed out next to XC 115, XC 125 timber	Sent people to fix XC 115 Done 5/19/07
3rd North haulage <sup>SLAB</sup>	20.9	0	0	SW	OK	none observed	
1st Right haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>SW</del> <sup>LD</sup>	OK	none observed	
Chargers	20.9	0	0	<del>SW</del> <sup>LD</sup>	OK	none observed	
Storage Area	20.9	0	0	SW	OK	none observed	
Washdown	20.9	0	0	LD	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
#12 to #14 NW	Getting gray	Bulk dusted off
Main We	"	"

PRE-SHIFT REMARKS all Areas appeared safe at the time of exam except those noted above,

Signature

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 9548  
 CERT. # 9660  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 03892

2MSHA03319

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-19-07 SECTION/AREA Gen mine

TIME OF EXAMINATION START 11:59 AM/PM END 1:33 AM/PM Examiners Initials BH  
 TIME OF EXAMINATION START 11:55 AM/PM END 12:52 AM/PM Examiners Initials TC  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North <sup>Haulage</sup> Seals	20.9	0	0	BH	OK	None Observed	
Main West <sup>Haulage</sup> Seals	20.9	0	0	BH	OK	<del>None Observed</del> <sup>see before</sup>	Sent people to set timber at above CA
3 <sup>rd</sup> North <sup>Haulage</sup> Seals	20.9	0	0	BH	OK	None Observed	51907
1 <sup>st</sup> Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Rob sluffage xc 125 need timbers set  
All other AREAS safe AT Time of Exa -

**Signature**  
 PRE-SHIFT/MINE EXAMINEE CERT. # 8395  
 PRE-SHIFT/MINE EXAMINEE CERT. # 9362  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE **Signature** CERT. # 03892

2MSHA03320

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-19-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 7:50  
 TIME OF EXAMINATION START 8:35  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM (AM)  
 AM/PM (AM)  
 AM/PM \_\_\_\_\_

END 9:05 AM/PM (AM)  
 END 9:20 AM/PM (AM)  
 END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials SW  
 Examiners Initials LD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North <sup>SLABS</sup> haulage	20.9	0	0	SW	OK	none observed	
Main West <sup>SLABS</sup> haulage	20.9	0	0	<del>SW</del> LD	OK	none observed	
3 <sup>rd</sup> North <sup>SLABS</sup> haulage	20.9	0	0	SW	OK	none observed	
1 <sup>st</sup> Right haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>SW</del> LD	OK	none observed	
chargers	20.9	0	0	<del>SW</del> LD	OK	none observed	
Washdown	20.9	0	0	LD	OK	none observed	
Storage Area.	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas Apperd safe at the time of exam

Signature

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 9548  
 CERT. # 9660  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 7485

2MSHA03321

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-20-07

SECTION/AREA General 1 mile

TIME OF EXAMINATION START 3:10  
 TIME OF EXAMINATION START 3  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM    END 4:30  AM/PM  
 AM/PM    END 3:40  AM/PM  
 AM/PM    END \_\_\_\_\_ AM/PM

Examiners Initials dg  
 Examiners Initials dg  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage <sup>seals</sup>	20.9	0	0	SW	OK	none observed	
Main West haulage <sup>seals</sup>	20.9	0	.1	<del>SW</del> dg	ok	none observed	
3 <sup>rd</sup> North haulage <sup>seals</sup>	20.9	0	0	SW	OK	none observed	
1 <sup>st</sup> Right haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>SW</del> dg	OK	none observed	
chargers	20.9	0	0	<del>SW</del> dg	OK	none observed	
Washdown	20.9	0	0	dg	ok	none observed	
Storage Area	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

\_\_\_\_\_  
 Signature

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 9548  
 CERT. # 6622  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

\_\_\_\_\_  
 Signature

COUNTER SIGNATURE

CERT. # 03892

2MSHA03322

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-20-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 11:48 AM/PM  
 TIME OF EXAMINATION START 12:29 AM/PM  
 TIME OF EXAMINATION START 12:15 AM/PM

END 1:30 AM/PM  
 END 1:28 AM/PM  
 END 1:07 AM/PM

Examiners Initials BH  
 Examiners Initials TC  
 Examiners Initials BD

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North <sup>Plantage</sup> Seals	20.9	0	0	BH	OK	None Observed	
Main West <sup>Plantage</sup> Seals	20.9	0	0	BH/TC	OK	None Observed	
3 <sup>rd</sup> North <sup>Plantage</sup> Seals	20.9	0	0	BH	OK	None Observed	
1 <sup>st</sup> Right <sup>Plantage</sup> Seals	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH/TC	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9362  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4579  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 03892

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-20-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 7:55 AM/PM  
 TIME OF EXAMINATION START 8:45 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 9:25 AM/PM  
 END 9:10 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials SW  
 Examiners Initials dy  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage <sup>Scals</sup>	20.9	0	0	SW	OK	none observed	
Main West haulage <sup>Scals</sup>	20.9	0	1	<del>SW</del> dy	OK	none observed	
3rd North haulage <sup>Scals</sup>	20.9	0	0	SW	OK	none observed	
1st Right haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>SW</del> dy	OK	none observed	
Chargers	20.9	0	0	<del>SW</del> dy	OK	none observed	
Washdown	20.9	0	0	dy	OK	none observed	
Storage Area	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at Time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 9548  
 CERT. # 6622  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03324

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5/2/07 SECTION/AREA Gen 1 Mine 1

TIME OF EXAMINATION START 3  AM/PM  PM/PM END 3:45  AM/PM  PM/PM Examiners Initials dy  
 TIME OF EXAMINATION START 3:15  AM/PM  PM/PM END 4:40  AM/PM  PM/PM Examiners Initials SW  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITJONS	ACTION TAKEN
UG Parking	20.9	0	0	SW	OK	none observed	
Main Seals North Haulage	20.9	0	0	SW	OK	none observed	
Main Seals/Pumps West Haulage	20.9	0	1	<del>dy</del> SW	OK	none observed	
3RD No Haulage Seals	20.9	0	0	SW	OK	none observed	
1st Right Haulage	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>dy</del> SW	OK	none observed	
Chargers	20.9	0	0	<del>dy</del> SW	OK	none observed	
Washdown	20.9	0	0	dy	OK	none observed	
Storage areas	20.9	0	0	SW	OK	none observed.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas examined appear reasonably safe at time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6622  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9548  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 8462

2MSHA03325

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-21-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 11:52  AM/PM  
 TIME OF EXAMINATION START 1130  AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1:05  AM/ PM  
 END 120  AM/ PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials DD mc  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
MAIN North haulage seals	20.9	0	0	FM	OK	None observed	
MAIN West haulage seals	20.9	0	0	DD mc	OK	none obs.	
3rd North haulage seals	20.9	0	0	FM	OK	None observed	
1st Right	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	FM DD/mc	OK	none obs.	
chargers	20.9	0	0	FM DD/mc	OK	none obs.	
wash down	20.9	0	0	mc	OK	none obs.	
Storage Area	20.9	0	0	mc	OK	none obs.	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

— CERT. # 8297  
 — CERT. # 8058  
 — CERT. # 7375  
 — CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATUR \_\_\_\_\_

— CERT. # 4735

2MSHA03326

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-21-07

SECTION/AREA General Mine 1

TIME OF EXAMINATION START 8:30  
 TIME OF EXAMINATION START 8:00  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM AM END 9:30 AM/PM AM  
 AM/PM AM END 9:50 AM/PM AM  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials SW  
 Examiners Initials KK/RL  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North <sup>SEAB</sup> haulage	20.9	0	0	SW	OK	none observed	
Parking Area	20.9	0	0	SW	OK	none observed	
Main West <sup>haulage</sup> Seals	20.9	0	0	<del>SW</del> <sup>RL/KK</sup> OK	OK	none observed	
3 <sup>rd</sup> North <sup>SEAB</sup> haulage	20.9	0	0	SW	OK	none observed	
15 <sup>th</sup> Right	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>SW</del>	OK	none observed	
chargers	20.9	0	0	<del>SW</del> <sup>RL</sup>	OK	none observed	
washdown	20.9	0	0	KK	OK	none observed	
Storage Area	20.9	0	0	KK	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

Areas appeared safe at time of exam.

Signature

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 9548  
 CERT. # 6406  
 CERT. # 7964  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 4735

2MSHA03327

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-22-07 SECTION/AREA 2nd Shift

TIME OF EXAMINATION START 300 AM/PM END 550 AM/PM Examiners Initials R/K  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RK</u>	<u>OK</u>	<u>none</u>	
<u>M. West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RK</u>	<u>OK</u>	<u>none observed</u>	
<u>3rd Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RK</u>	<u>OK</u>	<u>none observed</u>	
<u>1st right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RK</u>	<u>OK</u>	<u>none observed</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RK</u>	<u>OK</u>	<u>none observed</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RK</u>	<u>OK</u>	<u>none observed</u>	
<u>M. West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RK/R</u>	<u>OK</u>	<u>none observed</u>	
<u>Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RK/R</u>	<u>OK</u>	<u>none observed</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RK/R</u>	<u>OK</u>	<u>none observed</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All gases appeared safe at time of report

Signature

CERT. # 640  
 CERT. # 7954  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ ERT. # 8462 2MSHA03328

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-22-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 12:00 AM/PM AM/PM END 1:13 AM/PM  
 TIME OF EXAMINATION START 11:30 ~~AM/PM~~ END 1:25 ~~AM/PM~~  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials DD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
Main North haulage seals	20.9	0	0	FM	OK	None observed	
Main West haulage seals	20.9	0	0	DD/mc	OK	None obs.	
3rd North haulage seals	20.9	0	0	FM	OK	None observed	
1st Right	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	DD/mc	OK	None obs.	
Chargers	20.9	0	0	DD/mc	OK	None obs.	
Washdown	20.9	0	0	DD	OK	None obs.	
Storage Area	20.9	0	0	DD	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINE \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8462

2MSHA03329

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-22-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 7:48 AM/PM  
START 7:25 AM/PM  
START \_\_\_\_\_ AM/PM

END 9:05 AM/PM  
END 9:30 AM/PM  
END \_\_\_\_\_ AM/PM

Examiners Initials KK  
Examiners Initials WR/RL  
Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>3rd Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>None obs</u>	
<u>1st right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>None obs</u>	
<u>M. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>WR/RL</u>	<u>OK</u>	<u>Deep water #7311</u>	<u>sent me to pump Done 8-23-07</u>
<u>Trucks</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>WR/RL</u>	<u>OK</u>	<u>None obs.</u>	
<u>Charger</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>WR/RL</u>	<u>OK</u>	<u>None obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

Area appeared safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMIN  
PRE-SHIFT/MINE EXAMIN  
PRE-SHIFT/MINE EXAMIN  
PRE-SHIFT/MINE EXAMIN

CERT. # 7954  
CERT. # 4375  
CERT. # 6401  
CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 4735

2MSHA03330

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-23-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 300 AM/PM  
 TIME OF EXAMINATION START 300 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 5:20 AM/PM  
 END 400 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KK/LR  
 Examiners Initials RL  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>α</u>	<u>none observed</u>	
<u>M. North Haulage seals</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>α</u>	<u>none observed</u>	
<u>M. West Haulage seal</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>α</u>	<u>none obs</u>	
<u>Trans</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>α</u>	<u>None obs</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>α</u>	<u>None obs</u>	
<u>3rd Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>α</u>	<u>none observed</u>	
<u>1st Flight tunnel</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>α</u>	<u>none observed</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>α</u>	<u>none</u>	
<u>Washroom</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>α</u>	<u>none</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved Safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 7951  
 CERT. # 4375  
 CERT. # 6400  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03331

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5/23/07

SECTION/AREA Gen Mining

TIME OF EXAMINATION START 11:52 AM/PM  
 TIME OF EXAMINATION START 11:28 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1:10 AM/PM  
 END 1:34 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials DD mc  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
MAIN North haulage seals	20.9	0	0	FM	OK	None observed	
MAIN West haulage seals	20.7	0	0	DD/mc	OK	none obs.	
3rd North haulage seals	20.9	0	0	FM	OK	None observed	
1st Right	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	DD mc	OK	none obs.	
Chargers	20.9	0	0	DD mc	OK	Not the required amount of dust for mini trak charger	Working on Done 5-23-07
Washdown	20.9	0	0	mc	OK	none obs.	
Storage Area	20.9	0	0	mc	OK	none obs.	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Signature \_\_\_\_\_

- PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8297
- PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8058
- PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 2321
- PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_  
 Signature \_\_\_\_\_  
 CERT. # 8462

2MSHA03332

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-23-07

SECTION/AREA Emulsion 1

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 7:00 AM/PM  
START 8:00 AM/PM  
START \_\_\_\_\_ AM/PM

END 9:05 AM/PM  
END 8:10 AM/PM  
END \_\_\_\_\_ AM/PM

Examiners Initials KK/LR  
Examiners Initials \_\_\_\_\_  
Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO X

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>OK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. North Hunter seats</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>OK</u>	<u>OK</u>	<u>none obs</u>	
<u>M.W. of Hunter seats</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>OK</u>	<u>none obs</u>	
<u>3rd Hunter seats</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>1st right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Travis</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>OK</u>	<u>none obs</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>OK</u>	<u>none obs</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.8</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift  
Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7954  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4735  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4325  
PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 4735 2MSHA03333

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-24-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 300 AM/PM  
 TIME OF EXAMINATION START 500 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 555 AM/PM  
 END 555 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials RL/KK  
 Examiners Initials RL  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (B)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none observed</u>	
<u>Main North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>None obs.</u>	
<u>Main West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>None obs.</u>	
<u>3rd North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none observed</u>	
<u>Int Right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none observed</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>none observed</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>none observed</u>	
<u>Workdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LK</u>	<u>OK</u>	<u>None obs.</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>None obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 6401  
 CERT. # 4325  
 CERT. # 7954  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 8462

2MSHA03334

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-24-07 SECTION/AREA Gem Mine 1

TIME OF EXAMINATION START 11:30  AM/PM  END 1:15 AM/PM  Examiners Initials MC/DD  
 TIME OF EXAMINATION START 11:55  AM/PM  END 1:12 AM/PM  Examiners Initials FM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_ Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO  CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLLED OUT BY \_\_\_\_\_  
 CALLLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
MAIN NORTH Haulage seals	20.9	0	0	FM	OK	None observed	
MAIN WEST Haulage seals	20.9	0	0	MC/DD	OK	None observed	
3 <sup>RD</sup> NORTH Haulage seals	20.9	0	0	FM	OK	None observed	
1 <sup>ST</sup> Right Haulage	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	FM MC/DD	OK	None observed	
chargers	20.9	0	0	FM MC/DD	OK	None observed	
washdown	20.9	0	0	DD	OK	None observed	
Storage Area	20.9	0	0	DD	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_  
 \_\_\_\_\_ CERT. # 4130

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_ 2MSHA03335

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-24-07

SECTION/AREA General

TIME OF EXAMINATION START 7:00  
 TIME OF EXAMINATION START 7:30  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM (AM) END 9:20 AM/PM (PM)  
 AM/PM (AM) END 9:20 AM/PM (PM)  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials RL  
 Examiners Initials RL  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	RL	0	none observed	
Main North Haulage Seal	20.9	0	0	RL	0	none observed	
Main West Haulage Seal	20.9	0	0	RL/KL/JP	0	none observed	
3rd N <sub>1</sub> Haulage Seal	20.9	0	0	RL	0	none observed	
1st Right	20.9	0	0	RL	0	none observed	
Transformers	20.9	0	0	RL/KL/JP	0	none observed	
chargers	20.9	0	0	KL/JP	0	none observed	
Washdown	20.9	0	0	RL	0	none observed	
Storage area	20.9	0	0	R	0	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 040  
 CERT. # 7954  
 CERT. # 4375  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 4735

2MSHA03336

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-25-07

SECTION/AREA General | |

TIME OF EXAMINATION START 300 AM/PM  
 TIME OF EXAMINATION START 400 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 525 AM/PM  
 END 340 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials KK/LR  
 Examiners Initials RL  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>30.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>M. North Haulage seals</u>	<u>30.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none observed</u>	
<u>M. West Haulage seals</u>	<u>30.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>OK</u>	<u>none obs</u>	
<u>3 up ch haulage seals</u>	<u>30.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none observed</u>	
<u>1<sup>st</sup> right</u>	<u>30.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none observed</u>	
<u>Trucks</u>	<u>30.9</u>	<u>0</u>	<u>0</u>	<u>KK/LR</u>	<u>OK</u>	<u>none obs.</u>	
<u>chargers</u>	<u>30.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none obs</u>	
<u>Washdown</u>	<u>30.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	
<u>Storage area</u>	<u>30.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at time of Exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7924  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4375  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6401  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 7485

2MSHA03337

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-25-07

SECTION/AREA General 1 Mile

TIME OF EXAMINATION START 11:00  AM/PM  
 TIME OF EXAMINATION START 11:45  AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 12:00 AM/PM  
 END 1:15 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials SW  
 Examiners Initials FM  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
Main North <sup>seals</sup> haulage	20.9	0	0	FM	OK	None observed	
Main West <sup>seals</sup> haulage	20.9	0	0	FM	OK	None observed	
3 <sup>rd</sup> North <sup>seals</sup> haulage	20.9	0	0	FM	OK	None observed	
1 <sup>st</sup> Right	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	<del>FM</del> SW	OK	None observed	
Chargers	20.9	0	0	<del>FM</del> SW	OK	None observed	
Washdown	20.9	0	0	SW	OK	None observed	
Storage Area	20.9	0	0	FM	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 9548  
 CERT. # 8297  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE

CERT. # 7485

2MSHA03338

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-25-07 SECTION/AREA Open Mine 1

TIME OF EXAMINATION START 8:15 AM/PM AM END 8:40 AM/PM AM Examiners Initials B/A/C

TIME OF EXAMINATION START 7:00 AM/PM AM END 8:40 AM/PM AM Examiners Initials BH

TIME OF EXAMINATION START 8:15 AM/PM AM END 8:40 AM/PM AM Examiners Initials

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

CALLED OUT BY \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
main North Garage	20.9	0	0	BH	OK	None Observed	
main West Garage	20.9	0	0	BH	OK	None Observed	
3rd North Garage	20.9	0	0	BH	OK	None Observed	
1st Garage	20.9	0	0	BH	OK	None Observed	
Truck Area	20.9	0	0	BH	OK	None Observed	
Charger	20.9	0	0	BH	OK	None Observed	
washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9599

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8395

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 936

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 9279

2MSHA03339

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-26-07

SECTION/AREA Gen Minal 1

TIME OF EXAMINATION START 4:15 AM/PM  
 TIME OF EXAMINATION START 3:47 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 4:30 AM/PM  
 END 3:15 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials BP  
 Examiners Initials TC  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	none obs.	
<sup>5246</sup> main North hallway	20.9	0	0	BH	OK	none obs.	
<sup>5246</sup> main west hallway	20.9	0	0	BP/TC	OK	none observed	
<sup>5246</sup> 3rd North hallway	20.9	0	0	BH	OK	none obs.	
15th Right	20.9	0	0	BH	OK	none obs.	
Transformer	20.9	0	0	BP/TC	OK	none observed	
chargers	20.9	0	0	TC/BH	OK	none obs.	
crashdown	20.9	0	0	BH	OK	None observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 9389  
 CERT. # 9365  
 CERT. # 8395  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE CERT. # 7480

2MSHA03340

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5 26 07

SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 11:20 AM/PM  
 TIME OF EXAMINATION START 11 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1240 AM/PM  
 END 1140 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials JG  
 Examiners Initials dy  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE - SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE - SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE - SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	dy/JG	ok	NONE observed	
CHARGERS	20.9	0	0	JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	dy	ok	none observed	
STORAGE AREA	20.9	0	0	dy	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINE Signature CERT. # 7485  
 PRE-SHIFT/MINE EXAMINE CERT. # 6622  
 PRE-SHIFT/MINE EXAMINE CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03341

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-26-08 SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START 7:45 AM/PM AM END 9:25 AM/PM PM Examiners Initials BH  
 TIME OF EXAMINATION START 7:50 AM/PM AM END 9:01 AM/PM PM Examiners Initials JS  
 TIME OF EXAMINATION START 7:55 AM/PM AM END 8:50 AM/PM PM Examiners Initials RS

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- AM/PM

CALLER BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_  
 CALLER BY \_\_\_\_\_  
 CALLER BY \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Haulage seals	20.9	0	0	BH	OK	None Observed	
Main West Haulage seals	20.9	0	0	BH/BP JS	OK	None Observed	
3 <sup>rd</sup> North Haulage seals	20.9	0	0	BH	OK	None Observed	
1 <sup>st</sup> Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/BP JS	OK	None Observed	
Chargers	20.9	0	0	BH/RS BP	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 838  
 PRE-SHIFT/MINE EXAMINER CERT. # 936  
 PRE-SHIFT/MINE EXAMINER CERT. # 8599  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

Signature  
 COUNTER SIGNATUR \_\_\_\_\_ CERT. # 9279

2MSHA03342

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-27-07 SECTION/AREA GENERAL MINE

TIME OF EXAMINATION START 3:40 AM/PM END 5:00 AM/PM Examiners Initials TL  
 TIME OF EXAMINATION START 3:50 AM/PM END 5:30 AM/PM Examiners Initials BH  
 TIME OF EXAMINATION START 3:50 AM/PM END 5:00 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None observed	
Main north haulage & seals	20.9	0	0	BH	OK	None observed	
Main West Haulage Seal >	20.9	0	0	<del>TCBP</del> BH	OK	None obs.	
3rd north haulage seals	20.9	0	0	BH	OK	None observed	
1st right haulage	20.9	0	0	BH	OK	None observed	
Transformers	20.9	0	0	<del>TCBP</del> BH	OK	None obs.	
Chargers	20.9	0	0	<del>TCBP</del> BH	OK	None obs.	
Washhouse	20.9	0	0	BH	OK	None observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362  
 PRE-SHIFT/MINE EXAMINER CERT. # 9599  
 PRE-SHIFT/MINE EXAMINER CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE CERT. # 7485

2MSHA03343

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-27-07

SECTION/AREA General Mine 1

TIME OF EXAMINATION START 11:15 AM/PM  
 TIME OF EXAMINATION START 11:10 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 12:25 AM/PM  
 END 12:15 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials JG  
 Examiners Initials SW  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	21.0	0	0	SW/JG	OK	none observed	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	21.0	0	0	SW/JG	OK	none observed	
CHARGERS	21.0	0	0	SW/JG	OK	none observed	
WASHDOWN	21.0	0	0	SW	OK	none observed	
STORAGE	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe to travel at time of exam.

Signature

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

CERT. # 7485  
 CERT. # 9548  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR

CERT. # 7485

2MSHA03344

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-27-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 7:55 AM/PM (PM) END 9:48 AM/PM (PM) Examiners Initials BH  
 TIME OF EXAMINATION START 7:45 AM/PM (PM) END 9:20 AM/PM (PM) Examiners Initials TC  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North <small>Haulage seals</small>	20.9	0	0	BH	OK	None Observed	
Main West <small>Haulage seals</small>	20.9	0	0	BH/TC	OK	None Observed	
3 <sup>rd</sup> North <small>Haulage seals</small>	20.9	0	0	BH	OK	None Observed	
1 <sup>st</sup> Right Haulage	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/TC	OK	None Observed	
Chargers	20.9	0	0	BH/TC	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6395  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9362  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 9279

2MSHA03345

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5/26/07

SECTION/AREA General Mine

TIME OF EXAMINATION START 3:00 AM/PM  
 TIME OF EXAMINATION START 3:57 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 5:20 AM/PM  
 END 5:20 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials TC  
 Examiners Initials BH  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None obs.	
Main North Haulage & Seals	20.9	0	0	BH	OK	None obs.	
Main West Haulage & Seals	20.9	0	0	TC	OK	None obs.	
3rd North Haulage Seals	20.9	0	0	TC	OK	None obs.	
1st Right Haulage	20.9	0	0	TC	OK	None obs.	
Transformers	20.9	0	0	TC	OK	None obs.	
Chargers	20.9	0	0	TC	OK	None obs.	
Washdown	20.9	0	0	TC	OK	None obs.	
Storage Area	20.9	0	0	TC	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas seemed safe  
AT Time of Exam

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 9362  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_  
 Signature \_\_\_\_\_  
 CERT. # 8925

2MSHA03346

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-29-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 3:00  
 TIME OF EXAMINATION START 305  
 TIME OF EXAMINATION START \_\_\_\_\_

~~AM/PM~~ END 4:34 ~~AM/PM~~  
~~AM/PM~~ END 445 ~~AM/PM~~  
 AM/PM END \_\_\_\_\_ AM/PM

Examiners Initials SW  
 Examiners Initials KR/KK  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North <sup>Seals</sup> haulage	21.0	0	0	SW	OK	none observed	
Main West <sup>Seals</sup> haulage	21.0	0	0	<del>SW</del> <u>KR/KK</u>	OK	deepwater r-cut 73" diam.	sediment pump pumped 5-29-07
3rd North <sup>Seals</sup> haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	<del>SW</del> <u>KR/KK</u>	OK	None observed	
Chargers	21.0	0	0	<del>SW</del> <u>KR/KK</u>	OK	None observed	
Washdown	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 9548  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 4325  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 7954  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 473

2MSHA03347

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-29-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 11:55 ~~AM~~/PM  
 TIME OF EXAMINATION START 11:00 ~~AM~~/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1:21 AM/~~PM~~  
 END 1:50 AM/~~PM~~  
 END \_\_\_\_\_ AM/PM

Examiners Initials EM  
 Examiners Initials KK/R  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	EM	OK	None observed	
MAIN North haulage seals	20.9	0	0	EM	OK	None observed	
MAIN West haulage seals	20.9	0	0	EM/RR/HR	OK	none obs	
3rd North haulage seals	20.9	0	0	EM	OK	None observed	
1st Right	20.9	0	0	EM	OK	None observed	
Transformers	20.9	0	0	EM/RR/HR	OK	none obs	
Changers	20.9	0	0	EM/RR/HR	OK	none obs	
Wash down	20.9	0	0	EM	OK	None observed	
Storage Area	20.9	0	0	KK	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam  
 \_\_\_\_\_  
 Signature

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 7154  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 4325  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8462 2MSHA03348

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-29-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 2:20  
 TIME OF EXAMINATION START 7:28  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM AM END 8:08 AM/PM PM  
 AM/PM PM END 9:35 AM/PM PM  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials PC  
 Examiners Initials DD mc  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES NO  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	ok	None Observed	
Main North <sup>Haulage</sup> seals	20.9	0	0	PC	ok	None Observed	
Main West <sup>Haulage</sup> seals	20.9	0	0	DD/mc	ok	none obs.	
3rd North <sup>Haulage</sup> seals	20.9	0	0	DD/mc	ok	none obs.	
1st Right	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	DD/mc	ok	none obs.	
chargers	20.9	0	0	DD/mc	ok	none obs.	
Wash down	20.9	0	0	mc	ok	none obs.	
Storage area	20.9	0	0	mc	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE CERT. # 8462  
 PRE-SHIFT/MINE EXAMINEE CERT. # 8058  
 PRE-SHIFT/MINE EXAMINEE CERT. # 8375  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE CERT. # 8462

2MSHA03349

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-30-02 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 3:55 ~~AM~~/PM END 4:21 ~~AM~~/PM Examiners Initials PL  
 TIME OF EXAMINATION START 3:30 ~~AM~~/PM END 5:40 ~~AM~~/PM Examiners Initials MC/DD  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO  CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PL	OK	None Observed	
Main North seals <sup>Harlage</sup>	20.9	0	0	PL	OK	None Observed	
Main West seals <sup>Harlage</sup>	20.9	0	0	MC/DD	OK	None Observed	
3 <sup>rd</sup> North seals <sup>Harlage</sup>	20.9	0	0	MC/DD	OK	None Observed	
1 <sup>st</sup> Night	20.9	0	0	MC/DD	OK	None Observed	
Trans Formers	20.9	0	0	MC/DD	OK	None Observed	
Chargers	20.9	0	0	MC/DD	OK	None Observed	
Wash down	21.9	0	0	DD	OK	None Observed	
Storage area	20.9	0	0	DD	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8462  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 7335  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # 4435

2MSHA03350

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5.30.07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:00 AM/PM END 12:30 AM/PM Examiners Initials FM  
 TIME OF EXAMINATION START 11:00 AM/PM END 1:40 AM/PM Examiners Initials LR  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
MAIN North haulage seals	20.9	0	0	FM	OK	None observed	
MAIN West haulage seals	20.9	0	0	FWY LR/RR	OK	none obs.	
3rd North haulage seals	20.9	0	0	FM	OK	None observed	
1st Right	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	FWY LR/RR	OK	none obs.	
chargers	20.9	0	0	FWY LR/RR	OK	none obs.	
Washdown	20.9	0	0	FM	OK	None observed	
Storage Area	20.9	0	0	FM	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4325  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7954  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-30-67

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 2:00 AM/PM  
 TIME OF EXAMINATION START 7:30 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 2:36 AM/PM  
 END 9:40 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials PC  
 Examiners Initials mc/ld  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	ok	None observed	
Main North seals <sup>Haulage</sup>	20.9	0	0	PC	ok	None observed	
Main West seals <sup>Haulage</sup>	20.9	0	0	mc/ld	ok	none observed	
3 <sup>rd</sup> North seals <sup>Haulage</sup>	20.9	0	0	mc/ld	ok	none observed	
1 <sup>st</sup> Right	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	mc/ld	ok	none observed	
chargers	20.9	0	0	mc/ld	ok	none observed	
wash down	20.9	0	0	mc	ok	none observed	
Storage area	20.9	0	0	mc	ok	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe  
at time of preshift

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 8462  
 CERT. # 7375  
 CERT. # 8058  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature

CERT. # 8462

2MSHA03352

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-31-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 3:50 AM/PM  
 TIME OF EXAMINATION START 3:30 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 4:17 AM/PM  
 END 5:40 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials PC  
 Examiners Initials DD/mc  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	ok	None observed	
Main North seals <sup>Haulage</sup>	20.9	0	0	PC	ok	None observed	
Main West seals <sup>Haulage</sup>	20.9	0	0	DD/mc	ok	none obs.	
3 <sup>rd</sup> North seals <sup>Haulage</sup>	20.9	0	0	DD/mc	ok	none obs.	
1st Right	20.9	0	0	DD	ok	none obs.	
transformers	20.9	0	0	DD/mc	ok	none obs.	
Chargers	20.9	0	0	DD/mc	ok	none obs.	
Wash down	20.9	0	0	DD	ok	none obs.	
Storage area	20.9	0	0	DD	ok	none obs.	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 8462  
 CERT. # 8058  
 CERT. # 7325  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 4735

2MSHA03353

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-31-07

SECTION/AREA Gen. Mine / /

TIME OF EXAMINATION START 11:00 ~~AM~~/PM  
 TIME OF EXAMINATION START 11:40 ~~AM~~/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1235 AM/PM  
 END 12:20 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials LR/KK  
 Examiners Initials FM  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
Main North Haulage Seals	20.9	0	0	FM	OK	None observed	
Main West Haulage Seals	20.9	0	0	LR/KK/DA	OK	None obs.	
3 <sup>rd</sup> North Haulage Seals	20.9	0	0	KK	OK	None obs.	
1 <sup>st</sup> Right	20.9	0	0	KK	OK	None obs.	
Transformers	20.9	0	0	KK/PM DE/LR	OK	None obs.	
Chargers	20.9	0	0	KK/LR	OK	None obs	
Wash down	20.9	0	0	KK	OK	None obs	
Storage Area	20.9	0	0	KK	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

PRE-SHIFT/MINE EXAMINEF  
 PRE-SHIFT/MINE EXAMINEF  
 PRE-SHIFT/MINE EXAMINEF  
 PRE-SHIFT/MINE EXAMINEF

Signature

CERT. # 4325  
 CERT. # 7954  
 CERT. # 8897  
 CERT. # \_\_\_\_\_

COUNTER SIGNATURE

Signature

CERT. # 8462

2MSHA03354

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 5-31-07

SECTION/AREA Gen Mines

TIME OF EXAMINATION START 8:20  
 TIME OF EXAMINATION START 7:00  
 TIME OF EXAMINATION START \_\_\_\_\_

~~AM/PM~~  
 END 9:10 AM/PM  
 END 9:15 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials PC  
 Examiners Initials mc/DD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North <sup>Haulage</sup> seals	20.9	0	0	PC	OK	None observed	
Main West <sup>Haulage</sup> seals	20.9	0	0	mc/DD	OK	none observed	
2 <sup>nd</sup> North <sup>Haulage</sup> seals	20.9	0	0	PC	OK	None Observed	
1 <sup>st</sup> Right	20.9	0	0	PC	OK	None observed	
Transformers	20.9	0	0	PC	OK	None observed	
Chargers	20.9	0	0	mc/DD	OK	None observed	
wash down	20.9	0	0	MC	OK	None observed	
Storage area	20.9	0	0	MC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of preshift

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER CERT. # 8462  
 PRE-SHIFT/MINE EXAMINER CERT. # 7325  
 PRE-SHIFT/MINE EXAMINER CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_  
 RT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-1-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 4:15 ~~AM~~/PM  
 TIME OF EXAMINATION START 3:30 ~~AM~~/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 4:45 ~~AM~~/PM  
 END 5:40 ~~AM~~/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials PC  
 Examiners Initials DD mc  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North <sup>Haulage seals</sup>	20.9	0	0	PC	ok	None Observed	
Main West <sup>Haulage seals</sup>	20.9	0	0	DD mc	ok	none obs.	
3 <sup>rd</sup> North <sup>Haulage seals</sup>	20.9	0	0	DD/mc	ok	none obs.	
1 <sup>st</sup> Right	20.9	0	0	DD/mc	ok	none obs.	
Transformers	20.9	0	0	DD/mc	ok	none obs.	
Chargers	20.9	0	0	DD/mc	ok	none observed	
Wash down	20.9	0	0	DD	ok	none observed	
Storage area	20.9	0	0	DD	ok	none observed	
Parking area	20.9	0	0	PC	ok	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 8462  
 CERT. # 8058  
 CERT. # 7325  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 1125

2MSHA03356

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-1-07

SECTION/AREA Gen M. N. 4 / /

TIME OF EXAMINATION START 11:50 ~~AM~~/PM  
 TIME OF EXAMINATION START 11:00 ~~AM~~/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 1:10 AM/~~PM~~  
 END 1:15 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials KLR  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	α	none observed	
Main North haulage seals	20.9	0	0	FM	α	none observed	
Main West haulage seals	20.9	0	0	<del>FM</del> KLR	α	none observed	
3rd North haulage seals	20.9	0	0	FM	α	none observed	
1st Right	20.9	0	0	FM	α	none observed	
Transformers	20.9	0	0	<del>FM</del> KLR	α	none observed	
chargers	20.9	0	0	<del>FM</del> KLR	α	none observed	
Storage Area	20.9	0	0	FM	α	none observed	
Washdown	20.9	0	0	FM	α	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 8297  
 CERT. # 7950  
 CERT. # 4355  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03357

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-1-07

SECTION/AREA Gen mine

TIME OF EXAMINATION START 7:50 AM/PM  
 TIME OF EXAMINATION START 8:30 AM/PM  
 TIME OF EXAMINATION START 8:45 AM/PM

END 8:50 AM/PM  
 END 9:25 AM/PM  
 END 8:50 AM/PM

Examiners Initials JM  
 Examiners Initials DD MC  
 Examiners Initials PC

EXAM. CALLED OUT ---- YES  NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North <sup>Haulage Seals</sup>	20.9	0	0	JM	OK	NONE observed	
Main West <sup>Haulage Seals</sup>	20.9	0	0	DD/MC	ok	none obs.	
3rd North <sup>Haulage Seals</sup>	20.9	0	0	JM	OK	NONE observed	
1 <sup>st</sup> Right	20.9	0	0	JM	OK	NONE observed	
TRANS.	20.9	0	0	DD/MC	ok	none obs.	
Chargers	20.9	0	0	JM/PC	OK	None observed	
Wash down	20.9	0	0	MC	ok	none obs.	
Storage Area	20.9	0	0	MC	ok	none obs.	
Parking Area	20.9	0	0	PC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS appear safe at time of inspection

PRE-SHIFT/MINE EXAMINE Signature

CERT. # 9713  
 CERT. # 8058  
 CERT. # 7378  
 CERT. # 8462

COUNTER SIGNATURE Signature

CERT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-2-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 3:35 ~~AM~~/PM END 5:15 ~~AM~~/PM Examiners Initials mc/DD  
 TIME OF EXAMINATION START 4:05 AM/PM END 5:20 AM/PM Examiners Initials PC  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	ok	None Observed	
Main North <sup>Haulage</sup> seals	20.9	0	0	PC	ok	None Observed	
Main West <sup>Haulage</sup> seals	20.9	0	0	mc/DD	ok	None observed	
3rd North <sup>Haulage</sup> seals	20.9	0	0	PC	ok	None observed	
1st Right	20.9	0	0	PC	ok	None observed	
Transformers	20.9	0	0	<del>mc/DD</del> PC	ok	None observed	
Chargers	20.9	0	0	mc/DD	ok	None observed	
Wash down	20.9	0	0	DD	ok	None observed	
Storage area	20.9	0	0	DD	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe  
at time of pre-shift

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINE CERT. # 7375  
 PRE-SHIFT/MINE EXAMINE CERT. # 8058  
 PRE-SHIFT/MINE EXAMINE CERT. # 8462  
 PRE-SHIFT/MINE EXAMINE CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4735

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-2-07

SECTION/AREA 6m/11w1

TIME OF EXAMINATION START 11:05 AM/PM  
 TIME OF EXAMINATION START 11:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 11:30 AM/PM  
 END 1:55 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials LR  
 Examiners Initials RL/KK  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>None observed</u>	
<u>Miscell haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>None observed</u>	
<u>M. West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>None obs</u>	
<u>South Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/KK</u>	<u>OK</u>	<u>None obs</u>	
<u>1st right Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>None obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>None obs</u>	
<u>Washed down</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>None obs</u>	
<u>Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>None obs</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>OK</u>	<u>None obs</u>	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ **Signature** \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 4375  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7954  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6401  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
**Signature** \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8460

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-2-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 7:00 AM/PM AM END 8:30 AM/PM PM Examiners Initials PC  
 TIME OF EXAMINATION START 700 AM/PM AM END 930 AM/PM PM Examiners Initials DD MC  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North seals <sup>Haulage</sup>	20.9	0	0	PC	OK	None Observed	
3rd North seals <sup>Haulage</sup>	20.9	0	0	PC	OK	None Observed	
1st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC/mc DD	OK	none observed	
Chargers	20.9	0	0	PC/mc DD	OK	none observed	
Main West seals <sup>Haulage</sup>	20.9	0	0	mc/DD	OK	none observed	
Wash down	20.9	0	0	mc	OK	none observed	
Storage area	20.9	0	0	mc	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8462  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature \_\_\_\_\_  
 COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-3-02 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 4:25 AM/PM END 5:02 AM/PM Examiners Initials PC  
 TIME OF EXAMINATION START 330 AM/PM END 540 AM/PM Examiners Initials DDmc  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North seals <sup>Haulage</sup>	20.9	0	0	PC	ok	None Observed	
Main West seals <sup>Haulage</sup>	20.9	0	0	DD/mc	ok	none obs.	
Parking area	20.9	0	0	PC	ok	None Observed	
3rd North seals <sup>Haulage</sup>	20.9	0	0	DD/mc	ok	none obs.	
1st Right seals <sup>Haulage</sup>	20.9	0	0	DD	ok	none obs.	
Transformers	20.9	0	0	<del>PC/mc</del> DD	ok	none obs.	
chargers	20.9	0	0	DD/mc	ok	none obs.	
wash down	20.9	0	0	DD	ok	none obs.	
Storage area	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8462  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8058  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 7375  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 Signature \_\_\_\_\_  
 COUNTER SIGNATURE \_\_\_\_\_ CERT. # 415

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-3-07 SECTION/AREA Gen Mine 1 1

TIME OF EXAMINATION START 11:00 AM/PM END 1:10 AM/PM Examiners Initials RL/LR  
 TIME OF EXAMINATION START 11:00 AM/PM END 12:25 AM/PM Examiners Initials KK  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Main North Haulage Seals	20.9	0	0	KK	OK	Bad Top <sup>of</sup> 12 Seal	Barred down
Parking Area	20.9	0	0	KK	OK	None observed	
W/West Haulage Seals	20.9	0	0	RL/LR KK	OK	None observed	
3 <sup>rd</sup> North Haulage Seals	20.9	0	0	KK	OK	None observed	
1 <sup>st</sup> Right Haulage Seals	20.9	0	0	KK	OK	None observed	
Tramways	20.9	0	0	RL/LR KK	OK	None observed	
Changars	20.9	0	0	RL/LR KK	OK	None observed	
Wash down	20.9	0	0	KK	OK	None observed	
Storage area	20.9	0	0	KK	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 4375  
 PRE-SHIFT/MINE EXAMINER CERT. # 6401  
 PRE-SHIFT/MINE EXAMINER CERT. # 7154  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature RT. # 8462

2MSHA03363

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-3-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7:55  
 TIME OF EXAMINATION START 7:25  
 TIME OF EXAMINATION START \_\_\_\_\_

AM/PM AM END 8:45 AM/PM AM  
 AM/PM AM END 9:25 AM/PM AM  
 AM/PM \_\_\_\_\_ END \_\_\_\_\_ AM/PM \_\_\_\_\_

Examiners Initials PC  
 Examiners Initials D/mc  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	ok	None observed	
North Haulage seals	20.9	0	0	PC	ok	None observed	
West Haulage seals	20.9	0	0	<del>PC</del> <u>D/mc</u>	ok	none observed	
3 <sup>rd</sup> North Haulage seals	20.9	0	0	PC	ok	None Observed	
1 <sup>st</sup> Right	20.9	0	0	PC	ok	None observed	
Transformers	20.9	0	0	<u>PC/mc</u> <u>DD</u>	ok	none observed	
chargers	20.9	0	0	<u>DD</u> <u>mc</u>	ok	none observed	
Storage area	20.9	0	0	mc	ok	none observed	
Wash down	20.9	0	0	mc	ok	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe  
at time of exam

PRE-SHIFT/MINE EXAMINER Signature :ERT. # 8462  
 PRE-SHIFT/MINE EXAMINER :ERT. # 8058  
 PRE-SHIFT/MINE EXAMINER :ERT. # 7375  
 PRE-SHIFT/MINE EXAMINER :ERT. # \_\_\_\_\_

Signature  
 CERT. # 8462

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-4-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 4:30 AM/PM  
 TIME OF EXAMINATION START 3:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 4:58 AM/PM  
 END 5:40 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials PC  
 Examiners Initials mc/DD  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	ok	None Observed	
N. North Haulage seals	20.9	0	0	PC	ok	None Observed	
W. West Haulage seals	20.9	0	0	mc/DD	ok	None observed	
3rd North Haulage seals	20.9	0	0	mc/DD	ok	None observed	
1st Right	20.9	0	0	mc/DD	ok	None observed	
Transformers	20.9	0	0	pc/mc/DD	ok	None observed	
Charger	20.9	0	0	mc/DD	ok	None observed	
Wash down	20.9	0	0	DD	ok	None observed	
Storage area	20.9	0	0	DD	ok	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS ARRIVS APPEARED REASONABLY SAFE AT TIME OF EXAM

Signature \_\_\_\_\_

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

CERT. # 7225  
 CERT. # 8058  
 CERT. # 8262  
 CERT. # \_\_\_\_\_

Signature \_\_\_\_\_

COUNTER SIGNATUR CERT. # 7485

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-4-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 11:51 AM/PM AM  
 TIME OF EXAMINATION START 11:40 AM/PM AM  
 TIME OF EXAMINATION START 12:45 AM/PM AM

END 1:10 AM/PM AM  
 END 1:40 AM/PM AM  
 END 1 AM/PM AM

Examiners Initials SW  
 Examiners Initials FM/DG  
 Examiners Initials dg

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage <sup>seals</sup>	20.9	0	0	SW	OK	none observed	
Main West haulage <sup>seals</sup>	20.9	0	0	<del>SW</del> FM/DG	OK	None observed	
3rd North haulage <sup>seals</sup>	20.9	0	0	SW	OK	none observed	
1st Right	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>SW</del> FM/DG	OK	None observed	
chargers	20.9	0	0	<del>SW</del> FM/DG	OK	None observed	
Storage Area	20.9	0	0	SW	OK	none observed	
Washdown	20.9	0	0	FM	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared Reasonably safe  
at time of exam

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

Signature

CERT. # 9548  
 CERT. # 8397  
 CERT. # 6622  
 CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATUR CERT. # 7485

2MSHA03366

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-4-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7:50 AM/PM (AM) END 8:55 AM/PM (PM) Examiners Initials GA  
 TIME OF EXAMINATION START 7:10 AM/PM (AM) END 8:40 AM/PM (PM) Examiners Initials LP  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	GA	OK	None observed	
Main No. Haulage <sup>Seals</sup>	20.9	0	0	GA	OK	None observed	
Main West Haulage <sup>Seals</sup>	20.9	0	0	LP	OK	None observed	
3rd No Haulage <sup>Seals</sup>	20.9	0	0	GA	OK	None observed	
1st Rf	20.9	0	0	GA	OK	None observed	
Trans Farmers	20.9	0	0	LP	OK	None observed	
chargers	20.9	0	0	LP	OK	None observed	
Storage Area	20.9	0	0	LP	OK	None observed	
wash down	20.9	0	0	LP	OK	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared To Be safe at Time of exam

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ **Signature** CERT. # 6908  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 03892  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 \_\_\_\_\_ **Signature**

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 03892

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-5-07

SECTION/AREA General Mine 1

TIME OF EXAMINATION START 3:04 AM/PM  
 TIME OF EXAMINATION START 350 AM/PM  
 TIME OF EXAMINATION START 3:00 AM/PM

END 4:20 AM/PM  
 END 502 AM/PM  
 END 3:22 AM/PM

Examiners Initials LP  
 Examiners Initials CT  
 Examiners Initials BT

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CT	OK	None observed	
Main No Haulage <sup>Seals</sup>	20.9	0	0	CT	OK	None observed	
Main West seals <sup>Haulage</sup>	20.9	0	0	LP/CT	OK	None observed	
3rd No Haulage <sup>Seals</sup>	20.9	0	0	CT	OK	None observed	
1st Rt Haulage	20.9	0	0	CT	OK	None observed	
Transformers	20.9	0	0	LP/CT	OK	None observed	
chargers	20.9	0	0	LP	OK	None observed	
Storage Area	20.9	0	0	LP	OK	None observed	
wash down	20.9	0	0	LP	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main section intake	Getting gray	Dusted CT 6507

PRE-SHIFT REMARKS All Area Appeared To Be safe  
At Time Of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 6908  
 PRE-SHIFT/MINE EXAMINER CERT. # 03823  
 PRE-SHIFT/MINE EXAMINER CERT. # 8395  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE **Signature** CERT. # 7485 2MSHA03368

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-5-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:00 ~~AM~~/PM END 12:42 AM/~~PM~~  
 TIME OF EXAMINATION START 11:59 ~~AM~~/PM END 1:07 AM/~~PM~~  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

Examiners Initials FM  
 Examiners Initials SW  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/~~NO~~ CALL OUT TIME ----- \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
Main North haulage seals	20.9	0	0	SW	OK	none observed	
Main West haulage seals	20.9	0	0	<del>SW</del> FM	OK	none observed	
3rd North haulage seals	20.9	0	0	SW	OK	none observed	
1st Right	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	<del>SW</del> FM	OK	none observed	
chargers	20.9	0	0	<del>SW</del> FM	OK	none observed	
Washdown	20.9	0	0	FM	OK	None observed	
Storage Area	20.9	0	0	FM	OK	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
Main North haulage	loose top	pryed down

PRE-SHIFT REMARKS All areas appeared safe to travel at time of exam.

PRE-SHIFT/MINE EXAMINE **Signature** CERT. # 8297  
 PRE-SHIFT/MINE EXAMINE CERT. # 9548  
 PRE-SHIFT/MINE EXAMINE CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINE CERT. # \_\_\_\_\_

COUNTER SIGNATURE **Signature** CERT. # 7485

2MSHA03369

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-5-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7:03 AM/PM (AM) END 8:40 AM/PM (AM) Examiners Initials LP  
 TIME OF EXAMINATION START 7:50 AM/PM (AM) END 8:55 AM/PM (AM) Examiners Initials GA  
 TIME OF EXAMINATION START 7:30 AM/PM (AM) END 7:30 AM/PM (AM) Examiners Initials BH

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- AM/PM  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	GA	OK	None observed	
Main No. <sup>seals</sup> haulage	20.9	0	0	GA	OK	None observed	
main west <sup>haulage</sup> seals	20.9	0	0	LP/BA	OK	None observed	
3rd No. <sup>seals</sup> haulage	20.9	0	0	GA	OK	None observed	
1st Rt Haulage	20.9	0	0	GA	OK	None observed	
Transformers	20.9	0	0	LP	OK	None observed	
chargers	20.9	0	0	LP	OK	None observed	
storage Area	20.9	0	0	LP	OK	None observed	
wash down	20.9	0	0	LP	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared To Be Safe at Time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6908  
 PRE-SHIFT/MINE EXAMINER CERT. # 03892  
 PRE-SHIFT/MINE EXAMINER CERT. # 6385  
 PRE-SHIFT/MINE EXAMINER CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 03892 2MSHA03370

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-6-07

SECTION/AREA Ben Mine 1

TIME OF EXAMINATION START 3:04 AM/PM  
 TIME OF EXAMINATION START 344 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 4:45 AM/PM  
 END 450 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials LP  
 Examiners Initials CA  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CA	OK	None observed	
Main No haulage <sup>5 seals</sup>	20.9	0	0	CA	OK	None observed	
Main west seal <sup>7 seals</sup>	20.9	0	0	LP	OK	None observed	
3rd No haulage <sup>5 seals</sup>	20.9	0	0	CA	OK	None observed	
1st Rt.	20.9	0	0	CA	OK	None observed	
Transformers	20.9	0	0	LP	OK	None observed	
chargers	20.9	0	0	LP	OK	None observed	
storage Area	20.9	0	0	LP	OK	None observed	
wash down	20.9	0	0	LP	OK	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
25 seal	stumbling hazards	Removed
3 No.		

PRE-SHIFT REMARKS All Areas appeared to be safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

ERT. # 6908  
 ERT. # 03892  
 ERT. # \_\_\_\_\_  
 ERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_

CERT. # 7485

2MSHA03371

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-6-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 11:00 ~~AM~~/PM  
 TIME OF EXAMINATION START 11:50 ~~AM~~/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 12:30 AM/~~PM~~  
 END 1:00 AM/~~PM~~  
 END \_\_\_\_\_ AM/PM

Examiners Initials SW  
 Examiners Initials FM  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
Main North <sup>SEALS</sup> haulage	20.9	0	0	FM	OK	none observed	
Main West <sup>SEALS</sup> haulage	20.9	0	0	<del>FM</del> SW	OK	Leak water x at 73 #1 roadway	Pumping Rep'd 6-6-07
3rd North <sup>haulage</sup> SEALS	20.9	0	0	FM	OK	none observed	
1st Right haulage	20.9	0	0	FM	OK	none observed	
Transformers	20.9	0	0	<del>FM</del> SW	OK	none observed	
chargers	20.9	0	0	<del>FM</del> SW	OK	none observed	
Storage Area	20.9	0	0	SW	OK	none observed	
wash down	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe  
At time of exam

Signature \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE CERT. # 9548  
 PRE-SHIFT/MINE EXAMINEE CERT. # 8297  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINEE CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03372

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-6-07

SECTION/AREA Gen 1 Mine 1

TIME OF EXAMINATION START 7:07 AM/PM  
 TIME OF EXAMINATION START 7:00 AM/PM  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 8:50 AM/PM  
 END 8:55 AM/PM  
 END \_\_\_\_\_ AM/PM

Examiners Initials LP  
 Examiners Initials A  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES  NO

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CA	OK	None observed	
Main No haulage <sup>Seals</sup>	20.9	0	0	CA	OK	None observed	
Main West <sup>Haulage</sup> seals	20.9	0	0	LP	OK	None observed	
3rd No haulage <sup>Seals</sup>	20.9	0	0	CA	OK	None observed	
1st RT	20.9	0	0	CA	OK	None observed	
Trans Formers	20.9	0	0	LP	OK	None observed	
chargers	20.9	0	0	LP	OK	None observed	
Storage Area	20.9	0	0	LP	OK	None observed	
Wash down	20.9	0	0	LP	OK	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
Wash down	water getting deep	pumped out

PRE-SHIFT REMARKS all areas appeared to be safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER  
 PRE-SHIFT/MINE EXAMINER

CERT. # 6908  
 CERT. # 03892  
 CERT. # \_\_\_\_\_  
 CERT. # \_\_\_\_\_

Signature

2MSHA03373

COUNTER SIGNATURE

CERT. # 03892

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-7-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 3:00 ~~AM/PM~~  
 TIME OF EXAMINATION START 3:50 ~~AM/PM~~  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END 4:50 ~~AM/PM~~  
 END 4:55 ~~AM/PM~~  
 END \_\_\_\_\_ AM/PM

Examiners Initials LP  
 Examiners Initials CT  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CT	α	None observed	
Main Ho. Haulage <sup>5 seals</sup>	20.9	0	0	CT	α	None observed	
Main West Haulage <sup>seals</sup>	20.9	0	0	LP	α	None observed	
3rd Ho Haulage <sup>seals</sup>	20.9	0	0	CT	α	None observed	
1st RT Haulage	20.9	0	0	CT	α	None observed	
Transformers	20.9	0	0	LP	α	None observed	
chargers	20.9	0	0	LP	α	None observed	
storage Area	20.9	0	0	LP	α	None observed	
wash down	20.9	0	0	LP	α	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
M/W Section intake	Getting gray	Bulk dusted

PRE-SHIFT REMARKS All Area Appeared to Be safe at Time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 6908  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 03892  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 7488 2MSHA03374

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-7-07 SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 11:00 ~~AM~~/PM END 12:27 AM/~~PM~~  
 TIME OF EXAMINATION START 11:48 ~~AM~~/PM END 12:56 AM/~~PM~~  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

Examiners Initials SW  
 Examiners Initials FM  
 Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ----- YES/NO (O) CALL OUT TIME ----- \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	α	none observed	
Main North haulage <sup>SLATS</sup>	20.9	0	0	FM	α	none observed	
Main West haulage <sup>SLATS</sup>	20.9	0	0	<del>SW</del> /FM	α	had dust main section transformer	dusted 6-7-07
3rd North haulage <sup>SLATS</sup>	20.9	0	0	FM	α	none observed	
1st Right haulage	20.9	0	0	FM	α	none observed	
Transformers	20.9	0	0	<del>SW</del> /FM	α	none observed	
Chargers	20.9	0	0	<del>SW</del> /FM	α	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Wash down	21.0	0	0	SW	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 9548  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # 8297  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03375

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6 7 07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 7:48 AM/PM  
 TIME OF EXAMINATION START 7:00 AM/PM  
 TIME OF EXAMINATION START 7:00 AM/PM

END 8:50 AM/PM  
 END 8:56 AM/PM  
 END 7:36 AM/PM

Examiners Initials CT  
 Examiners Initials LP  
 Examiners Initials BH

EXAM. CALLED OUT ----- YES  NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CT	OK	None observed	
Main <sup>seals</sup> haulage	20.9	0	0	CT	OK	None observed	
Main west <sup>haulage</sup> seals	20.9	0	0	LP/BH	OK	None observed	
3rd <sup>seals</sup> haulage	20.9	0	0	CT	OK	None observed	
15th <sup>haulage</sup> haulage	20.9	0	0	CT	OK	None observed	
Trans Frames	20.9	0	0	LP	OK	None observed	
Chargers	20.9	0	0	LP	OK	None observed	
Storage Area	20.9	0	0	LP	OK	None observed	
wash down	20.9	0	0	LP	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas & travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE  
 PRE-SHIFT/MINE EXAMINEE

**Signature**  
 ERT. # 03892  
 ERT. # 6908  
 ERT. # 8395  
 ERT. # \_\_\_\_\_

COUNTER SIGNATURE **Signature** CERT. # 03892

2MSHA03376

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-8-07 SECTION/AREA Genl Mine 1

TIME OF EXAMINATION START 3:00 AM/PM END 4:55 AM/PM Examiners Initials LP  
 TIME OF EXAMINATION START 3:50 AM/PM END 4:50 AM/PM Examiners Initials GA  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_  
 CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
U.G. Parking	20.9	0	0	GA	OK	None observed	
Main No haulage <sup>seals</sup>	20.9	0	0	GA	OK	None observed	
main west haulage <sup>seal</sup>	20.9	0	0	LP	OK	None observed	
3rd No haulage <sup>seals</sup>	20.9	0	0	GA	OK	None observed	
1st Rt haulage	20.9	0	0	GA	OK	None observed	
Transformers	20.9	0	0	LP	OK	None observed	
chargers	20.9	0	0	LP	OK	None observed	
storage Area	20.9	0	0	LP	OK	None observed	
wash down	20.9	0	0	LP	OK	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS
#5 seal	stumbling hazards	Cleared GA
3 No.		

PRE-SHIFT REMARKS All Areas appeared safe at time of exam.

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ ERT. # 6908  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ ERT. # 03892  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ ERT. # \_\_\_\_\_  
 PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

Signature

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 8462

2MSHA03377

# PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-8-07

SECTION/AREA Geomining

TIME OF EXAMINATION  
TIME OF EXAMINATION  
TIME OF EXAMINATION

START 11:49 AM/PM  
START 11:40 AM/PM  
START 11:52 AM/PM

END 1:08 AM/PM  
END 1:10 AM/PM  
END 1:20 AM/PM

Examiners Initials MC  
Examiners Initials EM/LD  
Examiners Initials LD

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_  
CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	none observed	
Main North Haulage Seals	20.9	0	0	MC	OK	none observed	
Main West Haulage Seals	20.9	0	0	MC EM LD	OK	none observed	
3 <sup>rd</sup> North Haulage Seals	20.9	0	0	MC	OK	none observed	
1 <sup>st</sup> Right Seal	20.9	0	0	MC	OK	none observed	
Trampers	20.9	0	0	MC EM LD	OK	none observed	
Chargers	20.9	0	0	MC EM LD	OK	none observed	
Storage Area	20.9	0	0	EM	OK	none observed	
Washdown	20.9	0	0	LD	OK	none observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTIONS

**PRE-SHIFT REMARKS**

ALL Areas Appeared Reasonably Safe At time of exam

**Signature**

PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER  
PRE-SHIFT/MINE EXAMINER

CERT. # 7375  
CERT. # 8297  
CERT. # 9660  
CERT. # \_\_\_\_\_

**Signature**

COUNTER SIGNATURE

CERT. # 8462

2MSHA03378

2MSHA03379